




NR5/10.11/1987-88  
C.2



**STATE ENGINEER'S  
FIFTH ANNUAL REPORT TO THE  
GENERAL ASSEMBLY ON  
DAM SAFETY FOR  
F. Y. 87-88**

**November 1, 1988**

**OFFICE OF THE STATE ENGINEER  
DIVISION OF WATER RESOURCES**



Jeris A. Danielson  
State Engineer



ROY ROMER  
Governor



JERIS A. DANIELSON  
State Engineer

**OFFICE OF THE STATE ENGINEER**  
DIVISION OF WATER RESOURCES

1313 Sherman Street-Room 818  
Denver, Colorado 80203  
(303) 866-3581

October 19, 1988

The Honorable Roy Romer  
Governor, State of Colorado  
State Capitol Building  
Denver, Colorado

The Honorable Ted Strickland  
President of the Senate  
Colorado State Senate  
Denver, Colorado

The Honorable Bev Bledsoe  
Speaker of the House  
Colorado House of Representatives  
Denver, Colorado

Gentlemen:

Pursuant to Section 37-87-114.4, C.R.S. 1973 (1987 Supp.), I am pleased to transmit the enclosed report describing the activities of the State Engineer with respect to dam safety in Colorado for fiscal year 1987-1988.

Colorado's dam safety program has matured as a result of resources made available by the General Assembly and as a result of increased awareness by dam owners of their responsibilities. This awareness has been gained by informing the owner through public meetings and seminars on dam safety issues.

I still believe our dam safety program can be improved by continued education of dam owners and the public, additional staffing (2.0 FTE), additional funds (\$5,000) for on-going training of our professional staff, and additional funds (\$30,000) for rental of "All-Terrain Vehicles" and a helicopter for efficient access to remote areas as described in detail in the report.

I have also taken steps to decentralize the dam inspection program by moving field engineers from Denver to Glenwood Springs, Montrose, and Durango. This will permit inspections at less cost and will enhance the program.




Governor Roy Romer  
October 19, 1988

Page 2

If you have any questions or would like additional information, please feel free to call upon me at any time.

Sincerely,



Jeris A. Danielson  
State Engineer

JAD/AEP:jad/02271

Enclosure (a/s)

cc: Senate Majority Leader Jeffrey M. Wells  
Senate Minority Leader Ray E. Peterson  
House Majority Leader Chris Paulson  
House Minority Leader Ruth Wright  
Senator Tilman Bishop, Chairman  
Senate Agriculture Committee  
Representative Scott McInnis, Chairman  
House Agriculture Committee  
Senator Robert DeNier, Vice-Chairman  
Joint Budget Committee  
Senator Mike Bird, Joint Budget Committee  
Senator James Rizzuto, Joint Budget Committee  
Representative Elwood Gillis, Chairman  
Joint Budget Committee  
Representative Vickie Armstrong, Joint Budget Committee  
Representative Richard R. Bond, Joint Budget Committee



# STATE ENGINEER'S ANNUAL REPORT

## TABLE OF CONTENTS

### 1987-1988

|   |    |
|---|----|
| INTRODUCTION . . . . .  | 1  |
| APPROVAL OF PLANS & SPECIFICATIONS FOR CONSTRUCTION OF DAMS & RESERVOIRS. . . . . | 5  |
| SAFETY INSPECTIONS AND CONSTRUCTION OBSERVATION . . . . .                         | 6  |
| USE OF APPROPRIATED FUNDS . . . . .   | 10 |
| RECEIPTS GENERATED FOR COSTS OF INSPECTIONS & FILING OF PLANS . . . . .           | 10 |
| RULES AND REGULATIONS . . . . .   | 10 |
| ENFORCEMENT ORDERS AND PROCEEDINGS . . . . .                                      | 11 |
| EMERGENCY PREPAREDNESS PLANS . . . . .  | 13 |
| DAM SAFETY DATA BASE MANAGEMENT SYSTEM . . . . .                                  | 14 |
| EFFECTIVENESS OF PROGRAM . . . . .  | 14 |
| LEGISLATION . . . . .   | 14 |
| RECOMMENDED LEGISLATION . . . . .   | 15 |

## TABLES

|  |   |
|--|---|
| TABLE 1 - JURISDICTIONAL DAM OWNERSHIP STATUS . . . . .                    | 3 |
| TABLE 2 - DISTRIBUTION OF DAMS BY IRRIGATION DIVISION/HAZARD . . . . .     | 4 |
| TABLE 3 - CAUSE FOR RESTRICTIONS BY CATEGORY/HAZARD . . . . .              | 8 |
| TABLE 4 - CAUSE FOR RESTRICTIONS BY CATEGORY/IRRIGATION DIVISION . . . . . | 8 |

## APPENDICES

|                      |   |
|----------------------|---|
| APPENDIX A . . . . . | DAM SAFETY BRANCH PERSONNEL             |
| APPENDIX B . . . . . | LISTS OF APPROVED PLANS                 |
| APPENDIX C . . . . . | WATER COMMISSIONER'S OBSERVATION REPORT |
| APPENDIX D . . . . . | ENGINEERS REPORT                        |
| APPENDIX E . . . . . | CURRENT RESTRICTION LIST, JUNE 30, 1988 |

The Field Engineering Units' principal duties are to conduct Safety Evaluations of Existing Dams (SEED),<sup>1</sup> design review and construction inspection of repairs,<sup>2</sup> and investigation of complaints on the safety of dams.<sup>3</sup> They investigate the construction of dams in violation of Section 37-87-105(1) and (4), C.R.S., (1973) (1987 Supp.), assist the Department of Health in the inspection of failing dams, and conduct training on the inspection of dams for division personnel, dam owners, interested agencies, engineers, and the public. They also do other related work as assigned.

<sup>1</sup>Per Section 37-87-107, C.R.S. (1973) (1987 Supp.)

<sup>2</sup>Per Section 37-87-105(4), C.R.S. (1973) (1987 Supp.)

<sup>3</sup>Per Section 37-87-109, C.R.S. (1973)



STATE ENGINEER'S FIFTH ANNUAL REPORT  
TO THE  
GENERAL ASSEMBLY  
ON  
DAM SAFETY  
FOR  
FY 87-88

## INTRODUCTION

### Statutory Provisions

Colorado's Dam Safety Program is administered by the State Engineer in accordance with Title 37, Article 87, of C.R.S. (1973) (1987 Supp.), and the Livestock Water Tank Act, Title 35, Article 49 of C.R.S. (1973), as amended. Rules and Regulations for filing plans and specifications for the construction of reservoir dams, and standard specifications for Livestock Water Tanks and Erosion Control Dams, establish the procedures and requirements of the State Engineer for administration of these statutes.

This report is submitted in compliance with Section 37-87-114.4, C.R.S. (1987 Supp.) concerning the activities of the State Engineer and the Division of Water Resources relating to Sections 37-87-105 to 37-87-114, C.R.S. (1973) (1987 Supp.).

### Organization

Implementation of the dam safety program is done by the State Engineer through the Dam Safety Branch.

The branch is organized into three units, two being field engineering units (FEU), and the other, a design review and construction inspection unit (DRCIU). Each unit is led by a Supervising Water Resource Engineer. (See Appendix A for tables and charts of the personnel and organization of the branch.)

The Field Engineering Units' principal duties are to conduct Safety Evaluations of Existing Dams (SEED),<sup>1</sup> design review and construction inspection of repairs,<sup>2</sup> and investigation of complaints on the safety of dams.<sup>3</sup> They investigate the construction of dams in violation of Section 37-87-105(1) and (4), C.R.S., (1973) (1987 Supp.), assist the Department of Health in the inspection of tailing dams, and conduct training on the inspection of dams for division personnel, dam owners, interested agencies, engineers, and the public. They also do other related work as assigned.

<sup>1</sup> Per Section 37-87-107, C.R.S. (1973) (1987 Supp.)

<sup>2</sup> Per Section 37-87-105(4), C.R.S. (1973) (1987 Supp.)

<sup>3</sup> Per Section 37-87-109, C.R.S. (1973)



The Design Review and Construction Inspection Unit's principal duties are to review the plans and specifications for the construction, alteration, modification, repair, and enlargement of reservoirs or dams in accordance with Section 37-87-105, C.R.S. (1973) (1987 Supp.) (this involves a comprehensive engineering review of the plans and specifications to assure that a safe design has been developed), and to inspect the construction of the work. It processes the Livestock Water Tank and Erosion Control Dam applications per Section 35-49-101 through 116, C.R.S. (1973) and Section 37-87-122, C.R.S. (1973). The Unit assists the Department of Health in the technical evaluation of tailing impoundments through a "Memorandum of Understanding," and participates in the State's "Joint Review Process" with the Department of Natural Resources. They also do other related work as assigned.

#### Goals and Objectives of the Program

The primary goal of the State Engineer with respect to dam safety is to provide maximum public safety against dam failures within the resources of his office. Towards this goal, the resources are directed at the safety inspection of each high and moderate hazard nonfederal dam and reservoir on an annual basis, and the safety inspection of each low hazard nonfederal dam and reservoir on a five-year basis. The program concentrates on "jurisdictional" dams and reservoirs as defined in Section 37-87-105 C.R.S. (1973) (1987 Supp.) which are greater than 10 feet high at the spillway, or greater than 20 acres in surface area at the high water line, or greater than 100 acre-feet in capacity at the high water line.

Safety inspections are made of U.S. Bureau of Reclamation and U.S. Corps of Engineers dams on a cooperative basis, their safety inspections being carried out in accordance with the "Federal Guidelines for Dam Safety." Arrangements are made with other federal agencies for the safety inspection of their dams by the Bureau of Reclamation, the Corps of Engineers, their own forces, consulting engineers, or by the State Engineer. When other than State Engineer personnel conduct the safety inspections, the agencies submit the findings/recommendations and follow-up to the State Engineer in order to assure the safety of these dams. A memorandum of understanding has been formulated with the Bureau of Reclamation relating to dam safety activities in Colorado. It provides for the exchange of safety-related information of dams under each agencies jurisdiction.

A related objective is the inspection of construction for compliance with approved plans, and to assure that plans are adequate for the site conditions. Inspections are made of the foundation, outlet works, spillways, and final construction as a minimum. Interim inspections are made as necessary.

An adjunct to the inspection objectives, but an important element of the dam safety program, is the goal to have each owner of high hazard dams prepare an Emergency Preparedness Plan to combat any incident which would jeopardize the safety of the dams, and to give warning to appropriate emergency preparedness agencies/officials so they may mobilize their plans for mitigating the consequences of dam-break flooding.

The following Table 1 shows the ownership of jurisdictional dams in Colorado by owner; and Table 2 shows the distribution of dams in the state by Water Division and hazard rating.



APPROVAL OF PLANS AND SPECIFICATIONS FOR CONSTRUCTION  
OF DAMS AND RESERVOIRS

TABLE 1

JURISDICTIONAL<sup>1</sup> DAM OWNERSHIP STATUS  
IN COLORADO

| HAZARD RATING       | TYPE OF OWNER |       |             | PRIVATE | TOTAL |
|---------------------|---------------|-------|-------------|---------|-------|
|                     | FEDERAL       | STATE | OTHER GOVT. |         |       |
| HIGH (Class I )     | 38            | 12    | 77          | 127     | 254   |
| MODERATE (Class II) | 11            | 22    | 74          | 210     | 317   |
| LOW (Class III)     | 52            | 32    | 134         | 954     | 1,172 |
| TOTAL               | 101           | 66    | 285         | 1,291   | 1,743 |

<sup>1</sup>Greater than ten feet high to spillway, or 20 acres in surface area at the high-water line, or 100 acre-feet in capacity at the high-water line.

H = High Hazard = Class I - loss of human life is expected in the event of failure of the dam, while the reservoir is at the high-water line.

M = Moderate Hazard = Class II - significant damage to improved property is expected in the event of failure of the dam while the reservoir is at the high-water line, but no loss of human life is expected.

L = Low Hazard = Class III - loss of human life is not expected, and damage to improved property is expected to be small, in the event of failure of the dam while the reservoir is at the high-water line.



Table 2

DISTRIBUTION OF DAMS BY IRRIGATION DIVISION/HAZARD

| DIVISION | NONFEDERAL |       |       | FEDERAL |     |    | TOTAL |     |       |
|----------|------------|-------|-------|---------|-----|----|-------|-----|-------|
|          | H          | M     | L     | H       | M   | L  | H     | M   | L     |
| 1        | 113        | 128   | 446   | 13      | 6   | 18 | 126   | 134 | 464   |
| 2        | 32         | 50    | 201   | 5       | 3   | 8  | 37    | 53  | 209   |
| 3        | 9          | 15    | 37    | 1       | 0   | 5  | 10    | 15  | 42    |
| 4        | 21         | 39    | 166   | 8       | 0   | 7  | 29    | 39  | 173   |
| 5        | 21         | 41    | 120   | 7       | 1   | 9  | 28    | 42  | 129   |
| 6        | 10         | 15    | 105   | 0       | 1   | 4  | 10    | 16  | 109   |
| 7        | 10         | 18    | 45    | 4       | 0   | 1  | 14    | 18  | 46    |
|          | 216        | 306   | 1,120 | 38      | 11  | 52 | 254   | 317 | 1,172 |
| TOTALS   |            | 1,642 |       |         | 101 |    |       |     | 1,743 |

H = High Hazard = Class I - loss of human life is expected in the event of failure of the dam, while the reservoir is at the the high water line.

M = Moderate Hazard = Class II - significant damage to improved property is expected in the event of failure of the dam while the reservoir is at the high water line, but no loss of human life is expected.

L = Low Hazard = Class III - loss of human life is not expected, and damage to improved property is expected to be small, in the event of failure of the dam while the reservoir is at the high water line.

The following Table 1 shows the ownership of jurisdictional dams in Colorado by owner; and Table 2 shows the distribution of dams in the state by Water Division and hazard rating.



APPROVAL OF PLANS AND SPECIFICATIONS FOR CONSTRUCTION  
OF DAMS AND RESERVOIRS

During FY 87-88, the State Engineer received plans for eight new dams, and 52 plans for alteration, modification, repair, or enlargement. Sixteen change orders to previously approved plans were also reviewed and all were approved within the time frame. Eighteen separate hydrology/hazard studies were also received for determination of the inflow design flood for spillway designs or hazard classifications. Estimated cost of construction for the submitted plans was \$5,267,041. Four thousand one hundred and eighty dollars (\$4,180.00) was collected for the examination and filing of the submitted plans.

Forty-two sets of plans and specifications were approved by the State Engineer for construction during FY 87-88. (See Appendix B for lists of dams which were approved by Water Division/District, and use.) In order to expedite the approval of repair plans for dams, the State Engineer has modified the approval process for these type of plans by delaying the filing requirements until the end of construction and approving the work by letter. This enables the owners to repair their dams sooner by shortening the review time. Since these types of repairs are usually simple procedures, they do not require the same detail as plans for new dams.

Three special studies associated with dams were also performed, including geotechnical reports, feasibility reports, subdivision plans, and requests from the Department of Health, and Division of Mined Land Reclamation.

Upon completion of construction, the owner's engineer submits copies of the "AS-CONSTRUCTED" plans, showing the changes made during construction. These plans are reviewed by the engineer who monitored the construction for completeness before being accepted for filing. The superseded plans are disposed of and the "AS-CONSTRUCTED" plans serve as the public record as provided by the statutes.

Section 37-87-114.5, C.R.S. (1987 Supp.) exempts certain structures from the State Engineer's approval. They are, structures not designed or operated for the purpose of storing water, mill tailing impoundments permitted under Article 32 or 33 of Title 34, C.R.S. (Minerals or Coal Mines), uranium mill tailing and liquid impoundment structures permitted under Article 11 of Title 25, C.R.S., siltation structures permitted under Article 33 of Title 34, C.R.S. (Coal Mines), and structures which store water only below the natural surface of the ground.

In order to prevent administrative problems arising from the construction of small dams which do not fall under the jurisdiction of the State Engineer's review and approval, Section 37-87-125, C.R.S. (1987 Supp.) requires that a notice of intent to construct an impoundment must be submitted to the State Engineer prior to beginning construction. The State Engineer has developed a



form for submitting the notice, which is directed to the Division Engineer of the Division that the impoundment is located in for processing. The notification also serves to address any dam safety issues which are evident.

### SAFETY INSPECTIONS AND CONSTRUCTION OBSERVATION

#### Scheduling

Jurisdictional dams identified for inspection in accordance with the objectives of the State Engineer are assigned to the field engineers on a geographic and hazard related basis. The field engineers each schedule the inspection of approximately 85 separate dams each "inspection season," which begins about April 1 and ends about November 1. Subsequent follow-up and problem solving results in additional inspections each year. Within the planned schedules are the inclusion of all the high and moderate hazard dams, and approximately one-fifth of the low ones. Inspection of Federal dams are integrated with these schedules. In addition, the State Engineer has executed a memorandum of understanding with the Regional Forester, Rocky Mountain Region, USDA Forest Service, concerning the statutory obligations each has in regard to the administration and safety of dams on National Forest lands in Colorado. The memorandum of understanding provides for the exchange of information, assuring access to dams (e.g. wilderness areas), scheduling of the inspection of Forest Service dams, and the joint review for approval of plans and specifications. The two field engineering units, therefore, collectively conduct about 900 safety inspections on an "inspection season" basis, which is equivalent to a fiscal year in the amount planned.

In order to track potential problems which could develop at low hazard dams between their five-year engineered inspections, the Division's Water Commissioners are assigned lists of low hazard dams to observe and to fill out a report. The report is submitted to the branch for review, and a copy is furnished to the owner for their information and to implement any recommendations for maintenance and repair. A copy of the WATER COMMISSIONER DAM OBSERVATION REPORT is in Appendix C.

#### Scope

A safety inspection involves more than just a visit to the dam. The site visit is preceded by a review of the file and history of performance, and coordination with the owner, division staff, and other interested parties so they may take part in the inspection. (The statute specifies that a safety inspection include the review of previous inspection reports and drawings, site inspection of the dam, spillways, outlet facilities, seepage control and measurement system, and permanent monument or monitoring installations.)

A safety inspection also includes an evaluation of the adequacy of the spillway to pass the appropriate sized flood for the dam's size and hazard class, to make an evaluation of the dam's hazard classification and whether it has been affected, and to assess the several emergency preparedness plans for the dams.



The findings of the inspection are documented on a report form which rates the conditions observed of the several components of the dam and reservoir. The overall conditions are rated as satisfactory, conditionally satisfactory, or unsatisfactory (unsafe) for full storage, and a recommendation is made on the safe storage level. The report also enumerates the several repair and maintenance items which the owner must attend to, and specifies the several engineering and monitoring requirements necessary to assure the safety of the dam. (A copy of the ENGINEERS INSPECTION REPORT is in Appendix D.

An invoice for the cost of the inspection is also prepared in accordance with the provisions of the statutes, the payment being due within 30 days of receipt by the owner.

If the safety inspection finds that the overall conditions are unsafe, an order is written by the State Engineer restricting the storage in the reservoir to a safe level. If the findings are conditionally satisfactory, full storage is recommended contingent upon appropriate monitoring provisions being provided by the owner. Restriction orders are accompanied by orders to rehabilitate the dam to make it safe for full storage, or to breach the dam.

Orders to repair or maintain the dam usually require the reinspection of the dam in order to verify that the work has been done in a workmanlike manner. Reinspections normally occur to assure follow-up of the State Engineer's orders, or by request from the owner.

In the event the owner fails to comply with an order to make a dam safe, a breach order is issued to remove the hazard created by the dam and reservoir. This subject will be covered in more detail later in this report under RESULTS OF SAFETY INSPECTIONS and ENFORCEMENT ORDERS AND PROCEEDINGS, where the Attorney General is requested to commence proceedings against owners refusing to obey the written orders of the State Engineer.

#### Number of Inspections

During FY 87-88, a total of 996 safety inspections were conducted (and 70 construction inspections) for a total of 1066. This included 265 safety inspections of high hazard dams, 229 safety inspections of moderate hazard dams, and 402 safety inspections of low hazard dams (including Federal dams). The objective of inspecting all high and moderate hazard dams on an annual basis is an "inspection season" objective versus a fiscal year one. This objective was reached for "inspection season" 1987 and is expected for 1988, in spite of the loss of one FTE that was eliminated by the legislature for FY 88-89.

#### Results of Safety Inspections

The 996 safety inspections resulted in the issuance of 42 restriction orders due to unsafe conditions during FY 87-88. Fifty-seven former restrictions were removed, and 29 revised.

As of June 30, 1988, there were a total of 279 restriction orders in effect. The following tables show the cause for restrictions by category and hazard class in Table 3, and by category and Irrigation Division in Table 4.



TABLE 3

CAUSE FOR RESTRICTION BY CATEGORY/HAZARD<sup>1</sup>

| HAZARD   | CATEGORY             |          |          |          |                  |      |  |  |
|----------|----------------------|----------|----------|----------|------------------|------|--|--|
|          | A                    | B        | C        | D        | TOTAL            |      |  |  |
| HIGH     | 11 (-8) <sup>2</sup> | 3 (-40)  | 12 (+20) | 5 (0)    | 31               | (-3) |  |  |
| MODERATE | 20 (-13)             | 32 (+3)  | 13 (-13) | 10 (-9)  | 75               | (-6) |  |  |
| LOW      | 68 (+6)              | 69 (+8)  | 21 (-16) | 15 (-17) | 173              | (+1) |  |  |
| TOTAL    | 99 (0)               | 104 (+4) | 46 (-8)  | 30 (-12) | 279 <sup>3</sup> | (-1) |  |  |

TABLE 4

CAUSE FOR RESTRICTIONS BY CATEGORY/IRRIGATION DIVISION<sup>1</sup>

| DIVISION | CATEGORY |     |    |    |                  | NO. OF<br>NONFEDERAL<br>DAMS |
|----------|----------|-----|----|----|------------------|------------------------------|
|          | A        | B   | C  | D  | TOTAL            |                              |
| 1        | 43       | 45  | 17 | 15 | 120              | 687                          |
| 2        | 15       | 18  | 3  | 6  | 42               | 283                          |
| 3        | 5        | 1   | 1  | 0  | 7                | 61                           |
| 4        | 11       | 12  | 10 | 4  | 37               | 226                          |
| 5        | 16       | 15  | 12 | 1  | 44               | 182                          |
| 6        | 9        | 5   | 2  | 2  | 19               | 130                          |
| 7        | 3        | 4   | 1  | 2  | 10               | 73                           |
| TOTAL    | 99       | 104 | 46 | 30 | 279 <sup>3</sup> | 1,642                        |

A - Inadequate Spillway/Freeboard

B - Structural Problem (Deteriorated appurtenances, cracking, erosion, scarps, sinkholes, deteriorated riprap, etc.)

C - Leakage/Piping Conditions

D - Stability (Slides, saturated slopes)

<sup>1</sup> In effect as of June 30, 1988

<sup>2</sup> (%) change from FY 86-87

<sup>3</sup> All nonfederal dams



The approximate amount of storage lost due to restrictions is 132,628 acre-feet. The number of restrictions has reduced slightly, reflecting the repairs the owners are making to their dams, or breaching. A list of the storage restrictions by name, former water district, amount of restriction, date, reason, hazard rating, and approximate storage lost is contained in Appendix E.

The greatest problems causing the unsafe conditions according to the tables are inadequate spillway capacity-insufficient freeboard (freeboard is the vertical distance between the bottom of the spillway and the crest of the dam), and structural deficiencies. As a single category, inadequate spillway capacity represents almost half of these deficiencies; it being judged by hydrologic standards related to a dam's "hazard" to the floodplain. The State Engineer's hydrologic requirements for spillway flood capacity range from the 100-year flood to the Probable Maximum Flood (PMF); any spillway capacity less than the PMF requiring demonstration that the overtopping failure of the dam will be insignificant on the floodplain. The number of leakage and piping problems increased again, especially for high hazard dams; the moderate and lows decreasing. There were significant decreases in other categories, however, such as inadequate spillways for high and moderate hazard dams, structural problems with high hazard dams, and stability problems with moderate and low hazard dams.

With inadequate spillways identified as a frequent deficiency concerning the safety of dams in Colorado, a large number of orders issued by the State Engineer to dam owners is the need to repair and enlarge spillways. For "inspection season" 1988, all dams are still being evaluated for hydrologic adequacy in accordance with the following policy: All dams must pass a 100-year flood with one foot of residual freeboard. For high and moderate hazard dams that cannot do this, the dam is restricted to a level that can handle the 100-year event, and an order issued to upgrade the spillway (to the PMF, if needed). For low hazard dams that cannot pass the 50-year flood, the dam is restricted to handle the 50-year event, and an order issued to upgrade the spillway (to at least the 100-year event). If a low hazard dam will pass the 50-year event but not the 100-year event, an order is issued to upgrade the spillway to the 100-year event. In each case, the owner has the alternative to partially or fully breach the dam. These policies will be applied until the revised rules and regulations are promulgated, upon which the hydrologic requirements will be enforced.

In cases where the restriction orders cannot be enforced during flooding due to inadequate outlet capacity, and the owner has not complied with the orders to rehabilitate the dam, orders are issued to partially breach the dam by cutting the spillway down to the restricted level. The work must be done under the supervision of a registered professional engineer, and the spillway must be able to pass the 100-year flood.

In the event the owner does not comply with any of the above orders, another order is issued to completely breach the dam. The breach must be of sufficient width to pass abnormal flood flows without surcharging the reservoir basin, by passing the 100-year event at less than five feet of depth.



Following is a list of dams which were breached during the fiscal year 87-88:

| <u>NAME</u>       | <u>COUNTY</u> | <u>DIV/DIST</u> | <u>DESCRIPTION</u>          |
|-------------------|---------------|-----------------|-----------------------------|
| Joe Vento         | El Paso       | 2/10            | To 7 ft below dam crest.    |
| Bergen #5         | Jefferson     | 1/9             | To 10 ft below dam crest.   |
| Citizens          | Mesa          | 4/41            | To 7 ft below dam crest.    |
| Pear              | Boulder       | 1/5             | Totally removed.            |
| Sandbeach         | Boulder       | 1/5             | Totally removed.            |
| Flickinger        | Saguache      | 3/26            | To 9.3 ft. below dam crest. |
| Brewer            | Adams         | 1/2             | Totally breached.           |
| Williams-McCreery | Morgan        | 1/1             | To 15 ft. above outlet.     |

#### USE OF APPROPRIATED FUNDS

The Legislature, for FY 87-88, budgeted \$836,559 for dam safety personal services. The Division of Water Resources allocated \$42,250 for both operating costs and for travel and subsistence to the Dam Safety Branch.

Dam Safety personal services expenditures for the fiscal year were \$823,827. Total operating and travel and subsistence expenditures were \$39,912. (No capital expenditures were made during the fiscal year.) In order to more effectively and efficiently administer the program, the State Engineer has transferred three field engineers to the division offices in Glenwood Springs, Montrose, and Durango. The engineer in Durango also supports the program in the Alamosa division office. Besides realizing a savings in travel costs to administer the program in these areas, another benefit being achieved is availability to the dam owners to assist them with the maintenance and repair of their dams.

#### RECEIPTS GENERATED FOR COSTS OF INSPECTION AND FILING OF PLANS

Fees collected by the State Engineer for dam safety were \$67,536.30 for safety inspections and construction observation, and \$4,180.34 for filing plans and specifications. Invoices totaling \$66,556.49 were issued for safety inspections during the period.

#### RULES AND REGULATIONS

No regulations were promulgated during the fiscal year. Existing rules and regulations promulgated in 1967 were in force. With the passage of HB-1052 (1984), and HB 1186 (1986), preparation of revised regulations is nearly complete. Due to the concern about the hydrologic requirements for spillways, resulting from criticisms of the National Weather Service's Hydrometeorological Report No. 55, which is a basis for the criteria, they were delayed. An Attorney General's opinion on the proposed criteria was also



needed before they could be completed. Upon completion of the final draft of regulations, public meetings were held in Delta, Alamosa, and Denver to receive input on the proposed rules. The proposed fiscal impact statement was filed with the Office of Regulatory Reform, and the notice of the hearing on the rule making was published in the Colorado Register. A prehearing conference was held on March 25, 1988, and the hearings were held from April 13 to 18, 1988. Substantial revisions were made to the rules based upon testimony from the hearings. The revisions were transmitted to the parties to the hearings on August 1, 1988, with final comments due by August 15, 1988. Several additional revisions were made, and the rules were adopted on August 26, 1988. They were published in the September 10, 1988, issue of the Colorado Register, and became effective on September 30, 1988.

The new regulations have reduced the size requirements for spillways by relating them to the dam's size and hazard class (lesser requirements for smaller dams). The cost for determining spillway adequacy should be less in most cases, and the cost of the spillways themselves should be less, without jeopardizing the public safety.

In order to safe guard life, health, and property, the design and construction of dams must be done by professional engineers who are certified to practice in accordance with the laws regulating the practice of professional engineering. The regulations require the use of engineers for the design and construction of dams where they constitute a significant hazard to life and property; the requirements for assuring safe design and construction, however, vary with the size and hazard class of the dam. For very low hazard dams, the dam owners will be able to repair their dams themselves, with assistance from the State Engineer.

The regulations also provide for the safety inspection of dams by the owner's engineer, where it is more expedient and beneficial to the owner. The manner in which fees are collected for safety inspections of dams was revised to lessen the daily charge to owners of dams who have more than one of their dams inspected the same day.

#### ENFORCEMENT ORDERS AND PROCEEDINGS

During the fiscal year, the State Engineer was involved in enforcement proceedings under Section 37-87-114 , C.R.S. (1973) (1986 Supp.). Following is a brief description of each case.

##### 1. Flickinger Reservoir Dam, Saguache County

Flickinger Dam is located on Ford Creek in the southwest quarter of Section 2, Township 45N, Range 6E, New Mexico P.M., in the vicinity of Saguache, Colorado. It is a 20-foot high, 15.5 acre-foot, low hazard dam.



While inspecting other dams in the area during 1980, it was discovered that this dam was constructed without having been approved by the State Engineer. On November 12, 1980, the State Engineer issued a restriction order to the owner, providing for a safe storage level 17 feet below the crest of the dam. The owner was ordered to retain the services of an engineer to conduct a hydrologic analysis of the drainage area and design a spillway for the dam which would handle a 100-year flood; to investigate the geotechnical properties of the embankment and analyze the stability of the dam; and to ascertain the integrity of the outlet works; and other administrative data such as capacity tables. The restriction remained in effect until 1986, when the outlet became plugged (under suspicious circumstances) and the reservoir filled to the spillway. No engineering analysis had been done as requested. In September of 1986, the State Engineer issued another order to the owner to either: breach the dam; rehabilitate the dam in accordance with the previous order; or reduce the height of the dam to nonjurisdictional size.

In March of 1987, the State Engineer learned that the owner was being foreclosed, and had filed for bankruptcy. A mortgage company intended taking control of the property. On May 1, 1987, the State Engineer issued another order to breach the dam at the spillway to a nonjurisdictional height and to unplug the outlet, with a due date of May 22, 1987, to notify him when the work would be done. After the due date passed without any response from the owner, the State Engineer requested the assistance of the Attorney General on June 8, 1987, to file an action in the District Court of Saguache County, pursuant to Section 37-87-114, C.R.S. (1973) (1986 Supp.), to have the court enforce the order. The complaint was filed on June 29, 1987, Case No. 87 CV 78.

Plans were submitted to open the outlet and modify the dam by lowering the spillway about nine feet. The plan was approved, and the work completed by April 19, 1988. The case was dismissed in the District Court on August 16, 1988.

## 2. Brewer Reservoir Dam, Adams County

Brewer Dam is located in the vicinity of Colorado Boulevard and East 104th Avenue, within the city limits of Thornton. It is a 20-foot high, 36 acre-foot, low hazard dam. On September 26, 1985, the State Engineer issued a zero storage restriction order due to the unsafe conditions at the dam, and the increased hazard conditions resulting from development downstream. The owner was directed to prepare plans for the rehabilitation of the dam, or have it breached. During July of 1986, large rainstorms in the area filled the reservoir to the point where Thornton city officials became concerned about the safety and an emergency response plan to patrol the dam by Thornton police was implemented. The owner subsequently began work to pump the reservoir down to the restricted level, but apparently due to poor communications with the contractor, many delays occurred. On August 27, 1986, the State Engineer issued an order to have the spillway enlarged by September 30, 1986, in order to protect the public safety during large rainstorms. Because the owner failed to comply with the order by the due date, the State Engineer requested the Attorney General on November 12, 1986, to initiate legal proceedings to have the order enforced. The Attorney General filed a complaint for



Preliminary and Permanent Injunction in District Court of Adams County on November 25, 1986, Case No. 86 CV 2742. The owner's attorney subsequently prepared a plan for breach of the dam, and upon approval by the State Engineer, proceeded to breach the dam, after a small delay, on July 15, 1987. The case was dismissed on October 14, 1987.

### 3. Douglas (Charles) Frost Dam, Park County

The Charles Frost dams are located in the Roland Valley Subdivision, adjacent to U.S. 285, about five miles east of Bailey in Park County.

The Frost dams are three of several "nonjurisdictional" dams less than 10 feet high which the Board of County Commissioners of Park County requested assistance to require spillways for in 1983 due to drainage problems caused by the dams. Upon complaint filed by the Attorney General for the State Engineer in the Division One Water Court, the judge ordered the owner on August 2, 1985, case no. 85CW40, to construct spillways and other provisions in accordance with plans approved by the State Engineer by August 30, 1985. In 1986, when the State Engineer was able to check the structures, it was determined that the dams were not in conformance with the court order. A hearing was requested and scheduled for January 22, 1987, in the Water Court of Water Division No. 1, where an order was issued for the water referee to determine whether the owner's dams were in reasonable compliance with the original order of August 2, 1985.

The referee conducted an inspection of the dams on June 15, 1987, and issued his findings on September 3, 1987. The referee found that the dams were not in compliance. Another meeting was held with the owner, his engineer, and attorney on November 24, 1987, where they were given directions on the repairs and modifications necessary to bring the dams into compliance. On December 21, 1987, we were notified that the work was completed and the case was closed on January 22, 1988.

#### EMERGENCY PREPAREDNESS PLANS

During the National Dam Safety Program's inspection and Phase I findings/recommendations on high hazard dams, the preparation and maintenance of plans to combat incidents at dams, and to give warning to the floodplain area downstream, became a common recommendation of the reviewing professional engineers. At the conclusion of the National Dam Safety Program in 1981, the State Engineer requested that all owners of high hazard dams prepare emergency preparedness plans and provided a guideline for them to follow.

As of June 30, 1988, a total of 131 plans for high hazard dams have been filed with the State Engineer, out of the 254 Federal and nonfederal high hazard dams on file. Of the 131, twenty-eight are for Federal dams, primarily of the Bureau of Reclamation. In addition, plans have been submitted for thirty-four moderate hazard dams (three Federal), and twenty-two low hazard dams (one Federal). During FY 88-89, the State Engineer plans to return comments on submitted EPP's to the owners for updating and to request the balance of the high hazard dam owners and the moderate hazard dam owners to prepare plans, and file them with the State Engineer in accordance with the regulations. The owners will also be requested to coordinate with the Division of Disaster Emergency Services and local disaster coordinators.



### DAM SAFETY DATA BASE MANAGEMENT SYSTEM

During FY 87-88, the Dam Safety Branch continued to enter data and make corrections to the data base, primarily being done by the several field engineers and a secretary. The FOCUS data base management software was acquired and installed in late June, 1986. It is being tested to learn its features and capabilities. Part of the data base (VS-300) was transferred to a dBase III format in the branches personal computer in order to prepare reports and print the headings for our inspection forms.

### EFFECTIVENESS OF PROGRAM

As expressed by the goals and objectives of the State Engineer, the program's effectiveness can be measured by the prevention of dam failures. No failures occurred during the period of the report. Another example of the effectiveness of the dam safety program is shown in the tables of causes for restriction and the restriction list in the appendix. The identification of the unsafe conditions at the several dams and reservoirs and the subsequent restrictions to safe storage levels, prevented inevitable failures of these structures and the costly consequences thereof. The enforcement of the State Engineer's orders also plays a role in assuring the effectiveness of the program. The combination of the State Engineer's safety inspections, restrictions to safe storage, follow-up inspections, Emergency Preparedness Plans, and programs to make the dam owners more knowledgeable about the safe operation and maintenance of their dams through the State Engineer's "Dam Safety Manual," makes Colorado's Dam Safety Program one of the most effective in the United States.

In order to make dam owners aware of the value of designing, constructing, and maintaining safe dams, the State Engineer's office sponsored a dam safety workshop in Delta, Colorado, on April 5, 1988. About one-hundred participants received valuable information from engineers and dam owners in the safe design of dams and their appurtenances, and the safe operation and maintenance of their dams. The State Engineer's office also sponsored a training session on Risk Based Assessment of the Repair of Dams for Engineers in the Denver Area.

### LEGISLATION

House Bill 1356 (Long Bill) removed one FTE from the branch, as well as the operating funds for three FTE. Footnotes to the bill requested that dam inspection efforts give priority to high and moderate hazard dams, and requiring that two supervisor level positions (in the branch) work half-time as dam inspectors.

The full impact of this has not been realized yet, but for fiscal year 87-88 it is expected that we will meet our inspection objectives as outlined previously. The loss of the operating funds, however, will place a severe strain on our ability to accomplish our objectives for inspection year 1989.



RECOMMENDED LEGISLATION

Program Funding

Increased funding is recommended for several areas of the dam safety program in order to maintain and improve it. One area is increased full time employees (FTE); one FTE for the Design Review Unit; and another FTE for the Dam Safety Branch's data base management system. Due to increased emphasis on safety inspections, one of the FTE's allocated to the Design Review Unit has been transferred back to the Field Engineering Units. However, the Design Review Unit has been assigned the responsibility to inspect the construction of the plans which they review. Another FTE is needed in Design Review in order to maintain the 180 day review time limit, and to assure quality design review.


With the transfer of the dams data base to the DNR WANG VS-300 computer (and the intent to place as much relevant data as possible into the system), in order to produce comprehensive management and report data, there is a need for an FTE to support the data base, the branch, and to achieve its objectives.

Rapid changes occur in the field of dam safety engineering and related disciplines. New designs of dams (and rehabilitation of dams) are utilizing new material whose behavior and properties are unknown to the staff, and several conferences are held throughout the country with the object of sharing knowledge and experience in the field of dam safety. It is proposed to establish a training plan to send our dam safety engineers to these training programs in order to maintain a knowledge of the state-of-the-art of dam safety. The estimated first year's cost for such a program would be about \$5,000.

Another area is the rental of "All-Terrain Vehicles (ATV)" and helicopters to allow fast and efficient access to many dams in remote areas. It is proposed to reserve about one-fourth of the helicopter time for emergency use. Estimated first year's cost for this program is \$30,000.



APPENDIX A  
PERSONNEL  
DAM SAFETY BRANCH



Field engineer position being used for design review and construction inspection:  
Position deleted in FY88-89



APPENDIX A  
PERSONNEL  
DAM SAFETY BRANCH

| <u>TITLE</u>                            | <u>NAME</u>      | <u>AREA OF</u>                                   |
|---|------------------|--|
| Principal Water Resource Eng.           | Alan Pearson     | Chief, Dam Safety Branch                         |
| Superv. Water Resource Eng.             | Steve Spann      | Chief, Design Review Unit                        |
| Senior Water Resource Eng.              | Louis DeGrave    | Design Review/Const. Insp. <sup>1</sup>          |
| Senior Water Resource Eng.              | Dennis Miller    | Design Review/Const. Insp.                       |
| Superv. Water Resource Eng.             | Gary Barta       | Chief, Field Eng. Unit - 1                       |
| Senior Water Resource Eng.              | Chin Lee         | Field Engineering Unit - 1                       |
| Senior Water Resource Eng. <sup>2</sup> | Brian Ahrens     | Field Engineering Unit - 1                       |
| Senior Water Resource Eng.              | Robert Campbell  | Field Engineering Unit - 1                       |
| Water Resource Eng C.                   | John Blair       | Field Engineering Unit - 1                       |
| Water Resource Eng C.                   | Michael Cola     | Field Engineering Unit - 1                       |
| Superv. Water Resource Eng.             | John Van Sciver  | Chief, Field Eng. Unit - 2                       |
| Senior Water Resource Eng.              | Jim Norfleet     | Field Engineering Unit - 2                       |
| Senior Water Resource Eng.              | William McIntyre | Field Engineering Unit - 2                       |
| Senior Water Resource Eng.              | Greg Hammer      | Field Engineering Unit - 2                       |
| Senior Water Resource Eng.              | Sally Lewis      | Field Engineering Unit - 2                       |
| Senior Water Resource Eng.              | Frank Kugel      | Field Engineering Unit - 2                       |
| Senior Admin. Clerk Typist              | Janice Dermer    | Typing, Word Processing,<br>Maintain File System |
| Senior Admin. Clerk Typist              | Chris Frederick  | Typing, Word Processing,<br>Maintain File System |

<sup>1</sup>Field Engineer position being used for Design Review and Construction Inspection.

<sup>2</sup>Position deleted in FY88-89



APPENDIX C  
WATER COMMISSIONER • DAM OBSERVATION REPORT • OFFICE OF THE STATE ENGINEER

APPENDIX B

APPROVED PLANS AND SPECIFICATIONS FOR NEW DAMS  
OR OLD DAMS NOT PREVIOUSLY APPROVED

| Name                  | Division/<br>District | "C" No. 1 | Use         | Date     |
|-----------------------|-----------------------|-----------|-------------|----------|
| Lily Lake             | 1/04                  | C-1666    | REC         | 07/17/87 |
| Jolly Ranch           | 1/01                  | C-1667    | STOCK       | 08/07/87 |
| Pinery No. 11         | 1/08                  | C-1668    | FLOOD DET   | 08/08/87 |
| Lost Lake #1          | 4/62                  | C-1669    | IRR         | 09/11/87 |
| Brewer Dam            | 1/02                  | C-1670    | BREACHED    | 09/23/87 |
| Hyatt                 | 1/07                  | C-1671    | IRR         | 12/15/87 |
| Kendall               | 5/72                  | C-1672    | REC         | 12/23/87 |
| Jasper                | 1/06                  | C-1673    | IRR/MUN/IND | 01/11/88 |
| Pagosa                | 7/29                  | C-1674    | MUN         | 01/11/88 |
| Teller                | 2/10                  | C-1675    | REC         | 01/15/88 |
| Monument Dam          | 4/40                  | C-1676    | IRR         | 02/09/88 |
| Holbrook              | 2/17                  | C-1677    | IRR/MUN/REC | 03/08/88 |
| Water Storage Pond #3 | 5/39                  | C-1678    | IND         | 04/21/88 |
| McCullough W.T.D. Dam | 2/10                  | C-1679    | STL         | 05/23/88 |
| Saddle Pond Dam       | 5/38                  | C-1680    | REC/IRR     | 06/15/88 |
| Augmentation Pond     | 1/09                  | C-1681    | DOM/REC     | 06/15/88 |

1 Filing system for approved plans (C-1651). Assigned to new dams, and existing dams without previously approved plans which are being altered, enlarged, or repaired.

LHD:ict:7402I



# APPENDIX B (continued)

## APPROVED PLANS AND SPECIFICATIONS FOR ALTERATIONS ENLARGEMENTS, OR REPAIR OF EXISTING DAMS

| Name               | Division/<br>District | "C" No. <sup>2</sup> | Use             | Date     |
|--------------------|-----------------------|----------------------|-----------------|----------|
| Chief Creek #4     | 1/65                  | C- 771E              | FSH             | 08/06/87 |
| Horse Creek        | 2/17                  | C-1329A              | IRR             | 08/03/87 |
| Pear Dam           | 1/05                  |                      | BREACHED        | 08/14/87 |
| Sand Beach Dam     | 1/05                  |                      | BREACHED        | 08/14/87 |
| Polly A. Dean      | 1/07                  | C- 538A              | IRR/MUN/REC/FSH | 08/17/87 |
| Beckwith           | 2/15                  | C- 63A               | MUN/IRR/REC     | 08/14/87 |
| Lower Chinns       | 1/07                  | C- 281A              | IRR/MUN         | 10/15/87 |
| Johnston Reservoir | 1/08                  | C-1397A              | IRR/REC         | 10/19/87 |
| Gurley             | 4/60                  | C- 460C              | REC/IRR/MUN/FSH | 11/30/87 |
| Lake Henry         | 2/17                  | C- 555B              | IRR             | 12/07/87 |
| Signal #1          | 1/02                  | C-1650A              | IRR/MUN         | 12/15/87 |
| Albion             | 1/06                  | C- 36A               | MUN             | 12/30/87 |
| Buffalo Creek      | 1/23                  | C-1539A              | AUG/REC         | 12/28/87 |
| Cattail Pond       | 1/04                  | C-1475A              | IRR             | 01/15/88 |
| Lake Brennand      | 4/40                  | C- 287B              | MUN/FSH/REC/IRR | 01/26/88 |
| Marston Reservoir  | 1/09                  | C- 970B              | MUN/REC         | 02/03/88 |
| Johnston Dam       | 7/30                  | C-1565A              | REC             | 02/23/88 |
| Milton Seaman      | 1/03                  | C- 385B              | IRR/MUN         | 02/23/88 |
| Goodhue No. 1      | 1/06                  | C- 318A              | REC             | 04/01/88 |
| Cotter Tailings    | 2/12                  | C-1526A              | IND             | 04/18/88 |
| Milton Lake        | 1/02                  | C-1471A              | IRR/MUN         | 05/23/88 |
| Bauer Lake #1      | 7/34                  | C- 368B              | IRR             | 05/23/88 |
| Trout Lake         | 4/60                  | C- 675B              | HYDRO/REC       | 05/27/88 |
| Ireland            | 1/01                  | C- 425B              | IRR/REC         | 05/23/88 |
| West #1            | 4/40                  | C- 545A              | IRR             | 05/31/88 |
| Cucaharas #5       | 2/16                  | C-1021B              | IRR             | 04/21/88 |

<sup>2</sup> Filing system for approved plans (C-1008A). Letters denote revisions to previously approved plans.

NOTE: Includes AS-CONSTRUCTED plans which were prepared after sketch plans or emergency actions were completed.

LHD:ict:7402I

DAM NAME  
DAM ID.  
OWNER  
ADDRESS  
CONTACT  
CLASS  
CURRENT  
FIELD  
COND  
OBSER

UPSTREAM  
SLOPE  
PR  
Crest  
PR  
DOWNSTREAM  
SLOPE  
PR  
SEEPAGE  
PR  
OUTLET  
PR  
SPILLWAY  
PR  
MAINTENANCE  
PR

The State Engineer, by providing this dam safety observation report, is not responsible for the safety of this dam rests with the reservoir owner or operator, who

0/86 JTS



# APPENDIX C WATER COMMISSIONER • DAM OBSERVATION REPORT • OFFICE OF THE STATE ENGINEER

DAM NAME \_\_\_\_\_ W. DIV. \_\_\_\_\_ W. DIST. \_\_\_\_\_ DATE OF INSPECTION \_\_\_\_/\_\_\_\_/\_\_\_\_

DAM ID \_\_\_\_\_ FILE NO. C \_\_\_\_\_ FOREST I.D. \_\_\_\_\_ DATE OF LAST INSPECTION \_\_\_\_/\_\_\_\_/\_\_\_\_

OWNER NAME \_\_\_\_\_ OWNER PHONE \_\_\_\_\_

ADDRESS \_\_\_\_\_ ZIP CODE \_\_\_\_\_

CONTACT NAME \_\_\_\_\_ CONTACT PHONE \_\_\_\_\_

CLASS \_\_\_\_\_ CAPACITY \_\_\_\_\_ AF SURFACE AREA \_\_\_\_\_ AC HEIGHT \_\_\_\_\_ FT. CREST LENGTH \_\_\_\_\_ FT CREST WIDTH \_\_\_\_\_ FT

CURRENT RESTRICTION ☐ (NO) ☐ (YES) LEVEL \_\_\_\_\_ EPP ON FILE ☐ (NO) ☐ (YES) SPWY WIDTH \_\_\_\_\_ FT. FBD. \_\_\_\_\_ FT. Z \_\_\_\_\_

FIELD CONDITIONS OBSERVED

WATER LEVEL: BELOW DAM CREST \_\_\_\_\_ FT. BELOW SPILLWAY \_\_\_\_\_ FT. GAGE ROD READING \_\_\_\_\_

GROUND MOISTURE CONDITION: DRY \_\_\_\_\_ WET \_\_\_\_\_ SNOWCOVER \_\_\_\_\_ OTHER \_\_\_\_\_

**DIRECTIONS: MARK AN X FOR CONDITIONS FOUND AND UNDERLINE WORDS THAT APPLY.**

|                  |  | Conditions Observed |            |      |
|------------------|--|---------------------|------------|------|
|                  |  | GOOD                | ACCEPTABLE | POOR |
| UPSTREAM SLOPE   | <b>PROBLEMS NOTED:</b> <input type="checkbox"/> (0) NONE <input type="checkbox"/> (1) RIPRAP - MISSING, SPARSE, DISPLACED, WEATHERED <input type="checkbox"/> (2) WAVE EROSION-WITH SCARPS<br><input type="checkbox"/> (3) CRACKS-WITH DISPLACEMENT <input type="checkbox"/> (4) SINKHOLE <input type="checkbox"/> (5) APPEARS TOO STEEP <input type="checkbox"/> (6) DEPRESSIONS OR BULGES <input type="checkbox"/> (7) SLIDES<br><input type="checkbox"/> (8) CONCRETE FACING-HOLES, CRACKS, DISPLACED, UNDERMINED <input type="checkbox"/> (9) OTHER _____  |                     |            |      |
| CREST            | <b>PROBLEMS NOTED:</b> <input type="checkbox"/> (10) NONE <input type="checkbox"/> (11) RUTS OR PUDDLES <input type="checkbox"/> (12) EROSION <input type="checkbox"/> (13) CRACKS - WITH DISPLACEMENT <input type="checkbox"/> (14) SINKHOLES<br><input type="checkbox"/> (15) NOT WIDE ENOUGH <input type="checkbox"/> (16) LOW AREA <input type="checkbox"/> (17) MISALIGNMENT <input type="checkbox"/> (18) IMPROPER SURFACE DRAINAGE<br><input type="checkbox"/> (19) OTHER _____   |                     |            |      |
| DOWNSTREAM SLOPE | <b>PROBLEMS NOTED:</b> <input type="checkbox"/> (20) NONE <input type="checkbox"/> (21) LIVESTOCK DAMAGE <input type="checkbox"/> (22) EROSION OR GULLIES <input type="checkbox"/> (23) CRACKS - WITH DISPLACEMENT <input type="checkbox"/> (24) SINKHOLE<br><input type="checkbox"/> (25) APPEARS TOO STEEP <input type="checkbox"/> (26) DEPRESSION OR BULGES <input type="checkbox"/> (27) SLIDE <input type="checkbox"/> (28) SOFT AREAS<br><input type="checkbox"/> (29) OTHER _____  |                     |            |      |
| SEEPAGE          | <b>PROBLEMS NOTED:</b> <input type="checkbox"/> (30) NONE <input type="checkbox"/> (31) SATURATED EMBANKMENT AREA <input type="checkbox"/> (32) SEEPAGE EXITS ON EMBANKMENT<br><input type="checkbox"/> (33) SEEPAGE EXITS AT POINT SOURCE <input type="checkbox"/> (34) SEEPAGE AREA AT TOE <input type="checkbox"/> (35) FLOW ADJACENT TO OUTLET <input type="checkbox"/> (36) SEEPAGE INCREASED/MUDDY<br>DRAIN OUTFALLS SEEN <input type="checkbox"/> No <input type="checkbox"/> Yes <input type="checkbox"/> (37) FLOW INCREASED/MUDDY <input type="checkbox"/> (38) DRAIN DRY/OBSTRUCTED<br><input type="checkbox"/> (39) OTHER _____                |                     |            |      |
| OUTLET           | <b>PROBLEMS NOTED:</b> <input type="checkbox"/> (40) NONE <input type="checkbox"/> (41) NO OUTLET FOUND <input type="checkbox"/> (42) POOR OPERATING ACCESS <input type="checkbox"/> (43) INOPERABLE<br><input type="checkbox"/> (44) UPSTREAM OR DOWNSTREAM STRUCTURE DETERIORATED <input type="checkbox"/> (45) OUTLET NOT OPERATED DURING INSPECTION<br>INTERIOR INSPECTED <input type="checkbox"/> (120) NO <input type="checkbox"/> (121) YES <input type="checkbox"/> (46) CONDUIT DETERIORATED OR COLLAPSED <input type="checkbox"/> (47) JOINTS DISPLACED <input type="checkbox"/> (48) VALVE LEAKAGE<br><input type="checkbox"/> (49) OTHER _____ |                     |            |      |
| SPILLWAY         | <b>PROBLEMS NOTED:</b> <input type="checkbox"/> (50) NONE <input type="checkbox"/> (51) NO EMERGENCY SPILLWAY FOUND <input type="checkbox"/> (52) EROSION-WITH BACKCUTTING <input type="checkbox"/> (53) CRACK - WITH DISPLACEMENT<br><input type="checkbox"/> (54) APPEARS TO BE STRUCTURALLY INADEQUATE <input type="checkbox"/> (55) APPEARS TOO SMALL <input type="checkbox"/> (56) INADEQUATE FREEBOARD <input type="checkbox"/> (57) FLOW OBSTRUCTED<br><input type="checkbox"/> (58) CONCRETE DETERIORATED/UNDERMINED <input type="checkbox"/> (59) OTHER _____   |                     |            |      |
| MAINTENANCE      | <b>PROBLEMS NOTED:</b> <input type="checkbox"/> (60) NONE <input type="checkbox"/> (61) ACCESS ROAD NEEDS MAINTENANCE <input type="checkbox"/> (62) CATTLE DAMAGE<br><input type="checkbox"/> (63) BRUSH ON UPSTREAM SLOPE, CREST, DOWNSTREAM SLOPE, TOE <input type="checkbox"/> (64) TREES ON UPSTREAM SLOPE, CREST, DOWNSTREAM SLOPE, TOE<br><input type="checkbox"/> (65) RODENT ACTIVITY ON UPSTREAM SLOPE, CREST, DOWNSTREAM SLOPE, TOE <input type="checkbox"/> (66) DETERIORATED CONCRETE-FACING, OUTLET, SPILLWAY<br><input type="checkbox"/> (67) GATE AND OPERATING MECHANISM NEED MAINTENANCE <input type="checkbox"/> (68) OTHER _____        |                     |            |      |

See Guidelines on Back of this Sheet

**DIRECTIONS: ENTER PROBLEM NUMBER ( ) THEN LOCATION DIMENSIONS, DEGREE, ETC.**

LOCATION OF PROBLEMS & COMMENTS: \_\_\_\_\_

**MAINTENANCE - MINOR REPAIR - MONITORING - ACTION REQUIRED OF OWNER TO IMPROVE THE SAFETY OF THE DAM.**

- ☐ (80) PROVIDE ADDITIONAL RIPRAP: \_\_\_\_\_
- ☐ (81) LUBRICATE AND OPERATE OUTLET GATES THROUGH FULL CYCLE: \_\_\_\_\_
- ☐ (82) CLEAR TREES AND/OR BRUSH FROM: \_\_\_\_\_
- ☐ (83) INITIATE RODENT CONTROL PROGRAM AND PROPERLY BACKFILL EXISTING HOLES: \_\_\_\_\_
- ☐ (84) GRADE CREST TO A UNIFORM ELEVATION WITH DRAINAGE TO THE UPSTREAM SLOPE: \_\_\_\_\_
- ☐ (85) PROVIDE SURFACE DRAINAGE FOR: \_\_\_\_\_
- ☐ (86) MONITOR: \_\_\_\_\_
- ☐ (88) OTHER: \_\_\_\_\_
- ☐ (89) OTHER: \_\_\_\_\_

DAM REQUIRES INSPECTION BY A FIELD ENGINEER ☐

☐ FIELD DIMENSIONS SHOWN ON BACK

OBSERVATION BY WATER COMMISSIONER

DATE

The State Engineer, by providing this dam safety observation report, does not assume responsibility for any unsafe condition of the dam subject to the sole responsibility of the dam owner or operator, who should take every step necessary to prevent damages caused by leakage or overflow of waters from the reservoir or floods resulting from a failure of the dam.



## APPENDIX D

## ENGINEERS INSPECTION REPORT

OFFICE OF THE STATE ENGINEER-DIVISION OF WATER RESOURCES - DAM SAFETY BRANCH  
1313 Sherman Street, Room 818, Denver, CO 80203. (303) 866-3581

DAM NAME \_\_\_\_\_ W. DIV. \_\_\_\_\_ W. DIST. \_\_\_\_\_ DATE OF INSPECTION \_\_\_\_/\_\_\_\_/\_\_\_\_

DAM ID \_\_\_\_\_ FILE NO. C- \_\_\_\_\_ FOREST I.D. \_\_\_\_\_ DATE OF LAST INSPECTION \_\_\_\_/\_\_\_\_/\_\_\_\_

OWNER NAME \_\_\_\_\_ OWNER PHONE \_\_\_\_\_

ADDRESS \_\_\_\_\_ ZIP CODE \_\_\_\_\_

CONTACT NAME \_\_\_\_\_ CONTACT PHONE \_\_\_\_\_

CLASS \_\_\_\_\_ CAPACITY \_\_\_\_\_ AF SURFACE AREA \_\_\_\_\_ AC. HEIGHT \_\_\_\_\_ FT. CREST LENGTH \_\_\_\_\_ FT. CREST WIDTH \_\_\_\_\_ FT.

CURRENT RESTRICTION ☐ (NO) ☐ (YES) LEVEL \_\_\_\_\_ EPP ON FILE ☐ (NO) ☐ (YES) SPWY WIDTH \_\_\_\_\_ FT. FBD. \_\_\_\_\_ FT. Z \_\_\_\_\_

INSPECTION PARTY REPRESENTING \_\_\_\_\_

**DIRECTIONS:** MARK AN X FOR CONDITIONS FOUND AND UNDERLINE WORDS THAT APPLY. GIVE LOCATION AND EXTENT WITH NUMBER REFERENCE I.E. (25) ALL ALONG SLOPE, OR SHOW IT ON SKETCH.

## FIELD CONDITIONS OBSERVED

WATER LEVEL - BELOW DAM CREST \_\_\_\_\_ FT., BELOW SPILLWAY \_\_\_\_\_ FT., GAGE ROD \_\_\_\_\_

GROUND MOISTURE CONDITION: DRY \_\_\_\_\_ WET \_\_\_\_\_ SNOWCOVER \_\_\_\_\_ OTHER \_\_\_\_\_

PROBLEMS NOTED: ☐ (0) NONE ☐ (1) RIPRAP - MISSING, SPARSE, DISPLACED, WEATHERED ☐ (2) WAVE EROSION-WITH SCARPS

☐ (3) CRACKS-WITH DISPLACEMENT ☐ (4) SINKHOLE ☐ (5) APPEARS TOO STEEP ☐ (6) DEPRESSIONS OR BULGES ☐ (7) SLIDES

☐ (8) CONCRETE FACING-HOLES, CRACKS, DISPLACED, UNDERMINED ☐ (9) OTHER \_\_\_\_\_

Comments: \_\_\_\_\_

PROBLEMS NOTED: ☐ (10) NONE ☐ (11) RUTS OR PUDDLES ☐ (12) EROSION ☐ (13) CRACKS - WITH DISPLACEMENT ☐ (14) SINKHOLES

☐ (15) NOT WIDE ENOUGH ☐ (16) LOW AREA ☐ (17) MISALIGNMENT ☐ (18) INADEQUATE SURFACE DRAINAGE

☐ (19) OTHER \_\_\_\_\_

Comments: \_\_\_\_\_

PROBLEMS NOTED: ☐ (20) NONE ☐ (21) LIVESTOCK DAMAGE ☐ (22) EROSION OR GULLIES ☐ (23) CRACKS - WITH DISPLACEMENT ☐ (24) SINKHOLE

☐ (25) APPEARS TOO STEEP ☐ (26) DEPRESSION OR BULGES ☐ (27) SLIDE ☐ (28) SOFT AREAS ☐ (29) OTHER \_\_\_\_\_

Comments: \_\_\_\_\_

PROBLEMS NOTED: ☐ (30) NONE ☐ (31) SATURATED EMBANKMENT AREA ☐ (32) SEEPAGE EXITS ON EMBANKMENT

☐ (33) SEEPAGE EXITS AT POINT SOURCE ☐ (34) SEEPAGE AREA AT TOE ☐ (35) FLOW ADJACENT TO OUTLET ☐ (36) SEEPAGE INCREASED/MUDDY

DRAIN OUTFALLS SEEN ☐ No ☐ Yes ☐ (37) FLOW INCREASED/MUDDY ☐ (38) DRAIN DRY/OBSTRUCTED

☐ (39) OTHER \_\_\_\_\_ Show location of drains on sketch and indicate amount and quality of discharge.

Comments: \_\_\_\_\_

PROBLEMS NOTED: ☐ (40) NONE ☐ (41) NO OUTLET FOUND ☐ (42) POOR OPERATING ACCESS ☐ (43) INOPERABLE

☐ (44) UPSTREAM OR DOWNSTREAM STRUCTURE DETERIORATED ☐ (45) OUTLET NOT OPERATED DURING INSPECTION

INTERIOR INSPECTED ☐ (120) NO ☐ (121) YES ☐ (46) CONDUIT DETERIORATED OR COLLAPSED ☐ (47) JOINTS DISPLACED ☐ (48) VALVE LEAKAGE

☐ (49) OTHER \_\_\_\_\_

Comments: \_\_\_\_\_

PROBLEMS NOTED: ☐ (50) NONE ☐ (51) NO EMERGENCY SPILLWAY FOUND ☐ (52) EROSION-WITH BACKCUTTING ☐ (53) CRACK - WITH DISPLACEMENT

☐ (54) APPEARS TO BE STRUCTURALLY INADEQUATE ☐ (55) APPEARS TOO SMALL ☐ (56) INADEQUATE FREEBOARD ☐ (57) FLOW OBSTRUCTED

☐ (58) CONCRETE DETERIORATED/UNDERMINED ☐ (59) OTHER \_\_\_\_\_

Comments: \_\_\_\_\_

## Conditions Observed

|                |            |      |
|----------------|------------|------|
| GOOD           | ACCEPTABLE | POOR |
| UPSTREAM SLOPE |            |      |

|       |            |      |
|-------|------------|------|
| GOOD  | ACCEPTABLE | POOR |
| CREST |            |      |

|                  |            |      |
|------------------|------------|------|
| GOOD             | ACCEPTABLE | POOR |
| DOWNSTREAM SLOPE |            |      |

|         |            |      |
|---------|------------|------|
| GOOD    | ACCEPTABLE | POOR |
| SEEPAGE |            |      |

|        |            |      |
|--------|------------|------|
| GOOD   | ACCEPTABLE | POOR |
| OUTLET |            |      |

|          |            |      |
|----------|------------|------|
| GOOD     | ACCEPTABLE | POOR |
| SPILLWAY |            |      |

See Guidelines on Back of this Sheet



## APPENDIX D

DAM NAME: \_\_\_\_\_ DAM I.D.: \_\_\_\_\_ DATE: \_\_\_\_/\_\_\_\_/\_\_\_\_

|                        |   |                            |                         |
|------------------------|---|----------------------------|-------------------------|
| MONITORING             | EXISTING INSTRUMENTATION FOUND <input type="checkbox"/> (110) NONE <input type="checkbox"/> (111) GAGE ROD <input type="checkbox"/> (112) PIEZOMETERS <input type="checkbox"/> (113) SEEPAGE WEIRS/FLUMES | GOOD<br>ACCEPTABLE<br>POOR | MONITORING              |
|                        | <input type="checkbox"/> (114) SURVEY MONUMENTS <input type="checkbox"/> (115) OTHER _____  |                            |                         |
| MAINTENANCE AND REPAIR | MONITORING OF INSTRUMENTATION: <input type="checkbox"/> (116) NO <input type="checkbox"/> (117) YES PERIODIC INSPECTIONS BY: <input type="checkbox"/> (118) OWNER <input type="checkbox"/> (119) ENGINEER | GOOD<br>ACCEPTABLE<br>POOR | MAINTENANCE AND REPAIRS |
|                        | Comments: _____   |                            |                         |
| OVERALL CONDITIONS     | PROBLEMS NOTED: <input type="checkbox"/> (60) NONE <input type="checkbox"/> (61) ACCESS ROAD NEEDS MAINTENANCE <input type="checkbox"/> (62) CATTLE DAMAGE  | GOOD<br>ACCEPTABLE<br>POOR | OVERALL CONDITIONS      |
|                        | <input type="checkbox"/> (63) BRUSH ON UPSTREAM SLOPE, CREST, DOWNSTREAM SLOPE, TOE <input type="checkbox"/> (64) TREES ON UPSTREAM SLOPE, CREST, DOWNSTREAM SLOPE, TOE                                   |                            |                         |
| OVERALL CONDITIONS     | <input type="checkbox"/> (65) RODENT ACTIVITY ON UPSTREAM SLOPE, CREST, DOWNSTREAM SLOPE, TOE <input type="checkbox"/> (66) DETERIORATED CONCRETE-FACING, OUTLET, SPILLWAY                                | GOOD<br>ACCEPTABLE<br>POOR | OVERALL CONDITIONS      |
|                        | <input type="checkbox"/> (67) GATE AND OPERATING MECHANISM NEED MAINTENANCE <input type="checkbox"/> (68) OTHER _____   |                            |                         |
| OVERALL CONDITIONS     | Comments: _____   | GOOD<br>ACCEPTABLE<br>POOR | OVERALL CONDITIONS      |
|                        | REMARKS: _____  |                            |                         |
| OVERALL CONDITIONS     | Based on this Safety Inspection and recent file review, the overall condition is determined to be:  | GOOD<br>ACCEPTABLE<br>POOR | OVERALL CONDITIONS      |
|                        | <input type="checkbox"/> 71 SATISFACTORY <input type="checkbox"/> 72 CONDITIONALLY SATISFACTORY <input type="checkbox"/> 73 UNSATISFACTORY  |                            |                         |

### ITEMS REQUIRING ACTION BY OWNER TO IMPROVE THE SAFETY OF THE DAM

#### MAINTENANCE - MINOR REPAIR - MONITORING

- ☐ (80) PROVIDE ADDITIONAL RIPRAP: \_\_\_\_\_
- ☐ (81) LUBRICATE AND OPERATE OUTLET GATES THROUGH FULL CYCLE: \_\_\_\_\_
- ☐ (82) CLEAR TREES AND/OR BRUSH FROM: \_\_\_\_\_
- ☐ (83) INITIATE RODENT CONTROL PROGRAM AND PROPERLY BACKFILL EXISTING HOLES: \_\_\_\_\_
- ☐ (84) GRADE CREST TO A UNIFORM ELEVATION WITH DRAINAGE TO THE UPSTREAM SLOPE: \_\_\_\_\_
- ☐ (85) PROVIDE SURFACE DRAINAGE FOR: \_\_\_\_\_
- ☐ (86) MONITOR: \_\_\_\_\_
- ☐ (87) DEVELOP AND SUBMIT AN EMERGENCY PREPAREDNESS PLAN: \_\_\_\_\_
- ☐ (88) OTHER: \_\_\_\_\_
- ☐ (89) OTHER: \_\_\_\_\_

#### ENGINEERING - EMPLOY AN ENGINEER EXPERIENCED IN DESIGN AND CONSTRUCTION OF DAMS TO: (Plans & Specification must be approved by State Engineer prior to construction.)

- ☐ (90) PREPARE PLANS AND SPECIFICATIONS FOR THE REHABILITATION OF THE DAM: \_\_\_\_\_
- ☐ (91) PREPARE AS-BUILT DRAWINGS OF: \_\_\_\_\_
- ☐ (92) PERFORM A GEOTECHNICAL INVESTIGATION TO EVALUATE THE STABILITY OF THE DAM: \_\_\_\_\_
- ☐ (93) PERFORM A HYDROLOGIC STUDY TO DETERMINE REQUIRED SPILLWAY SIZE: \_\_\_\_\_
- ☐ (94) PREPARE PLANS AND SPECIFICATIONS FOR AN ADEQUATE SPILLWAY: \_\_\_\_\_
- ☐ (95) SET UP A MONITORING SYSTEM INCLUDING WORK SHEETS, REDUCED DATA AND GRAPHED RESULTS: \_\_\_\_\_
- ☐ (96) PERFORM AN INTERNAL INSPECTION OF THE OUTLET: \_\_\_\_\_
- ☐ (97) OTHER: \_\_\_\_\_
- ☐ (98) OTHER: \_\_\_\_\_
- ☐ (99) OTHER: \_\_\_\_\_

#### SAFE STORAGE LEVEL RECOMMENDED AS A RESULT OF THIS INSPECTION

- ☐ (101) FULL STORAGE
- ☐ (102) CONDITIONAL FULL STORAGE RESTRICTED LEVEL OFFICIAL ORDER TO FOLLOW
- ☐ (103) RECOMMENDED RESTRICTION
- \_\_\_\_\_ FT. BELOW DAMS CREST
- \_\_\_\_\_ FT. BELOW SPILLWAY CREST
- \_\_\_\_\_ FT. GAGE HEIGHT
- \_\_\_\_\_ NO STORAGE-MAINTAIN OUTLET FULLY OPEN

REASON FOR RESTRICTION: \_\_\_\_\_

ACTIONS REQUIRED FOR CONDITIONAL FULL STORAGE OR CONTINUED STORAGE AT THE RESTRICTED LEVEL: \_\_\_\_\_

Engineer's Signature \_\_\_\_\_ Owner's Signature \_\_\_\_\_ DATE: \_\_\_\_/\_\_\_\_/\_\_\_\_



## APPENDIX E

DAM SAFETY BRANCH  
CURRENT RESTRICTIONS<sup>1</sup>

JUNE 30, 1988

## DIVISION ONE

| NAME                     | DIST. | AMOUNT  | DATE     | REASON   | HAZARD | APPROX.<br>STG. LOST<br>ACRE-FOOT |
|--------------------------|-------|---|----------|--|--------|-----------------------------------|
| A-20                     | 2     | 5' below crest                                    | 11/27/85 | Poor overall condition   | M      | 30                                |
| Adams & Bunker #3        | 1     | 6' below crest                                    | 5/22/75  | Inadequate freeboard, high seepage   | L      | 150                               |
| Adrian Pond              | 4     | 8' below crest                                    | 12/3/86  | No spillway  | L      | 18                                |
| Akers & Tarr             | 5     | 7' below crest                                    | 2/17/83  | Sloughing on downstream slope  | M      | 95                                |
| Allis                    | 8     | 11.5' below crest                                 | 5/03/85  | Spillway prone to erosion  | M      | 80                                |
| Angel Lake               | 3     | 8' below crest                                    | 2/21/78  | Poor condition   | L      | 309                               |
| Antero                   | 23    | G.H. 18.0   | 2/04/86  | Stab. berm const. & new instrumen.<br>monitoring                                       | H      | 5,100                             |
| Badding/Croke 12<br>West | 7     | 11' below embank-<br>ment crest                   | 12/30/83 | Lack of maint. & repair; no serv.<br>spwy.; no invest. of seepage<br>situation, no EPP | H      | 751                               |
| Beaver Brook #2          | 7     | 3' below crest                                    | 8/26/85  | Inadequate spwy., maint.   | H      | 2                                 |
| Beaver Brook #3          | 7     | 4' below spillway                                 | 6/11/87  | Low area in crest, inadequate spwy.  | M      |                                   |
| Beaver Brook #3A         | 7     | 15' below crest                                   | 9/17/85  | Seepage high on embankment   | H      | 48                                |
| Beaver Park              | 5     | 5' below spillway                                 | 11/8/84  | Inadequate spillway  | H      | 570                               |
| Bergen #2                | 9     | 10' below crest                                   | 4/30/84  | Cracks in crest; inadequate<br>spillway  | H      | 209                               |
| **Bergen West            | 09    | 30 acre-feet                                      | 05/10/88 | Piping of dam  | M      |                                   |
| Bijou #2                 | 1     | G.H. 15 ft.                                       | 5/16/83  | Erosion on upstream slope  | M      | 470                               |
| Bluebird                 | 5     | No storage  | 11/21/74 | Poor condition   | M      | 966                               |
| Box Elder #3             | 3     | 5' below outlet                                   | 10/10/84 | No emergency spillway  | L      | 150                               |
| Bright View #1           | 2     | 7' below crest                                    | 9/30/85  | Inoperable outlet, inadequate frbd.  | L      | 17                                |
| Camp Shoshoni            | 6     | 3' below crest                                    | 6/12/87  | Inadequate freeboard   | L      | 4                                 |
| Cantrill                 | 8     | G.H. 0.0  | 10/22/87 | No spillway, inoperable outlet   | L      | 64                                |
| Carlin                   | 2     | 5' below crest                                    | 3/21/86  | No spillway  | L      | 0                                 |
| Carmody                  | 9     | 3' below crest                                    | 4/30/84  | No spillway  | M      | 0                                 |
| Chambers                 | 3     | No storage above<br>gage 45' more<br>than 30 days | 11/22/78 | Excessive seepage over gage 45   | H      | 0                                 |
| Clarks Lake              | 3     | G.H. 5 ft.  | 4/23/84  | Poor condition   | M      | 338                               |
|                          |       |   |          |  |        | 9,371.0                           |

<sup>1</sup>Total Storage Lost - 132,628.50

\*Restrictions imposed this month

\*\*Restrictions removed this month (date)

+Revised existing restrictions



Division One (cont.)

| <u>NAME</u>    | <u>DIST.</u> | <u>AMOUNT</u>              | <u>DATE</u> | <u>REASON</u>   | <u>HAZARD</u> | <u>APPROX.<br/>STG. LOST<br/>ACRE-Feet</u> |
|----------------|--------------|----------------------------|-------------|---|---------------|--|
| Clennon        | 5            | 6' below crest             | 7/11/85     | Eroded and scarped u/s slope and eroded crest.  | M             | 25   |
| Comanche       | 3            | G.H. 25                    | 7/24/87     | Sand boils in outlet discharge channel & inadequate spillway                                | H             | 340  |
| Cooke          | 1            | 5' below crest             | 3/20/74     | Deteriorated conditions   | L             | 75   |
| Croke #12 East | 7            | 4' below emerg. spillway   | 6/01/84     | Leakage from outlet pipe, sinkholes & depressions above outlet pipe                         | M             | 44   |
| Crystal        | 5            | 5' below crest at outlet   | 4/17/85     | Excessive seep. erosion of u/s slope, no spwy., brush, trees, and slough areas on d/s slope | M             | 50   |
| Curtis         | 3            | G.H. 10'                   | 7/2/85      | Irr. narrow crst, eroded unprotected u/s slope, exten. seep. area below d/s toe.            | M             | 173  |
| D. A. Lord #4  | 1            | 7' below crest             | 2/10/76     | Inadequate spillway - seepage   | L             | 450  |
| Davis          | 5            | 3' below crest             | 10/21/87    | Inadequate freeboard  | L             | 40   |
| Davis 1, 2, 3  | 80           | 10' below crest            | 9/13/84     | Inadequate emergency spillways  | L             | 10   |
| Derby          | 2            | 14.5' below crest          | 2/5/85      | Inadequate Spillway   | M             | 400  |
| Dixon Canyon   | 3            | 6' below crest             | 4/13/84     | Erosion of u/s slope, sliding of d/s slope, lack of maintenance                             | M             | 195  |
| Dry Creek      | 3            | 6' below crest             | 3/27/84     | Outlet deter., u/s face erosion seep. d/s slope cracking                                    | L             | 125  |
| Duck           | 65           | 4' below spillway          | 3/23/87     | Narrow crest, steep slopes  | L             | 15   |
| Eaton Law      | 3            | 6' below crest             | 1/3/77      | Questionable condition of outlet  | M             | 200  |
| Elder          | 3            | 8.5' below crest           | 10/20/81    | Inadequate spillway   | H             | 264  |
| Empire         | 1            | No storage above G.H. 29.0 | 7/9/84      | Excess seepage and no spillway  | H             | 6,000                                      |
| Erie           | 6            | 3.0' below crest           | 06/02/86    | Insufficient freeboard  | M             | 29   |
| Fairport       | 4            | 6' below spillway          | 6/22/87     | Poor condition  | L             | 30   |
| Florissant     | 23           | No storage                 | 5/21/73     | Spillway failed; dam breached   | L             | 20   |
| Foothills      | 5            | G.H. 41.0 ft.              | 5/20/86     | Excessive leakage   | H             | 450  |
| Geist/aka/B-22 | 3            | 5' below crest             | 1/27/84     | Erosion, seep., inad. spwy. no acceptable outlet  | L             | 57.5                                       |
| Gerlits        | 8            | No storage                 | 11/13/84    | Dam partially breached due to overtopping   | L             | 10   |
| Gray #3        | 3            | 2' below spillway          | 3/11/83     | Severe erosion u/s slope  | M             | 200  |
| Green Lake #1  | 6            | 13.5' below crest          | 10/12/84    | Seepage, no spillway  | L             | 30   |
| Green Lake #3  | 6            | 3' below crest             | 10/8/84     | Leaks, inadequate spwy. freeboard   | L             | 60   |
| Hanshaw        | 65           | 5' below crest             | 7/7/87      | Seepage, slide  | L             | 20   |

9,312.5



Division One (cont.)

| <u>NAME</u>                 | <u>DIST.</u> | <u>AMOUNT</u>     | <u>DATE</u> | <u>REASON</u>  | <u>HAZARD</u> | <u>APPROX.<br/>STG. LOST<br/>ACRE-FOOT</u> |
|-----------------------------|--------------|-------------------|-------------|--|---------------|--|
| Havana Street               | 2            | No storage        | 1/2/87      | No spillway  | L             | 75   |
| Haystack #1                 | 9            | No storage        | 5/8/87      | Spillway undermined  | L             | 3  |
| Henry                       | 2            | No storage        | 1/2/87      | Piping into outlet, no spillway  | L             | 100  |
| Highland                    | 5            | 4' below crest    | 3/7/77      | Inadequate freeboard   | L             | 90   |
| Hoder                       | 8            | 4' below spillway | 9/14/87     | Inadequate spillway with<br>backcutting, seepage   | L             | 20   |
| Hourglass                   | 3            | 9.5' below crest  | 10/27/75    | Excessive seepage  | H             | 259  |
| Hyatt                       | 7            | 8' below crest    | 5/8/84      | Seepage d/s of toe and continual<br>pressure on outlet pipe                              | M             | 360  |
| Idaho Springs               | 7            | 9' below crest    | 7/9/84      | Freeboard, leakage, depression spot  | M             | 59   |
| Ide & Starbird #1           | 5            | 3' below crest    | 7/3/85      | Poor maintenance, eroded u/s face<br>questionable spillway                               | M             |  |
| Jasper                      | 6            | Zero storage      | 1/8/88      | Inadequate spillway; leakage   | H             | 376  |
| John Law                    | 3            | 3' below crest    | 6/27/86     | Inadequate freeboard & spillway  | L             | 20   |
| Johnson/aka<br>Hohnholtz #3 | 48           | 5' below crest    | 7/24/86     | Erosion on u/s face, lack of<br>proper freeboard, seepage<br>along d/s toe.              | L             | 88   |
| Julesburg                   | 64           | G.H. 23.0         | 6/13/88     | Seepage at toe dam #2  | H             | 6000                                       |
| Kalcevic                    | 7            | 11' below crest   | 2/10/83     | Sloughing on upstream slope  | H             | 69   |
| Kelly                       | 7            | 3' below crest    | 12/5/86     | No spwy, inad. outlet construction   | L             | 30   |
| Knoth                       | 5            | Zero storage      | 12/24/85    | Never completed dam  | L             | 204  |
| Lake Loveland               | 4            | 8.0' below crest  | 6/27/85     | Deteriorated outlet, no spillway   | H             | 1,000                                      |
| Lambert                     | 8            | 8' below crest    | 7/10/84     | Large slide, abandoned outlet  | L             | 50   |
| Leyden                      | 7            | 8' below crest    | 5/29/74     | Inadequate spillway, unstable<br>embankment  | M             | 207  |
| Lilly Lake                  | 4            | 3.5' below crest  | 10/9/85     | Spillway too small   | M             | 5  |
| Little Gem                  | 5            | 10' below crest   | 10/11/85    | Erosion on u/s slope & crest<br>& trees on u/s slope                                     | L             | 60   |
| Louisville #1               | 6            | 5.5' below crest  | 6/28/85     | Excessive seepage<br>This is a seasonal restriction<br>between the months of 10/1 & 4/30 | M             |  |
| Lower Chinns                | 7            | 7' below crest    | 11/13/84    | Excessive seepage in vicinity<br>of outlet   | L             | 14   |
| Lower Cochran               | 9            | 4.5' below crest  | 5/22/86     | Poor condition of upstream slope   | L             | 2  |
| Lower Long Lake             | 7            | 5' below crest    | 6/21/85     | Poor condition of upstream face<br>and crest, no spillway                                | M             | 52   |
| McLain                      | 23           | 3' below crest    | 7/7/87      | Slip on upstream slope   | L             | 6  |
| Magnusun #1                 | 23           | 8' below crest    | 12/4/85     | Provide adequate freeboard   | L             | 18   |

9,167.0



Division One (cont.)

|      | <u>NAME</u>                      | <u>DIST.</u> | <u>AMOUNT</u>                  | <u>DATE</u> | <u>REASON</u>   | <u>HAZARD</u> | <u>APPROX.<br/>STG. LOST<br/>ACRE-FEET</u> |
|------|----------------------------------|--------------|--------------------------------|-------------|---|---------------|--|
| 75   | Mountain                         | 23           | 4' below crest                 | 11/06/85    | Insufficient freebd., seepage @ toe                             | L             | 3  |
| 3    | Mountain Supply #8               | 3            | No storage                     | 10/3/78     | Poor condition  | L             | 643  |
| 00   | North Poudre #1                  | 3            | 7' below crest                 | 5/2/84      | Poor u/s slope, decaying tree stumps, deteriorated riprap       | M             | 106  |
| 90   | North Poudre #2                  | 3            | G.H. 18 ft.                    | 5/15/84     | Concentrated seep, questions concerning abandoned outlet        | H             | 985  |
| 20   | North Poudre #4                  | 3            | G.H. 17 ft.                    | 4/25/84     | Poor u/s face, general condition                                | M             | 265  |
| 59   | North Poudre #5                  | 3            | 5.5' below spillway            | 12/12/78    | Seepage instability   | H             | 2,375                                      |
| 60   | North Poudre #6                  | 3            | G.H. 9 ft.                     | 1/21/83     | Inadequate spillway, outlet, riprap                             | H             | 4,567                                      |
| 59   | North Poudre #17                 | 3            | 15' below crest after repaired | 7/15/83     | Poor condition, outlet  | M             | 600  |
|      | Oberon #1 (Lower) aka/ Hays Lake | 7            | No storage                     | 6/8/85      | Inadequate spwy., inoperable & disintegrating outlets.          | M             | 54   |
| 76   | Ohio Lake                        | 2            | 5' below crest                 | 5/14/84     | Erosion on u/s slope, rodent activity, lack of maintenance      | M             | 0  |
| 20   | Park Creek #2                    | 3            | 8' below crest                 | 10/3/84     | Generally poor condition, seepage                               | M             | 10   |
| 88   | Pear                             | 5            | No storage                     | 11/21/74    | Poor condition  | L             | 420  |
| 00   | Pennock Creek/aka/ Twin Lakes    | 3            | Zero storage                   | 1/22/86     | Deteriorated outlet, etc.                                       | M             | 278  |
| 69   | Peterson                         | 3            | 12.6' below principal spillway | 8/16/82     | Excessive uplift at toe   | H             | 246  |
| 30   | Polly Deane                      | 9            | 6.5' below crest               | 4/30/84     | Erosion of upstream slope, poor general condition               | M             | 57   |
| 00   | Prospect                         | 1            | G.H. 35.5 ft.                  | 4/15/80     | Post-failure monitor; cracking on d/s slope                     | M             | 720  |
| 50   | Quick                            | 8            | G.H. 0.0                       | 10/22/87    | No spillway, inoperable outlet                                  | L             | 37   |
| 07   | Rainbow Falls #5                 | 8            | 9' below crest                 | 9/11/85     | Inadequate spillway   | L             | 25   |
| 5    | Richards                         | 2            | 6' below crest                 | 12/22/83    | Erosion, narrow crest, seepage, plugged outlet, etc.            | L             | 140  |
| 60   | Rist Canyon                      | 3            | 3' below crest                 | 4/19/83     | Poor condition  | L             | 30   |
|      | Rist George                      | 4            | Gage 10.8                      | 7/18/85     | Dilapidated condition, no spwy.                                 | M             | 200  |
|      | Riverside                        | 1            | G.H. 33.55 ft.                 | 5/9/84      | Prevent overfilling of reservoir                                | H             | 0  |
| 14   | Rockwell Dam                     | 4            | 8' below crest                 | 6/8/72      | Poor riprap, no access to outlet control                        | L             | 62   |
| 2    | Ryan Gulch                       | 4            | 8' below crest                 | 2/15/78     | Inadequate spillway and leakage                                 | M             | 217  |
| 52   | Sandbeach                        | 5            | No storage                     | 2/7/83      | Poor condition  | M             | 297  |
| 6    | Section 19 Res.                  | 6            | 4' below crest                 | 7/24/84     | No spillway   | N             | 10   |
| 18   | Signal #1                        | 2            | 10' below crest                | 5/25/84     | Concentrated seepage areas and questionable condition of outlet | L             | 100  |
| 67.0 | Southside                        | 4            | 8' below crest                 | 7/7/78      | Inadequate spillway   | M             | 144  |

12,591.0



APPROX.  
STG. LOST  
ACRE-FEET



**DAM SAFETY BRANCH  
CURRENT RESTRICTIONS**

**JUNE 30, 1988**

**DIVISION TWO**

| <u>NAME</u>                  | <u>DIST.</u> | <u>AMOUNT</u>  | <u>DATE</u> | <u>REASON</u>  | <u>HAZARD</u> | <u>APPROX.<br/>STG. LOST<br/>ACRE-FEET</u> |
|------------------------------|--------------|--|-------------|--|---------------|--|
| Browning & Reese #1          | 17           | Zero storage   | 12/28/87    | Generally poor condition; inoperable outlet              | L             | 383  |
| Browning & Reese #2          | 17           | Zero storage   | 12/28/87    | Generally poor condition; inoperable outlet              | L             | 100  |
| Calahan                      | 10           | 8' below crest   | 12/6/84     | Saturated downstream slope                               | L             | 180  |
| Cripple Creek #3             | 12           | 6' below crest   | 6/27/83     | Inadequate spillway                                      | L             | 112  |
| Cudahy #1                    | 17           | 5' below crest   | 7/15/85     | Outlet disrepair   | L             | 900  |
| Cucharas #5                  | 16           | 85' below crest  | 3/25/88     | Damage to u/s face which would permit undesirable damage | H             | 49   |
| Evans Gulch                  | 11           | 3' below crest   | 9/14/84     | Insufficient freeboard                                   | L             | 2  |
| Evans Gulch #2               | 11           | 1.5' below spillway  | 9/14/84     | Insufficient freeboard                                   | M             | 39   |
| Gagliardi, Mike              | 19           | Zero storage   | 10/21/87    | Large animal holes in u/s slope                          | L             | 75   |
| *Garden of the Gods          | 10           | 3' crest   | 5/31/88     | No spillway  | L             |  |
| Holita                       | 16           | 3' below crest   | 6/2/77      | Inadequate freeboard, slip on d/s slope                  | L             | 189  |
| Horse Creek & Black Draw     | 17           | 5' below crest   | 4/24/86     | In disrepair, abandoned                                  | L             | 112  |
| Lake Chipita                 | 10           | 5' below crest   | 3/11/83     | Provide adequate freeboard                               | L             | 5  |
| Lake Henry                   | 17           | 7.0' below crest   | 7/15/87     | Seepage on east dam                                      | M             | 2,659                                      |
| Lolita #3                    | 17           | 5' below crest   | 8/12/85     | Inoperable outlet, uneven crest                          | L             | 700  |
| Martin Lake                  | 16           | 5' below crest   | 2/18/83     | Inadequate spillway, poor condition of outlet            | H             | 412  |
| Mill Lake                    | 16           | 9' below crest   | 2/16/83     | Inadequate spillway, poor condition                      | L             | 40   |
| Modern Woodmen of America #2 | 10           | No storage   | 8/12/83     | Spillway obstructed                                      | L             | 18   |
| Monument                     | 10           | 3' below spillway  | 4/23/85     | Unsat. Spillway condition                                | M             | 150  |
| Mount Pisgah                 | 12           | 5.2' below spillway  | 6/6/85      | Inadequate spillway capacity                             | M             | 586  |
| Nee-Noshe                    | 67           | Gage 22.5 with special requirements to allow storage to 23.5 | 1/17/83     | No spillway  | M             | 7,392                                      |
| Orlando #2                   | 16           | G.H. 22.5 ft.  | 7/24/84     | Cracks on downstream slope                               | L             | 750  |
| Park Center L&W#2            | 12           | No storage   | 9/26/85     | Slide on downstream slope                                | L             | 15   |
| Park Center #10              | 12           | 6' below crest   | 1/5/74      | Severe cracking  | L             | 12   |
|                              |              |  |             |  |               | <hr/> 14,880.0                             |

\*Restrictions imposed this month

\*\*Restrictions removed this month (date)

+Revised existing restrictions



Division Two (cont.)

| <u>NAME</u>                | <u>DIST.</u> | <u>AMOUNT</u>        | <u>DATE</u> | <u>REASON</u>  | <u>HAZARD</u> | <u>APPROX.<br/>STG. LOST<br/>ACRE-FEET</u> |
|----------------------------|--------------|----------------------|-------------|--|---------------|--|
| Prospect Lake              | 10           | 3 1/2' crest         | 05/31/88    | No spillway, outlet operability questionable   | L             | 0  |
| Queen                      | 67           | 7' below crest       | 2/20/87     | U/S slope erosion; inadq. riprap   | M             | 500  |
| Rainbow Lake               | 11           | 5.0/8.0' below crest | 12/23/87    | Inadequate spillway  | L             | 0  |
| Seven Lakes                | 19           | 7' below crest       | 5/6/87      | Dilapidated cond. of dam   | L             | 1,200                                      |
| Sharps Orchard             | 16           | 7' below crest       | 5/1/72      | Badly eroded upstream slope  | L             | 20   |
| Silver Spruce #7           | 12           | 4' below crest       | 1/18/85     | Seepage and slide  | L             | 6  |
| Swink #1                   | 17           | 5' below crest       | 4/24/86     | In disrepair, abandoned  | L             | 500  |
| Swink #2                   | 17           | 5' below crest       | 4/24/86     | In disrepair, abandoned  | L             | 600  |
| Swink #5                   | 17           | 5' below crest       | 4/24/86     | In disrepair, abandoned  | L             | 750  |
| Swink #6<br>(aka - Powell) | 17           | 5' below crest       | 4/24/86     | In disrepair, abandoned  | L             | 650  |
| Timpas #3                  | 17           | 10' below crest      | 4/21/86     | In disrepair, abandoned  | L             | 500  |
| Two Buttes                 | 67           | 35' below crest      | 1/24/83     | Inadequate spillway  | H             | 22,200                                     |
| Valley #1                  | 10           | 15' below crest      | 12/27/84    | Poor condition and blocked spillway  | L             | 50   |
| Valley #2                  | 10           | 40' below crest      | 12/27/84    | Inoperable outlet, poor condition  | L             | 150  |
| Victor #2                  | 12           | 8' below crest       | 6/22/84     | Extensive cracking along embankment  | M             | 17   |
| Wahatoya                   | 16           | 5' below crest       | 5/12/75     | Excess seepage, cracks   | H             | 52   |
| +Walsenburg Wtr.<br>System | 16           | 13'                  | 6/22/88     | Extensive seepage along the toe<br>saturated foundation, and<br>potential instability. | M             | 67   |
| Wilson                     | 12           | 3' below spillway    | 8/24/87     | Structural cracks, spillway  | M             | 120  |
|                            |              |                      |             |  |               | <hr/> 27,382.0                             |
| Division Two Total         |              |                      |             |  |               | 42,262.0                                   |

14,880.0

Revised existing restrictions  
Restrictions removed this month (date)  
Restrictions imposed this month



**DAM SAFETY BRANCH  
CURRENT RESTRICTIONS**

**JUNE 30, 1988**

**DIVISION THREE**

| <u>NAME</u>                              | <u>DIST.</u> | <u>AMOUNT</u>  | <u>DATE</u> | <u>REASON</u>                                    | <u>HAZARD</u> | <u>APPROX.<br/>STG. LOST<br/>ACRE-FEET</u> |
|--|--------------|--|-------------|--|---------------|--|
| Bristol Head #2<br>(Upper)               | 20           | 6.0 feet below<br>lowest point of<br>dam crest                                       | 4/20/87     | Erosion damage, etc.                             | M             | 20   |
| Eastdale #1                              | 24           | G.H. 18 (12' below<br>crest) 11/1 - 7/31<br>G.H. 15 (15' below<br>crest) 8/1 - 10/31 | 08/21/87    | Upstream slope erosion, seepage                  | L             | 1,700                                      |
| **Flickinger                             | 26           | 17' below crest  | 11/12/80    | Inadequate spwy., poor construction              | L             | 30   |
| Forbes Park                              | 35           | 2.5' spillway  | 7/19/85     | Inadequate spillway                              | L             | 45   |
| Lost Lake #2                             | 20           | 3.5' below crest   | 8/14/87     | Cracking, inadequate freeboard,<br>rusted outlet | L             | 80   |
| Mountain Home                            | 35           | G.H. 87.5'   | 9/16/82     | Inadequate spillway                              | H             | 15,000                                     |
| Terrace                                  | 21           | 7' below spillway  | 7/18/84     | Inadequate spillway                              | H             | 2,000                                      |
| <hr/>                                    |              |  |             |  |               | 18,855.0                                   |
| Division Three Total                     |              |  |             |  |               | 18,855.0                                   |
| <hr/>                                    |              |  |             |  |               |  |
| *Restrictions imposed this month         |              |  |             |  |               |  |
| **Restrictions removed this month (date) |              |  |             |  |               |  |
| +Revised existing restrictions           |              |  |             |  |               |  |



**DAM SAFETY BRANCH  
CURRENT RESTRICTIONS**

JUNE 30, 1988

DIVISION FOUR

| <u>NAME</u>      | <u>DIST.</u> | <u>AMOUNT</u>      | <u>DATE</u> | <u>REASON</u>  | <u>HAZARD</u> | <u>APPROX.<br/>STG. LOST<br/>ACRE-FEET</u> |
|------------------|--------------|--------------------|-------------|--|---------------|--|
| Alta #1          | 60           | 5' below crest     | 8/18/76     | Inadequate spillway  | L             | 20   |
| Alta #3          | 60           | 5' below crest     | 9/16/85     | Provide sufficient freeboard                                       | L             | 10   |
| Arch Slough      | 40           | G.H. 0.0           | 12/12/85    | Poor condition, reservoir abandoned                                | L             | 66   |
| Beaver           | 40           | 10' below spillway | 7/7/87      | Excessive seepage  | H             | 300  |
| Brockman #2      | 40           | 5' below spwy      | 7/11/86     | Saturation/instability   | L             | 20   |
| Casto            | 63           | 12' below crest    | 4/6/84      | Rodent holes, abandoned outlet,<br>thin crest                      | M             | 477  |
| Citizens         | 41           | 2' below spwy      | 9/29/86     | Inadequate freeboard and general<br>poor maintenance               | L             | 30   |
| Coffey           | 41           | Zero storage       | 10/22/85    | Poor condition & excessive seepage                                 | L             | 35   |
| Craig #1         | 63           | 3' below spillway  | 05/1/86     | Seepage ponding at toe and brush<br>obscuring upstream slope       | M             | 95   |
| Cushman Lake     | 60           | 6' below crest     | 7/29/75     | Provide sufficient freeboard                                       | L             | 6  |
| Doughty          | 40           | 5' below spillway  | 11/10/86    | Seepage adjacent to outlet   | L             | 21   |
| Duvall #1        | 73           | 16' below crest    | 5/22/85     | Poor condition, no outlet  | L             | 15   |
| Fullmoon         | 68           | 3' below crest     | 11/27/85    | Maintain minimum freeboard   | L             |  |
| Gobbo #3         | 42           | 16' below crest    | 11/7/86     | Slide on d/s slope   | M             | 100  |
| Granby #11       | 40           | 4' below spillway  | 10/15/87    | Seepage  | M             | 72   |
| Granby #12       | 40           | G.H. 17            | 10/15/87    | Seepage  | M             | 98   |
| Grand Mesa No. 1 | 42           | 3' below crest     | 1/27/88     | Inadequate freeboard   | L             | 48   |
| Hale             | 40           | 5' below crest     | 9/17/85     | Sinkholes  | L             | 15   |
| Holy Terror      | 40           | 6' below crest     | 11/10/86    | Inadequate spwy., spwy. erosion<br>& debris, seepage, narrow crest | L             | 67   |
| Knox             | 40           | G.H. 17.0          | 1/8/88      | Seepage on embankment<br>revision until 8/15/87                    | L             | 135  |
|                  |              |                    |             |  |               | <hr/> 1,630.0                              |

\*Restrictions imposed this month

\*\*Restrictions removed this month (date)

+Revised existing restrictions



Division Four (cont.)

| NAME                  | DIST. | AMOUNT                     | DATE     | REASON  | HAZARD | APPROX.<br>STG. LOST<br>ACRE-Feet |
|-----------------------|-------|----------------------------|----------|---|--------|-----------------------------------|
| Little Giant #1       | 40    | 6' crest, 10.5' GH         | 6/6/88   | Poor outlet, inadequate spillway.                     | L      |                                   |
| Lone Cabin            | 40    | 3' below spillway          | 9/11/84  | Slide on downstream slope                             | L      | 40                                |
| Lone Star #1          | 40    | 10' below crest            | 4/12/85  | Constructed without approved plans and specifications | L      |                                   |
| **Lone Star #3        | 40    | 4' below crest of spillway | 4/12/85  | Constructed without approved plans and specifications | L      |                                   |
| Meridian Lake Park #1 | 59    | 2' below spillway          | 6/4/87   | Severe erosion of the spillway                        | L      | 10                                |
| Mock #1               | 41    | 9' below crest             | 9/20/82  | Poor condition  | L      | 20                                |
| +Monument             | 40    | 5' below spillway          | 6/6/88   | Cracks in left abutment                               | M      | 100                               |
| Norwood Pond          | 60    | 5' below crest             | 1/5/83   | Seepage high up on d/s slope                          | L      | 4                                 |
| Oasis                 | 40    | 3' below crest             | 11/9/84  | Lack of freeboard, poor outlet                        | L      | 21                                |
| Paxton                | 60    | 5' below spwy              | 8/6/86   | Seepage   | L      | 400                               |
| Priest Lake           | 60    | 3' below crest             | 9/16/85  | Insufficient freeboard                                | L      | 25                                |
| Reeder                | 42    | 8' below crest             | 8/14/85  | Insufficient freeboard<br>Seepage, trees              | L      | 96                                |
| Todd                  | 40    | 10' below crest            | 10/19/84 | 6' elevation difference along crest with no spillway  | L      | 112                               |
| Trout Lake            | 60    | 12' below crest            | 7/7/87   | Sandboils   | H      | 530                               |
| Waterbug              | 40    | 6' below spillway          | 11/10/86 | Poor condition, slip on u/s slope, d/s outlet valve   | L      | 65                                |
| Weir & Johnson        | 40    | Zero storage               | 12/4/87  | Failed outlet   | M      | 630                               |
| Womack #3             | 40    | 4' below crest             | 9/14/84  | Inadequate cross-section                              | L      | 23                                |

2,076.0

Division Four Total

3,706.0



**DAM SAFETY BRANCH  
CURRENT RESTRICTIONS**

**JUNE 30, 1988**

**DIVISION FIVE**

| <u>NAME</u>                 | <u>DIST.</u> | <u>AMOUNT</u>                                 | <u>DATE</u> | <u>REASON</u>  | <u>HAZARD</u> | <u>APPROX.<br/>STG. LOST<br/>ACRE-FEET</u> |
|-----------------------------|--------------|---|-------------|--|---------------|--|
| Battlement #2               | 45           | Zero storage                                  | 11/5/85     | Damaged outlet   | L             | 70   |
| Big Beaver                  | 72           | 10' below crest                               | 11/17/87    | Sinkholes in right embankment                          | L             | 96   |
| Bull Basin #1               | 72           | 10' below crest                               | 11/23/87    | Spillway flows impinge on embankment toe               | L             | 80   |
| Bull Creek #3               | 72           | Zero Storage<br>Maintain Outlet<br>Fully Open | 11/23/87    | Sinkhole on u/s slope                                  | L             | 59   |
| Carpenter                   | 72           | G.H. zero                                     | 11/7/86     | Sinkhole, seepage                                      | L             | 34   |
| Coon Creek #1               | 72           | 8' below spillway                             | 9/24/87     | Inadequate spillway                                    | M             | 475  |
| Coon Creek #2               | 72           | Zero Storage<br>Maintain Outlet<br>Fully Open | 11/23/87    | Sinkhole on u/s slope, excessive seepage               | M             | 225  |
| Coon Creek #3               | 72           | 5' below crest                                | 9/29/87     | Outlet deteriorated                                    | L             | 30   |
| Coon Creek #4               | 72           | No storage                                    | 9/16/86     | Poor Condition   | L             | 9  |
| Cottonwood #2               | 72           | 3' below spwy.                                | 10/17/85    | Inadequate spwy., ext. seepage                         | M             | 50   |
| Currier #2                  | 72           | Zero Storage                                  | 10/16/87    | Land slides into spillway                              | L             | 222  |
| Dale                        | 51           | 15.5' below crest                             | 7/6/87      | Outlet distress, sloughing at outlet                   | L             |  |
| Dale #2                     | 51           | 5' below crest                                | 7/5/85      | Insufficient freeboard                                 | L             | 15   |
| Dawson/aka/Lambert          | 72           | 3' below crest                                | 10/17/85    | Inadequate spwy., poor condition                       | L             | 70   |
| Fruita Settling<br>Basin #2 | 72           | Zero storage                                  | 11/23/87    | Poor condition   | L             | 38   |
| G. G. Lower                 | 37           | No storage                                    | 2/14/86     | Inadequate freeboard                                   | L             | 37   |
| G. G. Upper                 | 37           | No storage                                    | 2/14/86     | Inadequate frbd. & questionable stability of d/s slope | L             | 30   |
| Harris                      | 39           | 6' below spwy.                                | 11/27/85    | Undersized spillway                                    | M             | 50   |
| Jones                       | 52           | 5' below p. spwy.                             | 10/23/85    | Outlet disrepair, seepage on embmnt.                   | M             | 35   |
| Kelly Dam                   | 53           | 5' below crest                                | 11/21/84    | Insufficient freeboard                                 | L             | 100  |
| Langholen                   | 51           | 4' below spwy.                                | 6/28/85     | Inadequate spillway                                    | L             | 60   |
|                             |              |   |             |  |               | <hr/> 1,785.0                              |

\*Restrictions imposed this month

\*\*Restrictions removed this month (date)

+Revised existing restrictions



Division Five (cont.)

| <u>NAME</u>        | <u>DIST.</u> | <u>AMOUNT</u>                            | <u>DATE</u> | <u>REASON</u>   | <u>HAZARD</u> | <u>APPROX.<br/>STG. LOST<br/>ACRE-FEET</u> |
|--------------------|--------------|--|-------------|---|---------------|--|
| Leon Lake          | 72           | G.H. 18.5                                | 9/18/87     | Sinkhole and leakages                                       | H             |  |
| Little King Ranch  | 51           | 10' below spillway<br>gage-height 41.0   | 4/16/73     | Excessive leakage   | M             | 180  |
| Mesa Creek #4      | 72           | G.H. 10.0 or<br>5' below spwy. crest     | 1/18/83     | Instability of d/s slope and<br>seepage                     | M             | 324  |
| Michaelson         | 72           | G.H. 0.0                                 | 10/21/87    |   | L             | 88   |
| Milk Creek         | 50           | 20' below crest or<br>15' below spillway | 09/16/87    | Excessive seepage on embankment                             | L             | 60   |
| Muddy Gulch        | 72           | No storage                               | 6/2/86      | Inad. s/w, seepage, poor condition                          | L             | 5  |
| Newton Gulch       | 53           | 20' below crest                          | 7/3/75      | Abutment piping failure                                     | L             | 400  |
| Noeker             | 37           | 5' below crest                           | 10/10/84    | Badger holes down into crest                                | L             | 65   |
| Parkerson          | 72           | No storage                               | 9/24/87     | Improper construction                                       | L             | 10   |
| Parsons            | 50           | Zero strg.                               | 11/28/86    | Inadequate spwy. sagging crest,<br>abutment slides at spwy. | L             | 27   |
| Pheney             | 51           | 5' below crest                           | 7/18/86     | No spillway, extensive seepage                              | L             | 100  |
| Rapid Creek #1     | 72           | 6' below crest                           | 9/12/86     | Poor condition & seepage                                    | M             | 400  |
| Rapid Creek #2     | 72           | 6' below crest                           | 9/11/86     | Poor condition & inoperable<br>outlet                       | M             | 147  |
| Rifle Valley       | 39           | 5' below crest                           | 2/14/77     | No spillway, outlet, inoperable                             | M             | 49   |
| Rock Creek         | 51           | 15' below crest                          | 1/22/79     | Inadequate spillway, poor embankmt.                         | L             | 125  |
| Ruby Lee           | 72           | No storage                               | 6/25/85     | Inadequate spillway, poor condition                         | L             | 367  |
| Rudolph            | 50           | Zero storage                             | 9/16/87     | Failed outlet   | L             | 70   |
| Scholl             | 51           | 22' below crest                          | 6/30/86     | Sinkholes in abutment                                       | L             | 250  |
| **Schorn Fish Pond | 72           | No storage                               | 9/14/82     | Poor condition  | L             | 7  |
| Sylvan             | 51           | 5' below crest                           | 9/30/85     | Insufficient freeboard                                      | M             | 130  |
| Upper Highline     | 72           | 10' below spwy.                          | 8/22/85     | Seepage of dissolved solids                                 | M             | 1,860                                      |
| Welsh              | 37           | 8' below crest                           | 5/17/78     | Poor condition  | L             | 36   |
| Willow Creek       | 37           | 5' below crest                           | 09/29/87    | Inadequate spillway   | L             | 7  |
| Y-T Reservoir      | 72           | 6' below crest                           | 9/24/87     | Extensive historic seepage,<br>inadequate spillway          | L             | 40   |

4,747.0

Division Five Total

6,532.0



DAM SAFETY BRANCH  
CURRENT RESTRICTIONS

JUNE 30, 1988

DIVISION SIX

| <u>NAME</u>        | <u>DIST.</u> | <u>AMOUNT</u>     | <u>DATE</u> | <u>REASON</u>  | <u>HAZARD</u> | <u>APPROX.<br/>STG. LOST<br/>ACRE-FEET</u> |
|--------------------|--------------|-------------------|-------------|--|---------------|--|
| Anderson           | 44           | 6' below crest    | 6/06/86     | Blocked spillway   | L             | 60   |
| Bar-Bee            | 58           | 1' below spillway | 11/17/87    | Spillway erosion   | L             | 6  |
| Basin              | 57           | 13' below crest   | 9/17/85     | Dam is breached  | L             | 200  |
| Biskup Dam         | 44           | 5' below spwy     | 6/27/86     | Inadequate spillway, slide,<br>poor condition                      | L             | 45   |
| Bunker             | 44           | 5' below crest    | 11/15/85    | Poor condition, no spillway  | L             | 60   |
| Clayton Lake       | 47           | 5' below spwy     | 7/23/86     | Seepage on d/s face  | L             | 60   |
| D D & E Wise       | 44           | 5' below spwy     | 11/27/85    | Poor outlet condition  | M             | 200  |
| Drescher           | 44           | 1' below spillway | 9/22/87     | Cracks in crest and<br>spillway backcutting                        | L             | 30   |
| Ellgen #2          | 44           | No storage        | 5/30/86     | Poor outlet condition  | L             | 60   |
| Elk Lake           | 54           | 5' below crest    | 9/12/85     | Spillway obstructed, poor maint.                                   | M             | 40   |
| Fait               | 58           | Zero storage      | 10/1/87     | Illegal dam  | L             | 4  |
| Gill               | 44           | 10' below crest   | 10/20/86    | Seepage high on embankment   | L             | 60   |
| Lake Emrich        | 57           | 15' below crest   | 5/6/87      | Slide on d/s face  | L             | 250  |
| Lake Gloria        | 43           | 5' below crest    | 12/29/87    | Illegal dam w/o plans & specs.;<br>inad. frbd.; questionable spwy. | L             | 7  |
| Mystic #2          | 58           | 10' below crest   | 11/16/87    | Severe cracking of embankment                                      | L             | 5  |
| Nofstger           | 57           | 3' below spillway | 12/16/87    | Spillway too small   | L             | 40   |
| Nofstger-Zeigler   | 57           | 5' below crest    | 6/18/85     | No spillway, poor condition  | L             | 40   |
| Overman            | 58           | No storage        | 11/18/87    | Hole in d/s slope  | L             | 50   |
| Pole Mountain      | 47           | No storage        | 3/30/83     | Slide, upstream slope  | M             | 1,905                                      |
|                    |              |                   |             |  |               | 3,122.0                                    |
| Division Six Total |              |                   |             |  |               | 3,122.0                                    |

\*Restrictions imposed this month

\*\*Restrictions removed this month (date)

+Revised existing restrictions



DAM SAFETY BRANCH  
CURRENT RESTRICTIONS

JUNE 30, 1988

DIVISION SEVEN

| <u>NAME</u>          | <u>DIST.</u> | <u>AMOUNT</u>                                    | <u>DATE</u> | <u>REASON</u>  | <u>HAZARD</u> | <u>APPROX.<br/>STG. LOST<br/>ACRE-FEET</u> |
|----------------------|--------------|--|-------------|--|---------------|--|
| Bauer #1             | 34           | 3' below spwy<br>for 45 days or<br>5' below spwy | 8/27/84     | Saturation high on embankment  | M             | 144  |
| Belmear              | 69           | 7' below crest                                   | 7/17/84     | Backcutting of spillway, concentra-<br>ted leakage, questionable outlet  | M             | 168  |
| Big Pine             | 71           | 2' below spillway                                | 8/12/85     | Steepness of d/s slope around out-<br>let and seepage and sloughing<br>from abutment left of outlet                        | M             | 70   |
| Caballo Lake         | 31           | 2' below spillway                                | 7/29/86     | Leakage along outlet; inadequate<br>spillway   | L             | 8  |
| Charles Lemon        | 30           | G.H. 8.5   | 3/7/86      | Poor condition - restriction is to<br>top of principle spwy. pipe  | L             | 15   |
| Coppinger #1         | 34           | 3' below crest                                   | 1/27/84     | Inadequate freeboard, inoperable<br>outlet, rodent activity  | L             | 12   |
| Coppinger #2         | 34           | 3' below crest                                   | 8/85        | Inadequate freeboard   | L             | 5  |
| Highland Mary        | 30           | 11' below crest                                  | 9/12/85     | Inoperable outlet, partially<br>breached condition of dam  | L             | 60   |
| J. O. Spencer        | 34           | 5' below spillway                                |             | Poor condition   | L             | 13   |
| Short                | 30           | No storage. Outlet<br>full open.                 | 11/13/86    | Inadequate spwy.; erosion on u/s<br>face; current rest. results<br>in about 3 AF of dead storage<br>below invert of outlet | L             | 40   |
|                      |              |  |             |  |               | 535.0                                      |
| Division Seven Total |              |  |             |  |               | 535.0                                      |

\*Restrictions imposed this month  
\*\*Restrictions removed this month (date)  
+Revised existing restrictions



RECEIVED

NOV 11 1988

COLORADO  
State P

ARY  
sitor