



OF

·COLC

1876





BUDGET RECOMMENDATIONS PRESENTED TO THE CAPITAL DEVELOPMENT COMMITTEE

DECEMBER 5, 2000



BUDGET RECOMMENDATIONS FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

DECEMBER 2000

TABLE OF CONTENTS

- I. INTRODUCTION
- II. EXECUTIVE SUMMARY
- III. SBP PRIORITIZED STATEWIDE FUNDING RECOMMENDATIONS
- IV. SBP PRIORITIZED STATEWIDE PROJECT REQUEST DESCRIPTIONS
- V. AGENCY GENERAL FUNDED GROSS SQUARE FOOTAGE
- VI. FACILITIES AUDIT SUMMARY
- VII. ENERGY EFFICIENCY CONTRACTS
- VIII. AGENCY PRIORITIZED FIVE YEAR PLAN PROJECT REQUESTS
- IX. AGENCY CONTROLLED MAINTENANCE PROJECT STATUS REPORTS
- X. SBP EMERGENCY FUND STATUS REPORT

I. INTRODUCTION

STATE OF COLORADO

GENERAL SUPPORT SERVICES DIVISION OF CENTRAL SERVICES

STATE BUILDINGS AND REAL ESTATE PROGRAMS 1525 Sherman Street Suite 250 Denver, Colorado 80203 (303) 866-6141 Fax:(303) 894-7478



Bill Owens Governor

Larry E. Trujillo, Sr. Executive Director

Rick Malinowski Division Director

December 5, 2000

Representative Joyce Lawrence, Chairperson Capital Development Committee 46 State Capitol Building Denver, CO 80203

RE: Fiscal Year 2001/2002 Controlled Maintenance Recommendations

Dear Representative Lawrence:

State Buildings Programs is pleased to submit to the Committee the Fiscal Year 2001/2002 Controlled Maintenance Budget Recommendations. As in past years, this budget request has been prepared following an evaluation of agencies/institutions' individual requests, on-site observations of specific problems, and an analysis of statewide major maintenance needs. This request identifies the magnitude of reported major maintenance needs statewide to the actual dollar amount that was appropriated on an annual basis for the past **eleven fiscal years**.

Consistent with the manner in which the recommendations have been prepared in recent years, State Buildings Programs has prioritized a ranking of agency requests by life safety, program disruption, and deterioration factors, and, in addition, given recommendations for appropriate funding levels. We have weighed factors such as: each agency's effective management of previously funded projects, the relative criticality of the elements of each project in relationship to the overall condition of the agency/institution's facilities, incorporation of energy saving practices and the equitable distribution of limited funds. Please refer to the attachment A outlining the Controlled Maintenance process.

In an effort to provide the committee with the most comprehensive and accurate information possible, State Buildings Programs initiated a statewide process (facility audit condition surveys) in FY98/99 to assess the condition of all state owned general funded facilities at each agency/institution. The intent of this process was to enable each agency/institution to incorporate their data into a comprehensive controlled maintenance master plan and eventually into a coordinated asset management tool. This controlled maintenance master plan is now the basis for all subsequent control maintenance requests starting with a rolling five year project plan request and continuing on with a quantifiable estimate of future needs.

To date over ninety percent of all agency/institution's facilities have been audited and have provided State Buildings Programs with enough data to provide an approximate "order of magnitude" of the state's controlled maintenance needs based on the current inventory of existing facilities. Please refer to Section II, Executive Summary for more details.

However, the state's general funded inventory has increased by unprecedented levels. In the last decade nine million square feet has been added to the State's inventory which includes new construction and the acquisition of existing buildings along with supporting infrastructure, (newly constructed buildings account for approximately

December 5, 2000 Page 2

seventy percent of the increase and the acquisition of existing buildings accounting for approximately thirty percent). Please refer to Section V, Agency General Funded Gross Square Footage for more detail.

Controlled Maintenance funding alone cannot be effective in reducing or maintaining the magnitude of the state's existing and future needs at acceptable levels. At the least, the following issues should therefore be addressed and possibly coordinated into an overall strategy:

- 1. Eligibility requirements for funding newly constructed or remodeled building and acquired older existing buildings.
- 2. The funding of operating maintenance as it impacts an agency/institution's ability to maintain the condition of its facilities and its supporting infrastructure.
- 3. Alternative funding methods to allow future Controlled Maintenance funds to be set aside for new capital construction projects.
- 4. Limitations on the scope or dollar amount of a Controlled Maintenance project.
- 5. Use of the Facilities Audit Process to establish a method of measuring the improvements made to each agency/institution's facilities through capital construction renovations and controlled maintenance projects.
- 6. Establishment of a process to track the condition of the State's auxiliary funded buildings.

The past support of the Committee has been sincerely appreciated by all state agencies. Due to the Committee's awareness of Controlled Maintenance needs and the increased funding over the last five fiscal years, the condition of state facilities is improving. The controlled maintenance process is no longer in a "crisis mode", but is instead in a "management mode". Continued legislative support is essential to maintain the appropriate management oversight and reinvestment in our State's assets.

State Buildings Programs would also like to convey to the Committee our genuine appreciation for all of the time and effort that the participating agencies have put into this budget recommendation. The level of professionalism, commitment, and pride conveyed by staff for their respective agencies is impressive.

State Buildings Programs looks forward to the Controlled Maintenance presentation of December 5. I am available to meet with you and the Committee at any other time to discuss the issues stated above or answer any questions.

Respectfully submitted,

/_ PEDPE

Lawrence J. Friedberg, AIA Manager, State Buildings and Real Estate Programs

Attachment A

ATTACHMENT A

CONTROLLED MAINTENANCE PROCESS

<u>AUTHORITY:</u> 24-30-1301, CRS (State Buildings)

DEFINITIONS:

Controlled Maintenance - Corrective repairs or replacement used for existing state-owned, <u>general-funded</u> buildings and other physical facilities, including, but not limited to, utilities and site improvements, which are suitable for retention and use for at least five years, and replacement and repair of the fixed equipment necessary for the operation of such facilities, when such work is **not funded in an agency's operating budget** to be accomplished by the agency's physical plant staff.

The difference between capital construction and controlled maintenance projects has also been described by the application of certain project drivers:

- **Maintenance Driven:** defined as those projects arising out of the deterioration of a facility's physical and functional condition, including site and infrastructure, and the inability to comply with current codes. These types of requests would be considered as controlled maintenance.
- Program Driven: defined as those projects arising out of an agency's need to create, expand, or alter a program due to growth, advances in technology or changes in methods or program delivery. Requests addressing physical space requirements needed to accommodate particular functions, such as those traditionally included in facility program plan would constitute a "Program Driven" request, and, therefore, would be considered as capital construction.

PROCESS:

- 1. **April/May**: State Buildings Programs (SBP) consults with the Office of State Planning and Budget (OSPB) to establish controlled maintenance budget projections and schedules for the following fiscal year. **(OSPB establishes overall capital construction/controlled maintenance projected budgets.)**
- May: SBP provides and distributes the controlled maintenance budget instructions to all state agencies and institutions with the exception of the Department of Transportation and the Department of Natural Resources. (OSPB provides the inflation factor to be applied to all agency/institution controlled maintenance project cost estimates.)
- 3. **June through August**: SBP conducts site visits to all state agencies/institutions to technically verify controlled maintenance project requests; to assess progress on previously funded controlled maintenance and capital construction projects, and to review and approve drafts of controlled maintenance request documents.

SBP coordinates its reviews of the controlled maintenance requests with the capital construction requests submitted to OSPB and the Colorado Commission on Higher Education (CCHE) on an agency-by-agency basis. The reviews assess the following:

a. Are all agency/institution controlled maintenance project requests appropriately categorized as controlled maintenance or should any be considered as capital construction? Additionally, the Five Year Rule is also applied. State owned facilities are eligible for controlled maintenance funding provided that they have been state owned and operated through general funding for a minimum of five years, and/or that it has been a minimum of five years since the facility was either renovated or constructed with general funds.

- b. Could an agency/institution's controlled maintenance requests also be included in their capital construction requests? If duplicate project funding requests exist, the agency/institution is consulted, and the appropriate category and funding source are selected and either the controlled maintenance or capital construction request is revised.
- c. SBP provides additional expertise and technical assistance to OSPB or CCHE during their review of capital construction project requests.
- 4. **Approximately September 1**: SBP receives the final copy of all agency/institution controlled maintenance budget request submittals.
- 5. September through November: SBP reviews the submittals and prioritizes requested controlled maintenance projects on a statewide basis. (SBP justifies to OSPB the actual controlled maintenance budget.) SBP prepares the controlled maintenance budget recommendations to the CDC according to statute.
- 6. **November/December**: SBP presents controlled maintenance budget recommendations to the CDC.

II. EXECUTIVE SUMMARY

SECTION II: EXECUTIVE SUMMARY FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

CONTROLLED MAINTENANCE PROJECT RECOMMENDATIONS

- 168 Controlled Maintenance project requests have been prioritized and ranked by State Buildings Programs for a total recommended amount of \$68,780,833 for FY01/02. (Compared to 163 projects recommended in FY00/01 for a total of \$54,671,981). The prioritization is as follows:
 - Level 1 (most critical/predominantly life safety) 37 ranked projects (including \$1,000,000 for the Emergency Fund) for a total of **\$20,240,915**
 - Level 2 (predominantly causing program disruption) 51 ranked projects for a total of \$22,051,921
 - Level 3 (predominantly varying degrees of deterioration) 80 ranked projects for a total of \$26,487,997
- State Buildings Programs recommends funding all three levels for a total of <u>\$68,780,833</u>. Please refer to Chapter III for the SBP Prioritized Statewide Funding Recommendations List of Projects and Chapter IV for Descriptions of Projects.

AGENCY REPORTED CONTROLLED MAINTENANCE NEEDS

- The reported five year plan project request needs for FY01/02 totals **\$346,360,359** (compared with \$303,718,594 in FY00/01). Note: the recommended FY01/02 funding amount of \$68,780,833 is within the five year plan project request as the current fiscal year. The five year plan is a direct result of each agency/institution utilizing their Facilities Audit to develop their specific project requests which incorporates \$224,441,977 of building needs and \$121,918,382 of infrastructure needs. (Please refer to Chart A).
- Beyond the specific five year plan needs, agency's/institution's have also incorporated data from their Facilities Audits to estimate future needs. These estimates are quantifiable but have not been developed into actual project requests because the majority of these repairs/replacements/upgrades are not needed in the next five years. Therefore, the projected dollar estimates are for out year budgeting purposes. The estimated future Controlled Maintenance needs total \$558,723,992 (compared with \$421,283,547 in FY00/01). The estimates incorporate \$448,311,664 of building needs and \$110,412,348 of infrastructure needs. (Potentially, a significant amount of estimated future needs may be incorporated into future capital construction renovation projects as per past practices)
- The increase in the reported dollar amounts over the last five years is due to inflation, physical plant deterioration, increase in the State's inventory of newly constructed and acquisition of older existing buildings and mostly to the agencies completing comprehensive facility condition surveys (Facilities Audits) of their general funded buildings and supporting infrastructure. Please refer to Chapter VI, Facilities Audit Summary.
- The Departments of Public Health and the Environment, Local Affairs, along with the HEAT Center at Lowry, and the Community College of Aurora did not submit Controlled Maintenance requests for 01/02.

INCREASES IN STATE OWNED AND OPERATED GROSS SQUARE FOOTAGE

- The reported general funded gross square footage (GSF) of all participating agencies has increased by approximately 887,833 GSF from 35,103,341 GSF in FY00/01 to 35,991,174 GSF in FY01/02.
- In the last eleven fiscal years the reported general funded gross square footage has increased by approximately 9,010,637 GSF from 26,980,537 GSF in FY90/01 to 35,991,174 GSF in FY01/02 (please refer

to chart B). Of that 9,010,637 GSF approximately one third (3,000,000 GSF) is attributable to the acquisition of existing buildings with varying degrees of Controlled Maintenance needs (additionally a total of 19,188,561 GSF of state owned buildings are funded through auxiliary funds or from other sources and are not part of the Controlled Maintenance program nor tracked by State Buildings Programs). Please refer to Chapter V, Agency Total General Funded Gross Square Footage.

- At least eight additional agencies with existing facilities and supporting site infrastructures have become eligible to request Controlled Maintenance funds in the last five fiscal years. The additional gross square footage is included in the reported general funded gross square footage number above.
- The additional agencies are: Northeastern Junior College, HEAT Center at Lowry, Colorado Northwestern Community College, Community College of Aurora, Front Range Community College-Larimer Campus, the Health Sciences Center at Fitzimons Building 500, the Colorado State Fair and The Cumbres and Toltec Scenic Railroad.


FUNDING RECOMMENDATIONS VS REPORTED CONTROLLED MAINTENANCE NEEDS

- Prior to FY95/96 the amount of money appropriated on an annual basis to Controlled Maintenance was not targeted as a specific ratio of the total reported Controlled Maintenance needs. Funding fluctuated between 3% and 8.3% of the total reported need between FY90/91 and FY95/96.
- From FY96/97 to FY99/00 an approximate ratio of 10% funding to reported need was established and nearly met. The ratio was established as a temporary means to keep pace with the known major maintenance needs at that time.
- In FY98/99 facility audit surveys were required to be implemented by all agencies requesting CM funding. By FY99/00 47% of all state owned facilities had been audited. By FY00/01 61% had been audited. Currently, over 90% of all state owned facilities have been audited.
- In order to help maintain facilities, and reduce the overall Controlled Maintenance needs to acceptable levels, continued annual funding is required. Nationally recognized guidelines recommend a range (or ratio) for annual "Reinvestment Rate" funding between 1% to 4% of current replacement value (CRV) of the total physical plant (statewide inventory). This reinvestment rate funding is dedicated to major maintenance and is synonymous with Controlled Maintenance funding. (The 10% ratio of funding to reported need is no longer relevant because facilities audit data is now identifying specific needs.)
- Currently the recommended FY01/02 Controlled Maintenance funding of \$68,780,833 is approximately 1.3% of the current replacement value of general funded facilities totaling approximately \$4.8 billion compared with \$54,671,981 in FY00/01 (a reinvestment rate of 1.3% of the CRV of \$4.3 billion in FY00/01).
- With over 90% completion of facilities audits to date, Controlled Maintenance need's can now be categorized into: Immediate Needs (current year recommendations), Short Term Needs (specific five year plan project requests) and Long Term Needs (estimated future needs). Although the condition of the State's existing facilities are improving due to the increased levels of funding over the last five fiscal years, Controlled Maintenance funding alone cannot be effective in reducing nor maintaining the magnitude of the states existing and future needs unless the State's agencies/institutions have the resources to properly maintain and operate their facilities.


SECTION II: EXECUTIVE SUMMARY FY2001/2002 CONTROLLED MAINTENANCE PROGRAM

CHART A: HISTORICAL FUNDING VS. AGENCY REQUEST

This chart compares the dollar amount of Controlled Maintenance statewide reported needs to actual dollars funded over the last eleven fiscal years. The right column indicates reported needs and recommended dollars for FY 2001/2002.







III. SBP PRIORITIZED STATEWIDE FUNDING RECOMMENDATIONS

SECTION III: SBP PRIORITIZED STATEWIDE FUNDING RECOMMENDATIONS FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

The following 9 pages provide the prioritized funding recommendations for CM projects. The total recommended funding for FY 01/02 (**\$68,780,833**) based on State Buildings Programs' determination of the most critical needs is as follows:

Level 1 - Recommends funding the 37 ranked requests for a total of **\$20,240,915**.

Level 2 - Recommends funding the 51 ranked requests for a total of **\$22,051,921**.

Level 3 - Recommends funding the 80 ranked requests for a total of **\$26,487,997**.

Level 1 incorporates the most critical needs such as life safety. Level 2 incorporates projects that are predominantly causing program disruptions and contain some life safety concerns. Level 3 incorporates projects that predominantly contain differing levels of deterioration.

Breakdown of recommended requests for all levels:

| PROJECT STATUS | | LVL 1 | LVL 2 | LVL 3 | TOTALS |
|---------------------------------|--------|-------|-------|-------|--------|
| Completed multi-phased projects | | 7 | 15 | 11 | 33 |
| New single phase projects | | 11 | 14 | 36 | 61 |
| New multi-phase projects | | 9 | 8 | 20 | 37 |
| Continuing multi-phase projects | | 9 | 14 | 13 | 36 |
| Emergency fund request | | 1 | 0 | 0 | 1 |
| | TOTALS | 37 | 51 | 80 | 168 |

This recommendation has, for the most part, used phasing amounts indicated as practical by the agencies. It has, however, modified the dollar amount of some project requests with a view toward accomplishing the following goals:

- 1) Deferring less critical elements of specific projects where these less critical elements are believed not to carry the same priority as the rest of the project. Projects are prioritized and ranked by the following factors in order of importance: life safety, program disruption and deterioration.
- 2) Providing a more appropriate level of equity in the distribution of the funds among the various state agencies, while not sacrificing the principal concept of the scoring system, which prioritizes based on need.
- 3) Assuring that the total amount of funding to each individual agency is within that agency's capability to perform, considering such factors as agency staff workload and past performance.

State Buildings Programs strongly believes that all projects recommended represent a total program level that can be effectively managed by state agencies in FY 01/02.

This program provides assistance to all eligible agencies in the state; and, to the extent that the Controlled Maintenance program is geographically distributed throughout the entire State of Colorado, it aids the state economy in all regions and districts.

Description of each of the recommended projects are contained in Section IV, SBP Descriptions of Prioritized Statewide Funding Recommendations.

SBP PRIORITIZED STATEWIDE FUNDING RECOMMENDATIONS FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

December 5, 2000

| Ref No. S | core | Agency Project Title: | Project M# | SBP Recommended Funding | Project Balance | Cumulative Total of Recommended Projects |
|--------------|------|---|---------------|-------------------------------|--------------------|---|
| LE | /EL | . 1 | | | | |
| 1 | 1 | State Buildings and Real Estate Programs Emergency Fund | | \$1,000,000 | | \$1,000,000 |
| 2 | 2 | Department of Human Services Suicide Risk Assessment and Prevention, Ph 1 of 1 | | \$796,300 | \$0 | \$1,796,300 |
| 3 | 2 | Colorado Northwestern Community College Sewer and Electrical Utility Lines Replacement, Rangely Campus, Ph 1 of 1 | | \$273,333 | \$0 | \$2,069,633 |
| 4 | 3 | Department of Corrections Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4 | M90005 | \$1,440,698 | \$1,464,592 | \$3,510,331 |
| 5 | 3 | State Capitol Building House and Senate Chamber Brass Handrail Safety Improvements, Ph 1 of 1 | | \$193,735 | \$0 | \$3,704,066 |
| 6 | 4 | Department of Revenue Replace Fire Alarm System, Ph 1 of 1 | | \$219,098 | \$0 | \$3,923,164 |
| 7 | 4 | University of Colorado at Boulder Fire Sprinkler Upgrades Various Buildings A, Ph 3 of 6 | M80053 | \$646,512 | \$2,859,703 | \$4,569,676 |
| 8 | 4 | Department of Human Services Fire Alarm System Upgrades, Ph 2 of 2 | M00090 | \$436,056 | \$0 | \$5,005,732 |
| 9 | 4 | University of Colorado at Boulder Engineering Center Fire Sprinkler System Upgrades, Ph 2 of 2 | M90033 | \$597,240 | \$0 | \$5,602,972 |
| 10 | 4 | Otero Junior College Kiva Repair and Code Corrections, Ph 2 of 2 | M00067 | \$335,851 | \$0 | \$5,938,823 |
| 11 | 4 | University of Colorado Health Sciences Center Replace Underground Storage Tanks, Ph 2 of 3 | M00050 | \$862,125 | \$543,250 | \$6,800,948 |
| 12 | 5 | University of Colorado at Boulder Upgrade Central Fire Alarm Systems, Ph 3 of 4 | M90032 | \$430,703 | \$422,460 | \$7,231,651 |
| 13 | 5 | Colorado School for the Deaf and Blind Campus Safety/Fire Lanes Upgrade, Ph 1 of 1 | | \$301,000 | \$0 | \$7,532,651 |
| 14 | 5 | University of Colorado at Boulder Chemical Engineering HVAC Upgrades, Ph 1 of 3 | | \$885,876 | \$1,479,732 | \$8,418,527 |
| 15 | 6 | Lamar Community College Fire Alarm/Emergency Lighting Modernization, Bowman/Trustees Buildings, Ph 1 of 2 | | \$207,211 | \$109,947 | \$8,625,738 |
| 16 | 6 | University of Colorado at Boulder Code and Life Safety Upgrades, Various Buildings, Ph 1 of 2 | | \$198,882 | \$201,105 | \$8,824,620 |
| 17 | 8 | Department of Agriculture - Zuni & Insectary BioChem Lab Building System Replacement, Ph 2 of 2 | M00001 | \$259,325 | \$0 | \$9,083,945 |
| 18 | 8 | State Fair - Pueblo Infrastructure Repair/Replacement, Ph 3 of 4 | M90001 | \$1,143,300 | \$1,442,000 | \$10,227,245 |
| 19 | 8 | University of Southern Colorado Replace Deteriorated Steam Distribution System, Ph 2 of 3 | M00035 | \$1,444,144 | \$1,444,143 | \$11,671,389 |

| Ref No. S | Score | Agency Project Title: | Project M# | SBP Recommended Funding | Project Balance | Cumulative Tota of Recommended Projects |
|--------------|-------|--|---------------|-------------------------------|--------------------|--|
| 20 | | Auraria Higher Education Center Repair/Replace Storm Drain System - Campus, Ph 4 of 5 | M80101 | \$667,900 | \$569,200 | \$12,339,289 |
| 21 | 8 | Colorado State University Replace Deteriorated Mechanical, VTH, Ph 1 of 5 | | \$652,599 | \$2,505,951 | \$12,991,888 |
| 22 | | Department of Corrections Upgrade Fire Detection/Alarm/Suppression Systems, Ph 4 of 4 | M90005 | \$1,464,592 | \$0 | \$14,456,480 |
| 23 | 9 | Capitol Complex Facilities Repair Passenger and Freight Elevators in Annex and Centennial Buildings, Ph 1 of 3 | | \$325,670 | \$2,107,820 | \$14,782,150 |
| 24 | | Western State College Repair/Replace Miscellaneous Fire Alarm System, Ph 2 of 2 | M00029 | \$94,050 | \$0 | \$14,876,200 |
| 25 | | Department of Military Affairs Emergency Lighting/Electrical Violations Various Locations, Ph 2 of 3 | M00097 | \$236,293 | \$190,255 | \$15,112,493 |
| 26 | 10 | Adams State College Upgrade Campus Fire Alarm System, Ph 1 of 1 | | \$600,390 | \$0 | \$15,712,883 |
| 27 | 10 | Morgan Community College Main Campus Fire Alarm System Integration, Ph 1 of 1 | | \$130,406 | \$0 | \$15,843,28 |
| 28 | 10 | University of Colorado at Colorado Springs Network Campus Fire Alarm System, Ph 1 of 1 | | \$144,425 | \$0 | \$15,987,714 |
| 29 | 10 | Colorado School of Mines Campus Pool HVAC Replacement, Ph 1 of 2 | | \$887,900 | \$365,240 | \$16,875,614 |
| 30 | 10 | Trinidad State Junior College Campus Electric Power Upgrades, Ph 2 of 2 | M00080 | \$271,175 | \$0 | \$17,146,78 |
| 31 | | Auraria Higher Education Center Repair/Replace Electrical High Voltage Cable System - Campus, Ph 3 of 4 | M90078 | \$1,056,200 | \$708,500 | \$18,202,98 |
| 32 | 10 | Colorado State University Replace Deteriorated Electrical Feeders and Main Campus Feeders, Ph 1 of 1 | | \$632,996 | \$0 | \$18,835,98 |
| 33 | | Cumbres & Toltec Scenic Railroad Commission Antonito Shop Mechanical/Electrical Upgrades, Ph 1 of 1 | | \$61,400 | \$0 | \$18,897,38 |
| 34 | 10 | University of Colorado at Boulder Repair/Replace Building Electrical Services, Ph 1 of 5 | | \$487,526 | \$2,022,588 | \$19,384,91 |
| 35 | | University of Northern Colorado Water Main Improvements Central/West Campus, Ph 1 of 2 | | \$75,418 | \$533,985 | \$19,460,32 |
| 36 | 10 | Colorado State University Replace Deteriorated Items, Music, Ph 1 of 3 | | \$600,586 | \$1,309,869 | \$20,060,91 |
| 37 | 10 | Department of Human Services Repair Structural Problems in Building 54, Ph 1 of 1 | | \$180,000 | \$0 | \$20,240,91 |
| | | Level 1 | Totals: | \$20,240,915 | \$20 280 340 | |

CM Cumulative Totals: \$20,240,915 \$20,280,340

| Ref No. Sc | ore | Agency Project Title: | Project M# | SBP Recommended Funding | Project Balance | Cumulative Tota of Recommended Projects |
|---------------|-----|--|---------------|-------------------------------|--------------------|--|
| LEV | EL | 2 | | | | |
| 38 | | Department of Corrections Repair/Replace Security Systems, Ph 2 of 4 | M00006 | \$538,679 | \$911,072 | \$20,779,594 |
| 39 | | Red Rocks Community College Safety Improvements, Kiln, Ph 1 of 1 | | \$76,336 | \$0 | \$20,855,930 |
| 40 | | Colorado School of Mines Campus Primary Electrical Power Distribution, Ph 1 of 1 | | \$396,740 | \$0 | \$21,252,670 |
| 41 | | Colorado State University Replace Deteriorated Electrical Alyesworth Hall, Ph 1 of 1 | | \$397,895 | \$0 | \$21,650,56 |
| 42 | | State Fair - Pueblo Correct Accessibility Problems on the Fairgrounds, Ph 1 of 4 | | \$275,000 | \$825,000 | \$21,925,56 |
| 43 | | Northeastern Junior College Campus Accessibility Design and Improvements, Ph 1 of 1 | | \$103,481 | \$0 | \$22,029,04 |
| 44 | | Morgan Community College HVAC Repairs to Spruce Hall, Ph 2 of 2 | M00062 | \$237,738 | \$0 | \$22,266,78 |
| 45 | | Department of Military Affairs HVAC Modifications, Various Locations, Ph 1 of 5 | | \$299,104 | \$1,249,028 | \$22,565,88 |
| 46 | | Adams State College Replace/Resurface Stadium Field House Tracks, Ph 2 of 2 | M00027 | \$174,296 | \$0 | \$22,740,18 |
| 47 | | State Capitol Building Renovate State Capitol First Floor Lights, Ph 1 of 1 | | \$466,375 | \$0 | \$23,206,55 |
| 48 | | Colorado Historical Society Ft. Vasquez Energy and Site Security Upgrade, Ph 1 of 1 | | \$150,877 | \$0 | \$23,357,43 |
| 49 | | Department of Corrections Repair Utility Tunnel, Ph 2 of 2 | M90009 | \$1,246,228 | \$0 | \$24,603,664 |
| 50 | | Front Range Community College Small Central Plant to Replace Deteriorating Rooftop HVAC Units, Larimer Campus, Ph 1 of 2 | | \$1,605,604 | \$538,615 | \$26,209,26 |
| 51 | | University of Colorado at Boulder Repair/Replace Obsolete Central HVAC Controls, Ph 3 of 3 | M90035 | \$177,942 | \$0 | \$26,387,21 |
| 52 | | University of Colorado at Colorado Springs Replace HVAC Science Building, Ph 2 of 5 | M90038 | \$590,867 | \$1,433,498 | \$26,978,07 |
| 53 | | University of Colorado Health Sciences Center School of Medicine Exhaust System Replacement, Ph 2 of 4 | M00051 | \$596,695 | \$1,029,100 | \$27,574,77 |
| 54 | | University of Northern Colorado Replace Deteriorated Systems Butler Hancock, Ph 2 of 2 | M00053 | \$480,872 | \$0 | \$28,055,644 |
| 55 | | Colorado State University Replace Deteriorated Items, Wagar, Ph 2 of 3 | M00032 | \$684,877 | \$676,013 | \$28,740,52 |
| 56 | | Pikes Peak Community College Roof Replacement Aspen and Breckenridge Buildings, Ph 2 of 4 | M00088 | \$315,543 | \$514,602 | \$29,056,064 |

| | | | | SBP | | Cumulative Tota of |
|--------------|-------|---|---------------|------------------------|--------------------|-------------------------|
| Ref Io. S | Score | Agency Project Title: | Project M# | Recommended Funding | Project Balance | Recommended Projects |
| 57 | 15 | Arapahoe Community College Roof, Window and Door Replacement: Main, North and Annex, Ph 2 of 2 | M90048 | \$186,538 | \$0 | \$29,242,602 |
| 58 | 15 | Fort Lewis College Replace Sewers/Pavement/Sidewalks, North Campus, Ph 1 of 1 | | \$1,221,885 | \$0 | \$30,464,487 |
| 59 | 16 | University of Colorado at Boulder Campus Steam Tunnel Structural Upgrades, Ph 2 of 3 | M00038 | \$527,391 | \$617,952 | \$30,991,878 |
| 60 | 16 | University of Colorado Health Sciences Center Colorado Psychiatric Hospital Infrastructure, Ph 4 of 4 | M727 | \$394,805 | \$0 | \$31,386,68 |
| 61 | 18 | Colorado Historical Society Ft. Garland Code/Safety Upgrade, Ph 2 of 2 | M00086 | \$134,645 | \$0 | \$31,521,32 |
| 62 | 16 | Adams State College Repair/Replace Stadium Field House Bleachers, Ph 1 of 2 | | \$368,267 | \$170,216 | \$31,889,59 |
| 63 | 18 | Department of Military Affairs Safety Standards Compliance, Various locations, Ph 1 of 3 | | \$329,246 | \$578,929 | \$32,218,84 |
| 64 | 18 | Department of Corrections Repair/Replace Security Systems, Ph 3 of 4 | M00006 | \$408,548 | \$502,524 | \$32,627,38 |
| 65 | 18 | Northeastern Junior College Install Pitched Roofs on Four Main Campus Buildings, Ph 3 of 3 | M90057 | \$525,938 | \$0 | \$33,153,32 |
| 66 | 18 | Colorado Government Technology Services Replace Roofs on Remote TX Buildings (B), Ph 3 of 5 | M90101 | \$53,280 | \$104,520 | \$33,206,60 |
| 67 | 18 | Capitol Complex Facilities Replace Deteriorated Roofs at SOB, Centennial, and Power Plant, Ph 1 of 1 | | \$607,180 | \$0 | \$33,813,78 |
| 68 | 18 | Auraria Higher Education Center Repair/Replace Roofing/Weathertight Enclosures, Ph 2 of 2 | M00081 | \$805,600 | \$0 | \$34,619,38 |
| 69 | 18 | Judicial Heritage Waterproof Sloped Roof and Plaza Deck, Ph 2 of 3 | M00095 | \$539,325 | \$306,812 | \$35,158,71 |
| 70 | 18 | University of Colorado at Boulder Repair/Replace Main Campus Compressed Air System, Ph 1 of 2 | | \$348,780 | \$729,753 | \$35,507,49 |
| 71 | 18 | Colorado State University Replace Deteriorated Refrigeration Units, Ph 1 of 1 | | \$527,495 | \$0 | \$36,034,98 |
| 72 | 18 | Pueblo Community College Replace Boilers and Associated Equipment, Boiler House, Ph 1 of 1 | | \$197,495 | \$0 | \$36,232,48 |
| 73 | 18 | Department of Corrections Replace Boiler Refractory, Ph 1 of 1 | | \$108,051 | \$0 | \$36,340,53 |
| 74 | 18 | University of Colorado Health Sciences Center Power Plant and Campus Cooling System Improvements, Ph 6 of 9 | M728 | \$564,007 | \$1,891,989 | \$36,904,54 |
| 75 | 18 | Department of Human Services Repair/Replace HVAC Systems, Ph 3 of 4 | M90084 | \$375,000 | \$488,118 | \$37,279,54 |
| 76 | 18 | Red Rocks Community College Groundwater Problem - West Building, Ph 2 of 2 | M90072 | \$221,088 | \$0 | \$37,500,62 |
| | | | | | | |

| Ref No. S | Score | Agency Project Title: | Project M# | SBP Recommended Funding | Project Balance | Cumulative Tota of Recommended Projects |
|--------------|-------|--|---------------|-------------------------------|--------------------|--|
| 77 | | Department of Human Services Replace Deteriorated Campus Infrastructure System, CMHIFL, Ph 1 of 5 | | \$575,000 | \$3,000,000 | \$38,075,628 |
| 78 | | Colorado State University Replace Deteriorated Items, Forestry, Ph 1 of 3 | | \$450,700 | \$1,107,350 | \$38,526,328 |
| 79 | | University of Northern Colorado Exterior Building Systems Repair, Ph 3 of 3 | M90045 | \$393,197 | \$0 | \$38,919,525 |
| 80 | | Mesa State College Building Repairs, Walter Walker Fine Arts Center, Ph 3 of 4 | M90020 | \$435,209 | \$467,667 | \$39,354,734 |
| 81 | | Lamar Community College Window Upgrades Bowman/Trustees Buildings, Ph 2 of 2 | M00058 | \$135,192 | \$0 | \$39,489,926 |
| 82 | | Colorado Government Technology Services Replace Emergency Generators, Ph 3 of 5 | M90102 | \$71,060 | \$139,400 | \$39,560,986 |
| 83 | | Department of Agriculture - Zuni & Insectary Metrology Lab Building System Replacement, Ph 2 of 2 | M00002 | \$169,528 | \$0 | \$39,730,514 |
| 84 | | University of Colorado at Boulder Regents Repair/Replace Air Handling Systems, Ph 2 of 2 | M90036 | \$608,030 | \$0 | \$40,338,544 |
| 85 | | Capitol Complex Facilities Variable Air Volume Boxes Replacement at Centennial Building, Ph 1 of 1 | | \$1,396,800 | \$0 | \$41,735,344 |
| 86 | | Colorado School for the Deaf and Blind Electrical Distribution Upgrade, Ph 2 of 3 | M00025 | \$212,128 | \$247,758 | \$41,947,472 |
| 87 | | Fort Lewis College Repair/Replace Geology Storage Building, Ph 1 of 1 | | \$296,744 | \$0 | \$42,244,216 |
| 88 | | Colorado School of Mines Green Center Roof and Abatement Assessment, Ph 1 of 1 | | \$48,620 | \$0 | \$42,292,836 |
| | | Level 2 | Totals: | \$22,051,921 | \$17,529,916 | |

CM Cumulative Totals: \$42,292,836 \$37,810,256

| Ref No. S | Score | Agency Project Title: | Project M# | SBP Recommended Funding | Project Balance | Cumulative Tota of Recommended Projects |
|--------------|-------|---|---------------|-------------------------------|--------------------|--|
| LE | VEL | . 3 | | | | |
| 89 | 21 | Department of Public Safety CSP Academy/CGW Repairs, Ph 2 of 3 | M00105 | \$304,962 | \$149,122 | \$42,597,79 |
| 90 | 21 | Department of Corrections Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 2 of 4 | M90007 | \$395,950 | \$996,784 | \$42,993,74 |
| 91 | 21 | Colorado State University Install East Drive to Center Street Steam Loop, Ph 3 of 3 | M90025 | \$619,386 | \$0 | \$43,613,13 |
| 92 | 21 | University of Colorado at Boulder Drainage Improvements, Main Campus, East Half, Ph 2 of 2 | M00043 | \$449,807 | \$0 | \$44,062,94 |
| 93 | 21 | Colorado State University Replace Deteriorated Roads and Sidewalks, Ph 2 of 5 | M00033 | \$293,191 | \$861,207 | \$44,356,13 |
| 94 | 21 | University of Northern Colorado Replace Deteriorated Stairs and Walkways Campus Wide, Ph 2 of 2 | M00054 | \$580,480 | \$0 | \$44,936,61 |
| 95 | 24 | Department of Military Affairs Armory Roof Replacements, Ph 2 of 5 | M00098 | \$214,413 | \$755,408 | \$45,151,02 |
| 96 | 24 | Colorado State University Replace Deteriorated Roofing Various Buildings, Ph 2 of 2 | M00034 | \$328,930 | \$0 | \$45,479,95 |
| 97 | 24 | Colorado School of Mines Campus Secondary Electrical Power Repair Deficiency Assessment, Ph 1 of 1 | | \$55,176 | \$0 | \$45,535,13 |
| 98 | 24 | University of Colorado at Colorado Springs Repair/Replace Water Main Valves, Ph 1 of 1 | | \$73,986 | \$0 | \$45,609,11 |
| 99 | 24 | Department of Human Services Repair/Replace Campus Tunnel and Utility Infrastructure System, CMHIP, Ph 1 of 5 | | \$1,057,801 | \$3,882,000 | \$46,666,91 |
| 100 | 24 | Adams State College Upgrade Campus Irrigation, Ph 1 of 3 | | \$25,000 | \$1,340,976 | \$46,691,91 |
| 101 | 24 | Colorado Government Technology Services Replace Batteries for Back-Up Generators, Ph 2 of 3 | M00104 | \$87,780 | \$28,700 | \$46,779,69 |
| 102 | 24 | Department of Corrections Repair/Replace Water Treatment and Piping Systems, Ph 1 of 1 | | \$368,648 | \$0 | \$47,148,34 |
| 103 | 24 | Fort Lewis College Replace Deteriorated Tennis Courts, Ph 1 of 2 | | \$94,090 | \$790,900 | \$47,242,43 |
| 104 | 24 | University of Colorado Health Sciences Center Colorado Psychiatric Hospital, Window Replacement, Ph 1 of 2 | | \$515,000 | \$425,000 | \$47,757,43 |
| 105 | 24 | Western State College Repair/Replace Heating/HVAC, Systems, Ph 1 of 1 | | \$396,210 | \$0 | \$48,153,64 |
| 106 | 24 | Colorado Historical Society Trinidad Site Accessibility and Building Improvements, Ph 1 of 1 | 9 | \$293,572 | \$0 | \$48,447,21 |
| 107 | 24 | Colorado State University Replace Deteriorated Items, San Luis Valley and CSFS Foothills, Ph 1 of 1 | | \$294,042 | \$0 | \$48,741,26 |

| | | | | SBP | | Cumulative Total of |
|--------------|-------|--|---------------|------------------------|--------------------|-------------------------|
| Ref No. S | Score | Agency e Project Title: | Project M# | Recommended Funding | Project Balance | Recommended Projects |
| 108 | 24 | Western State College Repair/Replace Parking Lots/Streets - Zone 1, Ph 2 of 5 | M00030 | \$365,279 | \$936,926 | \$49,106,539 |
| 109 | 24 | Camp George West Limited CGW Paving and Removal of 2 Hazardous Buildings, Ph 1 of 1 | | \$122,346 | \$0 | \$49,228,885 |
| 110 | 28 | Department of Corrections Repair/Replace Roofs, Ph 3 of 4 | M80022 | \$345,540 | \$135,110 | \$49,574,425 |
| 111 | 28 | Pueblo Community College Replace HVAC System and Roof Repair Health Science Annex, Ph 1 of 1 |) | \$162,659 | \$0 | \$49,737,084 |
| 112 | 28 | University of Northern Colorado Replace Theater Ceiling Frasier Hall, Ph 1 of 1 | | \$360,792 | \$0 | \$50,097,876 |
| 113 | 30 | University of Colorado at Colorado Springs Repair Campus Infrastructure, Ph 1 of 3 | | \$297,812 | \$794,327 | \$50,395,688 |
| 114 | 30 | Arapahoe Community College Structural/Exterior Concrete Repair Main Annex, Ph 2 of 2 | M00055 | \$375,573 | \$0 | \$50,771,261 |
| 115 | 30 | Trinidad State Junior College Repair Basketball/Volleyball Courts and Campus Streets/Parking Lots, Ph 1 of 1 | | \$253,710 | \$0 | \$51,024,971 |
| 116 | 30 | Department of Human Services Repair/Replace Secondary Electrical Systems, Ph 3 of 3 | M90083 | \$698,750 | \$0 | \$51,723,721 |
| 117 | 30 | Pikes Peak Community College Lighting and Controls Retrofit Aspen and Breckenridge Buildings, Ph 1 of 2 | 9 | \$325,629 | \$235,801 | \$52,049,350 |
| 118 | 30 | Colorado Northwestern Community College HVAC Modifications and Upgrade - Rangely Campus, Ph 1 of 1 | | \$611,500 | \$0 | \$52,660,850 |
| 119 | 30 | Otero Junior College Wheeler/Life Science HVAC Equipment Replacement, Ph 1 of 2 | | \$202,118 | \$92,705 | \$52,862,968 |
| 120 | 30 | Arapahoe Community College Replace HVAC Equipment, Ph 1 of 2 | | \$383,179 | \$197,510 | \$53,246,147 |
| 121 | 30 | Red Rocks Community College Replace Expansion Tank, Ph 1 of 1 | | \$38,284 | \$0 | \$53,284,431 |
| 122 | 30 | Capitol Complex Facilities Upgrade/Replace Domestic Water Pump Systems and Heat Exchangers, Ph 1 of 1 | | \$326,315 | \$0 | \$53,610,746 |
| 123 | 30 | Mesa State College Building Repairs - Houston Hall, Ph 4 of 4 | M80034 | \$325,493 | \$0 | \$53,936,239 |
| 124 | 30 | Adams State College Replace Doors/Windows, Various Buildings, Ph 1 of 2 | | \$393,657 | \$282,238 | \$54,329,896 |
| 125 | 30 | Judicial Heritage Repair Building Exterior, Ph 1 of 1 | | \$42,680 | \$0 | \$54,372,576 |
| 126 | 30 | Colorado School for the Deaf and Blind Roof Repair/Replacement Campus-wide, Ph 3 of 3 | M80029 | \$164,813 | \$0 | \$54,537,389 |
| 127 | 30 | Western State College Repair/Replace Roofing System, Ph 1 of 2 | | \$275,375 | \$232,000 | \$54,812,764 |

| | | | | SBP | | Cumulative Total of |
|------------|-------|--|---------------|------------------------|--------------------|-------------------------|
| Ref No. | Score | Agency Project Title: | Project M# | Recommended Funding | Project Balance | Recommended Projects |
| 128 | 30 | State Capitol Building Repair/Replace State Capitol Roof, Ph 1 of 1 | | \$511,890 | \$0 | \$55,324,654 |
| 129 | 32 | Department of Corrections Replace Mechanical/Plumbing Systems, Ph 1 of 2 | | \$242,770 | \$255,970 | \$55,567,424 |
| 130 | 35 | Mesa State College Electrical Service and Lighting Houston Hall, Ph 1 of 1 | | \$468,160 | \$0 | \$56,035,584 |
| 131 | 36 | Auraria Higher Education Center Replace Fire Security Monitoring Infrastructure System - Campus, Ph 1 of 1 | | \$858,000 | \$0 | \$56,893,584 |
| 132 | 36 | Front Range Community College Repair Deficiencies in Electrical Switch Gear, Westminster Campus, Ph 1 of 3 | | \$201,488 | \$1,185,224 | \$57,095,072 |
| 133 | 36 | Colorado State University Replace Deteriorated Mechanical, VTH, Ph 2 of 5 | | \$633,686 | \$1,872,265 | \$57,728,758 |
| 134 | 36 | University of Colorado Health Sciences Center Campus Elevator Upgrades, Ph 1 of 4 | | \$550,000 | \$1,225,000 | \$58,278,758 |
| 135 | 36 | Department of Corrections South Pump House and Water Distribution System Improvements, Ph 1 of 1 | | \$585,300 | \$0 | \$58,864,058 |
| 136 | 36 | University of Colorado at Boulder Storm/Sanitary Sewer Cross Connection, Ph 1 of 1 | | \$235,903 | \$0 | \$59,099,961 |
| 137 | 40 | Western State College Repair/Replace Pool and Filter System, Ph 1 of 2 | | \$234,598 | \$300,000 | \$59,334,559 |
| 138 | 42 | University of Southern Colorado Replace Electrical Panels and Transformers, Ph 1 of 3 | | \$275,000 | \$450,000 | \$59,609,559 |
| 139 | 42 | Colorado Historical Society Upgrade Building Deficiencies, Fort Garland, Ph 1 of 1 | | \$175,055 | \$0 | \$59,784,614 |
| 140 | 42 | University of Northern Colorado Replace Deteriorated Systems Gray Hall, Ph 1 of 3 | | \$824,296 | \$1,170,430 | \$60,608,910 |
| 141 | 42 | University of Colorado Health Sciences Center Office Annex Window Replacement, Ph 1 of 2 | | \$280,000 | \$275,000 | \$60,888,910 |
| 142 | 42 | Department of Corrections Window Replacement, Ph 1 of 1 | | \$219,688 | \$0 | \$61,108,598 |
| 143 | 42 | University of Colorado at Boulder Repair/Replace Deteriorated Roadways, Ph 2 of 2 | M00040 | \$157,129 | \$0 | \$61,265,727 |
| 144 | 42 | Fort Lewis College Replace Sewers/Pavement/Sidewalks, Central Campus, Ph 1 of 3 | | \$223,382 | \$1,733,820 | \$61,489,109 |
| 145 | 42 | Colorado State University Replace Deteriorated Roads and Sidewalks, Ph 3 of 5 | M00033 | \$260,024 | \$601,183 | \$61,749,133 |
| 146 | 45 | Otero Junior College McDivitt Hall Roof Replacement, Ph 1 of 1 | | \$184,247 | \$0 | \$61,933,380 |
| 147 | 45 | Western State College Repair/Replace Parking Lots/Streets - Zone 1, Ph 3 of 5 | M00030 | \$329,394 | \$607,532 | \$62,262,774 |
| 148 | 45 | Department of Military Affairs Paving Projects Various Locations, Ph 1 of 5 | | \$355,069 | \$1,060,084 | \$62,617,843 |
| 149 | 48 | Morgan Community College Replace HVAC units and Controls, Cottonwood Hall, P 1 of 2 | h | \$563,500 | \$302,780 | \$63,181,343 |

| Ref No. Scor | Agency e Project Title: | Project M# | SBP Recommended Funding | Project Balance | Cumulative To of Recommende Projects |
|-----------------|---|---------------|-------------------------------|--------------------|---|
| 150 48 | Department of Human Services Repair/Replace Elevator, Ph 1 of 1 | | \$405,000 | \$0 | \$63,586,34 |
| 151 48 | Colorado State University Replace Deteriorated Items, Wagar, Ph 3 of 3 | M00032 | \$676,013 | \$0 | \$64,262,3 |
| 152 48 | Department of Military Affairs Exterior Closure Replacement, Ph 2 of 4 | M00099 | \$279,734 | \$829,942 | \$64,542,0 |
| 153 48 | Adams State College Replace Sewer Line Richardson Hall and Business and Economics, Ph 1 of 1 | l | \$132,319 | \$0 | \$64,674,4 |
| 154 48 | University of Colorado at Boulder Replace Chemistry and Ekeley Generators, Ph 1 of 5 | | \$585,600 | \$2,482,610 | \$65,260,0 |
| 155 48 | University of Southern Colorado Campus Structural Repairs/Safety Study, Ph 1 of 1 | | \$180,000 | \$0 | \$65,440,0 |
| 156 54 | Colorado School of Mines Campus Pool HVAC Replacement, Ph 2 of 2 | | \$365,240 | \$0 | \$65,805,2 |
| 157 54 | Northeastern Junior College Replace HVAC Units, Ph 1 of 1 | | \$35,685 | \$0 | \$65,840,9 |
| 158 54 | Red Rocks Community College Replace Multizone HVAC Equipment, Ph 1 of 1 | | \$211,952 | \$0 | \$66,052,8 |
| 159 54 | Department of Human Services Heating Plant and Infrastructure Upgrade, Ph 1 of 1 | | \$561,000 | \$0 | \$66,613,8 |
| 160 54 | Pueblo Community College Repair Interior and Exterior Deteriorating Items, Academic Building, Ph 1 of 1 | | \$214,965 | \$0 | \$66,828,8 |
| 161 63 | Trinidad State Junior College Interior Repair/Replacement Davis/Berg/Mullen Buildings, Ph 1 of 2 | | \$250,000 | \$250,000 | \$67,078,8 |
| 162 63 | Pikes Peak Community College Plumbing Fixture Replace Aspen and Breckenridge Buildings, Ph 1 of 1 | | \$92,167 | \$0 | \$67,171,0 |
| 163 63 | Morgan Community College Campus Wide Utility Infrastructure Analysis, Ph 1 of 1 | | \$50,950 | \$0 | \$67,221,9 |
| 164 72 | University of Colorado at Colorado Springs Repair Campus Infrastructure, Ph 2 of 3 | | \$501,744 | \$292,583 | \$67,723,7 |
| 165 72 | Capitol Complex Facilities Secondary Electrical Power Service Upgrade, Ph 1 of 1 | | \$380,870 | \$0 | \$68,104,5 |
| 166 84 | Trinidad State Junior College East Boundary Retaining Wall Repair/Stabilize, Ph 1 of 1 | | \$195,200 | \$0 | \$68,299,7 |
| 167 84 | University of Colorado at Colorado Springs Replace Exterior Lighting, Ph 1 of 1 | | \$154,500 | \$0 | \$68,454,2 |
| 168 84 | Colorado Historical Society Silver Plume Depot Site Upgrade, Ph 1 of 1 | | \$326,551 | \$0 | \$68,780,8 |
| | Level 3 | Totals: | \$26,487,997 | \$27.031.137 | |

| Level | 3 | Totals: | \$26,487,997 | \$27,031,137 |
|-----------------------|------|----------|--------------|--------------|
| CM Cumula | tive | Totals: | \$68,780,833 | \$64,841,393 |
| FY01/02 Recommended G | Gran | d Total: | \$68,780,833 | |

IV. SBP PRIORITIZED STATEWIDE PROJECT REQUEST DESCRIPTIONS

The following 168 pages provide a brief written description and photographic representation of each controlled maintenance project request at the funding levels recommended by State Building Programs.

The reference number, project score, Division of Risk Management ID Number (RM#) and funding amounts correspond directly to those found in Section III (SBP Prioritized Statewide Funding Recommendations) and Section VIII (Agency Prioritized Five Year Plan Project Requests). Please note that an accounting of prior, present and future phase funding is included for every project request in chart format. The actual current phased dollar amount recommended for FY 01/02 is highlighted in the chart by **bold** letters and numbers. It is suggested that, where project funding is recommended by the Committee consistent with State Buildings recommendations, the titles in this section should be used for appropriation purposes.

Ref.

1

Score No.

> 1 State Buildings and Real Estate Programs

Emergency Fund

The Emergency Fund appropriation is included in the annual Controlled Maintenance Budget as priority number one. Typically the demand for these funds are on an as-needed basis through out the fiscal year. State Buildings and Real Estate Programs administers the fund and approves/disapproves funding directly to state agencies and institutions that own and maintain general funded facilities. Project requests meeting the emergency criteria are immediate in nature and directly affect the health, safety and welfare of the public. Specifically, project requests involving systems and fixed equipment critical to the functionality of a facility are eligible. However, project requests involving moveable equipment, furniture and fixtures related to the programmatic activities conducted in the facility are not eligible for emergency funding. Due to the decrease in demand, SBP proposes \$1,000,000 for the Emergency Fund in 2001/2002. The following lists funding amounts for the current and the last five prior fiscal years. Please refer to chapter 10 for a complete accounting of the last three years of emergency funding.

| PRIOR FL | JNDING | |
|----------|--------------------|-------------|
| FY96/97 | GSS Emergency Fund | \$750,000 |
| FY97/98 | GSS Emergency Fund | \$950,000 |
| FY98/99 | GSS Emergency Fund | \$1,250,000 |
| FY99/00 | GSS Emergency Fund | \$1,250,000 |
| FY00/01 | GSS Emergency Fund | \$1,250,000 |
| CURREN | T REQUEST | |
| FY01/02 | GSS Emergency Fund | \$1,000,000 |

December 5, 2000

Current Funding Recommendation

\$1,000,000

Ref. No. Score Current Funding Recommendation

\$796,300

2 2 Department of Human Services

Suicide Risk Assessment and Prevention, Ph 1 of 1

This project is intended to reduce the risk of self-harm to patients with mental illness or clients who are developmentally disabled. The greatest risks exist in areas where patients/clients are not under continuous staff observation such as bathrooms or sleeping rooms. Modifications proposed include: bathroom privacy partitions; high mounted door closing hardware; exposed ceiling fire sprinkler heads; exposed ceiling-mounted ventilation grills; protruding shower hardware; cable and wiring extending from ceiling tiles to appliances, venetian blind cords and telephone cords; high mounted handles on tall cabinets, all of which represent hanging risks; and lack of audio and video monitoring of patients in seclusion and/or restraint. This project will further evaluate and identify risks and develop conceptual design solutions as well as fund mitigation of the highest priority risks. Colorado Mental Health Institute at Fort Logan is pictured.


| PRIOR PHASING | | FUTURE PHASING | |
|------------------|----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | 5796,300 | All Phases | \$796,300 |











December 5, 2000

Current Funding Recommendation

\$273,333

3 2 Colorado Northwestern Community College

Ref.

No.

Score

Sewer and Electrical Utility Lines Replacement, Rangely Campus, Ph 1 of 1

Approximately 550 feet of 4-inch sewer main line is collapsing from approximately the Hefley Building (RM #7722) to the Blakeslee Building (RM #7728). Periodically the entire sewage system becomes clogged until the line can be cleaned out (approximately 10-12 times a year). The sewer service line from the Rector Building (RM #7727) is suffering the same deterioration. The underground sewage storage tank, part of the original sewage system for the President's Residence (RM # 7725), is also suffering massive scale buildup and deterioration and needs to be removed from the system. With the current campus population the main sewage line should be replaced with an 8-ince line. The 6-inch line should be installed to Rector. The overhead electrical service line that provides all the power to the Rangely campus is old, deteriorated, and dangerous. The power pole equipment is obsolete and replacement parts are no longer available. If the line or power pole equipment should be without power for days or weeks until a repair could be made. The existing service lines and equipment would be replaced with underground service.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$273,333 | All Phases | \$273,333 |







| | | 1 Sector | -a. | |
|---------------------------|-----|----------|-------|------------------|
| | EX. | | | |
| | - | - | . (| THINK SAFETY! |
| DANGER HIGH VOLTAGE | - | 1 | | |
| VOLTAGE | - | K | ·** 2 | |
| | | | | |
| | | | | |
| SWD | - 2 | . 1 . | ×., | |
| | , | | | - |

Ref. No. Score

Recommendation \$1,440,698

Department of Corrections 3 4


Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4

This multi-phase project has evaluated fire and smoke detection and alarm systems at several correctional facilities. Buena Vista Correctional Facility (BVCF) (pictured) does not have a facility-wide comprehensive fire alarm system. Phase 3 will provide a system utilizing an analog addressable fire alarm control panel and peripheral devices (pull stations, detectors, hornstrobes) and control center fire alarm upgrades for the following buildings at BVCF: South Housing Unit (RM #2969), East Housing Unit (RM #2970), Segregation Housing Unit (RM #2973), A/O Housing Unit (RM #2974), North Housing Unit (RM #2975), Administration (RM #2967), Print Shop (RM #2968), and Gymnasium (RM #2971).

| PRIOR PHASING M90005 FY99/00 Ph 1 - BVCF, CCC, CTCF, FCF, CCF FY00/01 Ph 2 - FCF, SCC, LCF, PMC | \$184,800 \$262,499 | FUTURE PHASING FY02/03 Ph 4 - BVCF, CCF, FCF, CCC | \$1,464,592 |
|--|------------------------|--|-------------|
| (FUNDED TO DATE) | \$477,299 | (PROJECT BALANCE) | \$1,464,592 |
| CURRENT PHASE FY01/02 Ph 3 - BVCF | \$1,440,698 | PROJECT TOTAL All Phases | \$3,352,589 |







December 5, 2000

Current Funding

Current Funding

Recommendation

\$193,735

5 3 State Capitol Building

House and Senate Chamber Brass Handrail Safety Improvements, Ph 1 of 1

The existing handrail installation in the House and Senate Chambers of the Capitol Building (RM #137) (pictured) does not meet code requirements. The height of the existing handrails is 36" instead of 42". This violation will be eliminated by upgrading the existing handrails and installing an additional 360 lineal feet of 2" diameter brass handrail. The scope of work also includes all related repairs of the existing handrail structure and connections, re-design and high quality pre-fabrication, welding, and polishing of the curved and straight sections of brass handrails.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$193,735 | All Phases | \$193,735 |









Ref. No. Score

6 4 Department of Revenue

Ref.

No.

Score

Replace Fire Alarm System, Ph 1 of 1

The fire alarm system is not audible in all spaces of the Department of Revenue 1881 Pierce Street building (RM #8142) (pictured) and the visual strobes do not meet current codes. There are three fire alarm panels distributed through the building; the number of panels makes it very hard for the fire department to pinpoint the location of a fire in an emergency. The north wing system was installed in 1972 with high voltage wiring; the south wing was installed in 1983 with a low voltage wiring system making them incompatible with each other and very susceptible to false alarms. This request provides funding for 55% of the project budget reflecting the 55% general funded operations located in the building.

| PRIOR PHASING | CCFE | CF/CFE | FUTURE PHASING | CCFE | CF/CFE |
|-------------------------------|--------------------------|----------------------------|-----------------------------|--------------------------|----------------------------|
| (FUNDED TO DATE) | \$0 | \$0 | (PROJECT BALANCE) | \$0 | \$0 |
| CURRENT PHASE FY01/02 Ph 1 | CCFE \$219,098 | CF/CFE \$179,262 | PROJECT TOTAL All Phases | CCFE \$219,098 | CF/CFE \$179,262 |









Current Funding Recommendation

\$219,098

Ref.

No. Score

Current Funding

Recommendation

\$646,512

7 4 University of Colorado at Boulder

Fire Sprinkler Upgrades Various Buildings A, Ph 3 of 6

Buildings have been constructed at a time when no fire or life safety codes were in effect. Many of the older buildings have open stairs and unprotected corridors. A fire in any part of a floor will quickly spread to other parts of the floor through non-fire-rated corridors and corridor doors. It is therefore proposed that the buildings discussed in this request be provided with complete sprinkler coverage throughout. Sprinklers are the most effective fire protection system at minimizing the risk to life, health, property, and continuity of operations. Phase 3: 100% sprinkler coverage in Environmental Design (RM #9195) and LASP (RM #9201). Fire alarm work in Environmental Design will replace deficient smoke detectors, horns and strobes. Alarm work in Fiske Planetarium (RM #9226) will replace the existing fire alarm control panel, smoke detectors, and horns and strobes. Alarm work in IBG (RM #9248) will also replace devices. Environmental Design is pictured.

| PRIOR PHASING M80053 FY98/99 Ph 1 - Various Buildings FY99/00 Ph 2 - Various Buildings | \$539,755 \$580,433 | FUTURE PHASING FY02/03 Ph 4 - Various Locations FY03/04 Ph 5 - Various Locations FY04/05 Ph 6 - Various Locations | \$1,252,535 \$863,706 \$743,462 |
|---|------------------------|--|---------------------------------------|
| (FUNDED TO DATE) | \$1,120,188 | (PROJECT BALANCE) | \$2,859,703 |
| CURRENT PHASE FY01/02 Ph 3 - Various Locations | \$646,512 | PROJECT TOTAL All Phases | \$4,626,403 |









| Ref. | | |
|------|-------|-------|
| No. | Score | Score |

8 4 Department of Human Services

Fire Alarm System Upgrades, Ph 2 of 2

This project upgrades and replaces fire alarm systems in the youth corrections buildings, nursing homes, and the Grand Junction and Wheat Ridge Regional Centers. Phase 2 replaces internal boards in the main fire alarm panels at Grand Mesa (GMYSC) (RM #2198) and Gilliam Youth Service Centers (GYSC) (RM #2826). Related safety and security issues at GMYSC include intercom repairs, a new camera and monitoring system, exterior lighting modifications, and replacement of the solenoid exterior door hardware system. Twenty-five domiciliary buildings are located 100 yards from a centralized monitoring station in the nursing home building at Homelake State Veterans Nursing Home. Phase 1 funded a new code-compliant fire alarm system supervised by a fire alarm control panel. It has been determined that the elderly, infirm occupants of these domiciliary buildings need additional protection through the use of fire sprinklers. The newly completed facility audit at all Department of Human Services facilities has identified new fire alarm and security system priorities for these facilities; therefore, this project which was originally scheduled for five phases will be terminated at two. GMYSC and Homelake domiciliary buildings are pictured.


| PRIOR PHASING M00090 | | FUTURE PHASING | |
|------------------------------|-----------|-------------------|-----------|
| FY00/01 Ph 1 - DYC, Homelake | \$346,225 | | |
| (FUNDED TO DATE) | \$346,225 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - DYC, Homelake | \$436,056 | All Phases | \$782,281 |













Current Funding Recommendation

\$436,056

December 5, 2000

Ref.

No. Score

9 4 University of Colorado at Boulder

Engineering Center Fire Sprinkler System Upgrades, Ph 2 of 2

Protection of people, property, and continuity of operations are vital in order to fulfill University's mission in the Engineering Center (RM #9238, 9232, 9231 and 9271). The change of use, additions, and renovations, and increases in the number of occupants, have increased fire hazards in these buildings that have been constructed by outdated standards. In addition, increasing use of flammable and hazardous chemicals in the recent years have increased the overall fire hazard in these buildings. Also, the massive size of the Engineering Center complex prevents effective and timely access and fire fighting by Boulder Fire Department. Phase 2: Fire sprinkler work in the north and south towers, classroom wing and computer science wing. Engineering building is pictured.

| PRIOR PHASING M90033 | | FUTURE PHASING | |
|--|-----------|-------------------|-------------|
| FY99/00 Ph 1 - Mechanical/Civil/Aeronautical | \$716,057 | | |
| (FUNDED TO DATE) | \$716,057 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - N & S Towers/Clrms/Comp. Sci. | \$597,240 | All Phases | \$1,313,297 |









Current Funding Recommendation

\$597,240

Current Funding

December 5, 2000

Recommendation

\$335,851

10 4 Otero Junior College

Ref.

No.

Score


Kiva Repair and Code Corrections, Ph 2 of 2

The critical life safety concerns include the lack of fire protection systems (sprinklers, fire alarm and smoke detection); exit stairwells and fire rated corridors. Other code issues concern the lack of building accessibility and handicap accessible restrooms. Phase 1 of this project will correct the major code compliance issues in the Kiva Museum. Phase 2 will address the mechanical and electrical deficiencies. The deterioration of the artifacts do to ultra-violet light and the lack of humidity control would be addressed. The required air changes for the building would be corrected and the building would then meet minimum air quality standards for the occupants. The Kiva Museum (RM #124) is pictured.

| PRIOR PHASING M00067 | | FUTURE PHASING | |
|---------------------------------------|-----------|-------------------|-------------|
| FY00/01 Ph 1 - Access/Fire Protection | \$682,687 | | |
| (FUNDED TO DATE) | \$682,687 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Mechanical/Electrical | \$335,851 | All Phases | \$1,018,538 |
| | | | |









Current Funding Recommendation

11 4 University of Colorado Health Sciences Center

Ref.

No.

Score

Replace Underground Storage Tanks, Ph 2 of 3

Due to emissions permit mandates and other health and safety concerns, the tanks must be removed and replaced with new tanks used for the storage of #2 fuel oil. The current #6 fuel oil is very heavy and viscous, and is high in sulfur content. When burned, the resulting emissions contain excessive sulfur dioxide. The 1990 Federal Clean Air Act sets emission limits. Tank removal includes asbestos abatement of both tank insulation and steam pipe fittings. By reviewing previous boring samples, it appears that ground water contamination is not significant, although this has not been officially verified. The new tank capacity includes two 40,000 gallon tanks. Phase 2 includes tank installation and partial demolition of six existing tanks.

| PRIOR PHASING M00050 | | FUTURE PHASING | |
|----------------------------------|-----------|----------------------------|-------------|
| FY00/01 Ph 1 - Investigation | \$245,000 | FY02/03 Ph 3 - Remediation | \$543,250 |
| (FUNDED TO DATE) | \$245,000 | (PROJECT BALANCE) | \$543,250 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Tank Installation | \$862,125 | All Phases | \$1,650,375 |
| | | | |





\$862,125

Ref.

No. Score

Current Funding Recommendation

\$430,703

12 5 University of Colorado at Boulder

Upgrade Central Fire Alarm Systems, Ph 3 of 4


The existing campus central fire alarm system is old, obsolete, and extremely unreliable. The central fire alarm system notifies the campus and Boulder Fire Department of a fire on campus. The existing network communication system, in the recent past, has crashed leaving the campus without fire protection coverage. Due to the age of the equipment the local service organizations can no longer support this system. Phase 3 - includes replacing smoke detectors in numerous buildings throughout the campus. Old detectors are susceptible to false alarms and are not reliable. Also fire alarm panels will be upgraded to accommodate the new smoke detectors. The Mathematics building (RM #9273) is pictured.

| CURRENT PHASE FY01/02 Ph 3 - Various Buildings | \$430,703 | PROJECT TOTAL All Phases | \$1,581,289 |
|--|-----------|----------------------------------|-------------|
| (FUNDED TO DATE) | \$728,126 | (PROJECT BALANCE) | \$422,460 |
| FY00/01 Ph 2 - Duane, LASP | \$338,158 | | |
| FY99/00 Ph 1 - Various Buildings | \$389,968 | FY02/03 Ph 4 - Various Buildings | \$422,460 |
| PRIOR PHASING M90032 | | FUTURE PHASING | |









December 5, 2000

Ref.

No. Score

13 5 Colorado School for the Deaf and Blind


Campus Safety/Fire Lanes Upgrade, Ph 1 of 1

This project will resolve a number of identified safety issues at CSDB. Currently there are not adequate fire lanes through the campus for the Colorado Springs Fire Department. Cars drive through the campus on the sidewalks. There is a limited number of visual communication banners for staff in the event of an emergency. There is limited ability to observe areas in the buildings for security and safety. This project will address all of these issues by installing fire lanes, removable bollards where sidewalks and parking lots meet, install additional messaging banners and video equipment, and increase the number of doors controlled on the card access system.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$301,000 | All Phases | \$301,000 |







Current Funding Recommendation

\$301,000

December 5, 2000

Current Funding Recommendation

\$885,876

14 5 University of Colorado at Boulder

Chemical Engineering HVAC Upgrades, Ph 1 of 3

The HVAC system in Chemical Engineering (RM #9233) has deteriorated and is unable to maintain comfort levels within the space. To meet current codes and regulations additional outside air needs to be introduced for the system to operate properly. Life safety and code issues also require fume hood replacement, emergency shower and eye washing installations and exhaust air upgrades. This project will modify air handling units, install pre-heat coils, repair or replace terminal boxes, modify the return air system, replace fume hoods, modify exhaust systems, repair or replace exhaust fans, and install fire/smoke dampers to improve return air paths. Phase 1: Will start work on the air distribution system, upgrade air handling units, exhaust fan and fume hood replacement, and HVAC control work. Engineering building is pictured,

Ref.

No.

Score

| FY01/02 Ph 1 - Air Distribution System | \$885,876 | All Phases | \$2,365,608 |
|--|-----------|--|-------------|
| CURRENT PHASE | | PROJECT TOTAL | |
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$1,479,732 |
| | | FY03/04 Ph 3 - Testing & Balancing | \$780,157 |
| | | FY02/03 Ph 2 - Processed Chilled Water | \$699,575 |
| PRIOR PHASING | | FUTURE PHASING | |







December 5, 2000

Current Funding Recommendation

\$207,211

6 Lamar Community College 15

Fire Alarm/Emergency Lighting Modernization, Bowman/Trustees Buildings, Ph 1 of 2

The existing fire alarm systems and emergency/egress illumination are antiquated and require replacement in the Bowman (RM #2773) and Trustees (RM #1774) Buildings. These buildings are approximately 30 years old and retain the original systems. They should be replaced after 15-20 years of service. The fire alarm systems are manually activated only, with no automatic detection and annunciation features. The emergency lighting systems consist of minimal wall packs lighting the original illuminated exit signs and original corridor strip lighting fixtures wired ahead of the main building breaker with no battery backup. Solution is to replace the deficient fire alarm system and emergency lighting system and install a remote alarm panel at the entrance to Bowman Building (pictured). Phase 1 will modernize the Bowman Building. Phase 2 will modernize the Trustees Building.

Ref.

No.

Score

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Trustees | \$109,947 |
|------------------------------|-----------|---|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$109,947 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Design/Bowman | \$207,211 | All Phases | \$317,158 |









Ref.

No. Score

6 University of Colorado at Boulder 16

Code and Life Safety Upgrades, Various Buildings, Ph 1 of 2

Problems identified through the facilities audit process include: Life-Safety/Code deficiencies including inadeguate number of exits, lack of enclosure for fire exits, door hardware deficiencies such as lack of door closures and latching hardware where needed, lack of fire stopping of penetrations, inadequate exit signage, improper exit arrangement, inadequate handrails or guardrails and corridor enclosures. Phase 1 - will install magnetic door holders in Muenzinger (RM #9203), Ramaley (RM #9202), RL-1 (RM #9254), IBG (RM #9248), RL-4 (RM #9250) and Education (RM #9135). New doors and hardware will be added in Muenzinger, RL-1, IBS4 (RM #9167), and IBG. Smoke detectors and heat detectors will be installed in Ramaley, RL-4, and IBS4. Muenzinger and Education will have fire/Smoke dampers installed. Signage and exit signage will be brought up to code in Ramaley, RL-4 and IBS4. Extra room ventilation will be added to Ramaley to allow a door to be closed. New walls with doors and hardware will be added to Education. Existing walls in RL-4 will be extended up to the structure. A stairwaylanding ramp will be added to IBG. A local fire detection and alarm system will be added to IBS4. RL-1 will have an additional fire extinguisher installed. Safety glass will be added (replacing existing glass) to a display case in Education and a fire extinguisher will be installed din RL-1. Fire caulking and fire retardant will be added to Muenzinger wall openings and to IBG carpet, respectively. IBS4's hand rails and guardrails will be brought up to code. Ramaley is pictured.

FUTURE PHASING

Maniaus Lasations

PRIOR PHASING

| (FUNDED TO DATE)\$0(PROJECT BALANCE)\$201,105CURRENT PHASEFOJECT TOTALFY01/02 Ph 1 - Various Locations\$198,802Image: Content of the state o |
|--|
| <image/> |
| <image/> |
| |
| East Campus and Research Park |
| East Campus and Research Park |
| Colorado University of Colorado at Boulder |

December 5, 2000

Current Funding Recommendation

\$198,882

0004 40F

Ref.

No. Score

17 8 Department of Agriculture - Zuni & Insectary

BioChem Lab Building System Replacement, Ph 2 of 2

BioChemistry Facility (RM #1001) serves as a testing center for grains, fertilizers, blood and other agricultural products and byproducts. It also serves as an inspection facility and working laboratory for the division. Improper ventilation hoods in the feed and fertilizer grinding rooms, and ventilation problems in working and storage areas create unsafe working conditions. In terms of laboratory functions, lighting that has outlasted original design longevity is substandard. Restrooms do not conform to building codes. Interior of building evidences aging and deferred maintenance. Proposed remedies: Phase 1 install new downdraft hood at fertilizer room and at feed grinding room, certify all existing hoods, modify ventilation in computer and refrigeration storage areas, upgrade restrooms to meet code, paint entire facility throughout, install new ceiling tiles in all rooms, paint existing grid and vents, and replace existing fluorescent lighting at 2nd floor. Phase 2 includes improving roof drainage, ADA ramp, tuckpointing parapet and new airlock/entry. BioChemistry Facility is pictured.

| PRIOR PHASING M00001 | | FUTURE PHASING | |
|-------------------------------------|-----------|-------------------|-----------|
| FY00/01 Ph 1 - Fume Hoods/Restrooms | \$399,852 | | |
| (FUNDED TO DATE) | \$399,852 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Roof/Airlock | \$259,325 | All Phases | \$659,177 |











Current Funding Recommendation

\$259,325

December 5, 2000

Current Funding Recommendation

\$1,143,300

18 8 State Fair - Pueblo

Ref.


No.

Score

Infrastructure Repair/Replacement, Ph 3 of 4

The problem is a combination of inadequate design and deterioration of water, sewer, and drainage facilities. The connection of storm sewer and sanitary sewer facilities results in frequent sanitary sewer backups and creates an unhealthy situation. The condition of all facilities is poor. There is no outfall to the existing storm system within a reasonable distance in which to discharge drainage. Low flows in the stormwater system contain animal wastes and other pollutants. Water facilities are over 50 years of age and are failing, resulting in low pressure and inadequate fire protection. Phase 1 and 2 will be completed in November 2001. Phase 3 (the dashed area) will finish all the remaining utility repair and replacement as well as the remaining asphalt repair, from the area south of the amphitheater to the area around the north side of the Livestock Pavilion. Phase 4 will finish the project.

| PRIOR PHASING M90001 | | FUTURE PHASING | |
|-----------------------------|-------------|-----------------------------|-------------|
| FY99/00 Ph 1 - 1st Quadrant | \$1,600,920 | FY02/03 Ph 4 - 4th Quadrant | \$1,442,000 |
| FY00/01 Ph 2 - 2nd Quadrant | \$1,552,210 | | |
| (FUNDED TO DATE) | \$3,153,130 | (PROJECT BALANCE) | \$1,442,000 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 3 - 3rd Quadrant | \$1,143,300 | All Phases | \$5,738,430 |
| | | | |



Ref.

No. Score


19 8 University of Southern Colorado

Replace Deteriorated Steam Distribution System, Ph 2 of 3

Aging steam lines have not been replaced since installation. Outer conduit has been deeply corroded or in some cases has completely corroded away. Water is breaching the protective linings and is initiating corrosive processes on the steam and condensate piping. Original bitumastic waterproofing finishes to manholes have lost their effectiveness. Manholes are often found with significant impounded water. Major breakdowns have occurred yearly since 1994. Major repairs in winter would shut down the campus for an indefinite period of time. This project will replace the aging steam system components remaining outside of the CM Project M616. Phase 1 initial design and work on distribution system. Phase 2 this will include construction work on the distribution system and connection to buildings. Phase 3 this will include construction work on the distribution system and supply.

| PRIOR PHASING M00035 FY00/01 Ph 1 - Primary Loops | \$987,552 | FUTURE PHASING FY02/03 Ph 3 - Secondary Loops | \$1,444,143 |
|---|-------------|--|-------------|
| (FUNDED TO DATE) | \$987,552 | (PROJECT BALANCE) | \$1,444,143 |
| CURRENT PHASE FY01/02 Ph 2 - Secondary Loops | \$1,444,144 | PROJECT TOTAL All Phases | \$3,875,839 |





December 5, 2000

Current Funding Recommendation

\$1,444,144

Ref.

No. Score


20 8 Auraria Higher Education Center

Repair/Replace Storm Drain System - Campus, Ph 4 of 5

The campus relies on a century old storm sewer system inherited without improvements before the campus was built in the 1970's. Studies show the system is insufficient for five-year storm run-off and largely inadequate for two-year run-off. This limited system results in extensive water damage as frequently as three times per year. Phase 3, provides for the replacement of lines in basin A from Ninth Street near Tivoli, west to 7th Street, south to Curtis, then west to 6th. Phases 4 and 5 are for the balance of Basin A and for Basins B and C.

| CURRENT PHASE FY01/02 Ph 4 - Basins A3 + C | \$667,900 | PROJECT TOTAL All Phases | \$2,536,700 |
|---|-------------|-----------------------------|-------------|
| (FUNDED TO DATE) | \$1,299,600 | (PROJECT BALANCE) | \$569,200 |
| FY00/01 Ph 3 - Basin A2 | \$439,200 | | |
| FY99/00 Ph 2 - Basin A | \$701,400 | | |
| FY98/99 Ph 1 - Design | \$159,000 | FY02/03 Ph 5 - Basin B | \$569,200 |
| PRIOR PHASING M80101 | | FUTURE PHASING | |





Current Funding Recommendation

\$667,900

Current Funding

Recommendation

\$652,599

21 8 Colorado State University

Replace Deteriorated Mechanical, VTH, Ph 1 of 5

The HVAC system in the Veterinary Teaching Hospital (VTH) (RM #3445) is 20 years old, and in need of replacement. Heating coils and cooling coils are corroded and leaking. Fan wheels are cracked, indicating the possibility of structural failure. Leaks in coils, expansion valves and capillary tubes result in losses of HCFC's. Phase 1 builds the chiller building and installs the chiller. Phase 2 installs the chiller equipment and 1 RTU. Phase 2 installs 2 RTU's. Phase 3 installs 2 RTU's. Phase 4 installs 4 RTU's. Phase 5 installs 1RTU and provides water and air balance.


Score

Ref.

No.

| PRIOR PHASING | | FUTURE PHASING FY02/02 Ph 2 - RTU's - A & B FY03/04 Ph 3 - RTU's - C & D FY04/05 Ph 4 - RTU's - E, F, G & H | \$633,686 \$676,180 \$676,180 |
|--------------------------------------|-----------|--|-------------------------------------|
| (FUNDED TO DATE) | \$0 | FY05/06 Ph 5 - RTU - I/Balancing (PROJECT BALANCE) | \$519,905 \$2,505,951 |
| CURRENT PHASE FY01/02 Ph 1 - Chiller | \$652,599 | PROJECT TOTAL All Phases | \$3,158,550 |









Ref. No. Score

22 8 Department of Corrections

Upgrade Fire Detection/Alarm/Suppression Systems, Ph 4 of 4

Buena Vista Correctional Facility (BVCF) and Colorado Correctional Center (CCC) do not have comprehensive fire alarm systems. Phase 4 will provide a system utilizing an analog addressable fire alarm control panel and peripheral devices (pull stations, detectors, hornstrobes) for fifteen additional buildings including the Main Kitchen and Dining (RM #2976) at BVCF and twenty buildings at CCC as well as the Administration Building (RM #1367) at Fremont Correctional Facility and the Boiler Room/Dock (RM #3019) at Centennial Correctional Facility (CCF). The project also includes physical (wall, window, mechanical equipment) and equipment upgrades to control rooms at BVCF, CCC, and FCF. CCC is pictured.

| PRIOR PHASING M90005 | | FUTURE PHASING | |
|--|-------------|-------------------|-------------|
| FY99/00 Ph 1 - BVCF, CCC, CTCF, FCF, CCF | \$184,800 | | |
| FY00/01 Ph 2 - FCF, SCC, LCF, PMC | \$262,499 | | |
| FY01/02 Ph 3 - BVCF | \$1,440,698 | | |
| (FUNDED TO DATE) | \$1,887,997 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 4 - BVCF, CCF, FCF, CCC | \$1,464,592 | All Phases | \$3,352,589 |
| | | | |







Current Funding Recommendation

Ref.

Score No.

23 9 **Capitol Complex Facilities**

Repair Passenger and Freight Elevators in Annex and Centennial Buildings, Ph 1 of 3

The three passenger elevators and one freight elevator in the Annex Building (RM #138) (lower pictures) are more than 20 years old and need to be repaired to prevent potential injury accidents. The six passenger elevators and one freight elevator in the Centennial Building (RM #140) (upper pictures) are 25 years old and also need to be repaired to prevent potential accidents. The elevators have been malfunctioning for several years and now require constant attention and repairs. The following modernization repairs are required: installation of new controller and drive equipment in the elevator machine room, new door operators including work on electrical power connections, circuit breakers and switches, additional rewiring, a cooling system upgrade for new controls, repair of doors and interiors, and replacement of inadequate safety devices. Phase 1 will include design. Phase 2 will repair the Annex elevators with Phase 3 repairing those in Centennial.

| PRIOR PHASING | | FUTURE PHASING | • |
|-----------------------|-----------|------------------------------------|-------------|
| | | FY02/03 Ph 2 - Annex Building | \$849,420 |
| | | FY03/04 Ph 3 - Centennial Building | \$1,258,400 |
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$2,107,820 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Design | \$325,670 | All Phases | \$2,433,490 |











Current Funding Recommendation

\$325,670

Ref.

No. Score

24 9 Western State College

Repair/Replace Miscellaneous Fire Alarm System, Ph 2 of 2

The present fire alarm systems do not function. The main panel is in trouble alarm with parts being obsolete and the manufacture can not supply. Smoke detectors do not function and the wiring throughout the system is worn and the insulation is broken exposing the wiring. Phase 2 includes Old Savage (RM #102) and Maintenance (RM #103) - Installing a new fire alarm system throughout the buildings new smoke detectors, wiring, hold open devices, horns, strobes, and new fire alarm control panels. Old Savage is pictured.

| FUTURE PHASING | |
|-------------------|-------------------|
| (PROJECT BALANCE) | \$0 |
| PROJECT TOTAL | 050 |
| | (PROJECT BALANCE) |





December 5, 2000

Current Funding Recommendation

Current Funding

\$94,050

Current Funding

December 5, 2000

Recommendation

\$236,293

25 9 Department of Military Affairs

Emergency Lighting/Electrical Violations Various Locations, Ph 2 of 3

The Facilities Assessment Report has identified numerous code violations and unsafe conditions pertaining to exit and egress lighting and the electrical service for various buildings within the Department. Exit and egress lighting must be retrofitted to meet minimal safety requirements. The electrical service equipment is obsolete and deteriorated including the main distribution equipment, service conductors, panel board, branch circuits, and other related equipment. GFI outlets need to be retrofitted in the wet areas. Fire alarm systems are required to be repaired or installed for the safety of the occupants. Phase 2 included the Grand Junction Armory (RM #935) (pictured), along with ten other locations.

| PRIOR PHASING M00097 | CCFE | FF | FUTURE PHASING | CCFE | FF |
|----------------------------------|------------------|-----------------|----------------------------------|------------------|-----------------|
| FY00/01 Ph 1 - Various Locations | \$234,450 | \$50,000 | FY02/03 Ph 3 - Various Locations | \$190,255 | \$54,845 |
| (FUNDED TO DATE) | \$234,450 | \$50,000 | (PROJECT BALANCE) | \$190,255 | \$54,845 |
| CURRENT PHASE | CCFE | FF | PROJECT TOTAL | CCFE | FF |
| FY01/02 Ph 2 - Various Locations | \$236,293 | \$77,833 | All Phases | \$660,998 | \$182,678 |









Ref.



December 5, 2000

Current Funding Recommendation

\$600,390

26 10 Adams State College

Ref.

No.

Score

Upgrade Campus Fire Alarm System, Ph 1 of 1


Buildings on campus require connection to main reporting fire alarm control panels to be located in both Facilities Services and Public Safety buildings as well as the other buildings listed in the general fund. This is now possible with the anticipated completion of the campus technology project. Older buildings on campus require annunciators at the main entrances, smoke detectors at corridors and special hazard rooms, elevator recall modules, duct detectors on all fans over 2000 C.F.M. and horn strobes per ADA and NFPA requirements. Buildings included are: Facilities Services (RM #170), Business & Economics (RM #158), Richardson (RM #157), Music (RM #159), Leon (RM #160), Plachy (RM #163), Porter (RM #766), Planetarium (RM #156), President Residence (RM #171), Library (RM #167), Public Safety (RM #165), Fine Arts (RM #155).

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$600,390 | All Phases | \$600,390 |









December 5, 2000

| Ref. No. | Score | | | urrent Funding commendation |
|-------------|--------|---|----------------|-----------------------------|
| 27 | 10 | Morgan Community College | | \$130,406 |
| Mai | in Can | pus Fire Alarm System Integration, Ph 1 of | I | |
| | • | st will tie all the fire alarm panels within their building ew visual/audible fire devices in the Spruce (RM #74 | • | This request |
| PRIC | OR PHA | SING | FUTURE PHASING | |

| FRIOR FRASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$130,406 | All Phases | \$130,406 |





Current Funding

December 5, 2000

Recommendation

28 10 University of Colorado at Colorado Springs

Network Campus Fire Alarm System, Ph 1 of 1

Campus fire and burglar alarms are not centrally monitored. This project will network all alarm systems to a central point in the Public Safety Department (pictured) of the Campus Services Building (RM #9005). Completion will enhance safety and response time. Additionally, centralization will save approximately \$12,000 per year currently being expended for monitoring services.

| PRIOR PHASING | |
|---------------|--|
| | |

| (FUNDED TO DATE) |
|------------------|
| CURRENT PHASE |
| FY01/02 Ph 1 |


Ref.

No.

Score

| | FUTURE PHASING | |
|-----------|-------------------|-----------|
| \$0 | (PROJECT BALANCE) | \$0 |
| | PROJECT TOTAL | |
| \$144,425 | All Phases | \$144,425 |





\$144,425

Current Funding Recommendation

December 5, 2000

\$887,900

29 10 Colorado School of Mines

Ref.

No.

Score

Campus Pool HVAC Replacement, Ph 1 of 2

This project provides replacement of the air handlers and air distribution systems for the campus pool facility in Volk Gymnasium (RM #4146) (pictured) that were not included in the campus HVAC Systems Replacement Project (M627). The remaining air handlers in this building are over 40 years old. These air handlers are beyond their useful life and are not capable of delivering the quantities of outside air required to meet current standards for indoor air quality. This building is not in compliance with ventilation requirements of the current building code or ASHRAE Standard 62R. The existing ventilation system uses the corridors to return air to the units and uses stairwells as air plenums. This arrangement is a fire hazard and poses a serious risk to the life safety of students and faculty who use this facility seven days a week.

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Auxiliary Spaces | \$365,240 |
|---------------------|-----------|---|-------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$365,240 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Pool | \$887,900 | All Phases | \$1,253,140 |
| | | | |









Current Funding Recommendation

\$271,175

30 10 Trinidad State Junior College

Ref.

No.


Score


Campus Electric Power Upgrades, Ph 2 of 2

Berg Building (RM #205) was constructed in 1940 and the Mullen Building (RM #202) in 1946. The buildings have had some minor electrical improvements over the years, but with modern electronic equipment in offices and classrooms the wiring is inadequate. There are numerous code violations and overloaded circuits. The Davis Building (RM #203) was constructed in 1968 and the electrical system needs upgrades including isolated grounding and distribution adjustments. Phase 1 included the Berg and Davis Buildings. Phase 2 includes the Mullen Building. The Mullen Building is pictured.

| \$259,500 | FUTURE PHASING | |
|-----------|-------------------|--|
| \$259,500 | (PROJECT BALANCE) | \$0 |
| | PROJECT TOTAL | |
| \$271,175 | All Phases | \$530,675 |
| | \$259,500 | \$259,500 \$259,500 (PROJECT BALANCE) PROJECT TOTAL |







Ref.

No. Score

31 10 Auraria Higher Education Center

Repair/Replace Electrical High Voltage Cable System - Campus, Ph 3 of 4

The 24 year old XLPE high-voltage cable on campus has exceeded its known 15 to 20 year service life, putting the campus in an extremely vulnerable position, and needs to be replaced with the newer EPR cable. For safety reasons, the load break terminals (used for switching) need to be relocated out and away from the manholes, which frequently contain water to remote switchgear locations. In addition, the circuits in the manholes are too closely grouped and need to be separated to prevent others from being extensively damaged if one were to fail. Phase 2 provides for replacement of the portion related to circuits 1A/1B. Phase 3 provides for the replacement of the portion related to circuits 3A/3B.

| PRIOR PHASING M90078 | | FUTURE PHASING | |
|-------------------------------|-------------|-------------------------------|-------------|
| FY99/00 Ph 1 - Design | \$293,900 | FY02/03 Ph 4 - Circuits 3A/3B | \$708,500 |
| FY00/01 Ph 2 - Circuits 1A/1B | \$760,600 | | |
| (FUNDED TO DATE) | \$1,054,500 | (PROJECT BALANCE) | \$708,500 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 3 - Circuits 2A/2B | \$1,056,200 | All Phases | \$2,819,200 |
| | | | |





December 5, 2000

Current Funding Recommendation

\$1,056,200


Ref. No. Score

32 10 Colorado State University

Replace Deteriorated Electrical Feeders and Main Campus Feeders, Ph 1 of 1

The original building transformers and primary feeders are over 30 years old. These systems are obsolete, beyond their useful life and replacement parts are no longer available. The main campus feeder will provide a backup power feed to the main campus substation. This project replaces transformers and primary electrical feeders to several buildings and provides a third primary feeder to the main campus substation.

| PRIOR PHASING (FUNDED TO DATE) | \$0 | FUTURE PHASING (PROJECT BALANCE) | \$0 |
|-----------------------------------|-----------|-------------------------------------|-----------|
| CURRENT PHASE FY01/02 Ph 1 | \$632,996 | PROJECT TOTAL All Phases | \$632,996 |



Current Funding Recommendation

\$632,996

December 5, 2000

Current Funding Recommendation

\$61,400

33 10 Cumbres & Toltec Scenic Railroad Commission

Ref.

No.

Score

Antonito Shop Mechanical/Electrical Upgrades, Ph 1 of 1

The Antonito Shop (RM #n/a) is deficient in heating capacity and ventilation. The existing heating system is undersized and inefficient. The existing unit heaters are designed to heat the air within the space, which is inherently inefficient in a high, vaulted space with high infiltration losses. The existing heating system will be replaced in two stage, 75,000 BTUH infrared tube heaters and an exhaust system and minor ducting will be installed. The electrical service is not sized to handle any additional loads and all panels are covered with soot and are not up to current NEMA standards for dust and vapor. Electrical service will be replaced with greater capacity panels throughout the building. Additionally, lighting levels will be increased to accommodate the light loss caused by the soot and dusty conditions.

| PRIOR PHASING | СО | NM | FUTURE PHASING | CO | NM |
|-------------------------------|-----------------------|-----------------------|-----------------------------|-----------------------|-----------------------|
| (FUNDED TO DATE) | \$0 | \$0 | (PROJECT BALANCE) | \$0 | \$0 |
| CURRENT PHASE FY01/02 Ph 1 | CO \$61,400 | NM \$61,400 | PROJECT TOTAL All Phases | CO \$61,400 | NM \$61,400 |









Current Funding Recommendation

\$487,526

34 10 University of Colorado at Boulder

Repair/Replace Building Electrical Services, Ph 1 of 5

The transformers serving these buildings are old, at or near capacity and most are running hot. The main gear is obsolete and past useful life with parts unavailable. The solution is to replace and relocate the feeding transformers and main distribution switchboards in Engineering Center South Tower (RM #9232) (ECST) and Environmental Design (RM #9195). The Engineering Center is pictured.

FUTURE PHASING

PRIOR PHASING

| CURRENT PHASE FY01/02 Ph 1 - ECST/Environmental Design | \$487,526 | PROJECT TOTAL All Phases | \$2,510,114 |
|---|-----------|--------------------------------|-------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$2,022,588 |
| | | FY05/06 Ph 5 - Porter/Hellems | \$514,036 |
| | | FY04/05 Ph 4 - Muenzinger | \$544,415 |
| | | FY03/04 Ph 3 - Norlin Library | \$439,236 |
| | | FY02/03 Ph 2 - Electrical Eng. | \$524,901 |





December 5, 2000

Ref. No. Score

35 of 168

SBP PRIORITIZED STATEWIDE PROJECT REQUEST DESCRIPTIONS FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

Ref.


No. Score

35 10 University of Northern Colorado

Water Main Improvements Central/West Campus, Ph 1 of 2

Central Campus is located in a low-pressure water main area. Inadequate pressure is causing problems with low flush toilets and the irrigation systems that cannot effectively water the grounds with this level of pressure. West Campus is newer and does not have the same pressure problems. However valving is inadequate, and several buildings are at the end of a "dead leg" supply. This project would upsize some of the Central Campus piping from 4" to 6". The west campus water supply would be upgraded by establishing another feed to the west campus water loop. Phase 1 of this project would hire the civil engineer to design the project and phase 2 would fund the construction phase of this project.

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Construction | \$533,985 |
|-----------------------|----------|---|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$533,985 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Design | \$75,418 | All Phases | \$609,403 |
| | | | |



Current Funding Recommendation

\$75,418

Current Funding

December 5, 2000

Recommendation

\$600,586

36 10 Colorado State University

Replace Deteriorated Items, Music, Ph 1 of 3

All systems in the Music building (RM #3224) are 73 years old and well beyond their life cycle. The heating system will no longer heat the building properly, and the plumbing, electrical and fire alarm systems do not meet code. The skylights leak and are beyond repair. Wood windows are single glazed and the exterior of the frames and sashes have dry rot. Flooring is badly deteriorated and tiles contain asbestos. Phase 1 replaces skylights, windows, flooring, fire alarm system and ceiling tiles. Phase 2 replaces the electrical and plumbing systems. Phase 3 replaces the heating system.

Score


Ref.

No.

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Electrical & Plumbing FY03/04 Ph 3 - Heating System | \$677,248 \$632,621 |
|---|-----------|---|------------------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$1,309,869 |
| CURRENT PHASE FY01/02 Ph 1 - Skylights/Fire Alarm/Flooring | \$600,586 | PROJECT TOTAL All Phases | \$1,910,455 |







Ref.

Score No.

37 10 Department of Human Services

Repair Structural Problems in Building 54, Ph 1 of 1

This project will repair the structural problems along the north wall of Building 54 (RM #2870) at Colorado Mental Health Institute at Pueblo. Investigation has indicated that settlement resulting from wet soils has caused this problem along the loading dock and adjacent wall.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$180,000 | All Phases | \$180,000 |







December 5, 2000

Current Funding Recommendation

\$180,000

Current Funding Recommendation

\$538,679

38 12 Department of Corrections

Ref.

No.

Score

Repair/Replace Security Systems, Ph 2 of 4

This project replaces security electronic components and locks at four correctional facilities. Phase 2 replaces locks at Colorado Territorial Correctional Facility; the locks cannot be repaired because replacement parts are unavailable. Many locations also require the addition of new steel doors or the modification of existing doors and frames to accept a new lockset in lieu of existing padlocks.

| PRIOR PHASING M00006 FY00/01 Ph 1 - FCF, CSP | \$384,617 | FUTURE PHASING FY02/03 Ph 3 - AVCF FY03/04 Ph 4 - AVCF | \$408,548 \$502,524 |
|--|-----------|--|------------------------|
| (FUNDED TO DATE) | \$384,617 | (PROJECT BALANCE) | \$911,072 |
| CURRENT PHASE FY01/02 Ph 2 - CTCF | \$538,679 | PROJECT TOTAL All Phases | \$1,834,368 |








| Ref. No. | Score | | Current Funding Recommendation |
|-------------|--------|-----------------------------|-----------------------------------|
| 39 | 12 | Red Rocks Community College | \$76,336 |
| Saf | ety Im | provements, Kiln, Ph 1 of 1 | |
| | • | • • • | |

The pottery department has several exterior kilns located on the north side of West Building (RM #766). The kilns are fired using many different types of fuel including wood, gas, straw and coal. The area is a potential fire hazard because it is located adjacent to fields with natural grasses. The kilns sometimes fire for days without constant monitoring. This project would pave the area and provide a low wall to separate it from the grasslands.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|----------|-------------------|----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$76,336 | All Phases | \$76,336 |
| | | | |







Ref.

No. Score

40 12 Colorado School of Mines

Campus Primary Electrical Power Distribution, Ph 1 of 1

A portion of the campus primary electrical distribution is carried overhead by poles. This portion of the system was installed in 1929 and has reached the end of its useful life. The system wire and components are aging and at risk for complete failure. The overhead lines and poles are subjected to the high winds that scour the Golden area each year. The buildings and laboratories that are served by the overhead electrical system are at risk for extended loss of electrical power when the lines fail. The lines and poles will be replaced with a new system of buried electrical conductors and associated distribution components.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|---------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 \$ | 396,740 | All Phases | \$396,740 |





Current Funding Recommendation

\$396,740

Ref.

No. Score

41 12 Colorado State University

Replace Deteriorated Electrical Alyesworth Hall, Ph 1 of 1

Electrical system in Aylesworth Hall (RM #3204) is subject to failure with parts difficult or impossible to obtain. Multiple building code violations need to be corrected. The solution is to replace the systems as required. Replacement includes the transformer, entrance cables, and main distribution panel and secondary panels.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$397,895 | All Phases | \$397,895 |







December 5, 2000

Current Funding Recommendation

\$397,895

Current Funding Recommendation

\$275,000

42 12 State Fair - Pueblo

Correct Accessibility Problems on the Fairgrounds, Ph 1 of 4

The State Fair became eligible for state general fund appropriations after the statewide ADA program was funded. ADA compliance problems include: lack of access to restrooms, non-compliant restrooms, buildings, stages, inadequate clearances, no access to second floor of Palace of Agriculture, non-compliant ticket counters, no access to stages, etc. This request is based on information provided by the 1998 facilities audit. Phase 1 addresses the accessibility problems in the Palace of Agriculture (RM #1338) pictured.

FUTURE PHASING

PRIOR PHASING

Score

Ref.

No.

| CURRENT PHASE FY01/02 Ph 1 - Palace of Agriculture | \$275,000 | PROJECT TOTAL All Phases | \$1,100,000 |
|---|-----------|----------------------------------|-------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$825,000 |
| | | FY04/05 Ph 4 - Various Locations | \$275,000 |
| | | FY03/04 Ph 3 - Various Locations | \$275,000 |
| | | FY02/03 Ph 2 - Various Locations | \$275,000 |
| | | | |







December 5, 2000

Ref.

No. Score

43 12 Northeastern Junior College

Campus Accessibility Design and Improvements, Ph 1 of 1

Many ADA violations exist on the NJC Campus. NJC became part of the Community Colleges of Colorado after the statewide project for ADA compliance. This project would identify the ADA non-compliance problems in NJC buildings and on the campus and determinate the cost to repair.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$103,481 | All Phases | \$103,481 |





Current Funding Recommendation

\$103,481

| Ref. No. | Score | e Curre Recon | |
|-------------|-------|------------------|--|
| | | | |

44 12 Morgan Community College

HVAC Repairs to Spruce Hall, Ph 2 of 2

The completion of a Facility Audit indicates the need to replace the HVAC units and air compressor on Spruce Hall (RM #741) to improve health and safety of occupants. Additionally, the ceiling and lighting in the distance education classroom, and some floor finishes in Spruce Hall are in need of repair. The HVAC units are insufficient to heat and cool the building and there are ongoing air quality issue concerns. An air quality monitoring study completed in March 1998 showed high levels of carbon monoxide and carbon dioxide in Spruce Hall. These emissions are caused by the presence of the two automotive programs that bracket both ends of the building. The steel buildings comprising MCC were never appropriately ventilated for these types of programs or for the areas (including several health education classrooms, the distance learning classroom, and physical plant shop) that occupy the center of the building. Phase 1 of the project would replace the HVAC units at the shops with the correct size units (including digital controls) to efficiently heat and cool the building. Phase 2 would retrofit the existing HVAC units with digital controls and replace the air compressor in the classroom area.

| PRIOR PHASING M00062 FY00/01 Ph 1 - HVAC/Shops | \$249,900 | FUTURE PHASING | |
|--|-----------|-----------------------------|-----------|
| (FUNDED TO DATE) | \$249,900 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE FY01/02 Ph 2 - HVAC/Classroom | \$237,738 | PROJECT TOTAL All Phases | \$487,638 |





December 5, 2000

Fundina endation

\$237,738

Current Funding Recommendation

\$299,104

Ref.

No. Score

45 12 Department of Military Affairs

HVAC Modifications, Various Locations, Ph 1 of 5

The 1999 Facility Assessment has identified mechanical issues that are essential to keeping the facilities operational and to maintain the health of the occupants. Buildings #248 and #268 - Englewood STARC Headquarters (RM #6021): The rooftop mechanical units are at the end of their useful life and are failing. Building #330 CSMS building (RM #7266) - Longmont welding area is not safely ventilated. The vehicle bays do not have proper means to exhaust the vehicle exhausts. Gas piping is rusted and needs to be replaced. Aurora Armory is pictured.

| PRIOR PHASING | CCFE | FF | FUTURE PHASING FY02/03 Ph 2 - Various Locations FY03/04 Ph 3 - Various Locations FY04/05 Ph 4 - Various Locations FY05/06 Ph 5 - Various Locations | CCFE \$299,235 \$293,744 \$291,065 \$364,984 | FF \$135,401 \$0 \$0 \$0 |
|---|--------------------------|-----------------|--|--|--------------------------------------|
| (FUNDED TO DATE) | \$0 | \$0 | (PROJECT BALANCE) | \$1,249,028 | \$135,401 |
| CURRENT PHASE FY01/02 Ph 1 - Englewood, Aurora | CCFE \$299,104 | FF \$126,457 | PROJECT TOTAL All Phases | CCFE \$1,548,132 | FF \$261,858 |









46 12 Adams State College

Ref.

No.

Score

Replace/Resurface Stadium Field House Tracks, Ph 2 of 2

Trip and fall hazards exist on both tracks. The Stadium (RM #173) running track has an unsuitable sub-base which is causing cracking in the track surface. The indoor track at Plachy Gym (RM #163) has areas that are badly worn. Some areas have holes. Patching of both tracks has occurred over past years but no longer is a viable solution. Phase 2 includes replacing Plachy Gym running surface. Plachy Gym is pictured.

| PRIOR PHASING M00027 FY00/01 Ph 1 - Stadium | \$649.472 | FUTURE PHASING | |
|---|------------------------|-----------------------------|-----------|
| (FUNDED TO DATE) | \$649,472 \$649,472 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE FY01/02 Ph 2 - Plachy Gym | \$174,296 | PROJECT TOTAL All Phases | \$823,768 |







Current Funding Recommendation

\$174,296

Ref.

No. Score

47 12 State Capitol Building

Renovate State Capitol First Floor Lights, Ph 1 of 1

The existing antique lighting fixtures on the first floor of the Capitol Building (RM #137) are in need of cleaning, rewiring and repair. The degree of deterioration varies from light to light. They require costly repair and maintenance; some parts are difficult to obtain. Lights at the second and third floors were recently renovated. The old lighting fixtures cause unsafe conditions for the maintenance personnel and occupants of the building.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$466,375 | All Phases | \$466,375 |
| | | | |

| | * |
|-------|---|
| | |
| | |
| | |
| 12 1: | |





Current Funding Recommendation

\$466,375

Ref.

No. Score

48 14 Colorado Historical Society

Ft. Vasquez Energy and Site Security Upgrade, Ph 1 of 1

The facility had a burglary in 1999 that resulted in the loss of valuable artifacts. Upgraded site security and improved lighting will address security concerns. Electrical upgrades will reduce energy costs. The roof needs to be replaced; the roof and walls need insulation. A vault is required for the propane tank. The drinking water system needs to be upgraded because it recently failed inspection by the Weld County Public Health Department.

| \$0 |
|-------|
| |
| 0,877 |
| 1 |

48 of 168







Current Funding Recommendation

\$150,877

| Ref. No. Score | | | Current Funding Recommendation |
|-------------------|----|---------------------------|-----------------------------------|
| 49 | 14 | Department of Corrections | \$1,246,228 |

Repair Utility Tunnel, Ph 2 of 2

The sidewalk/driveway roof over the portion of the utility tunnel (RM #1379) (pictured) running from the Boilerhouse to Cellhouses 7 and 8 at Fremont Correctional Facility has deteriorated significantly from water infiltration. The conduit and other piping attached to the ceiling of the tunnel have rusted. Water infiltration from an exterior stairwell into the basement to the Administration Building (RM #1367) has also caused upward wall and slab movement. Phase 2 funds completion of this project.

| PRIOR PHASING M90009 | | FUTURE PHASING | |
|-----------------------------|-------------|-------------------|-------------|
| FY99/00 Ph 1 - Design | \$169,526 | | |
| (FUNDED TO DATE) | \$169,526 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Construction | \$1,246,228 | All Phases | \$1,415,754 |









December 5, 2000

Current Funding Recommendation


\$1,605,604

50 15 Front Range Community College

Small Central Plant to Replace Deteriorating Rooftop HVAC Units, Larimer Campus, Ph 1 of 2

The current RTU's are approximately thirty years old. They are labor intensive, pneumatically controlled and parts are difficult to find. Several condenser pans leak causing significant water damage to facilities. The DX units leak freon and must be recharged constantly. There is an ongoing concern regarding stagnant air resulting from the dirty and improperly sized ductwork. The first phase will include design and construction of the mini-central plant, installation of underground piping, and the replacement of existing RTU's with fan coil units on Mount Antero (RM #2001) and Blanca Peak (RM #2002) buildings. Phase 2 replacement of RTU's with fan coil units on Mount Antero, Red Cloud Peak (RM #2003), and Maroon Peak (RM #2004) buildings. Capital Construction project (P0028) will renovate classroom/lab/office space in the Mount Antero and Blanca Peak buildings. All work of this CC project is inside the buildings. This CM request is the central plant and on the roofs of these buildings. This project is necessary if the renovated space is to be comfortable.

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Replace RTU's | \$538,615 |
|--------------------------------------|-------------|--|-------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$538,615 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Design, Central Plant | \$1,605,604 | All Phases | \$2,144,219 |



Ref.

Score

No.

Ref.

No. Score

51 15 University of Colorado at Boulder


Repair/Replace Obsolete Central HVAC Controls, Ph 3 of 3

The existing Control System has not been manufactured since 1986. It has become very difficult to obtain replacement parts, since the technology is obsolete. The new system is an energy-management and remote-monitoring system for failure alarms. It is also used in some buildings for load-shedding when electrical supply to the campus is being reduced. By replacing the monitoring points in these buildings it will be possible to eliminate this obsolete system. Phase 3: Will replace existing panels and install new network connections in Macky (RM #9148), Muenzinger (RM #9203), Porter (RM #9204), Ramaley (RM #9202), Regents (RM #9181), Stadium (RM #9206), and Theatre (RM #9136). Regents building is pictured.

| PRIOR PHASING M90035 | | FUTURE PHASING | |
|----------------------------------|-----------|-------------------|-----------|
| FY99/00 Ph 1 - Various Buildings | \$165,320 | | |
| FY00/01 Ph 2 - Various Buildings | \$170,279 | | |
| (FUNDED TO DATE) | \$335,599 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 3 - Various Buildings | \$177,942 | All Phases | \$513,541 |



Repair/Replace Obsolete Central HVAC Controls



Current Funding Recommendation

\$177,942

Current Funding Recommendation

\$590,867

52 15 University of Colorado at Colorado Springs

Ref.

No.

Score

Replace HVAC Science Building, Ph 2 of 5

The Science Building (RM #9066) has inadequate heating and cooling systems. Laboratory exhaust and make-up air systems cannot maintain negative air pressure in the labs. This project will add mechanical cooling, additional heating and renovate and replace air handlers and exhaust systems. Phase 2 will replace VAV terminals, provide a wet pipe fire sprinkler system with a new 4" water line, and replace two deteriorated cooling towers. Future phases will replace laboratory exhaust fans, make-up air fans, heat recovery modules and ductwork.

| PRIOR PHASING M90038 FY99/00 Ph 1 - Heating/Cooling | \$800,000 | FUTURE PHASING FY02/03 Ph 3 - Labs FY03/04 Ph 4 - Labs FY04/05 Ph 5 - Exhaust | \$593,285 \$414,920 \$425,293 |
|---|-----------|--|-------------------------------------|
| (FUNDED TO DATE) | \$800,000 | (PROJECT BALANCE) | \$1,433,498 |
| CURRENT PHASE FY01/02 Ph 2 - Air Handlers, Fire Sprinklers | \$590,867 | PROJECT TOTAL All Phases | \$2,824,365 |









53 of 168

SBP PRIORITIZED STATEWIDE PROJECT REQUEST DESCRIPTIONS FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

Ref.

No. Score

53 15 University of Colorado Health Sciences Center

School of Medicine Exhaust System Replacement, Ph 2 of 4

The School of Medicine (RM #9003) uses approximately 350 small exhaust fans to provide general air exhaust, laboratory fumehood exhaust, and bathroom toilet exhaust. Most of these fans are defined as "utility-sets" and are generally used for single purpose exhaust service. This configuration does not provide flexibility when space usage and assignment are frequently changing. Many of these fan systems have been pushed beyond their originally intended purpose. Many of these fans require mechanical upgrading beyond general maintenance and modifications are becoming increasingly more difficult and expensive. This project will eliminate, in most cases, the single fan approach. The many existing constant volume single fan systems will be replaced with several variable-flow manifold exhaust systems. Depending on the existing location of fans and their respective ductwork, the project's four phases will encompass three to four larger exhaust systems per building quadrant (a maximum of 12 exhaust systems for the entire School of Medicine in lieu of the existing 295 fans). The second phase of the project includes the central quadrant of the School of Medicine.

| PRIOR PHASING M00051 FY00/01 Ph 1 - Southeast Quadrant | \$611,320 | FUTURE PHASING FY02/03 Ph 3 - Southwest Quadrant FY03/04 Ph 4 - Northwest Quadrant | \$550,425 \$478,675 |
|--|-----------|--|------------------------|
| (FUNDED TO DATE) | \$611,320 | (PROJECT BALANCE) | \$1,029,100 |
| CURRENT PHASE FY01/02 Ph 2 - Central Core Quadrant | \$596,695 | PROJECT TOTAL All Phases | \$2,237,115 |







Current Funding Recommendation

\$596,695

Ref.

No. Score

54 15 University of Northern Colorado

Replace Deteriorated Systems Butler Hancock, Ph 2 of 2

The Butler Hancock Gymnasium (RM #828) floor has the original synthetic surface that was installed in 1972. This surface has deteriorated over the years and is increasingly becoming a safety hazard. The solution is to remove the center court section of the synthetic surface and replace this floor with a new maple floor with a suspension system. The remaining floor will be overlaid with new synthetic material. Women's restroom and locker room facilities do not meet code requirements for number of fixtures and lockers. Phase 1 addressed these issues. Phase 2 will replace the deteriorated sound system, provide sound attenuation for the gym and replace the deteriorated lighting systems in the gym.

| | FUTURE PHASING | |
|-----------|-------------------|--|
| \$671,158 | | |
| \$671,158 | (PROJECT BALANCE) | \$0 |
| | PROJECT TOTAL | |
| \$480,872 | All Phases | \$1,152,030 |
| | \$671,158 | \$671,158 \$671,158 (PROJECT BALANCE) PROJECT TOTAL |





December 5, 2000

Current Funding Recommendation

\$480,872

Current Funding Recommendation

\$684,877

55 15 Colorado State University

Ref.

No.

Score

Replace Deteriorated Items, Wagar, Ph 2 of 3

Major building systems are almost 60 years old and failing in the Wagar Building (RM #3264). Electrical and heating systems need to be replaced. Exterior walls and glass curtain walls need repairs. Most floor coverings are loose or chipped, contain asbestos, and need to be replaced. Interior walls, doors, and ceilings need moderate repairs. Heating system is obsolete, controls are corroded and system needs to be replaced. Electrical system has old sub-standard wiring, insulation, and panels. Phase 2 - replaces heating in the north wing and electrical system in the east wing. Phase 3 - replaces electrical system in the north wing and ceiling.

| PRIOR PHASING M00032 | | FUTURE PHASING | |
|---|-----------|--------------------------------------|-------------|
| FY00/01 Ph 1 - Design/E. Heating | \$660,413 | FY02/03 Ph 3 - N. Electrical/Windows | \$676,013 |
| (FUNDED TO DATE) | \$660,413 | (PROJECT BALANCE) | \$676,013 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - N. Heating/E. Elecricial | \$684,877 | All Phases | \$2,021,303 |
| | | | |







December 5, 2000

Ref.

No. Score

56 15 Pikes Peak Community College

Roof Replacement Aspen and Breckenridge Buildings, Ph 2 of 4

Roofs have ponding water in several locations on both Aspen (RM #57) and Breckenridge (RM #58) Buildings. The roofs are exhibiting blisters large and small and the roof flashings are warped and tearing in several locations on both buildings. The built up, flat roofs on both buildings, have been in place for 22 years and are beyond useful life. A single ply EPDM roof membrane system, consisting of R-30 tapered adhered insulation, with an EPDM membrane of 60 mils nominal thickness adhered to the insulation, and 30"x30" walkway pads of molded rubber is the proposed new roof. Phase 1 funded the replacement of sections 1, sections on the Aspen Building. Phase 2 replaces the roof in sections 4, 5, and 6 on the Aspen Building. Pikes Peak Centennial Campus is pictured.

| PRIOR PHASING M00088 FY00/01 Ph 1 - Aspen 1,1a,2,3 | \$222,074 | FUTURE PHASING FY02/03 Ph 3 - Aspen7/Brknrdge. 8,9,10,11 FY03/04 Ph 4 - Breckenridge 12, 13, 14 | \$283,492 \$231,110 |
|--|-----------|---|------------------------|
| (FUNDED TO DATE) | \$222,074 | (PROJECT BALANCE) | \$514,602 |
| CURRENT PHASE FY01/02 Ph 2 - Aspen 4,5,6 | \$315,543 | PROJECT TOTAL All Phases | \$1,052,219 |





Current Funding Recommendation

\$315,543

Current Funding Recommendation

December 5, 2000

Ref. No. Score

57 15 Arapahoe Community College

Roof, Window and Door Replacement: Main, North and Annex, Ph 2 of 2

Phase 2 of this project replaces 128 original steel frame windows with energy efficient double pane units and three wood entrance doors with storefront systems at the North Building (RM #770) (pictured). The project also replaces six aluminum sliding doors in the swimming pool area of the Annex Building (RM #769) (pictured lower right) with vinyl clad wood doors and window units. The existing doors are corroded as a result of high humidity and chemicals.


| PRIOR PHASING M90048 | | FUTURE PHASING | |
|------------------------------|-----------|-------------------|-----------|
| FY99/00 Ph 1 - Roof | \$141,445 | | |
| (FUNDED TO DATE) | \$141,445 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Windows/Doors | \$186,538 | All Phases | \$327,983 |











Ref.

No. Score

58 15 Fort Lewis College


Replace Sewers/Pavement/Sidewalks, North Campus, Ph 1 of 1

This project replaces the main sanitary sewer for the northern part of the campus and replaces the pavement on Raider Avenue. The sewer was constructed of clay tile in 1957. It has deteriorated, is undersized and fails often. The project also replaces the asphalt pavement and sidewalks on Raider Avenue that have deteriorated due to weak and inadequate drainage. Repair of the sewer and pavement is an ongoing requirement. This project will correct significant operational and maintenance problems.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-------------|-------------------|-------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$1,221,885 | All Phases | \$1,221,885 |







Current Funding Recommendation

\$1,221,885



December 5, 2000

Ref.

No. Score

Recommendation


59 16 University of Colorado at Boulder

Campus Steam Tunnel Structural Upgrades, Ph 2 of 3

Moisture infiltration is a chronic problem in most segments of the tunnel system. The persistent wetting and drying of the concrete envelope has promoted the deterioration of the concrete and the corrosion of embedded and exposed metals. Surface scaling, delaminations and efflorescence deposits are found throughout the tunnel system. Phase 1-tunnel section 46 has temporary shoring in place that is inadequate for long-term structural performance. Phase 2 - will repair structural damage in section #46 and improve lighting, drainage, ventilation and waterproofing.

| PRIOR PHASING M00038 | | FUTURE PHASING | |
|---------------------------------|-----------|---------------------------------------|-------------|
| FY00/01 Ph 1 - Sections 46, 46A | \$296,600 | FY02/03 Ph 3 - Sections 6, 32, 33, 45 | \$617,952 |
| (FUNDED TO DATE) | \$296,600 | (PROJECT BALANCE) | \$617,952 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Section 46 | \$527,391 | All Phases | \$1,441,943 |







Current Funding

\$527,391

Ref.

No. Score


16 University of Colorado Health Sciences Center 60

Colorado Psychiatric Hospital Infrastructure, Ph 4 of 4

The Colorado Psychiatric Hospital (CPH) (RM #9007) was constructed in 1924 as part of the initial construction of the University of Colorado Medical School complex. The building's original size was 43,160 square feet, and was expanded in 1954 with an addition of 22,320 square feet. Proposals to alter the functional usage of this facility have been numerous, but none have come to realization. As this facility will remain an integral part of the 9th Avenue and Colorado Boulevard campus well into the next century, the UCHSC has requested funding to restore the facility's infrastructure to an acceptable condition through a four-phase upgrade, of which three are already funded. Previously, this project request included a phase 5 for limited window replacement due to the facilities audit process, asbestos-containing material was found in the weatherproofing caulk of most window units. Additional abatement costs and requirements have now prompted the University to resubmit phase 5 as a separate project request. The work under Phase 4 includes correcting the plumbing system by replacing piping and plumbing fixtures. The heating water piping will be upgraded by installing a chemical treatment system.

| PRIOR PHASING M727 FY97/98 Ph 1 - Elec./Fire Prot. FY98/99 Ph 2 - HVAC/North | \$374,756 \$800,000 | FUTURE PHASING | |
|---|---------------------------------|-----------------------------|-------------|
| FY00/01 Ph 3 - HVAC/South (FUNDED TO DATE) | \$593,692 \$1,768,448 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE FY01/02 Ph 4 - Plumbing | \$394,805 | PROJECT TOTAL All Phases | \$2,163,253 |

| | | - | Se . Chief | |
|---|------------|-------|------------|--|
| | | - All | 1 | |
| | À | 1 P | A A A | |
| | The second | 7 | 1. | |
| - | - | - | -363 | |





December 5, 2000

Current Funding Recommendation

\$394,805

| Ref. No. | Score | | Current Funding Recommendation |
|-------------|----------|-----------------------------|-----------------------------------|
| 61 | 18 | Colorado Historical Society | \$134,645 |
| - | <u> </u> | | |


Ft. Garland Code/Safety Upgrade, Ph 2 of 2

The first phase of this project corrected code deficiencies in several buildings at the Fort Garland site. Phase 2 addresses site security, accessibility, and maintenance concerns with the addition of a security fence, site lighting, drainage and walkway improvements.

| PRIOR PHASING M00086 | | FUTURE PHASING | |
|---------------------------------|-----------|-------------------|-----------|
| FY00/01 Ph 1 - Building Repairs | \$250,840 | | |
| (FUNDED TO DATE) | \$250,840 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Site Repairs | \$134,645 | All Phases | \$385,485 |







Current Funding Recommendation

\$368,267

Repair/Replace Stadium Field House Bleachers, Ph 1 of 2


Adams State College

All bleachers do not meet current codes. They are badly deteriorated. Injuries have occurred from splinters and lack of handrails. Previous ADA funding did not address the area. Vertical transportation is planned for phase 2 along with the east side bleachers if the new proposal for the stadium as outlined in the concept report delivered to CCHE September 2000 does not result in a Capital Construction Project.

FUTURE PHASING

PRIOR PHASING

| | | FY02/03 Ph 2 - East Bleachers/Vert. Trans | \$170,216 |
|-------------------------------|-----------|---|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$170,216 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - West Bleachers | \$368,267 | All Phases | \$538,483 |











Ref.

62

Score No.

16

Current Funding Recommendation

\$329,246

63 18 Department of Military Affairs

Safety Standards Compliance, Various locations, Ph 1 of 3

This project includes Building #205, Colorado Springs Armory (RM #925). The Drill Hall was remodeled many years ago with a two story interior addition. The North end of the Armory has also been remodeled over the years. The remodeled areas have numerous code violations including dead end corridors, insufficient exits and exits through adjoining rooms, endangering the public and users of the Armory.

| PRIOR PHASING | CCFE | FF | FUTURE PHASING FY02/03 Ph 2 - Grand Junction FY03/04 Ph 3 - Canyon City | CCFE \$290,332 \$288,597 | FF \$0 \$103,762 |
|--|--------------------------|------------------|---|--------------------------------|------------------------|
| (FUNDED TO DATE) | \$0 | \$0 | (PROJECT BALANCE) | \$578,929 | \$0 |
| CURRENT PHASE FY01/02 Ph 1 - Colorado Springs | CCFE \$329,246 | FF \$0 | PROJECT TOTAL All Phases | CCFE \$908,175 | FF \$103,762 |







Ref. No. Score

Current Funding

Recommendation

\$408,548

64 18 Department of Corrections

Ref.

No.


Score

Repair/Replace Security Systems, Ph 3 of 4

This project replaces security electronic components and locks at four correctional facilities. Phase 3 provides touch screens and programmable logic controllers for Receiving, Segregation, Checkpoint and Visiting (RM #9061) and Towers 1 and 2 (RM #913) at Arkansas Valley Correctional Facility. Components in the existing fourteen-year-old door control and security electronics system (pictured) have become obsolete and are no longer manufactured; no substitutes are currently available.

| PRIOR PHASING M00006 FY00/01 Ph 1 - FCF, CSP FY01/02 Ph 2 - CTCF | \$384,617 \$538,679 | FUTURE PHASING FY02/03 Ph 4 - AVCF | \$502,524 |
|---|------------------------|---------------------------------------|-------------|
| (FUNDED TO DATE) | \$923,296 | (PROJECT BALANCE) | \$502,524 |
| CURRENT PHASE FY01/02 Ph 3 - AVCF | \$408,548 | PROJECT TOTAL All Phases | \$1,834,368 |





December 5, 2000

No. Score

Ref.

65 18 Northeastern Junior College


Install Pitched Roofs on Four Main Campus Buildings, Ph 3 of 3

This CM request initially included roof replacements for six buildings. Because of two recent capital construction requests NJC which include replacement for Phillips-Whyman and E.S. French roofs, these two buildings have been removed from this request. This project is now being reduced to three phases. The buildings included are Walker (RM #4265), Beedle-Hamil (RM #4258), Hays (RM #4262), and Knowles (RM #4261). This is the final request to install pitched roofs on these four buildings. Hays is pictured.

| PRIOR PHASING M90057 | | FUTURE PHASING | |
|------------------------------|-----------|-------------------|-----------|
| FY99/00 Ph 1 - Wa ker | \$272,643 | | |
| FY00/01 Ph 2 - Beedle-Hamil | \$189,596 | | |
| (FUNDED TO DATE) | \$462,239 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 3 - Hays, Knowles | \$525,938 | All Phases | \$988,177 |







Current Funding Recommendation

\$525,938

Score

Ref.

No.

66 18 Colorado Government Technology Services

Replace Roofs on Remote TX Buildings (B), Ph 3 of 5

Built-up flat roofs on remote transmitter buildings need to be replaced with sloped metal roofs. The buildings contain electronic transmitting equipment that support state safety communication systems and other systems. Twelve buildings will be included in a five-phase project to upgrade the roofs. Phase 3 includes the following sites: Mead (RM #1897), Point of Rocks (RM #1898), and Reiradon Hill (RM #1899). Point of Rocks is pictured.

| PRIOR PHASING M90101 | | FUTURE PHASING | |
|----------------------------------|-----------|----------------------------------|-----------|
| FY99/00 Ph 1 - Various Locations | \$49,500 | FY02/03 Ph 4 - Various Locations | \$52,260 |
| FY00/01 Ph 2 - Various Locations | \$50,985 | FY03/04 Ph 5 - Various Locations | \$52,260 |
| (FUNDED TO DATE) | \$100,485 | (PROJECT BALANCE) | \$104,520 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 3 - Various Locations | \$53,280 | All Phases | \$258,285 |





December 5, 2000

Current Funding Recommendation

\$53,280

Ref.

No. Score

67 18 Capitol Complex Facilities

Replace Deteriorated Roofs at SOB, Centennial, and Power Plant, Ph 1 of 1

This project will replace the roofs at the State Office Building (RM #143), Centennial Building (RM #140) and the Power Plant (RM #139). They have numerous leaks in different locations; the cost of repairs has become prohibitively expensive. Centennial Building and the Power Plant are pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$607,180 | All Phases | \$607,180 |

NAMES



67 of 168





Current Funding Recommendation

\$607,180

Ref.

No. Score

68 18 Auraria Higher Education Center

Repair/Replace Roofing/Weathertight Enclosures, Ph 2 of 2

The roofing on Central Classroom (RM #1207) and South Classroom (RM #1217) is extremely deteriorated and beyond repair with blisters, wrinkles, splits, poor drainage and wet insulation. Copings and building sealant have also deteriorated. West Classroom (RM #1221) roofing has been replaced using emergency funds, although coping replacement is still required. Phase 1 is for replacing the roofing (adding sloped insulation), coping and building sealant on Central Classroom and the deteriorated coping on West Classroom. Phase 2 is for replacing the roofing, coping and building sealant on South Classroom (pictured).

| | FUTURE PHASING | |
|-----------|-------------------|--|
| \$441,500 | | |
| \$441,500 | (PROJECT BALANCE) | \$0 |
| | PROJECT TOTAL | |
| \$805,600 | All Phases | \$1,247,100 |
| | \$441,500 | \$441,500 \$441,500 (PROJECT BALANCE) PROJECT TOTAL |







December 5, 2000

Current Funding Recommendation

\$805,600

Ref.

No. Score

69 18 Judicial Heritage

Waterproof Sloped Roof and Plaza Deck, Ph 2 of 3

The sloped roof and plaza deck levels of the Judicial (RM #117)/Heritage (RM #118) Complex have leaked into the building structure for many years. Expansion joints and brick pavers are a continuous source of water entry into the building structure. The sloped brick and plaza deck need to be water proofed and all caulking joints replaced. Positive drainage needs to be provided in the plaza deck. This project involves installing deck drains in order to rectify the situation. Phase 2 will repair and reconstruct the terrace and planter areas of the Heritage Building (pictured). Phase 3 will repair and replace the roof of the Heritage Building.

| PRIOR PHASING M00095 | | FUTURE PHASING | |
|----------------------|-----------|---------------------|-------------|
| FY00/01 Ph 1 - Plaza | \$419,400 | FY02/03 Ph 3 - Roof | \$306,812 |
| (FUNDED TO DATE) | \$419,400 | (PROJECT BALANCE) | \$306,812 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Decks | \$539,325 | All Phases | \$1,265,537 |









December 5, 2000

Current Funding Recommendation

\$539,325

Ref.

Score No.

70 18 University of Colorado at Boulder

Repair/Replace Main Campus Compressed Air System, Ph 1 of 2


Compressed air supply piping is old and deteriorated, improperly sized and has many leaks. It is subject to failure at any time. Parts of this piping system contains old copper-coated steel pipe, this pipe is a legacy from World War II when solid copper pipe was not available. Solution is to replace piping with larger piping valves, drainage devices, etc., and to install supplementary air compressors to the Power House in the east part of the main campus. Phase 1: Repair/Replace tunnel piping from the Power House east, north and south.

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Compressor/Controls | \$729.753 |
|--------------------------------------|-----------|--|-------------|
| | | FT02/03 FTT2 - Compressor/Controls | \$729,755 |
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$729,753 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Replace Tunnel Piping | \$348,780 | All Phases | \$1,078,533 |











Current Funding Recommendation

\$348,780

| Current Funding |
|-----------------|
| Recommendation |

\$527,495

71 18 Colorado State University

Replace Deteriorated Refrigeration Units, Ph 1 of 1

There are 16 walk-in coolers with refrigeration systems that are considerably past their 20 year life expectancy. Maintenance is excessive, and parts are often difficult to obtain. Older systems are also R-12 refrigerant, and often leak. R-12 is now regulated and gas loss is prohibited by law. Systems should be replaced. This project repairs walk-in coolers and freezers in Animal Sciences (RM #3305), Physiology (RM #3336) and Shepardson (RM #3281).

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$527,495 | All Phases | \$527,495 |
| | | | |



December 5, 2000

/_00_

Score

Ref.

No.

December 5, 2000

Current Funding Recommendation

\$197,495

72 18 Pueblo Community College

Ref.

No.

Score

Replace Boilers and Associated Equipment, Boiler House, Ph 1 of 1

The steel fire tube boilers are 17 years old and have deteriorated due to the lack of proper operation and maintenance of the boilers. This has resulted in a shortened life expectancy of the boilers. PCC is planning to install a series of smaller boilers that can be stepped up to meet the heating needs and be more energy efficient. Currently PCC generates 12 million BTU's when the boilers are operating. The facility can only operate at full capacity and does not have the controls necessary to regulate or step down to the BTU's required. As the boilers are replaced it will be necessary to replace and repair the associated hydronic specialties such as the air separator, expansion tank, and hot water distribution pumps. These pumps should be replaced with new VFD type for energy conservation. Central boilers supply heat to 5 of the 9 buildings on campus. Boiler House (RM #73) is pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|-------------------|--------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 \$19 | 97,495 | All Phases | \$197,495 |
| FY01/02 Ph 1 \$15 | 97,495 | All Phases | \$197,495 |







| Ref. No. | Score | Current Funding Recommendation |
|-------------|---------|---|
| 73 | 18 | Department of Corrections \$108,051 |
| Rep | olace E | oiler Refractory, Ph 1 of 1 |
| | | er inspections of the three boilers in the Heating Plant (RM #2960) (pictured) at Buena Vista Correctional Facility |

have indicated that the firebrick and refractory need to be replaced on all three boilers. This equipment is forty years old and is now experiencing extreme temperatures. Boiler #1 has recently failed and has been repaired through an emergency project. This project repairs Boilers #2 and 3.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$108,051 | All Phases | \$108,051 |
| | \$108,051 | All Phases | \$108,051 |







Ref.

No. Score

74 18 University of Colorado Health Sciences Center


Power Plant and Campus Cooling System Improvements, Ph 6 of 9

The UCHSC has initiated a program to upgrade its' central Campus Power Plant (RM #9021). The Power Plant has significant problems as a result of the deterioration of plant equipment, which has reached a condition where normal maintenance and repair can no longer guarantee continuous operation. This project includes a phased approach to improving the campus cooling system. This approach will replace aged equipment located in the Central Power Plant and throughout the campus buildings and will save energy and provide greater cooling capacity. Phase 6 includes modification of the piping system located in the individual campus buildings, at both the main piping take-off and at each air-handling-unit in the building.

| PRIOR PHASING M728 | | FUTURE PHASING | |
|--|-------------|--------------------------------------|-------------|
| FY95/96 Ph 1 - Chiller Replacement A + B | \$1,367,539 | FY02/03 Ph 7 - Direct Buried Piping | \$177,028 |
| FY96/97 Ph 2 - Equipment Replacement | \$650,000 | FY03/04 Ph 8 - Chiller Replacement C | \$829,820 |
| FY97/98 Ph 3 - Cooling Tower | \$1,461,680 | FY04/05 Ph 9 - Chiller Replacement D | \$885,141 |
| FY98/99 Ph 4 - Piping Improvements | \$424,000 | | |
| FY99/00 Ph 5 - System Conversion | \$649,760 | | |
| (FUNDED TO DATE) | \$4,552,979 | (PROJECT BALANCE) | \$1,891,989 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 6 - Building Piping | \$564,007 | All Phases | \$7,008,975 |







Current Funding

December 5, 2000

Recommendation

| Ref. | | Current Funding | |
|-----------|----|------------------------------|----------|
| No. Score | | Recommendation | |
| 75 | 18 | Department of Human Services | \$375,00 |

Repair/Replace HVAC Systems, Ph 3 of 4

Approximately 27 buildings built between 1888 and 1939 at the Colorado Mental Health Institute at Fort Logan house various treatment and support programs. The heating systems operate with the original low pressure steam and radiators; the boilers have been converted from coal to natural gas. The systems are very inefficient and subject to frequent breakdown and repair. Phase 3 will provide new boilers, piping, and fin tube radiators in Building 3 (RM #1025), 9 (RM #1031), 11 (RM #1033), 14 (RM #1035), 15(RM #1036), 17 (RM #1038) and 18 (piping and fin-tube only) (RM #1039). Asbestos will be removed from the boiler jacketing.

| PRIOR PHASING M90084 | | FUTURE PHASING | |
|--|-----------|------------------------------------|-------------|
| FY99/00 Ph1-Boiler Buildings 2, 4, 5, 6 | \$348,740 | FY02/03 Ph4-Boiler Buildings 19-29 | \$488,118 |
| FY00/01 Ph2-Boiler Buildings 7, 8, 10, 13, 16 | \$567,338 | | |
| (FUNDED TO DATE) | \$916,078 | (PROJECT BALANCE) | \$488,118 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 3 - Boiler Bldgs 3, 9, 11, 14, 15, 17, 18 | \$375,000 | All Phases | \$1,779,196 |
| | | | |





December 5, 2000

ng on

\$375,000

Current Funding

Recommendation

\$221,088

76 18 Red Rocks Community College

Ref.

No.

Score

Groundwater Problem - West Building, Ph 2 of 2

Red Rocks Community College has experienced seepage of ground water through the walls in the lower levels of the West Building (RM #766). An investigation determined that the perimeter drain line and the storm collection system need to be repaired and/or be extended, and have manholes, sump pumps, and clean outs installed. The granular fill behind the wall should be drained.

| PRIOR PHASING M90072 | | FUTURE PHASING | |
|-------------------------------|-----------|-------------------|-----------|
| FY99/00 Ph 1 - Design | \$21,820 | | |
| (FUNDED TO DATE) | \$21,820 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Implementation | \$221,088 | All Phases | \$242,908 |





December 5, 2000

December 5, 200

Ref.


No. Score

77 18 Department of Human Services

Replace Deteriorated Campus Infrastructure System, CMHIFL, Ph 1 of 5

It has been determined through selective forensic testing that the domestic water, sanitary sewer, manholes, storm sewer, and fire mains and hydrants need to be replaced at the Colorado Mental Health Institute at Fort Logan. Phase 1 replaces these utilities on West Oxford Avenue and the northern portion of South Knox Court. Paving in this area has been funded through a previous CM project; that work will be deferred until the utilities are replaced. Paving and infrastructure utilities will be replaced on South Julian Way and Knox Court in Phase 2, on West Princeton Place and the adjacent parking lots in Phase 3, on West Princeton Circle in Phase 4, and on South Newton Court, West Oxford Avenue, and South Meade Street in Phase 5.

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - S Julian, Knox Court FY03/04 Ph 3 - W Princeton Place FY04/05 Ph 4 - W Princeton Circle | \$750,000 \$750,000 \$750,000 |
|--|-----------|--|-------------------------------------|
| (FUNDED TO DATE) | \$0 | FY05/06 Ph 5 - S Newton, W Oxford, S Meade (PROJECT BALANCE) | \$750,000 \$3,000,000 |
| CURRENT PHASE FY01/02 Ph 1 - W Oxford, S Knox | \$575,000 | PROJECT TOTAL All Phases | \$3,575,000 |



77 of 168

December 5, 2000

Current Funding Recommendation

\$575,000

Current Funding

Recommendation

\$450,700

78 18 Colorado State University

Replace Deteriorated Items, Forestry, Ph 1 of 3

Building heating, plumbing, and electrical systems are nearly 60 years old and are obsolete in the Forestry building (RM #3260). Parts are difficult to obtain. The heating system is leaking and outages are becoming more frequent. The plumbing system no longer meets code. All systems need to be replaced. The windows are single glazed and the sashes have dry rot. Phase 1 replaces windows will provide asbestos abatement for the new mechanical room and builds the mechanical room. Phase 2 replaces the electrical and plumbing systems. Phase 3 replaces the heating system and ceiling tiles.

FUTURE PHASING

PRIOR PHASING

Score

Ref.

No.

| | | FY02/03 Ph 2 - Electrical/Plumbing FY03/04 Ph 3 - Heating System | \$535,802 \$571,548 |
|--|-----------------|---|------------------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$1,107,350 |
| CURRENT PHASE | • • • • • • • • | PROJECT TOTAL | |
| FY01/02 Ph 1 - Windows/Mechanical Room | \$450,700 | All Phases | \$1,558,050 |







December 5, 2000

| Score | | | |
|-------|--|--|--|

79 18 University of Northern Colorado

Ref.

No.

Exterior Building Systems Repair, Ph 3 of 3


During the summer of 1998 UNC contracted with a consultant to review the condition of the exterior masonry, stone, and precast on all campus buildings. A cost estimate for repairs to these structures was prepared. Along with exterior building masonry, the exterior painting needs have also been evaluated. The intent of this project is to identify, specify, repair and complete the stabilization of exterior building systems. Other exterior repair includes downspout repair or replacement on older buildings. A historical masonry site entrance structure at the northeast corner of the campus has been included for repairs. Phase 1 for design was approved in FY99/00. Phase 2 was to start construction on the most critical. Phase 3 is to finish the work on the following buildings: Bishop Lehr Hall (RM #826), Butler Hancock (RM #828), Candelaria Hall (RM #829), Carter Hall (RM #830), Crabbe Hall (RM #833), Frasier Hall (RM #834), Garden Theatre (RM #835), Gray Hall (RM #836), Kepner Hall (RM #854), N/E Entry and Arts Annex (RM #824). Crabbe Hall is pictured.

| PRIOR PHASING M90045 | | FUTURE PHASING | |
|----------------------------------|-----------|-------------------|-----|
| FY99/00 Ph 1 - Design | \$135,000 | | |
| FY00/01 Ph 2 - Various Buildings | \$363,771 | | |
| (FUNDED TO DATE) | \$498,771 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| OURICEINT THACE | | | |









Current Funding Recommendation

\$393,197

Ref.

No. Score

80 18 Mesa State College

Building Repairs, Walter Walker Fine Arts Center, Ph 3 of 4

Walter Walker Fine Arts Center (RM #218) was constructed in 1969. The south wing of this building contains the only major theater space on the MSC campus. The facility exhibits significant health and safety issues, including major fire safety and exit distance code deficiencies. Ventilation problems as well as code related operational and access problems are evident. Student safety is a major concern. In addition, most of the building's HVAC equipment is nearing the end of its expected useful life and is in need of replacement. A capital construction project (P9907) identified as "Humanities and Social Sciences Facilities Expansion, Phase II" was requested for the north wing of the building. The projects are separate and do not involve the same building areas or systems. An open courtyard separates these wings. Phase 3 provide new chiller, boiler and fire exits in accordance with current code requirements. Walter Walker Fine Arts Center is pictured.

| PRIOR PHASING M90020 | | FUTURE PHASING | |
|--|-----------|---------------------------------|-------------|
| FY99/00 Ph 1 - Fire Alarm | \$390,788 | FY02/03 Ph 4 - Chiller/Boiler B | \$467,667 |
| FY00/01 Ph 2 - HVAC | \$425,125 | | |
| (FUNDED TO DATE) | \$815,913 | (PROJECT BALANCE) | \$467,667 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 3 - Chiller/Boiler A/Fire Exits | \$435,209 | All Phases | \$1,718,789 |
| | | | |







Current Funding Recommendation

\$435,209

Ref.

81

No. Score

18 Lamar Community College

Window Upgrades Bowman/Trustees Buildings, Ph 2 of 2

Windows in both facilities are original. Caulking and sealing components of frames and windows are deteriorated and leaking. Windows and glazing are single pane with no insulation capacity. Some window areas allow water infiltration into buildings. Solution is to upgrade glazed areas to double glazed, low E type to protect against heating losses, but will also cut down on solar gain loads in the summer thereby reducing utility costs. Phase 1 will replace the windows on the Bowman Building (RM #2773) and Phase 2 will replace the windows on the Trustees Building (RM #1774) pictured.

| PRIOR PHASING M00058 FY00/01 Ph 1 - Bowman | \$363.098 | FUTURE PHASING | |
|--|-----------|--------------------------|-----------|
| (FUNDED TO DATE) | \$363,098 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE FY01/02 Ph 2 - Trustees | \$135.192 | PROJECT TOTAL All Phases | ¢409 200 |
| | a135,192 | All Flidses | \$498,290 |







Current Funding Recommendation

\$135,192

| Ref. No. | Score | | Current Funding Recommendation |
|-------------|-------|---|-----------------------------------|
| 82 | 20 | Colorado Government Technology Services | \$71,060 |

Replace Emergency Generators, Ph 3 of 5

The remote radio sites have emergency generators to maintain power for public safety communications during power interruptions. The generators are 30+ years old. Parts are difficult to find and the reliability is questionable due to age. These generators need to be replaced. Phase 3 includes sites: Storm King (RM #1922), Eagle (RM #1931), Walton Mt. (RM #1927), Akron (RM #1894), and Pool Table (RM #1954). Akron is pictured.

| PRIOR PHASING M90102 | | FUTURE PHASING | |
|----------------------------------|-----------|----------------------------------|-----------|
| FY99/00 Ph 1 - Various Locations | \$68,000 | FY02/03 Ph 4 - Various Locations | \$69,700 |
| FY00/01 Ph 2 - Various Locations | \$68,000 | FY03/04 Ph 5 - Various Locations | \$69,700 |
| (FUNDED TO DATE) | \$136,000 | (PROJECT BALANCE) | \$139,400 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 3 - Various Locations | \$71,060 | All Phases | \$346,460 |





December 5, 2000

Ref.

No. Score

83 20 Department of Agriculture - Zuni & Insectary

Metrology Lab Building System Replacement, Ph 2 of 2

The Metrology Building Laboratory (RM #1002) (pictured) is the only facility that maintains Colorado's official mass, length, and volume standards. It also provides calibration of mass, frequency, length, volume, and moisture in grain for public and private agencies. The large mass room requires airlock and loading area modifications to prevent temperature and humidity changes that affect reliability of measurement systems. Phase 1 includes: install new airlock enclosure and dock, install new infrared heat and hood at large mass room, install new insulation at large mass room, and replace existing lighting/ceiling. Phase 2 includes: upgrade restrooms, replace compressor and repair roof and exterior walls.

| PRIOR PHASING M00002 | | FUTURE PHASING | |
|------------------------------|-----------|-------------------|-----------|
| FY00/01 Ph 1 - Dock/Hood | \$326,728 | | |
| (FUNDED TO DATE) | \$326,728 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Plumbing/Roof | \$169,528 | All Phases | \$496,256 |
| | | | |







Current Funding Recommendation

\$169,528

Ref.

No. Score

84 20 University of Colorado at Boulder

Regents Repair/Replace Air Handling Systems, Ph 2 of 2

The existing system in the Regents Administration Center (RM # 9181) (pictured) has reached the end of its useful life, and cannot meet the needs of the spaces it serves. This request proposes replacing the multi-zone DX Air-handling system with a chiller, VAV air handlers, terminal units, and ductwork sized to supply the air quantity required to meet current needs. Phase 2 - fabrication and installation, of ductwork, piping, VAV units, and controls. Electrical, structural, miscellaneous cutting and patching, and crane work will also occur.

| PRIOR PHASING M90036 | | FUTURE PHASING | |
|---|-----------|-------------------|-------------|
| FY99/00 Ph 1 - Design, Procurement | \$394,020 | | |
| (FUNDED TO DATE) | \$394,020 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Fabrication/Installation | \$608,030 | All Phases | \$1,002,050 |











Current Funding Recommendation

\$608,030

December 5, 2000

Current Funding Recommendation

85 20 Capitol Complex Facilities

Ref.

No.

Score

Variable Air Volume Boxes Replacement at Centennial Building, Ph 1 of 1

The existing moduline variable air volume (VAV) boxes/terminals in the Centennial Building (RM #140) are outdated, have exceeded their life expectancy, and do not operate properly. The dampers are deteriorated and have numerous cracks. The constant repairs are very expensive and time consuming. The scope of work also includes the re-zoning of air distribution to match the current tenant occupancies, duct repair and insulation, duct modifications to reduce air loss, and installation of additional return air grilles to improve return air flow to the plenum space above the ceiling.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-------------|-------------------|-------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$1,396,800 | All Phases | \$1,396,800 |







\$1,396,800

Current Funding

Recommendation

\$212,128

86 20 Colorado School for the Deaf and Blind

Ref.

No.

Score

Electrical Distribution Upgrade, Ph 2 of 3


Current panels and wiring is over thirty years old, in many cases grounding and bonding does not meet NEC. Additional loads on the panels given today's equipment have caused several concerns regarding over heating of the conductors and panels. CSDB proposes to replace Main distribution panels, sub distribution panels and sub panes and conductors over three phases. Phase 1 design - complete work at the industrial groups: SHC (RM #2610), Industrial (RM #2609), Deaf School (RM #2619), Argo (RM #2608) this phase has been funded. Phase 2 completes work at Palmer Group: Palmer (RM #2613), Jones (RM #2612), Preschool (RM #2625). Phase 3 design and complete work at West group: West (RM #2617), Vocational (RM #2624), Administration (RM #2607) and Barn (RM #2621). Palmer is pictured.

| PRIOR PHASING M00025 FY00/01 Ph 1 - Industrial | \$332.823 | FUTURE PHASING FY02/03 Ph 3 - West | \$247.758 |
|--|-----------|---------------------------------------|-----------|
| FT00/01 FILT-IIIuusulai | φ332,023 | F102/03 F113 - WESI | φ247,750 |
| (FUNDED TO DATE) | \$332,823 | (PROJECT BALANCE) | \$247,758 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Palmer | \$212,128 | All Phases | \$792,709 |









December 5, 2000

Ref.

No. Score

87 20 Fort Lewis College

Repair/Replace Geology Storage Building, Ph 1 of 1

The project will repair/replace the roof, siding and windows of the Geology Storage Building (RM #1307). Additionally the project will repair/replace the electrical and mechanical systems. It will also bring the facility into compliance with ADA requirements.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$296,744 | All Phases | \$296,744 |





December 5, 2000

Current Funding Recommendation

\$296,744

December 5, 2000

Current Funding Recommendation

\$48,620

Ref.

No. Score

88 20 Colorado School of Mines

Green Center Roof and Abatement Assessment, Ph 1 of 1

The roof of Green Center (RM #4144) is original and was installed in 1972. It requires constant maintenance and is saturated in several locations. Roof failure would affect not only on-going academic programs but also the main computer and networking center for the entire campus, which is located on the top floor of the building. The roof structure and underside of the roof deck contain sprayed-on asbestos fireproofing so a catastrophic roof failure could result in asbestos contamination of the building. Roof removal and replacement could dislodge the fireproofing, spreading it into the plenum return air system, and thereby contaminating the building with asbestos. An assessment is needed to determine the appropriate phasing of work for the project, including the relocation of building occupants and programs, maintenance of critical computer operations, sequencing of work activities and appropriate methods and scope of asbestos abatement required prior to roof replacement.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|----------|-------------------|----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$48,620 | All Phases | \$48,620 |









| Ref No. | Current Fun Recommenda |
|------------|---------------------------|
| | |

89 21 Department of Public Safety

CSP Academy/CGW Repairs, Ph 2 of 3

The Academy Building (RM #6227) is 33 years old. The mechanical and electrical systems are worn out and need repairs and replacement to bring the system up to current standards and codes. The roof has been replaced within the last 10 years but needs maintenance to last the 20-year life cycle. The exterior building system walls, windows and doors need repairs and replacement to prevent further deterioration. The interior walls, ceilings, and floors need repairs/replacement. Plumbing fixtures are old, worn out, and need replacement. The entire building has been transferred to DPS/CSP from DMA. Phase 1 provides for repair and replacement of the boiler, pumps, controls, valves, distribution piping and other components of mechanical system. Phase 2 electrical system repairs/update; facility exterior repairs/maintenance, roof, windows, doors. Phase 3 interior facility systems repairs/replacement; flooring, ceilings, bathroom partitions/fixtures. Academy Building is pictured

| PRIOR PHASING M00105 FY00/01 Ph 1 - Mechanical | \$257,854 | FUTURE PHASING FY02/03 Ph 3 - Interior Systems | \$149,122 |
|--|-----------|---|-----------|
| (FUNDED TO DATE) | \$257,854 | (PROJECT BALANCE) | \$149,122 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Electrical, Doors, Windows | \$304,962 | All Phases | \$711,938 |







nding

December 5, 2000

ation

\$304,962

Current Funding

December 5, 2000

Recommendation

\$395,950


90 21 Department of Corrections

Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 2 of 4

The storm sewer and sanitary sewer systems are cross-connected at several points throughout Colorado Territorial Correctional Facility (pictured). These cross-connections have created problems for the Fremont Sanitation District and have impacted its ability to fully process the demand. As a result the District is threatening to impose fines. The scope of the project and the number of impacted storm and sewer lines are now determined to be twenty-five percent larger than initially defined. Phase 2 of this project will correct the cross-connection deficiencies.

| PRIOR PHASING M90007 FY99/00 Ph 1 - Assessment | \$98,500 | FUTURE PHASING FY02/03 Ph 3 - Failed Sanitary Lines FY03/04 Ph 4 - Failing Sanitary Lines | \$390,692 \$606,092 |
|--|-----------|---|------------------------|
| (FUNDED TO DATE) | \$98,500 | (PROJECT BALANCE) | \$996,784 |
| CURRENT PHASE FY01/02 Ph 2 - Sanitary/Storm Cross | \$395,950 | PROJECT TOTAL All Phases | \$1,491,234 |





Ref. No.

Score

Ref.

No. Score


91 21 Colorado State University

Install East Drive to Center Street Steam Loop, Ph 3 of 3

Installation of this line creates a steam loop that can provide steam service to buildings around the Oval in the event of a failure in the main line currently feeding these buildings. This project had previously been submitted as a capital construction project, but due to its criteria it was submitted as a controlled maintenance project. Phase 1 is for design. Phase 2 installs a new concrete tunnel from the end of the existing tunnel at West Drive to the existing tunnel in Center Street. Phase 3 installs 16 inch steam and 6 inch condensate lines in the tunnel. University Avenue is pictured.

| | FUTURE PHASING | |
|-----------|-------------------------------|---|
| \$149,000 | | |
| \$439,244 | | |
| \$588,244 | (PROJECT BALANCE) | \$0 |
| | PROJECT TOTAL | |
| \$619,386 | All Phases | \$1,207,630 |
| | \$439,244 \$588,244 | \$149,000 \$439,244 \$588,244 (PROJECT BALANCE) PROJECT TOTAL |





Current Funding Recommendation

\$619,386


92 21 University of Colorado at Boulder


Drainage Improvements, Main Campus, East Half, Ph 2 of 2

Building construction and hardscaping over many years have contributed to problems with drainage. An overall plan has not been followed. The drainage systems that exist are old and inadequate. Wardenberg, Baker, and Libby Drive drainage's are not properly configured to channel flows. Phase 2- completes storm sewer improvements for drainage basin at Libby Drive, Baker Drive and Wardenberg Drive.

| PRIOR PHASING M00043 FY00/01 Ph 1 - Folsom St 18th St. | \$616.043 | FUTURE PHASING | |
|--|-----------|-------------------|-------------|
| (FUNDED TO DATE) | \$616,043 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Libby, Baker & Wardenberg | \$449,807 | All Phases | \$1,065,850 |







December 5, 2000

Current Funding Recommendation

\$449,807

Ref.

No.

| Current Funding |
|-----------------|
| Recommendation |

\$293,191

December 5, 2000

Ref.

No. Score

93 21 Colorado State University


Replace Deteriorated Roads & Sidewalks, Ph 2 of 5

Asphalt streets on campus have deteriorated due to age, intensity of use, and need to be repaired to remain viable for automobile and bicycle traffic. Sidewalks and gutters are broken and present safety hazards to pedestrians and bicycle riders. Phase 2 - replaces Mason S. Dr. and N. Meridian.

| PRIOR PHASING M00033 | | FUTURE PHASING | |
|-------------------------------|-----------|--------------------------|-------------|
| FY00/01 Ph 1 - Rampart | \$544,500 | FY02/03 Ph 3 - South | \$260,024 |
| | | FY03/04 Ph 4 - W. Pitkin | \$288,189 |
| | | FY04/05 Ph 5 - Oldmain | \$312,994 |
| (FUNDED TO DATE) | \$544,500 | (PROJECT BALANCE) | \$861,207 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Mason S. Drive | \$293,191 | All Phases | \$1,698,898 |







Ref.

No. Score

94 21 University of Northern Colorado

Replace Deteriorated Stairs and Walkways Campus Wide, Ph 2 of 2


The front and rear exits at several central campus buildings are in poor condition. Treads and landings have flaked, spalled or just been worn down, resulting in uneven tread surfaces. In addition, the landings were constructed with a riser near the door; this is specifically prohibited in building and life safety codes because of the tripping hazard. This project will also address broken, deteriorated and loose flagstone sidewalks, other sidewalks in disrepair and other site features requiring repair or replacement. Many of the sidewalks are utility tunnel tops and are in poor condition and do not meet the current load requirements of the campus. This project would either overlay the existing tunnel tops or remove and replace these slabs. This request consolidates various requests over several years to achieve an organized, systematic approach to needed repairs. Phase 1 includes architect/engineer fees, sidewalk, curb and gutter improvements. Phase 2 will finish the sidewalk, curb, and gutter improvements.

| PRIOR PHASING M00054 | | FUTURE PHASING | |
|---------------------------------|-----------|-------------------|-----------|
| FY00/01 Ph 1 - Design/Repairs A | \$214,721 | | |
| (FUNDED TO DATE) | \$214,721 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Repairs B | \$580,480 | All Phases | \$795,201 |









Current Funding Recommendation

\$580,480

Current Funding Recommendation

\$214,413

No. Score 95 24 Department of Military Affairs

Ref.

Armory Roof Replacements, Ph 2 of 5

This project is phase 2 of a five-year plan to replace and repair roofs per the recommendations of the 1999 Roof Assessment performed for the Department of Military Affairs by a professional roofing consultant. The Assessment contains an economic analysis showing the most cost-effective method of maintenance-repair or replacement. The roof survey assessment has identified 21 repairs that are required. Two of those roof repairs are included in Phase 2 of this request. Phase 2 includes roofs at the Englewood Armory location (pictured), buildings #268 (RM #6021) and #248 (RM #n/a). The problems vary in complexity and cost.

| CURRENT PHASE FY01/02 Ph 2 - Englewood | CCFE \$214,413 | FF \$57,400 | PROJECT TOTAL All Phases | CCFE \$1,175,001 | FF \$658,354 |
|---|--------------------------|-----------------------|----------------------------------|----------------------------|-----------------|
| (FUNDED TO DATE) | \$205,180 | \$57,400 | (PROJECT BALANCE) | \$755,408 | \$600,954 |
| | | | FY04/05 Ph 5 - Various Locations | \$280,481 | \$204,564 |
| | | | FY03/04 Ph 4 - Various Locations | \$267,434 | \$113,044 |
| FY00/01 Ph 1 - Various Locations | \$205,180 | \$57,400 | FY02/03 Ph 3 - Various Locations | \$207,493 | \$283,346 |
| PRIOR PHASING M00098 | CCFE | FF | FUTURE PHASING | CCFE | FF |









Current Funding Recommendation

\$328,930

96 24 Colorado State University Replace Deteriorated Roofing Various Buildings, Ph 2 of 2

Ref.

No.

Score

Roofing on several buildings is deteriorated and leaking. The roofs on most of these buildings are original, and in some cases are over 50 years old and have little or no positive drainage. Phase 2 replaces roofing on Administration (RM #3258), Forestry (RM #3260), Insectary (RM #3296), Engineering Res. Center (RM #3557), Copp Institute (RM #3573), Solar Houses (RM #3577, 3579 & 3580), Animal Quarters (RM #3664) and Heating Plant (RM #3245). Administration is pictured.

| PRIOR PHASING M00034 | | FUTURE PHASING | |
|----------------------------------|-----------|-------------------|-----------|
| FY00/01 Ph 1 - Various Buildings | \$464,260 | | |
| (FUNDED TO DATE) | \$464,260 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Various Buildings | \$328,930 | All Phases | \$793,190 |









Ref.

No. Score

97 24 Colorado School of Mines

Campus Secondary Electrical Power Repair Deficiency Assessment, Ph 1 of 1

The facility audit identified secondary power distribution deficiencies as a major concern in several buildings on campus. These deficiencies result from breaker panels and distribution wiring that are reaching the end of their useful life. Some areas appear to be overloaded with circuits added for computers and other office equipment that were not accounted for in the original design. The assessment will develop the scope of system modifications and logical phasing required eliminating this life safety concern.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|----------|-------------------|----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$55,176 | All Phases | \$55,176 |

97 of 168

| 1 |
|--------|
| |
| 1 |
| |
| - Ball |
| - |
| |
| - |
| |
| - |
| |

Current Funding

Recommendation

\$55,176

CURRENT PHASE

FY01/02 Ph 1

| Ref. No. Score | | | Current Funding Recommendation |
|---|---------|----------------------------------|-----------------------------------|
| 98 24 University of Colorado at Colorado Springs | | | \$73,986 |
| Repair/Replace Water Main Valves, Ph 1 of 1 | | | |
| Water main valves in numerous locations are deterior replace 26 water valves. | ating a | nd in some cases are inoperable. | This project will repair or |
| PRIOR PHASING | | FUTURE PHASING | |
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |

\$73,986

PROJECT TOTAL

All Phases

December 5, 2000

\$73,986

| | University of Colorado at Colorado Springs Campus Map |
|--|---|
| CAMPUS HOUSING VILLACE APPLY HOUSE (23) HIGH FILL HIGH FILL HI | DOINCERING BURDING BURDING CONTER UNITER CON |
| | ROMINISTRATIVE BOUTH ROMINISTRATIVE COT & CREATION COT & CREATION CENTER |

Ref.

No. Score

99 24 Department of Human Services

Repair/Replace Campus Tunnel and Utility Infrastructure System, CMHIP, Ph 1 of 5

It has been determined through selective forensic testing (cameras and destructive testing) that the chilled water, soft water, compressed air, raw water, steam distribution, domestic water, and the distribution tunnel need to be repaired and/or replaced. Some of the tunnel infrastructure systems have not been replaced since they were originally installed over 50 years ago. Phase 1 repairs utility systems in North Crossover Tunnel, West Crossover Tunnel, a portion of Northeast Tunnel, and West Tunnel to Center Road. Phase 2 repairs utility systems in West Tunnel to 17th Street and South Crossover Tunnel. Phase 3 repairs utility systems in West Crossover Tunnels to Buildings 120-121 and 125-126. Phase 4 repairs utility systems in East Tunnel. Phase 5 repairs utility systems in Main Tunnel South Campus.


FUTURE PHASING

PRIOR PHASING

| | | FY02/03 Ph 2 - W, SX Tunnels | \$1,235,000 |
|--------------------------------------|-------------|---|-------------|
| | | FY03/04 Ph 3 - WX, NX Tunnels | \$1,235,000 |
| | | FY04/05 Ph 4 - E Tunnel | \$1,235,000 |
| | | FY05/06 Ph 5 - Main Tunnel South Campus | \$177,000 |
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$3,882,000 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - NX, WX, NE, W Tunnels | \$1,057,801 | All Phases | \$4,939,801 |







Current Funding Recommendation

\$1,057,801

Current Funding

100 24 Adams State College

Ref.

No.


Score

Upgrade Campus Irrigation, Ph 1 of 3

Existing irrigation systems are served by city potable water through multiple buildings. Efforts throughout the years to standardize materials have not been possible and a patchwork system remains which is now badly in need of upgrading. The college currently owns a well that has been capped temporarily. The well is approximately a quarter of a mile deep and has capacity of about 500 gallons per minute. The well casing will potentially require rebuilding due to age. The proper sized pumps, holding pond, centralized control and distribution system would be developed. Approximately 50% of the old piping systems will remain intact by capping the lines at the building source and then tying into new main lines. The balance of the existing system would require new design and total replacement. By utilizing existing water rights instead of paying the city water fees in addition to a sophisticated and central control system a cost savings would be realized. Phase 1 is a feasibility analysis to determine the condition of the well and if it is necessary to re-case as is anticipated.

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Well Casing FY03/04 Ph 3 - Distribution System | \$522,500 \$818,476 |
|--|----------|--|------------------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$1,340,976 |
| CURRENT PHASE FY01/02 Ph 1 - Analysis | \$25,000 | PROJECT TOTAL All Phases | \$1,365,976 |





December 5, 2000

Recommendation

\$25,000

| PRIOR PHASING M00104 |
|------------------------------|
| FY00/01 Ph 1 - Various Sites |
| (FUNDED TO DATE) |
| CURRENT PHASE |

LHK-01201

Colorado Government Technology Services

Ref.

No. 101 24

Score

Replace Batteries for Back-Up Generators, Ph 2 of 3 The remote sites have emergency generators, which charge a series of eight heavy-duty power storage batteries. In the event of a power outage from the commercial source regularly used, the batteries are an integral part of the system needed in order to maintain power for the public safety communications system. There are 60 sets of batteries that were installed in 1980.

There are additional 10 sets that will have been installed for 20 years by the end of this five year controlled maintenance cycle. Although the manufacturer's warranty is for 20 years, CGTS has already experienced failures and had to replace site battery sets over the past few years. These batteries need to be replaced as soon as possible. Phase 2 includes 28 sites. Akron is pictured.

| PRIOR PHASING M00104 | | FUTURE PHASING | |
|------------------------------|----------|------------------------------|-----------|
| FY00/01 Ph 1 - Various Sites | \$84,000 | FY02/03 Ph 3 - Various Sites | \$28,700 |
| (FUNDED TO DATE) | \$84,000 | (PROJECT BALANCE) | \$28,700 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Various Sites | \$87,780 | All Phases | \$200,480 |

101 of 168



Current Funding Recommendation

\$87,780

Ref.

Score No.


102 24 Department of Corrections

Repair/Replace Water Treatment and Piping Systems, Ph 1 of 1

The water quality at Arkansas Valley Correctional Facility is very hard with high concentrations of calcium and magnesium. This has contributed to both corrosion and scaling conditions in the domestic water system. The project funds the initial monitoring of the water treatment plant softening system, replacing the supply lines to the toilets and showers in the housing units with larger diameter copper pipe, and replacing buried copper pipe with polyvinyl chloride pipe and associated valves.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$368,648 | All Phases | \$368,648 |





Current Funding Recommendation

\$368,648

December 5, 2000

Current Funding Recommendation

\$94,090

103 24 Fort Lewis College

Replace Deteriorated Tennis Courts, Ph 1 of 2

The existing tennis courts have deteriorated to the point that they must be replaced, the asphalt base has settled which has created an irregular playing surface. The reconstruction will require removal and replacement of the sub-base materials. Additionally, the plastic playing surface has deteriorated faster then anticipated and now renders the courts unusable and unsafe. The work will be accomplished in two phases. The design work will be accomplished in Phase I. It is expected that the design work will be completed in time to permit the Phase II construction of the new tennis courts the following summer and in time for use the next academic year.

PRIOR PHASING

Score

Ref.


No.

| CURRENT PHASE FY01/02 Ph 1 - Design | \$94,090 | PROJECT TOTAL All Phases | \$884,990 |
|--|----------|-----------------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$790,900 |
| | | FY02/03 Ph 2 - Construction | \$790,900 |
| | | | |

FUTURE PHASING







104 of 168

SBP PRIORITIZED STATEWIDE PROJECT REQUEST DESCRIPTIONS FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

Ref.

No. Score

104 24 University of Colorado Health Sciences Center


Colorado Psychiatric Hospital, Window Replacement, Ph 1 of 2

The Colorado Psychiatric Hospital (CPH) (RM #9007) was constructed in 1924 as part of the initial construction of the University of Colorado medical School complex. This facility will remain an integral part of the 9th Avenue and Colorado Boulevard campus well into the next century. Windows in the building are mostly original construction units. They are old single pane glazing in wood encasements and have significantly outlived their useful life. Although every effort has been made to maintain these windows at an acceptable functional level, many years of usage and the outdoor environment have caused noticeable deterioration. The window glazing and weatherproofing seals are brittle, loose and ineffective. Much of the window weatherproofing caulk contains asbestos material and lead-based paint and must be removed as a hazardous material. Drafts are a particular problem in many rooms. Thermal energy losses via single pane glazing and ineffective weatherproofing can be assumed to be substantial. Phase 1 - replace north-facing windows and doors. Phase 2 - replace south-facing windows and doors.

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - South Facing | \$425,000 |
|-----------------------------|-----------|---|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$425,000 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - North Facing | \$515,000 | All Phases | \$940,000 |







December 5, 2000

Current Funding Recommendation

\$515,000

Ref.

Score No.

105 24 Western State College


Repair/Replace Heating/HVAC, Systems, Ph 1 of 1

The present HVAC and Heating systems at Paul W. Wright Gym (RM #100) are in poor condition after 25 to 30 years of use. The old piping system for the heating system is leaking and does not circulate the heated water throughout the system. The HVAC units throughout the building are broken, have missing parts, fan coil units are not working, exhaust fans are inoperable. The replacement of the old hydronic lines and steam heating lines within the building. Install new system pumps, air separator, expansion tanks and boiler pumps and air handling units in the west gymnasium.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|---------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 \$ | 396,210 | All Phases | \$396,210 |







Current Funding Recommendation

\$396,210

Ref.

No. Score

106 24 Colorado Historical Society

Trinidad Site Accessibility and Building Improvements, Ph 1 of 1

This project will upgrade site walkways and restrooms, add site lighting, and install an elevator in the Barglow House (RM #4115) to improve accessibility to the site. Other exterior improvements include a new site fence for improved security, demolition of three sheds, a sprinkler system to limit water overspray on porches, roof repairs at the Barglow House, and storm windows and exterior doors at the Baca House (RM #4114). The project also includes new furnaces at the Baca House and Bloom House (RM #4113).

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$293,572 | All Phases | \$293,572 |









Current Funding Recommendation

\$293,572

December 5, 2000

Current Funding Recommendation

107 24 Colorado State University

Ref.

No.

Score

Replace Deteriorated Items, San Luis Valley and CSFS Foothills, Ph 1 of 1

The existing Greenhouse (RM #7325) is extremely deteriorated, and cannot support the research being done at the station. Buildings (RM #'s 3532, 3531, 3550 and 3533) at CSFS are old and in poor condition. Roofing on the shop is leaking, and the floor has large cracks that allow water to enter the soil below causing settling. The modular office is in need of roofing, painting and window replacement. The headquarters needs emergency lighting to meet fire code. This project replaces the Greenhouse at San Luis valley and replaces or repairs items at the Fort Collins CSFS site, including roofing, windows, painting, caulking and emergency lighting. The Greenhouse is pictured in the upper corners and the CSFS is pictured in the lower corners.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|--------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 \$2 | 94,042 | All Phases | \$294,042 |









Current Funding

\$365,279

Ref.

Score No.

108 24 Western State College


Repair/Replace Parking Lots/Streets - Zone 1, Ph 2 of 5

The existing parking lots, curbs and streets have deteriorated over the past 35 years. The structural integrity of the sub-base has failed. There are very large potholes and large cracks throughout the parking lots and streets. This project includes Phase I through V - Zone I of Campus. These phases will include the removal of the existing asphalt and sub-base, curb and gutter. New sub-base will be installed, with the installation of the binder and wearing courses of Asphaltic Concrete Paving. Also the repair and replacement of curb and gutter will also be accomplished in Zone 2 of the Campus.

| PRIOR PHASING M00030 FY00/01 Ph 1- Zone 1 | \$360,500 | FUTURE PHASING FY02/03 Ph 3 - Zone 1 FY03/04 Ph 4 - Zone 1 FY04/05 Ph 5 - Zone 1 | \$329,394 \$337,840 \$269,692 |
|---|-----------|---|-------------------------------------|
| (FUNDED TO DATE) | \$360,500 | (PROJECT BALANCE) | \$936,926 |
| CURRENT PHASE FY01/02 Ph 2 - Zone 1 | \$365,279 | PROJECT TOTAL All Phases | \$1,662,705 |







December 5, 2000

Ref.

No. Score

109 24 Camp George West

Limited CGW Paving and Removal of 2 Hazardous Buildings, Ph 1 of 1

This request is for the most deteriorated paving section to be repaired and for two hazardous and deteriorated buildings to be removed. Previous CM projects include repair and replacement of deteriorated infrastructure including sanitary sewer, water distribution, electrical, gas, and telephone distribution systems. Future plans call for the analysis of the remaining paving needs, storm sewer, and other site enhancements. The identification and prioritization of the future repairs will be based upon the master plans of the current Camp George West occupying agencies.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 \$ | 5122,346 | All Phases | \$122,346 |











Current Funding Recommendation

\$122,346

| Ref. No. | Score | Current Funding Recommendation |
|-------------|---------|---|
| 110 | 28 | Department of Corrections \$345,540 |
| Rep | oair/Re | place Roofs, Ph 3 of 4 |
| Corr | ectiona | has replaced various roofs at Colorado Correctional Center, Colorado Territorial Correctional Facility, Buena Vista I Facility, Fremont Correctional Facility, and Centennial Correctional Facility. This phase funds the replacement of 20-year-old roofs for Housing Units A through G (RM #3020) at Centennial (pictured). |

| 0 | , | 0 | 0 (| , | (i) | |
|------------|--------------------------|---|------------|-----------------------|------|-------------|
| PRIOR PHAS | ING M80022 | | | FUTURE PHASING | | |
| FY98/99 Ph | 1 - CCC, CTCF, BVCF, FCF | | \$321,432 | FY02/03 Ph 4 - CCF, C | 200 | \$135,110 |
| FY00/01 Ph | 2 - CCF, FCF, CTCF | | \$476,786 | | | |
| (FUNDED TO | DATE) | | \$798,218 | (PROJECT BALANCE) |) | \$135,110 |
| CURRENT PI | HASE | | | PROJECT TOTAL | | |
| FY01/02 Ph | 3 - CCF | | \$345,540 | All Phases | | \$1,278,868 |
| | | | | | | |







December 5, 2000

Ref.

No. Score

111 28 Pueblo Community College

Replace HVAC System and Roof Repair Health Science Annex, Ph 1 of 1

Currently the facility is air conditioned by the "Critical Cooling" units that were installed when the building was used as a MRI clinic for the area hospitals. Since the facility was given to PCC it has been used for the Readtech program that include classroom, lab, and offices. The cooling is very marginal throughout the building. The system is showing corrosion on the cooling coils. An energy analysis was done and showed the HVAC equipment runs continuously 24 hours a day, 7 days a week. Upgrades to the existing campus wide DDC system campus wide will be integrated with this system when done. The roof is in need of repair on the "built up" portion needing patches and ballast replacement, the roof tiles have pieces that are broken or missing that need to be replaced. Health Science Annex (RM #8119) is pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|---------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 \$1 | 162,659 | All Phases | \$162,659 |







Current Funding Recommendation

\$162,659

Ref.

No. Score


112 28 University of Northern Colorado

Replace Theater Ceiling Frasier Hall, Ph 1 of 1

The 600-seat theater in Frasier Hall (RM #834) is the largest single auditorium on campus, and is used extensively for theater and music productions, including guest appearances by nationally known performers. The College of Performing and Visual Arts has undertaken restoration of the theater finishes with private contributions, except for the ceiling. The ceiling is stained and cracked, with some missing plaster. The finish material applied to the ceiling was discovered to contain asbestos, requiring special removal procedures. Frasier Hall is pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$360,792 | All Phases | \$360,792 |

| -Silvines | |
|-----------|---|
| | |
| | THE REAL PROPERTY OF THE PARTY |
| | |
| | |
| | |
| | |





Current Funding Recommendation

\$360,792

| Ref. No. | Score | | Current Funding Recommendation |
|-------------|-------|--|-----------------------------------|
| 113 | 30 | University of Colorado at Colorado Springs | \$297,812 |

Repair Campus Infrastructure, Ph 1 of 3


The campus is experiencing erosion and drainage problems in many areas. There is deterioration of roads and fire lanes campus wide. Repairs and corrections will be made in three phases. Phase 1 will address subsurface drainage around the Science Building and repair a damaged 21" storm sewer in the fire access road west of the Engineering Building. It will also address the main access road to Lot 4 and widen and resurface the fire lane behind the Campus Services Building. Phase 2 will stabilize a slope failure behind Dwire Hall and upgrade the footpath and drainage behind the Housing Village. It will also address the main access road to Lot 3 and East Entrance as well as Lot 1 access. Phase 3 will address filled drainage ditches and road erosion adjacent to Stanton Road. It will also replace two retaining walls and repair and resurface fire lane and access roads in three areas.

| PRIOR PHASING | | FUTURE PHASING | |
|---|-----------|--------------------------------|-------------|
| | | FY02/03 Ph 2 - Slope Failures | \$501,744 |
| | | FY03/04 Ph 3 - Retaining Walls | \$292,583 |
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$794,327 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Fire Access, Subsurface Drainage | \$297,812 | All Phases | \$1,092,139 |









December 5, 2000

| Score | | | |
|-------|--|--|--|

Ref.

No.

114 30 Arapahoe Community College

Structural/Exterior Concrete Repair Main Annex, Ph 2 of 2

The Main Building (RM #768) decks are 3 1/2" concrete poured on top of pan roofs over occupied areas. The concrete has cracked and deteriorated exposing structural steel. The steel is beginning to rust and leaks are entering occupied spaces. The existing concrete topping slab and waterproofing will be replaced by a rubberized asphalt waterproofing membrane system, insulation, and concrete topping slab.

| PRIOR PHASING M00055 FY00/01 Ph 1 - Roof Beams | \$331,950 | FUTURE PHASING | |
|--|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$331,950 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | A |
| FY01/02 Ph 2 - Concrete Decks | \$375,573 | All Phases | \$707,523 |









Current Funding Recommendation

Ref.

No. Score

115 30 Trinidad State Junior College

Repair Basketball/Volleyball Courts and Campus Streets/Parking Lots, Ph 1 of 1


Outdoor basketball and volleyball courts have serious cracking and heaving problems. The uneven surfaces present a safety hazard to persons playing on them. Several streets on campus are badly deteriorated and have chuckholes, which damage vehicles and make snow removal difficult. As part of this project, it is proposed that the two main parking areas are patched, cracks filled and seal coated. Sealing of these lots will prevent further water penetration and prevent costly overlay or replacement. The courts will be excavated, backfilled and have a new surface installed.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$253,710 | All Phases | \$253,710 |











Current Funding Recommendation

\$253,710

Ref.

No. Score

116 30 Department of Human Services

Repair/Replace Secondary Electrical Systems, Ph 3 of 3

This project replaces secondary electrical service at Colorado Mental Health Institute at Fort Logan (CMHIFL), Colorado Mental Health Institute at Pueblo (CMHIP), Grand Junction Regional Center (GJRC) and Division of Youth Corrections (DYC) facilities. Many of the existing secondary components present safety hazards, are not code compliant, and replacement parts are no longer available. Phase 3 (the final phase of what was originally a five-phase project) will replace the main switchgear and Federal Pacific secondary electrical panels and emergency generator in Building 125 (RM #2891) (pictured) at CMHIP.

| PRIOR PHASING M90083 | | FUTURE PHASING | |
|------------------------------------|-----------|-------------------|-------------|
| FY99/00 Ph 1 - CMHIFL, CMHIP, GJRC | \$407,850 | | |
| FY00/01 Ph 2 - CMHIP | \$269,550 | | |
| (FUNDED TO DATE) | \$677,400 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 3 - CMHIP | \$698,750 | All Phases | \$1,376,150 |
| | | | |





December 5, 2000

Current Funding Recommendation

\$698,750

December 5, 2000

Current Funding Recommendation

\$325,629

117 30 Pikes Peak Community College

Lighting and Controls Retrofit Aspen and Breckenridge Buildings, Ph 1 of 2

The lighting plan of 22 years ago for the Centennial Campus was developed during a national energy shortage, so energy usage was held to a minimum. The lighting levels in all areas of the campus are between thirty and fifty foot-candles at the work surface. These levels are below IEEE accepted standards for most tasks, and in some cases create an unsafe condition. Project would improve the overall lighting levels within the buildings by approximately 30% throughout the campus and also reduce energy costs for lighting by 50%. The project will consist of the removal of existing lamps and ballasts and installing new ballasts, reflectors, lamps and (motion and heat sensitive) control devices in each classroom, office and corridor. Phase 1 will be the design and the first and second floors in Aspen Building. Phase 2 will be the third floor of Aspen building, and the second and third floors of Breckenridge building. Pikes Peak Centennial Campus is pictured.

Ref.

No.

Score

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Aspen 3rd Fl./Breckenridge 2nd & | \$235,801 |
|---|-----------|---|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$235,801 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Design/Aspen 1st & 2nd Floor | \$325,629 | All Phases | \$561,430 |







118 of 168

SBP PRIORITIZED STATEWIDE PROJECT REQUEST DESCRIPTIONS FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

Ref.

No. Score

118 30 Colorado Northwestern Community College

HVAC Modifications and Upgrade - Rangely Campus, Ph 1 of 1

A majority of CNCC's buildings use evaporative cooling systems, which are both, outdated and do not have enough cooling adequate capacity for our current needs. Several offices in the McLaughlin Building (RM #7723) do not have access to HVAC vents or ducts needed to provide heating or cooling. Some of the control valves and other components in our heating systems are not fully operable and thus reduce our ability to maintain consistent heat throughout the buildings. The HVAC systems in Rector (RM #7727), Allesbrook (RM #7726), Hill (RM #7729), Hefley (RM #7722), Cramer (RM #7737), Yaeger (RM #7736), Allred/Real (RM #7735), Hays (RM #7739) buildings need to be upgraded a with refrigerated air cooling system that use the existing heating ductwork wherever possible. McLaughlin building needs additional ductwork to provide heating and cooling to all existing rooms. Heating system components throughout the Rangely campus would be tested and repaired and/or replaced where needed. The HVAC system control would be upgraded to remove non-compliable components and to standardize the system. Allesbrook building is pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$611,500 | All Phases | \$611,500 |







Current Funding Recommendation

\$611,500



hydronic boilers in the building's mechanical room eliminating the need to supply steam from the central heating plant. Wheeler Hall is pictured

PRIOR PH

No.

Score

| CURRENT PHASE FY01/02 Ph 1 - Design/Unit Ventilators | \$202,118 | PROJECT TOTAL All Phases | \$294,823 |
|---|-----------|---------------------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$92,705 |
| | | FY02/03 Ph 2 - Hydronic Boilers | \$92,705 |
| FRICKFHASING | | FUTURE FTIAGING | |

The aging unit ventilators will continue to deteriorate, disrupting operations as they are taken out of service for repair. Inefficient and inadequate heating and cooling is typical. The 20-year-old existing steam supply and condensate lines need repaired. Phase 1 would consist of all the design work and replacing all of the 39-year-old unit ventilators in Wheeler Hall (RM #126) and the Life Science Building (RM #127). The ventilators have served beyond their useful life; parts are extremely difficult to obtain and some components are not available. The new ventilators will be more energy-efficient and will have the ability to be controlled by the campus energy management system. Phase 2 would consist of installing four packaged modular

SBP PRIORITIZED STATEWIDE PROJECT REQUEST DESCRIPTIONS FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM



| HASING | | FUTURE PHASING | |
|--------------------------------|-----------|---------------------------------|-----------|
| | | FY02/03 Ph 2 - Hydronic Boilers | \$92,705 |
| D TO DATE) | \$0 | (PROJECT BALANCE) | \$92,705 |
| IT PHASE | | PROJECT TOTAL | |
| Ph 1 - Design/Unit Ventilators | \$202,118 | All Phases | \$294,823 |
| | | | |

119 30 Otero Junior College Wheeler/Life Science HVAC Equipment Replacement, Ph 1 of 2



December 5, 2000

Current Funding Recommendation

\$202,118

| Ref. No. | | | Current Funding Recommendation |
|-------------|----|----------------------------|-----------------------------------|
| 120 | 30 | Arapahoe Community College | \$383,179 |

Replace HVAC Equipment, Ph 1 of 2

This project will replace rooftop units on the Annex Building (RM #769). The rooftop mechanical systems for the Automotive Technology Center, the Gym/Fitness Center, and the natatorium are deteriorating. The gas heat exchangers are beginning to lose efficiency and the pneumatic controllers fail repeatedly. The Automotive area and the Fitness Center are a constant source of complaints from users. These units are over 20 years old and replacement parts are difficult to obtain. Phase 1 would address replacement of the equipment serving the Automotive Technology Center and the Gym/Fitness Center. Phase 2 will provide a replacement for the swimming pool area.

PRIOR PHASING

| | | FY02/03 Ph 2 - Natatorium | \$197,510 | |
|---------------------------------------|-----------|---------------------------|-----------|--|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$197,510 | |
| CURRENT PHASE | | PROJECT TOTAL | | |
| FY01/02 Ph 1 - Auto Tech, Gym/Fitness | \$383,179 | All Phases | \$580,689 | |

FUTURE PHASING









| Ref. No. | Score | | Current Funding Recommendation |
|-------------|--------|--|---|
| 121 | 30 | Red Rocks Community College | \$38,284 |
| Rep | lace I | Expansion Tank, Ph 1 of 1 | |
| | • | sion tank that regulates the water pressure to both lacement. The tank was rebuilt 10 years ago and ha | Main Building (RM #764) and West Building (RM #766) is in s now deteriorated beyond repair. |
| PRIC | R PHA | SING | FUTURE PHASING |

| (FUNDED TO DATE) | |
|------------------|--|

CURRENT PHASE FY01/02 Ph 1

\$0 (PROJECT BALANCE) \$0 PROJECT TOTAL \$38,284 All Phases \$38,284





Current Funding

Recommendation

122 30 Capitol Complex Facilities

Ref.

No.

Score

Upgrade/Replace Domestic Water Pump Systems and Heat Exchangers, Ph 1 of 1

The existing domestic water booster pump systems in the Centennial Building (RM #140), Power Plant (RM #139) and State Services Building (RM #144) are outdated. Adequate water pressure cannot be maintained to the upper floors of the buildings. All gate valves, pipes and other equipment are deteriorated. Water quality is poor because of corrosion and contamination of related piping. The systems have high maintenance costs and waste water and energy. The existing domestic water heat exchangers in three buildings, Centennial Building (RM #140), State Human Services Building (RM #146) and State Office Building (RM #143) are old and deteriorated. They leak and are incapable of holding a constant temperature, which causes a scalding hazard.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|---------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | 326,315 | All Phases | \$326,315 |







December 5, 2000

\$326,315

Ref.

No. Score

123 30 Mesa State College

Building Repairs - Houston Hall, Ph 4 of 4

Houston Hall (RM #213) was constructed in 1940 and is the oldest building on campus. It was extensively remodeled in 1980. During the past several years, it has become evident that several major problems exist within the building. These problems include: a lack of sufficient ventilation to several major classroom and office areas causing concern for the health and safety of students; a lack of adequate temperature control in several major classroom and office areas; and boilers and chillers which are nearing the end of their expected useful life and are beginning to show signs that imminent replacement is necessary. The roof is also nearing the end of expected useful life. It is now leaking in a few areas. Phase 4 replaces the roof. Houston Hall is pictured.

| PRIOR PHASING M80034 | | FUTURE PHASING | |
|------------------------------|-------------|-------------------|-------------|
| FY98/99 Ph 1 - Rooftop Units | \$316,245 | | |
| FY99/00 Ph 2 - Units/Boilers | \$425,387 | | |
| FY00/01 Ph 3 - VAV, Controls | \$323,341 | | |
| (FUNDED TO DATE) | \$1,064,973 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 4 - Roof | \$325,493 | All Phases | \$1,390,466 |







Current Funding Recommendation

\$325,493

Ref.

Score No.


124 30 Adams State College

Replace Doors/Windows, Various Buildings, Ph 1 of 2

These buildings were built prior to the energy efficient window and doors systems utilized in today's construction. Many windows and doors are antiquated, leak and do not operate properly. Due to the age of the system, parts for repairs are hard to come by if not impossible. The pay back in energy savings once installations occurs will be substantial due to the condition and number of buildings affected. Phase one would replace windows and doors in the following buildings: Facilities Services (RM #170), Music (RM #159), Leon Memorial (RM #160), Plachy Hall (RM #163), and Richardson Hall (RM #157). Music is pictured.

| ,238 |
|------|
| ,238 |
| |
| ,895 |
| , |







December 5, 2000

Current Funding Recommendation

\$393,657

Score No.

Ref.

125 30 Judicial Heritage

Repair Building Exterior, Ph 1 of 1

There is a large window panel (7' x 8') in the Judicial Building (RM #117) that has a bullet hole. This hole has weakened the integrity of the window and resulted in a potential hazard to anyone entering or exiting the building. A flaw in the engraving process used to install the inscription on the west side of the Judicial Building has resulted in a marring of the exterior granite building panels. The chemicals, which have damaged the stone panels, will be removed and the panels restored.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|----------|-------------------|----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$42,680 | All Phases | \$42,680 |
| | | | |

125 of 168









Recommendation \$42,680

Current Funding

Ref.

Score No.

126 30 Colorado School for the Deaf and Blind

Roof Repair/Replacement Campus-wide, Ph 3 of 3

CSDB campus has many roof areas that have deteriorated to the point that repair is no longer a viable option. In some areas the useful life of roofs can be extended with extensive maintenance on the field and flashing areas. The school proposes replacing approximately 40,000 square feet of flat and shingled roofing surfaces, and repairing approximately 15,000 square feet. Additionally the school plans to repair valley gutters and down spouts. This phase will finish the work. Barn is (RM #2621) pictured.

| | FUTURE PHASING | |
|-----------|-------------------------------|---|
| \$170,773 | | |
| \$204,138 | | |
| \$374,911 | (PROJECT BALANCE) | \$0 |
| | PROJECT TOTAL | |
| \$164,813 | All Phases | \$539,724 |
| | \$204,138 \$374,911 | \$170,773 \$204,138 \$374,911 (PROJECT BALANCE) PROJECT TOTAL |





Current Funding Recommendation

\$164,813

Current Funding Recommendation

\$275,375

127 30 Western State College

Ref.

No.

Score

Repair/Replace Roofing System, Ph 1 of 2

The existing roofing system at the Maintenance building (RM #103) and the Warehouse building (RM #104) which is a flat roof, is leaking into the building. The flashing is coming off and water is penetrating under the roofing system and into the building interior. The water from the leaks is dripping on electrical equipment, HVAC systems and power tools. Also the water leaking into the building is causing damage to the brick and ceiling systems. The plan is to replace the roofing system with a metal standing seam concealed clip sheet metal roofing system. New structural steel framing to support this roofing system is also included to create a sloped roof structure. Maintenance is pictured.

| (FUNDED TO DATE) \$0 (PROJECT BALANCE) \$232,000 |
|--|
| |
| CURRENT PHASE PROJECT TOTAL |
| FY01/02Ph 1 - Maintenance Building\$275,375All Phases\$507,375 |









Ref.

No. Score

128 30 State Capitol Building


Repair/Replace State Capitol Roof, Ph 1 of 1

The Capitol Building (RM #137) roof is deteriorated; the outer office areas on the third floor are experiencing numerous leaks. The membrane lining the gutter has perforations and is beyond patching. The project replaces asphalt shingles and four 6' x 10' flat roofs over the south and north basement entrances with a fiberglass asphalt roofing system, repairs 5,050 square feet of clay tile, repairs valleys and metal flashing, and installs a safety platform at the base of the flag pole and safety tie-off on roof corners. This project includes the damaged and deteriorated roof areas that were not covered by the insurance reimbursement for hail damage.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$511,890 | All Phases | \$511,890 |







December 5, 2000

Current Funding Recommendation

\$511,890

Current Funding

Ref.

No. Score

129 32 Department of Corrections

Replace Mechanical/Plumbing Systems, Ph 1 of 2

This project funds the replacement of inadequate plumbing and mechanical components and systems that have produced unsanitary conditions that have been cited by the health department. The first phase will replace cracked mop sinks, leaking shower pans, and rusted shower partitions at Arkansas Valley Correctional Facility (RM #910) (upper picture) and replace cracked mop sinks at Limon Correctional Facility (RM #7035-7038) (lower picture). Phase 2 will replace shower exhaust fans and mechanical equipment at Arrowhead Correctional Center.

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - ACC | \$255,970 |
|--------------------------|-----------|--------------------------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$255,970 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - AVCF, LCF | \$242,770 | All Phases | \$498,740 |









Recommendation

\$242,770

Ref.

Score No.

130 35 Mesa State College

Electrical Service & Lighting Houston Hall, Ph 1 of 1

Houston Hall was originally construction in 1940 and last renovated in 1980. The electrical service is in need of replacement. During construction of the building repairs - Houston Hall project (see controlled maintenance project M-80034) it was discovered that the main building switch had welded closed. Lighting has not been upgraded since 1980 and is in need of replacement. This project will satisfy the needs of both conditions. Houston Hall (RM #213) is pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$468,160 | All Phases | \$468,160 |







Current Funding

December 5, 2000

Recommendation

\$468,160

Ref.

No. Score


131 36 Auraria Higher Education Center

Replace Fire Security Monitoring Infrastructure System - Campus, Ph 1 of 1

The fire/security infrastructure system is outdated, no longer supported by the manufacture and will not provide the technical or special capacity currently required from recently upgraded building fire/security systems. Currently, there are large portions of the system that need repair/replacement of major components, however, replacement parts are not available. New infrastructure technologies must be integrated with current building fire/security system. Facilities Management building (RM #1212) is pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$858,000 | All Phases | \$858,000 |

| | | | * |
|--------|-----|------------|---|
| Arrech | 北北北 | Landith | |
| | | The second | |
| | | | |
| | - | | |
| | | | |





Current Funding Recommendation

\$858,000

Ref.

No. Score

132 36 Front Range Community College

Repair Deficiencies in Electrical Switchgear, Westminster Campus, Ph 1 of 3

The facility audit performed in 1999 identified that the Main Building electrical rooms and switchgear violate State Code and is a life safety concern. In addition, the components can no longer be maintained due to obsolescence. This project will replacement three-switchgears and branch circuits and add room clearance to comply with overall safety standards. The project proposes the work to be done in three phases. Phase 1 complete design of entire project. Phase 2 will replace 2 main electrical switchgears. Phase 3 will replace the remaining switchgears. Westminster Building (RM #750) is pictured.

FUTURE PHASING

| | | FY02/03 Ph 2 - 2 Main Switch Gears FY03/04 Ph 3 - 1 Main Switch Gears | \$766,864 \$418,360 |
|-----------------------|-----------|--|------------------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$1,185,224 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Design | \$201,488 | All Phases | \$1,386,712 |





Current Funding Recommendation

\$201,488

Current Funding

Recommendation

\$633,686

133 36 Colorado State University

Ref.

No.


Score

Replace Deteriorated Mechanical, VTH, Ph 2 of 5

The HVAC system in the Veterinary Teaching Hospital (VTH) (RM #3445) is 20 years old, and in need of replacement. Heating coils and cooling coils are corroded and leaking. Fan wheels are cracked, indicating the possibility of structural failure. Leaks in coils, expansion valves and capillary tubes result in losses of HCFC's. Phase 1 builds the chiller building and installs the chiller. Phase 2 installs the chiller equipment and 1 RTU. Phase 2 installs 2 RTU's. Phase 3 installs 2 RTU's. Phase 4 installs 4 RTU's. Phase 5 installs 1RTU and provides water and air balance.

| PRIOR PHASING FY01/02 Ph 1 - Chiller | \$652,599 | FUTURE PHASING FY02/03 Ph 3 - RTU's - C & D FY04/05 Ph 4 - RTU's - E, F, G & H FY05/06 Ph 5 - RTU - I/Balancing | \$676,180 \$676,180 \$519,905 |
|---|-----------|--|-------------------------------------|
| (FUNDED TO DATE) | \$652,599 | (PROJECT BALANCE) | \$1,872,265 |
| CURRENT PHASE FY01/02 Ph 2 - RTU'S - A & B | \$633,686 | PROJECT TOTAL All Phases | \$3,158,550 |









| Ref. No. | Score | | Current Funding Recommendation |
|-------------|-------|---|-----------------------------------|
| 134 | 36 | University of Colorado Health Sciences Center | \$550,000 |

Campus Elevator Upgrades, Ph 1 of 4


This project is proposed as a new elevator upgrade project. The previous Controlled Maintenance project #M520 has been completed up to phase 4 of 8. The new project is expanded to include extra safety components, hoistway ventilation systems, machine room HVAC improvements, and electrical power upgrades in the 4 remaining phases of the previous project. In many cases these improvements are necessary to comply with building codes. In each case, per identified car, the electrictraction type elevator will include all necessary components to provide a complete and fully functional elevator system. Where practical, existing components will be retained and modified. Additionally, safety equipment will be added. Such as smoke detection that includes fire protection upgrades and automatically controlled hoistway ventilation. Phase 1 upgrade elevators & associated mechanical equipment; Research Bridge (RM #9002) pictured, School of Dentistry (RM #9019), and School of Nursing (RM #9004).


PRIOR PHASING

| | | FY02/03 Ph 2 - Various Locations | \$500,000 |
|----------------------------------|-----------|----------------------------------|-------------|
| | | FY03/04 Ph 3 - Various Locations | \$350,000 |
| | | FY04/05 Ph 4 - Various Locations | \$375,000 |
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$1,225,000 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Various Locations | \$550,000 | All Phases | \$1,775,000 |

FUTURE PHASING







Ref.

No. Score

135 36 Department of Corrections

South Pump House and Water Distribution System Improvements, Ph 1 of 1

This project provides for emergency fire flow to the southern half of the East Canon City Prison Complex and addresses water supply issues. The project includes a new emergency generator and transfer switch, re-piping the existing South Pump House (RM #7607) (pictured), upgraded controls, a new pump and the re-building of two existing pumps for back-up, and an 8" water loop on the west side of complex to the North Pump House to provide dual water feeds.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$585,300 | All Phases | \$585,300 |





December 5, 2000

Current Funding Recommendation

\$585,300

_ _ _

Recommendation

136 36 University of Colorado at Boulder

Ref.


No.

Score

Storm/Sanitary Sewer Cross Connection, Ph 1 of 1

In eight general fund buildings on campus there are ten basement level mechanical rooms with floor drains that tie into the campus storm sewer system, which terminates at Boulder Creek. These floor drains receive the discharge from various mechanical equipment that contains chemically treated fluids for normal operations. In addition to normal discharges there is the potential for abnormal dumping of harmful chemicals into these drains. To eliminate the potential for polluting Boulder Creek, the University will need to tie all of these drains into the sanitary system. In Alumni (RM #9152), Ramaley (RM #9202), Fleming Law (RM #9219), Carlson (RM #9211) and two mechanical rooms each in Norlin (RM #9150) and Cristol Chemistry (RM #9138) the floor will be cut, hand excavation to cap storm drain connections, install floor drains with sump pump to sanitary sewer tie-in, and replace floor.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$235,903 | All Phases | \$235,903 |
| | | | |



December 5, 2000

Current Funding

\$235,903

Current Funding Recommendation

\$234,598

No. Score

137 40 Western State College

Repair/Replace Pool and Filter System, Ph 1 of 2

The existing pool filter system at Paul Wright Gymnasium (RM #100) is leaking with the connecting piping. The chemical dispenser system does not work properly. Tile is falling out and needs to be replaced. The pool lights are not working. It is proposed to replace the existing pool filter system and the associated piping to and from the existing pool. It is proposed to replace the existing chemical dispenser system with a new state of the art dispenser system. Repair and replace the existing pool light system with a new and safe lighting fixture. Repair the pool tile and install a new stainless steel gutter system.


| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Chemical System/Tile | \$300,000 |
|--|-----------|---|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$300,000 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Chemical Dispenser System | \$234,598 | All Phases | \$534,598 |











Ref.

Ref.

No. Score

138 42 University of Southern Colorado

Replace Electrical Panels and Transformers, Ph 1 of 3

After over 35 years in service, building transformers and main electrical panels no longer support the increased campus electrical power requirements. The transformers do not meet the new electrical and building codes. Any minor electrical upgrades will require total replacement of major items to meet current electrical codes. The old transformers leak cooling oil that can be damaging to the environment. Existing transformers and main service panels do not support all these new power demands, they have aged and parts are not readily available for regular maintenance. This project will replace undersized and aged transformers, as well as, replace undersized main panels to provide power demand and meet current electrical codes. Phase 1 install transformers for Art-Music (RM #1251), Administration (RM #1254), and Psychology (RM #1255) buildings and the main electrical panel for Psychology, and Administration buildings. Upgrade electrical room to code. Phase 2 replaces electrical meters for all campus buildings except the three science buildings. Phase 3 replaces the main electrical panels for the ASET building and finishes upgrading electrical rooms to code. Administration Building is pictured.

FUTURE PHASING

FY02/03 Ph 2 - Electrical Meters

PRIOR PHASING

| | | FY03/04 Ph 3 - Electrical Panels |
|--|-----------|----------------------------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) |
| CURRENT PHASE | | PROJECT TOTAL |
| FY01/02 Ph 1 - Design/Replace Transformers | \$275,000 | All Phases |
| | | |







Current Funding Recommendation

\$275,000

\$180,000 \$270,000 **\$450,000**

\$725,000

Ref. Score

No.

139 42 Colorado Historical Society

Upgrade Building Deficiencies, Fort Garland, Ph 1 of 1

The project provides surveillance cameras to be installed in the gallery spaces with monitors located in the Visitors Center (RM #4098), replaces the roof over the Museum Store (RM #4098), and provides radiant heating in the Events Center area of the Cavalry Barracks (RM #4099).

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$175,055 | All Phases | \$175,055 |







December 5, 2000

Current Funding Recommendation

\$175,055

Current Funding Recommendation

\$824,296

Ref.

Score No.

140 42 University of Northern Colorado

Replace Deteriorated Systems Gray Hall, Ph 1 of 3

This request will update most buildings systems in Gray Hall (RM #836). The 1995 University Buildings Facility Audit identified the most deteriorated systems in this building. The building systems include flooring, ceiling, interior walls, complete window replacements and mechanical/electrical improvements. The project has been broken into three major phases. The first phase will include the architectural and engineering fee's for the project along with the window replacement. Phase 2 will deal primarily with the mechanical and electrical systems in the building. Phase 3 will complete any of the necessary architectural changes to the building. Gray Hall is pictured.

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Mechanical/Electrical Systems FY03/04 Ph 3 - Architectural Items | \$720,165 \$450,265 |
|-------------------------------------|-----------|--|------------------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$1,170,430 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Design/Window Repair | \$824,296 | All Phases | \$1,994,726 |







Current Funding

December 5, 2000

Recommendation

\$280,000

141 42 University of Colorado Health Sciences Center

Ref.

No.

Score

Office Annex Window Replacement, Ph 1 of 2

This project request addresses Office Annex (RM #9022) windows and doors, which will be replaced in two phases. The first phase includes south-phasing windows and doors near the courtyard. Windows in the building are mostly of original construction, single pane glazed units. Many years of usage and the outdoor environment have caused noticeable deterioration. The window glazing and weatherproofing seals are brittle, loose and ineffective. Much of the window weatherproofing caulk contains asbestos material and lead-based paint and must be removed as a hazardous material. Drafts are particular problem in many rooms. Thermal energy losses via single pane glazing and ineffective weatherproofing are substantial. Phase 1 - replace south-facing windows and doors. Phase 2 - replace north-facing windows and doors.

| URE PHASING 2/03 Ph 2 - North Facing \$275,000 |
|---|
| DJECT BALANCE) \$275,000 |
| JECT TOTAL |
| hases \$555,000 |
| |









| Ref. No. Score | | Current Funding Recommendation |
|-------------------|---|-----------------------------------|
| 142 42 | Department of Corrections | \$219,688 |
| Window | Replacement, Ph 1 of 1 | |
| | ng windows of this honor dorm for female inmates Housing Unit #5 (RM #7651), are single | 5 |

infiltration of air and water. The project includes removal of the exterior security grilles to allow window installation, abatement of the weld connections if required, 98 new window units, and miscellaneous interior and exterior finish repair and replacement.

| PRIOR PHASING | | FUTURE PHASING | |
|-------------------------------|------------------|-----------------------------|------------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE FY01/02 Ph 1 | \$219.688 | PROJECT TOTAL All Phases | \$219.688 |
| | \$219,000 | AIIFIIdses | φ2 19,000 |





December 5, 2000

143 42 University of Colorado at Boulder

Ref.

No.

Score

Repair/Replace Deteriorated Roadways, Ph 2 of 2

These general funded roadways which serve general fund and auxiliary sites on campus are deteriorated, cracked, with numerous pot holes and poor drainage. Poor drainage conditions have a direct effect on the asphalt surface. The existing conditions have caused several bike accidents. Proposed solutions include drainage improvements, road base improvements, and resurfacing. Phase 2 replaces the service drive at Fleming Law School.

| PRIOR PHASING M00040 | ¢205.005 | FUTURE PHASING | |
|----------------------------------|-----------|-------------------|-----------|
| FY00/01 Ph 1 - 33rd Street | \$305,285 | | |
| (FUNDED TO DATE) | \$305,285 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Law Service Drive | \$157,129 | All Phases | \$462,414 |









Current Funding Recommendation

\$157,129

December 5, 2000

Current Funding Recommendation

\$223,382

Ref.

No. Score

144 42 Fort Lewis College


Replace Sewers/Pavement/Sidewalks, Central Campus, Ph 1 of 3

The project will correct three major problems in the center of the campus. The work includes replacement of deficient sanitary and storm sewers, reconstruction of deteriorated sidewalks and installation of adequate lighting. Due to the extensive scope of the project, it will be necessary to phase the project in order to accommodate ongoing College operations. The design work will be accomplished in Phase I. Design work will be completed in time for Phase 2 construction work to begin in the following spring in the southern section of the project area. Phase 3 will include construction work in the northern section, which will be accomplished the following year. All work will be scheduled to minimize the impact of the construction to academic programs.

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Southern Section FY03/04 Ph 3 - Northern Section | \$908,600 \$825,220 |
|----------------------------------|-----------|--|------------------------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$1,733,820 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Design/Inspection | \$223,382 | All Phases | \$1,957,202 |







Current Funding

Recommendation

\$260,024

145 42 Colorado State University

Ref.

No.

Score


Replace Deteriorated Roads & Sidewalks, Ph 3 of 5

Asphalt streets on campus have deteriorated due to age, intensity of use, and need to be repaired to remain viable for automobile and bicycle traffic. Sidewalks and gutters are broken and present safety hazards to pedestrians and bicycle riders. Phase 2 - replaces Mason S. Dr. and N. Meridian. Phase 3 - replaces South Drive.

| PRIOR PHASING M00033 | | FUTURE PHASING | |
|-------------------------------|-----------|--------------------------|-------------|
| FY00/01 Ph 1 - Rampart | \$544,500 | FY03/04 Ph 4 - W. Pitkin | \$288,189 |
| FY01/02 Ph 2 - Mason S. Drive | \$293,191 | FY04/05 Ph 5 - Oldmain | \$312,994 |
| (FUNDED TO DATE) | \$837,691 | (PROJECT BALANCE) | \$601,183 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 3 - South | \$260,024 | All Phases | \$1,698,898 |







December 5, 2000

Current Funding Recommendation

\$184,247

146 45 Otero Junior College

McDivitt Hall Roof Replacement, Ph 1 of 1

Portions of the McDivitt Hall (RM #131) roofing system range in age from 11 years to 20 years old. The roof system consists of a ballasted EPDM membrane applied over a failed 3 ply built-up roof. Although the roof system has been extensively patched in recent years, the water trapped between the layers of the two roofing systems has caused damage to some of the interior finishes and has saturated the roofing insulation rendering it useless. In addition, the numerous supporting legs of the antiquated solar panels that penetrate the roof's membrane have been a primary source of moisture infiltration. Ponding water on the roof has even made the situation worse. The best solution to the roof problem would be to remove the antiquated solar panels and to replace the roof with a 4-ply asphalt roof applied over a tapered insulation system, thus allowing for a positive drainage of water off the roof. The slop of the tapered insulation would be 1/4 inch/ft. McDivitt Hall is pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$184,247 | All Phases | \$184,247 |









Ref. No. Score

Current Funding Recommendation

\$329,394

December 5, 2000

Ref.

No. Score

147 45 Western State College


Repair/Replace Parking Lots/Streets - Zone 1, Ph 3 of 5

The existing parking lots, curbs and streets have deteriorated over the past 35 years. The structural integrity of the sub base has failed. There are very large potholes and large cracks throughout the parking lots and streets. This project includes Phase I through V - Zone I of Campus. These phases will include the removal of the existing asphalt and sub-base, curb and gutter. New sub-base will be install, with the installation of the binder and wearing courses of Asphaltic Concrete Paving. Also the repair and replacement of curb and gutter will also be accomplished in Zone 2 of the Campus.

| | FUTURE PHASING | |
|-----------|-------------------------------|---|
| \$360,500 | FY03/04 Ph 4 - Zone 1 | \$337,840 |
| \$365,279 | FY04/05 Ph 5 - Zone 1 | \$269,692 |
| \$725,779 | (PROJECT BALANCE) | \$607,532 |
| | PROJECT TOTAL | |
| \$329,394 | All Phases | \$1,662,705 |
| | \$365,279 \$725,779 | \$360,500 FY03/04 Ph 4 - Zone 1 \$365,279 FY04/05 Ph 5 - Zone 1 \$725,779 (PROJECT BALANCE) PROJECT TOTAL |







December 5, 2000

Current Funding Recommendation

\$355,069

148 45 Department of Military Affairs

Ref.

No.

Score

Paving Projects Various Locations, Ph 1 of 5

This project includes building #205 - Colorado Springs Armory (RM #925): The access drive from the street to the motor pool Is a steep gravel road that is a safety and maintenance problem. The road needs to be paved. The Parking lot paving is cracked & deteriorated and is beyond repair. The paving must be replaced.

| PRIOR PHASING | CCFE | FF | FUTURE PHASING FY02/03 Ph 2 - Englewood FY03/04 Ph 3 - Cortez, Buckley FY04/05 Ph 4 - Various Locations FY05/06 Ph 5 - Various Locations | CCFE \$265,728 \$236,356 \$280,000 \$278,000 | FF \$0 \$82,750 \$0 \$0 |
|--|--------------------------|------------------|--|--|-------------------------------------|
| (FUNDED TO DATE) | \$0 | \$0 | (PROJECT BALANCE) | \$1,060,084 | \$82,750 |
| CURRENT PHASE FY01/02 Ph 1 - Colorado Springs | CCFE \$355,069 | FF \$0 | PROJECT TOTAL All Phases | CCFE \$1,415,153 | FF \$82,750 |









Ref.

Score No.

149 48 Morgan Community College

Replace HVAC units and Controls, Cottonwood Hall, Ph 1 of 2

There are 7 HVAC units of varying age on the Cottonwood Building (RM #739) with most units over 20 years old. With the extreme temperature changes it is necessary that each unit work properly to provide a comfortable teaching and learning space. The units are often out of service or in need of repair with the repairs occurring more frequently as they deteriorate with age. Phase 1 will fund the design of 7 new units and the purchase and installation of 4 of the units. Also included would be the installation of a campus wide Direct Digital control system. Phase 2 will fund the purchase and installation of the remaining 3 units. Cottonwood Hall (RM #739) is pictured.

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - 3 Units | \$302,780 |
|--|-----------|--|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$302,780 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Design/4 Units/Controls | \$563,500 | All Phases | \$866,280 |







Current Funding Recommendation

\$563,500

Current Funding Recommendation

\$405,000

150 48 Department of Human Services

Ref.

No.


Score


Repair/Replace Elevator, Ph 1 of 1

This project will upgrade the elevator that serves the office functions in Building B (RM #1010) at Colorado Mental Health Institute at Fort Logan. The scope of work includes reconditioning the hoist machine, new controller, ACV3F motor drive, governor, hoist ropes and governor ropes, traveling cables and wiring, car door operator, car and hoist way doors, roller guides, demolition, HVAC upgrades to mechanical room, emergency power and electrical upgrades.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|---------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 \$ | 405,000 | All Phases | \$405,000 |
| Ψ | 403,000 | | φ+05,000 |







Current Funding

Recommendation

\$676,013

151 48 Colorado State University

Ref.

No.

Score

Replace Deteriorated Items, Wagar, Ph 3 of 3

Major building systems are almost 60 years old and failing in the Wagar Building (RM #3264). Electrical and heating systems need to be replaced. Exterior walls and glass curtain walls need repairs. Most floor coverings are loose or chipped, contain asbestos, and need to be replaced. Interior walls, doors, and ceilings need moderate repairs. Heating system is obsolete, controls are corroded and system needs to be replaced. Electrical system has old sub-standard wiring, insulation, and panels. Phase 2 - replaces heating in the north wing and electrical system in the east wing. Phase 3 - replaces electrical system in the north wing and windows, flooring and ceiling.

| PRIOR PHASING M00032 | | FUTURE PHASING | |
|---|-------------|-------------------|-------------|
| FY00/01 Ph 1 - Design/E. Heating | \$660,413 | | |
| FY01/02 Ph 2 - N. Heating/E. Electrical | \$684,877 | | |
| (FUNDED TO DATE) | \$1,345,290 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 3 - N. Electrical/Windows | \$676,013 | All Phases | \$2,021,303 |





| Ref. No. | Score | | Current Funding Recommendation |
|-------------|-------|--------------------------------|-----------------------------------|
| 152 | 48 | Department of Military Affairs | \$279,734 |

Exterior Closure Replacement, Ph 2 of 4

The exterior curtain wall system has failed on building #248 and #268 at the Englewood Administration Buildings (RM #604) due to improper installation and age. The systems are obsolete and must be replaced to address the problem. Water infiltration is damaging the buildings. The entry doors are worn and must be replaced to provide security and efficiency. The project will be phased to complete the exterior glazing of Building #268 in the second phase. Building #268 is pictured.

| PRIOR PHASING M00099 FY00/01 Ph 1 - Bldg 268/Roof | CCFE \$267,688 | FF \$0 | FUTURE PHASING FY02/03 Ph 3 - Bldg #248/Ext. Glass A FY03/04 Ph 4 - Bldg #248/Ext. Glass B | CCFE \$414,971 \$414,971 | FF \$0 \$0 |
|---|--------------------------|------------------|--|--------------------------------|------------------|
| (FUNDED TO DATE) | \$267,688 | \$0 | (PROJECT BALANCE) | \$829,942 | \$0 |
| CURRENT PHASE FY01/02 Ph 2 - Bidg #268/Ext. Glass | CCFE \$279,734 | FF \$0 | PROJECT TOTAL All Phases | CCFE \$1,377,364 | FF \$0 |







Ref.

No. Score


153 48 Adams State College

Replace Sewer Line Richardson Hall & Business and Economics, Ph 1 of 1

Existing sewer is clay tile. It is deteriorating and has been breached with root systems from nearby trees causing frequent disruption in services, unsightly sewage and unsanitary conditions exist with frequent backups. Richardson (RM #157) is pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$132,319 | All Phases | \$132,319 |





December 5, 2000

Current Funding Recommendation

\$132,319

Current Funding Recommendation

Score No.

Ref.

University of Colorado at Boulder 154 48

Replace Chemistry and Ekeley Generators, Ph 1 of 5

Currently no fume hoods or HVAC system components are on emergency power in the Cristol Chemistry building (RM #9138) or in the Eckeley Hall (RM #9140), creating hazardous situations every time power is lost. The two existing small generators are drastically undersized, old, unreliable, and hard to service and refuel. Phase 1 - Chemistry Site Preparation - consists of constructing the facility to house the generator. Installation of the transfer switches and modifying the electrical system to accept the Phase 2 generator. Ekeley (RM #9140) is pictured

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Chemistry Generator FY03/04 Ph 3 - Ekeley Site Preparation FY04/05 Ph 4 - Ekeley Generator FY05/06 Ph 5 - Site Finishes | \$602,290 \$756,535 \$756,535 \$367,250 |
|--|-----------|---|--|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$2,482,610 |
| CURRENT PHASE FY01/02 Ph 1 - Chemistry Site Prep | \$585,600 | PROJECT TOTAL All Phases | \$3,068,210 |





December 5, 2000

\$585,600

Ref.


No. Score

155 48 University of Southern Colorado

Campus Structural Repairs/Safety Study, Ph 1 of 1

Building foundations have shifted, and damaged finish work, utilities and the structure. In the past shifting has caused structural pre-cast members to slip off supports. Structural movements open exterior panel joints to weather and other intrusions. Building utilities suffer leaks & other damages. Cracks in structure, finishes, and the shifting of members cause public concerns. This request will evaluate/identify buildings with structural/foundation problems, and design and implement emergency repairs/shoring as needed. This phase will develop a standard inspection process for routine observation of buildings with structural distress and identify buildings, which may experience distress due to the campus adverse soil conditions. This phase will identify with cost estimates future structural repairs on the USC campus. Technology Building (RM #1256) pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$180,000 | All Phases | \$180,000 |
| | | | |



December 5, 2000

Current Funding Recommendation

\$180,000

| Current F | undina |
|-----------|--------|
| Recomme | |

\$365,240

Colorado School of Mines Campus Pool HVAC Replacement, Ph 2 of 2

Ref.

No. 156 54

Score

This project completes replacement of the air handlers and air distribution systems for the campus pool facility in Volk Gymnasium (RM #1015). The existing ventilation system uses the corridors to return air to the units and uses stairwells as air plenums. This arrangement is a fire hazard and poses a serious risk to the life safety of students and faculty who use this facility seven days a week.

| PRIOR PHASING | A | FUTURE PHASING | |
|---------------------------------|-----------|-------------------|-------------|
| Y01/02 Ph 1 - Pool | \$887,900 | | |
| (FUNDED TO DATE) | \$887,900 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Auxiliary Spaces | \$365,240 | All Phases | \$1,253,140 |









| Ref. No. | Score | | Current Funding Recommendation |
|-------------|-------|-----------------------------|-----------------------------------|
| 157 | 54 | Northeastern Junior College | \$35,685 |

Replace HVAC Units, Ph 1 of 1

All HVAC units are over 20 years old. All units were identified by the NJC Facility Audit as needing replacement. One unit on the Cosmetology Building was damaged beyond repair by fire in 1999. This unit was replaced and is not included in this request. The other units need to be replaced before they fail. This request is to replace 7 HVAC units. There is one at the Welding Shop (RM #8311), three at Cosmetology (RM #4260) and three at Child Development (RM #4259). Cosmetology is pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|--------|-------------------|----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 \$ | 35,685 | All Phases | \$35,685 |







| Ref. No. Score | | Current Funding Recommendation |
|-------------------|--|-----------------------------------|
| 158 54 Red | d Rocks Community College | \$211,952 |
| Replace Multi | tizone HVAC Equipment, Ph 1 of 1 | |
| Parts are impos | unit that serves the classrooms in the Construction Technology Building (RM #765) is v ssible to acquire; the unit can't keep the classroom environment adequately heated or roughout the school year. | |
| | | |

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$211,952 | All Phases | \$211,952 |





December 5, 2000

Ref.

No. Score

159 54 Department of Human Services


Heating Plant and Infrastructure Upgrade, Ph 1 of 1

This project at Lookout Mountain Youth Services Center includes the replacement of site paving, site drainage, fire, water, storm and sanitary sewer systems, heating plant upgrades, and steam distribution systems. The systems have deteriorated to the point where replacement is required. Some of the infrastructure systems (pictured) have not been replaced since they were originally installed over 50 years ago. The project will evaluate a formal infrastructure replacement program and provide design and construction documents for the heating plant and utility distribution systems replacement.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$561,000 | All Phases | \$561,000 |







December 5, 2000

Current Funding Recommendation

\$561,000

159 of 168

Ref.

No. Score

160 54 Pueblo Community College

Repair Interior and Exterior Deteriorating Items, Academic Building, Ph 1 of 1

These items were identified in the Facility Audit completed June 2000. The project will include replacement of leaking skylights over the Learning Resource Center and the Science Department Greenhouse, replacement of entry doors in the Amphitheater, replacement of exterior lighting fixtures to more energy efficient and light output, replace the inline circulating pumps on the HVAC system, replace broken bricks and walks around the exterior. The existing valves in all the restrooms are worn out due to over stress. PCC plans to replace all the valves with electronically operated valves that will control the on/off and time of flow. Academic Building (RM #6100) pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$214,965 | All Phases | \$214,965 |

<image>







Current Funding Recommendation

\$214,965

December 5, 2000

Current Funding Recommendation

\$250,000

Score No.

Ref.

161 63 Trinidad State Junior College

Interior Repair/Replacement Davis/Berg/Mullen Buildings, Ph 1 of 2

The age of these buildings and the lack of renovation and upgrading have resulted in the need for major repair and replacement. This request is to replace damaged ceiling systems, deficient wall finishing systems, floors and stairways floors that are expensive to maintain and inadequate for the present use of the building. Piping including heating steam lines are exposed in several classroom areas and corridors where they have the potential to burn persons in these areas aside from being very unsightly. Phase 1 of this project will cover Mullen Building (RM #202) and Phase 2 will cover Berg (RM #205) and Davis (RM #203).

| PRIOR PHASING | | FUTURE PHASING FY02/03 Ph 2 - Berg, Davis | \$250,000 |
|-----------------------|-----------|--|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$250,000 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 - Mullen | \$250,000 | All Phases | \$500,000 |





Current Funding Recommendation

\$92,167

162 63 Pikes Peak Community College

Plumbing Fixture Replace Aspen and Breckenridge Buildings, Ph 1 of 1

The plumbing fixtures in both buildings are worn out and damaged from 22 years of hard usage. Flush valves and faucet sets are increasingly requiring individual replacement due to housing failures and poor appearance. Several sinks, urinals and toilets are cracked chipped etc. Repair parts for these fixtures are becoming difficult to fine, hence uniformity of appearance and parts standardization is compromised. This project will consist of removal and replacement of approximately 109 flush valves and 156 faucet assemblies, 6 restroom sinks, 4 urinals, 4 toilets and 71 toilet seats in the Aspen (RM #57) and Breckenridge (RM #58) buildings. Repair parts for 40 drinking fountains are included. Pikes Peak Centennial Campus is pictured.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|----------|-------------------|----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$92,167 | All Phases | \$92,167 |





December 5, 2000

Ref.

No.

Score

Current Funding

December 5, 2000

Recommendation

\$50,950

Ref.


No. Score

163 63 Morgan Community College

Campus Wide Utility Infrastructure Analysis, Ph 1 of 1

Due to numerous capital construction and maintenance project repairs and updates in recent years, the campus electrical, gas, water and sewer infrastructures are at their maximum capacity. Currently the electrical system is at it's maximum based on an electrical audit conducted in the Spring of 2000. This audit also recommends electrical upgrades campus wide. Along with the electrical capabilities, the gas, water and sewer are also operating at a maximum level. With the new fire alarm project and other capital construction projects currently funded the current capabilities will be insufficient almost immediately. This study would review future Capital Construction and Controlled Maintenance requests to determine repair/replacement recommendation for the campus infrastructure.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|--------|-------------------|----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 \$5 | 50,950 | All Phases | \$50,950 |



| Ref. No. | Score | | Current Funding Recommendation |
|-------------|-------|--|-----------------------------------|
| 164 | 72 | University of Colorado at Colorado Springs | \$501,744 |
| Don | air C | ampus Infrastructura Bh 2 of 2 | |

Repair Campus Infrastructure, Ph 2 of 3


The campus is experiencing erosion and drainage problems in many areas. Phase 2 will stabilize a slope failure behind Dwire Hall and upgrade the footpath and drainage behind the Housing Village. It will also address the main access road to Lot 3 and East Entrance as well as Lot 1 access.

| PRIOR PHASING | | FUTURE PHASING | |
|---|-----------|--------------------------------|-------------|
| FY01/02 Ph 1 - Fire Access, Subsurface Drainage | \$297,812 | FY02/03 Ph 3 - Retaining Walls | \$292,583 |
| (FUNDED TO DATE) | \$297,812 | (PROJECT BALANCE) | \$292,583 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 2 - Slope Failures | \$501,744 | All Phases | \$1,092,139 |









Ref.

No. Score

165 72 Capitol Complex Facilities

Secondary Electrical Power Service Upgrade, Ph 1 of 1

Unreliable power supply has caused disruption in the General Government Computer Center (GGCC) and CBI operations in the 690 Kipling Building (RM #149). This facility maintains statewide information and data for the Department of Public Safety, law enforcement programs, and Colorado Bureau of Investigation. Public Service (PSC) provides power utility service for the GGCC/CBI building. On several occasions, the existing emergency generator has failed to supply emergency power to the building. In such cases it takes four to six hours to restore power and computer systems operation. The facility power outages are costly (according to GGCC management, every hour of power shutdown costs \$1,000,000 to the State). The second independent service (second power feed from deferent grids) should be installed and building loads should be connected to the existing and new electrical services through an automatic transfer switch.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$380,870 | All Phases | \$380,870 |







December 5, 2000

Current Funding Recommendation

\$380,870

Current Funding Recommendation

\$195,200

166 84 Trinidad State Junior College

East Boundary Retaining Wall Repair/Stabilize, Ph 1 of 1

The East boundary retaining wall is a limestone structure that is approximately 65 years old. One section is severely cracked and needs to be repaired or stabilized. The entire wall system, which is approximately 600 feet in length, needs to be capped with concrete to prevent further sever weathering damage. Approximately 300 feet of guardrail at the West end of the wall is homemade from old railroad rails and not suitable for preventing vehicles from going over the wall. This request will stabilize the wall, remove damaging trees, and cap the wall to protect against water intrusion.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$195,200 | All Phases | \$195,200 |





December 5, 2000

Ref.

No.

Score

| Ref. No. | Score | Current Funding Recommendation |
|-------------|--|-----------------------------------|
| 167 | 84 University of Colorado at Colorado Springs | \$154,500 |
| Rep | lace Exterior Lighting, Ph 1 of 1 | |
| | rior and street lighting is inadequate, old and obsolete and a mixture of many types of fixtures and bu dardize fixtures and bulbs and will provide sufficient lighting to improve safety for pedestrian paths on | |

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$154,500 | All Phases | \$154,500 |





December 5, 2000

December 5, 2000

Current Funding Recommendation

\$326,551

No. Score


Ref.

 168
 84
 Colorado Historical Society

Silver Plume Depot Site Upgrade, Ph 1 of 1

The main entrance to the Silver Plume Depot of the Georgetown Historic Mining and Railroad Park has conflicting vehicular, pedestrian and train traffic. There is no clear delineation for safe pedestrian access from the remote parking area or for pedestrians arriving by tour bus. This project will provide a safe entrance to the depot and yard area.

| PRIOR PHASING | | FUTURE PHASING | |
|------------------|-----------|-------------------|-----------|
| (FUNDED TO DATE) | \$0 | (PROJECT BALANCE) | \$0 |
| CURRENT PHASE | | PROJECT TOTAL | |
| FY01/02 Ph 1 | \$326,551 | All Phases | \$326,551 |





V. AGENCY GENERAL FUNDED GROSS SQUARE FOOTAGE

SECTION V: AGENCY TOTAL GENERAL FUNDED GROSS SQUARE FOOTAGE FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

The reported Agency General Funded Gross Square Footage (GSF) is listed below and in detail on Chart A on the preceding pages. Included in the list is a reference to the number of priority projects that an individual agency may expect based on size. Since square footage is only the initial factor in determining the prioritization and recommendations for funding, it is neither a guarantee nor a limitation of the number of Controlled Maintenance projects an agency will receive. The actual number of recommended CM projects each agency will receive is determined based on a number of factors including: progress of on-going controlled maintenance projects, resources available to manage additional controlled maintenance projects, site verification of needs and long range comprehensive planning supported by a facilities condition survey process. Please refer to Section III SBP Prioritized, Funding Recommendations. Chart B, is the Agency Historical Reported General Funded Gross Square Footage from FY1990/1991 to present. It indicates by agency, by fiscal year change in general funded gross square footage. **Please note that auxiliary cash funded facilities are not included in this gross square footage total but are included on the Agency Current Replacement Value (CRV) Chart C on the preceding pages.**

The reported overall general statewide funded gross square footage for the current and last eleven fiscal years including FY 2001/2002 is as follows:

| FY2001/2002 | 35,991,174 GSF |
|-------------|----------------|
| FY2000/2001 | 35,103,341 GSF |
| FY1999/2000 | 33,875,149 GSF |
| FY1998/1999 | 32,905,445 GSF |
| FY1997/1998 | 31,690,727 GSF |
| FY1996/1997 | 31,172,895 GSF |
| FY1995/1996 | 29,060,278 GSF |
| FY1994/1995 | 28,349,213 GSF |
| FY1993/1994 | 27,760,192 GSF |
| FY1992/1993 | 28,513,710 GSF |
| FY1991/1992 | 28,513,710 GSF |
| FY1990/1991 | 26,980,537 GSF |

December 5, 2000

CHART A, AGENCY GENERAL FUNDED GROSS SQUARE FOOTAGE FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| Abbreviation | Department / Agency | Gross Square Footage | # of Priority/Projects = 1/500,000 GSF + 1/(Remainder > 250,000) | Potential Number Priority/ Projects |
|--------------|--|----------------------------|--|--|
| GSS-CCF | Capitol Complex Facilities | 1,149,699 | 2 + 149,699 (R) = 1 | 2 2 |
| GSS-CGTS | Colorado Government Technology Services | 16,406 | 0 + 16,406 (R) = | 1 1 |
| GSS-CGW | Camp George West | 0 | | 1 |
| GSS-SCB | State Capitol Building | 307,467 | 0 + 307,467 (R) = | 1 1 |
| DOAg | Department of Agriculture | 745,770 | | |
| DOAg | Department of Agriculture - Zuni & Insectary | 40,814 | 0 + 40,814 (R) = | 1 1 |
| DOAg-CSF | State Fair - Pueblo | 704,956 | 1 + 204,956 (R) = | 1 1 |
| DOC | Department of Corrections | 5,881,987 | 11 + 381,987 (R) = 1 | 2 12 |
| DOE | Department of Education | 294,775 | | |
| CSDB | Colorado School for the Deaf and Blind | 294,775 | 0 + 294,775 (R) = | 1 1 |
| CDPHE | Department of Public Health and Environment | 90,107 | 0 + 90,107 (R) = | 1 1 |
| DOHE | Department of Higher Education | 23,258,137 | | |
| DOHE-CHS | Colorado Historical Society | 119,939 | 0 + 119,939 (R) = | 1 1 |
| DOHE-REG | University of Colorado Board of Regents | 7,284,069 | | |
| DOHE-UCHSC | University of Colorado Health Sciences Center | 2,377,675 | 4 + 377,675 (R) = | 5 5 |
| DOHE-UCB | University of Colorado at Boulder | 4,302,511 | 8 + 302,511 (R) = | 9 9 |
| DOHE-UCCS | University of Colorado at Colorado Springs | 603,883 | 1 + 103,883 (R) = | 1 1 |
| DOHE-AG | State Board of Agriculture | 6,351,728 | | |
| DOHE-CSU | Colorado State University | 5,261,957 | 10 + 261,957 (R) = 1 | 1 11 |
| DOHE-USC | University of Southern Colorado | 649,123 | 1 + 149,123 (R) = | 1 1 |
| DOHE-FLC | Fort Lewis College | 440,648 | 0 + 440,648 (R) = | 1 1 |
| DOHE-TUNC | Trustees of the University of Northern Colorado | 1,354,439 | | |
| DOHE-UNC | University of Northern Colorado | 1,354,439 | 2 + 354,439 (R) = | 3 3 |
| DOHE-TSC | Trustees of State Colleges | 1,542,654 | | |
| DOHE-ASC | Adams State College | 539,644 | 1 + 39,644 (R) = | 1 1 |
| DOHE-MSC | Mesa State College | 505,034 | 1 + 5,034 (R) = | 1 1 |
| DOHE-WSC | Western State College | 497,976 | 0 + 497,976 (R) = | 1 1 |
| DOHE-TCSM | Board of Trustees of the Colorado School of Mines | 1,129,240 | | |
| DOHE-CSM | Colorado School of Mines | 1,129,240 | 2 + 129,240 (R) = | 2 2 |
| DOHE-BAHEC | Board of Directors of the Auraria Higher Education Center | 1,573,929 | | |
| DOHE-AHEC | Auraria Higher Education Center | 1,573,929 | 3 + 73,929 (R) = | 3 3 |
| DOHE-CCC | Community Colleges of Colorado | 3,965,098 | | |
| DOHE-ACC | Arapahoe Community College | 405,067 | 0 + 405,067 (R) = | 1 1 |
| DOHE-CNCC | Colorado Northwestern Community College | 179,708 | 0 + 179,708 (R) = | 1 1 |
| DOHE-FRCC | Front Range Community College | 539,155 | 1 + 39,155 (R) = | 1 1 |
| DOHE-LCC | Lamar Community College | 247,498 | 0 + 247,498 (R) = | 1 1 |
| DOHE-MCC | Morgan Community College | 73,901 | 0 + 73,901 (R) = | 1 1 |

| Abbreviation | Department / Agency | Gross Square Footage | # of Priority/Projects = 1/500,000 GSF + 1/(Remainder > 250,000) | Potential Number Priority/ Projects |
|--------------|---|----------------------------|--|--|
| DOHE-NJC | Northeastern Junior College | 336,813 | 0 + 336,813 (R) = 7 | 1 1 |
| DOHE-OJC | Otero Junior College | 202,041 | 0 + 202,041 (R) = 2 | 1 1 |
| DOHE-PPCC | Pikes Peak Community College | 416,979 | 0 + 416,979 (R) = 7 | 1 1 |
| DOHE-PCC | Pueblo Community College | 330,402 | 0 + 330,402 (R) = 2 | 1 1 |
| DOHE-RRCC | Red Rocks Community College | 373,974 | 0 + 373,974 (R) = 7 | 1 1 |
| DOHE-TSJC | Trinidad State Junior College | 285,093 | 0 + 285,093 (R) = 2 | 1 1 |
| DOHE-HEAT | Higher Education and Advanced Technology Center at Lowry | 548,567 | 1 + 48,567 (R) = 7 | 1 1 |
| DOHE-CCA | Community College of Aurora | 25,900 | 0 + 25,900 (R) = 7 | 1 1 |
| DHS | Department of Human Services | 2,768,384 | 5 + 268,384 (R) = 6 | 6 6 |
| JUD | Judicial Heritage | 222,632 | 0 + 222,632 (R) = 2 | 1 1 |
| DOMA | Department of Military Affairs | 840,898 | 1 + 340,898 (R) = 2 | 2 2 |
| CDPS | Department of Public Safety | 216,119 | 0 + 216,119 (R) = 2 | 1 1 |
| DOR | Department of Revenue | 130,234 | 0 + 130,234 (R) = 2 | 1 1 |
| DOLA | Department of Local Affairs | 5,600 | | |
| CTSRC | Cumbres & Toltec Scenic Railroad Commission | 0 | | 1 |

Total General Funded Gross Square Footage of All35,9Agencies and Institutions Listed and Eligible for the
Controlled Maintenance Program.35,9

35,991,174

CHART B, AGENCY HISTORICAL REPORTED GENERAL FUNDED GROSS SQUARE FOOTAGE FY2001/2001 CONTROLLED MAINTENANCE PROGRAM

| Agency | FY90/91 | FY91/92 | FY92/93 | FY93/94 | FY94/95 | FY95/96 | FY96/97 |
|--|------------|------------|------------|------------|------------|------------|------------|
| GSS/Department of Personel | 1,460,300 | 1,467,498 | 1,467,498 | 1,467,498 | 1,467,498 | 1,467,498 | 2,802,437 |
| Department of Agriculture | 789,750 | 789,750 | 789,750 | 36,232 | 36,232 | 36,232 | 36,232 |
| Department of Corrections | 2,381,150 | 2,835,694 | 2,835,694 | 2,835,694 | 3,424,715 | 3,424,715 | 4,014,457 |
| CO School for Deaf and Blind | 194,050 | 294,000 | 294,000 | 294,000 | 294,000 | 294,000 | 294,000 |
| Public Health and Environment | 92,233 | 92,233 | 92,233 | 92,233 | 92,233 | 92,233 | 92,233 |
| Colorado Historical Society | 97,241 | 130,272 | 130,272 | 130,272 | 130,272 | 130,272 | 130,272 |
| CU-Health Sciences Center | 1,626,942 | 1,626,942 | 1,626,942 | 1,626,942 | 1,626,942 | 1,626,942 | 1,626,942 |
| CU-Boulder | 3,776,437 | 3,791,770 | 3,791,770 | 3,791,770 | 3,791,770 | 3,791,770 | 3,791,770 |
| CU-Colorado Springs | 254,563 | 254,563 | 254,563 | 254,563 | 254,563 | 254,563 | 385,425 |
| Colorado State University | 4,312,884 | 4,928,804 | 4,928,804 | 4,928,804 | 4,928,804 | 4,928,804 | 4,928,804 |
| Univresity of Southern Colorado | 592,955 | 592,955 | 592,955 | 592,955 | 592,955 | 592,955 | 598,898 |
| Fort Lewis College | 352,580 | 359,003 | 359,003 | 359,003 | 359,003 | 359,003 | 359,003 |
| University of Northern Colorado | 1,330,511 | 1,330,511 | 1,330,511 | 1,330,511 | 1,330,511 | 1,330,511 | 1,340,308 |
| Adams State College | 483,937 | 483,937 | 483,937 | 483,937 | 483,937 | 483,937 | 483,937 |
| Mesa College | 420,152 | 426,019 | 426,019 | 426,019 | 426,019 | 426,019 | 426,019 |
| Western State College | 421,063 | 432,976 | 432,976 | 432,976 | 432,976 | 432,976 | 432,976 |
| Colorado School of Mines | 832,955 | 855,160 | 855,160 | 855,160 | 855,160 | 855,160 | 1,080,507 |
| Auraria Higher Education Center | 1,228,666 | 1,414,841 | 1,414,841 | 1,414,841 | 1,414,841 | 1,414,841 | 1,414,841 |
| Arapahoe Community College | 326,351 | 326,351 | 326,351 | 326,351 | 326,351 | 326,351 | 326,351 |
| Colorado Northwestern Community College | - | - | - | - | - | - | - |
| Front Range Community College | 295,498 | 295,498 | 295,498 | 295,498 | 295,498 | 295,498 | 423,872 |
| Lamar Community College | 119,353 | 119,353 | 119,353 | 119,353 | 119,353 | 119,353 | 119,353 |
| Morgan Community College | 50,890 | 50,890 | 50,890 | 50,890 | 50,890 | 50,890 | 50,890 |
| Northeastern Junior College | - | - | - | - | - | - | - |
| Otero Junior College | 182,074 | 182,074 | 182,074 | 182,074 | 182,074 | 182,074 | 182,074 |
| Pikes Peak Community College | 285,135 | 285,135 | 285,135 | 285,135 | 285,135 | 285,135 | 285,135 |
| Pueblo Community College | 236,256 | 236,256 | 236,256 | 236,256 | 236,256 | 236,256 | 236,256 |
| Red Rocks Community College | 285,053 | 285,053 | 285,053 | 285,053 | 285,053 | 285,053 | 285,053 |
| Trinidad State Junior College | 217,577 | 217,577 | 217,577 | 217,577 | 217,577 | 217,577 | 217,577 |
| Higher Education and Advance Technology | - | - | - | - | - | - | - |
| Community College of Aurora | - | - | - | - | - | - | - |
| Department of Human Services | 3,502,264 | 3,469,242 | 3,469,242 | 3,469,242 | 3,469,242 | 3,469,242 | 3,270,967 |
| Jucicial Department | 222,562 | 222,562 | 222,562 | 222,562 | 222,562 | 222,562 | 222,562 |
| Department of Military Affairs | 446,367 | 554,003 | 554,003 | 554,003 | 554,003 | 1,265,068 | 1,265,068 |
| Department of Public Safety | 48,676 | 48,676 | 48,676 | 48,676 | 48,676 | 48,676 | 48,676 |
| Department of Revenue | 114,112 | 114,112 | 114,112 | 114,112 | 114,112 | 114,112 | - |
| Departmento Labor and Employeement | | - | - | - | - | - | - |
| Department of Local Affairs | - | - | - | - | - | - | - |
| Cumbres & Toltec Scenic Railroad Commision | | - | - | - | - | - | - |
| TOTAL | 26,980,537 | 28,513,710 | 28,513,710 | 27,760,192 | 28,349,213 | 29,060,278 | 31,172,895 |

CHART B, AGENCY HISTORICAL REPORTED GENERAL FUNDED GROSS SQUARE FOOTAGE FY2001/2001 CONTROLLED MAINTENANCE PROGRAM

| Agency | FY97/98 | FY98/99 | FY99/00 | FY00/01 | FY01/02 |
|--|------------|------------|------------|------------|------------|
| GSS/Department of Personel | 2,802,437 | 1,576,124 | 1,576,124 | 1,569,672 | 1,473,572 |
| Department of Agriculture | 36,232 | 788,215 | 757,738 | 745,770 | 745,770 |
| Department of Corrections | 4,014,457 | 4,595,894 | 4,838,904 | 5,546,544 | 5,881,987 |
| CO School for Deaf and Blind | 294,000 | 294,775 | 294,775 | 294,775 | 294,775 |
| Public Health and Environment | 92,233 | 67,615 | 90,360 | 90,107 | 90,107 |
| Colorado Historical Society | 130,272 | 140,514 | 140,514 | 124,467 | 119,939 |
| CU-Health Sciences Center | 1,753,202 | 1,635,938 | 1,704,447 | 1,793,872 | 2,377,675 |
| CU-Boulder | 3,791,770 | 4,193,299 | 4,193,299 | 4,361,593 | 4,302,511 |
| CU-Colorado Springs | 385,425 | 464,131 | 495,124 | 530,868 | 603,883 |
| Colorado State University | 4,928,804 | 5,010,480 | 5,355,877 | 5,374,651 | 5,261,957 |
| Univresity of Southern Colorado | 598,898 | 593,378 | 642,188 | 627,568 | 649,123 |
| Fort Lewis College | 359,003 | 423,177 | 423,177 | 436,498 | 440,648 |
| University of Northern Colorado | 1,340,308 | 1,361,636 | 1,361,636 | 1,358,459 | 1,354,439 |
| Adams State College | 483,937 | 570,553 | 478,478 | 548,369 | 539,644 |
| Mesa College | 426,019 | 439,962 | 439,962 | 501,905 | 505,034 |
| Western State College | 432,976 | 434,867 | 434,867 | 435,701 | 497,976 |
| Colorado School of Mines | 1,080,507 | 1,060,333 | 1,060,333 | 1,060,333 | 1,129,240 |
| Auraria Higher Education Center | 1,414,841 | 1,420,421 | 1,420,403 | 1,413,696 | 1,573,929 |
| Arapahoe Community College | 326,351 | 304,962 | 311,851 | 351,906 | 405,067 |
| Colorado Northwestern Community College | - | - | 179,708 | 179,708 | 179,708 |
| Front Range Community College | 423,872 | 498,528 | 609,685 | 609,715 | 539,155 |
| Lamar Community College | 119,353 | 179,532 | 181,332 | 254,611 | 247,498 |
| Morgan Community College | 50,890 | 69,787 | 69,787 | 68,543 | 73,901 |
| Northeastern Junior College | 277,460 | 312,264 | 345,400 | 361,997 | 336,813 |
| Otero Junior College | 182,074 | 188,457 | 199,835 | 202,039 | 202,041 |
| Pikes Peak Community College | 285,135 | 289,990 | 408,003 | 416,000 | 416,979 |
| Pueblo Community College | 236,256 | 327,132 | 327,132 | 327,132 | 330,402 |
| Red Rocks Community College | 285,053 | 332,053 | 336,562 | 336,653 | 373,974 |
| Trinidad State Junior College | 217,577 | 280,163 | 280,163 | 281,087 | 285,093 |
| Higher Education and Advance Technology | - | 739,241 | 548,567 | 548,567 | 548,567 |
| Community College of Aurora | - | - | - | - | 25,900 |
| Department of Human Services | 3,270,967 | 2,819,826 | 2,819,826 | 2,852,111 | 2,768,384 |
| Jucicial Department | 222,562 | 222,632 | 222,632 | 222,632 | 222,632 |
| Department of Military Affairs | 1,265,068 | 951,047 | 951,047 | 798,525 | 840,898 |
| Department of Public Safety | 48,676 | 50,821 | 107,715 | 210,259 | 216,119 |
| Department of Revenue | 114,112 | 130,924 | 130,924 | 130,234 | 130,234 |
| Departmento Labor and Employeement | - | 131,174 | 131,174 | 131,174 | - |
| Department of Local Affairs | - | 5,600 | 5,600 | 5,600 | 5,600 |
| Cumbres & Toltec Scenic Railroad Commision | - | - | - | - | - |
| TOTAL | 31,690,727 | 32,905,445 | 33,875,149 | 35,103,341 | 35,991,174 |

CHART C, AGENCY CURRENT REPLACEMENT VALUE (CRV) FY2001/2002 CONTROLLED MAINTENANCE PROGRAM

| | GSF | CRV | CRV/GSF | GSF | CRV | CRV/GSF |
|---|-------------|-----------------|-------------|-----------------|-----------------|------------|
| AGENCY | (all bldgs) | (all bldgs) | (all bldgs) | (gen fund only) | (gen fund only) | (gen fund) |
| Capitol Complex Facilities | 1,149,699 | \$181,564,631 | \$157.92 | 1,149,699 | \$181,564,631 | \$157.92 |
| Colorado Government Technology Services | 16,406 | \$1,626,307 | \$99.13 | 16,406 | \$1,626,307 | \$99.13 |
| Camp George West | 0 | | | 0 | | |
| State Capitol Building | 307,467 | \$169,106,850 | \$550.00 | 307,467 | \$169,106,850 | \$550.00 |
| Agriculture, Department of - Zuni & Insectary | 40,814 | \$4,846,633 | \$118.75 | 40,814 | \$4,846,633 | \$118.75 |
| Colorado State Fair | 717,865 | \$57,339,494 | \$79.88 | 704,956 | \$56,675,708 | \$80.40 |
| Corrections, Department of | 5,881,987 | \$813,355,907 | \$138.28 | 5,881,987 | \$813,355,907 | \$138.28 |
| Colorado School for the Deaf and the Blind | 294,775 | \$38,906,320 | \$131.99 | 294,775 | \$38,906,320 | \$131.99 |
| Public Health & Environment, Department of | 90,167 | \$13,520,000 | \$149.94 | 90,107 | \$13,520,000 | \$150.04 |
| Colorado Historical Society | 119,939 | \$7,268,788 | \$60.60 | 119,939 | \$7,268,788 | \$60.60 |
| University of Colorado Health Science Center | 3,229,090 | \$294,654,463 | \$91.25 | 2,377,675 | \$225,309,600 | \$94.76 |
| University of Colorado at Boulder | 9,126,939 | \$1,266,282,091 | \$138.74 | 4,302,511 | \$691,878,034 | \$160.81 |
| University of Colorado at Colorado Springs | 867,270 | \$148,799,200 | \$171.57 | 603,883 | \$105,618,143 | \$174.90 |
| Colorado State University | 7,819,478 | \$862,131,056 | \$110.25 | 5,261,957 | \$588,576,304 | \$111.86 |
| University of Southern Colorado | 963,277 | \$138,782,891 | \$144.07 | 649,123 | \$96,598,435 | \$148.81 |
| Fort Lewis College | 918,230 | \$108,533,993 | \$\$118.20 | 440,648 | \$57,434,367 | \$130.34 |
| University of Northern Colorado | 2,627,237 | \$355,244,021 | \$135.22 | 1,354,439 | \$186,680,698 | \$137.83 |
| Adams State College | 998,075 | \$130,614,804 | \$130.87 | 539,644 | \$72,656,158 | \$134.64 |
| Mesa State College | 809,773 | \$111,897,252 | \$138.18 | 505,034 | \$76,597,727 | \$151.67 |
| Western State College | 994,924 | \$137,064,809 | \$137.76 | 497,976 | \$68,818,567 | \$138.20 |
| Colorado School of Mines | 1,533,537 | \$274,971,835 | \$179.31 | 1,129,240 | \$205,777,266 | \$182.23 |
| Auraria Higher Education Center | 2,465,470 | \$343,026,994 | \$139.13 | 1,573,929 | \$262,602,189 | \$166.85 |
| Arapahoe Community College | 405,067 | \$52,906,842 | \$130.61 | 405,067 | \$52,906,842 | \$130.61 |
| Colorado Northwestern Community College | 323,568 | \$20,622,092 | \$63.73 | 179,708 | \$12,447,536 | \$69.27 |
| Front Range Community College | 609,715 | \$59,497,083 | \$97.58 | 539,155 | \$52,651,028 | \$97.65 |
| Lamar Community College | 298,498 | \$23,376,600 | \$78.31 | 247,498 | \$15,668,227 | \$63.31 |
| Morgan Community College | 73,901 | \$10,055,227 | \$136.06 | 73,901 | \$10,055,227 | \$136.06 |
| Northeastern Junior College | 481,606 | \$52,848,934 | \$109.73 | 336,813 | \$31,488,562 | \$93.49 |
| Otero Junior College | 264,136 | \$36,863,916 | • | 202,041 | \$28,793,426 | \$142.51 |
| Pikes Peak Community College | 443,850 | \$46,618,675 | \$105.03 | 416,979 | \$43,023,662 | \$103.18 |

CHART C, AGENCY CURRENT REPLACEMENT VALUE (CRV) FY2001/2002 CONTROLLED MAINTENANCE PROGRAM

| AGENCY | GSF (all bldgs) | CRV (all bldgs) | CRV/GSF (all bldgs) | GSF (gen fund only) | CRV (gen fund only) | CRV/GSF (gen fund) |
|---|--------------------|--------------------|------------------------|------------------------|------------------------|-----------------------|
| Pueblo Community College | 385,402 | \$43,537,520 | \$112.97 | 330,402 | \$37,641,218 | \$113.93 |
| Red Rocks Community College | 373,974 | \$46,125,782 | • | 373,974 | \$46,125,782 | \$123.34 |
| Trinidad State Junior College | 398,800 | \$62,588,367 | \$156.94 | 285,093 | \$47,326,723 | \$166.00 |
| Higher Ed & Advanced Tech Center at Lowry | 713,759 | \$62,358,984 | \$87.37 | 548,567 | \$38,937,992 | \$70.98 |
| Community College of Aurora | 25,900 | \$3,550,050 | \$137.07 | 25,900 | \$3,550,050 | \$137.07 |
| Human Services, Department of | 3,111,883 | \$393,842,083 | \$126.56 | 2,768,384 | \$364,905,228 | \$131.81 |
| Judicial Department | 222,632 | \$36,198,661 | \$162.59 | 222,632 | \$36,198,661 | \$162.59 |
| Military Affairs, Department of | 1,089,561 | \$130,015,910 | \$119.33 | 840,898 | \$100,198,153 | \$119.16 |
| Colorado Department of Public Safety | 216,119 | \$24,429,769 | \$113.04 | 216,119 | \$24,429,769 | \$113.04 |
| Revenue, Department of | 130,234 | \$19,257,387 | \$147.87 | 130,234 | \$19,257,387 | \$147.87 |
| Local Affairs, Department of | 5,600 | \$734,283 | \$131.12 | 5,600 | \$734,283 | \$131.12 |
| SUBTOTAL | 50,546,624 | \$6,584,966,504 | \$130.28 | 35,991,174 | \$4,891,758,388 | \$135.92 |
| Labor & Employment, Department of | 131,174 | \$20,253,663 | \$154.40 | | | |
| Transportation, Department of | 2,466,309 | \$202,348,104 | | | | |
| Parks & Outdoor Recreation, Division of | 1,068,430 | \$69,219,986 | | | | |
| Wildlife, Division of | 768,869 | \$61,534,140 | \$80.03 | | | |
| Water Resources, Division of | 23,165 | \$1,965,248 | \$84.84 | | | |
| State Land Board | 149,264 | \$2,002,467 | \$13.42 | | | |
| TOTAL FOR ALL AGENCIES | 55,153,835 | \$6,942,290,111 | \$125.87 | | | |

VI. FACILITIES AUDIT SUMMARY

SECTION VI: SBP FACILITIES AUDIT SUMMARY FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FACILITIES AUDIT

INTRODUCTION TO FACILITIES AUDIT

The facilities audit provides a source for identifying the existing physical condition of buildings and infrastructure, as well as their maintenance deficiencies. From the information gathered during an audit, estimates can be developed for capital renewal and replacement requirements for individual projects as well as annual forecasts. The facilities audit provides a basis for decision-making on routine maintenance, capital construction and controlled maintenance, and replacements and disposal of facilities. Using the audit to inspect building and infrastructure conditions helps with maintenance management and the prioritizing of projects for capital budgeting.

PURPOSE OF THE AUDIT

The facility audit systematically and routinely identifies facility deficiencies through an inspection program and observation report. The audit process can help management recommend actions for capital construction and controlled maintenance.

The audit is designed for use by facilities managers responsible for maintenance, capital renewal and replacements, and capital budgeting. A continuous process of facilities audits, rather than a one-time program, provides up-to-date major maintenance priorities, and can generate a significant portion of routine maintenance workloads. An effective audit program will extend the useful life of facilities, and reduce disruptions in use of space and equipment downtime.

STRUCTURE / AUDIT PHASES

The audit is a method of collecting information on the current maintenance conditions of a facility through an inspection process. The inspection process consists of systematic inspections of buildings and infrastructure by components, following the sequence of construction. The facilities condition is evaluated for future planning purposes, capital renewal, and replacements. The basic phases of an audit are shown in Diagram A.

UTILIZATION / CAPITAL ASSET MANAGEMENT

- A facilities audit process is one element of a comprehensive approach to a capital asset management program. This approach leads to better planning of maintenance and capital expenditures to protect and extend the life of capital assets. Frequently, lack of planning and limited funds create maintenance backlogs and unattended facilities deficiencies. These facilities deteriorate, resulting in deferred maintenance and a significant financial burden for corrective measures. Therefore, it is necessary to have a process facilities audit that clearly identifies and quantifies the condition and functional performance of the physical plant and the cost of various options for correcting deficiencies.
- How much to spend on correcting deficiencies is guided by the results on an audit and the total cost of prioritized projects. Questions to be posed are: How will X dollars for some years reduce a backlog of deficiencies at the end of the period? Or; How much must be spent to reach a desired level of conditions for all facilities over a certain number of years? Key variables are the capital reinvestment rate and the backlog targets. Factored into decisions in both cases are the inflation rate, the rate of plant deterioration, and the backlog deterioration rate.

The facility condition index (FCI), a method of comparing facilities conditions based on a ratio of facilities deficiencies to current replacement value (CRV), is useful in setting annual funding targets and the duration of deferred maintenance reduction.

 Facility Condition Index (FCI) =
 deficiencies

current replacement value (CRV)

STATUS OF THE STATE OF COLORADO'S FACILITIES AUDITS

Although resources are limited, SBP and the State of Colorado Facilities Managers Association (SCFMA) explored options for assisting various agencies and institutions to design and implement their facilities audits in FY1997/98. The current status of their efforts is listed in chart B. Additionally, SBP began compiling an inventory of all state-owned, general funded property with the assistance of the Division of Risk Management. This inventory list is updated annually with the agencies and institutions and the Division of Risk Management in order to provide consistent numbers for such things as: current replacement value (CRV), gross square footage and usage. The result is a single, comprehensive inventory of state owned general-funded facilities.

REPORT OF THE STATE AUDITOR, AUGUST 1996

The State Auditor completed a performance audit of the capital construction process in the State of Colorado. Included in the performance audit was a review of the state's controlled maintenance program. The report noted that, "The state must identify and adopt more cost-effective methods of identifying and prioritizing its controlled maintenance needs." Specifically, the auditor recommended that "State Buildings should work with state agencies to develop guidelines and standards that agencies can use to implement individual facilities audit programs, it should also provide technical assistance to agencies on carrying out the programs." SBP agreed.

DIAGRAM A

THE PHASES OF A FACILITIES AUDIT CYCLE




CHART B

AUDIT CYCLE STATUS BY AGENCY/INSTITUTION

| AGENCY | STATUS: | GROSS |
|--|--|------------|
| | BUILDING AUDIT | SQUARE |
| | INFRASTRUCTURE ASSESSMENT | FEET |
| General Support Services | Duilding Dhoop 4 Implementation | 1 1 10 000 |
| Capitol Complex Facilities | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 1,149,699 |
| Colorado Government Technology Services | Building: Phase 2, Conducting Inspections Infrastructure: Phase 2, Conducting Inspections | 16,406 |
| Camp George West | Building: Not Applicable Infrastructure: Phase 4, Implementation | 0 |
| State Capitol Building | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 307,467 |
| Department of Agriculture | | |
| Zuni, Insectary Facilities | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 40,814 |
| State Fair | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 704,956 |
| Department of Corrections | Building: Phase 4, Implementation (90% done) | 5,881,987 |
| - | Infrastructure: Phase 4, Implementation (90% done) | |
| Department of Education | | 004775 |
| Colorado School for the Deaf and Blind | Building: Phase 2, Conducting Inspections Infrastructure: Phase 2, Conducting Inspections | 294,775 |
| Department of Public Health and the | Building: Phase 1, Assessment of Resources Required | |
| Environment | Infrastructure: Phase 1, Assessment of Resources Required | 90,107 |
| Department of Higher Education Historical Society | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 119,939 |
| DOHE, CU Board of Regents | <u>Influence and</u> in flage if in planter and in | |
| University of Colorado - Health Science Center | Building: Phase 4, Implementation (70% done) Infrastructure: Phase 4, Implementation | 2,377,675 |
| University of Colorado - Boulder | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 4,302,511 |
| University of Colorado - Colorado Springs | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 603,883 |
| DOHE, State Board of Agriculture | | |
| Colorado State University | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 5,261,957 |
| University of Southern Colorado | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 649,123 |
| Fort Lewis College | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 440,648 |
| DOHE, Trustees of Univ. of N. Colo. | | |
| University of Northern Colorado | Building: Phase 4, Implementation Infrastructure: Phase 2, Conducting Inspections | 1,354,439 |
| DOHE, Trustees of State Colleges | | |
| Adams State College | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 539,644 |
| Mesa State College | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 505,034 |
| Western State College | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 497,976 |

| DOHE, Trustees of C. Sch. of Mines | | |
|---|---|-----------|
| Colorado School of Mines | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 1,129,240 |
| DOHE, Board of Directors of AHEC Auraria Higher Education Center | Building: Phase 4, Implementation | 1,573,929 |
| - | Infrastructure: Phase 4, Implementation | 1,070,929 |
| DOHE, CCC | | |
| Arapahoe Community College | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 405,067 |
| Colorado Northwestern Com. College | Building: Phase 2, Conducting Inspections Infrastructure: Phase 2, Conducting Inspections | 179,708 |
| Front Range Community College | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 539,155 |
| Lamar Community College | Building: Phase 4, Implementation Infrastructure: Phase 2, Conducting Inspections | 247,498 |
| Morgan Community College | Building: Phase 4, Implementation Infrastructure: Phase 2, Conducting Inspections | 73,901 |
| Northeastern Junior College | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 336,813 |
| Otero Junior College | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 202,041 |
| Pikes Peak Community College | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 416,972 |
| Pueblo Community College | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 330,402 |
| Red Rocks Community College | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 373,974 |
| Trinidad State Junior College | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 285,093 |
| HEAT - Lowry | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 548,567 |
| Department of Human Services | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 2,768,384 |
| Department of Justice | <u></u> | |
| Judicial Heritage | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 222,632 |
| Department of Military Affairs | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 840,898 |
| Department of Public Safety | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 216,119 |
| Department of Revenue | Building: Phase 4, Implementation Infrastructure: Phase 4, Implementation | 130,234 |
| Department of Local Affairs | Building: Phase 1, Assessment of Resources Required Infrastructure: Not Applicable | 5,600 |
| Cumbres & Toltec Scenic Railroad Commission | Building: Phase 1, Assessment of Resources Required Infrastructure: Phase 1, Assessment of Resources Required | 0 |

 TOTAL GSF
 35,991,174

 TOTAL AUDITED GSF
 34,832,785

 % AUDITED OF TOTAL GSF
 95%

(Compared with 61 % in FY 00/01, and 47% in FY 99/00)

VII. ENERGY EFFICIENCY CONTRACTS

SECTION VII: ENERGY EFFICIENCY CONTRACTS FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

CAPITAL IMPROVEMENTS FINANCED THROUGH ENERGY EFFICIENCY CONTRACTS

Six state agencies or institutions of higher education have installed \$7.2 million of energy efficient equipment in state buildings through Energy Efficiency Contracts. The contracts provide for improved lighting equipment, new or replaced heating and cooling systems, mechanical system repairs, and modern energy management control systems -- using existing utility budgets to pay for all project costs.

Pueblo Community College has selected an energy service company for an energy efficiency contract. The school had the energy audit completed in the spring of 2000 and is in the process of negotiating the contract. The University of Colorado Health Sciences Center is planning on issuing a Request for Proposal this December to select and then hire an energy service company for the Research Bridge Building on their 9th and Colorado campus. Front Range Community College - Larimer Campus is putting together the proposal documents with support from the Office of Energy Management and Conservation to release a Request for Proposal solicitation within the next few months.

Energy Efficiency Contracts in Colorado State Agencies

| State Agencies or Higher Education Institutions | Energy Efficiency Contract Capital Investment |
|---|--|
| Capitol Complex Facilities | \$ 193,045 |
| Department of Military Affairs | \$ 166,700 |
| Auraria Higher Education Center | \$2,135,000 |
| Adams State College | \$ 367,000 |
| Western State College | \$3,335,000 |
| University of Southern Colorado | \$1,055,005 |
| Total | \$7,251,750 |

PROCESS

Energy efficiency contracting is a practical and increasingly common way for building managers to implement energy saving projects. It has been used successfully by the private sector and local and state governments across the country, as well as by federal agencies.

Since FY1997/98 State Buildings Programs (SBP) and the Office of Energy Management and Conservation (OEMC) have helped state agencies effectively utilize energy efficiency contracts. In each case, a competitive procurement process was used to select an energy service company (ESCO). The ESCO conducts an energy audit of the agency's facilities to identify cost-effective energy saving opportunities. Based on audit results, the ESCO and agency negotiate an energy efficiency improvement contract to establish project specifications, roles of the contracting parties, methodology for determining energy cost savings, and type of financing mechanism. Financing is generally arranged through a lease-purchase agreement, with quarterly lease payments paid from energy savings through the agency's utility line item.

ESCOs provide a full range of services including engineering design, purchasing, construction management, long-term maintenance, staff training, savings guarantee and project financing. Energy savings are guaranteed by the ESCO, so if savings fall short the ESCO makes up the difference. In most cases the ESCO provides maintenance services throughout the contract term in order to ensure optimum equipment performance and maximum energy savings; however, some agencies declined this service because of their own in-house capability. Most contracts span ten years. This long-term

agreement allows agencies to include projects such as boiler or chiller replacements that do not have short payback periods.

UPDATE OF PROJECTS

Six state agencies or institutions of higher education have used energy efficiency contracts, as described below.

- The **Department of Military Affairs (DMA)** selected an ESCO to perform an audit of its Englewood headquarters in January 1995. A year and a half later, DMA signed a ten-year energy efficiency contract for \$167,000 worth of new energy efficient equipment and maintenance services. Actual energy savings measured for the first six months following installation were ahead of the projected savings of \$26,000 per year. This resulted in DMA receiving in the FY1998/99 Long Bill a supplemental appropriation of \$153,309 to "buy-out" the energy efficiency contract. This means that DMA paid off the loan for the energy efficiency equipment early. DMA subsequently ended the verification and measurement contact since the savings over the first two years are above the calculated expectations and thus the cost of verification is used for other operation and maintenance needs.
- Auraria Higher Education Center (AHEC) in Denver contracted with an ESCO to perform an energy audit of a portion of the campus in May 1995. A year later, AHEC signed a nine-year energy efficiency contract allowing AHEC to get \$2.1 million worth of new equipment and a long-term maintenance agreement. Although AHEC chose to provide its own financing (through Certificates of Participation), it used the ESCO to manage the project and used the ESCO's guarantee of energy savings to secure the funding. The installation was completed in the fall of 1997. The energy saving in the first year was \$142,700 (over a seven-month period) and in the second year was \$244,393. The energy saving in FY99/00 was \$226,203.
- Adams State College (ASC) in Alamosa selected an ESCO to audit its facilities in 1995. In May 1996 ASC signed a ten-year energy efficiency contract to upgrade lighting systems throughout the campus and to install stand-alone gas-fired boilers for five buildings. The total retrofit cost of \$548,000 was offset by rebates and grants, which brought the total financed cost down to \$346,000. The project was completed in April 1997 and is expected to generate savings of \$121,000 per year. In the first year, FY98/99, the college saved \$123,872. ASC subsequently signed another energy efficiency contract with the same ESCO to obtain gas-fired boilers for eight additional auxiliary funded buildings. The energy saving in FY99/00 was \$119,603.
- Western State College (WSC) of Gunnison selected an ESCO to audit its facilities in 1996. Four months later, WSC signed a ten-year energy efficiency contract for \$3.3 million worth of energy saving retrofits. In addition to the typical lighting upgrades and control system, WSC's contract included \$2.3 million to decentralize the heating plant. The installation was completed during the summer of 1997. The project has estimated annual savings of \$275,000. In the first year of the project savings guarantee, the measured savings were less than projected, resulting in the ESCO paying the college \$50,000. The payment was the results of complications with construction projects on campus and problems with the electric and gas meters. These problems affected the measurement and verification procedure, but both the college and the ESCO feel that this was a one-time event and actual savings can be documented in subsequent years. The energy saving have since than been documented to exist and be sustainable. WSC used an option in their contract to end the energy efficiency contract with the ESCO. Thus, the expense of the monitoring and verification by the ESCO and the energy saving are both used to pay off the loan, which will reduced the loan payments from seven to five years.
- University of Southern Colorado (USC) of Pueblo selected an ESCO to audit its facilities in September 1996. One year later, USC signed a \$1.1 million energy efficiency contract lasting 10 years. A significant benefit is that the contract will replace USC's existing but failed controls system.

The contract also will provide lighting retrofits, steam trap replacements, and automated irrigation water controls. The retrofits are expected to be paid for in ten years through the annual energy savings. The construction project was completed in the summer of 1998. The savings in FY98/99 were \$105,499. The energy saving in FY99/00 was \$130,722.

 Capitol Complex Facilities (CCF) entered into a five-year energy efficiency contract in late 1989. By 1995 CCF had paid for \$193,045 worth of energy efficient lighting equipment, including installation and maintenance over the contract period. Energy savings of \$42,000 per year allowed CCF to make payments through the utility line item.

The Office of Energy Conservation (OEC) in the summer of 1998 launched a new program, *Rebuild Colorado*, to assist building owners throughout the state with energy efficiency contracting. ESCOs provide a full range of services including engineering design, purchasing, construction management, long-term maintenance, staff training and project financing.


ENERGY EFFICIENCY CONTRACTS REDUCE CONTROLLED MAINTENANCE REQUESTS

A review of the Energy Performance Contracts identified a total of \$2.8 million in unfunded Controlled Maintenance requests that were later funded through energy efficiency contracts.

| Agency | Fiscal Year of CM request | CM Reference Number | Description | Request Amount |
|------------------------------------|------------------------------|---------------------------|---|-------------------|
| Adams State College | 1996/1997 | 140 | Replace Interior Lighting – Campus | \$ 278,000 |
| Auraria Higher Education Center | 1996/1997 | 184 | Replace CFC Refrigerants in Chillers | \$ 769,300 |
| Auraria Higher Education Center | 1996/1997 | 20 | Repair/Replace Mechanical System (ECMS, PE Heat Recovery) | \$ 800,000 |
| University of Southern Colorado | 1995/1996 | 255 | Replace Deteriorated Mechanical Equipment & HVAC controls | \$ 565,251 |
| Western State College | 1997/1998 | 434 | Repair/Replace Lighting System – Maintenance Building | \$ 42,675 |
| Western State College | 1997/1998 | 456 | Repair/Replace Lighting System – Kelly Hall | \$ 47,784 |
| Western State College | 1997/1998 | 485 | Repair/Replace Lighting System – Quigley Hall | \$ 126,366 |
| Western State College | 1997/1998 | 488 | Repair/Replace Lighting System – Savage Library | \$ 103,131 |
| Western State College | 1997/1998 | 496 | Repair/Replace Lighting System – Hurst Hall | \$ 72,880 |
| Western State College | 1997/1998 | 499 | Repair/Replace Lighting System – Taylor Hall | \$ 84,242 |
| TOTAL | | | | \$ 2,889,629 |

POTENTIAL FOR ENERGY EFFICIENCY CONTRACTING

The projected dollar amount of short-term major maintenance for FY 2001/2002 in the cumulative fiveyear plan project request was \$346,360,359 of the prioritized projects. A review of the five-year plan indicated an amount of \$66,132,902 in projects that are energy related. This is 20.7% of the five-year plan. These include equipment replacements or upgrades such as lighting systems, heating and chiller systems, and control systems. These types of improvements are needed in most buildings, so energy efficiency contracts could be beneficial.



These projects are excellent candidates for funding through energy efficiency contracts, which could reduce the amount of future CM requests and effectively increase the number of projects that are funded.

CONTROLLED MAINTENANCE ENERGY EFFICIENCY CONTRACTS REQUEST

The FY2001/2002 controlled maintenance instructions have a section relating to energy efficiency contracts. Agencies that have an existing energy efficiency contract or are planning to enter into an energy efficiency contract in the next fiscal year are required to complete the forms. One agency submitted the forms in this year's CM request seeking to start the process to enter into an energy efficiency contract. The Department of Corrections is interested in using the performance contracting process for a \$4,000,000 project to improve its water system at the East Canon City Prison Complex. This project has the potential of funding approximately \$1,500,000 in identified future CM requests. The Colorado School for the Deaf and Blind submitted the forms in FY98/99 and are still interested in an energy efficiency contract. CSDB identified projects in their five-year plan worth \$400,000 that could be funded through an energy efficiency contract. When the energy audits are completed by the ESCOs, the potential CM impact can be determined. Since the energy efficiency contract upgrades and retrofits state owned facilities, they will reduce future CM requests.

VIII. AGENCY PRIORITIZED FIVE YEAR PLAN PROJECT REQUESTS

SECTION VIII: AGENCY PRIORITIZED FIVE YEAR PLAN PROJECT REQUESTS FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

This list (23 pages) represents a prioritized listing of all agency Five Year Plan Project Requests eligible for Controlled Maintenance.

The total number of projects listed has increased from last year from 813 to 815. The total amount requested for five year plan project requests increased by \$42,641,765 from \$303,718,594 in FY00/01 to \$346,360,359 in FY01/02. The increase in reporting is due, in large part, to the agencies and institutions of the state completing comprehensive facility condition surveys (Facilities Audits) of their state owned Buildings and supporting Infrastructure. Please refer to Section VI, facilities audit summary.

Also listed are the agencies estimated future needs compiled from their facility audits. The majority of these needs for repair/replacement/upgrades to existing buildings and infrastructures are not needed in the next five fiscal years. The estimated future controlled maintenance needs totals \$558,723,992 for FY01/02.

The Department of Public Health and the Environment, the Department of Local Affairs, the Community College of Aurora and the HEAT Center at Lowry did not submit controlled maintenance requests for fiscal year 2001/2002.

AGENCY PRIORITIZED FIVE YEAR PLAN PROJECT REQUESTS FY2001/2002 CONTROLLED MAINTENANCE PROGRAM

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount | | | | |
|-------------|--|-----------------|----------------|--|---------------------|--|--|--|--|
| State | State Buildings and Real Estate Programs | | | | | | | | |
| 1 | 1 | FY01/02 | | Emergency Fund | \$1,000,000 | | | | |
| | | | | GSS-SBREP | \$1,000,000 | | | | |
| Capi | tol Com | plex Facil | ities | | | | | | |
| 23 | 9 | FY01/02 | | Repair Passenger and Freight Elevators in Annex and Centennial Buildings, Ph 1 of 3 | \$325,670 | | | | |
| 67 | 18 | FY01/02 | | Replace Deteriorated Roofs at SOB, Centennial, and Power Plant, Ph 1 of 1 | \$607,180 | | | | |
| 85 | 20 | FY01/02 | | Variable Air Volume Boxes Replacement at Centennial Building, Ph 1 of 1 | \$1,396,800 | | | | |
| 122 | 30 | FY01/02 | | Upgrade/Replace Domestic Water Pump Systems and Heat Exchangers, Ph 1 of 1 | \$326,315 | | | | |
| 165 | 72 | FY01/02 | | Secondary Electrical Power Service Upgrade, Ph 1 of 1 | \$380,870 | | | | |
| | | FY02/03 | | Chilled Water System Upgrades at 690 Kipling, Ph 1 of 1 | \$195,505 | | | | |
| | | FY02/03 | | Mechanical Upgrades at 700 Kipling, Ph 1 of 2 | \$120,925 | | | | |
| | | FY02/03 | | Recarpet SOB, Ph 1 of 1 | \$195,645 | | | | |
| | | FY02/03 | | Repair Passenger and Freight Elevators in Annex and Centennial Buildings, Ph 2 of 3 | \$849,420 | | | | |
| | | FY02/03 | | Repair/Recaulk Leaking Exterior Walls, Windows and Waterproof Loading Dock at Centennial, Ph 1 of 1 | \$169,360 | | | | |
| | | FY03/04 | | Mechanical Upgrades at 700 Kipling, Ph 2 of 2 | \$793,800 | | | | |
| | | FY03/04 | | Repair Passenger and Freight Elevators in Annex and Centennial Buildings, Ph 3 of 3 | \$1,258,400 | | | | |
| | | FY04/05 | | Architectural Upgrades at Centennial, Ph 1 of 2 | \$474,800 | | | | |
| | | FY04/05 | | Install Electrical Sub-Metering in 6 Capitol Complex Buildings, Ph 1 of 1 | \$169,845 | | | | |
| | | FY04/05 | | Install Energy Management Light System at RES Complex Building, Ph 1 of 1 | \$233,905 | | | | |
| | | FY04/05 | | LSB Lighting System Upgrades and Print Shop Floor Repairs, Ph 1 of 1 | \$68,740 | | | | |
| | | FY04/05 | | North Campus, West Building, Domestic Water Pipe Replacement, Ph 1 of 1 | \$52,170 | | | | |
| | | FY05/06 | | Architectural Upgrades at Centennial, Ph 2 of 2 | \$254,310 | | | | |
| | | FY05/06 | | Mechanical System Upgrades at SOB, Ph 1 of 1 | \$585,395 | | | | |
| | | FY05/06 | | North Campus Shops Suspended Ceiling System, Ph 1 of 1 | \$56,065 | | | | |
| | | FY05/06 | | Recarpet Grand Junction SSB Common Areas, Ph 1 of 1 | \$76,100 | | | | |
| | | FY05/06 | | Repair/Replace Delaminated Doors at GGCC/CBI, Ph 1 of 1 | \$66,035 | | | | |
| | | | | GSS-CCF 5 Year Plan Project Request Total: | \$8,657,255 | | | | |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$1,064,855 | | | | |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$0 \$0,700,440 | | | | |
| | | | | Agency Reported Controlled Maintenance Total: | \$9,722,110 | | | | |
| Colo | | | | ogy Services | | | | | |
| 66 | | FY01/02 | M90101 | Replace Roofs on Remote TX Buildings (B), Ph 3 of 5 | \$53,280 | | | | |
| 82 | | | | Replace Emergency Generators, Ph 3 of 5 | \$71,060 | | | | |
| 101 | 24 | | | Replace Batteries for Back-Up Generators, Ph 2 of 3 | \$87,780 | | | | |
| | | | | Replace Batteries for Back-Up Generators, Ph 3 of 3 | \$28,700 | | | | |
| | | | | Replace Emergency Generators, Ph 4 of 5 | \$69,700 | | | | |
| | | | | Replace Roofs on Remote TX Buildings (B), Ph 4 of 5 | \$52,260 | | | | |
| | | | | Replace Emergency Generators, Ph 5 of 5 | \$69,700 | | | | |
| | | FY03/04 | M90101 | Replace Roofs on Remote TX Buildings (B), Ph 5 of 5 | \$52,260 | | | | |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|----------|--------------------|----------------|--|------------------------|
| | | | | GSS-CGTS 5 Year Plan Project Request Total: | \$484,740 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$0 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$484,740 |
| Cam | p Georg | ge West | | | |
| 109 | 24 | FY01/02 | | Limited CGW Paving and Removal of 2 Hazardous Buildings, Ph 1 of 1 | \$122,346 |
| | | FY02/03 | | Site Paving Infrastructure Project, Ph 1 of 3 | \$892,230 |
| | | FY03/04 | | Site Paving Infrastructure Project, Ph 2 of 3 | \$535,724 |
| | | FY04/05 | | Site Paving Infrastructure Project, Ph 3 of 3 | \$726,012 |
| | | FY05/06 | | Irrigation System Automation and Replacement Project, Ph 1 of 1 | \$67,500 |
| | | | | GSS-CGW 5 Year Plan Project Request Total: | \$2,343,812 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$0 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$2,343,812 |
| Stat | e Capito | l Building | | | |
| 5 | 3 | FY01/02 | | House and Senate Chamber Brass Handrail Safety Improvements, Ph 1 of 1 | \$193,735 |
| 47 | 12 | FY01/02 | | Renovate State Capitol First Floor Lights, Ph 1 of 1 | \$466,375 |
| 128 | 30 | FY01/02 | | Repair/Replace State Capitol Roof, Ph 1 of 1 | \$511,890 |
| | | FY02/03 | | Capitol Water Lines Replacement, Ph 1 of 1 | \$2,303,955 |
| | | FY02/03 | | Repair/Renovate Exterior Windows at Capitol, Ph 1 of 4 | \$450,660 |
| | | FY03/04 | | Capitol Carpet and Draperies Replacement, Ph 1 of 1 | \$110,730 |
| | | FY03/04 | | Clean and Preserve Granite at Capitol, Ph 1 of 1 | \$353,970 |
| | | FY03/04 | | Repair/Refinish Capitol Doors and Woodwork, Ph 1 of 3 | \$272,625 |
| | | FY03/04 | | Repair/Renovate Exterior Windows at Capitol, Ph 2 of 4 | \$407,185 |
| | | FY04/05 | | Refurbish Capitol Interior Hallways, Ph 1 of 2 | \$741,115 |
| | | FY04/05 FY04/05 | | Repair/Refinish Capitol Doors and Woodwork, Ph 2 of 3 | \$272,630 \$407,185 |
| | | FY04/05 | | Repair/Renovate Exterior Windows at Capitol, Ph 3 of 4 Replace Capitol Venetian Blinds, Ph 1 of 1 | \$407,185 \$253,490 |
| | | FY05/06 | | Refurbish Capitol Interior Hallways, Ph 2 of 2 | \$741,110 |
| | | FY05/06 | | Repair/Refinish Capitol Doors and Woodwork, Ph 3 of 3 | \$545,250 |
| | | FY05/06 | | Repair/Renovate Exterior Windows at Capitol, Ph 4 of 4 | \$407,185 |
| | | 1 100,00 | | GSS-SCB 5 Year Plan Project Request Total: | \$8,439,090 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$6,253,975 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$0 \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$14,693,065 |
| Dep | artment | of Aaricu | lture - Zui | ni & Insectary | |
| 17 | | - | | BioChem Lab Building System Replacement, Ph 2 of 2 | \$259,325 |
| 83 | | | | Metrology Lab Building System Replacement, Ph 2 of 2 | \$169,528 |
| | | FY02/03 | | Metrology Bldg. Large Lab Floor Upgrade, Ph 1 of 1 | \$75,000 |
| | | FY03/04 | | BioChem Building Sprinkler System/Pk Lot, Ph 1 of 1 | \$70,000 |
| | | FY04/05 | | Insectary Architectural Upgrades, Ph 1 of 1 | \$182,875 |
| | | FY05/06 | | Warehouse Upgrade, Ph 1 of 1 | \$175,560 |
| | | | | DOAg 5 Year Plan Project Request Total: | \$932,288 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$0 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$932,288 |
| | | | | | |

| 42 12 FY01/02 Correct Accessibility Problems on the Fairgrounds, Ph 1 of 4 \$21,012; FY02/03 Correct Accessibility Problems on the Fairgrounds, Ph 2 of 4 \$275; FY02/03 Electrical Infrastructure Repair/Replacement, Ph 2 of 2 \$993; FY02/03 M00001 Infrastructure Repair/Replacement, Ph 2 of 2 \$975; FY03/04 Correct Accessibility Problems on the Fairgrounds, Ph 3 of 4 \$1,422; FY03/04 Replace HVAC in Place of Agricuture, Ph 1 of 1 \$1,200; FY04/05 Correct Accessibility Problems on the Fairgrounds, Ph 4 of 4 \$275; FY04/05 Repair Livestock Pavilion, Ph 1 of 1 \$12,000; FY04/05 Repair Livestock Pavilion, Ph 1 of 1 \$3600; FY04/05 Repair Livestock Pavilion, Ph 1 of 1 \$14,001; FY05/06 Outdoor Stage Replacement, Ph 1 of 1 \$14,001; Livestock Pavilion, Ph 1 of 1 \$14,001; \$14,001; Livest | Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount | | | | |
|--|-------------|---------------------|-----------------|----------------|--|---------------------|--|--|--|--|
| 42 12 FY01/02 Correct Accessibility Problems on the Fairgrounds, Ph 1 of 4 \$215, FY02/03 FY02/03 Correct Accessibility Problems on the Fairgrounds, Ph 2 of 4 \$275, FY02/03 FY02/03 Electrical Infrastructure Repair/Replacement, Ph 2 of 2 \$993, FY02/03 FY02/04 Repair/Replacement, Ph 4 of 4 \$1,422, FY03/04 FY03/04 Replace Roof on 5 Buildings, Ph 2 of 2 \$875, FY03/04 FY04/05 Correct Accessibility Problems on the Fairgrounds, Ph 3 of 4 \$2275, FY04/05 FY04/05 Repair/Replace Roof on 5 Buildings, Ph 2 of 2 \$875, FY04/05 FY04/05 Repair Livestock Pavilion, Ph 1 of 1 \$12,000, FY04/05 \$8650, FY04/05 FY04/05 Repair Livestock Pavilion, Ph 1 of 1 \$13,000, FY05/06 \$14,000, Outdoor Stage Replacement, Ph 1 of 1 \$14,001, \$14,000, S14,000, Ph 2 of 2 Estimated Long Term Infrastructure Major Maintenance Total: \$11,716, \$14,000, S14,000, Ph 2 of 2 \$14,400, \$14,400, \$14,400, \$14,400, \$14,400, \$14,400, \$14,400, \$14,400, \$14,400, \$14,400, \$14,500, \$17,504, \$14,240, \$14,500, \$17,504, \$14,240, \$17,504, \$14,240, \$14,400, \$1 | State | State Fair - Pueblo | | | | | | | | |
| FY01/02 Electrical Infrastructure Repair/Replacement, Ph 1 of 2 \$1.012 FY02/03 Correct Accessibility Problems on the Fairgrounds, Ph 2 of 4 \$275; FY02/03 Electrical Infrastructure Repair/Replacement, Ph 2 of 2 \$993; FY02/03 M00001 Infrastructure Repair/Replacement, Ph 4 of 4 \$1.420; FY03/04 Replace HOAC in Place of Agriculture, Ph 1 of 1 \$1.200; FY04/05 Correct Accessibility Problems on the Fairgrounds, Ph 4 of 4 \$725; FY04/05 Horse Stall Inprovements, Ph 1 of 1 \$700; FY04/05 Repair Evestock Pawlion, Ph 1 of 1 \$300; FY05/06 Repair Livestock Pawlion, Ph 1 of 1 \$300; FY05/06 Event Center Parking Lot Improvements, Ph 1 of 1 \$300; FY05/06 Cured Correct Accessibility Problems on the Fairgrounds, Ph 3 of 4 \$1.400; FY05/06 Cured Correct Major Maintenance Total: \$1.400; FY01/02 M00005 Lipgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4 \$1.400; 22 8 FY01/02 M00006 Repair/Replace Socurity Systems, Ph 3 of 4 \$1.460; </td <td>18</td> <td>8</td> <td>FY01/02</td> <td>M90001</td> <td>Infrastructure Repair/Replacement, Ph 3 of 4</td> <td>\$1,143,300</td> | 18 | 8 | FY01/02 | M90001 | Infrastructure Repair/Replacement, Ph 3 of 4 | \$1,143,300 | | | | |
| FY0203 Correct Accessibility Problems on the Fairgrounds, Ph 2 of 4 \$275, FY0203 FY0203 Electrical Infrastructure Repair/Replacement, Ph 2 of 2 \$993, \$15, FY0304 Correct Accessibility Problems on the Fairgrounds, Ph 3 of 4 \$275, FY0304 Repair/Replace Rod on 5 Buildings, Ph 2 of 2 \$875, FY0304 FY0304 Repair/Replace Rod on 5 Buildings, Ph 2 of 2 \$875, FY0304 Repair Foode Facilities, Ph 1 of 1 \$1,420, S775, FY0405 FY0405 Correct Accessibility Problems on the Fairgrounds, Ph 4 of 4 \$275, FY0306 \$704005 Repair Evestock Pavilion, Ph 1 of 1 \$1,400, FY04005 \$8660, FY04005 \$1400, FY05/06 Outdoor Stage Replacement, Ph 1 of 1 \$13,000, FY05/06 \$1400, Outdoor Stage Replacement, Ph 1 of 1 \$14,000, S1,900, Agency Reported Controlled Maintenance Total: \$13,900, Agency Reported Controlled Maintenance Total: \$13,900, Agency Reported Controlled Maintenance Total: \$14,001, \$19,000, Agency Reported Controlled Maintenance Total: \$14,040, \$14,040, \$19,000 2 8 FY01/02 M90005 Uggrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4 \$1,440, \$1,464, \$1 | 42 | 12 | FY01/02 | | Correct Accessibility Problems on the Fairgrounds, Ph 1 of 4 | \$275,000 | | | | |
| FY02/03 Electrical Infrastructure Repair/Replacement, Ph 2 of 2 \$9933, FY02/03 M90001 Infrastructure Repair/Replacement, Ph 4 of 4 \$1,442, FY03/04 Correct Accessibility Problems on the Fairgrounds, Ph 3 of 4 \$2755, FY03/04 Repair/Replace Roof on 5 Buildings, Ph 2 of 2 \$8750, FY04/05 Correct Accessibility Problems on the Fairgrounds, Ph 4 of 4 \$2751, FY04/05 Repaire Chood Faoilities, Ph 1 of 1 \$6800, FY04/05 Repair Evodor Faoilities, Ph 1 of 1 \$350, FY04/05 Repair Evodor Stage Replacement, Ph 1 of 1 \$3100, FY05/06 Event Center Parking Lot Improvements, Ph 1 of 1 \$1,400, DOAg-CSF 5 Year Plan Project Request Total: \$11,716, Estimated Long Term Infrastructure Major Maintenance Total: \$13,930, Lestimated Long Term Infrastructure Major Maintenance Total: \$11,440,0 2 8 FY01/02 M00006 Repair/Replace Security Systems, Ph 3 of 4 \$1,444,43 12 FY01/02 M00006 Repair/Replace Security Systems, Ph 3 of 4 \$1,444,43 12 FY01/02 M00006 Repair/Repl | | | FY01/02 | | Electrical Infrastructure Repair/Replacement, Ph 1 of 2 | \$1,012,769 | | | | |
| FY02/03 M90001 Infrastructure Replair/Replacement, Ph 4 of 4 \$1,442, FY03/04 Correct Accessibility Problems on the Fairgrounds, Ph 3 of 4 \$275, FY03/04 Replace HVAC in Place of Agriculture, Ph 1 of 1 \$12,00, FY04/05 Correct Accessibility Problems on the Fairgrounds, Ph 4 of 4 \$275, FY04/05 Correct Accessibility Problems on the Fairgrounds, Ph 4 of 4 \$275, FY04/05 Repair Food Facilities, Ph 1 of 1 \$560, FY05/06 Event Center Parking Lot Improvements, Ph 1 of 1 \$350, FY05/06 Outdoor Stage Replacement, Ph 1 of 1 \$340, DVAg-CSF 5 Year Plan Project Request Total: \$11,716, Estimated Long Term Building Major Maintenance Total: \$13,900, A 3 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4 \$1,464, 22 8 FY01/02 M00006 Repair/Replace Security Systems, Ph 2 of 4 \$13,464, 3 FY01/02 M00006 Repair/Replace Security Systems, Ph 3 of 4 \$1,464, 318 FY01/02 M00006 Repair/Replace Vact \$1246, <t< td=""><td></td><td></td><td>FY02/03</td><td></td><td>Correct Accessibility Problems on the Fairgrounds, Ph 2 of 4</td><td>\$275,000</td></t<> | | | FY02/03 | | Correct Accessibility Problems on the Fairgrounds, Ph 2 of 4 | \$275,000 | | | | |
| FY03/04 Correct Accessibility Problems on the Fairgrounds, Ph 3 of 4 \$275, FY03/04 Repair/Replace Roof on 5 Buildings, Ph 2 of 2 \$876, FY03/04 Repair/Replace HVAC in Place of Agriculture, Ph 1 of 1 \$1,200, FY04/05 FY04/05 Correct Accessibility Problems on the Fairgrounds, Ph 4 of 4 \$275, FY04/05 \$760, Repair Food Facilities, Ph 1 of 1 \$560, FY04/05 FY04/05 Repair Food Facilities, Ph 1 of 1 \$560, FY04/05 \$860, FY05/06 \$500, Cutdoor Stage Replacement, Ph 1 of 1 \$14,00, FY05/06 FY05/06 Cutdoor Stage Replacement, Ph 1 of 1 \$11,716, Stamated Long Term Building Major Maintenance Total: \$13,900, S1,900, Agency Reported Controlled Maintenance Total: \$13,900, S1,900, Agency Reported Controlled Maintenance Total: \$11,900, S1,900, Agency Reported Controlled Maintenance Total: \$11,900, S1,9000, S1,9000, S1,9000, S1,9000, S1,9000, S1,9000, S1,9000, S1,9000, S1,90 | | | FY02/03 | | Electrical Infrastructure Repair/Replacement, Ph 2 of 2 | \$993,386 | | | | |
| FY03/04 Repair/Replace Roof on 5 Buildings, Ph 2 of 2 \$\$75,1 FY03/04 Replace HVAC in Place of Agriculture, Ph 1 of 1 \$\$1,200,1 FY04/05 Correct Accessibility Problems on the Fairgrounds, Ph 4 of 4 \$\$275,1 FY04/05 Repair Livestock Pavilion, Ph 1 of 1 \$\$500,1 FY04/05 Repair Livestock Pavilion, Ph 1 of 1 \$\$350,1 FY05/06 Event Center Parking Lot Improvements, Ph 1 of 1 \$\$350,1 FY05/06 Outdoor Stage Replacement, Ph 1 of 1 \$\$350,1 FY05/06 Outdoor Stage Replacement, Ph 1 of 1 \$\$300,1 DOAg-CSF 5 Year Plan Project Request Total: \$\$1,900,0 Agency Reported Controlled Maintenance Total: \$\$1,900,0 \$\$1,754, Agency Reported Controlled Maintenance Total: \$\$1,900,0 \$\$1,440,1 22 8 FY01/02 M00006 Repair/Replace Security Systems, Ph 2 of 4 \$\$1440,1 31 12 FY01/02 M00006 Repair/Replace Security Systems, Ph 2 of 4 \$\$148,4 31 8 FY01/02 M00007 Replace Boiler Refractory, Ph 1 of 1 \$\$108,1 30 1 FY01/02 M00007 | | | FY02/03 | M90001 | Infrastructure Repair/Replacement, Ph 4 of 4 | \$1,442,000 | | | | |
| FY03/04 Replace HVACs (in Place of Agriculture, Ph 1 of 1 \$1,200, FY04/05 Correct Accessibility Problems on the Fairgrounds, Ph 4 of 4 \$275, FY04/05 Repair Food Facilities, Ph 1 of 1 \$600, FY04/05 Repair Livestock Pavilion, Ph 1 of 1 \$600, FY05/06 Event Center Parking Lot Improvements, Ph 1 of 1 \$100, FY05/06 Outdoor Stage Replacement, Ph 1 of 1 \$1400, FY05/06 Outdoor Stage Replacement, Ph 1 of 1 \$1400, DOAg-CSF 5 Year Plan Project Request Total: \$13,930, Agency Reported Controlled Maintenance Total: \$1,900, Agency Reported Controlled Maintenance Total: \$1,900, 2 8 FY01/02 M90005 Uggrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4 \$1,440, 3 12 FY01/02 M90006 Repair/Replace Security Systems, Ph 2 of 4 \$338, 3 8 FY01/02 M00006 Repair/Replace Security Systems, Ph 3 of 4 \$148, 4 18 FY01/02 N00000 Repair/Replace Security Systems, Ph 3 of 4 \$100, 2 FY01/02 M000000 Repair/Replace Moot Pint ont 1 | | | FY03/04 | | Correct Accessibility Problems on the Fairgrounds, Ph 3 of 4 | \$275,000 | | | | |
| FV04/05 Correct Accessibility Problems on the Fairgrounds, Ph 4 of 4 \$2750, FY04/05 Repair Food Facilities, Ph 1 of 1 \$350, FY04/05 FV04/05 Repair Food Facilities, Ph 1 of 1 \$350, FY05/06 \$450, FY05/06 \$450, FY05/06 FY05/06 Event Center Parking Lot Improvements, Ph 1 of 1 \$300, FY05/06 \$11,716, Estimated Long Term Building Major Maintenance Total: \$3,338, F190, F19 | | | FY03/04 | | Repair/Replace Roof on 5 Buildings, Ph 2 of 2 | \$875,000 | | | | |
| FY04/05Horse Stall Improvements, Ph 1 of 1\$750,FY04/05Repair Food Facilities, Ph 1 of 1\$350,FY04/05Repair Livestock Pavilion, Ph 1 of 1\$350,FY05/06Event Center Parking Lot Improvements, Ph 1 of 1\$800,FY05/06Event Center Parking Lot Improvements, Ph 1 of 1\$800,FY05/06Outdoor Stage Replacement, Ph 1 of 1\$1,400,FY05/06Event Center Parking Lot Improvements, Ph 1 of 1\$1,400,FY05/06DOAg-CSF5 Year Plan Project Request Total:\$1,900,Listimated Long Term Infrastructure Major Maintenance Total:\$1,900,\$1,755,Department of CorrectionsEstimated Long Term Infrastructure Major Maintenance Total:\$1,440,28 FY01/02M90005Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4\$1,440,312 FY01/02M90006Repair/Replace Security Systems, Ph 2 of 4\$338,312 FY01/02M00006Repair/Replace Security Systems, Ph 3 of 4\$10,240,318 FY01/02M00006Repair/Replace Water Treatment and Piping Systems, Ph 2 of 4\$305,1028 FY01/02Repair/Replace Water Treatment and Piping Systems, Ph 1 of 1\$368,11028 FY01/02Repair/Replace Water Treatment and Piping Systems, Ph 1 of 1\$3245,12932 FY01/02Repair/Replace Roofs, Ph 3 of 4\$345,12032 FY01/02Repair/Replace Roofs, Ph 3 of 4\$345,12132 FY01/02Window Replacement, Ph 1 of 1\$224,12335 FY01/02 | | | FY03/04 | | Replace HVAC in Place of Agriculture, Ph 1 of 1 | \$1,200,000 | | | | |
| FY04/05 Repair Food Facilities, Ph 1 of 1 \$650, FY05/06 Event Center Parking Lot Improvements, Ph 1 of 1 \$3800, FY05/06 Event Center Parking Lot Improvements, Ph 1 of 1 \$1,400, DOAg-CSF 5 Year Plan Project Request Total: \$1,17,16, Estimated Long Term Building Major Maintenance Total: \$3,938, Estimated Long Term Infrastructure Major Maintenance Total: \$1,900, Agency Reported Controlled Maintenance Total: \$1,900, 2 8 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4 \$1,440,4 2 8 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 4 of 4 \$1,440,4 3 12 FY01/02 M90005 Repair/Replace Security Systems, Ph 2 of 4 \$1,246,4 3 18 FY01/02 M90009 Repair/Replace Security Systems, Ph 3 of 4 \$1,246,4 9 14 FY01/02 M90007 Repair/Replace Security Systems, Ph 3 of 4 \$348,7 102 24 FY01/02 Repair/Replace Neofs, Ph 3 of 4 \$345,1 102 24 FY01/02 Repair/Replace Rofs, Ph 3 of 4 \$345,1 | | | FY04/05 | | Correct Accessibility Problems on the Fairgrounds, Ph 4 of 4 | \$275,000 | | | | |
| FY04/05 Repair Livestock Pavilion, Ph 1 of 1 \$350, FY05/06 Event Center Parking Lot Improvements, Ph 1 of 1 \$400, FY05/06 Outdoor Stage Replacement, Ph 1 of 1 \$14,716, BOAg-CSF 5 Year Plan Project Request Total: \$11,716, Listimated Long Term Building Major Maintenance Total: \$13,900, Agency Reported Controlled Maintenance Total: \$17,554, Pepartment Corrections \$14,716, 2 8 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4 \$1,440,1 2 8 FY01/02 M90006 Repair/Replace Security Systems, Ph 2 of 4 \$538,8 3 12 FY01/02 M00006 Repair/Replace Security Systems, Ph 3 of 4 \$1,246,4 3 14 FY01/02 M00007 Replace Security Systems, Ph 3 of 4 \$108,10 3 14 FY01/02 M00007 Replace Bolier Refractory, Ph 1 of 1 \$308,1 3 14 Y01/02 M80007 Replace Mochanical/Plumbing Systems, Ph 1 of 1 \$345,102 3 18 FY01/02 Melace Bolier Refractory, Ph 1 of 1 \$345,1104 \$345,1104 <td></td> <td></td> <td>FY04/05</td> <td></td> <td>Horse Stall Improvements, Ph 1 of 1</td> <td>\$750,000</td> | | | FY04/05 | | Horse Stall Improvements, Ph 1 of 1 | \$750,000 | | | | |
| FY05/06Event Center Parking Lot Improvements, Ph 1 of 1\$800,FY05/06Outdoor Stage Replacement, Ph 1 of 1\$1,400,DOAg-CSF5 Year Plan Project Request Total:\$1,400,Estimated Long Term Building Major Maintenance Total:\$3,338,Stear Plan Project Request Total:\$1,7554,Department of Corrections43 FY01/02M90005Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4\$1,464,228 FY01/02M90005Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4\$1,464,3812 FY01/02M00006Repair/Replace Security Systems, Ph 3 of 4\$1,464,3914 FY01/02M00006Repair/Replace Security Systems, Ph 3 of 4\$348,4914 FY01/02M00006Repair/Replace Security Systems, Ph 3 of 4\$1,246,5021 FY01/02Replace Boiler Refractory, Ph 1 of 1\$108,9021 FY01/02Replace Boiler Refractory, Ph 1 of 1\$108,9021 FY01/02Repair/Replace Water Treatment and Piping Systems, Ph 1 of 1\$368,11028 FY01/02Replace Mechanical/Plumbing Systems, Ph 1 of 2\$242,13536 FY01/02South Pump House and Water Distribution System Improvements, Ph 1 of 1\$258,14242 FY01/02Window Replacement, Ph 1 of 1\$242,15536 FY01/02South Pump House and Water Distribution System Improvements, Ph 1 of 1\$258,14242 FY01/02Window Replacement, Ph 1 of 1\$252, <t< td=""><td></td><td></td><td>FY04/05</td><td></td><td>Repair Food Facilities, Ph 1 of 1</td><td>\$650,000</td></t<> | | | FY04/05 | | Repair Food Facilities, Ph 1 of 1 | \$650,000 | | | | |
| FY05/06Outdoor Stage Replacement, Ph 1 of 1\$1,400,4DOAg-CSF5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Bagency Reported Controlled Maintenance Total: Capency Reported Controlled Maintenance Total: Standard Reported Controlled Maintenance Total: Standard Reported Controlled Maintenance Total:\$1,900,428FV01/02M90005Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4\$1,440,4228FV01/02M90006Upgrade Fire Detection/Alarm/Suppression Systems, Ph 4 of 4\$1,464,43812FV01/02M90009Repair/Replace Security Systems, Ph 3 of 4\$1,464,643914FV01/02M90009Repair/Replace Security Systems, Ph 3 of 4\$338,644014FV01/02M90009Repair/Replace Security Systems, Ph 3 of 4\$338,645021FV01/02Repair/Replace Security Systems, Ph 3 of 4\$308,615022FV01/02M80027Replace Roids, Ph 3 of 4\$308,6151028FV01/02Replace Mechanical/Plumbing Systems, Ph 1 of 1\$368,6151028FV01/02Replace Mechanical/Plumbing Systems, Ph 1 of 2\$242,2251336FV01/02South Pump House and Water Distribution System Improvements, Ph 1 of 1\$368,72,1451442FV01/02Window Replacement, Ph 1 of 1\$258,73,750,750,750,750,750,750,750,750,750,750 | | | FY04/05 | | Repair Livestock Pavilion, Ph 1 of 1 | \$350,000 | | | | |
| DOAg-CSF5 Year Plan Project Request Total:\$11,716, \$3,938, \$3,938, Estimated Long Term Building Major Maintenance Total:\$3,938, \$3,938, \$1,900, \$11,554,Department of CorrectionsEstimated Long Term Infrastructure Major Maintenance Total:\$1,900, \$17,554,Department of CorrectionsUpgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4\$1,440, \$1,464,28 FY01/02M90005Upgrade Fire Detection/Alarm/Suppression Systems, Ph 4 of 4\$1,464, \$1,464,3812 FY01/02M90009Repair/Replace Security Systems, Ph 2 of 4\$538, \$1,246,418 FY01/02M90009Repair/Replace Security Systems, Ph 3 of 4\$1,246, \$1,246,418 FY01/02M00006Repair/Replace Security Systems, Ph 3 of 4\$1,246, \$1,246,418 FY01/02M00007Repair/Replace Security Systems, Ph 3 of 4\$1,246, \$1,246,1021 FY01/02Replace Boiler Refractory, Ph 1 of 1\$108, \$102,24\$1,246, \$100007\$30142024 FY01/02Replace Mather Treatment and Piping Systems, Ph 2 of 4\$338, \$336, \$102,24\$242,2311028 FY01/02Replace Machanical/Plumbing Systems, Ph 1 of 1\$242,2312932 FY01/02Replace Machanical/Plumbing Systems, Ph 1 of 2\$242,2312932 FY01/02Replace Machanical/Plumbing Systems, Ph 1 of 4\$258,17120Yi02/03Chilled Water System Replacement, Ph 1 of 4\$258,17120Yi02/03Chilled Water System Replacement, Ph 1 of 4\$258,17142 <td></td> <td></td> <td>FY05/06</td> <td></td> <td>Event Center Parking Lot Improvements, Ph 1 of 1</td> <td>\$800,000</td> | | | FY05/06 | | Event Center Parking Lot Improvements, Ph 1 of 1 | \$800,000 | | | | |
| Estimated Long Term Building Major Maintenance Total:\$3,938, \$1,900, \$11,554,Department of Corrections43FY01/02M90005Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4\$1,440,1228FY01/02M90005Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4\$1,440,43812FY01/02M90006Repair/Replace Security Systems, Ph 2 of 4\$538,14914FY01/02M90006Repair/Replace Security Systems, Ph 3 of 4\$408,17318FY01/02M90007Replace Security Systems, Ph 3 of 4\$408,19021FY01/02Replace Boiler Refractory, Ph 1 of 1\$108,19021FY01/02Replar/Replace Roofs, Ph 3 of 4\$402,112024FY01/02Replar/Replace Roofs, Ph 3 of 4\$345,112028FY01/02Replar/Replace Roofs, Ph 3 of 4\$345,112128FY01/02Replar/Replace Roofs, Ph 3 of 4\$345,112224FY01/02Replar/Replace Roofs, Ph 3 of 4\$345,112336FY01/02Replar/Replace Roofs, Ph 3 of 4\$345,112442FY01/02Window Replacement, Ph 1 of 1\$345,112442FY01/02Window Replacement, Ph 1 of 1\$272,1FY02/03Chilled Water System Replacement, Ph 1 of 4\$67,1FY02/03Direct Exchange Units, Ph 1 of 1\$72,1FY02/03Main Floor Covering, Ph 1 of 1\$40,1FY02/03< | | | FY05/06 | | Outdoor Stage Replacement, Ph 1 of 1 | \$1,400,000 | | | | |
| Estimated Long Term Infrastructure Major Maintenance Total: \$1,900, \$17,554, Department of Corrections | | | | | DOAg-CSF 5 Year Plan Project Request Total: | \$11,716,455 | | | | |
| Agency Reported Controlled Maintenance Total: \$17,554, Department of Corrections 4 3 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4 \$1,440,1 22 8 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 4 of 4 \$1,464,1 38 12 FY01/02 M00006 Repair/Replace Security Systems, Ph 2 of 4 \$538,1 49 14 FY01/02 M00007 Repair/Replace Security Systems, Ph 3 of 4 \$408,6 73 18 FY01/02 M00007 Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 2 of 4 \$395,7 102 24 FY01/02 M80027 Repair/Replace Roofs, Ph 3 of 4 \$345,5 110 28 FY01/02 Repair/Replace Roofs, Ph 3 of 4 \$355,1 129 32 FY01/02 M80027 Repair/Replace Roofs, Ph 3 of 4 \$356,1 129 32 FY01/02 M80027 Repair/Replace Mothanical/Plumbing Systems, Ph 1 of 2 \$242,2 135 36 FY01/02 Window Replacement, Ph 1 of 1 \$258,6 < | | | | | Estimated Long Term Building Major Maintenance Total: | \$3,938,000 | | | | |
| Department of Corrections 4 3 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4 \$1,440,1 2 8 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 4 of 4 \$1,444,3 38 12 FY01/02 M00006 Repair/Replace Security Systems, Ph 2 of 4 \$538,4 49 14 FY01/02 M90009 Repair/Replace Security Systems, Ph 3 of 4 \$408,6 73 18 FY01/02 M90007 Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 2 of 4 \$395,1 90 21 FY01/02 M80027 Repiair/Replace Water Treatment and Piping Systems, Ph 1 of 1 \$368,1 10 28 FY01/02 M80022 Repiar/Replace Modes, Ph 3 of 4 \$345,5 110 28 FY01/02 M80022 Replace Mechanical/Plumbing Systems, Ph 1 of 1 \$368,1 10 28 FY01/02 Mindow Replacement, Ph 1 of 1 \$212,2 135 36 FY01/02 Window Replacement, Ph 1 of 1 \$212,1 142 42 FY01/ | | | | | | \$1,900,000 | | | | |
| 4 3 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4 \$1,440,422 8 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 4 of 4 \$14,64,433 12 FY01/02 M90009 Repair/Replace Security Systems, Ph 2 of 4 \$538,493 41 FY01/02 M90009 Repair/Replace Security Systems, Ph 3 of 4 \$408,408,473 18 FY01/02 M90007 Repair/Replace Security Systems, Ph 3 of 4 \$408,408,408,408,408,408,408,408,408,408, | | | | | Agency Reported Controlled Maintenance Total: | \$17,554,455 | | | | |
| 4 3 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4 \$1,440,4 22 8 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 4 of 4 \$14,64,4 38 12 FY01/02 M90009 Repair/Replace Security Systems, Ph 2 of 4 \$538, 41 FY01/02 M90006 Repair/Replace Security Systems, Ph 3 of 4 \$408, 73 18 FY01/02 M90007 Repair/Replace Security Systems, Ph 3 of 4 \$408, 73 18 FY01/02 M90007 Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 2 of 4 \$395, 102 24 FY01/02 Repair/Replace Water Treatment and Piping Systems, Ph 1 of 1 \$368, 110 28 FY01/02 Repair/Replace Moofs, Ph 3 of 4 \$345, 129 32 FY01/02 Replace Mechanical/Plumbing Systems, Ph 1 of 2 \$242, 135 36 FY01/02 Window Replacement, Ph 1 of 1 \$219, FY02/03 Correct Water Damage and Drainage, PMC, Ph 1 of 4 \$258, FY02/03 M90003 <td>Depa</td> <td>artment</td> <td>of Correct</td> <td>tions</td> <td></td> <td></td> | Depa | artment | of Correct | tions | | | | | | |
| 22 8 FY01/02 M90005 Upgrade Fire Detection/Alarm/Suppression Systems, Ph 4 of 4 \$1,464,3 38 12 FY01/02 M00006 Repair/Replace Security Systems, Ph 2 of 4 \$538,4 49 14 FY01/02 M00006 Repair/Replace Security Systems, Ph 3 of 4 \$408,7 73 18 FY01/02 M00007 Repair/Replace Security Systems, Ph 3 of 4 \$408,7 90 21 FY01/02 M90007 Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 2 of 4 \$3395,7 102 24 FY01/02 M90007 Repair/Replace Roofs, Ph 3 of 4 \$345,7 103 28 FY01/02 M80022 Repair/Replace Roofs, Ph 3 of 4 \$345,1 112 32 FY01/02 M80022 Repair/Replace Moothania (Plumbing Systems, Ph 1 of 1 \$345,1 123 36 FY01/02 Window Replacement, Ph 1 of 1 \$242,2 142 42 FY01/02 Window Replacement, Ph 1 of 1 \$219,1 FY02/03 Correct Water Damage and Drainage, PMC, Ph 1 of 4 \$258,1 FY02/03< | - | | | | Upgrade Fire Detection/Alarm/Suppression Systems, Ph 3 of 4 | \$1,440,698 | | | | |
| 38 12 FY01/02 M00006 Repair/Replace Security Systems, Ph 2 of 4 \$538, 49 14 FY01/02 M00008 Repair Utility Tunnel, Ph 2 of 2 \$1,246, 64 18 FY01/02 M00006 Repair/Replace Security Systems, Ph 3 of 4 \$408, 73 18 FY01/02 Replace Boiler Refractory, Ph 1 of 1 \$108, 90 21 FY01/02 M00007 Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 2 of 4 \$395, 102 24 FY01/02 Repair/Replace Water Treatment and Piping Systems, Ph 1 of 1 \$368, 110 28 FY01/02 Replace Mechanical/Plumbing Systems, Ph 1 of 2 \$242, 125 36 FY01/02 Replace Mechanical/Plumbing Systems, Ph 1 of 1 \$258, 142 42 FY01/02 Window Replacement, Ph 1 of 1 \$219, FY02/03 Correct Water Damage and Drainage, PMC, Ph 1 of 4 \$258, FY02/03 Direct Exchange Units, Ph 1 of 1 \$763, FY02/03 M00001 Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 1 of 4 \$383, | | | | | | \$1,464,592 | | | | |
| 49 14 FY01/02 M90009 Repair Utility Tunnel, Ph 2 of 2 \$1,246,3 64 18 FY01/02 M00006 Repair/Replace Security Systems, Ph 3 of 4 \$408,7 73 18 FY01/02 M90007 Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 2 of 4 \$395,1 102 24 FY01/02 Repair/Replace Water Treatment and Piping Systems, Ph 1 of 1 \$368,1 102 28 FY01/02 Repair/Replace Mochanical/Plumbing Systems, Ph 1 of 1 \$345,1 129 32 FY01/02 Replace Mechanical/Plumbing Systems, Ph 1 of 2 \$242,1 135 36 FY01/02 Keplace Mechanical/Plumbing Systems, Ph 1 of 4 \$258,1 142 42 FY01/02 Window Replacement, Ph 1 of 1 \$219,1 FY02/03 Correct Water Damage and Drainage, PMC, Ph 1 of 4 \$258,1 FY02/03 Direct Exchange Units, Ph 1 of 1 \$72,1 FY02/03 Direct Exchange Units, Ph 1 of 1 \$72,1 FY02/03 Main Floor Covering, Ph 1 of 1 \$72,1 FY02/03 Main Floor Covering, Ph 1 of 1 \$72,1 FY02/03 Paving and Resurfacing - FCC, DCC, Ph 1 of 2 | 38 | 12 | FY01/02 | | | \$538,679 | | | | |
| 64 18 FY01/02 M00006 Repia/Replace Security Systems, Ph 3 of 4 \$408, 73 18 FY01/02 Replace Boiler Refractory, Ph 1 of 1 \$108, 90 21 FY01/02 M90007 Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 2 of 4 \$3395, 102 24 FY01/02 Repair/Replace Water Treatment and Piping Systems, Ph 1 of 1 \$368, 110 28 FY01/02 Replace Mechanical/Plumbing Systems, Ph 1 of 1 \$345, 129 32 FY01/02 Replace Mechanical/Plumbing Systems, Ph 1 of 2 \$242, 135 36 FY01/02 South Pump House and Water Distribution System Improvements, Ph 1 of 1 \$258, 142 42 FY01/02 Window Replacement, Ph 1 of 1 \$219, FY02/03 Correct Water Damage and Drainage, PMC, Ph 1 of 4 \$258, FY02/03 Direct Exchange Units, Ph 1 of 1 \$72, FY02/03 M90003 Electrical Improvements, Ph 2 of 3 \$763, FY02/03 Main Floor Covering, Ph 1 of 1 \$40, \$700, FY02/03 Paving-CMC, AVCF, CSP, | | | | | | \$1,246,228 | | | | |
| 7318FY01/02Replace Boiler Refractory, Ph 1 of 1\$108,9021FY01/02M90007Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 2 of 4\$395,10224FY01/02Repair/Replace Water Treatment and Piping Systems, Ph 1 of 1\$368,11028FY01/02Repair/Replace Roofs, Ph 3 of 4\$345,12932FY01/02Replace Mechanical/Plumbing Systems, Ph 1 of 2\$242,13536FY01/02South Pump House and Water Distribution System Improvements, Ph 1 of 1\$585,14242FY01/02Window Replacement, Ph 1 of 1\$219,FY02/03Chilled Water System Replacement, Ph 1 of 4\$258,FY02/03Correct Water Damage and Drainage, PMC, Ph 1 of 4\$67,FY02/03Direct Exchange Units, Ph 1 of 1\$72,FY02/03Main Floor Covering, Ph 1 of 1\$40,FY02/03Paving and Resurfacing - FCC, DCC, Ph 1 of 2\$750,FY02/03Paving and Resurfacing - FCC, DCC, Ph 1 of 4\$383,FY02/03Paving Perimeter Walls, Ph 1 of 2\$233,FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528,FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$1,799,FY02/03Repair/Replace Roofs | 64 | 18 | FY01/02 | M00006 | | \$408,548 | | | | |
| 90 21 FY01/02 M90007 Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 2 of 4 \$395, 102 24 FY01/02 Repair/Replace Water Treatment and Piping Systems, Ph 1 of 1 \$368, 110 28 FY01/02 Repair/Replace Roofs, Ph 3 of 4 \$345, 129 32 FY01/02 Replace Mechanical/Plumbing Systems, Ph 1 of 2 \$242, 135 36 FY01/02 Window Replacement, Ph 1 of 1 \$585, 142 42 FY01/02 Window Replacement, Ph 1 of 1 \$219, FY02/03 Chilled Water System Replacement, Ph 1 of 4 \$272, FY02/03 Correct Water Damage and Drainage, PMC, Ph 1 of 4 \$67, FY02/03 Direct Exchange Units, Ph 1 of 1 \$722, FY02/03 M90003 Electrical Improvements, Ph 2 of 3 \$763, FY02/03 Main Floor Covering, Ph 1 of 1 \$40, \$702, FY02/03 Paving and Resurfacing - FCC, DCC, Ph 1 of 2 \$750, FY02/03 Paving ender ender Walls, Ph 1 of 1 \$343, FY02/03 Paving ender enderadenent, Ph 2 of 3 | 73 | 18 | FY01/02 | | | \$108,051 | | | | |
| 102 24 FY01/02 Repair/Replace Water Treatment and Piping Systems, Ph 1 of 1 \$368, 110 28 FY01/02 M80022 Repair/Replace Roofs, Ph 3 of 4 \$345, 129 32 FY01/02 Replace Mechanical/Plumbing Systems, Ph 1 of 2 \$242, 135 36 FY01/02 South Pump House and Water Distribution System Improvements, Ph 1 of 1 \$585, 142 42 FY01/02 Window Replacement, Ph 1 of 1 \$219, FY02/03 Correct Water Damage and Drainage, PMC, Ph 1 of 4 \$67,4 FY02/03 Correct Water Damage and Drainage, PMC, Ph 1 of 4 \$67,4 FY02/03 Direct Exchange Units, Ph 1 of 1 \$72,5 FY02/03 M90003 Electrical Improvements, Ph 2 of 3 \$763,6 FY02/03 Main Floor Covering, Ph 1 of 1 \$40, FY02/03 Paving and Resurfacing - FCC, DCC, Ph 1 of 2 \$750, FY02/03 Paving and Resurfacing - FCC, DCC, Ph 1 of 4 \$383, FY02/03 N00012 Phased Power System Replacement, Ph 2 of 3 \$343, FY02/03 Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1 \$528,4 FY02/03 Repair/Replace Asphalt Pav | 90 | 21 | FY01/02 | M90007 | | \$395,950 | | | | |
| 129 32 FY01/02 Replace Mechanical/Plumbing Systems, Ph 1 of 2 \$242, 135 36 FY01/02 South Pump House and Water Distribution System Improvements, Ph 1 of 1 \$585, 142 42 FY01/02 Window Replacement, Ph 1 of 1 \$219, FY02/03 Chilled Water System Replacement, Ph 1 of 4 \$258, FY02/03 Correct Water Damage and Drainage, PMC, Ph 1 of 4 \$67, FY02/03 Direct Exchange Units, Ph 1 of 1 \$72, FY02/03 M90003 Electrical Improvements, Ph 2 of 3 \$763, FY02/03 Main Floor Covering, Ph 1 of 1 \$40, FY02/03 Paving and Resurfacing - FCC, DCC, Ph 1 of 2 \$750, FY02/03 Paving and Resurfacing - FCC, DCC, Ph 1 of 4 \$383, FY02/03 Paving Perimeter Walls, Ph 1 of 2 \$750, FY02/03 Pointing Perimeter Walls, Ph 1 of 2 \$233, FY02/03 Pointing Perimeter Walls, Ph 1 of 2 \$233, FY02/03 Repair/Replace Asphalt Paving at BVCF, Ph 1 of 3 \$1,799, FY02/03 Repair/Replace Roofs at BVCF, Ph 1 of 3 \$1,799, FY02/03 Repair/Replace Roofs at BVCF, Ph 1 of 3 \$416, </td <td>102</td> <td>24</td> <td>FY01/02</td> <td></td> <td></td> <td>\$368,648</td> | 102 | 24 | FY01/02 | | | \$368,648 | | | | |
| 13536FY01/02South Pump House and Water Distribution System Improvements, Ph 1 of 1\$585,14242FY01/02Window Replacement, Ph 1 of 1\$219,FY02/03Chilled Water System Replacement, Ph 1 of 4\$258,FY02/03Correct Water Damage and Drainage, PMC, Ph 1 of 4\$67,FY02/03Direct Exchange Units, Ph 1 of 1\$72,FY02/03M90003Electrical Improvements, Ph 2 of 3\$763,FY02/03Main Floor Covering, Ph 1 of 1\$40,FY02/03Paving and Resurfacing - FCC, DCC, Ph 1 of 2\$750,FY02/03Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 1 of 4\$383,FY02/03Phased Power System Replacement, Ph 2 of 3\$343,FY02/03Pointing Perimeter Walls, Ph 1 of 2\$233,FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528,FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$1,799,FY02/03M80022Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,FY02/03M00006Repair/Replace Roofs, Ph 4 of 4\$135,FY02/03M00006Repair/Replace Security Systems, Ph 2 of 2\$255, | 110 | 28 | FY01/02 | M80022 | Repair/Replace Roofs, Ph 3 of 4 | \$345,540 | | | | |
| 14242FY01/02Window Replacement, Ph 1 of 1\$219,FY02/03Chilled Water System Replacement, Ph 1 of 4\$258,FY02/03Correct Water Damage and Drainage, PMC, Ph 1 of 4\$67,FY02/03Direct Exchange Units, Ph 1 of 1\$72,FY02/03M90003Electrical Improvements, Ph 2 of 3\$763,FY02/03Main Floor Covering, Ph 1 of 1\$40,FY02/03Paving and Resurfacing - FCC, DCC, Ph 1 of 2\$750,FY02/03Paving and Resurfacing - FCC, DCC, CF, SCC, Ph 1 of 4\$383,FY02/03M00012Phased Power System Replacement, Ph 2 of 3\$343,FY02/03Pointing Perimeter Walls, Ph 1 of 2\$233,FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528,FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$1,799,0FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,FY02/03Repair/Replace Roofs, Ph 4 of 4\$135,FY02/03Repair/Replace Roofs, Ph 4 of 4\$502,FY02/03Repair/Replace Security Systems, Ph 4 of 4\$502,FY02/03Replace Mechanical/Plumbing Systems, Ph 2 of 2\$255, | 129 | 32 | FY01/02 | | Replace Mechanical/Plumbing Systems, Ph 1 of 2 | \$242,770 | | | | |
| FY02/03Chilled Water System Replacement, Ph 1 of 4\$258,4FY02/03Correct Water Damage and Drainage, PMC, Ph 1 of 4\$67,4FY02/03Direct Exchange Units, Ph 1 of 1\$72,4FY02/03M90003Electrical Improvements, Ph 2 of 3\$763,4FY02/03Main Floor Covering, Ph 1 of 1\$40,7FY02/03Paving and Resurfacing - FCC, DCC, Ph 1 of 2\$750,7FY02/03Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 1 of 4\$383,7FY02/03Pointing Perimeter Walls, Ph 1 of 2\$233,1FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528,1FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$1,799,0FY02/03M80022Repair/Replace Roofs, Ph 4 of 4\$135,7FY02/03M00006Repair/Replace Roofs, Ph 4 of 4\$502,7FY02/03Repair/Replace Security Systems, Ph 2 of 2\$255,5 | 135 | 36 | FY01/02 | | South Pump House and Water Distribution System Improvements, Ph 1 of 1 | \$585,300 | | | | |
| FY02/03Correct Water Damage and Drainage, PMC, Ph 1 of 4\$67,4FY02/03Direct Exchange Units, Ph 1 of 1\$72,4FY02/03M90003Electrical Improvements, Ph 2 of 3\$763,4FY02/03Main Floor Covering, Ph 1 of 1\$40,7FY02/03Paving and Resurfacing - FCC, DCC, Ph 1 of 2\$750,4FY02/03Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 1 of 4\$383,4FY02/03Pointing Perimeter Walls, Ph 1 of 2\$233,4FY02/03Pointing Perimeter Walls, Ph 1 of 2\$233,4FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528,4FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$1,799,4FY02/03M80022Repair/Replace Roofs, Ph 4 of 4\$135,5FY02/03M00006Repair/Replace Security Systems, Ph 4 of 4\$502,4FY02/03Repair/Replace Security Systems, Ph 2 of 2\$255,4 | 142 | 42 | FY01/02 | | Window Replacement, Ph 1 of 1 | \$219,688 | | | | |
| FY02/03Direct Exchange Units, Ph 1 of 1\$72,5FY02/03M90003Electrical Improvements, Ph 2 of 3\$763,1FY02/03Main Floor Covering, Ph 1 of 1\$40,1FY02/03Paving and Resurfacing - FCC, DCC, Ph 1 of 2\$750,1FY02/03Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 1 of 4\$383,1FY02/03M00012Phased Power System Replacement, Ph 2 of 3\$343,3FY02/03Pointing Perimeter Walls, Ph 1 of 2\$233,1FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528,1FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$1,799,0FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,1FY02/03M80022Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,2FY02/03M80020Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,2FY02/03M00006Repair/Replace Roofs, Ph 4 of 4\$502,2FY02/03M00006Repair/Replace Security Systems, Ph 2 of 2\$255,5 | | | FY02/03 | | Chilled Water System Replacement, Ph 1 of 4 | \$258,000 | | | | |
| FY02/03M90003Electrical Improvements, Ph 2 of 3\$763,1FY02/03Main Floor Covering, Ph 1 of 1\$40,7FY02/03Paving and Resurfacing - FCC, DCC, Ph 1 of 2\$750,0FY02/03Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 1 of 4\$383,1FY02/03M00012Phased Power System Replacement, Ph 2 of 3\$343,2FY02/03Pointing Perimeter Walls, Ph 1 of 2\$233,1FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528,0FY02/03Repair/Replace Fire Life Safety Systems, Ph 1 of 3\$1,799,0FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,3FY02/03Repair/Replace Roofs, Ph 4 of 4\$135,5FY02/03M00006Repair/Replace Security Systems, Ph 2 of 2\$255,5 | | | FY02/03 | | Correct Water Damage and Drainage, PMC, Ph 1 of 4 | \$67,000 | | | | |
| FY02/03Main Floor Covering, Ph 1 of 1\$40,FY02/03Paving and Resurfacing - FCC, DCC, Ph 1 of 2\$750,FY02/03Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 1 of 4\$383,FY02/03M00012Phased Power System Replacement, Ph 2 of 3\$343,FY02/03Pointing Perimeter Walls, Ph 1 of 2\$233,FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528,FY02/03Repair/Replace Fire Life Safety Systems, Ph 1 of 3\$1,799,FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,FY02/03Repair/Replace Roofs, Ph 4 of 4\$135,FY02/03M00006Repair/Replace Security Systems, Ph 4 of 4\$502,FY02/03Repair/Replace Mechanical/Plumbing Systems, Ph 2 of 2\$255, | | | FY02/03 | | Direct Exchange Units, Ph 1 of 1 | \$72,512 | | | | |
| FY02/03Paving and Resurfacing - FCC, DCC, Ph 1 of 2\$750,FY02/03Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 1 of 4\$383,FY02/03M00012Phased Power System Replacement, Ph 2 of 3\$343,FY02/03Pointing Perimeter Walls, Ph 1 of 2\$233,FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528,FY02/03Repair/Replace Fire Life Safety Systems, Ph 1 of 3\$1,799,0FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$1416,5FY02/03Repair/Replace Roofs, Ph 4 of 4\$135,5FY02/03M00006Repair/Replace Security Systems, Ph 4 of 4\$502,5FY02/03Repair/Replace Mechanical/Plumbing Systems, Ph 2 of 2\$255,5 | | | FY02/03 | M90003 | Electrical Improvements, Ph 2 of 3 | \$763,000 | | | | |
| FY02/03Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 1 of 4\$383, 1FY02/03M00012Phased Power System Replacement, Ph 2 of 3\$343, 1FY02/03Pointing Perimeter Walls, Ph 1 of 2\$233, 1FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528, 1FY02/03Repair/Replace Fire Life Safety Systems, Ph 1 of 3\$1,799, 1FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$416, 3FY02/03Repair/Replace Roofs, Ph 4 of 4\$135, 5FY02/03M00006Repair/Replace Security Systems, Ph 4 of 4\$502, 4FY02/03Repair/Replace Mechanical/Plumbing Systems, Ph 2 of 2\$255, 5 | | | FY02/03 | | Main Floor Covering, Ph 1 of 1 | \$40,170 | | | | |
| FY02/03M00012Phased Power System Replacement, Ph 2 of 3\$343,5FY02/03Pointing Perimeter Walls, Ph 1 of 2\$233,1FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528,0FY02/03Repair/Replace Fire Life Safety Systems, Ph 1 of 3\$1,799,0FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,5FY02/03Repair/Replace Roofs, Ph 4 of 4\$135,5FY02/03M00006Repair/Replace Security Systems, Ph 4 of 4\$502,5FY02/03Repair/Replace Mechanical/Plumbing Systems, Ph 2 of 2\$255,5 | | | FY02/03 | | | \$750,000 | | | | |
| FY02/03Pointing Perimeter Walls, Ph 1 of 2\$233,0FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528,0FY02/03Repair/Replace Fire Life Safety Systems, Ph 1 of 3\$1,799,0FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,0FY02/03M80022Repair/Replace Roofs, Ph 4 of 4\$135,0FY02/03M00006Repair/Replace Security Systems, Ph 4 of 4\$502,0FY02/03Repair/Replace Mechanical/Plumbing Systems, Ph 2 of 2\$255,0 | | | FY02/03 | | Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 1 of 4 | \$383,000 | | | | |
| FY02/03Repair/Replace Asphalt Paving at BVCF, Ph 1 of 1\$528,1FY02/03Repair/Replace Fire Life Safety Systems, Ph 1 of 3\$1,799,0FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,0FY02/03M80022Repair/Replace Roofs, Ph 4 of 4\$135,0FY02/03M00006Repair/Replace Security Systems, Ph 4 of 4\$502,0FY02/03Repair/Replace Mechanical/Plumbing Systems, Ph 2 of 2\$255,0 | | | FY02/03 | M00012 | Phased Power System Replacement, Ph 2 of 3 | \$343,928 | | | | |
| FY02/03Repair/Replace Fire Life Safety Systems, Ph 1 of 3\$1,799,0FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,1FY02/03M80022Repair/Replace Roofs, Ph 4 of 4\$135,1FY02/03M00006Repair/Replace Security Systems, Ph 4 of 4\$502,1FY02/03Replace Mechanical/Plumbing Systems, Ph 2 of 2\$255,5 | | | | | - | \$233,000 | | | | |
| FY02/03Repair/Replace Roofs at BVCF, Ph 1 of 3\$416,4FY02/03M80022Repair/Replace Roofs, Ph 4 of 4\$135,5FY02/03M00006Repair/Replace Security Systems, Ph 4 of 4\$502,4FY02/03Replace Mechanical/Plumbing Systems, Ph 2 of 2\$255,5 | | | | | | \$528,000 | | | | |
| FY02/03M80022Repair/Replace Roofs, Ph 4 of 4\$135,FY02/03M00006Repair/Replace Security Systems, Ph 4 of 4\$502,FY02/03Replace Mechanical/Plumbing Systems, Ph 2 of 2\$255, | | | | | | \$1,799,000 | | | | |
| FY02/03M00006Repair/Replace Security Systems, Ph 4 of 4\$502,FY02/03Replace Mechanical/Plumbing Systems, Ph 2 of 2\$255, | | | | | | \$416,561 | | | | |
| FY02/03 Replace Mechanical/Plumbing Systems, Ph 2 of 2 \$255, | | | | | | \$135,110 | | | | |
| | | | | M00006 | | \$502,524 | | | | |
| FY02/03 M90007 Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 3 of 4 \$390, | | | | | | \$255,970 | | | | |
| | | | FY02/03 | M90007 | Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 3 of 4 | \$390,692 | | | | |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|-------|-----------------|----------------|---|---------------------|
| | | FY02/03 | | Slider Door and Operator Replacement, Ph 1 of 1 | \$287,370 |
| | | FY02/03 | M90008 | Structural Repairs, Ph 2 of 3 | \$787,000 |
| | | FY03/04 | | Asbestos Abatement, Ph 1 of 2 | \$250,000 |
| | | FY03/04 | | Chilled Water System Replacement, Ph 2 of 4 | \$515,000 |
| | | FY03/04 | | Chiller Replacement Project, Ph 1 of 3 | \$571,000 |
| | | FY03/04 | | Correct Water Damage and Drainage, PMC, Ph 2 of 4 | \$361,000 |
| | | FY03/04 | M90003 | Electrical Improvements, Ph 3 of 3 | \$618,000 |
| | | FY03/04 | M00008 | Electrical System Improvements, Ph 2 of 2 | \$853,836 |
| | | FY03/04 | | Heat Converters, Natural Gas Line, Ph 1 of 3 | \$82,000 |
| | | FY03/04 | | Hot Water/Steam/Hydronic Repairs, Ph 1 of 3 | \$248,000 |
| | | FY03/04 | | Paving and Resurfacing - FCC, DCC, Ph 2 of 2 | \$394,394 |
| | | FY03/04 | | Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 2 of 4 | \$816,000 |
| | | FY03/04 | M00012 | Phased Power System Replacement, Ph 3 of 3 | \$215,000 |
| | | FY03/04 | | Pointing Perimeter Walls, Ph 2 of 2 | \$225,000 |
| | | FY03/04 | | Repair/Replace Electrical Systems, Ph 1 of 3 | \$689,000 |
| | | FY03/04 | | Repair/Replace Fire Life Safety Systems, Ph 2 of 3 | \$2,298,000 |
| | | FY03/04 | | Repair/Replace Freight Elevator, Ph 1 of 1 | \$67,000 |
| | | FY03/04 | | Repair/Replace Roofs at BVCF, Ph 2 of 3 | \$318,200 |
| | | FY03/04 | | Replace Security Glazing, Ph 1 of 1 | \$85,989 |
| | | FY03/04 | | Roof Replacement-Various Locations, Ph 1 of 3 | \$482,000 |
| | | FY03/04 | M90007 | Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 4 of 4 | \$606,092 |
| | | FY03/04 | M90008 | Structural Repairs, Ph 3 of 3 | \$787,000 |
| | | FY03/04 | | Toilet and Lavatory Replacement, Ph 1 of 3 | \$309,000 |
| | | FY04/05 | | Asbestos Abatement, Ph 2 of 2 | \$250,000 |
| | | FY04/05 | | Carpet for Living Units DE-29 and DE-30, Ph 1 of 1 | \$58,680 |
| | | FY04/05 | | Chilled Water System Replacement, Ph 3 of 4 | \$505,000 |
| | | FY04/05 | | Chiller Replacement Project, Ph 2 of 3 | \$571,000 |
| | | FY04/05 | | Conduit Corridor, Ph 1 of 1 | \$94,245 |
| | | FY04/05 | | Correct Water Damage and Drainage, PMC, Ph 3 of 4 | \$309,000 |
| | | FY04/05 | | Emergency Generator Replacement, Ph 1 of 1 | \$515,000 |
| | | FY04/05 | | Floor Replacement-CCC, CTCF, LCF, BVCF, FCF, Ph 1 of 1 | \$422,609 |
| | | FY04/05 | | Heat Converters, Natural Gas Line, Ph 2 of 3 | \$27,000 |
| | | FY04/05 | | Hot Water/Steam/Hydronic Repairs, Ph 2 of 3 | \$269,000 |
| | | FY04/05 | | North and South Water Tank Exterior Walls, Ph 1 of 1 | \$45,577 |
| | | FY04/05 | | Paving - Interior Roads, Ph 1 of 2 | \$500,000 |
| | | FY04/05 | | Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 3 of 4 | \$1,042,000 |
| | | FY04/05 | | Repair Administration Buildings Floor Structure, Ph 1 of 1 | \$61,800 |
| | | FY04/05 | | Repair/Replace CH 6 Radiant Heat, Ph 1 of 1 | \$27,700 |
| | | FY04/05 | | Repair/Replace Electrical Systems, Ph 2 of 3 | \$515,000 |
| | | FY04/05 | | Repair/Replace Fire Life Safety Systems, Ph 3 of 3 | \$2,367,000 |
| | | FY04/05 | | Repair/Replace Roofs at BVCF, Ph 3 of 3 | \$135,125 |
| | | FY04/05 | | Replace Exit and Egress Lighting, Ph 1 of 1 | \$38,625 |
| | | FY04/05 | | Replace Gate Operators, Ph 1 of 1 | \$47,900 |
| | | FY04/05 | | Roof Replacement-Various Locations, Ph 2 of 3 | \$582,000 |
| | | FY04/05 | | Roofing -CTCF, Ph 1 of 2 | \$250,000 |
| | | FY04/05 | | Spray Paint Booth, Ph 1 of 1 | \$19,673 |
| | | FY04/05 | | Toilet and Lavatory Replacement, Ph 2 of 3 | \$309,000 |
| | | FY04/05 | | Tower Upgrades - BVCF, CTCF, FCF, Ph 1 of 2 | \$337,500 |
| | | FY05/06 | | Chilled Water System Replacement, Ph 4 of 4 | \$258,000 |
| | | FY05/06 | | Chiller Replacement Project, Ph 3 of 3 | \$571,000 |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|---------|-----------------|----------------|---|------------------------------|
| | | FY05/06 | | Correct Water Damage and Drainage, PMC, Ph 4 of 4 | \$309,000 |
| | | FY05/06 | | Heat Converters, Natural Gas Line, Ph 3 of 3 | \$27,000 |
| | | FY05/06 | | Hot Water/Steam/Hydronic Repairs, Ph 3 of 3 | \$289,000 |
| | | FY05/06 | | Paving - Interior Roads, Ph 2 of 2 | \$500,000 |
| | | FY05/06 | | Paving-CMC, AVCF, CSP, DCC, CCF, SCC, Ph 4 of 4 | \$1,042,000 |
| | | FY05/06 | | Repair/Replace Electrical Systems, Ph 3 of 3 | \$415,000 |
| | | FY05/06 | | Repair/Replace Fluorescent Ballasts, Ph 1 of 1 | \$103,000 |
| | | FY05/06 | | Repair/Replace Roofs at RCC, Ph 1 of 1 | \$251,000 |
| | | FY05/06 | | Replace Emergency Generators, Ph 1 of 1 | \$545,900 |
| | | FY05/06 | | Roof Replacement-Various Locations, Ph 3 of 3 | \$479,000 |
| | | FY05/06 | | Roofing -CTCF, Ph 2 of 2 | \$250,000 |
| | | FY05/06 | | Toilet and Lavatory Replacement, Ph 3 of 3 | \$309,000 |
| | | FY05/06 | | Tower Upgrades - BVCF, CTCF, FCF, Ph 2 of 2 | \$337,500 |
| | | FY05/06 | | Upgrade Cell Lighting, Ph 1 of 1 | \$174,700 |
| | | FY05/06 | | Upgrade Domestic Water Distribution, Ph 1 of 1 | \$360,000 |
| | | FY05/06 | | UPS for Administration Building, Ph 1 of 1 | \$20,600 |
| | | | | DOC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: | \$41,711,174 \$52,765,590 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$4,300,000 |
| | | | | Agency Reported Controlled Maintenance Total: | \$98,776,764 |
| Colo | orado S | chool for t | he Deaf a | nd Blind | |
| 13 | Ę | 5 FY01/02 | | Campus Safety/Fire Lanes Upgrade, Ph 1 of 1 | \$301,000 |
| 86 | 20 |) FY01/02 | M00025 | Electrical Distribution Upgrade, Ph 2 of 3 | \$212,128 |
| 126 | 30 |) FY01/02 | M80029 | Roof Repair/Replacement Campus-wide, Ph 3 of 3 | \$164,813 |
| | | FY01/02 | | Mechanical System Repair/Replacement, Vocational Building, Ph 1 of 1 | \$450,000 |
| | | FY01/02 | | Waste Water Line Replacement, Ph 1 of 2 | \$57,000 |
| | | FY02/03 | M00025 | Electrical Distribution Upgrade, Ph 3 of 3 | \$247,758 |
| | | FY02/03 | | Main Water Line Replacement, Ph 1 of 1 | \$225,000 |
| | | FY02/03 | | Waste Water Line Replacement, Ph 2 of 2 | \$248,000 |
| | | FY03/04 | | HVAC Replacement Adams School, Ph 1 of 1 | \$450,000 |
| | | FY03/04 | | Plumbing Replacement Administration, Ph 1 of 1 | \$150,000 |
| | | FY04/05 | | Steam Line Replacement, Ph 1 of 1 | \$475,000 |
| | | FY04/05 | | Window Replacement Gottlieb, Ph 1 of 1 | \$325,000 |
| | | FY05/06 | | Code Compliance West, Ph 1 of 1 | \$85,000 |
| | | FY05/06 | | Window Replacement West Hall, Ph 1 of 1 | \$275,000 |
| | | | | CSDB 5 Year Plan Project Request Total: | \$3,665,699 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$0 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$3,665,699 |
| Depa | artment | of Public | Health an | d Environment | |
| | | | | CDPHE 5 Year Plan Project Request Total: | \$0 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$0 \$0 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$0 \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$0 \$0 |
| | | | | Agency Reported Controlled Maintenance Folal. | φU |
| Colo | orado H | istorical S | ociety | | |
| 48 | 14 | FY01/02 | | Ft. Vasquez Energy and Site Security Upgrade, Ph 1 of 1 | \$150,877 |
| 61 | 18 | 3 FY01/02 | M00086 | Ft. Garland Code/Safety Upgrade, Ph 2 of 2 | \$134,645 |
| | | | | | |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|-----------|-----------------|----------------|---|---------------------|
| 106 | 24 | FY01/02 | | Trinidad Site Accessibility and Building Improvements, Ph 1 of 1 | \$293,572 |
| 139 | 42 | FY01/02 | | Upgrade Building Deficiencies, Fort Garland, Ph 1 of 1 | \$175,055 |
| 168 | 84 | FY01/02 | | Silver Plume Depot Site Upgrade, Ph 1 of 1 | \$326,551 |
| | | FY02/03 | | Healy House Code/Safety Upgrade, Ph 1 of 1 | \$108,289 |
| | | FY02/03 | | HVAC Upgrade - 3 Sites, Ph 1 of 1 | \$130,000 |
| | | FY02/03 | | Repair Statewide Historic Markers, Ph 1 of 1 | \$450,000 |
| | | FY02/03 | | Upgrade High Bridge at Georgetown Facility, Ph 1 of 1 | \$230,000 |
| | | FY03/04 | | Byers-Evans House Upgrade, Ph 1 of 1 | \$230,000 |
| | | FY03/04 | | Everett Mine and Lebanon Mine Timber Replacement, Ph 1 of 1 | \$300,000 |
| | | FY03/04 | | Georgetown Rock Scaling, Ph 1 of 1 | \$180,000 |
| | | FY03/04 | | Pikes Stockade General Repairs, Ph 1 of 1 | \$180,000 |
| | | FY04/05 | | Baca/Bloom House Upgrade, Ph 1 of 1 | \$210,000 |
| | | FY04/05 | | Grant Humphreys Exterior Maintenance, Ph 1 of 1 | \$180,000 |
| | | FY04/05 | | Museum Support Center-Lowry Facility Improvements, Ph 1 of 1 | \$262,500 |
| | | FY04/05 | | Repair Roofs at Ft. Garland, Ph 1 of 1 | \$100,000 |
| | | FY05/06 | | Georgetown Right of Way Scaling and High Bridge Inspection, Ph 1 of 1 | \$100,000 |
| | | FY05/06 | | Healy House Dexter Cabin Facility Upgrades, Ph 1 of 1 | \$180,000 |
| | | FY05/06 | | Security Upgrade, Ph 1 of 1 | \$350,000 |
| | | FY05/06 | | Upgrade Silver Plume Engine House, Ph 1 of 1 | \$200,000 |
| | | FY05/06 | | Ute Museum Facility Upgrade, Ph 1 of 1 | \$210,000 |
| | | | | DOHE-CHS 5 Year Plan Project Request Total: | \$4,681,489 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$3,496,950 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$3,734,589 |
| | | | | Agency Reported Controlled Maintenance Total: | \$11,913,028 |
| Univ | ersity of | Colorado | Health S | ciences Center | |
| 11 | 4 | FY01/02 | M00050 | Replace Underground Storage Tanks, Ph 2 of 3 | \$862,125 |
| 53 | 15 | FY01/02 | M00051 | School of Medicine Exhaust System Replacement, Ph 2 of 4 | \$596,695 |
| 60 | 16 | FY01/02 | M727 | Colorado Psychiatric Hospital Infrastructure, Ph 4 of 4 | \$394,805 |
| 74 | 18 | FY01/02 | M728 | Power Plant and Campus Cooling System Improvements, Ph 6 of 9 | \$564,007 |
| 104 | 24 | FY01/02 | | Colorado Psychiatric Hospital, Window Replacement, Ph 1 of 2 | \$515,000 |
| 134 | 36 | FY01/02 | | Campus Elevator Upgrades, Ph 1 of 4 | \$550,000 |
| 141 | 42 | FY01/02 | | Office Annex Window Replacement, Ph 1 of 2 | \$280,000 |
| | | FY01/02 | M729 | Campus Roof and Window Replacement, Ph 4 of 5 | \$319,770 |
| | | FY01/02 | M90043 | Power Plant Heating and Electrical System Improvements, Ph 3 of 3 | \$527,875 |
| | | FY02/03 | | Campus Elevator Upgrades, Ph 2 of 4 | \$500,000 |
| | | FY02/03 | M729 | Campus Roof and Window Replacement, Ph 5 of 5 | \$309,550 |
| | | FY02/03 | | Colorado Psychiatric Hospital, Window Replacement, Ph 2 of 2 | \$425,000 |
| | | FY02/03 | | Office Annex Window Replacement, Ph 2 of 2 | \$275,000 |
| | | FY02/03 | M728 | Power Plant and Campus Cooling System Improvements, Ph 7 of 9 | \$177,028 |
| | | FY02/03 | | Power Plant Turbine Generator Replacement, Ph 1 of 3 | \$835,375 |
| | | | M00050 | Replace Underground Storage Tanks, Ph 3 of 3 | \$543,250 |
| | | FY02/03 | | School of Medicine Electrical Power Distribution Upgrade, Ph 1 of 4 | \$497,125 |
| | | FY02/03 | M00051 | School of Medicine Exhaust System Replacement, Ph 3 of 4 | \$550,425 |
| | | FY03/04 | | Campus Elevator Upgrades, Ph 3 of 4 | \$350,000 |
| | | FY03/04 | M728 | Power Plant and Campus Cooling System Improvements, Ph 8 of 9 | \$829,820 |
| | | FY03/04 | | Power Plant Turbine Generator Replacement, Ph 2 of 3 | \$666,250 |
| | | FY03/04 | | School of Medicine Electrical Power Distribution Upgrade, Ph 2 of 4 | \$384,375 |
| | | FY03/04 | M00051 | School of Medicine Exhaust System Replacement, Ph 4 of 4 | \$478,675 |
| | | FY04/05 | | Campus Elevator Upgrades, Ph 4 of 4 | \$375,000 |
| | | | | | , |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|-----------|--|----------------|---|--|
| | | FY04/05 FY04/05 FY04/05 FY05/06 | M728 | Power Plant and Campus Cooling System Improvements, Ph 9 of 9 Power Plant Turbine Generator Replacement, Ph 3 of 3 School of Medicine Electrical Power Distribution Upgrade, Ph 3 of 4 School of Medicine Electrical Power Distribution Upgrade, Ph 4 of 4 | \$885,141 \$553,500 \$328,000 \$527,875 |
| | | | | DOHE-UCHSC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$14,101,666 \$19,265,371 \$18,383,848 \$51,750,885 |
| Univ | ersity of | f Colorado | at Bould | er | |
| 7 | 4 | FY01/02 | M80053 | Fire Sprinkler Upgrades Various Buildings A, Ph 3 of 6 | \$646,512 |
| 9 | 4 | FY01/02 | M90033 | Engineering Center Fire Sprinkler System Upgrades, Ph 2 of 2 | \$597,240 |
| 12 | 5 | FY01/02 | M90032 | Upgrade Central Fire Alarm Systems, Ph 3 of 4 | \$430,703 |
| 14 | 5 | FY01/02 | | Chemical Engineering HVAC Upgrades, Ph 1 of 3 | \$885,876 |
| 16 | 6 | FY01/02 | | Code and Life Safety Upgrades, Various Buildings, Ph 1 of 2 | \$198,882 |
| 34 | 10 | FY01/02 | | Repair/Replace Building Electrical Services, Ph 1 of 5 | \$487,526 |
| 51 | 15 | FY01/02 | M90035 | Repair/Replace Obsolete Central HVAC Controls, Ph 3 of 3 | \$177,942 |
| 59 | 16 | FY01/02 | M00038 | Campus Steam Tunnel Structural Upgrades, Ph 2 of 3 | \$527,391 |
| 70 | 18 | FY01/02 | | Repair/Replace Main Campus Compressed Air System, Ph 1 of 2 | \$348,780 |
| 84 | 20 | FY01/02 | M90036 | Regents Repair/Replace Air Handling Systems, Ph 2 of 2 | \$608,030 |
| 92 | | | M00043 | Drainage Improvements, Main Campus, East Half, Ph 2 of 2 | \$449,807 |
| 136 | | FY01/02 | | Storm/Sanitary Sewer Cross Connection, Ph 1 of 1 | \$235,903 |
| 143 | | FY01/02 | M00040 | Repair/Replace Deteriorated Roadways, Ph 2 of 2 | \$157,129 |
| 154 | 48 | FY01/02 | | Replace Chemistry and Ekeley Generators, Ph 1 of 5 | \$585,600 |
| | | FY01/02 | | Environmental Design HVAC Upgrades, Ph 1 of 1 | \$1,499,575 |
| | | FY01/02 | | Storm Sewer Drainage, Main Campus West Half, Ph 1 of 1 | \$567,000 |
| | | FY02/03 | | Campus Main Chilled Water System, Ph 1 of 4 | \$100,000 |
| | | FY02/03 | M00038 | Campus Steam Tunnel Structural Upgrades, Ph 3 of 3 | \$617,952 |
| | | FY02/03 | | Campus Wayfinding System, Ph 1 of 1 | \$484,880 |
| | | FY02/03 | | Chemical Engineering HVAC Upgrades, Ph 2 of 3 | \$699,575 |
| | | FY02/03 | 1400050 | Code and Life Safety Upgrades, Various Buildings, Ph 2 of 2 | \$201,105 |
| | | FY02/03 | M80053 | Fire Sprinkler Upgrades Various Buildings A, Ph 4 of 6 | \$1,252,535 |
| | | FY02/03 | 1400044 | Imig N/S Wing and Practice Room HVAC Renovation, Ph 1 of 1 | \$670,700 |
| | | | M00041 | Main Campus Tunnel Security Projects, Ph 2 of 3 | \$389,800 |
| | | FY02/03 FY02/03 | | Ramaley HVAC and Campus Fume Hood Vent Upgrades, Ph 1 of 5 Repair/Replace Building Electrical Services, Ph 2 of 5 | \$642,006 \$524,901 |
| | | FY02/03 | | Repair/Replace Campus Roofing Systems, Ph 1 of 4 | \$324,901 \$437,585 |
| | | FY02/03 | Megg | Repair/Replace Heating and Cooling Systems, Ph 4 of 4 | \$437,383 \$168,243 |
| | | FY02/03 | MOZZ | Repair/Replace Main Campus Compressed Air System, Ph 2 of 2 | \$729,753 |
| | | FY02/03 | | Replace Chemistry and Ekeley Generators, Ph 2 of 5 | \$602,290 |
| | | FY02/03 | M00042 | Roof Repair/Replace and Water Proofing, Ph 2 of 3 | \$1,061,436 |
| | | FY02/03 | | Steam Safety Relief Valve Upgrades, Ph 1 of 5 | \$333,083 |
| | | | M90032 | Upgrade Central Fire Alarm Systems, Ph 4 of 4 | \$422,460 |
| | | FY02/03 | | Water Main Upgrades, Ph 1 of 4 | \$633,258 |
| | | FY03/04 | | Campus Elevator Systems Upgrades, Ph 1 of 3 | \$341,715 |
| | | FY03/04 | | Campus Main Chilled Water System, Ph 2 of 4 | \$100,000 |
| | | FY03/04 | | Campus Steam Line Upgrades, Ph 1 of 2 | \$351,418 |
| | | FY03/04 | | Chemical Engineering HVAC Upgrades, Ph 3 of 3 | \$780,157 |
| | | FY03/04 | M80053 | Fire Sprinkler Upgrades Various Buildings A, Ph 5 of 6 | \$863,706 |
| | | FY03/04 | | Interior Lighting Upgrades, Ph 1 of 3 | \$566,390 |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|-----------|-----------------|----------------|---|---------------------|
| | | FY03/04 | M00041 | Main Campus Tunnel Security Projects, Ph 3 of 3 | \$400,211 |
| | | FY03/04 | | Ramaley HVAC and Campus Fume Hood Vent Upgrades, Ph 2 of 5 | \$614,364 |
| | | FY03/04 | | Repair/Replace Building Electrical Services, Ph 3 of 5 | \$439,236 |
| | | FY03/04 | | Repair/Replace Campus Roofing Systems, Ph 2 of 4 | \$375,426 |
| | | FY03/04 | | Replace Chemistry and Ekeley Generators, Ph 3 of 5 | \$756,535 |
| | | FY03/04 | M00042 | Roof Repair/Replace and Water Proofing, Ph 3 of 3 | \$519,638 |
| | | FY03/04 | | Steam Safety Relief Valve Upgrades, Ph 2 of 5 | \$319,369 |
| | | FY03/04 | | Structural Upgrade in Campus Steam Tunnels, Ph 1 of 3 | \$746,130 |
| | | FY03/04 | | Water Main Upgrades, Ph 2 of 4 | \$378,950 |
| | | FY04/05 | | Campus Elevator Systems Upgrades, Ph 2 of 3 | \$274,835 |
| | | FY04/05 | | Campus Main Chilled Water System, Ph 3 of 4 | \$100,000 |
| | | FY04/05 | | Campus Steam Line Upgrades, Ph 2 of 2 | \$639,658 |
| | | FY04/05 | M80053 | Fire Sprinkler Upgrades Various Buildings A, Ph 6 of 6 | \$743,462 |
| | | FY04/05 | | Interior Lighting Upgrades, Ph 2 of 3 | \$617,595 |
| | | FY04/05 | | Ramaley HVAC and Campus Fume Hood Vent Upgrades, Ph 3 of 5 | \$572,003 |
| | | FY04/05 | | Repair/Replace Building Electrical Services, Ph 4 of 5 | \$544,415 |
| | | FY04/05 | | Repair/Replace Campus Roads, Ph 1 of 2 | \$345,728 |
| | | FY04/05 | | Repair/Replace Campus Roofing Systems, Ph 3 of 4 | \$842,149 |
| | | FY04/05 | | Replace Chemistry and Ekeley Generators, Ph 4 of 5 | \$756,535 |
| | | FY04/05 | | Steam Safety Relief Valve Upgrades, Ph 3 of 5 | \$255,780 |
| | | FY04/05 | | Structural Upgrade in Campus Steam Tunnels, Ph 2 of 3 | \$834,955 |
| | | FY04/05 | | Upgrade Exterior Campus Lighting, Ph 1 of 2 | \$273,790 |
| | | FY04/05 | | Water Main Upgrades, Ph 3 of 4 | \$742,333 |
| | | FY05/06 | | Campus Elevator Systems Upgrades, Ph 3 of 3 | \$411,730 |
| | | FY05/06 | | Campus Main Chilled Water System, Ph 4 of 4 | \$100,000 |
| | | FY05/06 | | Interior Lighting Upgrades, Ph 3 of 3 | \$505,780 |
| | | FY05/06 | | Nuclear Physics Lab Chiller/Boiler Replacement, Ph 1 of 1 | \$409,640 |
| | | FY05/06 | | Ramaley HVAC and Campus Fume Hood Vent Upgrades, Ph 4 of 5 | \$594,547 |
| | | FY05/06 | | Repair/Replace Building Electrical Services, Ph 5 of 5 | \$514,036 |
| | | FY05/06 | | Repair/Replace Campus Roads, Ph 2 of 2 | \$315,189 |
| | | FY05/06 | | Repair/Replace Campus Roofing Systems, Ph 4 of 4 | \$598,245 |
| | | FY05/06 | | Replace Chemistry and Ekeley Generators, Ph 5 of 5 | \$367,250 |
| | | FY05/06 | | Steam Safety Relief Valve Upgrades, Ph 4 of 5 | \$266,124 |
| | | FY05/06 | | Structural Upgrade in Campus Steam Tunnels, Ph 3 of 3 | \$809,875 |
| | | FY05/06 | | Upgrade Exterior Campus Lighting, Ph 2 of 2 | \$259,160 |
| | | FY05/06 | | Water Main Upgrades, Ph 4 of 4 | \$436,874 |
| | | | | DOHE-UCB 5 Year Plan Project Request Total: | \$39,060,391 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$96,858,558 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$698,224 |
| | | | | Agency Reported Controlled Maintenance Total: | \$136,617,173 |
| Univ | versity o | f Colorado | o at Color | ado Springs | |
| 28 | - | FY01/02 | | Network Campus Fire Alarm System, Ph 1 of 1 | \$144,425 |
| 52 | | FY01/02 | M90038 | Replace HVAC Science Building, Ph 2 of 5 | \$590,867 |
| 98 | | FY01/02 | | Repair/Replace Water Main Valves, Ph 1 of 1 | \$73,986 |
| 113 | | FY01/02 | | Repair Campus Infrastructure, Ph 1 of 3 | \$297,812 |
| 164 | | FY01/02 | | Repair Campus Infrastructure, Ph 2 of 3 | \$501,744 |
| 167 | | FY01/02 | | Replace Exterior Lighting, Ph 1 of 1 | \$154,500 |
| | | FY02/03 | | Repair Campus Infrastructure, Ph 3 of 3 | \$292,583 |
| | | | M90038 | Replace HVAC Science Building, Ph 3 of 5 | \$593,285 |
| | | | | | , , |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|----------|-----------------|----------------|--|---------------------|
| | | FY03/04 | M90038 | Replace HVAC Science Building, Ph 4 of 5 | \$414,920 |
| | | FY04/05 | | Repair Structural Damage, Ph 1 of 1 | \$51,750 |
| | | FY04/05 | | Repair/Resurface Roof at Columbine and CSB, Ph 1 of 1 | \$37,500 |
| | | FY04/05 | | Repair/Upgrade Infrastructure - Heller, Ph 1 of 1 | \$255,000 |
| | | FY04/05 | M90038 | Replace HVAC Science Building, Ph 5 of 5 | \$425,293 |
| | | FY05/06 | | Replace Boilers Engineering Building, Ph 1 of 1 | \$117,500 |
| | | FY05/06 | | Replace Roof/Refurbish Art Gallery, Ph 1 of 1 | \$129,500 |
| | | | | DOHE-UCCS 5 Year Plan Project Request Total: | \$4,080,665 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$0 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$4,080,665 |
| Colo | rado Sta | ate Univer | sitv | | |
| 21 | | FY01/02 | , | Replace Deteriorated Mechanical, VTH, Ph 1 of 5 | \$652,599 |
| 32 | | FY01/02 | | Replace Deteriorated Electrical Feeders and Main Campus Feeders, Ph 1 of 1 | \$632,996 |
| 36 | | FY01/02 | | Replace Deteriorated Items, Music, Ph 1 of 3 | \$600,586 |
| 41 | | FY01/02 | | Replace Deteriorated Electrical Alyesworth Hall, Ph 1 of 1 | \$397,895 |
| 55 | | FY01/02 | M00032 | Replace Deteriorated Items, Wagar, Ph 2 of 3 | \$684,877 |
| 71 | | FY01/02 | 11100002 | Replace Deteriorated Refrigeration Units, Ph 1 of 1 | \$527,495 |
| 78 | | FY01/02 | | Replace Deteriorated Items, Forestry, Ph 1 of 3 | \$450,700 |
| 91 | | FY01/02 | M90025 | Install East Drive to Center Street Steam Loop, Ph 3 of 3 | \$619,386 |
| 93 | | FY01/02 | M00033 | Replace Deteriorated Roads and Sidewalks, Ph 2 of 5 | \$293,191 |
| 96 | | FY01/02 | | Replace Deteriorated Roofing Various Buildings, Ph 2 of 2 | \$328,930 |
| 107 | | FY01/02 | | Replace Deteriorated Items, San Luis Valley and CSFS Foothills, Ph 1 of 1 | \$294,042 |
| 133 | | FY01/02 | | Replace Deteriorated Mechanical, VTH, Ph 2 of 5 | \$633,686 |
| 145 | | FY01/02 | M00033 | Replace Deteriorated Roads and Sidewalks, Ph 3 of 5 | \$260,024 |
| 151 | | FY01/02 | M00032 | Replace Deteriorated Items, Wagar, Ph 3 of 3 | \$676,013 |
| | | FY02/03 | | Chilled Water Loop, Ph 1 of 5 | \$1,585,547 |
| | | FY02/03 | | Replace Deteriorated Items, Forestry, Ph 2 of 3 | \$535,802 |
| | | FY02/03 | | Replace Deteriorated Items, Military Science Annex BRP, Ph 1 of 1 | \$415,564 |
| | | FY02/03 | | Replace Deteriorated Items, Military Science BRP, Ph 1 of 1 | \$621,376 |
| | | FY02/03 | | Replace Deteriorated Items, Music, Ph 2 of 3 | \$677,248 |
| | | FY02/03 | | Replace Deteriorated Mechanical, VTH, Ph 3 of 5 | \$676,180 |
| | | FY02/03 | | Replace Deteriorated Plumbing Items, Ph 1 of 2 | \$488,254 |
| | | FY02/03 | | Replace Deteriorated Roofing, Ph 1 of 2 | \$429,981 |
| | | FY02/03 | | Replace Epoxy Flooring - Painter Center, Ph 1 of 1 | \$243,007 |
| | | FY02/03 | | Utility LRP Steam and Condensate North Line, Ph 1 of 3 | \$463,252 |
| | | FY03/04 | | Chilled Water Loop, Ph 2 of 5 | \$1,585,547 |
| | | FY03/04 | | Replace Deteriorated Items, Forestry, Ph 3 of 3 | \$571,548 |
| | | FY03/04 | | Replace Deteriorated Items, Guggenheim BRP, Ph 1 of 2 | \$540,098 |
| | | FY03/04 | | Replace Deteriorated Items, Music, Ph 3 of 3 | \$632,621 |
| | | FY03/04 | | Replace Deteriorated Plumbing Items, Ph 2 of 2 | \$488,254 |
| | | FY03/04 | M00033 | Replace Deteriorated Roads and Sidewalks, Ph 4 of 5 | \$288,189 |
| | | FY03/04 | | Replace Deteriorated Roofing, Ph 2 of 2 | \$950,400 |
| | | FY03/04 | | Replace Fire Alarms, Ph 1 of 3 | \$478,241 |
| | | FY03/04 | | Utility LRP Steam and Condensate North Line, Ph 2 of 3 | \$463,252 |
| | | FY04/05 | | Chilled Water Loop, Ph 3 of 5 | \$1,585,547 |
| | | FY04/05 | | Repair Sanitary Sewers - Basin C, Ph 1 of 3 | \$621,216 |
| | | FY04/05 | | Replace Deteriorated Items, Animal Science BRP, Ph 1 of 2 | \$606,733 |
| | | FY04/05 | | Replace Deteriorated Items, Guggenheim BRP, Ph 2 of 2 | \$474,281 |

| FY04/05 Replace Deteriorated Mechanical, VTH, Ph 4 of 5 \$677.180 FY04/05 Replace Deteriorated Mechanical, VTH, Ph 4 of 5 \$312.994 FY04/05 Replace Direivorated Roads and Sidewalks, Ph 5 of 5 \$312.994 FY04/05 Replace Direivorated Roads and Sidewalks, Ph 5 of 5 \$312.994 FY04/05 Replace Direivorated Roads and Sidewalks, Ph 5 of 5 \$312.994 FY04/05 Utility LRP - Durward Hall and Aylesworth Steam Lines, Ph 1 of 1 \$468.782 FY05/06 Childed Water Loop, Ph 4 of 5 \$1.585.647 FY05/06 Repaira Sintary, Sewers - Basin C, Ph 2 of 3 \$577.536 FY05/06 Repaira Sintary, Sewers - Basin C, Ph 2 of 3 \$579.031 FY05/06 Replace Deteriorated Items, Animal Science BRP, Ph 2 of 2 \$566.802 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$579.031 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$519.905 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$519.905 FY05/06 Replace Deteriorated Items, Shepardson BRV, Ph 1 of 2 \$438.484 FY05/06 Replace Deteriorated Items of There Marms, Ph 3 of 3 < | Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|---|-------------|----------|-----------------|----------------|---|----------------------|
| FY04/05 M00033 Replace Deteriorated Roads and Sidewalds, Ph 5 of 5 \$312,994 FY04/05 Replace Ductwork - Physiology, Ph 1 of 3 \$670,332 FY04/05 Utility LRP - Durward Hall and Aylesworth Steam Lines, Ph 1 of 1 \$468,732 FY04/05 Utility LRP - Durward Hall and Aylesworth Steam Lines, Ph 1 of 1 \$468,732 FY04/05 Utility LRP - Durward Hall and Aylesworth Steam Lines, Ph 1 of 1 \$468,732 FY05/06 Repair Sinitary Severs - Basin C, Ph 2 of 3 \$512,500 FY05/06 Replace Deteriorated Items, Insectary Potato Virus, Ph 1 of 2 \$237,641 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 2 \$3686,802 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 2 \$3643,845 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$5443,845 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$643,845 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$3443,338 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$3443,338 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$346,355 FY05/06 Replace Chemistry, Ph 1 of 3 <td></td> <td></td> <td>FY04/05</td> <td></td> <td>Replace Deteriorated Items, Shepardson BRP, Ph 1 of 3</td> <td>\$617,314</td> | | | FY04/05 | | Replace Deteriorated Items, Shepardson BRP, Ph 1 of 3 | \$617,314 |
| FV0405 Replace Ductwork - Physiology, Ph 1 of 3 \$\$77,332 FY0405 Replace Fire Alarms, Ph 2 of 3 \$\$74,556 FY0405 Utility LRP - Durward Hall and Aylesworth Steam Lines, Ph 1 of 1 \$468,752 FY0506 Repair Sanitary Sawars - Basin C, Ph 2 of 3 \$\$21,216 FY0506 Repair Condensate North Line, Ph 3 of 3 \$\$21,216 FY0506 Repair Condensate North Line, Ph 3 of 3 \$\$21,216 FY0506 Repair Condensate North Line, Ph 3 of 3 \$\$21,216 FY0506 Replace Deteriorated Items, Animal Science BRP, Ph 2 of 2 \$\$668,022 FY0506 Replace Deteriorated Items, Insectary Potato Virus, Ph 1 of 2 \$\$237,641 FY0506 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$\$919,905 FY0506 Replace Ductwork - Physiology, Ph 2 of 3 \$\$943,843 FY0506 Replace Ductwork - Physiology, Ph 2 of 3 \$\$34,0338 FY0506 Replace Ductwork - Physiology, Ph 2 of 3 \$\$34,0338 FY0506 Replace Ductwork - Physiology, Ph 2 of 3 \$\$33,128,626 St91,507 Southern Colocade \$\$33,128,626 Iss DOHE-CSU Svar Plan Project Request Total: \$\$27,567,773 13 42 FV01/02 Replace Electrical Panels and Transformers, Ph 1 of 3 \$\$27,567,775 13 8 </td <td></td> <td></td> <td>FY04/05</td> <td></td> <td>Replace Deteriorated Mechanical, VTH, Ph 4 of 5</td> <td>\$676,180</td> | | | FY04/05 | | Replace Deteriorated Mechanical, VTH, Ph 4 of 5 | \$676,180 |
| FY04/05 Replace Fire Alarms, Ph 2 of 3 \$\$74,566 FY04/05 Utility LRP Steam and Condensate North Line, Ph 3 of 3 \$463,752 FY05/06 Chilled Water Loop, Ph 4 of 5 \$1,586,547 FY05/06 Repair Sanitary Severs - Basin C, Ph 2 of 3 \$521,250 FY05/06 Repaire Sanitary Severs - Basin C, Ph 2 of 3 \$521,250 FY05/06 Replace Deteriorated Items - Lake Street Greenhouse BRP, Ph 1 of 2 \$438,948 FY05/06 Replace Deteriorated Items, Animal Science BRP, Ph 2 of 2 \$523,7641 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$513,905 FY05/06 Replace Deteriorated Items, Insectary Potato Virus, Ph 1 of 2 \$334,338 FY05/06 Replace Deteriorated Items, Insectary Potato Virus, Ph 1 of 2 \$343,348 FY05/06 Replace Deteriorated Items, Insectary Potato Virus, Ph 1 of 2 \$343,348 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$343,348 FY05/06 Replace Ductwork - Physiology, Ph 1 of 2 \$348,356 Estimated Long Term Infrastructure Major Maintenance Total: \$27,967,577 Agency Reported Controlled Maintenance To | | | | M00033 | • | |
| FY04/05Utility LRP - Durward Hall and Alyesworth Steam Lines, Ph 1 of 1\$468,782FY05/06Chilled Water Loop, Ph 4 of 5\$1,586,547FY05/06Repair Sanitary Sewers - Basin C, Ph 2 of 3\$521,216FY05/06Repair Canitary Sewers - Basin C, Ph 2 of 3\$521,216FY05/06Repair Canitary Sewers - Basin C, Ph 2 of 3\$521,216FY05/06Replace Deteriorated Items - Lake Street Greenhouse BRP, Ph 1 of 2\$338,948FY05/06Replace Deteriorated Items, Insectary Potato Virus, Ph 2 of 3\$797,031FY05/06Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3\$519,900FY05/06Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3\$340,338FY05/06Replace Deteriorated Items, Insectary Potato Virus, Ph 1 of 2\$33,128,265FY05/06Replace Deteriorated Items Infrastructure Major Maintenance Total:\$33,128,265Strots/06Replace Deteriorated Items Infrastructure Major Maintenance Total:\$33,128,265Strots/07Southern EctoradeStrets/Ph 1 of 1\$18,0001342FY01/02Replace Deteriorated Steam Distribution System, Ph 2 of 3\$1,444,1441342FY01/02Replace Deteriorated Steam Distribution System, Ph 2 of 3\$1,444,1441342FY01/02Replace Deteriorated Steam Distribution System, Ph 2 of 3\$1,444,14414\$18,0000FY02/03Replace Deteriorated Steam Distribution System, Ph 2 of 3\$1,444,14414\$18,0000FY01/02Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,144 <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> | | | | | | |
| FY04/05 Utility LPP Steam and Condensate North Line, Ph 3 of 3 \$463,252 FY05/06 Chilled Water Loop, Ph 4 of 5 \$1,385,547 FY05/06 Repair Sanitary Sewers - Basin C, Ph 2 of 3 \$521,216 FY05/06 Repair Utilities - Pingree Park, Ph 1 of 1 \$512,500 FY05/06 Replace Deteriorated Items, Lake Street Greenhouse BRP, Ph 1 of 2 \$438,948 FY05/06 Replace Deteriorated Items, Shepardots DRP, Ph 2 of 2 \$668,602 FY05/06 Replace Deteriorated Items, Shepardots DRP, Ph 2 of 3 \$737,031 FY05/06 Replace Deteriorated Mechanical, VTH, Ph 5 of 5 \$549,905 FY05/06 Replace Deteriorated Mechanical, VTH, Ph 5 of 5 \$463,845 FY05/06 Replace Deteriorated Incoms Shepardots DRP, Ph 2 of 3 \$444,343 FY05/06 Replace Deteriorated Incoms Chance Total: \$27,567,577 Sto5/06 Replace Deteriorated Steam Distribution System, Ph 2 of 3 \$1,444,144 13 8 FY01/02 Replace Electrical Panels and Transformers, Ph 1 of 3 \$27,567,577 Sto5/07 Replace Campus Water Lines, Ph 1 of 3 \$1,444,144 \$33 \$27,560,000 FY01/02 | | | | | - | |
| FY05/06 Chilled Water Loop, Ph 4 of 5 \$1,685,547 FY05/06 Repair Sanitary Sewers - Basin C, Ph 2 of 3 \$621,216 FY05/06 Replace Deteriorated Items, Animal Science BRP, Ph 1 of 2 \$438,948 FY05/06 Replace Deteriorated Items, Insectary Potato Virus, Ph 1 of 2 \$237,641 FY05/06 Replace Deteriorated Items, Insectary Potato Virus, Ph 1 of 2 \$237,641 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$579,031 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$643,845 FY05/06 Replace Deteriorated Items, Ph 3 of 3 \$340,333 FY05/06 Replace C fire Alarms, Ph 3 of 3 \$1443,144 FY05/06 Replace Deteriorated Nechanical, VTH, Ph 5 of 5 \$89,805,646 Estimated Long Term Infrastructure Major Maintenance Total: \$23,762,757 Agency Reported Controlled Maintenance Total: \$27,500,757 Agency Reported Controlled Maintenance Total: \$27,500,757 < | | | | | | |
| FY05/06 Repair Sanitary Sewers - Basin C, Ph 2 of 3 \$621,216 FY05/06 Repair Utilities - Pingree Park, Ph 1 of 1 \$512,500 FY05/06 Replace Deteriorated Items, Lake Street Greenhouse BRP, Ph 1 of 2 \$433,948 FY05/06 Replace Deteriorated Items, Insciary Potato Virus, Ph 1 of 2 \$237,641 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$797,031 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$512,900 FY05/06 Replace Deteriorated Mershinola, VTH, Ph 5 of 5 \$512,900 FY05/06 Replace Deteriorated Mershinola, VTH, Ph 5 of 5 \$543,945 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$643,845 FY05/06 Replace Deteriorated Mershinola, VTH, Ph 5 of 5 \$512,900 VAV Fume Hood Controls Chemistry, Ph 1 of 2 \$486,875 DOHE-CSU 5 Vear Plan Project Request Total: \$327,607,071 Agency Reported Controls Chemistry, Ph 1 of 3 \$27,507,071 \$350,000 155 48 FY01/02 Replace Deteriorated Steam Distribution System, Ph 2 of 3 \$144,144 138 42 FY01/02 Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3 \$27,607,001 FY02/03 Replace Campus Water Lines, Ph 1 of 3 \$100,000 \$100,000 FY02/03 Replace Deterior | | | | | • | |
| FY05/06 Repairu Utilities - Pingree Park, Ph 1 of 1 \$512.500 FY05/06 Replace Deteriorated Items, Lake Street Greenhouse BRP, Ph 1 of 2 \$438.948 FY05/06 Replace Deteriorated Items, Insectary Potato Virus, Ph 1 of 2 \$237.641 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$797.031 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$643.845 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$643.845 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$643.845 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$643.845 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$6443.845 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$6443.845 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$3128.626 Estimated Long Term Infrastructure Major Maintenance Total: \$32,726,757 Xagency Reported Controlled Maintenance Total: \$255,000 FY01/02 Replace Electrical Panels and Transformers, Ph 1 of 3 \$225,000 FY02/03 Replace Campus Structural Repairs/Cooling Towers/Pumps, Ph 2 of 3 \$100.000 FY02/03 Replace Campus Water Lines, Ph 1 of 3 \$250.000 <td></td> <td></td> <td></td> <td></td> <td>•</td> <td></td> | | | | | • | |
| FY05/06 Replace Deteriorated Items - Lake Street Greenhouse BRP, Ph 1 of 2 \$438,948 FY05/06 Replace Deteriorated Items, Animal Science BRP, Ph 2 of 2 \$666,802 FY05/06 Replace Deteriorated Items, Insecury Potato Virus, Ph 1 of 2 \$237,641 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$797,031 FY05/06 Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3 \$343,348 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$3443,345 FY05/06 Replace Fire Alarms, Ph 3 of 3 \$340,333 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$346,375 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$340,333 FY05/06 Replace Ductwork - Physiology, Ph 2 of 3 \$340,333 FY05/06 Replace Deteriorated Steam Distribution Maintenance Total: \$25,676,777 Strontore Strontoral Correl \$27,567,577 19 8 FY01/02 Replace Electrical Panels and Transformers, Ph 1 of 3 \$255,000 FY01/02 Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3 \$250,000 \$160,000 FY02/03 Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3 \$100,000 \$100,000 \$100,000< | | | | | | |
| FY05/06 Replace Deteriorated Items, Animal Science BRP, Ph 2 of 2 \$686.802 FY05/06 Replace Deteriorated Items, Insectary Potato Virus, Ph 1 of 2 \$237.641 FY05/06 Replace Deteriorated Items, Shepadosn BRP, Ph 2 of 3 \$579.031 FY05/06 Replace Deteriorated Items, Shepadosn BRP, Ph 2 of 3 \$643.845 FY05/06 Replace Ductowck - Physiology, Ph 2 of 3 \$643.845 FY05/06 Replace Ductowck - Physiology, Ph 2 of 3 \$643.845 FY05/06 Replace Ductowck - Physiology, Ph 2 of 3 \$643.845 FY05/06 Replace Ductowck - Physiology, Ph 2 of 3 \$643.845 FY05/06 VAV Fume Hood Controls Chemistry, Ph 1 of 2 \$486.875 DOHE-CSU 5 Year Plan Project Request Total: \$237.661 Estimated Long Term Infrastructure Major Maintenance Total: \$2767.577 Agency Reported Controlled Maintenance Total: \$275.000 155 48 FY01/02 Replace Cellectrical Panels and Transformers, Ph 1 of 3 \$275.000 155 48 FY01/02 Repair/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3 \$200.000 FY02/03 Replace Campus Water Lines, Ph 1 of 3 \$10.000 \$10.000 FY02/03 | | | | | | |
| FY05/06Replace Deteriorated Items, Insectary Potato Virus, Ph 1 of 2\$237,641FY05/06Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3\$797,031FY05/06Replace Deteriorated Mechanical, VTH, Ph 5 of 5\$519,905FY05/06Replace Dictwork - Physiology, Ph 2 of 3\$643,845FY05/06Replace Fire Alarms, Ph 3 of 3\$340,338FY05/06VAV Fume Hood Controls Chemistry, Ph 1 of 2\$486,875DOHE-CSU5 Year Plan Project Request Total:\$33,128,626Estimated Long Term Building Major Maintenance Total:\$27,567,577Agency Reported Controlled Maintenance Total:\$27,567,577Agency Reported Controlled Maintenance Total:\$19,051,849University of Southern Colorado198FY01/02Replace Electrical Panels and Transformers, Ph 1 of 3\$27,560,000FY02/03Replace Celtrical Panels and Transformers, Ph 1 of 3\$250,000FY02/03Replace Campus Water Lines, Ph 2 of 3\$100,000FY02/03Replace Campus Water Lines, Ph 3 of 3\$1,444,143FY02/03Replace Campus Water Lines, Ph 2 of 3\$100,000FY02/03Replace Campus Water Lines, Ph 2 of 3\$100,000FY02/03Replace Ca | | | | | - | |
| FY05/06Replace Deteriorated Items, Shepardson BRP, Ph 2 of 3\$797,031FY05/06Replace Deteriorated Mechanical, VTH, Ph 5 of 5\$519,905FY05/06Replace Ductwork - Physiology, Ph 2 of 3\$643,845FY05/06Replace Deteriorated Mechanical, VTH, Ph 5 of 5\$340,338FY05/06Replace Ductwork - Physiology, Ph 2 of 3\$340,338FY05/06VAV Fume Hood Controls Chemistry, Ph 1 of 2\$486,875DOHE-CSUS Year Plan Project Request Total:\$33,128,626Estimated Long Term Building Major Maintenance Total:\$98,805,646S98,805,646Seplace Deteriorated Steam Distribution System, Ph 2 of 3\$1,444,144198 FY01/02Replace Electrical Panels and Transformers, Ph 1 of 3\$275,00015548 FY01/02Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$250,000FY02/03Replace Campus Structural Repairs/Safety Study, Ph 1 of 1\$180,000FY02/03Replace Deteriorated Steam Distribution System, Ph 2 of 3\$14,441,413FY02/03Replace Campus Water Lines, Ph 1 of 3\$250,000FY02/03Replace Deteriorated Steam Distribution System, Ph 2 of 3\$100,000FY02/03Replace Electrical Panels and Transformers, Ph 2 of 3\$1444,143FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Campus Water Lines, Ph 1 of 3\$200,000FY02/03Replace Campus Water Lines, Ph 1 of 3\$200,000FY03/04Replace Collers/Collers/Cooling Towers/Pumps, Ph 3 of 3\$200,000FY03/04R | | | | | - | |
| FY05/06Replace Deteriorated Mechanical, VTH, Ph 5 of 5\$\$19,905FY05/06Replace Ductwork - Physiology, Ph 2 of 3\$643,845FY05/06Replace Fire Alams, Ph 3 of 3\$340,338FY05/06VAV Fume Hood Controls Chemistry, Ph 1 of 2\$486,875DOHE-CSU\$ Year Plan Project Request Total: \$89,805,646Estimated Long Term Building Major Maintenance Total: Agency Reported Controlled Maintenance Total: \$27,567,577198FV01/02M00035Replace Electrical Panels and Transformers, Ph 1 of 3\$27,567,577198FY01/02Replace Electrical Panels and Transformers, Ph 1 of 3\$27,567,577198FY01/02Replace Electrical Panels and Transformers, Ph 1 of 3\$27,567,577198FY01/02Replair/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$27,567,577198FY01/02Replair/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$27,500198FY01/02Replair/Replace Chillers/Cooling Towers/Pumps, Ph 2 of 3\$100,000FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$11,444,14418FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$100,000FY02/03Replace Campus Water Lines, Ph 1 of 3\$200,000FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$200,000FY02/03Replace Deteriorated | | | | | | |
| FY05/06Replace Ductwork - Physiology, Ph 2 of 3\$643,845FY05/06Replace Fire Alarms, Ph 3 of 3\$340,338FY05/06VAV Fume Hood Controls Chemistry, Ph 1 of 2\$486,875DOHE-CSU5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Agency Reported Controlled Maintenance Total: ZT,567,577198FY01/02M00035Replace Deteriorated Steam Distribution System, Ph 2 of 3\$1,444,14413842FY01/02Replace Electrical Panels and Transformers, Ph 1 of 3\$275,00015548FY01/02Replarce Chillers/Cooling Towers/Pumps, Ph 1 of 3\$250,000FY02/03Replar/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$250,000FY02/03Replar/Replace Chillers/Cooling Towers/Pumps, Ph 2 of 3\$300,000FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replar/Replace Chillers/Cooling Towers/Pumps, Ph 2 of 3\$300,000FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Campus Water Lines, Ph 1 of 1\$200,000FY03/04Replarce Campus Water Lines, Ph 1 of 3\$275,000FY03/04Replarce Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replarce Chillers/Cooling Towers/Pumps, Ph 3 of 3\$200,000FY03/04Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of | | | | | • | |
| FY05/06Replace Fire Alarms, Ph 3 of 3\$340,338FY05/06VAV Fume Hood Controls Chemistry, Ph 1 of 2\$486,875DOHE-CSU5 Year Plan Project Request Total:\$33,128,626Estimated Long Term Building Major Maintenance Total:\$39,805,646Lestimated Long Term Infrastructure Major Maintenance Total:\$27,567,577Agency Reported Controlled Maintenance Total:\$27,567,577198 FV01/02M00035Replace Electrical Panels and Transformers, Ph 1 of 3\$1,444,14413842 FY01/02Replace Electrical Panels and Transformers, Ph 1 of 3\$275,000FY01/02Repair/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$250,000FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY03/04Replace Campus Water Lines, Ph 1 of 3\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$270,000FY03/04Replace Compus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Compus Water Lines, Ph 2 of 3\$220,000FY03/04Replace Roofs: Administration, Library an | | | | | | |
| FY05/06VAV Fume Hood Controls Chemistry, Ph 1 of 2\$\$486,875DOHE-CSU\$ Year Plan Project Request Total: \$\$33,128,626Bistimated Long Term Building Major Maintenance Total: Estimated Long Term Building Major Maintenance Total: \$\$27,567,577 Agency Reported Controlled Maintenance Total: \$\$275,007\$\$39,805,646University of Southern ColoradoElectrical Panels and Transformers, Ph 1 of 3\$\$1,444,14413842FY01/02Replace Electrical Panels and Transformers, Ph 1 of 3\$\$275,00015548FY01/02Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$\$250,000FY02/03Replar/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$\$250,000FY02/03Replar/Replace Chillers/Cooling Towers/Pumps, Ph 2 of 3\$\$1,444,143FY02/03Replace Campus Water Lines, Ph 1 of 3\$\$100,000FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$\$1,444,143FY02/03Replace Campus Water Lines, Ph 1 of 2\$\$00,000FY03/04Replar/Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$\$1,444,143FY03/04Replar/Campus Service Accesses, Ph 1 of 1\$\$200,000FY03/04Replare Campus Water Lines, Ph 2 of 3\$\$180,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$\$270,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$\$270,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$\$240,700FY04/05Repla | | | | | | |
| DOHE-CSU5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: 327,567,577 \$150,501,849University ofSouthern Colorado198FY01/02M00035Replace Deteriorated Steam Distribution System, Ph 2 of 3 Replace Electrical Panels and Transformers, Ph 1 of 3\$1,444,14413842FY01/02Replace Electrical Panels and Transformers, Ph 1 of 3\$275,00015548FY01/02Replar/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$250,000FY02/03Replair/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$100,000FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY03/04Replace Campus Water Lines, Ph 1 of 2\$800,000FY03/04Replair/Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replair Campus Service Accesses, Ph 1 of 1\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$220,000FY03/04Replace Campus Water Lines, Ph 3 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 3 of 3\$220,000FY03/04Replace Campus Water Lines, Ph 3 of 3\$220,000FY03/04Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05< | | | | | | |
| Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: \$150,501,849University of Southern Colorado198FY01/02M00035Replace Deteriorated Steam Distribution System, Ph 2 of 3\$1,444,14413842FY01/02Replace Electrical Panels and Transformers, Ph 1 of 3\$275,00015548FY01/02Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$250,000FY02/03Replace Chillers/Cooling Towers/Pumps, Ph 2 of 3\$300,000FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY02/03Replace Clearcial Panels and Transformers, Ph 2 of 3\$100,000FY02/03Replace Electrical Panels and Transformers, Ph 2 of 3\$100,000FY02/03Replace Electricat Panels and Transformers, Ph 2 of 3\$100,000FY03/04Replace Campus Service Accesses, Ph 1 of 1\$200,000FY03/04Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Repaire/Replace Mindust Repairs, Ph 2 of 2\$775,000FY04/05Replace Repair | | | 1103/00 | | - | |
| Estimated Long Term Infrastructure Major Maintenance Total: \$27,567,577 Xgency Reported Controlled Maintenance Total: \$2150,501,849 University of Southern Colorado 19 8 FY01/02 M00035 Replace Deteriorated Steam Distribution System, Ph 2 of 3 \$1,444,144 138 42 FY01/02 Replace Electrical Panels and Transformers, Ph 1 of 3 \$275,000 155 48 FY01/02 Repair/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3 \$250,000 FY02/03 Repair/Replace Chillers/Cooling Towers/Pumps, Ph 2 of 3 \$100,000 FY02/03 Replace Campus Water Lines, Ph 1 of 3 \$100,000 FY02/03 Replace Deteriorated Steam Distribution System, Ph 3 of 3 \$1,444,143 FY02/03 Replace Deteriorated Steam Distribution System, Ph 3 of 3 \$100,000 FY02/03 Replace Campus Water Lines, Ph 1 of 2 \$800,000 FY03/04 Campus/Building Structural Repairs, Ph 1 of 2 \$800,000 FY03/04 Repair/Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3 \$275,000 FY03/04 Replace Campus Water Lines, Ph 2 of 3 \$200,000 FY03/04 Replace Campus Water Lines, Ph 2 of 3 \$200,000 FY03/04 <td< td=""><td></td><td></td><td></td><td></td><td>· ·</td><td></td></td<> | | | | | · · | |
| Agency Reported Controlled Maintenance Total:\$150,501,849University of Southern Colorado198FY01/02M00035Replace Deteriorated Steam Distribution System, Ph 2 of 3\$1,444,14413842FY01/02Replace Electrical Panels and Transformers, Ph 1 of 3\$275,00015548FY01/02Campus Structural Repair/Safety Study, Ph 1 of 1\$180,000FY02/03Repair/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$200,000FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Electrical Panels and Transformers, Ph 2 of 3\$800,000FY03/04Replace Campus Service Accesses, Ph 1 of 1\$200,000FY03/04Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Compus Water Lines, Ph 2 of 3\$270,000FY03/04Replace Consup Water Lines, Ph 2 of 3\$270,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05 <t< td=""><td></td><td colspan="4"></td><td></td></t<> | | | | | | |
| University of Southern Colorado 19 8 FY01/02 M00035 Replace Deteriorated Steam Distribution System, Ph 2 of 3 \$1,444,144 138 42 FY01/02 Replace Electrical Panels and Transformers, Ph 1 of 3 \$275,000 155 48 FY01/02 Repair/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3 \$250,000 FY02/03 Repair/Replace Chillers/Cooling Towers/Pumps, Ph 2 of 3 \$300,000 FY02/03 Replace Campus Water Lines, Ph 1 of 3 \$100,000 FY02/03 Replace Deteriorated Steam Distribution System, Ph 3 of 3 \$1,444,143 FY02/03 Replace Electrical Panels and Transformers, Ph 2 of 3 \$100,000 FY03/04 Campus/Building Structural Repairs, Ph 1 of 2 \$800,000 FY03/04 Replace Campus Service Accesses, Ph 1 of 1 \$200,000 FY03/04 Replace Campus Water Lines, Ph 2 of 3 \$200,000 FY03/04 Replace Campus Water Lines, Ph 2 of 3 \$200,000 FY03/04 Replace Campus Water Lines, Ph 2 of 3 \$200,000 FY03/04 Replace Campus Water Lines, Ph 2 of 3 \$200,000 FY03/04 Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3 \$215,100 | | | | | | |
| 198FY01/02M00035Replace Deteriorated Steam Distribution System, Ph 2 of 3\$1,444,14413842FY01/02Replace Electrical Panels and Transformers, Ph 1 of 3\$275,00015548FY01/02Campus Structural Repairs/Safety Study, Ph 1 of 1\$180,000FY02/03Repair/Replace Chillers/Cooling Towers/Pumps, Ph 2 of 3\$300,000FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Electrical Panels and Transformers, Ph 2 of 3\$180,000FY03/04Replace Electrical Panels and Transformers, Ph 2 of 3\$180,000FY03/04Replace Electrical Panels and Transformers, Ph 2 of 3\$180,000FY03/04Replace Campus Water Lines, Ph 1 of 2\$800,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$220,000FY03/04Replace Compus Water Lines, Ph 2 of 3\$220,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$220,000FY03/04Replace Campus Water Lines, Ph 2 of 2\$775,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$220,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$220,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$225,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$225,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05Replace Roofs: Administration, Lib | | | | | Agency Reported Controlled Maintenance Total. | \$150,501,649 |
| 13842FY01/02Replace Electrical Panels and Transformers, Ph 1 of 3\$275,00015548FY01/02Campus Structural Repairs/Safety Study, Ph 1 of 1\$180,000FY01/02Repair/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$250,000FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY02/03Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Electrical Panels and Transformers, Ph 2 of 3\$180,000FY03/04Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Electrical Panels and Transformers, Ph 2 of 3\$180,000FY03/04Replace Campus Water Lines, Ph 1 of 2\$800,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY05/06Leak Prevention - Repair/Replace Windo | Univ | ersity o | of Southern | n Colorad | 0 | |
| 15548FY01/02Campus Structural Repairs/Safety Study, Ph 1 of 1\$180,000FY01/02Repair/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$250,000FY02/03Repair/Replace Chillers/Cooling Towers/Pumps, Ph 2 of 3\$300,000FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY02/03M00035Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Electrical Panels and Transformers, Ph 2 of 3\$180,000FY03/04Replace Electrical Panels and Transformers, Ph 2 of 3\$200,000FY03/04Replace Campus Service Accesses, Ph 1 of 1\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, P | 19 | 8 | 8 FY01/02 | M00035 | Replace Deteriorated Steam Distribution System, Ph 2 of 3 | \$1,444,144 |
| FY01/02Repair/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3\$250,000FY02/03Repair/Replace Chillers/Cooling Towers/Pumps, Ph 2 of 3\$300,000FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY02/03M00035Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Electrical Panels and Transformers, Ph 2 of 3\$180,000FY03/04Campus/Building Structural Repairs, Ph 1 of 2\$880,000FY03/04Replace Electrical Panels and Transformers, Ph 3 of 3\$220,000FY03/04Repair Campus Service Accesses, Ph 1 of 1\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$150,000FY05/06Leak Prevention - Repair /Replace Windows, Ph 1 of 1\$300,000FY | 138 | 42 | 2 FY01/02 | | Replace Electrical Panels and Transformers, Ph 1 of 3 | \$275,000 |
| FY02/03Repair/Replace Chillers/Cooling Towers/Pumps, Ph 2 of 3\$300,000FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY02/03M00035Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Electrical Panels and Transformers, Ph 2 of 3\$180,000FY03/04Campus/Building Structural Repairs, Ph 1 of 2\$800,000FY03/04Repair Campus Service Accesses, Ph 1 of 1\$200,000FY03/04Repair Campus Service Accesses, Ph 1 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Repair Canels and Transformers, Ph 3 of 3\$270,000FY03/04Replace Reoofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$2250,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$11,700FY05/06Leak Prevention - Repair Amep Adust Classroom, Ph 3 of 3\$131,700< | 155 | 48 | 8 FY01/02 | | Campus Structural Repairs/Safety Study, Ph 1 of 1 | \$180,000 |
| FY02/03Replace Campus Water Lines, Ph 1 of 3\$100,000FY02/03M00035Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Electrical Panels and Transformers, Ph 2 of 3\$180,000FY03/04Campus/Building Structural Repairs, Ph 1 of 2\$800,000FY03/04Repair Campus Service Accesses, Ph 1 of 1\$200,000FY03/04Repair/Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Electrical Panels and Transformers, Ph 3 of 3\$270,000FY03/04Replace Confis: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700FY05/06Replace Roofs: Administration, L | | | FY01/02 | | Repair/Replace Chillers/Cooling Towers/Pumps, Ph 1 of 3 | \$250,000 |
| FY02/03M00035Replace Deteriorated Steam Distribution System, Ph 3 of 3\$1,444,143FY02/03Replace Electrical Panels and Transformers, Ph 2 of 3\$180,000FY03/04Campus/Building Structural Repairs, Ph 1 of 2\$800,000FY03/04Repair Campus Service Accesses, Ph 1 of 1\$200,000FY03/04Repair/Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Electrical Panels and Transformers, Ph 3 of 3\$270,000FY03/04Replace Electrical Panels and Transformers, Ph 3 of 3\$270,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$250,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$250,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$250,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$250,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$250,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$300,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$300,000FY05/06Leak Pr | | | FY02/03 | | Repair/Replace Chillers/Cooling Towers/Pumps, Ph 2 of 3 | \$300,000 |
| FY02/03Replace Electrical Panels and Transformers, Ph 2 of 3\$180,000FY03/04Campus/Building Structural Repairs, Ph 1 of 2\$800,000FY03/04Repair Campus Service Accesses, Ph 1 of 1\$200,000FY03/04Repair/Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Electrical Panels and Transformers, Ph 3 of 3\$277,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY04/05Campus/Building Structural Repairs, Ph 2 of 2\$775,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$250,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$250,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000K4,000,000\$250,000\$17,000,000FY05/06Re | | | | | | |
| FY03/04Campus/Building Structural Repairs, Ph 1 of 2\$800,000FY03/04Repair Campus Service Accesses, Ph 1 of 1\$200,000FY03/04Repair/Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Electrical Panels and Transformers, Ph 3 of 3\$270,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY04/05Campus/Building Structural Repairs, Ph 2 of 2\$775,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05Replace Campus/Building Structural Repairs, Ph 2 of 2\$775,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace/Repair Campus Building Exit Doors, Ph 1 of 1\$150,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$4,000,000 | | | FY02/03 | M00035 | Replace Deteriorated Steam Distribution System, Ph 3 of 3 | \$1,444,143 |
| FY03/04Repair Campus Service Accesses, Ph 1 of 1\$200,000FY03/04Repair/Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Electrical Panels and Transformers, Ph 3 of 3\$270,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY04/05Campus/Building Structural Repairs, Ph 2 of 2\$775,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$220,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$150,000FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000Fytomole Leak Dreg Term Infrastructure Major Maintenance Total:\$4,000,000 | | | | | - | |
| FY03/04Repair/Replace Chillers/Cooling Towers/Pumps, Ph 3 of 3\$275,000FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Electrical Panels and Transformers, Ph 3 of 3\$270,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY04/05Campus/Building Structural Repairs, Ph 2 of 2\$775,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$2250,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace/Repair Campus Building Exit Doors, Ph 1 of 1\$150,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$300,000FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000Estimated Long Term Infrastructure Major Maintenance Total:\$4,000,000 | | | | | | \$800,000 |
| FY03/04Replace Campus Water Lines, Ph 2 of 3\$200,000FY03/04Replace Electrical Panels and Transformers, Ph 3 of 3\$270,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY04/05Campus/Building Structural Repairs, Ph 2 of 2\$775,000FY04/05Replace Campus Water Lines, Ph 2 of 3\$250,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$220,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace/Repair Campus Building Exit Doors, Ph 1 of 1\$150,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000F400,000\$4,000,000 | | | | | | |
| FY03/04Replace Electrical Panels and Transformers, Ph 3 of 3\$270,000FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY04/05Campus/Building Structural Repairs, Ph 2 of 2\$775,000FY04/05Repair Underground Storage Tanks, Ph 1 of 1\$120,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$250,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace/Repair Campus Building Exit Doors, Ph 1 of 1\$150,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$1131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$4,000,000 | | | | | | |
| FY03/04Replace Roofs: Administration, Library and Music Classroom, Ph 1 of 3\$215,100FY04/05Campus/Building Structural Repairs, Ph 2 of 2\$775,000FY04/05Repair Underground Storage Tanks, Ph 1 of 1\$120,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$250,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace/Repair Campus Building Exit Doors, Ph 1 of 1\$150,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000Fy05/06Estimated Long Term Infrastructure Major Maintenance Total:\$4,000,000 | | | | | • • | |
| FY04/05Campus/Building Structural Repairs, Ph 2 of 2\$775,000FY04/05Repair Underground Storage Tanks, Ph 1 of 1\$120,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$250,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace/Repair Campus Building Exit Doors, Ph 1 of 1\$150,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000\$4,000,000\$4,000,000 | | | | | • | |
| FY04/05Repair Underground Storage Tanks, Ph 1 of 1\$120,000FY04/05Replace Campus Water Lines, Ph 3 of 3\$250,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace/Repair Campus Building Exit Doors, Ph 1 of 1\$150,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000\$4,000,000\$4,000,000\$4,000,000 | | | | | • | |
| FY04/05Replace Campus Water Lines, Ph 3 of 3\$250,000FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace/Repair Campus Building Exit Doors, Ph 1 of 1\$150,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000\$4,000,000\$4,000,000\$4,000,000 | | | | | | |
| FY04/05Replace Roofs: Administration, Library and Music Classroom, Ph 2 of 3\$240,700FY04/05Replace/Repair Campus Building Exit Doors, Ph 1 of 1\$150,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000\$4,000,000 | | | | | | |
| FY04/05Replace/Repair Campus Building Exit Doors, Ph 1 of 1\$150,000FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000Estimated Long Term Infrastructure Major Maintenance Total:\$4,000,000 | | | | | | |
| FY05/06Leak Prevention - Repair and Patch Exterior Finishes and Panels, Ph 1 of 1\$250,000FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000\$4,000,000 | | | | | | |
| FY05/06Leak Prevention - Repair/Replace Windows, Ph 1 of 1\$300,000FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC 5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000Stimated Long Term Infrastructure Major Maintenance Total:\$4,000,000 | | | | | | |
| FY05/06Replace Roofs: Administration, Library and Music Classroom, Ph 3 of 3\$131,700DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000Estimated Long Term Infrastructure Major Maintenance Total:\$4,000,000 | | | | | | |
| DOHE-USC5 Year Plan Project Request Total:\$8,350,787Estimated Long Term Building Major Maintenance Total:\$17,000,000Estimated Long Term Infrastructure Major Maintenance Total:\$4,000,000 | | | | | | |
| Estimated Long Term Building Major Maintenance Total: \$17,000,000 Estimated Long Term Infrastructure Major Maintenance Total: \$4,000,000 | | | 1 103/00 | | | |
| Estimated Long Term Infrastructure Major Maintenance Total: \$4,000,000 | | | | | | |
| | | | | | | |
| Agency Reported Controlled Maintenance Total: \$29,330,787 | | | | | | |
| | | | | | Agency Reported Controlled Maintenance Total: | φ ∠3, 330,101 |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|-----------|-----------------|----------------|--|------------------------|
| Fort | Lewis C | ollege | | | |
| 58 | 15 | FY01/02 | | Replace Sewers/Pavement/Sidewalks, North Campus, Ph 1 of 1 | \$1,221,885 |
| 87 | 20 | FY01/02 | | Repair/Replace Geology Storage Building, Ph 1 of 1 | \$296,744 |
| 103 | 24 | FY01/02 | | Replace Deteriorated Tennis Courts, Ph 1 of 2 | \$94,090 |
| 144 | 42 | FY01/02 | | Replace Sewers/Pavement/Sidewalks, Central Campus, Ph 1 of 3 | \$223,382 |
| | | FY01/02 | | Rehabilitate Deteriorated Stadium Facility, Ph 1 of 1 | \$607,000 |
| | | FY02/03 | | Replace Deteriorated Tennis Courts, Ph 2 of 2 | \$790,900 |
| | | FY02/03 | | Replace Sewers/Pavement/Sidewalks, Central Campus, Ph 2 of 3 | \$908,600 |
| | | FY03/04 | | Repair/Replace Deteriorated Pavements-South Campus, Ph 1 of 1 | \$648,000 |
| | | FY03/04 | | Repair/Replace Deteriorated Theatre Facility, Ph 1 of 2 | \$525,000 |
| | | FY03/04 | | Replace Sewers/Pavement/Sidewalks, Central Campus, Ph 3 of 3 | \$825,220 |
| | | FY03/04 | | Structural Repair/Replacement, Ph 1 of 2 | \$800,000 |
| | | FY04/05 | | Repair/Replace Deteriorated Pavements-West Campus, Ph 1 of 1 | \$538,000 |
| | | FY04/05 | | Repair/Replace Deteriorated Theatre Facility, Ph 2 of 2 | \$638,000 |
| | | FY04/05 | | Repair/Replace Mechanical Systems-Noble Hall, Ph 1 of 1 | \$684,000 |
| | | FY04/05 | | Structural Repair/Replacement, Ph 2 of 2 | \$720,000 |
| | | FY05/06 | | Repair/Replace Mechanical and Electrical Systems Berndt Hall East, Ph 1 of 1 | \$497,000 |
| | | FY05/06 | | Replace Roof Noble Hall, Ph 1 of 1 | \$447,000 |
| | | | | · · · | \$10,464,821 |
| | | | | | \$10,372,608 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$20,837,429 |
| Univ | ersity of | f Northern | Colorado | | |
| 35 | - | FY01/02 | | Water Main Improvements Central/West Campus, Ph 1 of 2 | \$75,418 |
| 54 | | FY01/02 | M00053 | | \$480,872 |
| 79 | | FY01/02 | | | \$393,197 |
| 94 | | FY01/02 | | • • • | \$580,480 |
| 112 | | FY01/02 | 1000001 | Replace Theater Ceiling Frasier Hall, Ph 1 of 1 | \$360,792 |
| 140 | | FY01/02 | | Replace Deteriorated Systems Gray Hall, Ph 1 of 3 | \$824,296 |
| 110 | | FY01/02 | | Replace Boiler #1 Heating Plant, Ph 1 of 2 | \$769,900 |
| | | FY01/02 | | Replace Buried HTHW Mains form Heating Plant to 19th Street Vault, Ph 1 of 2 | |
| | | FY01/02 | | Replace Cor-Ten Steel Wall Panel Butler Hancock Hall, Ph 1 of 1 | \$372,492 |
| | | FY02/03 | | Emergency Generator Michener Library, Ph 1 of 1 | \$266,399 |
| | | FY02/03 | | Rebalance HVAC Systems, Ph 1 of 2 | \$61,500 |
| | | FY02/03 | | Replace Boiler #1 Heating Plant, Ph 2 of 2 | \$584,000 |
| | | FY02/03 | | Replace Buried HTHW Mains from Heating Plant to 19th Street Vault, Ph 2 of 2 | |
| | | FY02/03 | | Replace Chiller Kepner Hall, Ph 1 of 2 | \$50,000 |
| | | FY02/03 | | Replace Deteriorated Systems Gray Hall, Ph 2 of 3 | \$720,165 |
| | | FY02/03 | | Replace Flooring Kepner Hall, Ph 1 of 1 | \$110,428 |
| | | FY02/03 | | Water Main Improvements Central/West Campus, Ph 2 of 2 | \$533,985 |
| | | FY03/04 | | Rebalance HVAC Systems, Ph 2 of 2 | \$610,050 |
| | | FY03/04 | | Replace Center Section Roof McKee Hall, Ph 1 of 1 | \$200,000 |
| | | FY03/04 | | Replace Chiller Kepner Hall, Ph 2 of 2 | \$375,000 |
| | | FY03/04 | | Replace Deteriorated Systems Gray Hall, Ph 3 of 3 | \$450,265 |
| | | FY03/04 | | Replace Roof Candelaria Hall, Ph 1 of 1 | \$200,000 |
| | | FY03/04 | | Window Replacement Frasier Hall and Carter Hall, Ph 1 of 2 | \$500,800 |
| | | FY04/05 | | Replace Chiller (Carter Hall), Leibert Units and HVAC Upgrades (Computer | \$500,000 \$500,000 |
| | | 1 10-7/00 | | Center), Ph 1 of 1 | ψυυυ,υυυ |
| | | FY04/05 | | Upgrade Building Automation System Campus Wide, Ph 1 of 1 | \$500,000 |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|-----------|--|----------------|--|--|
| | | FY04/05 FY04/05 FY05/06 FY05/06 | | Upgrade Existing Fire Alarm Systems, Ph 1 of 1 Window Replacement Frasier Hall and Carter Hall, Ph 2 of 2 Exterior Door and Hardware Replacement, Ph 1 of 1 Internal Electrical Distribution, Ph 1 of 1 | \$600,000 \$619,200 \$200,000 \$1,500,000 |
| | | | | DOHE-UNC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: | \$17,743,332 \$20,083,442 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$0 \$37,826,774 |
| Adar | ms State | e College | | | |
| 26 | | FY01/02 | | Upgrade Campus Fire Alarm System, Ph 1 of 1 | \$600,390 |
| 46 | 12 | FY01/02 | M00027 | | \$174,296 |
| 62 | 16 | FY01/02 | | Repair/Replace Stadium Field House Bleachers, Ph 1 of 2 | \$368,267 |
| 100 | 24 | FY01/02 | | Upgrade Campus Irrigation, Ph 1 of 3 | \$25,000 |
| 124 | 30 | FY01/02 | | Replace Doors/Windows, Various Buildings, Ph 1 of 2 | \$496,854 |
| 153 | 48 | FY01/02 | | Replace Sewer Line Richardson Hall and Business and Economics, Ph 1 of 1 | \$132,319 |
| | | FY01/02 | | Roof Replacement - Various Buildings, Ph 1 of 3 | \$344,571 |
| | | FY02/03 | | Repair/Replace Stadium Field House Bleachers, Ph 2 of 2 | \$170,216 |
| | | FY02/03 | | Replace Doors/Windows, Various Buildings, Ph 2 of 2 | \$282,238 |
| | | FY02/03 | | Roof Replacement - Various Buildings, Ph 2 of 3 | \$636,382 |
| | | FY02/03 | | Upgrade Campus Irrigation, Ph 2 of 3 | \$522,500 |
| | | FY03/04 | | Roof Replacement - Various Buildings, Ph 3 of 3 | \$571,106 |
| | | FY03/04 | | Upgrade Campus Irrigation, Ph 3 of 3 | \$818,476 |
| | | FY04/05 | | Electrical Code Deficiencies, Ph 1 of 1 | \$48,436 |
| | | FY04/05 | | Replace Parking Lot Maintenance, Ph 1 of 2 | \$645,810 |
| | | FY05/06 | | Elevator Upgrades Library and ES, Ph 1 of 1 | \$130,000 |
| | | FY05/06 | | Leon Seating and Paint, Ph 1 of 1 | \$125,000 |
| | | FY05/06 | | Plachy Pool Piping, Ceiling and Tile, Ph 1 of 1 | \$130,000 |
| | | FY05/06 | | Replace Parking Lot Maintenance, Ph 2 of 2 | \$622,724 |
| | | | | DOHE-ASC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: | \$6,844,585 \$4,231,052 |
| | | | | Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: | \$4,231,952 \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$11,076,537 |
| Mesa | a State (| College | | | |
| 80 | 18 | FY01/02 | M90020 | Building Repairs, Walter Walker Fine Arts Center, Ph 3 of 4 | \$435,209 |
| 123 | 30 | FY01/02 | M80034 | Building Repairs - Houston Hall, Ph 4 of 4 | \$325,493 |
| 130 | 35 | FY01/02 | | Electrical Service and Lighting Houston Hall, Ph 1 of 1 | \$468,160 |
| | | FY02/03 | M90020 | Building Repairs, Walter Walker Fine Arts Center, Ph 4 of 4 | \$467,667 |
| | | FY02/03 | | Repair Elevator, Heiny Hall and Saunders Field House, Ph 1 of 2 | \$82,500 |
| | | FY02/03 | | Replace Carpet Houston Hall and Heiny Hall, Ph 1 of 1 | \$333,554 |
| | | FY03/04 | | Repair Elevator, Heiny Hall and Saunders Field House, Ph 2 of 2 | \$82,500 |
| | | FY03/04 | | Repair Roof Saunders Field House and Library, Ph 1 of 2 | \$318,012 |
| | | FY03/04 | | Replace Library Air Handling Units, Ph 1 of 1 | \$362,500 |
| | | FY04/05 | | Repair Handball Courts Saunders Field House, Ph 1 of 1 | \$90,782 |
| | | FY04/05 | | Repair Roof Saunders Field House and Library, Ph 2 of 2 | \$395,312 |
| | | FY04/05 | | Site Lighting Project, Ph 1 of 1 | \$184,500 |
| | | FY05/06 | | Repair Roof, UTEC, Ph 1 of 1 | \$270,500 |
| | | FY05/06 | | Replace Sidewalks, Ph 1 of 1 | \$60,000 |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|----------|-----------------|----------------|--|---|
| | | | | DOHE-MSC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$3,876,689 \$9,503,536 \$745,985 \$14,126,210 |
| Wee | torn Sta | te College | | | |
| 24 | | FY01/02 | | Repair/Replace Miscellaneous Fire Alarm System, Ph 2 of 2 | \$94,050 |
| 105 | | FY01/02 | 11100020 | Repair/Replace Heating/HVAC, Systems, Ph 1 of 1 | \$396,210 |
| 108 | | | M00030 | Repair/Replace Parking Lots/Streets - Zone 1, Ph 2 of 5 | \$365,279 |
| 127 | | FY01/02 | | Repair/Replace Roofing System, Ph 1 of 2 | \$275,375 |
| 137 | | FY01/02 | | Repair/Replace Pool and Filter System, Ph 1 of 2 | \$234,598 |
| 147 | | FY01/02 | M00030 | Repair/Replace Parking Lots/Streets - Zone 1, Ph 3 of 5 | \$329,394 |
| | - | FY01/02 | | Repair/Replace Track, Ph 1 of 1 | \$516,261 |
| | | FY02/03 | | Repair/Replace Electrical Power Distribution, Ph 1 of 3 | \$371,340 |
| | | FY02/03 | | Repair/Replace Exterior Shell, Ph 1 of 2 | \$382,181 |
| | | FY02/03 | | Repair/Replace Pool and Filter System, Ph 2 of 2 | \$300,000 |
| | | FY02/03 | | Repair/Replace Roofing System, Ph 2 of 2 | \$232,000 |
| | | FY02/03 | | Repair/Replace Temperature Controls, Ph 1 of 2 | \$254,449 |
| | | FY03/04 | | Repair/Replace Electrical Power Distribution, Ph 2 of 3 | \$269,216 |
| | | FY03/04 | | Repair/Replace Exterior Shell, Ph 2 of 2 | \$285,052 |
| | | FY03/04 | M00030 | Repair/Replace Parking Lots/Streets - Zone 1, Ph 4 of 5 | \$337,840 |
| | | FY03/04 | | Repair/Replace Sewer Distribution System, Ph 1 of 2 | \$376,169 |
| | | FY03/04 | | Repair/Replace Temperature Controls, Ph 2 of 2 | \$251,268 |
| | | FY04/05 | | Repair Plumbing System, Ph 1 of 1 | \$384,375 |
| | | FY04/05 | | Repair/Replace Electrical Power Distribution, Ph 3 of 3 | \$332,561 |
| | | FY04/05 | M00030 | Repair/Replace Parking Lots/Streets - Zone 1, Ph 5 of 5 | \$269,692 |
| | | FY04/05 | | Repair/Replace Sewer Distribution System, Ph 2 of 2 | \$283,283 |
| | | FY05/06 | | Electrical Switch Gear and Distribution System, Ph 1 of 2 | \$375,000 |
| | | FY05/06 | | Rehabilitate Heat Plant, Ph 1 of 2 | \$525,000 |
| | | FY05/06 | | Repair/Replace Building Steam Distribution System, Ph 1 of 2 | \$225,000 |
| | | | | DOHE-WSC 5 Year Plan Project Request Total: | \$7,665,593 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$4,524,076 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$1,684,273 \$13,873,942 |
| 0.1. | | heel of M | • | | |

| Colorado | School | of | Mines | |
|----------|--------|-----|-------|--|
| | | ••• | | |

| 29 | 10 FY01/02 | Campus Pool HVAC Replacement, Ph 1 of 2 | \$887,900 |
|-----|------------|---|-----------|
| 40 | 12 FY01/02 | Campus Primary Electrical Power Distribution, Ph 1 of 1 | \$396,740 |
| 88 | 20 FY01/02 | Green Center Roof and Abatement Assessment, Ph 1 of 1 | \$48,620 |
| 97 | 24 FY01/02 | Campus Secondary Electrical Power Repair Deficiency Assessment, Ph 1 of 1 | \$55,176 |
| 156 | 54 FY01/02 | Campus Pool HVAC Replacement, Ph 2 of 2 | \$365,240 |
| | FY02/03 | Berthoud Hall Air Handler, Ph 1 of 1 | \$79,000 |
| | FY02/03 | Campus Roofs, Windows, Skylight Repairs, Ph 1 of 1 | \$350,900 |
| | FY02/03 | Campus Secondary Electrical Power Repairs, Ph 1 of 2 | \$524,800 |
| | FY03/04 | Brown Hall HVAC Replacement, Ph 1 of 2 | \$884,169 |
| | FY03/04 | Campus Secondary Electrical Power Repairs, Ph 2 of 2 | \$351,000 |
| | FY03/04 | Guggenheim HVAC Replacement, Ph 1 of 2 | \$692,887 |
| | FY04/05 | Brown Hall HVAC Replacement, Ph 2 of 2 | \$960,617 |
| | FY04/05 | Guggenheim HVAC Replacement, Ph 2 of 2 | \$480,060 |
| | FY05/06 | Brooks Field Bleacher Replacement, Ph 1 of 1 | \$482,625 |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|-----------|--------------------|----------------|--|--|
| | | FY05/06 FY05/06 | | Green Center Indoor Air Quality Improvements, Ph 1 of 2 Meyer Hall HVAC Replacement, Ph 1 of 2 | \$510,000 \$751,000 |
| | | | | DOHE-CSM 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$7,820,734 \$31,708,000 \$1,750,000 \$41,278,734 |
| Aura | aria High | ner Educat | ion Cente | er | |
| 20 | - | FY01/02 | | | \$667,900 |
| 31 | 10 | FY01/02 | M90078 | Repair/Replace Electrical High Voltage Cable System - Campus, Ph 3 of 4 | \$1,056,200 |
| 68 | 18 | FY01/02 | M00081 | Repair/Replace Roofing/Weathertight Enclosures, Ph 2 of 2 | \$805,600 |
| 131 | 36 | FY01/02 | | Replace Fire Security Monitoring Infrastructure System - Campus, Ph 1 of 1 | \$858,000 |
| | | FY01/02 | | Replace Portions of PE/Events Center and Plaza Building Roofs and Public Safety Roof, Ph 1 of 2 | \$801,000 |
| | | FY02/03 | | Life Cycle Replacement - Repair/Replace System Components, Ph 1 of 3 | \$593,600 |
| | | FY02/03 | | Repair Ninth Street Park Houses, Ph 1 of 2 | \$170,100 |
| | | FY02/03 | M90078 | Repair/Replace Electrical High Voltage Cable System - Campus, Ph 4 of 4 | \$708,500 |
| | | FY02/03 | | Repair/Replace Elevator Systems - Campus, Ph 1 of 3 | \$191,700 |
| | | FY02/03 | | Repair/Replace Mechanical System Components - Campus, Ph 1 of 5 | \$324,800 |
| | | FY02/03 | | Repair/Replace Mechanical Systems South Classroom, Ph 1 of 3 | \$879,600 |
| | | FY02/03 | | Repair/Replace Paving/Curbs at 10th Street Pedestrian Mall and Courtyards, Ph 1 of 4 | \$596,000 |
| | | FY02/03 | M80101 | Repair/Replace Storm Drain System - Campus, Ph 5 of 5 | \$569,200 |
| | | FY02/03 | | Replace Portions of PE/Events Center and Plaza Building Roofs and Public Safety Roof, Ph 2 of 2 | \$319,100 |
| | | FY03/04 | | Life Cycle Replacement - Repair/Replace System Components, Ph 2 of 3 | \$551,400 |
| | | FY03/04 | | Repair Ninth Street Park Houses, Ph 2 of 2 | \$169,700 |
| | | FY03/04 | | Repair/Replace Building Entryways Steps and Walkways - Campus, Ph 1 of 2 | \$135,600 |
| | | FY03/04 | | Repair/Replace Classroom Fixed Seating - Campus, Ph 1 of 2 | \$252,900 |
| | | FY03/04 | | Repair/Replace Elevator Systems - Campus, Ph 2 of 3 | \$191,700 |
| | | FY03/04 | | Repair/Replace Library Curtain Wall, Ph 1 of 3 | \$534,000 |
| | | FY03/04 | | Repair/Replace Mechanical System Components - Campus, Ph 2 of 5 | \$351,300 |
| | | FY03/04 | | Repair/Replace Mechanical Systems South Classroom, Ph 2 of 3 | \$862,800 |
| | | FY03/04 | | Repair/Replace Paving/Curbs at 10th Street Pedestrian Mall and Courtyards, Ph 2 of 4 | \$596,900 |
| | | FY03/04 | | Replace Floor Coverings Campus, Ph 1 of 4 | \$190,600 |
| | | FY04/05 | | Life Cycle Replacement - Repair/Replace System Components, Ph 3 of 3 | \$564,000 |
| | | FY04/05 | | Repair Building Exteriors Campus, Ph 1 of 4 | \$388,200 |
| | | FY04/05 | | Repair/Replace Building Entryways Steps and Walkways - Campus, Ph 2 of 2 | \$132,600 |
| | | FY04/05 | | Repair/Replace Classroom Fixed Seating - Campus, Ph 2 of 2 Repair/Replace Elevator Systems - Campus, Ph 3 of 3 | \$197,900 \$05,800 |
| | | FY04/05 FY04/05 | | Repair/Replace Elevator Systems - Campus, Ph 3 of 3 Repair/Replace Exterior Doors/Window Wall Frames/Railing - Campus, Ph | \$95,800 \$274,900 |
| | | | | 1 of 1 | |
| | | FY04/05 | | Repair/Replace Library Curtain Wall, Ph 2 of 3 | \$534,000 |
| | | FY04/05 | | Repair/Replace Mechanical System Components - Campus, Ph 3 of 5 | \$242,100 |
| | | FY04/05 | | Repair/Replace Mechanical Systems South Classroom, Ph 3 of 3 | \$862,600 \$505,000 |
| | | FY04/05 | | Repair/Replace Paving/Curbs at 10th Street Pedestrian Mall and Courtyards, Ph 3 of 4 | \$595,900 |
| | | FY04/05 | | Replace Floor Coverings Campus, Ph 2 of 4 | \$112,000 |
| | | FY05/06 | | Repair Building Exteriors Campus, Ph 2 of 4 | \$989,800 |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|---------|-----------------|----------------|---|---------------------|
| | | FY05/06 | | Repair/Replace Library Curtain Wall, Ph 3 of 3 | \$534,000 |
| | | FY05/06 | | Repair/Replace Mechanical System Components - Campus, Ph 4 of 5 | \$400,600 |
| | | FY05/06 | | Repair/Replace Paving/Curbs at 10th Street Pedestrian Mall and Courtyards, Ph 4 of 4 | \$595,900 |
| | | FY05/06 | | Replace Floor Coverings Campus, Ph 3 of 4 | \$112,000 |
| | | | | DOHE-AHEC 5 Year Plan Project Request Total: | \$19,010,500 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$4,285,441 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$1,005,000 |
| | | | | Agency Reported Controlled Maintenance Total: | \$24,300,941 |
| Arap | ahoe C | ommunity | College | | |
| 57 | 15 | FY01/02 | M90048 | Roof, Window and Door Replacement: Main, North and Annex, Ph 2 of 2 | \$186,538 |
| 114 | 30 | FY01/02 | M00055 | Structural/Exterior Concrete Repair Main Annex, Ph 2 of 2 | \$375,573 |
| 120 | 30 | FY01/02 | | Replace HVAC Equipment, Ph 1 of 2 | \$383,179 |
| | | FY01/02 | | Asbestos Removal/Carpet Replacement Main, Ph 1 of 1 | \$357,637 |
| | | FY01/02 | | Gym/Fitness Center Repairs Annex, Ph 1 of 1 | \$169,778 |
| | | FY02/03 | | Glass Walkway Replacement Main, Ph 1 of 1 | \$81,259 |
| | | FY02/03 | | Lighting/Ceiling Replacement, Ph 1 of 1 | \$171,480 |
| | | FY02/03 | | Replace HVAC Equipment, Ph 2 of 2 | \$197,510 |
| | | FY02/03 | | Sandblast and Paint HVAC Units and Block Walls, Ph 1 of 1 | \$132,656 |
| | | FY02/03 | | Service Drive Replacement, Ph 1 of 1 | \$175,297 |
| | | FY03/04 | | Emergency Phone Replacement, Ph 1 of 1 | \$56,294 |
| | | FY03/04 | | Irrigation System Repairs, Ph 1 of 1 | \$112,121 |
| | | FY03/04 | | Roof Replacement South, Ph 1 of 1 | \$117,464 |
| | | FY03/04 | | West Bus Duct Replacement, Ph 1 of 1 | \$141,334 |
| | | FY04/05 | | Gasoline Tank Removal/Waste Oil Tank Retrofit, Ph 1 of 1 | \$53,541 |
| | | FY05/06 | | Restroom Partition Replacement Main, Ph 1 of 1 | \$185,147 |
| | | FY05/06 | | Window Blind Replacement North, Ph 1 of 1 | \$70,536 |
| | | | | DOHE-ACC 5 Year Plan Project Request Total: | \$2,967,344 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$2,513,228 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$302,782 |
| | | | | Agency Reported Controlled Maintenance Total: | \$5,783,354 |
| Colo | rado No | orthwester | n Commu | unity College | |
| 3 | 2 | FY01/02 | | Sewer and Electrical Utility Lines Replacement, Rangely Campus, Ph 1 of 1 | \$273,333 |
| 118 | 30 | FY01/02 | | HVAC Modifications and Upgrade - Rangely Campus, Ph 1 of 1 | \$611,500 |
| | | FY01/02 | | Johnson Building Roof Repair and HVAC Replacement, Ph 1 of 1 | \$390,888 |
| | | FY02/03 | | Building Caulking, Painting, Insulation Replacement and Repair, Ph 1 of 1 | \$226,000 |
| | | FY02/03 | | Gym Floor Replacement Hefly Bldg, Ph 1 of 1 | \$379,000 |
| | | FY02/03 | | Weiss Building Walls and Floor Replacement and Repair, Ph 1 of 1 | \$279,000 |
| | | FY03/04 | | Boiler Retube and Repair Johnson Bldg, Ph 1 of 1 | \$55,000 |
| | | FY03/04 | | Irrigation System Upgrade Rangely Campus, Ph 1 of 1 | \$63,000 |
| | | FY03/04 | | Parking Lot Repair and Replacement - Rangely Campus, Ph 1 of 1 | \$488,000 |
| | | FY03/04 | | Sidewalk and Outdoor Lighting Repair Upgrade - Rangely Campus, Ph 1 of 1 | \$229,000 |
| | | FY04/05 | | Building Entrance Security/ADA Upgrades, Ph 1 of 1 | \$411,000 |
| | | FY04/05 | | Campus Fire Detection/Protection System Upgrade, Ph 1 of 1 | \$398,000 |
| | | FY04/05 | | Tennis Court Resurface, Ph 1 of 1 | \$74,000 |
| | | FY05/06 | | Fence Replacement and Repair, Ph 1 of 1 | \$73,000 |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|---------|-----------------|----------------|--|-------------------------|
| | | | | DOHE-CNCC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: | \$3,950,721 \$0 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$0 \$3,950,721 |
| | | | | Agency Reported Controlled Maintenance Total. | φ 3,930,7 21 |
| | - | e Commun | ity Colleg | | |
| 50 | 15 | FY01/02 | | Small Central Plant to Replace Deteriorating Rooftop HVAC Units, Larimer Campus, Ph 1 of 2 | \$1,605,604 |
| 132 | 36 | FY01/02 | | Repair Deficiencies in Electrical Switch Gear, Westminster Campus, Ph 1 of 3 | \$201,488 |
| | | FY02/03 | | Repair Deficiencies in Electrical Switch Gear, Westminster Campus, Ph 2 of 3 | \$766,864 |
| | | FY02/03 | | Replace Emergency Exit Stairs and Doors - Westminster Campus, Ph 1 of 2 | \$469,321 |
| | | FY02/03 | | Roof Replacement - Larimer Campus, Ph 1 of 2 | \$333,500 |
| | | FY02/03 | | Small Central Plant to Replace Deteriorating Rooftop HVAC Units, Larimer Campus, Ph 2 of 2 | \$538,615 |
| | | FY03/04 | | Repair Deficiencies in Electrical Switch Gear, Westminster Campus, Ph 3 of 3 | \$418,360 |
| | | FY03/04 | | Replace Electrical Switchgear - Larimer Campus, Ph 1 of 2 | \$425,300 |
| | | FY03/04 | | Replace Emergency Exit Stairs and Doors - Westminster Campus, Ph 2 of 2 | \$312,880 |
| | | FY03/04 | | Roof Replacement - Larimer Campus, Ph 2 of 2 | \$266,693 |
| | | FY03/04 | | Seal Exterior Block - Westminster Campus, Ph 1 of 1 | \$476,669 |
| | | FY04/05 | | Replace 6 Inch Underground Suppression Pipe - Larimer Campus, Ph 1 of 2 | \$470,000 |
| | | FY04/05 | | Replace Electrical Switchgear - Larimer Campus, Ph 2 of 2 | \$424,600 |
| | | FY04/05 | | Replace Security System - Westminster Campus, Ph 1 of 1 | \$364,938 |
| | | FY05/06 | | Replace 6 Inch Underground Suppression Pipe - Larimer Campus, Ph 2 of 2 | \$200,000 |
| | | FY05/06 | | Replace Elevator - Westminster Campus, Ph 1 of 1 | \$137,839 |
| | | FY05/06 | | Replace Security System - Larimer Campus, Ph 1 of 1 | \$214,000 |
| | | | | DOHE-FRCC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: | \$7,626,671 \$0 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$0 \$7,626,671 |
| Lam | ar Comi | munity Co | lleae | | |
| 15 | | FY01/02 | U | Fire Alarm/Emergency Lighting Modernization, Bowman/Trustees Buildings, Ph 1 of 2 | \$207,211 |
| 81 | 18 | FY01/02 | M00058 | Window Upgrades Bowman/Trustees Buildings, Ph 2 of 2 | \$135,192 |
| | | FY02/03 | | Fire Alarm/Emergency Lighting Modernization, Bowman/Trustees Buildings, Ph 2 of 2 | \$109,947 |
| | | FY03/04 | | Accessibility Code Compliance Bowman/Trustees, Ph 1 of 1 | \$522,681 |
| | | FY04/05 | | Bowman Library/Roof Replacement, Ph 1 of 1 | \$87,675 |
| | | FY05/06 | | Indoor/Outdoor Arena Repairs, Ph 1 of 1 | \$18,000 |
| | | FY05/06 | | Replace Betz Roof, Ph 1 of 1 | \$234,000 |
| | | FY05/06 | | Replace Bowman Trustees Building HVAC Controls, Ph 1 of 1 | \$260,000 |
| | | | | DOHE-LCC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: | \$1,574,706 \$68,000 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$1,642,706 |
| Morg | - | nmunity C | ollege | | |
| 27 | 10 | FY01/02 | | Main Campus Fire Alarm System Integration, Ph 1 of 1 | \$130,406 |
| 44 | 12 | FY01/02 | M00062 | HVAC Repairs to Spruce Hall, Ph 2 of 2 | \$237,738 |
| 149 | 18 | FY01/02 | | Replace HVAC units and Controls. Cottonwood Hall, Ph 1 of 2 | \$563 500 |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|----------|-----------------|----------------|---|----------------------------|
| 163 | 63 | FY01/02 | | Campus Wide Utility Infrastructure Analysis, Ph 1 of 1 | \$50,950 |
| | | FY01/02 | | Replace Interior Lighting - Aspen, Spruce, Cottonwood, Ph 1 of 1 | \$97,430 |
| | | FY01/02 | | Willow Hall Repairs, Ph 1 of 1 | \$260,500 |
| | | FY02/03 | | Campus Landscape Replacement, Ph 1 of 2 | \$120,412 |
| | | FY02/03 | | Interior Fire Sprinkler System, Ph 1 of 1 | \$405,961 |
| | | FY02/03 | | Repairs to Chemistry Lab, Ph 1 of 1 | \$54,879 |
| | | FY02/03 | | Replace HVAC units and Controls, Cottonwood Hall, Ph 2 of 2 | \$302,780 |
| | | FY03/04 | | Campus Landscape Replacement, Ph 2 of 2 | \$18,240 |
| | | FY03/04 | | Repairs to Aspen Hall/Entrance Area, Ph 1 of 1 | \$16,840 |
| | | FY03/04 | | Replace HVAC in Willow, Aspen, Sagebrush, 300 Main, Ph 1 of 2 | \$455,910 |
| | | FY04/05 | | Outdoor Study Areas Repairs, Ph 1 of 1 | \$37,880 |
| | | FY04/05 | | Replace HVAC in Willow, Aspen, Sagebrush, 300 Main, Ph 2 of 2 | \$304,290 |
| | | FY04/05 | | Sagebrush Hall Repairs, Ph 1 of 1 | \$38,060 |
| | | FY05/06 | | Extend Campus Roadways, Ph 1 of 1 | \$155,150 |
| | | FY05/06 | | West Spruce Parking Area Repairs, Ph 1 of 1 | \$101,000 |
| | | | | DOHE-MCC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: | \$3,351,926 \$0 \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$3,351,926 |
| | | | | | <i>+-,</i> |
| Nort | heasteri | n Junior C | ollege | | |
| 43 | 12 | FY01/02 | | Campus Accessibility Design and Improvements, Ph 1 of 1 | \$103,481 |
| 65 | 18 | FY01/02 | M90057 | Install Pitched Roofs on Four Main Campus Buildings, Ph 3 of 3 | \$525,938 |
| 157 | 54 | FY01/02 | | Replace HVAC Units, Ph 1 of 1 | \$35,685 |
| | | FY02/03 | | ADA Correction Project, Ph 1 of 2 | \$250,000 |
| | | FY02/03 | | Repair/Replace A/C of E.S. French, Ph 1 of 3 | \$250,000 |
| | | FY03/04 | | ADA Correction Project, Ph 2 of 2 | \$200,000 |
| | | FY03/04 | | Repair/Replace A/C of E.S. French, Ph 2 of 3 | \$250,000 |
| | | FY04/05 | | Area Vocational Replace HVAC System, Ph 1 of 1 | \$95,000 |
| | | FY04/05 | | Cosmetology Updated Electrical, Ph 1 of 1 | \$75,000 |
| | | FY04/05 | | Repair/Replace A/C of E.S. French, Ph 3 of 3 | \$250,000 |
| | | FY05/06 | | Campus Building Lighting Upgrade, Ph 1 of 1 | \$200,000 |
| | | FY05/06 | | Repair Paving N. Area of Main Campus, Ph 1 of 1 | \$300,000 |
| | | FY05/06 | | Replace Entry "storefronts" on Buildings, Ph 1 of 1 | \$150,000 |
| | | | | DOHE-NJC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: | \$2,685,104 \$5,961,753 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$480,000 \$9,126,857 |
| | | | | Agency Reported Controlled Maintenance Total. | \$9,120,037 |
| Oter | o Junio | College | | | |
| 10 | | - | M00067 | Kiva Repair and Code Corrections, Ph 2 of 2 | \$335,851 |
| 119 | | FY01/02 | | Wheeler/Life Science HVAC Equipment Replacement, Ph 1 of 2 | \$202,118 |
| 146 | | FY01/02 | | McDivitt Hall Roof Replacement, Ph 1 of 1 | \$184,247 |
| | | FY02/03 | | Repair Humanities Chiller, Ph 1 of 1 | \$114,558 |
| | | FY02/03 | | Replace Campus Building Automation System, Ph 1 of 2 | \$238,901 |
| | | FY02/03 | | Wheeler/Life Science HVAC Equipment Replacement, Ph 2 of 2 | \$92,705 |
| | | FY03/04 | | Campus Electrical Corrections, Ph 1 of 1 | \$331,417 |
| | | FY03/04 | | Replace Campus Building Automation System, Ph 2 of 2 | \$193,970 |
| | | FY04/05 | | Gym Roof Replacement, Ph 1 of 1 | \$190,000 |
| | | FY04/05 | | Humanities HVAC Replacement, Ph 1 of 1 | \$280,600 |
| | | | | | |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|----------|--------------------|----------------|--|--|
| | | FY05/06 FY05/06 | | McDivitt Hall HVAC Replacement, Ph 1 of 1 Repair Campus Floor Coverings, Ph 1 of 1 | \$314,420 \$155,266 |
| | | | | DOHE-OJC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$2,634,053 \$5,256,203 \$0 \$7,890,256 |
| Pike | s Peak (| Communit | v College | | |
| 56 | | FY01/02 | | Roof Replacement Aspen and Breckenridge Buildings, Ph 2 of 4 | \$315,543 |
| 117 | 30 | FY01/02 | | Lighting and Controls Retrofit Aspen and Breckenridge Buildings, Ph 1 of 2 | \$325,629 |
| 162 | 63 | FY01/02 | | Plumbing Fixture Replace Aspen and Breckenridge Buildings, Ph 1 of 1 | \$92,167 |
| | | FY02/03 | | Lighting and Controls Retrofit Aspen and Breckenridge Buildings, Ph 2 of 2 | \$235,801 |
| | | FY02/03 FY02/03 | M00088 | Repair/Replace Acoustic Ceilings Aspen and Breckenridge Buildings, Ph 1 of 2 Roof Replacement Aspen and Breckenridge Buildings, Ph 3 of 4 | \$160,806 \$283,492 |
| | | FY02/03 | 1000000 | Theater Seat Replacement Aspen Building, Ph 1 of 1 | \$203,492 \$71,060 |
| | | FY03/04 | | Repair/Replace Acoustic Ceilings Aspen and Breckenridge Buildings, Ph 2 of 2 | \$160,805 |
| | | FY03/04 | | Replace Classroom-Office Carpet Aspen and Breckenridge Building, Ph 1 of 2 | \$125,573 |
| | | FY03/04 | M00088 | Roof Replacement Aspen and Breckenridge Buildings, Ph 4 of 4 | \$231,110 |
| | | FY04/05 | | Convert All Motors 5hp and Above to VFD's, Ph 1 of 2 | \$154,350 |
| | | FY04/05 FY05/06 | | Replace Classroom-Office Carpet Aspen and Breckenridge Buildings, Ph 2 of 2 | \$125,572 \$154,250 |
| | | F105/00 | | Convert All Motors 5hp and Above to VFD's, Ph 2 of 2 | \$154,350 |
| | | | | DOHE-PPCC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: | \$2,436,258 \$1,300,000 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$2,247,000 |
| | | | | Agency Reported Controlled Maintenance Total: | \$5,983,258 |
| Puek | olo Com | munity Co | ollege | | |
| 72 | | FY01/02 | 0 | Replace Boilers and Associated Equipment, Boiler House, Ph 1 of 1 | \$197,495 |
| 111 | 28 | FY01/02 | | Replace HVAC System and Roof Repair Health Science Annex, Ph 1 of 1 | \$162,659 |
| 160 | 54 | FY01/02 | | Repair Interior and Exterior Deteriorating Items, Academic Building, Ph 1 of 1 | \$214,965 |
| | | FY02/03 | | Repair and Reinstall Electrical Dist. Panels - Central Administration, Ph 1 of 1 | \$20,680 |
| | | FY02/03 FY03/04 | | Upgrade HVAC system to Heat/Cool - Central Administration, Ph 1 of 1 Repair and Install Roadway West Side of Campus, Ph 1 of 1 | \$100,000 \$29,662 |
| | | FY03/04 | | Replace all Interior Doors Hardware and Lock - Central Administration, Ph | \$29,002 \$74,262 |
| | | 1 100/01 | | 1 of 1 | ф1 I,202 |
| | | FY04/05 | | Landscape Replacement Campus Wide, Ph 1 of 1 | \$278,500 |
| | | FY05/06 | | Replace Walks Campus Wide, Ph 1 of 1 | \$10,250 |
| | | | | DOHE-PCC 5 Year Plan Project Request Total: | \$1,088,473 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$0 \$0 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$0 \$1,088,473 |
| | | | | Agency Reported Controlled Maintenance Total. | φ1,000,475 |
| | | Communit | y College | | |
| 39 | | FY01/02 | | Safety Improvements, Kiln, Ph 1 of 1 | \$76,336 |
| 76 | | | M90072 | Groundwater Problem - West Building, Ph 2 of 2 | \$221,088 |
| 121 158 | | FY01/02 FY01/02 | | Replace Expansion Tank, Ph 1 of 1 Replace Multizone HVAC Equipment, Ph 1 of 1 | \$38,284 \$211,952 |
| 100 | 04 | FY01/02 | | Asbestos Removal Arvada Cafeteria, Ph 1 of 1 | \$211,952 \$388,949 |
| | | FY01/02 | | Convert Building Fans to Variable Speed, Ph 1 of 1 | \$184,830 |
| | | FY02/03 | | Replace Arvada Café Boiler and HVAC, Ph 1 of 1 | \$500,000 |
| | | | | | |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|---------|-----------------|----------------|--|--|
| | | FY02/03 | | Roof Repairs-West Building, Ph 1 of 1 | \$225,000 |
| | | FY02/03 | | South Forty Road Replacement, Ph 1 of 1 | \$109,000 |
| | | FY03/04 | | Replace Roof on Bridge, Ph 1 of 1 | \$50,000 |
| | | FY03/04 | | Reseal Concrete Exterior Main Campus, Ph 1 of 1 | \$150,000 |
| | | FY04/05 | | Repair/Replace Stairs in Courtyard, Ph 1 of 1 | \$50,000 |
| | | FY05/06 | | Replace Cooling Towers 1 and 2, Ph 1 of 1 | \$85,000 |
| | | | | DOHE-RRCC 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$2,290,439 \$750,000 \$250,000 \$3,290,439 |
| Trini | dad Sta | te Junior (| College | | |
| 30 | | FY01/02 | - | Campus Electric Power Upgrades, Ph 2 of 2 | \$271,175 |
| 115 | | FY01/02 | Webbee | Repair Basketball/Volleyball Courts and Campus Streets/Parking Lots, Ph 1 of 1 | \$253,710 |
| 161 | 63 | FY01/02 | | Interior Repair/Replacement Davis/Berg/Mullen Buildings, Ph 1 of 2 | \$250,000 |
| 166 | 84 | FY01/02 | | East Boundary Retaining Wall Repair/Stabilize, Ph 1 of 1 | \$195,200 |
| | | FY02/03 | | Interior Repair/Replacement Davis/Berg/Mullen Buildings, Ph 2 of 2 | \$250,000 |
| | | FY02/03 | | Replace Banta/Davis Boiler and Upgrade Controls, Ph 1 of 2 | \$200,000 |
| | | FY03/04 | | Replace Banta/Davis Boiler and Upgrade Controls, Ph 2 of 2 | \$200,000 |
| | | FY03/04 | | Replace Library Chiller and HVAC Controls, Ph 1 of 1 | \$300,000 |
| | | FY04/05 | | Mining Tech Structural Repair Roof Coating and Roof HVAC Replacement, Ph 1 of 1 | \$175,000 |
| | | FY04/05 | | Mullen/Berg Plumbing Upgrades, Ph 1 of 2 | \$210,945 |
| | | FY04/05 | | Replace Library/Mullen Roof and Davis Roofs, Ph 1 of 1 | \$330,000 |
| | | FY05/06 | | Mullen/Berg Plumbing Upgrades, Ph 2 of 2 | \$237,290 |
| | | FY05/06 | | Replace San Luis Valley Main Building Roof with Steel, Ph 1 of 1 | \$240,000 |
| | | | | DOHE-TSJC 5 Year Plan Project Request Total: | \$3,113,320 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$2,875,460 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$5,988,780 |
| High | er Educ | ation and | Advance | d Technology Center at Lowry | |
| | | | | DOHE-HEAT 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: | \$0 \$0 \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$0 |
| Depa | artment | of Human | Services | | |
| . 2 | | FY01/02 | | Suicide Risk Assessment and Prevention, Ph 1 of 1 | \$796,300 |
| 8 | | | M00090 | Fire Alarm System Upgrades, Ph 2 of 2 | \$436,056 |
| 37 | | FY01/02 | | Repair Structural Problems in Building 54, Ph 1 of 1 | \$180,000 |
| 75 | | FY01/02 | M90084 | Repair/Replace HVAC Systems, Ph 3 of 4 | \$375,000 |
| 77 | 18 | FY01/02 | | Replace Deteriorated Campus Infrastructure System, CMHIFL, Ph 1 of 5 | \$575,000 |
| 99 | 24 | FY01/02 | | Repair/Replace Campus Tunnel and Utility Infrastructure System, CMHIP, Ph 1 of 5 | \$1,057,801 |
| 116 | 30 | FY01/02 | M90083 | Repair/Replace Secondary Electrical Systems, Ph 3 of 3 | \$698,750 |
| 150 | 48 | FY01/02 | | Repair/Replace Elevator, Ph 1 of 1 | \$405,000 |
| 159 | 54 | FY01/02 | | Heating Plant and Infrastructure Upgrade, Ph 1 of 1 | \$561,000 |
| | | FY01/02 | | Repair/Replace Building Deficiencies PRC and Rehab Pool, CMHIP, Ph 1 of 4 | \$72,500 |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|-------|-----------------|----------------|--|---------------------|
| | | FY01/02 | | Repair/Replace Exterior, House #1, CMHIP, Ph 1 of 2 | \$75,000 |
| | | FY01/02 | | Repair/Replace Fire Detection and Suppression Systems, Ph 1 of 5 | \$300,000 |
| | | FY01/02 | | Repair/Replace HVAC Systems, Adams YSC, Ph 1 of 1 | \$180,000 |
| | | FY01/02 | | Repair/Replace Misc. Building Systems, DYC and CMHIP, Ph 1 of 5 | \$130,000 |
| | | FY01/02 | | Repair/Replace Primary and Secondary Electrical Systems MVYSC, Ph 1 of 1 | \$150,000 |
| | | FY01/02 | M90086 | Repair/Replace Primary Electrical Systems, Ph 2 of 5 | \$162,265 |
| | | FY01/02 | | Repair/Replace Utilities and Paving, WRRC, Ph 1 of 4 | \$430,000 |
| | | FY02/03 | | Repair/Replace Building Deficiencies PRC and Rehab Pool, CMHIP, Ph 2 of 4 | \$331,500 |
| | | FY02/03 | | Repair/Replace Campus Tunnel and Utility Infrastructure System, CMHIP, Ph 2 of 5 | \$1,235,000 |
| | | FY02/03 | | Repair/Replace Domestic Water and Sewer Mains CMHIP, Ph 1 of 2 | \$870,750 |
| | | FY02/03 | | Repair/Replace Exterior, House #1, CMHIP, Ph 2 of 2 | \$75,000 |
| | | FY02/03 | | Repair/Replace Fire Detection and Suppression Systems, Ph 2 of 5 | \$650,000 |
| | | FY02/03 | M90084 | Repair/Replace HVAC Systems, Ph 4 of 4 | \$488,118 |
| | | FY02/03 | | Repair/Replace Misc. Building Systems, DYC and CMHIP, Ph 2 of 5 | \$828,575 |
| | | FY02/03 | | Repair/Replace Primary Electrical Systems CMHIP, Ph 1 of 3 | \$1,075,000 |
| | | FY02/03 | M90086 | Repair/Replace Primary Electrical Systems, Ph 3 of 5 | \$518,400 |
| | | FY02/03 | | Repair/Replace Roads, CMHIP, Ph 1 of 3 | \$698,750 |
| | | FY02/03 | | Repair/Replace Utilities and Paving, WRRC, Ph 2 of 4 | \$350,000 |
| | | FY02/03 | | Replace Deteriorated Campus Infrastructure System, CMHIFL, Ph 2 of 5 | \$750,000 |
| | | FY02/03 | | Suicide Risk Prevention, Ph 1 of 4 | \$3,050,000 |
| | | FY03/04 | | Repair/Replace Building Deficiencies PRC and Rehab Pool, CMHIP, Ph 3 of 4 | \$60,000 |
| | | FY03/04 | | Repair/Replace Campus Tunnel and Utility Infrastructure System, CMHIP, Ph 3 of 5 | \$1,235,000 |
| | | FY03/04 | | Repair/Replace Domestic Water and Sewer Mains CMHIP, Ph 2 of 2 | \$1,118,000 |
| | | FY03/04 | | Repair/Replace Fire Detection and Suppression Systems, Ph 3 of 5 | \$650,000 |
| | | FY03/04 | | Repair/Replace Misc. Building Systems, DYC and CMHIP, Ph 3 of 5 | \$743,000 |
| | | FY03/04 | M90086 | Repair/Replace Primary Electrical Systems, Ph 4 of 5 | \$508,500 |
| | | FY03/04 | | Repair/Replace PrimaryElectrical Systems CMHIP, Ph 2 of 3 | \$967,500 |
| | | FY03/04 | | Repair/Replace Roads, CMHIP, Ph 2 of 3 | \$1,075,000 |
| | | FY03/04 | | Repair/Replace Utilities and Paving, WRRC, Ph 3 of 4 | \$425,000 |
| | | FY03/04 | | Replace Campus Infrastructure Systems LMYSC, Ph 1 of 4 | \$2,580,000 |
| | | FY03/04 | | Replace Deteriorated Campus Infrastructure System, CMHIFL, Ph 3 of 5 | \$750,000 |
| | | FY03/04 | | Suicide Risk Prevention, Ph 2 of 4 | \$3,050,000 |
| | | FY04/05 | | Repair/Replace Building Deficiencies PRC and Rehab Pool, CMHIP, Ph 4 of 4 | \$160,000 |
| | | FY04/05 | | Repair/Replace Campus Tunnel and Utility Infrastructure System, CMHIP, Ph 4 of 5 | \$1,235,000 |
| | | FY04/05 | | Repair/Replace Fire Detection and Suppression Systems, Ph 4 of 5 | \$650,000 |
| | | FY04/05 | | Repair/Replace Misc. Building Systems, DYC and CMHIP, Ph 4 of 5 | \$358,000 |
| | | FY04/05 | | Repair/Replace Primary Electrical Systems CMHIP, Ph 3 of 3 | \$430,000 |
| | | FY04/05 | M90086 | Repair/Replace Primary Electrical Systems, Ph 5 of 5 | \$508,500 |
| | | FY04/05 | | Repair/Replace Roads, CMHIP, Ph 3 of 3 | \$1,075,000 |
| | | FY04/05 | | Repair/Replace Utilities and Paving, WRRC, Ph 4 of 4 | \$300,000 |
| | | FY04/05 | | Replace Campus Infrastructure Systems LMYSC, Ph 2 of 4 | \$860,000 |
| | | FY04/05 | | Replace Deteriorated Campus Infrastructure System, CMHIFL, Ph 4 of 5 | \$750,000 |
| | | FY04/05 | | Suicide Risk Prevention, Ph 3 of 4 | \$3,050,000 |
| | | FY05/06 | | Repair/Replace Campus Tunnel and Utility Infrastructure System, CMHIP, Ph 5 of 5 | \$177,000 |
| | | FY05/06 | | Repair/Replace Fire Detection and Suppression Systems, Ph 5 of 5 | \$650,000 |
| | | FY05/06 | | Repair/Replace Misc. Building Systems, DYC and CMHIP, Ph 5 of 5 | \$50,000 |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|-----------|-------------------------------|----------------|--|--|
| | | FY05/06 FY05/06 FY05/06 | | Replace Campus Infrastructure Systems LMYSC, Ph 3 of 4 Replace Deteriorated Campus Infrastructure System, CMHIFL, Ph 5 of 5 Suicide Risk Prevention, Ph 4 of 4 | \$860,000 \$750,000 \$3,054,580 |
| | | | | DHS 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: | \$45,585,845 \$35,126,990 \$36,063,070 |
| | | | | Agency Reported Controlled Maintenance Total: | \$116,775,905 |
| Judi | cial Heri | itage | | | |
| 69 | 18 | FY01/02 | M00095 | Waterproof Sloped Roof and Plaza Deck, Ph 2 of 3 | \$539,325 |
| 125 | 30 | FY01/02 | | Repair Building Exterior, Ph 1 of 1 | \$42,680 |
| | | FY02/03 | | Re-roof Judicial/Heritage Building, Ph 1 of 1 | \$163,500 |
| | | FY02/03 | | Replace Sidewalks, Ph 1 of 3 | \$67,100 |
| | | FY02/03 | M00095 | Waterproof Sloped Roof and Plaza Deck, Ph 3 of 3 | \$306,812 |
| | | FY03/04 | | Replace Fountain, Ph 1 of 1 | \$35,100 |
| | | FY03/04 | | Replace Heat Exchanger, Ph 1 of 1 | \$27,500 |
| | | FY03/04 | | Replace Sidewalks, Ph 2 of 3 | \$84,400 |
| | | FY04/05 | | Energy Management, Ph 1 of 1 | \$222,800 |
| | | FY04/05 | | Replace Generator, Ph 1 of 1 | \$53,100 |
| | | FY04/05 | | Replace Sidewalks, Ph 3 of 3 | \$30,200 |
| | | FY04/05 FY05/06 | | Replace Water System, Ph 1 of 1 Replace Cooling Tower, Ph 1 of 1 | \$34,000 \$55,800 |
| | | FY05/06 | | Replace Damaged Granite Panels, Ph 1 of 1 | \$35,800 \$78,300 |
| | | FY05/06 | | Replace Steps, Ph 1 of 1 | \$276,900 |
| | | 1 100/00 | | | |
| | | | | JUD 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: | \$2,017,517 \$0,842,010 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$9,842,910 \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$11,860,427 |
| Dena | artment | of Military | ∕ Affairs | | ¢,••••, |
| 25 | | FY01/02 | | Emergency Lighting/Electrical Violations Various Locations, Ph 2 of 3 | \$236,293 |
| 45 | | FY01/02 | 1000037 | HVAC Modifications, Various Locations, Ph 1 of 5 | \$299,104 |
| 63 | | FY01/02 | | Safety Standards Compliance, Various locations, Ph 1 of 3 | \$329,246 |
| 95 | | FY01/02 | M00098 | Armory Roof Replacements, Ph 2 of 5 | \$214,413 |
| 148 | | FY01/02 | | Paving Projects Various Locations, Ph 1 of 5 | \$355,069 |
| 152 | | | M00099 | Exterior Closure Replacement, Ph 2 of 4 | \$279,734 |
| | | FY02/03 | | Armory Roof Replacements, Ph 3 of 5 | \$207,493 |
| | | FY02/03 | M00097 | | \$190,255 |
| | | FY02/03 | M00099 | Exterior Closure Replacement, Ph 3 of 4 | \$414,971 |
| | | FY02/03 | | HVAC Modifications, Various Locations, Ph 2 of 5 | \$299,235 |
| | | FY02/03 | | Paving Projects Various Locations, Ph 2 of 5 | \$265,728 |
| | | FY02/03 | | Safety Standards Compliance, Various locations, Ph 2 of 3 | \$290,332 |
| | | FY03/04 | M00098 | Armory Roof Replacements, Ph 4 of 5 | \$267,434 |
| | | FY03/04 | M00099 | Exterior Closure Replacement, Ph 4 of 4 | \$414,971 |
| | | FY03/04 | | HVAC Modifications, Various Locations, Ph 3 of 5 | \$293,744 |
| | | FY03/04 | | Paving Projects Various Locations, Ph 3 of 5 | \$236,356 |
| | | FY03/04 | | Safety Standards Compliance, Various locations, Ph 3 of 3 | \$288,597 |
| | | FY04/05 | M00098 | Armory Roof Replacements, Ph 5 of 5 | \$280,481 |
| | | FY04/05 FY04/05 | | HVAC Modifications, Various Locations, Ph 4 of 5 | \$291,065 |
| | | | | Paving Projects Various Locations, Ph 4 of 5 | \$280,000 |

| Ref. No. | Score | Request Year | Project M # | Project Title | Requested Amount |
|-------------|---------|--------------------|----------------|---|---|
| | | FY05/06 FY05/06 | | HVAC Modifications, Various Locations, Ph 5 of 5 Paving Projects Various Locations, Ph 5 of 5 | \$364,984 \$278,000 |
| | | 1100,00 | | DOMA 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$6,377,505 \$9,000,000 \$5,000,000 \$20,377,505 |
| Depa | artment | of Public | Safety | | |
| 89 | | | M00105 | CSP Academy/CGW Repairs, Ph 2 of 3 CSP Academy/CGW Repairs, Ph 3 of 3 Facilities Repairs CGW and State-wide Offices, Ph 1 of 1 Facilities Repairs CGW Ext/Roofs State-wide, Ph 1 of 1 CGW Facility Repairs; State-wide, Ph 1 of 3 | \$304,962 \$149,122 \$252,917 \$336,231 \$345,356 |
| | | | | CDPS 5 Year Plan Project Request Total: Estimated Long Term Building Major Maintenance Total: Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$1,388,588 \$459,120 \$300,000 \$2,147,708 |
| Depa | artment | of Revenu | le | | |
| 6 | 4 | FY01/02 | | Replace Fire Alarm System, Ph 1 of 1 | \$219,098 |
| | | FY02/03 | | Boiler Renovation, Ph 1 of 1 | \$80,000 |
| | | FY02/03 | | Upgrade Chillers, Ph 1 of 1 | \$200,000 |
| | | FY02/03 | | Upgrade HVAC Controls, Ph 1 of 1 | \$266,000 |
| | | FY03/04 | | Caulk Exterior Walls, Ph 1 of 1 | \$225,000 |
| | | FY03/04 | | Repair Parking Lot, Ph 1 of 1 | \$35,000 |
| | | FY04/05 | | Install Energy Management System, Ph 1 of 1 | \$75,000 |
| | | FY04/05 | | Restroom Remodel, Ph 1 of 1 | \$80,000 \$250,000 |
| | | FY05/06 | | Roof Replacement, Ph 1 of 1 | \$250,000 |
| | | | | DOR 5 Year Plan Project Request Total: | \$1,430,098 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$0 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: Agency Reported Controlled Maintenance Total: | \$0 \$1,430,098 |
| Cum | bres & | Toltec Sce | enic Railro | oad Commission | |
| 33 | 10 | FY01/02 | | Antonito Shop Mechanical/Electrical Upgrades, Ph 1 of 1 | \$61,400 |
| | | | | CTSRC 5 Year Plan Project Request Total: | \$61,400 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$0 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$0 |
| | | | | Agency Reported Controlled Maintenance Total: | \$61,400 |
| | | | | AGENCY TOTALS 5 Year Plan Project Request Total: | \$346,360,359 |
| | | | | Estimated Long Term Building Major Maintenance Total: | \$448,311,664 |
| | | | | Estimated Long Term Infrastructure Major Maintenance Total: | \$110,412,348 |
| | | | | Agency Reported Controlled Maintenance Total: | \$905,084,371 |

| \$80,729,020 |
|--------------|
| \$80,836,689 |
| \$73,558,474 |
| \$64,334,976 |
| \$46,901,200 |
| |

SECTION IX: AGENCY CONTROLLED MAINTENANCE PROJECT STATUS REPORT FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

The pages that follow (38 pages) provide a summary status report for controlled maintenance projects appropriated in **FY 98/99, FY 99/00 and FY 00/01**.

A status report is provided in section X for the Emergency Fund.

Of the 163 controlled maintenance projects appropriated in FY00/01 **99%** have met the six month encumbrance dead line to commence the project by procuring professional design services. The handful of projects that have not met this deadline will be discussed by the various agencies at their respective Capital Development Committee hearings.

Out of a total of 487 single and multi-phased controlled maintenance projects appropriated over the last three fiscal years, 174 projects, or **35%** have been completed to date.

Therefore, State Buildings Programs is confident that each and every agency/institution is capable of managing the additional projects as recommended in Chapter III, SBP Prioritized Statewide Funding Recommendations.

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | , FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|--------------------|--------------------|----------|--------|---------------------|------------------|----------|---------|--------------------------------|-------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract | | Constr. Bid Date | Contract Date | | , | Name of A/E | Name of Prime Contractor |
| Capitol | Complex Facilities | | | | | | | | | | | | |
| M501 | Mechanical & Electrical Upgrades, Ph 2 of 2 | \$661,280 | \$0 | 7/98 | 97% | 10/95 | 7/00 | 8/00 | 10/00 | 4/01 | 5/00 | IPE | TBD |
| M772 | Upgrade Haz. HVAC Equip, N. Campus, Ph 2 of 2 | \$181,450 | \$0 | 7/98 | 100% | 9/97 | 4/98 | 7/98 | 7/98 | 3/99 | 5/99 | МКК | Pasterkamp |
| M80121 | North Campus Fire Alarm System, Ph 1 of 1 | \$58,900 | \$0 | 7/98 | 80% | 8/98 | 12/98 | 1/99 | 5/99 | 8/00 | 10/00 | Corey | TBD |
| M80122 | LSB Structural Repairs, Ph 1 of 1 | \$182,440 | \$0 | 7/98 | 100% | 8/98 | 5/99 | 7/99 | 8/99 | 10/99 | 11/99 | Arneson & Associates | Rock & Co. |
| M80123 | 690 Kipling Underground Storage Tank Replacement, Ph 1 of 1 | \$49,185 | \$0 | 7/98 | 100% | 8/98 | 8/98 | 9/98 | 11/98 | 12/98 | 3/99 | Kumar & Associates | Eaton Metals |
| M80124 | 690 Kipling Reroofing/Cooling Sys. Upgrade, Ph 1 of 1 | \$132,300 | \$0 | 7/98 | 100% | 9/98 | 10/98 | N/A | 10/98 | 12/98 | 9/99 | Blauth & White | CEI West |
| M80125 | Cross Connection Control/Backflow Prevention, Ph 1 of 2 | \$306,550 | \$0 | 7/98 | 75% | 9/98 | 6/99 | 10/99 | 11/99 | 12/00 | 1/01 | EMC Engineers, Inc. | Colorado Piping Mechanical |
| M80125 | Cross Connection Control/Backflow Prevention, Ph 2 of 2 | \$143,733 | \$0 | 7/99 | 75% | 9/98 | 6/99 | 10/99 | 11/99 | 12/00 | 1/01 | EMC Engineers, Inc. | Colorado Piping Mechanical |
| M90096 | Fire Pump Re-powering at SOB, Ph 1 of 1 | \$81,520 | \$0 | 7/99 | 40% | 8/99 | 7/00 | 9/00 | 11/00 | 3/01 | 4/01 | EMC Engineers, Inc. | TBD |
| M90097 | Executive Residence Security System Upgrades, Ph 1 of 1 | \$169,480 | \$0 | 7/99 | 100% | N/A | N/A | N/A | N/A | N/A | N/A | N/A | Digatron |
| M90098 | Centennial Mechanical Upgrades, Ph 1 of 2 | \$758,905 | \$0 | 7/99 | 11% | 10/99 | 1/00 | 2/00 | 4/00 | 1/01 | 2/01 | Engineering Economics, Inc. | TBD |
| M90098 | Centennial Mechanical Upgrades, Ph 2 of 2 | \$479,870 | \$0 | 7/00 | 11% | 10/99 | 7/00 | 8/00 | 9/00 | 3/01 | 5/01 | Engineering Economics, Inc. | TBD |
| M90100 | LSB Temperature Control System Upgrade, Ph 1 of 2 | \$71,860 | \$0 | 7/99 | 100% | N/A | N/A | 9/99 | 9/99 | 12/99 | 12/99 | Engineering Economics, Inc. | Landis & Staefa |
| M90103 | Repair Annex Roof, Ph 1 of 1 | \$86,375 | \$0 | 7/99 | 100% | 8/99 | 9/99 | 11/00 | 1/00 | 5/00 | 8/00 | Blauth & White | United Materials |
| M90104 | Repair 690/700 Kipling Parking Lots, Ph 1 of 1 | \$64,490 | \$0 | 7/99 | 87% | 7/99 | 8//99 | 9/99 | 10/99 | 12/99 | 9/00 | Blauth & White | Colorado Asphalt Service |
| M00100 | Colorado Executive Residence Repairs/Upgrades, Ph 1 of 1 | \$1,672,030 | \$0 | 7/00 | 0% | 8/00 | 6/01 | 8/01 | 9/01 | 12/02 | 2/03 | Winter, Kramer & Jessup | TBD |
| M00101 | Mechanical Heating System Upgrades, Ph 1 of 1 | \$130,468 | \$0 | 7/00 | 11% | 6/00 | 2/01 | 3/01 | 4/01 | 10/01 | 12/01 | MKK | TBD |
| M00103 | Relocate Existing Generator From 690 Kipling to the Power Plant, Ph 1 of 1 | \$189,215 | \$0 | 7/00 | 0% | 8/00 | 3/01 | 5/01 | 6/01 | 7/01 | 8/01 | EMC Engineers, Inc. | TBD |
| GSS-CCF | Total for the last 3 fiscal years: | \$5,420,051 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | , FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|-------|--------------------|----------|--------|---------------------|----------|-------------------|---------|-----------------------------|--------------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | | Constr. Bid Date | Contract | Occupancy Date | | Name of A/E | Name of Prime Contractor |
| Colorad | o Government Technology Services | 5 | | | | | | | | | | | |
| M306 | Roofs, Ph 3 of 3 | \$39,000 | \$0 | 7/98 | 100% | N/A | 6/99 | 9/99 | 9/99 | 6/00 | 6/00 | Pahl, Pahl, Pahl | Trico, Inc. |
| M668 | Generators, Ph 3 of 3 | \$68,000 | \$0 | 7/98 | 100% | N/A | 11/96 | 11/99 | N/A | 6/00 | 6/00 | TBD | Computer Sites |
| M90101 | Replace Roofs on Remote TX Buildings (B), Ph 1 of 5 | \$49,500 | \$0 | 7/99 | 45% | N/A | 6/99 | 4/00 | 6/00 | 8/00 | 6/04 | Pahl, Pahl, Pahl | Pi kington Roofing |
| M90101 | Replace Roofs on Remote TX Buildings (B), Ph 2 of 5 | \$50,985 | \$0 | 7/00 | 0% | N/A | 6/99 | 3/01 | 4/01 | 8/01 | 6/04 | Pahl, Pahl, Pahl | TBD |
| M90102 | Replace Emergency Generators, Ph 1 of 5 | \$68,000 | \$0 | 7/99 | 20% | N/A | 11/96 | 11/99 | N/A | 6/00 | 6/02 | TBD | Computer Sites |
| M90102 | Replace Emergency Generators, Ph 2 of 5 | \$68,000 | \$0 | 7/00 | 0% | N/A | 11/96 | 1/01 | N/A | 6/01 | 6/02 | TBD | TBD |
| M00104 | Replace Batteries for Back-Up Generators, Ph 1 of 3 | \$84,000 | \$0 | 7/00 | 27% | N/A | 7/98 | 12/99 | 6/00 | 6/01 | 6/03 | N/A | Mountain Power & Communication, Inc. |
| GSS-CGT | TS Total for the last 3 fiscal years: | \$427,485 | | | | | | | | | | | |
| Camp G | eorge West | | | | | | | | | | | | |
| M90099 | Camp George West Site Utility Infrastructure, Ph 1 of 1 | \$1,376,953 | \$0 | 7/99 | 100% | 10/99 | 7/00 | 5/00 | 7/00 | N/A | 1/00 | Bucher, Willis & Ratliff | Eagle One Contractors, Inc. |
| M00102 | Telephone Distr bution System Replacement, Ph 1 of 1 | \$241,982 | \$0 | 7/00 | 100% | 10/99 | 4/00 | 5/00 | 7/00 | 8/00 | 1/01 | Bucher, Willis & Ratliff | Eagle One Contractors, Inc. |
| GSS-CGV | V Total for the last 3 fiscal years: | \$1,618,935 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 |), FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|--------------------|--------------------|------------------|--------------------|---------------------|------------------|-------------------|--------------------|------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract Date | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Departn | nent of Agriculture - Zuni & Insectar | у | | | | | | | | | | | |
| M80010 | Biochemistry Lab Building Renovation, Ph 1 of 2 | \$637,994 | \$0 | 7/98 | 64% | 9/99 | 11/99 | 8/99 | 10/99 | 5/01 | 6/01 | EMC Engineers, Inc. | Kile Systems |
| M80010 | Biochemistry Lab Building Renovation, Ph 2 of 2 | \$216,307 | \$0 | 7/99 | 50% | 10/99 | 9/00 | 10/00 | 12/00 | 5/02 | 6/02 | EMC Engineers, Inc. | TBD |
| M80014 | Cross Connection Control/Backflow Prevention, Ph 1 of 2 | \$20,425 | \$0 | 7/98 | 36% | 9/99 | 11/99 | 8/99 | 10/99 | 5/01 | 6/01 | EMC Engineers, Inc. | Kile Systems |
| M80014 | Cross Connection Control/Backflow Prevention, Ph 2 of 2 | \$25,448 | \$0 | 7/00 | 15% | 11/00 | 01/01 | 02/01 | 03/01 | 5/02 | 6/02 | TBD | TBD |
| M90000 | Insectary Facility Upgrade, Ph 1 of 1 | \$231,340 | \$0 | 7/99 | 75% | 5/00 | 6/00 | 7/00 | 7/00 | 5/02 | 6/02 | DPA A/E Group | Tusca II |
| M90002 | Chlorofluorocarbon Refrigeration Phase out, Ph 1 of 1 | \$20,960 | \$0 | 7/99 | 20% | 10/99 | 9/00 | 10/00 | 12/00 | 5/02 | 6/02 | EMC Engineers, Inc. | TBD |
| M00001 | Biochemistry Lab Building System Replacement, Ph 1 of 2 | \$399,852 | \$0 | 7/00 | 0% | 11/00 | 12/00 | 3/01 | 4/01 | 5/03 | 6/03 | Scheuber Darden | TBD |
| M00002 | Metrology Lab Building System Replacement, Ph 1 of 2 | \$326,728 | \$0 | 7/00 | 0% | 12/00 | 01/01 | 4/01 | 5/01 | 6/03 | 6/03 | TBD | TBD |
| DOAg | Total for the last 3 fiscal years: | \$1,879,054 | | | | | | | | | | | |
| State Fa | air - Pueblo | | _ | | | | | | | | | | |
| M80011 | Fire Detection & Alarm, Ph 1 of 1 | \$414,287 | \$0 | 7/98 | 100% | 6/98 | 11/98 | 2/99 | 3/99 | 10/99 | 12/00 | MKK | Interstate Electric |
| M80012 | Electrical Upgrade, Ph 1 of 1 | \$22,431 | \$0 | 7/98 | 100% | N/A | N/A | N/A | N/A | N/A | 7/98 | TBD | West Plains Energy |
| M80013 | Roof Replacement, Ph 1 of 1 | \$481,824 | \$0 | 7/98 | 100% | 11/98 | 3/99 | 7/99 | 9/99 | 10/99 | 10/00 | HGF Architects | PPP Roofing |
| M80015 | Cross Connection Control/Backflow Prevention, Ph 1 of 1 | \$66,877 | \$0 | 7/98 | 100% | 7/98 | 6/99 | 7/00 | 8/99 | 10/99 | 12/99 | Young & Company | K.D. Swerdferger |
| M90001 | Infrastructure Repair/Replacement, Ph 1 of 4 | \$1,600,920 | \$0 | 7/99 | 100% | 10/99 | 6/00 | 7/00 | 8/00 | N/A | 8/04 | Young & Company | K.D. Swerdfeger |
| M90001 | Infrastructure Repair/Replacement, Ph 2 of 4 | \$1,552,210 | \$0 | 7/00 | 0% | 6/00 | 9/00 | 10/00 | 11/00 | N/A | 8/04 | Young & Company | TBD |
| M00003 | Repair/Replace Electrical, Ph 1 of 1 | \$110,000 | \$0 | 7/00 | 0% | 8/00 | 10/00 | 11/00 | 12/00 | N/A | 8/01 | TBD | TBD |
| DOAg-CS | SF Total for the last 3 fiscal years: | \$4,248,549 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | 9, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|---------|--|-----------|-------|-----------|-----------|----------|------------|----------|---------|-----------|---------|-------------------------------|-------------------------------|
| Project | | CCFE | Other | Funds | Percent | Contract | Completion | Constr. | | Occupancy | | | Name of Prime |
| # | Project Description | Appr. | Funds | Available | e Encumb. | Date | Date | Bid Date | Date | Date | Date | Name of A/E | Contractor |
| Departr | nent of Corrections | | | | | | | | | | | | |
| M701 | ACC - Repair Prestress Building, Ph 2 of 2 | \$252,548 | \$0 | 7/98 | 50% | 7/98 | 10/99 | 10/99 | 1/00 | 1/01 | 3/01 | CSNA | N/A |
| M702 | Repair/Replace Asphalt Paving, Ph 2 of 3 | \$318,991 | \$0 | 7/98 | 60% | 4/00 | 5/00 | 7/00 | 8/00 | 10/00 | 12/00 | Gillans | TBD |
| M702 | Repair/Replace Asphalt, Ph 3 of 3 | \$456,221 | \$0 | 7/00 | 0% | 4/01 | 5/01 | 7/01 | 8/01 | 10/01 | 12/01 | BEAN | TBD |
| M80016 | SCC, CWCF Security Components, Ph 1 of 3 | \$311,093 | \$0 | 7/98 | 100% | 9/98 | 8/99 | N/A | N/A | N/A | 11/99 | BWG | DOC |
| M80016 | SCC, CWCF Security Components, Ph 2 of 2 | \$347,393 | \$0 | 7/99 | 11% | 9/99 | 12/99 | 1/00 | 3/00 | 10/00 | 12/00 | Lightle Fennel | Bennett |
| M80017 | Asbestos Abatement, Ph 2 of 2 | \$285,651 | \$0 | 7/99 | 0% | 9/99 | 1/00 | 3/00 | 5/00 | 10/00 | 12/00 | Versar | El Paso |
| M80017 | Asbestos Abatement, Ph 1 of 2 | \$385,405 | \$0 | 7/98 | 99% | 10/98 | 1/99 | 1/99 | N/A | 6/99 | 8/99 | Versar | El Paso |
| M80018 | Fuel Storage Tanks, Ph 1 of 1 | \$338,762 | \$0 | 7/98 | 99% | 8/98 | 9/98 | 11/98 | 1/00 | 5/99 | 12/99 | LT Environmental | Western Cleanup |
| M80019 | AVCF Domestic Water Distr bution, Ph 1 of 1 | \$465,707 | \$0 | 7/98 | 88% | 8/98 | 8/98 | 9/99 | 9/99 | 10/99 | 11/99 | Terracon | Interstate Electric |
| M80020 | BVCF Serving Lines/Dumb Waiters, Ph 1 of 1 | \$213,340 | \$0 | 7/98 | 10% | 10/99 | 12/99 | 2/00 | 3/00 | 5/01 | 5/01 | CSNA | TBD |
| M80021 | CTCF Mechanical Systems, Ph 1 of 2 | \$362,995 | \$0 | 7/98 | 100% | 9/98 | 1/99 | 3/99 | 3/99 | 7/99 | 8/99 | MKK | Ute Plumbing |
| M80022 | Repair/Replace Roofs - CCC, BVCF, CTCF, FCF, Ph 1 of 4 | \$321,432 | \$0 | 7/98 | 64% | 9/98 | 10/98 | 4/99 | 5/99 | 7/99 | 10/99 | Rooftech Consultants, Inc. | Black Roofing, CRS Roofing |
| M80022 | Repair/Replace Roofs - CCC, CTCF, FCF, Ph 2 of 4 | \$476,786 | \$0 | 7/00 | 0% | 9/00 | 3/01 | 5/01 | 7/01 | 11/01 | 1/02 | Rooftech Consultants, Inc. | TBD |
| M80023 | CCC, CCF - Bathrooms, Ph 1 of 1 | \$101,704 | \$0 | 7/98 | 75% | N/A | N/A | N/A | N/A | N/A | N/A | TBD | DOC |
| M80024 | FCF - Boiler and Equipment, Ph 1 of 2 | \$500,769 | \$0 | 7/98 | 95% | 9/98 | 12/99 | 2/00 | 4/00 | 10/00 | 12/00 | DMJM | TBD |
| M80025 | Cross Connection Control/Backflow Prevention, Ph 1 of 2 | \$108,060 | \$0 | 7/98 | 100% | N/A | N/A | N/A | N/A | N/A | 6/01 | TBD | TBD |
| M80025 | Cross Connection Control/Backflow Prevention, Ph 2 of 2 | \$165,900 | \$0 | 7/99 | 43% | N/A | N/A | N/A | N/A | N/A | 6/01 | TBD | DOC |
| M90003 | Electrical Improvements, Ph 1 of 3 | \$571,315 | \$0 | 7/99 | 95% | 9/99 | 12/99 | 2/00 | 3/00 | 4/00 | 5/00 | Gordon, Gumeson & Assoc. | Challenger Electric |
| M90004 | Asbestos Abatement, Ph 1 of 1 | \$284,588 | \$0 | 7/99 | 56% | 7/99 | 11/99 | 2/00 | 4/00 | 3/01 | 5/01 | Versar | TBD |
| M90005 | Upgrade Fire Detection/Alarm/Suppression Systems, Ph 1 of 4 | \$184,800 | \$0 | 7/99 | 0% | 11/99 | 5/00 | N/A | N/A | N/A | N/A | EMC Engineers, Inc. | N/A |
| M90005 | Upgrade Fire Detection/Alarm/Suppression Systems, Ph 2 of 4 | \$262,499 | \$0 | 7/00 | 0% | 10/00 | 6/01 | 7/01 | 9/01 | 9/02 | 10/02 | Carter Burgess | TBD |
| M90006 | North Pump Station Improvements, Ph 1 of 1 | \$82,263 | \$0 | 7/99 | 84% | 6/99 | 8/99 | 9/99 | 9/99 | 11/99 | 12/99 | Gordon, Gumeson & Assoc. | TBD |
| M90007 | Sanitary Sewer/Storm Sewer Distribution Improvements, Ph 1 of 4 | \$98,500 | \$0 | 7/99 | 93% | 11/99 | 5/00 | N/A | N/A | N/A | N/A | МКК | N/A |
| M90008 | Structural Repairs, Ph 1 of 3 | \$147,919 | \$0 | 7/99 | 91% | 11/99 | 6/00 | N/A | N/A | N/A | N/A | DCA | N/A |
| | | | | - | | | | | | | - | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| F 1 98/95 | 9, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|--------------------|--------------------|------------------|--------------------|---------------------|------------------|-------------------|--------------------|------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract Date | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| M90009 | Repair Utility Tunnel, Ph 1 of 2 | \$169,526 | \$0 | 7/99 | 99% | 11/99 | 6/00 | N/A | N/A | N/A | N/A | EMC Engineers, Inc. | N/A |
| M90010 | Repair/Replace Paving and Wa kways, Ph 1 of 2 | \$363,538 | \$0 | 7/99 | 20% | 11/99 | 3/00 | 8/00 | 10/00 | 6/01 | 9/01 | Harris | TBD |
| M90011 | Chlorofluorocarbon Refrigeration Phase out, Ph 1 of 2 | \$779,447 | \$0 | 7/99 | 5% | 9/99 | 11/99 | 1/00 | 2/00 | 2/00 | 4/00 | RMH Group, Inc | Cobb Mechanical |
| M90011 | Chlorofluorocarbon Refrigeration Phase out, Ph 2 of 2 | \$329,976 | \$0 | 7/00 | 0% | 10/00 | 6/01 | 7/01 | 9/01 | 12/02 | 2/03 | RMH Group, Inc | TBD |
| M00004 | Life Safety Upgrades, Ph 1 of 1 | \$920,914 | \$0 | 7/00 | 0% | 10/00 | 3/01 | 3/01 | 5/01 | 10/01 | 12/01 | EMC Engineers, Inc. | TBD |
| M00005 | Repair/Replace Security Components, Ph 1 of 1 | \$665,202 | \$0 | 7/00 | 0% | 10/00 | 3/01 | 5/01 | 7/01 | 12/01 | 2/02 | CSNA | TBD |
| M00006 | Repair/Replace Security Systems, Ph 1 of 4 | \$384,617 | \$0 | 7/00 | 0% | 8/00 | 3/01 | 5/01 | 7/01 | 8/02 | 11/02 | Architecture Plus | TBD |
| M00007 | Repair/Replace Cellhouse Showers, Ph 1 of 1 | \$810,710 | \$0 | 7/00 | 0% | 9/00 | 5/01 | 7/01 | 9/01 | 9/02 | 12/02 | Yon Tanner | TBD |
| M00008 | Electrical System Improvements, Ph 1 of 2 | \$123,556 | \$0 | 7/00 | 0% | 10/00 | 8/01 | 10/01 | 12/01 | 12/02 | 2/03 | RMH Group, Inc | TBD |
| M00009 | Segregation Unit Cell Front and Lock Replacement, Ph 1 of 1 | \$441,682 | \$0 | 7/00 | 0% | 10/00 | 8/01 | 10/01 | 12/01 | 12/02 | 2/03 | DLR Group | TBD |
| M00010 | Sewer Metering Station Replacement, Ph 1 of 1 | \$243,909 | \$0 | 7/00 | 0% | 10/00 | 4/01 | 6/01 | 8/01 | 4/02 | 7/02 | LATA | TBD |
| M00011 | Repair/Replace Mechanical Systems, Ph 1 of 3 | \$438,600 | \$0 | 7/00 | 0% | 10/00 | 5/01 | 7/01 | 9/01 | 7/02 | 9/02 | Stanley Consultants | TBD |
| M00012 | Phased Power System Replacement, Ph 1 of 3 | \$419,011 | \$0 | 7/00 | 0% | 10/00 | 8/01 | 10/01 | 1/02 | 11/02 | 1/03 | Cator Ruma | TBD |
| M00013 | Hot Water Generator Coil Replacement, Ph 1 of 1 | \$198,268 | \$0 | 7/00 | 0% | N/A | N/A | N/A | N/A | N/A | N/A | N/A | DOC |
| M00014 | Chlorofluorocarbon Refrigeration Phase-out, Ph 1 of 1 | \$172,555 | \$0 | 7/00 | 0% | 10/00 | 6/01 | 7/01 | 9/01 | 12/02 | 2/03 | RMH Group, Inc | TBD |
| M00015 | Chlorofluorocarbon Refrigeration Phase-out, Ph 1 of 1 | \$84,010 | \$0 | 7/00 | 0% | 10/00 | 6/01 | 7/01 | 9/01 | 12/02 | 2/03 | RMH Group, Inc | TBD |
| M00016 | Chlorofluorocarbon Refrigeration Phase-out, Ph 1 of 1 | \$5,833 | \$0 | 7/00 | 0% | 10/00 | 6/01 | 7/01 | 9/01 | 12/02 | 2/03 | RMH Group, Inc | TBD |
| M00017 | Chlorofluorocarbon Refrigeration Phase-out, Ph 1 of 1 | \$196,537 | \$0 | 7/00 | 0% | 10/00 | 6/01 | 7/01 | 9/01 | 12/02 | 2/03 | RMH Group, Inc | TBD |
| M00018 | Chlorofluorocarbon Refrigeration Phase-out, Ph 1 of 1 | \$32,444 | \$0 | 7/00 | 0% | 10/00 | 6/01 | 7/01 | 9/01 | 12/02 | 2/03 | RMH Group, Inc | TBD |
| M00019 | Chlorofluorocarbon Refrigeration Phase-out, Ph 1 of 1 | \$24,589 | \$0 | 7/00 | 0% | 10/00 | 6/01 | 7/01 | 9/01 | 12/02 | 2/03 | RMH Group, Inc | TBD |
| M00020 | Chlorofluorocarbon Refrigeration Phase-out, Ph 1 of 1 | \$124,738 | \$0 | 7/00 | 0% | 10/00 | 6/01 | 7/01 | 9/01 | 12/02 | 2/03 | RMH Group, Inc | TBD |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 | 0, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|--------------------|--------------------|------------------|--------------------|---------------------|------------------|-------------------|--------------------|------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract Date | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| M00021 | Chlorofluorocarbon Refrigeration Phase-out, Ph 1 of 1 | \$250,924 | \$0 | 7/00 | 0% | 10/00 | 6/01 | 7/01 | 9/01 | 12/02 | 2/03 | RMH Group, Inc | TBD |
| M00022 | Chlorofluorocarbon Refrigeration Phase-out, Ph 1 of 1 | \$336,898 | \$0 | 7/00 | 0% | 10/00 | 6/01 | 7/01 | 9/01 | 12/02 | 2/03 | RMH Group, Inc | TBD |
| M00023 | Chlorofluorocarbon Refrigeration Phase-out, Ph 1 of 1 | \$69,742 | \$0 | 7/00 | 0% | 10/00 | 6/01 | 7/01 | 9/01 | 12/02 | 2/03 | RMH Group, Inc | TBD |
| DOC | Total for the last 3 fiscal years: | \$14,631,867 | | | | | | | | | | | |
| Colorad | lo School for the Deaf and Blind | | | | | | | | | | | | |
| M80026 | Playground Safety Project, Ph 1 of 1 | \$93,758 | \$0 | 7/98 | 96% | 10/98 | 3/99 | 7/99 | N/A | 1/00 | 3/00 | Drexel Barrell | Radil Construction |
| M80027 | Sidewalk/Running Track Replacement, Ph 1 of 1 | \$225,000 | \$0 | 7/98 | 91% | 10/98 | 7/99 | 12/99 | 6/00 | 10/00 | 12/00 | Drexel Barrell | Radil Construction |
| M80028 | Restroom Upgrades, Ph 1 of 1 | \$91,500 | \$0 | 7/98 | 98% | 10/98 | 6/99 | 8/99 | 8/99 | 1/00 | 8/00 | Pahl, Pahl, Pahl | Radil Construction |
| M80029 | Campus Wide Roof Replacement and Repair, Ph 1 of 3 | \$170,773 | \$0 | 7/98 | 43% | 10/99 | 4/99 | 8/99 | 9/99 | 10/99 | 7/00 | Pahl, Pahl, Pahl | PPP Roofing |
| M80029 | Campus Wide Roof Replacement and Repair, Ph 2 of 3 | \$204,138 | \$0 | 7/00 | 0% | N/A | N/A | N/A | N/A | N/A | N/A | Pahl, Pahl, Pahl | PPP Roofing |
| M90014 | Hot Water Temperature Control - Campus, Ph 1 of 1 | \$41,000 | \$0 | 7/99 | 96% | 10/99 | 5/00 | 6/00 | 8/00 | 8/00 | 10/00 | GGA | AMS |
| M90015 | Exterior Doors Replacement - Campus, Ph 1 of 1 | \$199,800 | \$209,000 | 7/99 | 15% | 10/00 | 12/00 | 1/01 | 3/01 | 8/01 | 10/01 | Slater Paull | TBD |
| M90016 | Visual Intercom System Upgrade, Ph 1 of 1 | \$76,000 | \$0 | 7/99 | 15% | 10/00 | 9/00 | 9/00 | 11/00 | 2/01 | 12/00 | Plant Engineers | TBD |
| M90017 | Replace Corroded water Lines, Gottlieb, Ph 1 of 1 | \$292,000 | \$0 | 7/99 | 82% | 10/00 | 5/00 | 6/00 | 7/00 | 8/00 | 10/00 | GGA | Refine |
| M00024 | Remove and Replace Thermal Insulation, Ph 1 of 1 | \$70,700 | \$0 | 7/00 | 0% | 11/00 | 2/01 | 3/01 | 4/01 | 8/01 | 11/01 | TBD | TBD |
| M00025 | Electrical Distribution Upgrade, Ph 1 of 3 | \$332,823 | \$0 | 7/00 | 0% | 11/00 | 2/01 | 3/01 | 4/01 | 9/01 | 11/01 | TBD | TBD |
| M00026 | Cross Connection Control/Backflow Prevention, Ph 1 of 1 | \$58,150 | \$0 | 7/00 | 0% | 11/00 | 2/01 | 3/01 | 4/01 | 8/01 | 11/01 | TBD | TBD |
| CSDB | Total for the last 3 fiscal years: | \$1,855,642 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 |), FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Proiect | | |
|--------------|--|---------------|----------------|-------|--------------------|----------|--------------------|---------------------|------------------|-------------------|---------|-----------------------------|---|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | | Name of A/E | Name of Prime Contractor |
| Colorad | lo Historical Society | | | | | | | | | | | | |
| M80104 | Replace Electrical Systems - Ft. Vasquez, Barglow House, Ph 1 of 1 | \$80,500 | \$0 | 7/98 | 65% | 10/98 | 1/99 | 4/99 | 7/99 | 9/99 | 5/01 | Preservation Partnership | Lockhard Construction |
| M80105 | Repair Porch, Roof, Sidewalks - Barglow House, Bloom House, Ph 1 of 1 | \$41,250 | \$0 | 7/98 | 12% | 10/98 | 11/99 | 4/00 | 9/00 | N/A | 2/01 | Collaborative | TBD |
| M80106 | Replace Floor Coverings - 3 Sites, Ph 1 of 1 | \$20,813 | \$0 | 7/98 | 70% | N/A | N/A | 4/99 | N/A | N/A | 5/01 | TBD | Tony's Flooring Lockhart Construction |
| M90079 | Georgetown Loop Site Improvements, Ph 1 of 1 | \$251,725 | \$0 | 7/99 | 11% | 10/99 | 7/00 | 9/00 | 10/00 | N/A | 5/01 | Andrews & Anderson | TBD |
| M90081 | Ute Indian Landscape Upgrade, Ph 1 of 1 | \$282,097 | \$0 | 7/99 | 13% | 10/99 | 8/00 | 9/00 | 10/00 | N/A | 5/01 | Architecture 2000 | TBD |
| M90087 | Repair/Replace Roadways, Ph 1 of 1 | \$298,599 | \$0 | 7/99 | 12% | 10/99 | 8/00 | 9/00 | 10/00 | N/A | 5/01 | Andrews & Anderson | TBD |
| M00083 | Grant Humphreys Facility Improvements and Repair, Ph 1 of 1 | \$325,285 | \$0 | 7/00 | 0% | 10/00 | 2/01 | 3/01 | 3/01 | N/A | 10/01 | TBD | TBD |
| M00084 | Georgetown Loop Retaining Wall Repair/Replacement, Ph 1 of 1 | \$258,067 | \$0 | 7/00 | 0% | 10/00 | 2/01 | 3/01 | 3/01 | N/A | 10/01 | TBD | TBD |
| M00086 | Ft. Garland Code/Safety Upgrade, Ph 1 of 2 | \$250,840 | \$0 | 7/00 | 0% | 10/00 | 2/01 | 3/01 | 3/01 | N/A | 10/01 | TBD | TBD |
| M00087 | Cross Connection Control/Backflow Prevention, Ph 1 of 1 | \$46,608 | \$0 | 7/00 | 0% | 10/00 | 2/01 | 3/01 | 3/01 | N/A | 7/01 | TBD | TBD |
| DOHE-CI | HS Total for the last 3 fiscal years: | \$1,855,784 | | | | | | | | | | | |

December 5, 2000

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| F 198/9 | 9, F199/00, F100/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|--------------------|--------------------|------------------|--------------------|---------------------|------------------|-------------------|--------------------|-------------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract Date | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Univers | ity of Colorado Health Sciences Cen | ter | | | | | | | | | | | |
| M520 | Upgrade Elevators - Campus Buildings, Ph 3 of 8 | \$257,500 | \$0 | 7/98 | 100% | 10/95 | 6/99 | 2/99 | 9/99 | 9/99 | N/A | Lerch Bates Hospital Group | Montgomery KONE |
| M673 | Replace Hazardous Fume Hoods & Ventilation, Ph 12 of 12 | \$714,725 | \$0 | 7/98 | 21% | N/A | 7/99 | 8/99 | 12/00 | N/A | 5/01 | TBD | TBD |
| M727 | Repair/Replace Deteriorated Infrastructures - CPH, Ph 2 of 5 | \$800,000 | \$0 | 7/98 | 17% | 11/97 | 11/01 | 1/01 | 2/01 | 10/01 | N/A | Gordon, Gumeson & Assoc. | TBD |
| M727 | Repair/Replace Deteriorated Infrastructures - CPH, Ph 3 of 5 | \$593,692 | \$0 | 7/00 | 0% | 5/00 | 11/00 | 1/01 | 2/01 | 10/01 | 12/01 | Gordon, Gumeson & Assoc. | TBD |
| M728 | Power Plant and Campus Cooling System Improvements, Ph 4 of 9 | \$424,000 | \$0 | 7/98 | 0% | 11/97 | 1/00 | 4/00 | N/A | 8/00 | N/A | IPE | TBD |
| M728 | Power Plant and Campus Cooling System Improvements, Ph 5 of 9 | \$649,760 | \$0 | 7/99 | 0% | 9/00 | 4/01 | 5/01 | 6/01 | 10/01 | N/A | IPE | TBD |
| M729 | Replace Roofs & Windows, Ph 2 of 5 | \$258,214 | \$0 | 7/98 | 100% | 10/98 | 11/98 | 6/99 | 8/99 | 6/99 | 6/01 | Rooftech Consultants, Inc. | United Materials |
| M729 | Replace Roofs & Windows, Ph 3 of 5 | \$308,376 | \$0 | 7/00 | 0% | 9/00 | 12/00 | 1/01 | 1/01 | 4/01 | 7/01 | TBD | TBD |
| M90041 | Campus Fire Alarm System Upgrade, Ph 1 of 1 | \$345,000 | \$0 | 7/99 | 83% | 8/99 | 9/99 | 1/00 | 2/00 | 4/00 | 8/00 | Simplex | KG Electric |
| M90042 | Denison Memorial Library HVAC Improvements, Ph 1 of 1 | \$800,000 | \$0 | 7/99 | 2% | 8/99 | 7/00 | 9/00 | 2/00 | 2/01 | N/A | IPE | TBD |
| M90043 | Power Plant Heating & Electrical System Improvements, Ph 1 of 3 | \$595,700 | \$0 | 7/99 | 5% | 6/00 | 7/00 | 8/00 | 9/00 | 3/01 | 5/01 | IPE | TBD |
| M90043 | Power Plant Heating & Electrical System Improvements, Ph 2 of 3 | \$911,550 | \$0 | 7/00 | 0% | 12/00 | 2/01 | 3/01 | 6/00 | 9/01 | 10/01 | TBD | TBD |
| M00050 | Replace Underground Storage Tanks, Ph 1 of 3 | \$245,000 | \$0 | 7/00 | 0% | 7/00 | 10/00 | 12/00 | 1/01 | 5/01 | 10/01 | TBD | TBD |
| M00051 | School of Medicine Exhaust System Replacement, Ph 1 of 4 | \$611,320 | \$0 | 7/00 | 0% | 9/00 | 5/01 | 4/01 | 5/01 | 12/01 | 12/01 | TBD | TBD |
| DOHE-U | CHSC Total for the last 3 fiscal years: | \$7,514,837 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| Project CCFE # Other Project Description Contract Appr. Contract Funds Contract National Percent Funds Contract Date Contract Contra | Y98/99, | FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|---|-----------|---|-------------|-----|------|-----|--------|--------|-------|---------|----------|------------|--------------------|--------------------------------|
| M552 R/R Air Handling System, Ph 7 of 9 \$639,003 \$0 7/98 98% 9/98 12/98 3/99 4/99 8/99 10/99 PSE C M552 R/R Air Handling System, Ph 8 of 9 \$456,423 \$0 7/99 71% 8/99 10/99 11/00 11/00 2/00 1/01. PSE C M552 R/R Air Handling System, Ph 9 of 9 \$316,612 \$0 7/00 0% 7/00 10/00 11/00 1/00 2/00 4/00 RML Group, Inc M619 R/R Air Handling System, Ph 9 of 9 \$316,612 \$0 7/98 64% 10/98 11/00 1/00 2/00 3/00 3/00 Pahl, Pahl, Pahl M52 Repair/Replace Heating & Cooling Systems, Ph 7 of 7 \$0 7/98 99% 11/96 4/98 2/98 7/98 2/99 4/99 RMH Group, Inc Architects M52 Repair/Replace Central Compressed Air, Ph 2 \$307,800 \$0 7/98 94% 5/99 6/99 7/99 8/99 | | Project Description | | | | | | | | | | Settlement | Name of A/E | Name of Prime Contractor |
| M552 R/R Air Handling System, Ph 8 of 9 \$456,423 \$0 7/99 71% 8/99 10/99 11/99 12/99 2/00 1/01. PSE C M552 R/R Air Handling System, Ph 9 of 9 \$316,612 \$0 7/00 0% 7/00 10/00 11/00 2/00 4/00 RMH Group, Inc M619 R/R Deteriorated Rods, Ph 9 of 10 \$282,772 \$0 7/98 64% 10/98 11/00 1/00 2/00 4/00 RMH Group, Inc Architects M629 Repair/Replace Heating & Cooling Systems, Ph \$274,457 \$0 7/99 93% 10/99 4/00 5/00 8/00 9/04 11/04 Root Resemant & Architects M626 Repair/Replace Central Compressed Air, Ph 2 \$307,800 \$0 7/98 94% 5/99 6/99 7/98 2/99 4/99 RMH Group, Inc Group Inc Group Inc 6/2 10/00 Swanson Rink II Mechanic Repair/Replace Deteriorated Tornnel Utilities, Ph \$336,580 \$0 7/98 8/99 | Iniversit | ty of Colorado at Boulder | | | | | | | | | | | | |
| Mission Rink | 552 | R/R Air Handling System, Ph 7 of 9 | \$639,003 | \$0 | 7/98 | 98% | 9/98 | 12/98 | 3/99 | 4/99 | 8/99 | 10/99 | PSE | Colorado Piping Mechanical |
| M619 R/R Deteriorated Roofs, Ph 9 of 10 \$282,772 \$0 7/98 64% 10/98 11/00 1/00 2/00 3/00 Pahl, Pahl, Pahl, Pahl M622 Repair/Replace Heating & Cooling Systems, Ph \$274,457 \$0 7/99 93% 10/99 4/00 5/00 8/00 9/04 11/04 Root Rosenman K M626 Repair/Replace Secondary Electrical Systems, Ph \$307,800 \$0 7/98 99% 11/96 4/98 2/98 7/98 2/99 4/99 RMH Group, Inc Architects M723 Repair/Replace Central Compressed Air, Ph 2 \$307,800 \$0 7/98 23% 12/98 8/99 12/99 1/00 9/00 1/01 Farris Engineering M724 Repair/Replace Deteriorated Structural Features, Ph 1 of 1 \$320,112 \$0 7/98 83% 6/99 10/99 2/00 3/90 10/00 Roof M80049 R/R Deteriorated Structural Features, Ph 1 of 1 \$275,000 \$0 7/98 96% 10/98 11/98 | 552 | R/R Air Handling System, Ph 8 of 9 | \$456,423 | \$0 | 7/99 | 71% | 8/99 | 10/99 | 11/99 | 12/99 | 2/00 | 1/01. | PSE | Colorado Piping Mechanical |
| M622 3 of 4 Repair/Replace Heating & Cooling Systems, Ph \$274,457 \$27,457 \$0 7/99 93% 93% 10/99 4/00 5/00 8/00 9/04 11/04 Architects M626 Repair/Replace Secondary Electrical Systems, Ph 7 of 7 \$444,109 \$0 7/98 99% 11/96 4/98 2/98 7/98 2/99 4/99 RMH Group, Inc. M723 Repair/Replace Central Compressed Air, Ph 2 \$307,800 \$0 7/98 94% 5/99 6/99 7/98 8/99 2/00 1/00 Swanson Rink I M724 Repair/Replace Deteriorated Tunnel Utilities, Ph \$338,580 \$0 7/98 23% 12/98 8/99 12/99 1/00 9/00 1/01 Farris Engineering Creenberg & Creenberg | 552 | R/R Air Handling System, Ph 9 of 9 | \$316,612 | \$0 | 7/00 | 0% | 7/00 | 10/00 | 11/00 | 11/00 | 2/00 | 4/00 | RMH Group, Inc | TBD |
| 3 of 4 Architects M626 Repair/Replace Secondary Electrical Systems, Pr of 7 \$444,109 \$0 7/98 99% 11/96 4/98 2/98 7/98 2/99 4/99 RNH Group, Inc 97 M723 Repair/Replace Central Compressed Air, Ph 2 \$307,800 \$0 7/98 94% 5/99 6/99 7/98 2/99 4/99 RNH Group, Inc 97 M724 Repair/Replace Deteriorated Tunnel Utilities, Ph \$338,580 \$0 7/98 23% 12/98 8/99 12/99 1/00 9/00 1/01 Farris Engineering M724 Repair/Replace Deteriorated Structural Features, Ph 1 of 1 \$320,112 \$0 7/98 83% 6/99 10/99 2/00 3/99 9/00 10/00 Reof M80050 Repair/Replace Deteriorated Elevator Systems, Ph 1 of 2 \$219,927 \$0 7/98 89% 10/98 11/98 1/99 8/99 9/99 Stale M80051 Repair/Replace Deteriorated Elevator Systems, Ph 2 of 2 \$219,927 \$0 7/9 | 619 | R/R Deteriorated Roofs, Ph 9 of 10 | \$282,772 | \$0 | 7/98 | 64% | 10/98 | 11/00 | 1/00 | 2/00 | 3/00 | 3/00 | Pahl, Pahl, Pahl | TBD |
| Ph 7 of 7 Ph 7 of 7 Ph 7 of 7 Ph 7 of 7 M723 Repair/Replace Central Compressed Air, Ph 2 \$307,800 \$0 7/98 94% 5/99 6/99 7/99 8/99 2/00 10/00 Swanson Rink I M724 Repair/Replace Deteriorated Tunnel Utilities, Ph \$338,580 \$0 7/98 23% 12/98 8/99 12/99 1/00 9/00 1/01 Farris Engineering 2 of 2 M80049 R/R Deteriorated Structural Features, Ph 1 of 1 \$320,112 \$0 7/98 83% 6/99 10/99 2/00 3/99 9/00 10/00 Roof M80050 Repair/Replace Deteriorated Elevator Systems, Ph 1 of 1 \$275,000 \$0 7/98 96% 10/98 11/98 12/98 1/99 8/99 9/99 Stanley Consultants M80051 Repair/Replace Deteriorated Elevator Systems, Ph 1 of 1 \$275,000 \$0 7/98 89% 10/98 2/99 9/99 10/99 6/00 7/00 Associates M80051 Repair/Repla | | | \$274,457 | \$0 | 7/99 | 93% | 10/99 | 4/00 | 5/00 | 8/00 | 9/04 | 11/04 | | KCI Construction |
| of 2 M724 Repair/Replace Deteriorated Tunnel Utilities, Ph \$338,580 \$0 7/98 23% 12/98 8/99 12/99 1/00 9/00 1/01 Farris Engineering M80049 R/R Deteriorated Structural Features, Ph 1 of 1 \$320,112 \$0 7/98 83% 6/99 10/99 2/00 3/99 9/00 10/00 Roof Tech/Greenberg & Greenberg M80050 Repair/Replace Deteriorated Elevator Systems, Ph 1 of 2 \$219,927 \$0 7/98 89% 10/98 1/99 9/99 6/00 7/00 Lerch Bates & Associates M80051 Repair/Replace Deteriorated Elevator Systems, Ph 1 of 2 \$219,927 \$0 7/98 89% 10/98 2/99 9/99 10/99 6/00 7/00 Lerch Bates & Associates M80051 Repair/Replace Deteriorated Elevator Systems, Ph 2 of 2 \$216,156 \$0 7/99 95% 10/99 2/00 3/00 8/00 1/01 2/01 Lonnie Greim Elevator Systems, Associates M80052 R/R Pedestrian Routes, Ph 1 of 1 \$125,000< | | | \$444,109 | \$0 | 7/98 | 99% | 11/96 | 4/98 | 2/98 | 7/98 | 2/99 | 4/99 | RMH Group, Inc | Golden Tringle Construction |
| 2 of 2 M80049 R/R Deteriorated Structural Features, Ph 1 of 1 \$320,112 \$0 7/98 83% 6/99 10/99 2/00 3/99 9/00 10/00 Roof Tech/Greenberg & Greenberg M80050 Repair Storm Drain Laterals, Ph 1 of 1 \$275,000 \$0 7/98 96% 10/98 11/98 12/98 1/99 8/99 9/99 Stanley Consultants S M80051 Repair/Replace Deteriorated Elevator Systems, Ph 1 of 2 \$219,927 \$0 7/98 89% 10/98 2/99 9/99 6/00 7/00 Lerch Bates & Associates M80052 RR peair/Replace Deteriorated Elevator Systems, Ph 1 of 2 \$219,927 \$0 7/98 89% 10/98 2/99 9/99 10/99 6/00 7/00 Lerch Bates & Associates M80051 Repair/Replace Deteriorated Elevator Systems, Ph 2 of 2 \$216,156 \$0 7/99 95% 10/99 2/00 3/00 8/00 1/01 2/01 Lonnie Greim Ele Associates M80052 R/R Pedestrian Routes, Ph 1 of 1 \$125,000 \$0 7/98 7/98 73% 10/98 10/99 11/00 2/00 </td <td></td> <td></td> <td>\$307,800</td> <td>\$0</td> <td>7/98</td> <td>94%</td> <td>5/99</td> <td>6/99</td> <td>7/99</td> <td>8/99</td> <td>2/00</td> <td>10/00</td> <td>Swanson Rink</td> <td>US Engineering</td> | | | \$307,800 | \$0 | 7/98 | 94% | 5/99 | 6/99 | 7/99 | 8/99 | 2/00 | 10/00 | Swanson Rink | US Engineering |
| M80050 Repair Storm Drain Laterals, Ph 1 of 1 \$275,000 \$0 7/98 96% 10/98 11/98 12/98 1/99 8/99 9/99 Stanley Consultants Stanley Stanley Stanley Consultants Stanley | | | \$338,580 | \$0 | 7/98 | 23% | 12/98 | 8/99 | 12/99 | 1/00 | 9/00 | 1/01 | Farris Engineering | TBD |
| M80051 Repair/Replace Deteriorated Elevator Systems, Ph 1 of 2 \$219,927 \$0 7/98 89% 10/98 2/99 9/99 10/99 6/00 7/00 Lerch Bates & Associates M80051 Repair/Replace Deteriorated Elevator Systems, Ph 2 of 2 \$216,156 \$0 7/99 95% 10/99 2/00 3/00 8/00 1/01 2/01 Lonnie Greim Elevator Systems, Associates M80052 R/R Pedestrian Routes, Ph 1 of 1 \$125,000 \$0 7/98 48% 9/98 11/99 1/00 8/00 2/01 3/00 Design Concepts M80053 Fire Sprinkler Upgrades (Various Buildings:A), Ph 1 of 6 \$539,755 \$0 7/98 73% 10/98 10/99 11/00 2/00 1/01 MKK A M80054 Cross Connection Control/Backflow Prevention, Ph 2 of 6 \$10,99 10/98 9/00 10/01 11/00 9/00 5/01 Paul Seward Engineering M80054 Cross Connection Control/Backflow Prevention, Ph 2 of 3 \$10,98 0/99 2/00 4/00 5/00 | 80049 | R/R Deteriorated Structural Features, Ph 1 of 1 | \$320,112 | \$0 | 7/98 | 83% | 6/99 | 10/99 | 2/00 | 3/99 | 9/00 | 10/00 | Tech/Greenberg & | Krische |
| Ph 1 of 2 Associates M80051 Repair/Replace Deteriorated Elevator Systems, Ph 2 of 2 \$216,156 \$0 7/99 95% 10/99 2/00 3/00 8/00 1/01 2/01 Lonnie Greim Elevator M80052 R/R Pedestrian Routes, Ph 1 of 1 \$125,000 \$0 7/98 48% 9/98 11/99 1/00 8/00 2/01 3/00 Design Concepts M80053 Fire Sprinkler Upgrades (Various Buildings:A), Ph 1 of 6 \$539,755 \$0 7/98 73% 10/99 11/00 2/00 12/00 1/01 MKK A M80053 Fire Sprinkler Upgrades (Various Buildings:A), Ph 1 of 6 \$580,433 \$0 7/99 18% 10/99 4/00 8/00 10/00 7/01 8/01 Shaffer Baucom Engineering M80054 Cross Connection Control/Backflow Prevention, Ph 1 of 3 \$958,012 \$0 7/98 12% 10/98 9/00 10/01 11/00 9/00 5/01 Paul Seward Ph 2 of 3 M80054 Cross Connection Control/Backflow Prevention, Ph 2 of 3< | 80050 | Repair Storm Drain Laterals, Ph 1 of 1 | \$275,000 | \$0 | 7/98 | 96% | 10/98 | 11/98 | 12/98 | 1/99 | 8/99 | 9/99 | , | Scott Contracting |
| Ph 2 of 2 M80052 R/R Pedestrian Routes, Ph 1 of 1 \$125,000 \$0 7/98 48% 9/98 11/99 1/00 8/00 2/01 3/00 Design Concepts M80053 Fire Sprinkler Upgrades (Various Buildings:A), Ph 1 of 6 \$539,755 \$0 7/98 73% 10/98 10/99 11/00 2/00 12/00 1/01 MKK A M80053 Fire Sprinkler Upgrades (Various Buildings:A), Ph 1 of 6 \$580,433 \$0 7/99 18% 10/99 4/00 8/00 10/00 7/01 8/01 Shaffer Baucom Engineering M80054 Cross Connection Control/Backflow Prevention, Ph 1 of 3 \$958,012 \$0 7/98 12% 10/98 9/00 10/01 11/00 9/00 5/01 Paul Seward M80054 Cross Connection Control/Backflow Prevention, Ph 2 of 3 \$1,083,168 \$0 7/99 0% 10/99 2/00 4/00 5/00 11/00 1/01 TBD M80054 Cross Connection Control/Backflow Prevention, Ph 2 of 3 \$534,064 \$0 7/00 0% 10/99 2/00 4/00 5/00 11/00 | | | \$219,927 | \$0 | 7/98 | 89% | 10/98 | 2/99 | 9/99 | 10/99 | 6/00 | 7/00 | | Schindler |
| M80053 Fire Sprinkler Upgrades (Various Buildings:A), Ph 1 of 6 \$539,755 \$0 7/98 73% 10/98 10/99 11/00 2/00 12/00 1/01 MKK A M80053 Fire Sprinkler Upgrades (Various Buildings:A), Ph 2 of 6 \$580,433 \$0 7/99 18% 10/99 4/00 8/00 10/00 7/01 8/01 Shaffer Baucom Engineering M80054 Cross Connection Control/Backflow Prevention, Ph 1 of 3 \$958,012 \$0 7/98 12% 10/98 9/00 10/01 11/00 9/00 5/01 Paul Seward M80054 Cross Connection Control/Backflow Prevention, Ph 2 of 3 \$1,083,168 \$0 7/99 0% 10/99 2/00 4/00 5/00 11/00 1/01 TBD M80054 Cross Connection Control/Backflow Prevention, Ph 2 of 3 \$534,064 \$0 7/00 0% 10/99 2/00 4/00 5/00 11/00 1/01 TBD | | | \$216,156 | \$0 | 7/99 | 95% | 10/99 | 2/00 | 3/00 | 8/00 | 1/01 | 2/01 | Lonnie Greim | Elevators Unlimited |
| Ph 1 of 6 M80053 Fire Sprinkler Upgrades (Various Buildings:A), Ph 2 of 6 \$580,433 \$0 7/99 18% 10/99 4/00 8/00 10/00 7/01 8/01 Shaffer Baucom Engineering M80054 Cross Connection Control/Backflow Prevention, Ph 1 of 3 \$958,012 \$0 7/98 12% 10/98 9/00 10/01 11/00 9/00 5/01 Paul Seward M80054 Cross Connection Control/Backflow Prevention, Ph 1 of 3 \$1,083,168 \$0 7/99 0% 10/99 2/00 4/00 5/00 11/00 1/01 TBD M80054 Cross Connection Control/Backflow Prevention, Ph 2 of 3 \$534,064 \$0 7/00 0% 10/99 2/00 4/00 5/00 11/00 1/01 TBD | 80052 | R/R Pedestrian Routes, Ph 1 of 1 | \$125,000 | \$0 | 7/98 | 48% | 9/98 | 11/99 | 1/00 | 8/00 | 2/01 | 3/00 | Design Concepts | TBD |
| Ph 2 of 6 Engineering M80054 Cross Connection Control/Backflow Prevention, \$958,012 \$0 7/98 12% 10/98 9/00 10/01 11/00 9/00 5/01 Paul Seward M80054 Cross Connection Control/Backflow Prevention, \$1,083,168 \$0 7/99 0% 10/99 2/00 4/00 5/00 11/00 1/01 TBD M80054 Cross Connection Control/Backflow Prevention, \$1,083,168 \$0 7/99 0% 10/99 2/00 4/00 5/00 11/00 1/01 TBD M80054 Cross Connection Control/Backflow Prevention, \$534,064 \$0 7/00 0% 10/99 2/00 4/00 5/00 11/00 1/01 TBD | | | \$539,755 | \$0 | 7/98 | 73% | 10/98 | 10/99 | 11/00 | 2/00 | 12/00 | 1/01 | MKK | Alta Milla, Central Fire FP |
| Ph 1 of 3 M80054 Cross Connection Control/Backflow Prevention, \$1,083,168 \$0 7/99 0% 10/99 2/00 4/00 5/00 11/00 1/01 TBD M80054 Cross Connection Control/Backflow Prevention, \$1,083,168 \$0 7/00 0% 10/99 2/00 4/00 5/00 11/00 1/01 TBD M80054 Cross Connection Control/Backflow Prevention, \$534,064 \$0 7/00 0% 10/99 2/00 4/00 5/00 11/00 1/01 TBD | | | \$580,433 | \$0 | 7/99 | 18% | 10/99 | 4/00 | 8/00 | 10/00 | 7/01 | 8/01 | | TBD |
| Ph 2 of 3 M80054 Cross Connection Control/Backflow Prevention, \$534,064 \$0 7/00 0% 10/99 2/00 4/00 5/00 11/00 1/01 TBD | | | \$958,012 | \$0 | 7/98 | 12% | 10/98 | 9/00 | 10/01 | 11/00 | 9/00 | 5/01 | Paul Seward | TBD |
| | | | \$1,083,168 | \$0 | 7/99 | 0% | 10/99 | 2/00 | 4/00 | 5/00 | 11/00 | 1/01 | TBD | TBD |
| | | | \$534,064 | \$0 | 7/00 | 0% | 10/99 | 2/00 | 4/00 | 5/00 | 11/00 | 1/01 | TBD | TBD |
| M90032 Upgrade Central Fire Alarm Systems, Ph 1 of 4 \$389,968 \$0 7/99 75% 9/99 10/99 11/99 12/99 11/01 2/02 Simplex | 90032 | Upgrade Central Fire Alarm Systems, Ph 1 of 4 | \$389,968 | \$0 | 7/99 | 75% | 9/99 | 10/99 | 11/99 | 12/99 | 11/01 | 2/02 | Simplex | Simplex |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 Project # | , FY99/00, FY00/01 PROJECTS Project Description | CCFE Appr. | Other Funds | Date Funds Available | Percent Encumb. | Design Contract Date | Design Completion Date | Constr. Bid Date | Constr. Contract Date | Expected Occupancy Date | Project Settlement Date | Name of A/E | Name of Prime Contractor |
|-------------------------|--|---------------|----------------|----------------------------|--------------------|----------------------------|------------------------------|---------------------|-----------------------------|-------------------------------|-------------------------------|-------------------------------|-----------------------------|
| M90032 | Upgrade Central Fire Alarm Systems, Ph 2 of 4 | \$338,158 | \$0 | 7/00 | 0% | 9/00 | 11/00 | 1/01 | 2/01 | 2/02 | 4/02 | TBD | TBD |
| M90033 | Engineering Center Fire Sprinkler System Upgrades, Ph 1 of 2 | \$716,057 | \$0 | 7/99 | 12% | 10/99 | 6/00 | 8/00 | 10/00 | 4/01 | 5/01 | Gordon, Gumeson & Assoc. | TBD |
| M90034 | Muenzinger Building Fire Sprinkler System Installation, Ph 1 of 2 | \$445,371 | \$0 | 7/99 | 21% | 8/99 | 2/00 | 3/01 | 5/01 | 9/01 | 10/01 | Shaffer Baucom Engineering | TBD |
| M90034 | Muensinger Building Fire Sprinkler System Installation, Ph 2 of 2 | \$481,323 | \$0 | 7/00 | 0% | 8/99 | 2/00 | 3/01 | 5/01 | 9/01 | 10/01 | Shaffer Baucom Engineering | TBD |
| M90035 | Repair/Replace Obsolete Central HVAC Controls, Ph 1 of 3 | \$165,320 | \$0 | 7/99 | 75% | 8/99 | 11/99 | 1/00 | 2/00 | 6/00 | 9/00 | RMH Group, Inc | Westover |
| M90035 | Repair/Replace Obsolete Central HVAC Controls, Ph 2 of 3 | \$170,279 | \$0 | 7/00 | 0% | 7/00 | 9/00 | 10/00 | 11/00 | 11/01 | 1/02 | RMH Group, Inc | TBD |
| M90036 | Repair 3rd Floor A/C, Ph 1 of 2 | \$394,020 | \$0 | 7/99 | 13% | 9/99 | 12/99 | 9/01 | 4/02 | 7/03 | 9/03 | Engineering Solutions | TBD |
| M90037 | Engineering Center HVAC Upgrades, Design, Ph 1 of 1 | \$410,909 | \$0 | 7/99 | 30% | 9/99 | 9/00 | 10/00 | 11/00 | 1/04 | 1/04 | Cator Ruma | TBD |
| M924 | R/R Steam Distribution System, Ph 8B & 9 of 10 | \$557,058 | \$0 | 7/98 | 79% | 10/98 | 1/99 | 2/99 | 3/99 | 9/99 | 1/01 | Stanley Consultants | Scott Contracting |
| M00038 | Campus Steam Tunnel Structural Upgrades, Ph 1 of 3 | \$296,600 | \$0 | 7/00 | 30% | 9/00 | 4/01 | 5/01 | 6/01 | 9/01 | 11/01 | TBD | TBD |
| M00039 | Mt. Research Station Wastewater Treatment Plant, Ph 1 of 1 | \$977,705 | \$0 | 7/00 | 100% | 12/96 | 12/99 | 1/00 | 6/00 | 12/00 | 2/01 | Boyle Engineering | Grayon Corporation |
| M00040 | Repair/Replace Deteriorated Roadways, Ph 1 of 2 | \$305,285 | \$0 | 7/00 | 0% | 10/00 | 2/00 | 3/01 | 4/01 | 6/01 | 7/01 | TBD | TBD |
| M00041 | Main Campus Tunnel Security Projects, Ph 1 of 3 | \$169,156 | \$0 | 7/00 | 0% | 9/00 | 4/01 | 5/01 | 6/01 | 11/01 | 2/02 | TBD | TBD |
| M00042 | Roof Repair/Replace and Water Proofing, Ph 1 of 3 | \$439,272 | \$0 | 7/00 | 0% | 9/00 | 1/00 | 2/00 | 3/00 | 6/00 | 7/00 | Pahl, Pahl, Pahl | TBD |
| M00043 | Drainage Improvements, Ph 1 of 2 | \$616,043 | \$0 | 7/00 | 0% | 9/00 | 1/01 | 5/01 | 6/01 | 9/01 | 12/01 | WRC Engineering | TBD |
| DOHE-U | CB Total for the last 3 fiscal years: \$ | 14,783,907 | | | | | | | | | | | |

December 5, 2000

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 | , FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|---|---------------|----------------|--------------------|--------------------|------------------|--------|---------------------|----------|-------------------|---------|-----------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract Date | 0 | Constr. Bid Date | Contract | Occupancy Date | , | Name of A/E | Name of Prime Contractor |
| Univers | ity of Colorado at Colorado Springs | | | | | | | | | | | | |
| M80055 | Replace Fire Alarm System, Ph 1 of 1 | \$167,000 | \$0 | 7/98 | 90% | 10/98 | 10/99 | 11/99 | 11/99 | N/A | 8/00 | Cator Ruma | John Bowman, Inc. |
| M80056 | Replace Air Volume Controls, Ph 1 of 1 | \$54,000 | \$0 | 7/98 | 4% | 10/98 | 8/00 | 10/00 | 2/01 | N/A | 3/01 | MKK | TBD |
| M80057 | Replace Radiators & Controls, Ph 1 of 1 | \$125,000 | \$0 | 7/98 | 6% | 10/98 | 8/00 | 10/00 | 2/01 | N/A | 3/01 | MKK | TBD |
| M90038 | Replace HVAC Science Building, Ph 1 of 5 | \$800,000 | \$0 | 7/99 | 73% | 11/99 | 3/00 | 4/00 | 5/00 | N/A | 11/00 | Gordon, Gumeson & Assoc. | Commercial Design |
| M90039 | Replace Vane Axial Fans - Engineering Building, Ph 1 of 1 | \$121,000 | \$0 | 7/99 | 7% | 10/99 | 8/00 | 10/00 | 3/01 | N/A | 5/00 | MKK | TBD |
| M90040 | Repair & Waterproof Gallery A/C Area - Science Building, Ph 1 of 1 | \$23,000 | \$0 | 7/99 | 56% | 9/99 | 9/99 | 10/99 | 10/99 | N/A | 12/99 | N/A | Torres & Associates |
| M00044 | Relocate Emergency Generator Science Building, Ph 1 of 1 | \$56,650 | \$0 | 7/00 | 0% | 8/00 | 9/00 | 10/00 | 10/00 | N/A | 3/01 | TBD | TBD |
| M00045 | Replace Chiller/Cooling Tower Engineering Building, Ph 1 of 1 | \$140,000 | \$0 | 7/00 | 0% | 9/00 | 8/01 | 5/01 | 6/01 | N/A | 12/01 | TBD | TBD |
| M00046 | Replace Roof Dwire Hall, Ph 1 of 1 | \$155,000 | \$0 | 7/00 | 0% | 9/00 | 4/01 | 5/01 | 6/01 | N/A | 12/01 | TBD | TBD |
| M00047 | Replace Locks/Hardware Dwire Hall and Science Building, Ph 1 of 1 | \$112,270 | \$0 | 7/00 | 0% | 9/00 | 11/00 | 12/00 | 12/00 | N/A | 10/01 | TBD | TBD |
| M00048 | Replace Roof Engineering and Applied Science Building, Ph 1 of 1 | \$425,000 | \$0 | 7/00 | 0% | 9/00 | 4/01 | 5/01 | 5/01 | N/A | 12/01 | TBD | TBD |
| M00049 | Replace Boiler Dwire Hall, Ph 1 of 1 | \$144,200 | \$0 | 7/00 | 0% | 9/00 | 2/01 | 3/01 | 4/01 | N/A | 9/01 | TBD | TBD |
| DOHE-UC | CCS Total for the last 3 fiscal years: | \$2,323,120 | | | | | | | | | | | |

December 5, 2000

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | 9, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|---|---------------|----------------|-------|--------------------|----------|--------------------|---------------------|----------|----------|---------|-------------------------------|----------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract | | , | Name of A/E | Name of Prime Contractor |
| Colorad | lo State University | | | | | | | | | | | | |
| M612 | Replace Deteriorated Plumbing - Micro, Ph 3 of 3 | \$803,243 | \$0 | 7/98 | 99% | 10/96 | 3/99 | 3/99 | 5/99 | 9/99 | 1/00 | MKK | MBI |
| M709 | Replace Deteriorated Safety Systems - Campus Buildings, Ph 2 of 2 | \$138,345 | \$0 | 7/98 | 96% | 1/99 | 5/98 | 2/00 | 3/00 | 5/00 | 5/00 | Luis O. Acosta | Interstate Mechanical Systems |
| M710 | Replace Deteriorated Items - Student Services, Ph 2 of 2 | \$301,157 | \$0 | 7/98 | 96% | 9/97 | 3/98 | 3/98 | 3/98 | 9/98 | 12/98 | Luis O. Acosta | MBI |
| M711 | Replace Deteriorated Items - Administrative Annex, Ph 2 of 2 | \$819,144 | \$0 | 7/98 | 22% | N/A | N/A | N/A | N/A | N/A | N/A | ARG | MBI |
| M712 | Repair/Replace Deteriorated Mechanical Systems, Ph 2 of 3 | \$514,296 | \$0 | 7/98 | 84% | 10/98 | 6/99 | 6/99 | 7/99 | N/A | 4/00 | IPE | Phillips |
| M712 | Repair/Replace Deteriorated Mechanical Systems, Ph 3 of 3 | \$552,458 | \$0 | 7/99 | 0% | 9/99 | 5/00 | 6/00 | 6/00 | N/A | 4/01 | IPE | Natkin |
| M713 | Repair Campus Roads, Ph 2 of 2 | \$373,343 | \$0 | 7/98 | 37% | N/A | N/A | N/A | N/A | N/A | N/A | TBD | TBD |
| M714 | Replace Deteriorated Roofs - Campus Buildings, Ph 2 of 3 | \$343,705 | \$0 | 7/98 | 100% | 8/98 | 11/98 | 3/99 | 5/99 | N/A | 1/00 | Rooftech Consultants, Inc. | D&D Roofing/B&M |
| M714 | Replace Deteriorated Roofs - Campus Buildings, Ph 3 of 3 | \$346,342 | \$0 | 7/99 | 99% | 8/99 | 11/97 | 3/00 | 5/00 | N/A | 10/00 | Rooftech Consultants, Inc. | B&M Roofing |
| M715 | Replace Deteriorated Items - University Greenhouse, Ph 2 of 2 | \$370,985 | \$0 | 7/98 | 0% | in house | e N/A | N/A | N/A | N/A | N/A | Gene Leach | TBD |
| M80038 | Replace Heating Plant Oil Tank, Ph 1 of 1 | \$485,828 | \$0 | 7/98 | 98% | 8/97 | 5/98 | 4/99 | 5/99 | N/A | 12/99 | Terracon | Eaton Metals |
| M80039 | Replace Deteriorated Items - G bbons Hall, Ph 1 of 1 | \$135,000 | \$0 | 7/98 | 95% | 10/97 | N/A | 3/98 | 3/98 | N/A | N/A | Architecture 2000 | Sun Construction FCI, Inc. |
| M80040 | Chlorofluorocarbon Refrigeration Phase out, Ph 1 of 1 | \$349,526 | \$0 | 7/98 | 0% | 8/97 | 7/97 | 8/97 | N/A | N/A | N/A | Cator Ruma | BT Construction |
| M80041 | Cross Connection Control/Backflow Prevention, Ph 1 of 2 | \$400,000 | \$0 | 7/98 | 100% | 9/98 | 1/99 | 6/99 | 7/99 | N/A | 7/00 | Stanley Consultants | Natkin |
| M80041 | Cross Connection Control/Backflow Prevention, Ph 2 of 3 | \$855,182 | \$0 | 7/99 | 6% | 9/99 | 10/99 | 11/99 | 9/00 | N/A | 4/00 | Stanley Consultants | Natkin |
| M80041 | Cross Connection Control/Backflow Prevention, Ph 3 of 3 | \$880,837 | \$0 | 7/00 | 0% | 9/00 | 9/00 | 9/00 | 9/00 | N/A | 9/02 | Stanley Consultants | TBD |
| M90023 | Replace Deteriorating Mechanical - Gifford, Atmospheric Science, Ph 1 of 2 | \$147,000 | \$0 | 7/99 | 36% | 8/99 | 3/00 | 5/00 | 7/00 | N/A | 5/01 | IPE | Natkin |
| M90023 | Replace Deteriorating Mechanical - Gifford, Atmospheric Science, Ph 2 of 2 | \$352,981 | \$0 | 7/00 | 0% | 8/00 | 5/02 | 5/02 | 7/02 | N/A | 10/02 | IPE | Natkin |
| M90024 | Replace 13.8 KV Lines - Pitkin and Mason, Ph 1 of 2 | \$595,924 | \$0 | 7/99 | 49% | 10/99 | 3/00 | 5/00 | 6/00 | N/A | 2/01 | Gordon, Gumeson & Assoc. | Interstate Electric |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 | , FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|--------------------|--------------------|------------------|--------------------|---------------------|------------------|-------------------|--------------------|-------------------------------|-------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract Date | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| M90024 | Replace 13.8 KV Lines - Pitkin and Mason, Ph 2 of 2 | \$613,802 | \$0 | 7/00 | 0% | 10/99 | 3/00 | 5/00 | 6/00 | N/A | 2/01 | Gordon, Gumeson & Assoc. | Interstate Electric |
| M90025 | Install East Drive to Center Street Steam Loop, Ph 1 of 3 | \$149,000 | \$0 | 7/99 | 88% | 7/99 | 3/00 | 1/01 | 9/01 | N/A | 6/02 | Cator Ruma | Hoff |
| M90025 | Install east Drive to Center Street Steam Loop, Ph 2 of 3 | \$439,244 | \$0 | 7/00 | 0% | 7/99 | 3/00 | 1/01 | 9/01 | N/A | 6/02 | Cator Ruma | Hoff |
| M90026 | Replace Deteriorated Greenhouses, Ph 1 of 2 | \$656,958 | \$0 | 7/99 | 100% | 6/99 | 8/99 | 4/00 | 6/00 | 12/00 | 12/01 | KDA, P.C. | RusDen |
| M90026 | Replace Deteriorated Greenhouses, Ph 2 of 2 | \$378,498 | \$0 | 7/00 | 75% | 6/99 | 8/99 | 5/00 | 6/00 | 12/00 | 12/01 | KDA, P.C. | RusDen |
| M90027 | Replace Condensate Lines: 16G, H & South Loop, Ph 1 of 1 | \$366,303 | \$0 | 7/99 | 86% | 7/99 | 3/00 | 3/00 | 4/00 | N/A | 5/01 | Cator Ruma | Hoff |
| M90028 | Replace Deteriorated Flooring - Auditorium Gymnasium, Ph 1 of 2 | \$354,700 | \$0 | 7/99 | 100% | 8/99 | 5/99 | 5/99 | 6/99 | 8/99 | 9/99 | Aller Lingle | Western Floor, Inc. |
| M90028 | Replace Deteriorated Flooring - Auditorium Gymnasium, Ph 2 of 2 | \$402,936 | \$0 | 7/00 | 77% | 8/99 | 11/00 | 12/00 | 12/00 | 5/01 | 9/01 | Aller Lingle | Western Floor, Inc. |
| M90029 | Replace Deteriorated Items - Painting and Publications, Ph 1 of 2 | \$518,590 | \$0 | 7/99 | 28% | 8/99 | 5/00 | 5/00 | 8/00 | 8/01 | 8/02 | ARG | Sun Construction FCI, Inc. |
| M90029 | Replace Deteriorated Items - Painting and Publications, Ph 2 of 2 | \$585,036 | \$0 | 7/00 | 0% | 8/99 | 5/00 | 5/00 | 8/00 | 8/01 | 8/02 | ARG | Sun Construction FCI, Inc. |
| M90030 | Replace Deteriorated Items - Experiment Stations, CSFS, Ph 1 of 2 | \$360,000 | \$0 | 7/99 | 77% | 10/99 | 4/00 | 5/00 | 12/00 | N/A | 12/01 | KDA, P.C. | TBD |
| M90030 | Replace Deteriorated Items - Experiment Stations, CSFS, Ph 2 of 2 | \$104,451 | \$0 | 7/00 | 0% | 10/00 | 5/01 | 6/01 | 6/01 | N/A | 12/02 | KDA, P.C. | TBD |
| M90031 | Chlorofluorocarbon Refrigeration Phase out, Ph 1 of 2 | \$1,257,600 | \$0 | 7/99 | 100% | 7/99 | 12/99 | 3/00 | 3/00 | N/A | 6/00 | Cator Ruma | RK Mech/Haynes |
| M90031 | Chlorofluorocarbon Refrigeration Phase out, Ph 2 of 2 | \$980,411 | \$0 | 7/00 | 91% | 6/00 | 10/00 | 11/00 | 12/00 | N/A | 10/01 | Cator Ruma | TBD |
| M00031 | Replace Irrigation Intake Structure College Lake, Ph 1 of 1 | \$197,332 | \$0 | 7/00 | 0% | 10/00 | 7/00 | 1/01 | 1/01 | N/A | 4/01 | Love & Associates | TBD |
| M00032 | Replace Deteriorated Items - Wager, Ph 1 of 3 | \$660,413 | \$0 | 7/00 | 37% | 1/00 | 3/01 | 4/01 | 5/01 | N/A | 10/02 | ARG | TBD |
| M00033 | Replace Deteriorated Roads \$ Sidewalks, Ph 1 of 5 | \$544,500 | \$0 | 7/00 | 27% | 8/00 | 7/00 | 6/00 | 47/00 | N/A | 8/00 | S.A. Miro | Connell |
| M00034 | Replace Deteriorated Roofing, Ph 1 of 2 | \$464,260 | \$0 | 7/00 | 9% | 10/00 | 1/01 | 2/01 | 3/01 | N/A | 9/01 | Rooftech Consultants, Inc. | TBD |
| DOHE-CS | SU Total for the last 3 fiscal years: | \$17,799,330 | | | | | | | | | | | |

December 5, 2000

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | 9, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Proiect | | |
|--------------|---|---------------|----------------|-------|--------------------|----------|--------------------|---------------------|------------------|-------------------|---------|----------------------------------|------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | - , | Name of A/E | Name of Prime Contractor |
| Univers | ity of Southern Colorado | | | | | | | | | | | | |
| M80045 | Chlorofluorocarbon Refrigeration Phase out, Ph 3 of 3 | \$50,000 | \$0 | 7/00 | 100% | 10/98 | 8/99 | 9/99 | 10/99 | 6/00 | 9/00 | AMS | МКК |
| M616 | Replace Deteriorating Utility Distribution System, Ph 2 of 3 | \$648,921 | \$0 | 7/99 | 25% | 2/99 | 7/99 | 8/99 | 9/99 | 9/00 | 10/00 | Gordon, Gumeson & Assoc. | TBD |
| M616 | Replace Deteriorating Utility Distribution System, Ph 3 of 3 | \$445,549 | \$0 | 7/00 | 0% | 8/00 | 11/00 | 1/01 | 2/01 | 11/01 | 1/02 | TBD | TBD |
| M716 | Replace Fire Alarm Monitoring & Protection Sytem, Ph 2 of 3 | \$283,561 | \$0 | 7/98 | 100% | 7/98 | 7/99 | 8/99 | 9/99 | 11/00 | 1/01 | Peak Fire Engineering, Inc | Life Safety Systems |
| M716 | Replace Fire Alarm Monitoring & Protection Sytem, Ph 3 of 3 | \$790,978 | \$0 | 7/99 | 83% | 7/98 | 7/99 | 8/99 | 9/99 | 11/00 | 1/01 | Peak Fire Engineering, Inc. | Life Safety Systems |
| M80042 | Repair Hazardous Waste Storage Facility, Ph 1 of 1 | \$60,600 | \$0 | 7/98 | 92% | 9/98 | 10/98 | 1/99 | 1/99 | 9/99 | 10/99 | Gallegos Design Group | Carlisle Building Systems |
| M80043 | Repair/Replace Exterior Doors, Windows, and Panels, Ph 1 of 1 | \$307,919 | \$0 | 7/98 | 23% | 11/98 | 8/00 | 9/00 | 10/00 | 01/01 | 2/01 | Gifford Spurck and Associates | TBD |
| M80044 | Replace Campus Roofs, Ph 1 of 1 | \$323,590 | \$0 | 7/98 | 67% | 9/98 | 4/99 | 6/99 | 7/99 | 4/00 | 7/00 | Rooftech Consultants, Inc. | Athey-Beaman |
| M80045 | Chlorofluorocarbon Refrigeration Phase out, Ph 1 of 3 | \$418,797 | \$0 | 7/98 | 100% | 10/98 | 8/99 | 9/99 | 10/99 | 6/00 | 9/00 | AMS | МКК |
| M80045 | Chlorofluorocarbon Refrigeration Phase out, Ph 2 of 3 | \$569,397 | \$0 | 7/99 | 8% | 10/98 | 8/99 | 9/99 | 10/99 | 6/00 | 9/00 | AMS | МКК |
| M00035 | Replace Deteriorated Steam Distribution System, Ph 1 of 3 | \$987,552 | \$0 | 7/00 | 6% | 9/00 | 4/01 | 6/01 | 9/01 | 9/02 | 11/02 | TBD | TBD |
| DOHE-U | SC Total for the last 3 fiscal years: | \$4,886,864 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | 9, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|---|---------------|----------------|--------------------|--------------------|----------|--------------------|---------------------|------------------|-------------------|--------------------|-------------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Fort Le | wis College | | | | | | | | | | | | |
| M719 | Replace Campus Master Fire Alarm System, Ph 2 of 4 | \$418,141 | \$0 | 7/98 | 100% | 12/97 | 5/98 | 7/98 | 7/98 | N/A | 10/99 | Gordon, Gumeson & Assoc. | Nichols Electric, Inc. |
| M719 | Replace Campus Master Fire Alarm System, Ph 3 of 4 | \$448,692 | \$0 | 7/99 | 75% | 12/97 | 11/99 | 11/99 | 12/99 | N/A | 10/00 | Gordon, Gumeson & Assoc. | Nichols Electric, Inc. |
| M719 | Replace Campus Master Fire Alarm System, Ph 4 of 4 | \$451,358 | \$0 | 7/00 | 0% | 11/00 | 3/01 | 5/01 | 7/01 | N/A | 8/02 | Gordon, Gumeson & Assoc. | TBD |
| M80046 | Rehabilitate Deteriorated Natatorium Facility, Ph 1 of 2 | \$429,728 | \$0 | 7/98 | 100% | 7/98 | 5/99 | 6/99 | 7/99 | N/A | 4/00 | R. Michael Bell & Assoc. | N.I.C.E. |
| M80046 | Rehabilitate Deteriorated Natatorium Facility, Ph 2 of 3 | \$561,775 | \$0 | 7/99 | 8% | 7/98 | 10/99 | 12/99 | 1/00 | N/A | 10/00 | R. Michael Bell & Assoc. | N.I.C.E |
| M80047 | Roof Replacement, Library, Ph 1 of 1 | \$287,488 | \$0 | 7/98 | 99% | 7/98 | 5/99 | 6/99 | 6/99 | N/A | 10/99 | R. Michael Bell & Assoc. | N.I.C.E. |
| M80048 | Cross Connection Control/Backflow Prevention, Ph 1 of 3 | \$32,416 | \$0 | 7/98 | 100% | 9/98 | 3/99 | 10/99 | 10/99 | N/A | 12/99 | McLaughlin Water Engineers | TBD |
| M80048 | Cross Connection Control/Backflow Prevention, Ph 2 of 3 | \$133,299 | \$0 | 7/99 | 34% | 7/99 | 12/99 | 6/00 | 6/00 | N/A | 12/00 | Eng Econ Inc. | Neil's Excavation |
| M80048 | Cross Connection Control/Backflow Prevention, Ph 3 of 3 | \$123,773 | \$0 | 7/00 | 0% | 10/00 | 1/01 | 3/01 | 5/01 | N/A | 5/02 | TBD | TBD |
| M00036 | Rehabilitate West Physical Plant Building, Ph 1 of 1 | \$509,170 | \$0 | 7/00 | 0% | 10/00 | 4/01 | 6/01 | 8/01 | N/A | 8/02 | R. Michael Bell & Assoc. | TBD |
| M00037 | Repair/Replace Deteriorated Irrigation System, Ph 1 of 1 | \$456,084 | \$0 | 7/00 | 0% | 10/00 | 5/01 | 7/01 | 9/01 | N/A | 10/02 | EDAW Inc. | TBD |
| DOHE-FL | C Total for the last 3 fiscal years: | \$3,851,924 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | , FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|-------|--------------------|----------|--------------------|---------------------|----------|-------------------|--------------------|---------------------------------|-------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Univers | ity of Northern Colorado | | | | | | | | | | | | |
| M629 | Rebuild/Overhaul Elevators, Ph 3 of 3 | \$379,600 | \$0 | 7/98 | 94% | 10/96 | 11/98 | 12/98 | 9/99 | 8/00 | 9/00 | Lerch Bates North American | Amtech Elevator Services |
| M731 | HTHW Tunnel Piping, Ph 2 of 2 | \$569,400 | \$0 | 7/98 | 100% | 10/97 | 5/98 | 6/98 | 6/98 | 7/99 | 9/99 | Farris Engineering | Gracon Corporation |
| M732 | Campus-wide Roof Replacement, Ph 2 of 4 | \$295,500 | \$0 | 7/98 | 63% | 7/97 | 1/99 | 2/99 | 2/99 | 7/99 | 7/00 | Rooftech Consultants, Inc. | Arapahoe Roofing |
| M732 | Campus-wide Roof Replacement, Ph 3 of 4 | \$321,800 | \$0 | 7/99 | 69% | 7/97 | 1/00 | 3/00 | 5/00 | 7/00 | 7/00 | Rooftech Consultants, Inc. | Arapahoe Roofing |
| M732 | Campus-wide Roof Replacement, Ph 4 of 4 | \$292,108 | \$0 | 7/00 | 71% | 9/97 | 1/01 | 2/01 | 3/01 | 7/01 | 8/01 | Rooftech Consultants, Inc. | TBD |
| M80061 | Replace East/West High Voltage Cable, Ph 1 of 2 | \$322,700 | \$0 | 7/98 | 89% | 7/98 | 3/99 | 4/99 | 6/99 | 8/00 | 8/00 | Gordon, Gumeson & Assoc. | KEAL Corporation |
| M80061 | Replace East/West High Voltage Cable, Ph 2 of 2 | \$942,910 | \$0 | 7/99 | 58% | 7/99 | 3/99 | 2/00 | 2/99 | 8/00 | 8/00 | Gordon, Gumeson & Assoc. | KEAL Corporation |
| M80062 | Cross Connection Control/Backflow Prevention, Ph 1 of 2 | \$697,431 | \$0 | 7/98 | 75% | 10/98 | 5/99 | 6/99 | 6/99 | 8/00 | 8/00 | Seward Mechanical Systems | Colorado Piping Mechanical |
| M80062 | Cross Connection Control/Backflow Prevention, Ph 2 of 2 | \$349,560 | \$0 | 7/99 | 75% | 10/98 | 5/99 | 6/99 | 6/99 | 8/00 | 8/00 | Seward Merchanical System | Colorado Piping Mechanical |
| M80063 | Chlorofluorocarbon Refrigeration Phase out, Ph 1 of 1 | \$171,742 | \$0 | 7/98 | 100% | 9/98 | 1/99 | 2/99 | 2/99 | 7/99 | 9/99 | Seward Mechanical Systems | Midlands Mechanical |
| M90045 | Exterior Building Systems Repair, Ph 1 of 3 | \$135,000 | \$0 | 7/99 | 21% | 10/99 | 5/00 | 6/00 | 10/00 | N/A | 8/01 | Ken Dabbs Architect | TBD |
| M90045 | Exterior Building Systems Repair, Ph 2 of 3 | \$363,771 | \$0 | 7/00 | 0% | 10/99 | 5/00 | 6/00 | 10/00 | N/A | 8/01 | Ken Dabbs Architect | TBD |
| M00053 | Replace Deteriorated Systems Butler Hancock, Ph 1 of 2 | \$671,158 | \$0 | 7/00 | 64% | 6/00 | 9/00 | 9/00 | 11/00 | 8/01 | 10/02 | Barker Rinker Seacat | Sun Construction FCI, Inc. |
| M00054 | Replace Deteriorated Stairs and Wa kways Campus Wide, Ph 1 of 2 | \$214,721 | \$0 | 7/00 | 1% | 9/00 | 1/01 | 3/01 | 3/01 | 6/02 | 10/02 | TBD | TBD |
| DOHE-UN | NC Total for the last 3 fiscal years: | \$5,727,401 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 | 9, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|---------|--|-------------|-------|-----------|-----------|----------|------------|----------|----------|-----------|------------|---------------------------------|--|
| Project | | CCFE | Other | Funds | | Contract | Completion | Constr. | Contract | Occupancy | Settlement | | Name of Prime |
| # | Project Description | Appr. | Funds | Available | e Encumb. | Date | Date | Bid Date | Date | Date | Date | Name of A/E | Contractor |
| Adams | State College | | | | | | | | | | | | |
| M607 | Boiler Plant and Steam Distribution Replacement, Ph 3 of 3 | \$735,683 | \$0 | 7/98 | 95% | N/A | N/A | N/A | N/A | N/A | N/A | TBD | TBD |
| M80030 | Telephone Switch/Life Safety Upgrades - Richardson, Ph 1 of 1 | \$485,982 | \$0 | 7/98 | 95% | 7/98 | 1/99 | 2/99 | 4/99 | 8/99 | 8/99 | Carter Burgess | Van Iwarrden Builders Inc |
| M80031 | Art Building Roof/Ceiling Abatement, Ph 1 of 1 | \$390,200 | \$0 | 7/98 | 68% | 7/98 | 4/99 | 5/99 | 7/99 | N/A | 9/00 | Moyes Associates | Hazardous Waste Shurtleff-Gahatan |
| M80032 | Cross Connection Control/Backflow Prevention, Ph 1 of 2 | \$77,180 | \$0 | 7/98 | 87% | 7/98 | 3/99 | 4/99 | 3/99 | N/A | 3/00 | Seward Mechanical Systems | Vendola Plumbing and Heating |
| M80032 | Cross Connection Control/Backflow Prevention, Ph 2 of 2 | \$207,861 | \$0 | 7/99 | 87% | 7/98 | 3/99 | 4/99 | 3/99 | N/A | 3/00 | Seward Mechanical Systems | Vendola Plumbing and Heating |
| M90018 | Abate Asbestos ES & Plachy, Ph 1 of 2 | \$726,000 | \$0 | 7/99 | 68% | 8/99 | 10/99 | 1/00 | 2/00 | N/A | 9/00 | Walsh Environmental | National Service Cleaning Corporation |
| M90018 | Abate Asbestos ES & Plachy, Ph 2 of 2 | \$741,002 | \$0 | 7/00 | 68% | N/A | N/A | N/A | N/A | N/A | N/A | TBD | TBD |
| M90019 | Replace L brary Carpeting, Ph 1 of 1 | \$334,053 | \$0 | 7/98 | 98% | 6/99 | 9/99 | 10/99 | 1/99 | N/A | 4/00 | Pahl, Pahl, Pahl | United Flooring |
| M00027 | Replace/Resurface Stadium and Field House Tracks, Ph 1 of 2 | \$649,472 | \$0 | 7/00 | 100% | 9/00 | 2/01 | 3/01 | 4/01 | 8/01 | 10/01 | Davis Partnership | TBD |
| DOHE-AS | SC Total for the last 3 fiscal years: | \$4,347,433 | | | | | | | | | | | |
| Mesa S | tate College | | | | | | | | | | | | |
| M80033 | Replace Boilers, Heiny Hall & Saunders Fieldhouse, Ph 1 of 1 | \$191,180 | \$0 | 7/98 | 98% | 7/98 | 1/99 | 2/99 | 3/99 | N/A | 10/99 | Burke Associates | Lane & Co. |
| M80034 | Building Repairs - Houston Hall, Ph 1 of 4 | \$316,245 | \$0 | 7/98 | 99% | 7/98 | 3/99 | 4/99 | 7/99 | 8/99 | 2/00 | Burke Associates | Cookeys Mechanical |
| M80034 | Building Repairs - Houston Hall, Ph 2 of 4 | \$425,387 | \$0 | 7/99 | 75% | 7/98 | 3/99 | 4/99 | 6/99 | 8/99 | 2/00 | Burke Associates | Cookeys Mechanical |
| M80034 | Building Repairs - Houston Hall, Ph 3 of 4 | \$323,341 | \$0 | 7/00 | 0% | 7/98 | 3/01 | 4/01 | 5/01 | 8/01 | 10/01 | Burke Associates | TBD |
| M90020 | Building Repairs, Walter Walker Fine Arts Center, Ph 1 of 4 | \$390,788 | \$0 | 7/99 | 79% | 8/99 | 3/00 | 4/00 | 6/00 | 8/00 | 10/00 | Burke Associates | Eberhart Electric |
| M90020 | Building Repairs, Walter Walker Fine Arts Center, Ph 2 of 4 | \$425,125 | \$0 | 7/00 | 6% | 8/99 | 3/01 | 4/01 | 5/01 | 8/01 | 10/01 | Burke Associates | TBD |
| M00028 | Buildings Envelope Repairs Saunders Fieldhouse, Ph 1 of 1 | \$251,000 | \$0 | 7/00 | 0% | 9/00 | 3/01 | 4/01 | 5/01 | 8/01 | 10/01 | Kenneth Hunt, PC | TBD |
| DOHE-M | SC Total for the last 3 fiscal years: | \$2,323,066 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | , FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|---|---------------|----------------|--------------------|--------------------|----------|--------------------|---------------------|------------------|-------------------|--------------------|-------------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Westerr | N State College | | | | | | | | | | | | |
| M510 | Replace/Repair Roofing System, Ph 5 of 5 | \$516,780 | \$0 | 7/98 | 100% | 8/98 | 5/98 | 6/98 | 8/98 | 8/99 | 10/99 | Rooftech Consultants, Inc. | PPP Roofing |
| M80035 | Repair/Replace Fire Protection System, Ph 1 of 1 | \$344,711 | \$0 | 7/98 | 100% | 11/97 | 3/98 | 6/98 | 7/98 | 8/99 | 9/99 | Gordon Gumeson + JCN | Excell + Eberhart |
| M80036 | Repair/Replace HVAC and Heating, Ph 1 of 3 | \$239,314 | \$0 | 7/98 | 35% | 8/98 | 7/99 | 12/99 | 1/00 | 9/00 | 11/00 | RMH Group, Inc | Gunnison Metal Shop |
| M80036 | Repair/Replace HVAC and Heating, Ph 2 of 3 | \$263,706 | \$0 | 7/99 | 35% | 8/98 | 7/00 | 12/00 | 1/01 | 9/01 | 11/01 | RMH Group, Inc | TBD |
| M80036 | Repair/Replace HVAC and Heating, Ph 3 of 3 | \$335,215 | \$0 | 7/00 | 35% | 8/98 | 7/00 | 12/00 | 1/01 | 9/01 | 11/01 | RMH Group, Inc | TBD |
| M80037 | Cross Connection Control/Backflow Prevention, Ph 1 of 2 | \$182,984 | \$0 | 7/98 | 100% | 8/97 | 2/98 | 4/97 | 5/98 | 9/98 | 10/98 | McLaughlin Water Engineers | Schmalz Construction |
| M80037 | Cross Connection Control/Backflow Prevention, Ph 2 of 2 | \$20,960 | \$0 | 7/99 | 100% | 8/97 | 2/98 | 4/98 | 5/98 | N/A | 10/00 | McLaughlin Water Engineers | Schmalz Construction |
| M90021 | Replace Hazardous Ceiling Tile, Ph 1 of 1 | \$700,000 | \$0 | 7/99 | 100% | 7/99 | 7/99 | 7/99 | 7/99 | 8/99 | 9/99 | Walsh Environmental | NSC Corporation |
| M90022 | Repair/Replace Roofing Systems, Ph 1 of 2 | \$321,000 | \$0 | 7/99 | 90% | 7/99 | 7/99 | 8/99 | 9/99 | N/A | 3/01 | Rooftech Consultants, Inc. | PPP Roofing |
| M90022 | Repair/Replace Roofing Systems, Ph 2 of 2 | \$292,184 | \$0 | 7/00 | 90% | 7/00 | 7/00 | 8/00 | 9/00 | N/A | 3/01 | Rooftech Consultants, Inc. | PPP Roofing |
| M00029 | Repair/Replace Miscellaneous Fire Alarm Systems, Ph 1 of 2 | \$191,000 | \$0 | 7/00 | 15% | 8/00 | 3/01 | 5/01 | 6/01 | 9/01 | 10/01 | JCN Engineering | TBD |
| M00030 | Replair/Replace Parking Lots/Streets, Ph 1 of 5 | \$360,500 | \$0 | 7/00 | 15% | 9/00 | 4/01 | 5/01 | 6/01 | 9/01 | 10/01 | Bucher, Willis & Ratliff | TBD |
| DOHE-W | SC Total for the last 3 fiscal years: | \$3,768,354 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | 9, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|---|---------------|----------------|--------------------|--------------------|------------------|--------------------|---------------------|------------------|-------------------|--------------------|---|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract Date | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Colorad | to School of Mines | | | | | | | | | | | | |
| M627 | Deteriorated HVAC System Replacement, Ph 3 of 5 | \$781,765 | \$0 | 7/98 | 87% | 11/99 | 4/00 | 5/00 | 5/00 | 2/01 | 5/01 | ME Group | Westland Construction |
| M627 | Deteriorated HVAC System Replacement, Ph 4 of 5 | \$812,146 | \$0 | 7/99 | 87% | 11/99 | 4/00 | 5/00 | 5/00 | 2/01 | 5/01 | ME Group | Westland Construction |
| M627 | Deteriorated HVAC System Replacement, Ph 5 of 5 | \$843,550 | \$0 | 7/00 | 0% | 5/01 | 11/01 | 12/01 | 2/02 | 12/02 | 2/03 | TBD | TBD |
| M628 | Electrical Safety Fire Detection/Protection Systems Upgrade, Ph 3 of 5 | \$352,213 | \$0 | 7/98 | 5% | 3/00 | 5/01 | 6/01 | 7/01 | 1/02 | 3/02 | Grinnell/Corey Electrical Engineers | Grinnell |
| M628 | Electrical Safety Fire Detection/Protection Systems Upgrade, Ph 4 of 5 | \$364,545 | \$0 | 7/99 | 0% | 10/00 | 2/01 | 4/01 | 6/01 | 12/01 | 3/02 | TBD | TBD |
| M628 | Electrical Safety Fire Detection/Protection Systems Upgrade, Ph 5 of 5 | \$146,536 | \$0 | 7/00 | 0% | 2/01 | 5/01 | 7/01 | 9/01 | 11/01 | 1/02 | TBD | TBD |
| M80058 | Campus Steam and Condensate Line Repairs, Ph 1 of 3 | \$277,276 | \$0 | 7/98 | 100% | 8/98 | 9/98 | 9/98 | 10/98 | 3/99 | 4/99 | Stanley Consultants | Ram Mechanical |
| M80058 | Campus Steam and Condensate Line Repairs, Ph 2 of 2 | \$409,038 | \$0 | 7/99 | 0% | 9/00 | 12/00 | 1/01 | 3/01 | 8/01 | 10/01 | TBD | TBD |
| M80059 | Cross Connection Control/Backflow Prevention, Ph 1 of 2 | \$80,180 | \$0 | 7/98 | 5% | 10/98 | 7/00 | 8/00 | 8/00 | 8/01 | 12/01 | Stanley Consultants | TBD |
| M80059 | Cross Connection Control/Backflow Prevention, Ph 2 of 2 | \$121,893 | \$0 | 7/98 | 5% | 10/98 | 10/99 | 12/99 | 12/99 | 12/00 | 2/01 | Stanley Consultants | TBD |
| M80060 | Chlorofluorocarbon Refrigeration Phase out, Ph 1 of 2 | \$320,077 | \$0 | 7/98 | 34% | 10/98 | 12/99 | 2/00 | 3/00 | 8/00 | 9/00 | Engineering Solutions | Gracon Corporation |
| M80060 | Chlorofluorocarbon Refrigeration Phase out, Ph 2 of 2 | \$108,260 | \$0 | 7/00 | 0% | 5/01 | 12/01 | 3/02 | 5/02 | 12/02 | 2/03 | TBD | TBD |
| M00052 | Guggenheim Crawl Space Abatement, Ph 1 of 1 | \$198,480 | \$0 | 7/00 | 0% | 6/00 | 10/00 | 4/01 | 5/01 | 7/01 | 9/01 | AES | TBD |
| DOHE-C | SM Total for the last 3 fiscal years: | \$4,815,959 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | 9, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Proiect | | |
|--------------|---|---------------|----------------|--------------------|--------------------|----------|--------------------|---------------------|------------------|-------------------|--------------------|------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Auraria | Higher Education Center | | | | | | | | | | | | |
| M650 | Repair/Replace Fire Protection Systems, Ph 3 of 4 | \$443,100 | \$0 | 7/98 | 100% | 9/97 | 9/98 | 10/98 | 5/98 | 12/99 | 12/99 | EMC Engineers, Inc. | Johnson Controls |
| M650 | Repair/Replace Fire Protection Systems, Ph 4 of 4 | \$651,300 | \$0 | 7/99 | 100% | 2/00 | 4/00 | 5/00 | 6/00 | 6/01 | 7/01 | Carter Burgess | Interstate Electric |
| M80100 | Repair/Replace Plumbing Systems, Ph 1 of 1 | \$424,700 | \$0 | 7/98 | 85% | N/A | N/A | N/A | N/A | N/A | 12/00 | Stanley Consultants | ET Technologies |
| M80101 | Repair/Replace Storm Drain System, Ph 1 of 4 | \$159,000 | \$0 | 7/98 | 100% | N/A | N/A | N/A | N/A | N/A | 6/00 | AR7 Hoover Desmond | Hensel Phelps |
| M80101 | Repair/Replace Storm Drain System, Ph 2 of 4 | \$701,400 | \$0 | 7/99 | 60% | 8/99 | 1/00 | 10/00 | 1/01 | 8/01 | 9/01 | Merrik | Hensel Phelps |
| M80101 | Repair/Replace Storm Drain System, Ph 3 of 4 | \$439,200 | \$0 | 7/00 | 10% | 8/00 | 11/00 | 12/00 | 2/01 | 8/01 | 9/01 | Merr k | TBD |
| M80102 | Repair/Replace Plaza Decks, Ph 1 of 1 | \$708,800 | \$0 | 7/98 | 98% | N/A | N/A | N/A | 7/98 | 9/98 | 12/00 | Pahl, Pahl, Pahl | United Materials |
| M80103 | Cross Connection Control/Backflow Prevention, Ph 1 of 1 | \$472,900 | \$0 | 7/98 | 95% | 1/99 | 7/99 | 7/99 | 8/99 | 12/99 | 7/00 | Stanley Consultants | Westland Construction |
| M90078 | Repair/Replace Electrical High Voltage Cable System, Ph 1 of 4 | \$293,900 | \$0 | 7/99 | 100% | 9/99 | 1/99 | 6/00 | 8/00 | 8/01 | 12/01 | RMH Group, Inc | N/A |
| M90078 | Repair/Replace Electrical High Voltage Cable System, Ph 2 of 4 | \$760,600 | \$0 | 7/00 | 40% | 9/99 | 1/99 | 6/00 | 8/00 | 8/01 | 12/01 | RMH Group, Inc | Power Electric |
| M00081 | Repair/Replace Roofing/Weathertight Enclosures, Ph 1 of 2 | \$441,500 | \$0 | 7/00 | 10% | 9/00 | 11/00 | 2/01 | 3/01 | 7/01 | 8/01 | Pahl, Pahl, Pahl | TBD |
| M00082 | Chlorofluorocarbon Refrigeration Phase out, Ph 1 of 1 | \$509,388 | \$0 | 7/00 | 10% | 9/00 | 11/00 | 12/00 | 12/00 | 3/01 | 7/01 | RMH Group, Inc | TBD |
| DOHE-A | HEC Total for the last 3 fiscal years: | \$6,005,788 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| F 198/99 | , FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|--------------------|--------------------|------------------|--------------------|---------------------|------------------|-------------------|---------|--------------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract Date | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | | Name of A/E | Name of Prime Contractor |
| Arapaho | be Community College | | | | | | | | | | | | |
| M80064 | Asbestos Abatement, Ph 1 of 1 | \$114,000 | \$0 | 7/98 | 99% | 10/98 | 3/99 | 4/99 | 5/99 | 6/99 | 2/00 | Gobbell Hays Partners, Inc. | DLM, Inc. |
| M80065 | Engineering Analysis of Structural Concrete, Ph 1 of 1 | \$23,000 | \$0 | 7/98 | 70% | N/A | N/A | N/A | N/A | N/A | 8/00 | Wiss, Janney, Elstner | N/A |
| M80066 | Boiler Replacement, Ph 1 of 1 | \$124,000 | \$0 | 7/98 | 77% | 10/98 | 5/99 | 7/99 | 8/99 | 8/00 | 8/00 | The RMH Group | Longero |
| M80067 | Absorber Repair/Cooling Tower Replacement, Ph 1 of 1 | \$187,450 | \$0 | 7/98 | 98% | 10/98 | 3/99 | 3/99 | 5/99 | 12/00 | 12/00 | The RMH Group | Burgess Services |
| M90046 | South Building, Life Safety, Ph 1 of 1 | \$279,000 | \$0 | 7/99 | 10% | 10/99 | 7/00 | 8/00 | 10/00 | 1/01 | 2/01 | MKK | TBD |
| M90047 | Cafeteria Exhaust/Make-up Air Repair - Main Building, Ph 1 of 1 | \$123,787 | \$0 | 7/99 | 10% | 10/99 | 3/00 | 10/00 | N/A | 2/01 | 3/01 | MKK | TBD |
| M90048 | Roof, Window and Door Replacement: Main, North and Annex, Ph 1 of 2 | \$141,445 | \$0 | 7/99 | 85% | 10/99 | 3/00 | 4/00 | 4/00 | 7/00 | 8/00 | Marc Diament | B&M Roofing |
| M00055 | Structural/Exterior Concrete Repair Main Annex, Ph 1 of 2 | \$331,950 | \$0 | 7/00 | 0% | 9/00 | 12/00 | 1/01 | 2/01 | 7/01 | 8/01 | TBD | TBD |
| M00056 | Alamo Center Roof Replacement, Ph 1 of 1 | \$391,145 | \$0 | 7/00 | 13% | 7/00 | 12/00 | 1/01 | 2/01 | 12/01 | 1/01 | Marc Diament | TBD |
| DOHE-AC | CC Total for the last 3 fiscal years: | \$1,715,777 | | | | | | | | | | | |
| Colorad | lo Northwestern Community College | • | | | | | | | | | | | |
| M90059 | Asbestos Removal - Rangely Campus, Ph 1 of 1 | \$23,000 | \$0 | 7/99 | 100% | N/A | N/A | 9/99 | 10/99 | N/A | 6/00 | N/A | Asbestos Abatement, Inc. |
| M90060 | Roofing Replacement - Rangely Campus, Ph 1 of 3 | \$234,230 | \$0 | 7/99 | 10% | 10/99 | 7/00 | 8/00 | 8/00 | 12/00 | 3/01 | Blythe Design | TBD |
| M90061 | Sidewalk Replacement - Rangely Campus, Ph 1 of 3 | \$170,700 | \$0 | 7/99 | 10% | 10/99 | 7/00 | 8/00 | 8/00 | 12/00 | 3/01 | Blythe Design | TBD |
| M90062 | Parking Lot Replacement - Craig Campus, Ph 1 of 2 | \$145,468 | \$0 | 7/99 | 10% | 10/99 | 7/00 | 8/00 | 8/00 | 12/00 | 3/01 | Blythe Design | TBD |
| M90062 | Parking Lot Replacement - Craig Campus, Ph 2 of 2 | \$64,732 | \$0 | 7/00 | 0% | 5/00 | 7/00 | 8/00 | 8/00 | 12/00 | 3/01 | Blythe Design | TBD |
| M00065 | Outdoor Lighting Upgrade - Rangely Campus, Ph 1 of 2 | \$35,000 | \$0 | 7/00 | 10% | 5/00 | 7/00 | 8/00 | 8/00 | 12/00 | 3/01 | Blythe Design | TBD |
| M00066 | Air conditioning Upgrades - Rangely Campus, Ph 1 of 2 | \$73,286 | \$0 | 7/00 | 10% | 5/00 | 7/00 | 8/00 | 8/00 | 12/00 | 3/01 | Blythe Design | TBD |
| DOHE-CI | NCC Total for the last 3 fiscal years: | \$746,416 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 | 9, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|-------|--------------------|----------|--------------------|---------------------|------------------|-------------------|--------------------|---|--------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Front R | ange Community College | | | | | | | | | | | | |
| M634 | Renovate Swimming Pool, Ph 2 of 2 | \$275,000 | \$22,436 | 7/98 | 100% | 5/98 | 11/98 | 11/98 | 12/98 | 2/99 | 5/99 | Ohlson Lavoie/Gordon Gumeson | Golden Tringle Construction |
| M736 | Repair Deficiencies in HVAC System, Ph 2 of 4 | \$781,924 | \$0 | 7/98 | 100% | 10/97 | 4/98 | 5/98 | 6/98 | 5/99 | 5/99 | Gordon, Gumeson & Assoc. | AMI Mechanical |
| M736 | Repair Deficiencies in HVAC System, Ph 3 of 4 | \$583,217 | \$0 | 7/99 | 100% | 10/97 | 4/98 | 5/99 | 7/99 | 7/00 | 9/00 | Gordon, Gumeson & Assoc. | AMI Mechanical |
| M736 | Repair Deficiencies in HVAC System, Ph 4 of 4 | \$958,844 | \$0 | 7/00 | 10% | 10/97 | 4/98 | 5/00 | 7/00 | 12/00 | 1/01 | Gordon, Gumeson & Assoc. | AMI Mechanical |
| M90049 | Repair Fire Detection & Alarm System, Ph 1 of 1 | \$442,000 | \$0 | 7/99 | 8% | 8/99 | 8/00 | 8/00 | 9/00 | 5/01 | 6/01 | Gordon, Gumeson & Assoc. | TBD |
| M00057 | Asbestos Abatement Ceiling Tile - Larimer Campus, Ph 1 of 1 | \$348,694 | \$0 | 7/00 | 0% | 10/00 | 2/01 | 4/01 | 5/01 | 9/01 | 9/01 | Stewart Environmental Consultants | TBD |
| DOHE-FI | RCC Total for the last 3 fiscal years: | \$3,389,679 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 | 9, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Proiect | | |
|--------------|--|---------------|----------------|-------|--------------------|----------|--------------------|---------------------|------------------|-------------------|------------|---------------------------------|------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement | Name of A/E | Name of Prime Contractor |
| Lamar | Community College | | | | | | | | | | | | |
| M80068 | Parking Lot Lighting, Ph 1 of 1 | \$29,565 | \$0 | 7/98 | 30% | 10/98 | 8/99 | 10/99 | 2/99 | 5/01 | 6/01 | Michael Brendle & Associates | H.W. Houston Construction |
| M80069 | Exterior Repairs - Campus Buildings, Ph 1 of 1 | \$75,832 | \$0 | 7/98 | 17% | 10/98 | 8/99 | 10/99 | 2/99 | 5/01 | 6/01 | Michael Brendle & Associates | H.W. Houston Construction |
| M80070 | Replace Condensing Fan - Bowman, Ph 1 of 1 | \$32,250 | \$0 | 7/98 | 25% | 10/98 | 8/99 | 10/99 | 2/99 | 5/01 | 6/01 | Michael Brendle & Associates | H.W. Houston Construction |
| M80071 | Cross Connection Control/Backflow Prevention, Ph 1 of 2 | \$27,979 | \$0 | 7/98 | 20% | 10/98 | 8/99 | 10/99 | 2/99 | 5/01 | 6/01 | Michael Brendle & Associates | H.W. Houston Construction |
| M80071 | Cross Connection Control/Backflow Prevention, Ph 2 of 2 | \$4,826 | \$0 | 7/99 | 20% | 10/98 | 8/99 | 10/99 | 2/99 | 5/01 | 6/01 | Michael Brendle & Associates | H.W. Houston Construction |
| M90050 | Cosmetology Ventilation Bathroom Upgrade, Ph 1 of 1 | \$21,550 | \$0 | 7/99 | 12% | 9/99 | 12/00 | 1/01 | 1/01 | 3/01 | 4/01 | Michael Brendle & Associates | TBD |
| M90051 | Roof Replacement Trustees Buildings, Ph 1 of 1 | \$193,062 | \$0 | 7/99 | 73% | 9/99 | 4/00 | 7/00 | 8/00 | 10/00 | 10/00 | Rooftech Consultants, Inc. | Athey-Beaman |
| M90052 | Tennis, Basketball Court Repair, Ph 1 of 1 | \$56,718 | \$0 | 7/99 | 8% | 9/99 | 8/00 | 9/00 | 9/00 | 10/00 | 10/00 | Northstar Engineering | TBD |
| M00058 | Window Upgrades Bowman/Trustees Buildings, Ph 1 of 2 | \$363,098 | \$0 | 7/00 | 0% | 9/00 | 4/01 | 5/01 | 5/01 | 8/02 | 10/01 | TBD | TBD |
| M00059 | Cosmetology Sanitary Sewer Replacement, Ph 1 of 1 | \$16,620 | \$0 | 7/00 | 0% | 9/00 | 4/01 | 5/01 | 5/01 | 8/01 | 9/01 | TBD | TBD |
| M00060 | Exterior Caulking/Painting Campus Buildings, Ph 1 of 1 | \$31,450 | \$0 | 7/00 | 0% | 9/00 | 4/01 | 5/01 | 5/01 | 8/01 | 9/01 | TBD | TBD |
| DOHE-LO | CC Total for the last 3 fiscal years: | \$852,950 | | | | | | | | | | | |

23 of 34

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 |), FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|--------------------|--------------------|------------------|--------------------|---------------------|------------------|-------------------|--------------------|----------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract Date | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Morgan | Community College | | | | | | | | | | | | |
| M80072 | Replace Fire Alarm, Ph 1 of 1 | \$31,000 | \$0 | 7/98 | 99% | 9/98 | 3/99 | 6/99 | 8/99 | 4/00 | 6/00 | Stanley Consultants | Gregory Electric, Inc. |
| M80073 | Install Storage Decks, Ph 1 of 1 | \$20,400 | \$0 | 7/98 | 100% | N/A | N/A | N/A | 10/98 | 10/99 | 12/99 | N/A | Midwestern Millwright |
| M80074 | Exterior Building Renovation, Ph 1 of 1 | \$32,160 | \$0 | 7/98 | 100% | 9/98 | 10/98 | 11/98 | 11/98 | 3/99 | 8/99 | Bennett, Wagner & Grody | Restoration Specialists |
| M80075 | Rekey - New Security, Ph 1 of 1 | \$39,600 | \$0 | 7/98 | 100% | N/A | N/A | N/A | N/A | N/A | 2/99 | N/A | Best Access Systems |
| M90053 | Bloedorn Hall Classroom Repairs, Ph 1 of 1 | \$39,100 | \$0 | 7/99 | 65% | 9/99 | 5/00 | 5/00 | 6/00 | 10/00 | 12/00 | Bennett, Wagner & Grody | Central Coating Co. |
| M90054 | Exterior Envelope Upgrade, Ph 1 of 1 | \$168,614 | \$0 | 7/99 | 90% | 9/99 | 4/00 | 5/00 | 6/00 | 12/00 | 3/01 | Bennett, Wagner & Grody | Ash & White |
| M90055 | Bloedorn Center, Building Repairs, Ph 1 of 1 | \$16,874 | \$0 | 7/99 | 17% | 9/99 | 9/00 | 11/00 | 12/00 | 5/01 | 6/01 | Bennett, Wagner & Grody | TBD |
| M00061 | Handicapped Accessibility/Restrooms Relocation and Upgrade, Ph 1 of 1 | \$299,400 | \$0 | 7/00 | 5% | 9/00 | 12/00 | 1/01 | 2/01 | 4/01 | 8/01 | Bennett, Wagner & Grody | TBD |
| M00062 | Repairs to Spruce Hall, Ph 1 of 2 | \$249,900 | \$0 | 7/00 | 5% | 10/00 | 6/01 | 7/01 | 8/01 | 8/02 | 9/02 | DLR Group | TBD |
| DOHE-M | CC Total for the last 3 fiscal years: | \$897,048 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | , FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|---|---------------|----------------|-------|--------------------|----------|--------------------|---------------------|----------|-------------------|--------------------|-----------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Northea | stern Junior College | | | | | | | | | | | | |
| M80076 | Asphalt Replacement, Ph 1 of 2 | \$255,571 | \$0 | 7/98 | 100% | 11/98 | 5/99 | 6/99 | 7/99 | 8/99 | 10/00 | TSP-5 | McAtee Paving |
| M80076 | Asphalt Replacement, Ph 2 of 2 | \$126,370 | \$0 | 7/99 | 6% | 11/99 | 6/00 | 6/00 | 7/00 | 8/00 | 10/00 | TSP-5 | TBD |
| M80077 | Building Upgrades - Phillips-Whyman, Ph 1 of 2 | \$551,584 | \$0 | 7/98 | 11% | 9/00 | 10/00 | 11/00 | 12/00 | 6/01 | 6/01 | Hanson Enterprises | TBD |
| M80077 | Building Upgrades - Phillips-Whyman, Ph 2 of 2 | \$57,500 | \$0 | 7/99 | 0% | 9/00 | 10/00 | 11/00 | 12/00 | 8/01 | 9/01 | Hanson Enterprises | TBD |
| M80078 | Cross Connection Control/Backflow Prevention, Ph 1 of 2 | \$44,244 | \$0 | 7/98 | 69% | N/A | N/A | N/A | N/A | N/A | 10/00 | NJC | NJC |
| M80078 | Cross Connection Control/Backflow Prevention, Ph 2 of 2 | \$2,881 | \$0 | 7/99 | 94% | N/A | N/A | N/A | N/A | N/A | 10/00 | NJC | NJC |
| M90056 | Fire Detection and Alarm Upgrades, Ph 1 of 1 | \$102,423 | \$0 | 7/99 | 16% | 10/99 | 4/00 | 5/00 | 12/00 | 2/01 | 6/01 | Gordon, Gumeson & Assoc. | TBD |
| M90057 | Install Pitched Roofs on Four Main Campus Buildings, Ph 1 of 3 | \$272,643 | \$0 | 7/99 | 12% | 10/99 | 12/00 | 2/01 | 3/01 | 7/01 | 6/05 | Hanson Enterprises | TBD |
| M90057 | Install Pitched Roofs on Four Main Campus Buildings, Ph 2 of 3 | \$189,596 | \$0 | 7/00 | 0% | 10/99 | 12/00 | 2/01 | 3/01 | 7/01 | 8/01 | Hanson Enterprises | TBD |
| M90058 | Replace Rooftop Units on Beede-Hamil, Ph 1 of 1 | \$142,000 | \$0 | 7/99 | 9% | 10/99 | 12/00 | 2/01 | 3/01 | 7/01 | 8/01 | Abrahamson Engineering | TBD |
| M00063 | Replace Boiler in Phillips-Whyman, Ph 1 of 1 | \$113,062 | \$0 | 7/00 | 0% | 10/00 | 12/00 | 2/01 | 3/01 | 8/01 | 9/01 | TBD | TBD |
| M00064 | Replace Overhead Garae Doors on Campus, Ph 1 of 1 | \$54,852 | \$0 | 7/00 | 0% | 10/00 | 11/00 | 11/00 | 12/00 | 1/01 | 2/01 | TBD | TBD |
| DOHE-NJ | C Total for the last 3 fiscal years: | \$1,912,726 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 | , FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|---|---------------|----------------|--------------------|--------------------|------------------|--------------------|---------------------|------------------|-------------------|--------------------|-------------------------------|--------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract Date | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Otero Ju | unior College | | | | | | | | | | | | |
| M80079 | Humanities Stage Repair, Ph 1 of 1 | \$91,404 | \$0 | 7/98 | 100% | 8/98 | 2/99 | 4/99 | 5/99 | 9/99 | 11/99 | Christiansen Reece | Arc Valley Construction |
| M80080 | Boiler and Pump Replacement, Ph 1 of 1 | \$33,554 | \$0 | 7/98 | 100% | 6/98 | 8/98 | 11/98 | 12/98 | 1/99 | 1/99 | Farris Engineering | OJC/Longero, Inc. |
| M80081 | Resurface Athletic Court, Ph 1 of 1 | \$68,280 | \$0 | 7/98 | 100% | 6/98 | 2/99 | 3/99 | 5/99 | 8/99 | 10/00 | North Star Engineering | Kirkland Construction |
| M80082 | Replace Floor Coverings, Ph 1 of 1 | \$49,801 | \$0 | 7/98 | 100% | 8/98 | 10/98 | 8/99 | 8/99 | 6/99 | 6/00 | Christiansen Reece | Pryor Floor Floorcraft |
| M90063 | McBride Hall Heating System Repair & Code Corrections, Ph 1 of 2 | \$216,462 | \$0 | 7/99 | 100% | 10/99 | 3/00 | 4/00 | 5/00 | 9/00 | 10/00 | Shaffer Baucom Engineering | Lyle's Plumbing and Heating |
| M90063 | Mcbride Hall Heating System, Ph 2 of 2 | \$86,127 | \$0 | 7/00 | 100% | 10/99 | 3/00 | 4/00 | 7/00 | 9/00 | 10/00 | Shaffer Baucom Engineering | Lyle's Plumbing and Heating |
| M90064 | Maintenance Building HVAC Equipment Replacement, Ph 1 of 1 | \$18,128 | \$0 | 7/99 | 100% | 10/99 | 3/00 | 5/00 | 5/00 | 9/00 | 10/00 | Shaffer Baucom Engineering | Armor Street Metal |
| M00067 | Koshare Indian Museum Repair and Code Corrections, Ph 1 of 2 | \$628,687 | \$0 | 7/00 | 0% | 10/00 | 5/01 | 5/01 | 6/01 | 11/01 | 12/01 | TBD | TBD |
| M00068 | Cross Connection Control/Backflow Prevention, Ph 1 of 1 | \$67,012 | \$0 | 7/00 | 0% | 8/00 | 11/00 | 2/01 | 3/01 | 6/01 | 6/01 | TBD | TBD |
| DOHE-O. | IC Total for the last 3 fiscal years: | \$1,259,455 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | , FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|---|---------------|----------------|--------------------|--------------------|------------------|--------------------|---------------------|------------------|-------------------|--------------------|--------------------|--------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract Date | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Pikes P | eak Community College | | | | | | | | | | | | |
| M641 | Replace HVAC Units, Ph 3 of 5 | \$36,999 | \$0 | 7/98 | 100% | N/A | N/A | N/A | PO | 5/99 | 9/01 | TBD | Carrier |
| M641 | Replace HVAC Units, Ph 4 of 5 | \$38,708 | \$0 | 7/99 | 91% | N/A | N/A | N/A | PO | 7/00 | 9/01 | N/A | Carrier |
| M641 | Replace HVAC Units, Ph 5 of 5 | \$39,869 | \$0 | 7/00 | 0% | N/A | N/A | N/A | PO | 7/00 | 9/01 | N/A | Carrier |
| M80083 | DDC System Upgrade, Ph 1 of 3 | \$164,700 | \$0 | 7/98 | 100% | 10/98 | 10/99 | 10/99 | 1/00 | 7/00 | 6/01 | Farris Engineering | Baker White Electric |
| M80083 | DDC System Upgrade, Ph 2 of 3 | \$104,800 | \$0 | 7/99 | 46% | 10/98 | 10/99 | 10/99 | 1/00 | 7/00 | 9/01 | Farris Engineering | Baker White Electric |
| M80083 | DDC System Upgrade, Ph 3 of 3 | \$144,127 | \$0 | 7/00 | 0% | 10/98 | 10/99 | 10/99 | 1/00 | 7/00 | 9/01 | Farris Engineering | Baker White Electric |
| M80084 | Replace Steam Plant Coal Storge Bins, Ph 1 of 1 | \$75,842 | \$0 | 7/98 | 0% | N/A | N/A | N/A | N/A | N/A | N/A | Reverted | Reverted |
| M80085 | Repair and Resurface Tennis Courts, Ph 1 of 1 | \$43,751 | \$0 | 7/98 | 100% | N/A | N/A | 10/98 | 10/98 | 5/99 | 6/99 | N/A | Southwest Recreation, Inc. |
| M80086 | Roadway Repair & Asphalt Overlay, Ph 1 of 1 | \$156,094 | \$0 | 7/98 | 100% | N/A | N/A | 10/98 | 10/98 | 5/99 | 6/99 | N/A | Schmidt Constr. |
| M80087 | Cross Connection Control/Backflow Prevention, Ph 1 of 3 | \$14,126 | \$0 | 7/98 | 100% | N/A | N/A | 10/98 | 10/98 | 5/99 | 9/01 | N/A | Heating & Plumbing Engineer |
| M80087 | Cross Connection Control/Backflow Prevention, Ph 2 of 3 | \$38,117 | \$0 | 7/99 | 95% | N/A | N/A | 10/99 | 10/99 | 1/00 | 9/01 | TBD | Heating & Plumbing Engineer |
| M80087 | Cross Connection Control/Backflow Prevention, Ph 3 of 3 | \$5,227 | \$0 | 7/00 | 0% | N/A | N/A | 5/00 | 6/00 | 9/01 | 9/01 | N/A | Heating & Plumbing Engineer |
| M90065 | Emergency Lighting & Elevator Power, Ph 1 of 1 | \$35,000 | \$0 | 7/99 | 100% | N/A | N/A | 10/99 | 10/99 | 12/99 | 2/00 | N/A | Advanced Electric |
| M90066 | Steam Plant & Chiller Conversion, Ph 1 of 1 | \$650,000 | \$0 | 7/99 | 15% | 11/99 | 6/00 | 7/00 | 8/00 | 12/00 | 9/01 | Farris Engineering | TBD |
| M00069 | Electrical Systems Upgrade, Ph 1 of 1 | \$164,511 | \$0 | 7/00 | 0% | 10/00 | 1/01 | 2/01 | 3/01 | 3/02 | 9/02 | TBD | TBD |
| M00088 | Roof Replacement Aspen and Breckenridge Buildings, Ph 1 of 4 | \$222,074 | \$0 | 7/00 | 0% | 10/00 | 1/01 | 2/01 | 3/01 | 3/02 | 5/05 | TBD | TBD |
| DOHE-PF | Total for the last 3 fiscal years: | \$1,933,945 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 | , FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|-------|--------------------|----------|--------------------|---------------------|----------|-------------------|---------|--|-------------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract | Occupancy Date | , | Name of A/E | Name of Prime Contractor |
| Pueblo | Community College | | | | | | | | | | | | |
| M80088 | Asbestos Abatement Technical Education Building, Ph 1 of 1 | \$326,818 | \$0 | 7/98 | 78% | 7/98 | 11/98 | 2/99 | 3/99 | N/A | 6/01 | Occupational Health Technologies | Environmental Abatement Services |
| M80089 | Window & Roof Repair CA Building, Ph 1 of 1 | \$122,755 | \$0 | 7/98 | 80% | 8/98 | 10/98 | 11/98 | 10/99 | N/A | 12/99 | Pahl, Pahl, Pahl | G & K Glass Weathercraft Co. |
| M80090 | Building Repair - Technical Education Building, Ph 1 of 1 | \$222,081 | \$0 | 7/98 | 33% | 8/98 | 2/99 | 2/99 | 3/99 | N/A | 6/00 | TSP 5 | Bryan Construction |
| M90067 | Keyless Entry System Campus Wide, Ph 1 of 1 | \$197,581 | \$0 | 7/99 | 100% | N/A | N/A | N/A | N/A | N/A | 10/01 | PCC | PCC |
| M90068 | Repair Tennis Courts, Ph 1 of 1 | \$50,000 | \$0 | 7/99 | 76% | 8/99 | 9/99 | 11/99 | 11/99 | N/A | 6/00 | Bradley Bean | Allied Paving |
| M00070 | Video Monitoring System Campus Wide, Ph 1 of 1 | \$148,813 | \$0 | 7/00 | 0% | 8/00 | 8/00 | 9/00 | 10/00 | N/A | 6/01 | PCC | PCC |
| M00071 | Upgrade DDC System Campus Wide, Ph 1 of 1 | \$428,455 | \$0 | 7/00 | 0% | 8/00 | 8/00 | 8/00 | 10/00 | N/A | 6/02 | PCC | Trane Co. |
| M00072 | Roof Repairs on Industrial Technology/Technical Education Buildings, Ph 1 of 1 | \$73,185 | \$0 | 7/00 | 0% | 8/00 | 8/00 | 8/00 | 8/00 | N/A | 6/01 | PCC | Athey Beaman |
| DOHE-PC | CC Total for the last 3 fiscal years: | \$1,569,688 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 |), FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|---|---------------|----------------|-------|--------------------|----------|--------------------|---------------------|----------|-------------------|--------------------|-----------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Red Ro | cks Community College | | | | | | | | | | | | |
| M80091 | Upgrade Firelanes, Ph 1 of 1 | \$115,960 | \$0 | 7/98 | 100% | 10/98 | 7/99 | 4/00 | 6/00 | 7/00 | 12/00 | Design Workshop | RBI |
| M80092 | Pedestrian Walkway Lighting, Ph 1 of 1 | \$86,044 | \$0 | 7/98 | 10% | 10/98 | 6/00 | 8/00 | 10/00 | 1/01 | 3/01 | Design Workshop | TBD |
| M80093 | Upgrade Air Filtering System, Ph 1 of 1 | \$20,920 | \$0 | 7/98 | 100% | N/A | N/A | 10/98 | 10/98 | 2/99 | 2/99 | RRCC | APH Services |
| M80094 | Replacement of Air Cooled Condenser, Ph 1 of 1 | \$59,136 | \$0 | 7/98 | 100% | 9/98 | 4/99 | 7/99 | 10/99 | 3/00 | 8/00 | Gordon, Gumeson & Assoc. | Wesco |
| M80095 | Replacement of Fire Science Rooftop HVAC Unit, Ph 1 of 1 | \$36,355 | \$0 | 7/98 | 100% | 9/98 | 4/99 | 7/99 | 10/99 | 12/99 | 8/00 | Gordon, Gumeson & Assoc. | Wesco |
| M90069 | Replacement of Emergency Stairs, Ph 1 of 1 | \$21,764 | \$0 | 7/99 | 90% | 10/99 | 2/00 | 4/00 | 5/00 | 8/00 | 10/00 | MaxFour | Berville, Inc. |
| M90070 | Replacement of Domestic Water Line - CTB, Ph 1 of 1 | \$37,209 | \$0 | 7/99 | 99% | 10/99 | 11/99 | 3/00 | 5/00 | 7/00 | 11/00 | RMH Group, Inc | Berville, Inc. |
| M90071 | West Lot Restoration, Ph 1 of 1 | \$236,863 | \$0 | 7/99 | 10% | 10/99 | 3/00 | 4/00 | 8/00 | 11/00 | 2/01 | MaxFour | TBD |
| M90072 | Groundwater Problem - West Building, Ph 1 of 2 | \$21,820 | \$0 | 7/99 | 100% | 10/99 | 5/00 | N/A | N/A | N/A | N/A | MaxFour | N/A |
| M00073 | Fire Alarm Construction Technology Upgrade, Ph 1 of 1 | \$145,822 | \$0 | 7/00 | 0% | 10/00 | 2/01 | 3/01 | 7/01 | 8/01 | 11/01 | TBD | TBD |
| M00074 | West Wing Air Handling Unit Upgrade, Ph 1 of 1 | \$40,286 | \$0 | 7/00 | 0% | 10/00 | 1/01 | 3/01 | 6/01 | 8/01 | 11/01 | TBD | TBD |
| M00075 | Handicap Access to Classrooms, Ph 1 of 1 | \$58,636 | \$0 | 7/00 | 0% | 10/00 | 12/00 | 1/01 | 4/01 | 7/01 | 12/01 | TBD | TBD |
| M00076 | Electrical Power Supply Increase, Ph 1 of 1 | \$52,293 | \$0 | 7/00 | 0% | 9/00 | 10/00 | 11/00 | 12/00 | 1/01 | 4/01 | TBD | TBD |
| M00077 | Keyless Entry - Campus Buildings, Ph 1 of 1 | \$51,092 | \$0 | 7/00 | 0% | 10/00 | 2/01 | 3/01 | 4/01 | 7/01 | 11/01 | TBD | TBD |
| DOHE-RI | RCC Total for the last 3 fiscal years: | \$984,200 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | , FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|---|---------------|----------------|--------------------|--------------------|------------------|--------|---------------------|------------------|-------------------|--------------------|---------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds Available | Percent Encumb. | Contract Date | | Constr. Bid Date | Contract Date | Occupancy Date | Settlement Date | Name of A/E | Name of Prime Contractor |
| Trinidad | d State Junior College | | | | | | | | | | | | |
| M80096 | Repair Parking Lots/Curbs/Waks, Ph 1 of 1 | \$95,560 | \$0 | 7/98 | 90% | 8/98 | 8/98 | 9/98 | 10/98 | 12/98 | 1/99 | North Star Engineering | Kirkland Construction |
| M80097 | Repair Retaining Walls & Tennis Court, Ph 1 of 1 | \$365,200 | \$0 | 7/98 | 100% | 8/98 | 9/98 | 10/98 | 11/98 | Complete | 10/00 | North Star Engineering | TLM Construction |
| M80098 | Replace Underground Storage Tank, Ph 1 of 1 | \$22,850 | \$0 | 7/98 | 85% | 8/98 | 9/98 | 10/98 | 10/98 | 12/98 | 2/98 | AG Engineering | Fabbraro Construction |
| M80099 | Cross Connection Control/Backflow Prevention, Ph 1 of 2 | \$111,315 | \$0 | 7/98 | 90% | 8/98 | 10/98 | 11/98 | 1/99 | 4/99 | 5/99 | AG Engineering | Industrial Plumbing |
| M80099 | Cross Connection Control/Backflow Prevention, Ph 2 of 2 | \$39,195 | \$0 | 7/99 | 100% | 8/98 | 10/98 | 11/98 | 7/99 | 10/99 | 12/99 | AG Engineering | Insustrial Plumbing |
| M90073 | Replace Roof, Boyd Building, Ph 1 of 1 | \$159,200 | \$0 | 7/99 | 10% | 7/99 | 9/99 | 10/99 | 8/00 | 10/00 | 12/00 | Architecture Matters | Athey Beaman |
| M90074 | Building Settlement Repair and Analysis - Library/Massari, Ph 1 of 1 | \$26,900 | \$0 | 7/99 | 95% | 7/99 | 9/99 | 10/99 | 12/99 | 7/00 | 10/00 | North Star Engeering | D & W Concrete |
| M90075 | Replace Cooling Tower, L brary, Ph 1 of 1 | \$61,050 | \$0 | 7/99 | 95% | 7/99 | 9/99 | 10/99 | 12/99 | 10/00 | 12/00 | Farris Engineering | Industrial Mechanical |
| M90076 | Replace Stage Curtains - Massari, Ph 1 of 1 | \$27,650 | \$0 | 7/99 | 0% | N/A | N/A | 8/99 | 9/99 | 11/99 | 1/00 | TSJC | Paramount Fabrics |
| M90077 | Replace Roof & HVAC Unit - Massari, Ph 1 of 1 | \$69,515 | \$0 | 7/99 | 8% | 7/99 | 9/99 | 9/00 | 10/00 | 12/00 | 2/01 | Architecture Matters | TBD |
| M00078 | Install Fire Sprinkler System 3rd Floor L brary, Ph 1 of 1 | \$153,200 | \$0 | 7/00 | 0% | 8/00 | 10/00 | 1/01 | 3/01 | 7/01 | 9/01 | TBD | TBD |
| M00079 | Clean and Sanitize HVAC Duct Systems in Davis and L brary, Ph 1 of 1 | \$64,310 | \$0 | 7/00 | 0% | 10/00 | 11/00 | 12/00 | 02/01 | 07/01 | 8/01 | TBD | TBD |
| M00080 | Campus Electric Power Upgrades, Ph 1 of 2 | \$259,500 | \$0 | 7/00 | 0% | 8/00 | 10/00 | 1/01 | 3/01 | 8/01 | 10/01 | Farris Engineering | TBD |
| DOHE-TS | SJC Total for the last 3 fiscal years: | \$1,455,445 | | | | | | | | | | | |
| Higher I | Education and Advanced Technolog | y Center at | Lowry | | | | | | | | | | |
| M80107 | Repair/Replace Roofing, Ph 1 of 2 | \$721,950 | \$0 | 7/98 | 79% | 10/98 | 10/98 | 11/98 | 8/00 | 1/01 | 3/01 | Tremco | Black Roofing |
| M80107 | Repair/Replace Roofing, Ph 2 of 2 | \$384,111 | \$0 | 7/99 | 65% | 10/99 | 10/99 | 11/99 | 5/00 | 12/00 | 2/01 | Tremco | Black Roofing |
| M80108 | Cross Connection Control/Backflow Prevention, Ph 1 of 1 | \$49,500 | \$0 | 7/98 | 11% | 10/98 | 10/98 | 10/98 | 12/00 | 1/01 | 4/01 | Wilmar | HEAT |
| M90082 | Chlorofluorocarbon Refrigeration Phase out, Ph 1 of 1 | \$272,061 | \$0 | 7/99 | 10% | 10/99 | 10/99 | 11/99 | 1/01 | 4/01 | 6/01 | Concord West | HEAT |
| DOHE-HE | EAT Total for the last 3 fiscal years: | \$1,427,622 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 | 9, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|---|---------------|----------------|-------|--------------------|----------|--------|---------------------|------------------|-------------------|---------|-------------------------------|-----------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | | Constr. Bid Date | Contract Date | Occupancy Date | , | Name of A/E | Name of Prime Contractor |
| Departr | nent of Human Services | | | | | | | | | | | | |
| M288 | Replace Alarms, Electrical, CMHIP, Ph 7 of 7 | \$399,100 | \$0 | 7/98 | 100% | 5/93 | 3/99 | 4/99 | 5/99 | 11/99 | 12/99 | Farris Engineering | T&T Electrical |
| M546 | Repair/Replace Det. Roofs, WWRC Campus, Ph 2 of 2 | \$497,200 | \$0 | 7/98 | 70% | 6/98 | 3/00 | 5/00 | 7/00 | 10/00 | 11/00 | WJE | Westland-HVAC & Roof Zier Pool |
| M661 | Reroof Support Buildings, Homelake, Ph 2 of 2 | \$55,000 | \$0 | 7/98 | 100% | 7/98 | 7/98 | 7/98 | 7/98 | 8/98 | 8/98 | Pahl, Pahl, Pahl | High Country Building |
| M762 | Replace Mechanical Equipment, CMHIP, Ph 3 of 3 | \$462,700 | \$0 | 7/98 | 97% | 11/98 | 6/99 | 6/99 | 7/99 | 2/00 | 9/00 | ME&E | CDE |
| M765 | Repair/Replace Site Utilities/Infrasture, GJRC, Ph 3 of 3 | \$298,400 | \$0 | 7/98 | 60% | 9/98 | 4/99 | 5/00 | 11/99 | 11/00 | 12/00 | Farris Engineering | Enterprise Construction |
| M765 | Repair/Replace Site Utilities/Infrasture, GJRC, Ph 2 of 3 | \$545,421 | \$0 | 7/99 | 60% | 4/99 | 9/99 | 5/00 | 6/00 | 11/00 | 12/00 | Farris Engineering | Enterprise Construction |
| M80109 | Cross Connection Control/Backflow Prevention, Ph 1 of 3 | \$400,000 | \$0 | 7/98 | 90% | 9/98 | 11/99 | 12/99 | 1/00 | 11/00 | 12/00 | MKK | Westland Construction |
| M80109 | Cross Connection Control/Backflow Prevention, Ph 2 of 3 | \$1,003,825 | \$0 | 7/99 | 60% | 3/99 | 4/00 | 5/00 | 6/00 | 4/00 | 5/00 | MKK | Westland Construction |
| M80109 | Cross Connection Control/Backflow Prevention, Ph 3 of 3 | \$733,940 | \$0 | 7/00 | 14% | 8/00 | 11/00 | 12/00 | 2/01 | 8/01 | 10/01 | MKK | TBD |
| M80110 | Repair/Replace Exterior Envelope, DYC, Ph 1 of 1 | \$445,500 | \$0 | 7/98 | 60% | 4/99 | N/A | 4/00 | 6/00 | 12/00 | 2/01 | Greenberg DLR | K/S Construction |
| M80111 | Repair/Replace Personnel Elevators, CMHIP, Ph 1 of 1 | \$424,500 | \$0 | 7/98 | 90% | 7/98 | 12/99 | 1/99 | 3/00 | 8/00 | 9/00 | Lerch Bates & Associates | Millar Elevator Co. |
| M80112 | Repair/Replace Flooring, Cabinets, Counters, PRC, Ph 1 of 2 | \$120,400 | \$0 | 7/98 | 100% | N/A | N/A | N/A | N/A | 5/99 | 6/99 | DHS | Purchase Orders |
| M80113 | Chlorofluorocarbon Refrigeration Phase out, Ph 1 of 3 | \$229,500 | \$0 | 7/98 | 95% | 8/98 | 3/99 | 4/99 | 6/99 | 12/99 | 6/00 | IPE | US Engineering |
| M80113 | Chlorofluorocarbon Refrigeration Phase out, Ph 2 of 2 | \$170,247 | \$0 | 7/00 | 12% | N/A | N/A | N/A | N/A | N/A | N/A | TBD | TBD |
| M90083 | Repair/Replace Secondary Electrical Systems, Ph 1 of 5 | \$407,850 | \$0 | 7/99 | 90% | 10/99 | 5/00 | N/A | N/A | N/A | 6/00 | Stanley Consultants | N/A |
| M90083 | Repair/Replace Secondary Electrical Systems, Ph 2 of 5 | \$269,550 | \$0 | 7/00 | 14% | N/A | N/A | N/A | N/A | N/A | N/A | JCN Engineering | TBD |
| M90084 | Repair/Replace HVAC Systems, CMHIFL, Ph 1 of 4 | \$348,740 | \$0 | 7/99 | 14% | 6/00 | 8/00 | 9/00 | 10/00 | 2/01 | 3/01 | Shaffer Baucom Engineering | TBD |
| M90084 | Repair/Replace HVAC Systems, CMHIFL, Ph 2 of 4 | \$567,338 | \$0 | 7/00 | 14% | 7/00 | 8/00 | 9/00 | 10/00 | 2/01 | 3/01 | Shaffer Baucom Engineering | TBD |
| M90085 | Repair/Replace Infrastructure Utilities, Ph 1 of 5 | \$430,000 | \$0 | 7/99 | 100% | 10/99 | 8/00 | N/A | N/A | N/A | 8/00 | BCER | TBD |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

| FY98/99 |), FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|-------|--------------------|----------|--------|---------------------|------------------|-------------------|---------|---------------------------------|------------------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | | Constr. Bid Date | Contract Date | Occupancy Date | , | Name of A/E | Name of Prime Contractor |
| M90086 | Repair/Replace Primary Electrical Systems, Ph 1 of 5 | \$296,075 | \$0 | 7/99 | 95% | 10/99 | 6/00 | N/A | N/A | N/A | 8/00 | Gordon Gummeson & Stanley | TBD |
| M90087 | Repair/Replace Roadways, Ph 1 of 5 | \$159,000 | \$0 | 7/99 | 98% | 6/99 | 1/00 | N/A | N/A | N/A | 6/00 | BWR | TBD |
| M90087 | Repair/Replace Roadways, Ph 2 of 2 | \$722,921 | \$0 | 7/00 | 12% | N/A | N/A | N/A | N/A | N/A | N/A | BWR | TBD |
| M90088 | Repair/Replace Roofing Systems, Ph 1 of 3 | \$493,273 | \$0 | 7/99 | 90% | 6/99 | 9/99 | 10/99 | 11/99 | 6/00 | 7/00 | WJE | CRS Roofing |
| M90089 | Repair/Replace Miscellaneous Building Deficiencies, Ph 1 of 5 | \$361,096 | \$0 | 7/98 | 100% | N/A | N/A | N/A | N/A | 5/00 | 6/00 | DHS | Purchase Orders |
| M90089 | Repair/Replace Miscellaneous Building Deficiencies, Ph 2 of 5 | \$239,487 | \$0 | 7/00 | 2% | N/A | N/A | N/A | N/A | N/A | N/A | DHS | Purchase Orders |
| M00090 | Fire Alarm Systems Upgrades, Ph 1 of 5 | \$346,225 | \$0 | 7/00 | 14% | 8/00 | 3/01 | 5/01 | 6/01 | 11/01 | 12/01 | JCN Engineering | TBD |
| M00091 | Repair/Replace Medical Gas System, CMHIP, Ph 1 of 1 | \$264,700 | \$0 | 7/00 | 14% | 8/00 | 3/01 | 5/01 | 6/01 | 11/01 | 12/01 | ME&E | TBD |
| M00092 | Boiler Replacement, Homelake, Ph 1 of 1 | \$401,300 | \$0 | 7/00 | 14% | 8/00 | 4/01 | 5/01 | 6/01 | 10/01 | 11/01 | ME&E | TBD |
| M00093 | Repair/Replace Roofing, Ph 1 of 3 | \$310,650 | \$0 | 7/00 | 10% | 8/00 | 12/00 | 1/01 | 3/01 | 7/01 | 8/01 | WJE | TBD |
| DHS | Total for the last 3 fiscal years: | \$11,403,938 | | | | | | | | | | | |
| Judicia | l Department | | | | | | | | | | | | |
| M80114 | Elevator Life Jacket, Ph 1 of 1 | \$30,000 | \$0 | 7/98 | 100% | 9/98 | 10/98 | 10/98 | 11/98 | 5/00 | 5/00 | N/A | Millar Elevator Co. |
| M80115 | Carpet Replacement, Ph 1 of 2 | \$210,070 | \$0 | 7/98 | 100% | 9/98 | 10/98 | 10/98 | 10/98 | 1/01 | 1/01 | N/A | Western Contract Carpet Service |
| M80115 | Carpet Replacement, Ph 2 of 2 | \$164,900 | \$0 | 7/00 | 0% | 8/00 | 8/00 | 9/00 | 11/00 | 2/01 | 2/01 | N/A | TBD |
| M80116 | Water Booster Pump, Ph 1 of 1 | \$35,000 | \$0 | 7/98 | 100% | 9/98 | 9/98 | 10/98 | 11/98 | 8/00 | 8/00 | МКК | Security Plumbing Co. |
| M90090 | Fire Alarm System Upgrade, Ph 1 of 1 | \$193,710 | \$0 | 7/99 | 100% | 8/99 | 4/00 | 8/00 | 8/00 | 6/01 | 6/01 | MKK | TBD |
| M90090 | Fire Alarm System Upgrade, Ph 2 of 2 | \$208,900 | \$0 | 7/00 | 0% | 8/00 | 12/00 | 2/01 | 3/01 | 9/01 | 9/01 | TBD | TBD |
| M90091 | Elevator Repair/Retrofit, Ph 1 of 1 | \$328,500 | \$0 | 7/99 | 100% | 11/99 | 4/00 | 8/00 | 9/00 | 6/01 | 6/01 | Lerch Bates & Associates | TBD |
| M90092 | Cross Connection Control/Backflow Prevention, Ph 1 of 1 | \$35,208 | \$0 | 7/99 | 100% | 11/99 | 2/00 | 8/00 | 9/00 | 1/01 | 1/01 | MKK | TBD |
| M00094 | Mechanical Room Ventilation Upgrade, Ph 1 of 1 | \$78,000 | \$0 | 7/00 | 0% | 8/00 | 12/00 | 2/01 | 3/01 | 6/01 | 6/01 | TBD | TBD |
| M00095 | Waterproof Sloped Roof and Plaza Deck, Ph 1 of 3 | \$419,400 | \$0 | 7/00 | 0% | 8/00 | 12/00 | 2/01 | 3/01 | 9/01 | 9/01 | TBD | TBD |
| JUD | Total for the last 3 fiscal years: | \$1,703,688 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 |), FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|-------|--------------------|----------|--------|---------------------|----------|-------------------|----------|---------------------------------------|-----------------------------|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | 0 | Constr. Bid Date | Contract | Occupancy Date | , | Name of A/E | Name of Prime Contractor |
| Departr | nent of Military Affairs | | | | | | | | | | | | |
| M549 | General Maintenance Backlog, Ph 8 of 10 | \$53,750 | \$0 | 7/98 | 23% | Varies | Varies | Varies | 9/95 | 4/99 | 6/99 | Varies | DMA - multiple |
| M549 | General Maintenance Backlog, Ph 3 of 3 | \$175,951 | \$0 | 7/99 | 0% | 1/00 | 3/00 | 3/00 | 4/00 | 6/00 | 6/00 | TBD | TBD |
| M769 | Repair Armory Roof Projects, Statewide, Ph 2 of 5 | \$149,054 | \$136,096 | 7/98 | 90% | 10/98 | Varies | Varies | Varies | Varies | 5/01 | Varies | Varies |
| M769 | Repair Armory Roof Projects, Statewide, Ph 3 of 3 | \$154,897 | \$0 | 7/99 | 0% | 11/99 | 2/00 | 3/00 | 3/00 | 5/00 | 5/00 | Gimple | TBD |
| M80117 | Repair/Repave Parking Lots, Ph 1 of 1 | \$96,400 | \$0 | 7/98 | 100% | 6/99 | 7/99 | 8/99 | 8/00 | 12/00 | Complete | Bucher, Willis & Ratliff | Brener Construction |
| M80118 | Armory Rehab. Eval/Fac. Audits, Ph 1 of 1 | \$90,000 | \$0 | 7/98 | 90% | 8/98 | 12/99 | N/A | N/A | N/A | 4/01 | ССМК | TDB |
| M80119 | Cross Connection Control/Backflow Prevention, Ph 1 of 1 | \$145,560 | \$0 | 7/98 | 82% | N/A | 11/98 | 12/99 | 1/00 | 1/00 | 1/00 | DMA | Various |
| M90093 | HATS Sewer System Replacement, Ph 1 of 1 | \$239,500 | \$0 | 7/99 | 0% | 12/99 | 2/00 | 9/00 | 9/00 | 12/00 | 2/01 | Martin & Martin | TBD |
| M90094 | Fort Collins Armory Paving Replacement, Ph 1 of 1 | \$154,272 | \$0 | 7/99 | 100% | 11/99 | 7/00 | 7/00 | 6/00 | 9/00 | 10/00 | Bucher, Willis & Ratliff | GL Hoff |
| M00096 | Septic System Replacement, Fort Collins Armory, Ph 1 of 1 | \$76,613 | \$0 | 7/00 | 10% | 10/00 | 12/00 | 01/01 | 02/01 | 04/01 | 6/01 | Associated Consulting Engineers | N/A |
| M00097 | Emergency Lighting/Electrical Violations, Ph 1 of 3 | \$234,450 | \$50,050 | 7/00 | 10% | 10/00 | 3/01 | 4/01 | 4/01 | 6/01 | 7/01 | Cybercon Corporation | N/A |
| M00098 | Armory Roof Projects, Ph 1 of 1 | \$205,180 | \$57,400 | 7/00 | 50% | 11/00 | 2/01 | 2/01 | 3/01 | 5/01 | 10/01 | Rooftech Consultants, Inc. | N/A |
| M00099 | Exterior Closure Replacement, Ph 1 of 4 | \$267,688 | \$0 | 7/00 | 10% | 9/00 | 12/00 | 1/01 | 2/01 | 5/01 | 7/00 | Scheuber Darden | N/A |
| DMA | Total for the last 3 fiscal years: | \$2,043,315 | | | | | | | | | | | |

FY 2001/2002 CONTROLLED MAINTENANCE PROGRAM

FY98/99, FY99/00, FY00/01 PROJECTS

| FY98/99 | 9, FY99/00, FY00/01 PROJECTS | | | Date | | Design | Design | | Constr. | Expected | Project | | |
|--------------|--|---------------|----------------|-------|--------------------|----------|--------------------|---------------------|------------------|-------------------|---------|------------------------|--|
| Project # | Project Description | CCFE Appr. | Other Funds | Funds | Percent Encumb. | Contract | Completion Date | Constr. Bid Date | Contract Date | Occupancy Date | , | Name of A/E | Name of Prime Contractor |
| Departr | nent of Public Safety | | | | | | | | | | | | |
| M80126 | CSP General Facilities Repair, Ph 1 of 1 | \$127,542 | \$0 | 7/98 | 85% | 10/98 | 4/99 | 5/99 | 6/99 | N/A | 6/01 | Roof Tech & Diamond | Arapahoe Roofing Delta Construction Rob's Repair |
| M90105 | CSP General Facilities Repair, Ph 1 of 1 | \$307,224 | \$0 | 7/99 | 25% | 9/99 | 5/00 | 7/00 | 7/00 | N/A | 6/02 | Aguirre | Pasterkamp |
| M00105 | Colorado State Patrol Academy/Camp George West Repairs, Ph 1 of 3 | \$257,854 | \$0 | 7/00 | 0% | 9/00 | 1/01 | 4/01 | 5/01 | N/A | 6/03 | TBD | TBD |
| M00106 | Cross Connection Control/Backflow Prevention, Ph 1 of 1 | \$22,000 | \$0 | 7/00 | 0% | 8/00 | 9/00 | 9/00 | 10/00 | N/A | 6/03 | Sear Brown | TBD |
| M00107 | Chlorofluorcarbon Refrigeration Phase Out, Ph 1 of 1 | \$27,810 | \$0 | 7/00 | 0% | 8/00 | 9/00 | 9/00 | 10/00 | N/A | 6/03 | TBD | TBD |
| CDPS | Total for the last 3 fiscal years: | \$742,430 | | | | | | | | | | | |
| Cumbre | es & Toltec Scenic Railroad Commiss | sion | | | | | | | | | | | |
| M00085 | Chame Shop Electrical Upgrade/Rewire, Ph 1 of 1 | \$120,000 | \$120,000 | 7/00 | 0% | 9/00 | 11/00 | 12/00 | 1/01 | 3/01 | 4/01 | TBD | TBD |
| CTSRC | Total for the last 3 fiscal years: | \$120,000 | | | | | | | | | | | |

X. SBP EMERGENCY FUND STATUS REPORT

EMERGENCY PROJECTS November 7, 2000

| | | | DATE | DATE | |
|---|--------------------------------|----------------------------|----------|----------|---|
| PROJECT NUMBER AND TITLE | AMOUNT | AGENCY | OPENED | CLOSED | DESCRIPTION |
| FY 1999/2000 EMERGENCY FUND APPRN | 1,250,000 | | | | |
| Balance carried forward from | | | | | |
| from prior fiscal year | 629,517 | | | | |
| EM-410 WATER INTRUSION REPAIR/ TUCK POINTING - DESIGN FEES | (8,250) CO | Judicial Department | 06/28/99 | | Water intrusion at paver system base of building sloped roof. Design fees are authorized to determine extent of damage. |
| Project complete/funds returned | 2,600 | | | 11/29/00 | |
| EM-411 CLEAN HVAC SYSTEM Project complete/funds returned | (10,840) Trii 984 | nidad State Jr. College | 06/28/99 | 03/23/99 | A Petri dish study found mold/fungi contamination in the Davis Science Building. A contractor will be hired to clean the HVAC system and coat the system to prevent spread of mold/fungi. |
| EM-412 ROOF REPL BLDGS 70 AND 71 CAMP GEORGE WEST Project complete/funds returned | (25,131) De 3,776 | pt of Public Safety | 08/02/99 | 12/06/99 | Replace shingle roofs and metal flashing on badly deteriorated roofs. Roofs leaked during a major rain and hail storm. Water damage could create unsafe working conditions for staff in these buildings. |
| EM-413 REPAIRS TO FREIGHT ELEVATOR OIL VALVE Project complete/funds returned | (6,593) CC 1,054 | Judicial Department | 08/06/99 | 03/20/00 | Oil valve in freight elevator in basement of Heritage Building is deteriorating and requires replacement. Failure of the valve could cause the elevator to drop which would result in potential injury to any passengers. |
| CM-926 REMOVAL OF CONTAMINATED SOILS | | ot of Corrections | 08/06/99 | 06/30/00 | Four additional quarters of monitoring soils to assess contamina ion of groundwater are required by the Oil Inspec ion Section of the Department of Labor and Employment. |
| Project closed/funds reverted | 5,659 | | | | |
| EM-414 CONDENSER PUMP CONTROL REPLACEMENT Project complete/funds returned | (, , | es Peak Community llege | 08/06/99 | 02/04/00 | Condenser unit that operates the cooling systems in the Breckenridge Building on campus requires replacement. Breakers are tripping intermittently. Complete failure of the condenser will cease operation of the cooling system in the building. |
| EM-415 DESIGN FEES TO ASSESS SAFETY OF BLEACHERS | (10,000) CC | School of Mines | 08/10/99 | | Bleachers at the School of Mines campus are potentially hazardous to the public and the School requests engineering fees to assess the safety of the bleachers. |
| EM-416 HOT WATER HEATER REPLACEMENT | (43,500) Fo | t Lewis College | 08/30/99 | | Replace three gas fired domestic water heaters. Two have failed that were installed in tandem. Water heaters are located in the gymnasium and provide hot water for showers. |
| EM-417 DESIGN FEES FOR A VACUUM PUMP SYSTEM Increase appropria ion | (5,000) CC Blin (61,600) | School for Deaf and | 08/30/99 | 12/29/99 | A vacuum pump and a condensate pump have failed. Fees are being provided to determine the least costly solution to replace the pumps. |
| EM-418 REPLACE SEWER LINE Project complete/funds returned | (60,010) Un 2,348 | iv of CO at Boulder | 08/30/99 | 03/30/99 | Repair sewer line break to the north of Clare Small Building that caused sanitary sewage to leak on the surrounding ground and into Boulder Creek. |

| | | DATE [| DATE |
|---|---|----------------|--|
| PROJECT NUMBER AND TITLE | AMOUNT AGENCY | OPENED CL | LOSED DESCRIPTION |
| EM-419 REPLACE DEFECTIVE OMEGA SPRINKLER HEADS | (5,127) Univ of CO at Boulder | 09/02/99 03 | 3/30/00 Replace defective Omega sprinkler heads recalled by the U.S. Consumer Product Safety Commission. |
| Project complete/funds returned | 487 | | |
| EM-420 REPLACE DEFECTIVE OMEGA SPRINKLER HEADS | (120,652) Dept. of Corrections | 09/02/99 | Replace defective Omega sprinkler heads recalled by the U.S. Consumer Product Safety Commission. |
| Increase appropria ion | (104,960) | | |
| EM-421 REPLACE DEFECTIVE OMEGA SPRINKLER HEADS | (204,545) Dept of Human Service | s 09/02/99 | Replace defective Omega sprinkler heads recalled by the U.S. Consumer Product Safety Commission. |
| EM-422 ENGINEERING STUDY OF HVAC SYS ⁻ Increase appropria ion | (22,000) Real Estate Services (16,749) | 09/02/99 | Conduct an engineering study to assess the HVAC system at the Grand Junction State Services Building. |
| Increase appropria ion | (208,203) | 02/10/00 | |
| EM-423 REPL BOULDER ARMORY BOILER | (30,111) Dept of Military Affairs | 09/02/99 09 | 9/03/00 Replace inoperative boiler at the Boulder Armory. |
| Project complete/funds returned | 239 | | |
| EM-424 STEAM LINE REPAIR Project complete/funds returned | (36,272) Dept of Human Service 23,142 | s 09/07/99 12 | 2/22/99 Repair a leak in the buried steam line hat provides heat to the Lookout Mountain Youth Services Center. |
| EM-425 REPL EMERGENCY GENERATOR #1 AT DRDC | (101,200) Dept of Corrections | 09/16/99 | Replace emergency generator #1 at Denver Regional Diagnostic Center which is inoperable and cannot be repaired. |
| EM-426 DEPT OF HUMAN SERVICES Transfer from M-539 - \$156,585 | (25,992) Dept of Human Service | s 10/07/99 | Repair a rupture in a boiler tube in the rear lower section of the combustion chamber. The CMHIP is currently operating gas backup boilers. |
| EM-427 REPL TWO FURNACES AT 690 KIPLING | (27,350) Real Estate Services | 10/08/99 | Two duct furnaces at 690 Kipling must be replaced due to holes in the heat exchangers which may emit carbon monoxide during operation. |
| EM-428 CAPITOL RESTROOM REPAIRS Project complete/funds returned | (9,321) Real Estate Services 847 | 11/04/99 08 | Waste lines from the urinals and sinks in the men's restroom require repair. 8/03/00 |
| EM-429 REPL HOT WATER TANK Project complete/funds returned | (24,165) Pikes Peak Community 50 College | | A domestic hot water tank has deteriorated to the point where it must be replaced. The 9/06/00 hot water tank provides water for cooking services which will be shut down if the tank fails. |
| EM-430 DESIGN FEES FOR BOULDER ARMORY ROOF | (8,880) Dept of Military Affairs | 11/26/99 | Design fees have been approved to determine cost to replace the roof that has failed and caused interior damage. |
| Project complete/funds returned | 7,613 | 08 | 8/28/00 |

| | | DATE DATE | |
|---|--|------------------------------------|---|
| PROJECT NUMBER AND TITLE | AMOUNT AGENCY | OPENED CLOSED | DESCRIPTION |
| TROCEOT ROMBERTARD THEE | | OF EITED OLOOLD | |
| EM-431 REPAIR CHILLED WATER LEAK | (8,800) CO Judicial Dept. | is flo | ater leak has developed below grade at the Colorado Judicial Heritage Complex. Water owing into the building foundation walls and must be repaired to ensure cooling ability will be provided to the complex. |
| EM-432 REP/REPL PIPED WATER LINE | (6,330) Real Estate Services | | air and replace leaking pipe lines in the domestic cold water main supply at the North npus West Building. Approximately 150' of copper lines must be replaced immediately. |
| EM-433 GAS LINE REPLACEMENT | (10,767) Red Rocks Community | | gas line that fees the West Building of the college developed a leak that must be aced to avoid a safety hazard. |
| EM-434 WATER MAIN REPL - NORTH Project complete/funds returned | (34,178) Dept of Human Services 2,583 | | ater main failed at the CMHIP campus. The water main provides services to a total of buildings. The buildings do not have fire protection or potable water due to the break. |
| EM-435 ROOF REPAIRS - MUSEUM Project complete/funds returned | (18,653) CO Historical Society 3,847 | | agonal ridge beam failed in the western addition of the Museum Support Center in blo. If the roof fails, substantial property damage will occur. |
| EM-436 EAST WATER MAIN REPAIR | (11,330) Univ. of SO Colorado | | ter main break occurred between the Library and Art/Music Buildings. The campus is nout water and fire suppression sprinklers and hydrants are also without water. |
| EM-437 REPLACE HEAT SYSTEM CIR- CULATION PUMPS-ASPEN BLDG Project complete/funds returned | (7,175) Pikes Peak Community College 439 | 01/25/00 Repl leaki 08/02/00 | lace three heating system circulation pumps that have exceed their useful life and are ing. |
| EM-438 REPAIR GENERATOR AT THE COMPUTER CENTER Project complete/funds returned | (11,359) Real Estate Services 397 | | ower outage caused the backup generator to fail. The computer center, radio dispatch State Patrol emergency response functions were all inoperable as a result of the erator's failure. |
| EM-439 REPAIR SEWAGE PIT AT 3B LEVEL OF CENTENNIAL BLDG | (15,340) Real Estate Services | ejec | sewage ejec ion pit at the 3B level of the Centennial Building is inoperable. One tion pump has failed beyond repair and the tandem pump is ready to fail. |
| Project complete/funds returned | 1,395 | 08/03/00 | |
| EM-440 REPLACE HOT WATER HEAT EXCHANGER AT THE SOB | (9,016) Real Estate Services | 03/06/00 The | hot water heat exchanger at the State Office Building has failed and must be replaced. |
| Project complete/funds returned | 820 | 08/03/00 | |
| EM-441 BYERS-EVANS HOUSE ASBESTOS ABATEMENT | (13,210) CO Historical Society | 03/07/00 Rem | nove asbestos from the basement of the Byers-Evans House. |
| Increase appropria ion | (3,500) | 04/25/00 | |

| | | DATE | DATE |
|--|---|---------------|---|
| PROJECT NUMBER AND TITLE | AMOUNT AGENCY | OPENED | D CLOSED DESCRIPTION |
| EM-443 BRACE THREE MICROWAVE TOWERS | (39,548) CITS/Telecommunications | 6 04/11/00 | Provide braces for three microwave towers that are overstressed and may fall due to the current equipment loading conditions. |
| EM-444 REBUILD YORK CHILLER CONDENSER WATER PUMP Project complete/funds returned | (6,996) Div. of Central Services | 04/26/00 | York chiller condenser water pump in the State Office Building has failed and must be rebuilt. This water pump services three state buildings. 08/03/00 |
| EM-445 REROOF DAVIS BUILDING | (41,770) Trinidad St. Junior College | e 05/02/00 | |
| EM-446 REPL TWO BOILERS AT LOOKOUT MOUNTAIN YSC Project complete/funds returned | (11,519) Dept of Human Services 1,049 | 05/03/00 | Two boilers at the Lookout Mountain YSC must be replaced as they are hazardous due to malfunctioning gas valves. 09/12/00 |
| EM-447 REPL CHILLER PUMP Project complete/funds returned | (10,967) Pikes Peak Community C 2 | oll: 05/03/00 | A refrigerant chiller pump failed at the Centennial campus. Air conditioning will not be 08/21/00 available in the rooms which will become intolerable for the students, faculty and staff. |
| EM-448 SECURITY FENCE ALARM SYSTEM REPLACEMENT | (6,655) Dept. of Corrections | 05/11/00 | The security fence at the San Carlos Correctional Facility was damaged during an attempted escape. The fence will be repaired temporarily and a new fence that will provide more security will be installed in two years. |
| EM-449 REP FORT GARLAND IRRIGATION SY Project complete/funds returned | (8,336) CO Historical Society 157 | 05/12/00 | The sprinkler system located in the parade grounds at Fort Garland is in need of repair due 10/02/00 to deterioration and numerous leaks. |
| EM-450 HEAT EXCHANGER REPLACE- MENT AT SSB Project complete/funds returned | (27,930) Div of Central Services 2,540 | 05/23/00 | The domestic hot water heat exchanger at the SSB failed and must be replaced. Water temperatures cannot be controlled. 09/12/00 |
| EM-451 REPL FIRE MAIN AT NORTH PAVILION BUILDING | (33,614) Univ of Colo Health Science | ces 06/07/00 | The fire main at the North Pavilion Building ruptured. The sprinkler system to the building is not functional which puts the occupants of the building at risk. |
| FY 2000/2001 EMERGENCY FUND APPRN | 1,250,000 | | |
| EM-501 REPL TWO FURNACES AT MOUNT VIEW YSC Project complete/funds returned | Dept of Human Services (11,272) 1,024 | 07/12/00 | Two furnaces at the Mount View Youth Services Center are leaking combustion gasses that are blown into occupied space of the building creating a dangerous situation. 09/22/00 |
| EM-502 ELECTRICAL BREAKER/ BUSS BAR REPAIR Project complete/funds returned | CO Judicial Dept. (8,892) 808 | 07/18/00 | Replace a failed circuit breaker that could cause a fire. |

| | | | DATE | DATE | |
|---|--------------------|--------------------------------------|----------|-------|---|
| PROJECT NUMBER AND TITLE | AMOUNT | AGENCY | OPENED C | LOSED | DESCRIPTION |
| EM-504 REPL ROOF ON MCLAUGHLIN BUILDING | | CO Northwestern Community College | 08/02/00 | | High winds blew off a large portion of the roof. Damage continues to occur and the interior of the building could be ruined if the roof is not replaced. |
| EM-505 REPL CYLINDER IN FREIGHT ELEVATOR AT CO HERITAGE CENTER | (30,864) | CO Judicial Dept. | 08/10/00 | | Freight elevator developed a hydraulic oil leak in the steel pressure cylinder which could cause the elevator to fall and damage property or harm to occupants. |
| EM-506 REPL FIRE ALARM PANELS AT MSG BUILDING Project complete/funds returned | (5,964) 542 | Dept of Human Services | 08/11/00 | | Fire alarm panels have failed in two buildings at Fort Logan. Building occupants are at risk until the fire alarm panels are replaced. |
| EM-507 REP WATER MAIN AT SPRING CREEK YOUTH CENTER | (8,580) | Dept of Human Services | 08/11/00 | | A 3' domestic water main failed at the Spring Creek Youth Center. This water main is the sole source of potable water to he facility and must be repaired. |
| EM-508 SECOND LEVEL SITE ASSESS- MENT | (4,052) | Dept of Corrections | 09/27/00 | | Additional funds required to complete testing of groundwater at Rifle Correctional Center. |
| EM-509 REPL SECURITY GATE AT EXECUTIVE RESIDENCE | (24,950) | Division of Central Services | 09/11/00 | | The security gate operating system at the Executive Residence failed and must be replaced to enable entry into the grounds. Due to the age of the gates, repair is not an option. |
| EM-510 REPL WATER HEAT AT ADAMS YSC | (7,867) | Dept of Human Services | 09/14/00 | | The domestic water heater at the Adams YSC failed and must be replaced. Hot water is required for sanitation. |
| EM-511 REPL TRANSFORMER AT DELTA CORRECTIONAL CENTER | (6,507) | Dept of Corrections | 09/15/00 | | Transformer overheats which will cause a failure. All electrical power to the entire correctional facility will be lost if the transformer fails. |
| EM-512 REPL PNEUMATIC CONTROLS ON AIR COMPRESSORS | (12,093) | Pikes Peak Community College | 09/19/00 | | Insufficient air qualify or capacity are not provided for HVAC systems opera ions. The compressors for pneumatic controls are old and must be replaced. |
| EM-513 REPL BOILER, NORTH BUILDING Transfer from M-80066 | (12,355) 12,355 | Arapahoe Community College | 10/23/00 | | Replace two hot water tanks that provide domestic hot water for the main and annex buildings. These tanks serve the restrooms, shower rooms and food service kitchen. |
| EM-514 REMOVE/REPL DETERIORATING SLAB @ CWCF | (24,000) | Dept of Corrections | 11/13/00 | | The sanitary sewer line under the main corridor floor collapsed and blocked the flow. The line has been cleaned numerous times which has created further collapse. This is the main line from the facility kitchen. If this repair isn't made, food service will not be available and food will have to brought in from another facility. |
| EM-515 FIRE ALARM REPS AT ACC AND CWCF | (61,550) | Dept of Corrections | 11/30/00 | | Fire alarm systems at the Arrowhead Correctional Center and Colorado Women's Correctional Facility are not functioning. Repairs are essential due to life/safety issues. |

| PROJECT NUMBER AND TITLE | AMOUNT | AGENCY | DATE OPENED (| DATE CLOSED | DESCRIPTION |
|---|--------------------|-------------------------------|------------------|----------------|---|
| EM-516 REPL BOILER FIREBRICK/ REFRACTORY | (45,100) Dep | t of Corrections | 11/30/00 | | A boiler at the Buena Vista Correction Facility requires replacement of the firebrick. The boiler may not provide adequate steam heat if the boiler shuts down. |
| EM-517 REP HEATING SYSTEM | , | School for the Deaf the Blind | 11/30/00 | | The heating system in the Adams school has failed in several areas. Irregular heating is occurring in the school which is disruptive to the students and faculty. |
| EM-518 EXT REP TO ENGINEERING HALL | (68,000) CO | School of Mines | 11/30/00 | | Cracking has appeared in the structurally load bearing exterior masonry walls of the Engineering Hall. Portions of the masonry or sandstone may fall off the building. Also, the window frames are shifting and may fail. |
| EM-519 GREEN CENTER ROOF REP | <u>(61,500)</u> CO | School of Mines | 11/30/00 | | Portions of the Green Center roof are saturated with moisture. A study is in process to determine the amount of asbestos abatement that may be required. Emergency funds are requested for temporary repair of the roof. |
| Total Funda Availabla | 1 094 077 | | | | |

Total Funds Available

1,084,977

-

