

April 8, 2008

General Assembly State Capital Denver, CO 80203

In compliance with Colorado Revised Statues, Section 34-60-104 (III) (A), the Colorado Oil and Gas Conservation Commission is submitting its quarterly report to the General Assembly concerning the number of complaints received by the Commission. During this period, the Commission received a total of 53 complaints involving 65 issues.

The report is sorted by the type of complaint and provides information on the complainant's identity and the commission's response.



ACCESS

COGCC Complaint Report January 01, 2008 - March 31, 2008

Type: ACCESS	Date: 02/06/2008
Complainant: Dan Wit	ham WCR 63
Description of Complaint:	Dan Witham complained that WCR 63 was not adequately maintained for heavy truck traffic. The WCR 63 is unimproved from WCR 78 to 76.
COGCC Response:	COGCC discussed maintenance and commented that Petro-Canada was doing their part to build up WCR 63. COGCC staff recommended to landowner that they should contact county road department about future road
	grading. Conducted field visit and discovered that Petro-Canada has improved county road to their facilities.

Landowner lives beyond Petro-Canada well site.



BASELINE WATER REQUEST

Туре:	BASE	LINE WAT	ER REQUEST		D	ate:	02/07/200)8
Complai	inant:	Steuart	Readio	12695 Oxford Road	Longmont		CO	
Descript	tion of (Complaint:		II at his property that he uses for irreq nave his water well sampled.	gation. Due to v	vell dril	ling in his	
COGCC	Respon	se:	water well. EnCana will resample	d on February 6, 2008. Analytical resu e complainant's water well this summe nt to complainant on February 26, 200	er after drilling a	U	•	16
Type: Complai	Type: BASELINE WATER REQUEST Date: 02/13/2008 Complainant: Kazuko Nosaka)8	
Descript	tion of (Complaint:	Request for water quality analyse	s due to drilling nearby.				
COGCC	Respon	se:		d collected samples from water well fo nd BART kit test. Results pending.	or general inorga	inic wat	ter quality	
Туре:	BASE	LINE WAT	ER REQUEST		D	ate:	02/21/200)8
Complai	inant:	Virginia	Yeatts	19009 Wild Turkey RD	Weston		CO	810918721
Descript	tion of (Complaint:		ssible impacts to their water well from	n nearby CBM dr	illing ar	nd productio	วท
			operations.					



COGCC Response:	Visited site and collected water samples from well for general inorganic water quality parameters and								
	dissolved methane analysis as we	II as BART kit tests. Results of lab stu	udy pending.						
Type: BASELINE WAT	ER REQUEST			Date:	01/25/20	08			
Complainant: Val Van	Artsdalen	8350 Widow Woman Canyon	Trinidad		CO	810828506			
Description of Complaint:		water and venting from water well							
COGCC Response:	Sampled tap in kitchen to determine what concentration of methane present in water after transport to two large outdoor vented cisterns. Also took samples for BART test kits. Discussed methods of venting well and								
	cistern and possible need for activ	cistern and possible need for active removal of methane from water before bringing into house. Results of							
				Deter	02/12/20	00			
Type: BASELINE WAT Complainant: Lee Gisc		19558 Aspen Rose Drive	Weston	Date:	03/12/20 CO	81091			
Complainant: Lee Gisc Description of Complaint: COGCC Response:	Mr. Gisclon is concerned about po property.	ssible impacts to water quality as more solution well head for analysis of general inor	re CBM wells a		d near his				



DUST

Type: DUST	10447	MCD 74	Date	
Complainant: Mary An	derson 12447	WCR 76	Eaton	CO 80615
Description of Complaint:	Mary Anderson complained to EPA about o	lust on WCR 76 between WCF	R 23 and 27. EPA	-Cindy Beeler
	forwarded complaint via email. This well i	s used for API tracking contro	ol.	
COGCC Response:	Petro-Canada Resources conditioned WCR	76 with MgCL dust suppress	ant in early 2007 a	and attempted to do
	it again in November 2007 but their contra	actor was out of business. Th	ney are attempting	g to contract with
	Envrio Tech to do future dust control in co	operation with county along t	their operations ro	outes.
Type: DUST			Date	e: 03/18/2008
Complainant: Verna W	ilson 7777 (CR 309	Rulison	CO
Description of Complaint:	Dust coming from traffic on CR 309 in Gar	field County		
COGCC Response:	COGCC staff contracted Garfield County R	oad and Bridge Department.	GarCo stated too	much water on CR
	309 could degrade integrity of the road ba	se. Garco is planning on pav	ving the section of	CR 309 between
	CR301 and CR 320 as soon as the weathe	r will allow. COGCC staff will	check on dust cor	nditions until road is
	paved.			
Type: DUST			Date	e: 03/24/2008
Complainant: Verna W	ilson 7777 (CR 309	Rulison	CO



Description of Complaint:

Verna Wilson called to express concerns about dust on the county road. I called staff Gary Helgeland and asked him to inspect the site and report conditions

COGCC Response:

COGCC staff inspected the road and found it damp. County has required the operator to keep the road wet four times a day. Staff spoke with complainant and the road was wet at that time. The complainant were still of the opinion that there was too much dust.



FENCING

Type: FENCING					03/24/200	8			
Complainant:	Randle Bridge	P.O.Box 1435	Lamar		CO	81052			
Description of C	Description of Complaint:								

Fences are in disrepair allowing livestock access.

COGCC Response:

Contacting opeartor to discuss issue.



GROUND WATER

COGCC Complaint Report January 01, 2008 - March 31, 2008

GROUND WATER 03/04/2008 Type: Date: 1591 S Zang St CO Complainant: Frank Zele Lakewood 80228 **Description of Complaint:** Mr. Zele is concerned about possible impacts to groundwater (spring) in section 29, 31S, 65W 6PM from drilling and production at proposed Del Agua Canyon (24-29?) well. APD not filed yet but as surface owner, Mr Zele, was notified by Pioneer of their intentions to drill this well (orginally called Porzikova 24-29). Mr. Zele would like flow from spring to be determined before drilling activities and also requested that quality of water from spring along Canyon del Agua in this section be determined. **COGCC** Response: COGCC staff worked with operator and complainant to resolve issues. Conditions of Approval requiring monitoring of flow and quality of ground water from spring will be added to APD before approval. Type: GROUND WATER Date: 03/12/2008 Complainant: 99 Hawk Ridge Trail CO Bruce Hopke Walsenburg 810899633 **Description of Complaint:** Mr. Hopke is concerned about potential contamination of groundwater with volatile organic compounds. **COGCC** Response: COGCC staff installed frostproof hydrant near complainant's water well so samples could be collected from well and not out of cistern. Sampled water at the residence for VOC's and dissolved methane. Samples submitted to analytical laboratory in late March. Results are pending. Type: GROUND WATER 01/12/2008 Date:

Complainant: Ben and Melanie Bounds



Description of Complaint:

Toluene believed to be present in the groundwater.

COGCC Response:	onse: COGCC Staff and representative from Whetstone Associates sampled water at two different times with					
	results showings low (<1µg/l) con	centration of toleune. COGCC staff	consulting with	complai	nant about	
	possible sources of toluene.					
Type: GROUND WATE	ĒR		I	Date:	01/09/200	8
Complainant: Dorothy	Phelps	21421 Hwy 60	Platteville		CO	80651
Description of Complaint:		ed water vault with above-ground ta	ank. Complaina	nt claim	s soils and	
	shallow ground water potentially in	mpacted. Photographs indicate stair	ned soils and pos	ssible sł	neen on gro	und
	water in excavation. Operator has	s reportedly backfilled excavation.				
COGCC Response:	CGRS on behalf of COGCC conduct	ted a limited site investigation. Lab r	results of repres	entative	e ground wa	ter
	samples indicated benzene concer	ntrations that significantly exceed the	e Colorado Basic	: Standa	rds for Grou	und
	Water. A Notice of Alleged Violatio	n (NOAV #1175657) was issued. Co	prrective action i	ncluded	the submit	tal
	of a Form 27 - Site Investigation a	and Remediation Workplan. Form 27	was submitted	and con	ditionally	
	approved by the COGCC on 03/11	/08.				
Type: GROUND WATE	ER		I	Date:	02/05/200	8
Complainant: Tracy Da	ahl	14218 Switchback Road	Weston		СО	81091

Description of Complaint:

Concerned with possible impacts to groundwater from drilling and frac operations at CBM wells near home.



COGCC Response:						
	Sampled well for general inorganic	water quality parameters. Sample	es shipped to la	ab. Await	ting results	from
	lab.					
Type: GROUND WATE	R			Date:	02/05/20	08
Complainant: Marcia D	Dasko	15301 Logging Canyon Rd.	Weston		CO	810919558
Description of Complaint:		to groundwater and quality of wat	er from water v	vell due t	o nearby CE	BM
	drilling and completion operations.					
COGCC Response:						
	Sampled well for general inorganic	water quality parameters. Sample	es shipped to la	ab. Waiti	ng on result	S
	from lab.					



INACTIVE WELL

Type: INACTIVE	WELL		Date:	03/18/2008
Complainant: Sand	dra Dickens	19587 Weld County Roadd 50-1/2	Lasalle	CO 80645
Description of Compl	Well shut-in since April 2004.	Complainant would like to use the location that was approved 11/16/2007.	on for a hay barn. Not	ble Energy filed
COGCC Response:	COGCC issued NOAV 2001282	241 since well has been shut-in since April	2004. Noble has plar	ns to abandon
	the well by the end of April.	Noble will inform COGCC stafff when they	begin the job of aband	donment.



LAND USE CONFLICT

Type: LAND USE CONFLICT				03/24/20	08
Complainant: Randle Bridge	P.O.Box 1435	Lamar		CO	81052

Description of Complaint:

Operator has stored equipment in pasture without permission.

COGCC Response:

Contacting opeartor to discuss issue.



NOISE

COGCC Complaint Report January 01, 2008 - March 31, 2008

Type: NOISE Complainant: Elana Lo	zano	Date:	03/11/200)8
Description of Complaint:	Complainant indicates that noise levels from Compressor associated with this well a	re continu	ing to bothe	er
COGCC Response:	her. This is the fifth complaint lodged in reference to this same compressor.			
	COGCC conducted filed inspection and talked with the operator. Noise levels coming Compressor Station south of the residence were high. Field Inspector and Operator	-		ty in
	getting accurate readings from compressor subject of complaint due to the noise fro	om Red Ce	edar facility.	-
	Operator was told that sometimes a compressor will be taken offline for repair, etc. the facility runs as it is 24/7/365. Operator called Field Inspector back to relay this i			
	made a field visit and took sound measurements at 12:45 PM. Temperature was app	proximate	ly 50 degre	es,
	wind speed was < 5 mph. Measurements taken 25' from residence were between 63	3.8-64.5 c	lbC.	
Type: NOISE Complainant: Aaron Re	ogers 501 Mud Lane Ignacio	Date:	02/11/200 CO	08 81137
Description of Complaint:				

Complainant advises that noise levels coming from Elm Ridge Resources Amine Plant are bothering him.



COGCC Response:	Field Inspector worked with Operator to mitigate problem throughout month of Febru	uary but p	problems				
	persisted. As of March 7, Operator reported sound levels below 50dbA. Operator provided staff with further						
	plans to mitigate noise issues. Further sound measurements will be taken later in th	plans to mitigate noise issues. Further sound measurements will be taken later in the month. Complainant					
	called back later in March with more dates when noise levels were elevated.						
Type: NOISE Complainant: ROY LYC	IGNACIO	Date:	01/29/200 CO)8 81137			
Description of Complaint:	The noise from the drilling rig has been waking him up at 3 am and he wants the no	ise stoppe	ed or				
	something to be done to lower the levels. The applicable COGCC rules were explained	ed to him	as well as t	he			
	reasons for drilling 24 hours per day. He does have the operator`s phone number a	nd does h	nave a work	ing			
	relation with them. He was told that sound levels would be measured and that the c	operator v	vould be				
	contacted to inform them of the complaint and also to determine an estimate of how	/ much me	ore time it				
	would take to complete the drilling operations. He was assured that the applicable r	ules woul	d be enforc	ed			
	if out of compliance. The COGCC would report back to him regarding this informatio	n.					
COGCC Response:	Rig was indeed moved off location on Friday Feb. 1st. SW Field Inspector has never	heard bac	k from				
	Complainant after asking him to call back. It is assumed that the complaint can now	be closed	1.				
Type: NOISE Complainant: DAVE V	BLACKDUCK AVE JOHNSTOW	Date: N	01/02/200)8			
Description of Complaint:	Noise overnight rattling the windows - suspects drilling rig.						



COGCC Response:	COGCC staff went out and found no	GCC staff went out and found no current noise - activity east of the complainant but nothing like the						
	noise described. Assumption made	that sand masters filled tanks overn	ight for a fra	c that nex	t morning.			
Type: NOISE				Date:	02/22/200	8		
Complainant: Jeanne B	abin	PO Box 36	Cahone		CO	81320		
Description of Complaint:	There were all kinds of operators a	round my land. I am disabled becau	se of mental	trama, str	angers with	۱		
	large machinery have put me into r	major fear and panic attacks.						
COGCC Response:	COGCC does not have jurisdiction of	over civil matters. Refer to local She	riff's deparm	ent for foll	owup.			
Type: NOISE				Date:	02/13/200	8		
Complainant: Leslie Tag	ylor	PO Box 126	Cahone		СО	81320		
Description of Complaint:	Blasting goes on at all times.							
COGCC Response:	-	DOW admitted during January 2008 t night to scare elk away from hay ri			-	- a		
	setting on propane canisters late a	i night to scale cik away non hay n			1755140101	u		
	summary of the meeting.							
Type: NOISE				Date:	02/07/2008	8		
Complainant: Anita Sch	nanamen	11848 Billings Avenue	Lafayette		СО	80026		
Description of Complaint:	Complainant complained of excessi	ve noisewas calling on behalf of h	er mother-in	-law.				



COGCC Response:

COGCC Complaint Report January 01, 2008 - March 31, 2008

COGCC staff went to wellsite and found out that the operator had been fracing the well. The job was

completed at 5:00 P.M. Halliburton began moving trucks and was leaving the location.



NOTIFICATION

Type: NOTI	FICATION			Date:	02/20/20	800	
Complainant:	Juliet Craik	P.O. Box 116	Cahone		СО	81320	
Description of		sufficient time to review legal documents prior to access for	seismic survey.				

COGCC Response:

No COGCC jurisdiction on review time for seismic operations and land access. Refered to Sheriff and/or

legal counsel.



ODOR

COGCC Complaint Report January 01, 2008 - March 31, 2008

Type: ODOR Complainant: Dion Enle	ow	Date:	03/14/2008
Description of Complaint:	Odor coming from the south of the Enlows home. Odor is described as a "Dirty $\ensuremath{\mathbb{N}}$	Nater" odor.	
COGCC Response:	COGCC staff contacted Barrett Corp. to monitor pads located near complainant h	nome. Barrett	sent out a
	pumper to check out the pads. COGCC continues to monitor the sitution.		
Type: ODOR Complainant: Ms. Bonr	nie Smeltzer 100 Limberpine Cr Battlem	Date: ient Mesa	02/08/2008 CO
Description of Complaint:	Report of a petrolum odor in the battlement mesa area @ approx 1430 on 1/10/	/08.	
COGCC Response:	COGCC staff made a field visit the week after the initial call to try and determine likely casue was a stimulation crew. Inspection in the area found no reports of v pads. COGCC staff contacted complainant and informed them that nothing cond Staff member did provide some possible scenarios regarding the source of the o	venting on sur clusive could b	rrounding well be determined.
	COGCC Rules are in regards to trucks.		
Type: ODOR Complainant: Deon En	low None Given	Date:	01/15/2008

Description of Complaint:



	Mr. Enlow complained of an odor that he describes as a dirty water type of odor. Mr. Enlow believes that the						
	odor was coming from the north w	est, and originating at a drilling rig	located between	n his hom	e and Silt,		
	CO.						
COGCC Response:	COGCC staff contacted operator co	ncerning the odor complaint, they	were not aware o	of any ma	alfunctions		
	The operator dispatched a pumper to the Wilson pad located south of the complainant's residence. Staff						
	checked on the Wilson pad, Geiske pad, and found nothing out of the ordinary. Staff contacted complainant						
	and asked that they contact staff n	nember when they noticed the odd	r again so staff c	ould be i	n the area		
	and try to locate the source of the	odor.					
Type: ODOR			ſ	Date:	01/29/200	8	
Complainant: Dale Be	əll	1966 S. US Hwy 550	Durango		СО	81301	
Description of Complain	: Landowner has environmental and	safety concerns over gas which th	ey indicate they I	have bee	n smelling.		
	Landowner feels that gas is associa	ated with the well. Landowner cont	acted Fritzler 1 1	/2 years	ago and w	ere	
	told that someone would come out	to check on it. No one has contac	ted the complain	ants sinc	e then and	ł	

they have seen no one checking the well or ancillary equipment.

COGCC Response:

Complainant was contacted and informed that COGCC field representatives did not detect any methane or H2S gases in the atmosphere at or around the wellhead or around his propane tank during a field inspection.

ODOR 02/04/2008 Type: Date: **Complainant:** Dion Enlow 6 lazy K Rd Silt CO

Description of Complaint:

Smell of a petroleum odor.



COCCC Desmanas							
COGCC Response:	Checked on the stimulation operations on the McLaughlin pad to verify that no flow back operations were						
	being conducted. Inspected wel	Is associated to the pad and no violati	ions were fou	nd. No FF	AC operations		
	were underway during the time	of reported odors.					
Type: ODOR				Date:	02/04/2008		
Complainant: Kathy W	/illiams	1-970-876-0350	Silt		CO		
Description of Complaint:	Smell of a petroleum odor						
COGCC Response:	Checked on the Frac operations	on the McLaughlin pad on 1/23/08 an	d 1/24/08. TI	here was r	io activity		
	during the time frame of the con	nplaint.					



OPERATOR RELATIONSHIP

Type: OPER	ATOR RELATIONSHIP			Date:	02/20/2008	3
Complainant:	Juliet Craik	P.O. Box 116	Cahone		СО	81320
Description of (-	o questions. Intimidation by operator	r.			

COGCC Response:

No COGCC jurisdiction regarding operator relationships. If the complainant continues to feel threatened,

contact Sheriff of legal counsel. See document #01733154 for letter.



conversation. Operator was given 60 days to comply with NOAV. Operator is leaning towards PA'ing well.

ORPHANED EQUIPMENT

Type: ORPHANED EQ	UIPMENT		Date:	01/29/200	8
Complainant: Dale Bel	1	1966 S. US Hwy 550	Durango	CO	81301
Description of Complaint:	Old wellhead, horizontal separato	r, unlined pits, and unused fencing o een anyone come out to service the v			
COGCC Response:		C staff and agreed to remove misc. e or put it back into production. An N			



OTHER

Type: OTHER Complainant: Leslie T	aylor	PO Box 126	Cahone	Date:	02/13/200 CO)8 81320
Description of Complaint	: There is no local government des	ignee in Dolores county.				
COGCC Response:	Met with Mr. Vernon Legett with t	the Dolores County Planning Commist	sion. Dolores	County h	as no	
	regulatory means to appoint a LG	gulatory means to appoint a LGD and are not currently interested in appointing one. They may explore it				
	should O&G activity increase in th	ne area on a permanent basis. Howe	ver they are a	all voluntee	er and do no	ot
	have a mechanism to address it a	at this time.				
Type: OTHER				Date:	02/14/200)8
Complainant: Robert	Nash	11223 WCR 22.5	Ft Lupton		CO	
Description of Complaint		rucks releasing fluids onto Weld Cour	ity Road 22.50	0 near his	house. Flu	ids
	resembled drilling mud. He conta	acted Weld County and Colorado WQ0	D. The comp	plaint was	forwarded t	0
	COGCC because it was thought to	be associated with oil & gas operation	ons.			
COGCC Response:	COGCC staff visited area to inves	tigate allegations of dumping. The su	urface owner v	where the	disposal of	
	mud took place confirmed that th	e material did not originate from oil a	and gas opera	tions. As	a result, the	e
	details were forwarded to Charles	Johnson 303-692-3348 at CDPHE to	follow up on	dumping	of drilling wa	aste
	along WCR 22.50 and into the we	tland area on Shayne O'Hotto's prop	erty.			



PITS

COGCC Complaint Report January 01, 2008 - March 31, 2008

Type: PITS Complainant: Dale Be	Il 1966 S. US Hwy 550 Durango	Date:	01/29/200 CO	8 81301
Description of Complaint	: Landowner indicates that two unlined pits are on location. One is fenced and the ot	her is part	ially fenced.	
	Landowner is concerned for the safety of wildlife and family pets. Landowner has i		5	ing
	on the pit south of the wellhead.			
COGCC Response:	Operator was contacted by COGCC staff and agreed to close the pits. An NOAV wa conversation. Operator was given 60 days to comply with NOAV. The closing of the		5	
	coordinated through the COGCC EPS in the area.			
Type: PITS		Date:	01/28/200	8
Complainant: Randy	NeilP.O. Box 1207Ignacio		СО	81137
Description of Complaint	: Pit is being reclaimed with water still in it. Water is flowing onto the drill pad; it is	flowing un	der the fence	е
	around the pit and livestock can access it. Water is in the low area around the wel			
	livestock can get to it.			
COGCC Response:	COGCC staff attempted to make a site visit but was unable to reach site due to sev and poor roads. Contacted operator about concerns and was told Samson was accord After three week delay due to back to back snow storms, site inspection revealed n	elerating c	losure of pit.	
	violations. Samson provided documentation that pit fluids were removed to Basin of			-

Date: 02/27/2008



Complainant: Dave Hawkins

Description of Complaint:

Complainant said pit has been left open too long.

COGCC Response:

Operator indicated that there is no pit at that location. They have a permit refiled for the location that was built two years ago and has not been drilled on. Landowner wanted commission to put pressure on operator to buy his property. COGCC staff called complainant and they said they would prefer to handle the issues with operator themselves now.



PROPERTY DAMAGE

Type: PROPERTY	DAMAGE		Date:	03/21/20	08
Complainant: Deb	ora Parmenter	2295 Scout Ridge Road	Durango	CO	81301
Description of Comp	laint: The landowner reports that the dir she anticipated and feels that the land reclamation she was expectin	cut into the side of the hill is just		5	
COGCC Response:	COGCC staff sent an email to the or questions pertaining to consultation		·	swer a few	



RECLAMATION

COGCC Complaint Report January 01, 2008 - March 31, 2008

Type: RECLAMATION Complainant: Tom Bin	der	Date:	03/20/200	08			
Description of Complaint:	Surface reclamation around new well sites was delayed by frost in ground. The land	ndowner wanted to plow					
	the ground with frost and plant barley before the operator had opportunity to level	ne ground with frost and plant barley before the operator had opportunity to level and complete their					
	clamation. Well site personnel were asked to leave the site during casing flowback operations by						
	landowner over a surface contract dispute with operator.						
COGCC Response:	COGCC staff made site visit and found no violations. Operator had the pits closed v	within thre	e days of				
	drilling the well. The site has been resotred and planted in barley.						
Type: RECLAMATION		Date:	02/19/200)8			
Complainant: Sue Jarr	ett 52914 Hwy 385 Holyoke		CO	80734			
Description of Complaint:	Pipeline reclamation is not complete.						
COGCC Response:	The pipeline is a transmission line from a compressor to the south. This line and al	l issues wi	th it are not	t			
	under the jurisdiction of the COGCC and will be forwarded to the appropriate agenc	y. The lar	ndowner wa	S			
	informed of the decision by a phone call and was also told of the lack of standing by	y the COG	CC during th	ne			

field inspection.



ROADS

COGCC Complaint Report January 01, 2008 - March 31, 2008

Type: ROADS				Date:	02/19/200)8
Complainant: Chris Stu	llts	218 Elm Street	Wray		CO	80758
Description of Complaint:		es, and the lease attendant is driving	g around them	instead o	of staying o	วท
COGCC Response:	going into the pasture. Operator v	ere developing in lease roads and the vas notified that trucks had to stay o the operator. The road is to be repa	n the roads ar	nd the roa	ids needed	to
Type: ROADS				Date:	03/24/200)8
Complainant: Randle B	Bridge	P.O.Box 1435	Lamar		CO	81052
Description of Complaint:		causing personnel to travel into pastu	ure to drive ar	ound wat	er/mudhole	es.

COGCC Response:

Contacting opeartor to discuss issue.



SIGNS

COGCC Complaint Report January 01, 2008 - March 31, 2008

Type: SIGN	IS		Date:	01/29/20	08
Complainant:	Dale Bell	1966 S. US Hwy 550 Durango		CO	81301
Description of	•	Landowner indicates that there is no sign at the wellhead.			

COGCC Response:

Operator called and left a message that he had issued a work order on Monday (2/04/08) with roustabouts

to have sign installed.



SOIL CONTAMINATION

COGCC Complaint Report January 01, 2008 - March 31, 2008

Type: SOIL CONTAMINATION Date: 02/04/2008 Complainant: Michael Tolmachoff Eaton Со **Description of Complaint:** Used drilling mud contaminated with hydrocarbons was dumped into 3 large earthen pits excavated prior to drilling. Pits are unlined. Fluid has strong hydrocarbon odor. Approximately 175,000 gal (4200 bbls) of fluid originally dumped. The fluids were dumped over the weekend 2/2-2/3/08 and fluid level dropped about 1 foot by 2/4/08. Landowner is concerned about possible ground water impacts and soil contamination. Shallow water wells nearby and location is adjacent to Eaton Ditch. Owner grows alfalfa on his land and is concerned it won't grow if the soils become contaminated. Owner also feels this activity was not mentioned in the contract (land use agreement). **COGCC** Response: During onsite visit by COGCC staff no visible hydrocarbons were observed in or on the mud. Operator decided to haul off the mud to reduce concerns of the landowner. Operator requested their environmental department to collect a sample for TPH test. COGCC called complainant and informed him of operators removal of mud and the test result of mudpit base sample that was collected. Analyses for TPH came back as not detected < 50 mg/kg. SOUL CONTAMINATION 03/24/2008 Data Tunn

Type. Sole containation			Dale.	03/24/200	0	
Complainant:	Randle Bridge	P.O.Box 1435	Lamar		СО	81052
Description of C	Complaint:					

Soil has been contaminated at site and caused salt kill.



COGCC Response:

Contacting opeartor to discuss issue.

Type: SOIL CONTAMINATION		Date:	02/22/2008
Complainant: Anonymous	Dove Creek		CO
Description of Complaint:	in Davis Creation	20	

Dawn Trucking parks produced water trucks in a lot at 123 Hwy 491 in Dove Creek, CO nightly and leaves the valves open overnight. Several gallons of fluids can drain to the lot from each truck. Sometimes it is clear - often it is dark and oily looking. The ground used to be stained, but the lot was resurfaced (gravel) in late 2007. This has been going on for several years. Dawn does not own the property (an old gas station), it is used for a car racing/mechanic company or something. Concerned that this material is just dumped onto the ground and over time is causing a soil and/or water impact.

COGCC Response:

COGCC staff contacted Dawn Trucking. Dawn has written policies and procedures on valving and capping which is addressed at a minimum during annual training. Leaving valves open is not an accepted practice and they stated that this practice does not occur. They will fax a copy of their policy to the COGCC for our records. They are concerned that this is a complaint from a disgrunted ex-employee as several agencies have submitted queries this week, including OSHA. They will check into it and welcome any inspections.



SPILLS

Type: SPILLS		Date:	03/03/200)8	
Complainant: Marsha	Clark Ster	rling	CO	80751	
Description of Complaint:	Produced water tank had an upset condition. A spill occured from the tank, v	with the fluid runr	ning out into)	
	some pasture ground.				
COGCC Response:	The tank had been upset, spilling over less than 1/2 barrel of oil and some in	ron sulfide water.	The iron		
	sulfide has dried out and was blowing away in the wind, leaving a small oil s	scum to be cleaned	d up. The		
	operator cleaned it up by the end of the day. Complaintant was contacted by phone and informed of the				
	situation and was happy with the resolution.				
Type: SPILLS		Date:	03/10/200)8	
Complainant: Marcia S	Skowron Wes	ston	CO	81091	
Description of Complaint:	Marcia Skowron observed silty water in Wet Canyon on a day with little snov	w melt. She thoug	ght silt migl	nt	
	be a result of produced water spill or other activities of Pioneer in area upstr	ream the Skowron	n home.		
COGCC Response:	No evidence of recent spills of produced water observed in the area where to	urbid water was o	bserved in V	Wet	
	Canyon. Pioneer installed additional sediment control BMP's in an effort to p	prevent any meltw	ater caused	k	
	turbidity just above the confluence of San Pablo Canyon and Wet Canyon.	COGCC staff discu	ssed action	6	
	taken by operator with complainant. Complainant has not observed any mo	ore turbid water in	the Canyoi	n as	
	before.				



STORMWATER BMPs

Type: STORMWA	TER BMPs		Date:	02/28/200	80
Complainant: Nor	th Fork Ranch Landowner's	15301 Logging Canyon Rd.	Weston	СО	81091
Description of Comp	Non-compliance for stormwater Hand Fork Road of North Fork R	permit. Lack of erosion controls or Ranch. Culvert covered over with mu	ud and mud flowing down	hill from roa	
		se areas. Three previous complaint 2006, Feb. 28, 2007 and July 10, 20		pliance for	
COGCC Response:	from roadway and entering into poor maintenance of existing Bl	rk showed lack of maintenance of no b Left Hand Fork drainage in several MP's. COGCC contacted Pioneer and airs to existing stormwater controls	areas because of lack of E d operator responded that	BMP's and or a crew was	-



SURFACE WATER

COGCC Complaint Report January 01, 2008 - March 31, 2008

SURFACE WATER 02/22/2008 Type: Date: PO Box 36 СО Complainant: Jeanne Babin Cahone 81320 **Description of Complaint:** Cahone Creek is partly on my land and a spring which begins the creek is right in this area, the companies are setting explosives too close to the spring and creek as well as my home. This is a water source for Cross Canyon and beyond to the San Juan River. It must be protected and gas exploration should be secondary to our water resources. **COGCC** Response: Operator has stated that they are aware of the springs location and have taken precautions to not drill near

it. They have committed to sampling water wells and springs of concern prior to and post seismic testing. Suggested Ms. Babin and/or her neighbor where the spring actually is located contact Operator directly and request spring sampling. Gave operator's phone number to Ms. Babin for her to followup with. No actual potential damage to investigate as survey has not yet been conducted.



TRASH

Type: TRASH				03/24/20	800
Complainant: Randle Bridge	P.O.Box 1435	Lamar		CO	81052
Description of Complaint:					

Description of Complaint:

Trash and junk fitting on various leases in field.

COGCC Response:

Contacting opeartor to discuss issue.



TRESPASS

Type:TRESPASSComplainant:Vickie Cooke

P.O. Box 161

Cahone

Date:	02/22/2008			
	CO	81320		

Description of Complaint:



I am in charge of watching my neigbor's property when they are away. Their names are Tom and Margaret Gardner. They gave me total rights to kick people off their property that weren't supposed to be there. On Jan 16, 2008 I noticed a man on a four-wheeler putting up markers in their field. I rushed out and asked him what he was doing. he told me he was a surveyor and he dialed his boss and let me talk to him. The boss' name was Teddy and his phone number is (435)820-0356. Teddy said that the owner's had given permission to be on the land. I told him they had not. After we finished talking I told the surveyor that he needed to leave. He did not. I went to my house and called Margaret. She told me that they have never given permission to a surveyor (or anyone connected to the Bill Barrett corp.) to be on their property. In fact, they had told the people who called them asking for permission "no, they could not come on their property" Twenty minutes later, my daughter and I walked up to the field and the surveyor came out of the trees on his four-wheeler in a hurry to leave the property. He had put up two more markers and we found where he had tried to "plow" through the trees with his four-wheeler. I went in and called my local sheriffs office. Tim called me back the next day, and I told him of the incident. He said that he would call Tom and Margaret.

A man called me mid-January asking if he could come on the north side of our property to "just lay a cable on the land". I told him "no". He asked if he could set up a meeting to talk about it. I told him yes I have a lot of questions for you, but the answer is still "no". The date was set and when it came around he never showed up. We haven't received another phone call from him. I found out that what they were planning to do (drill 40 foot holes and put dynamite in them). The man who talked to me never mentioned setting off dynamite to be used in seismic testing. All he ever said was that they wanted to lay cable on my land. As a



	nd owner I don't take kindly to people deceiving me when it comes to my land.					
	Please note that in this fax we are	sending the letter and documents a	lawyer sent u	is and our	reply.	
COGCC Response:	Trespass and access issues are not	t within COGCC jurisdiction. Referre	ed to local She	riff and le	gal counsel	for
	follow-up.					
Type: TRESPASS				Date:	02/22/200	8
Complainant: Margaret	and Tom Gardner	11610 North 39th Drive	Phoenix		AZ	85029
Description of Complaint:	BBC has trespassed on our propert	ty to lay survey lines and then lied t	o our neighbo	r Vickie Co	ooke that th	еу
	had permission when they did not.					
COGCC Response:	COGCC cannot provide a resolution	n as trespass is a civil matter and th	e Colorado Oil	and Gas	Conservatio	n
	Act does not provide a mechanism	for the COGCC to address civil mat	ters. Referred	I the Cook	e's to both	the
	local Sheriff and possible legal cou	nsel if them deem it necessary.				
Type: TRESPASS				Date:	02/13/200	8
Complainant: Leslie Ta	ylor	PO Box 126	Cahone		CO	81320
Description of Complaint:	Leslie Taylor does not believe that	the Bill Barrett Seismic Company ha	as right to be o	on her pro	perty or	
	neighbors property.					
COGCC Response:	Trespass and access issues are not follow-up on civil matters.	t within COGCC jurisdiction. Referred	d to local Sher	iff and leg	al counsel f	or



WATER WELL

Type: WATER WELL				Date:	02/13/200)8
Complainant: Randy L	amp	22670 WCR 30	Hudson		CO	80642
Description of Complaint:		nestic water well after a nearby oil &	gas well was	worked o	ver. Descri	bes
COGCC Response:	no effervescing. Collected sample 3/6/08. No benzene, ethylbenzene	722/08 to collect sample from water for normal suite of organics, inorgan e or toluene detected. Trace concenti ds for Ground Water for xylenes. Hig nin aquifer.	ics and bacter ration of xylen	ria. Lab re	esults receiv ed, which is	ved
Type: WATER WELL	5			Date:	01/02/200	0
Type: WATER WELL Complainant: Mike Dix	on	20106 CR 38.4	Weston	Date.	CO	81091
Description of Complaint:		and water from well has developed o	odors and bad	taste rece	ently.	
COGCC Response:	COGCC staff visted site and sampled dissolved methane and BART anal	es were collected for general inorgar yses. Waiting on lab results.	nic water quali	ty parame	eters as we	ll as
Type: WATER WELL				Date:	01/16/200)8
<i>,</i>	Ann Karns	36207 WCR 65	Galster		CO	80622



Description of Complaint:	omplainant alleges impact to domestic water well from nearby oil & gas well.						
COGCC Response:	COGCC staff visited site and collect	ted samples from water well for labo	oratory analyse	es. Basec	l on labora	tory	
	results there is no evidence that the	ults there is no evidence that the water well was impacted as a result of nearby oil/gas operations. Letter					
	sent to complainant with lab result	ts showing no impact from nearby oil	I/gas operation	IS.			
Type: WATER WELL Complainant: Tim Bak	er	17910 CR 46	Aguilar	Date:	03/25/20 CO	08 810209714	
Description of Complaint:			rigunar		00	010207711	
	Water from domestic well has developed a brown color and also water now has suspended particles that clog						
	filters or nozzles. Mr. Baker is cor	filters or nozzles. Mr. Baker is concerned that that water from his well has been impacted by nearby CBM					
	drilling and production activities.						
COGCC Response:	COGCC staff sampled water from	complainant's water well. Analysis fo	r general inorg	anic wate	er quality		
	parameters, dissolved methane and BART kits. Results of lab samples pending.						
Type: WATER WELL				Date:	03/28/20	08	
Complainant: Rick Har	nson	157 South Ridge Court	Battlement M	lesa	CO	81635	
Description of Complaint:	Request from land owner to samp	e water.					
COGCC Response:	COGCC staff contacted land owner	and collected split samples. Results	s pending.				
Type: WATER WELL				Date:	02/14/20	08	
Complainant: Carolyn	Meehan	1781 E 141th Ave	Brighton		CO	80602	



Description of Complaint:	Ms. Meehan has been experiencing	a black colored sediment build	-up in her water well filter	. Wellington	
	Operating has recently drilled three	e new wells near her property a	and she was wondering if the	nere might b	e a
	connection.				
COGCC Response:	COGCC staff collected water sample	es form water well and collecte	d a sample of the black se	diment mate	rial
form the water filter. Water sampling results show no unusual water quality parameters and water quailty is					ty is
	typical of water wells in the area. Further investigation of the black sediment show that the material is an				
	organic material related to sulfate	organic material related to sulfate reducing bacteria that is present in complainant's well and/or house water			
	system.				
Type: WATER WELL			Date:	02/29/200	08
Complainant: Fran Fre	eemyer	32475 WCR 61.5	Gill	CO	80624
Description of Complaint:	Mr. Freemyer made a previous con	nplaint in December 2006, that	his domestic water well ha	ad been	
	impacted by a nearby oil & gas we	II. COGCC sampled the well on	12/15/06. Analytical resu	lts did not	
	indicate that the well had been imp	bacted. Mr. Freemyer made an	other complaint indicating	that he belie	ves
	the well is impacted and he didn't	think the 12/06 sample was col	lected from the correct loc	ation on his	
	property.				



COGCC Response:

COGCC staff visted the residence to collect another groundwater sample. Water at an inside faucet was checked with CGI due to strong sulfur odor. No combustible gas or hydrogen sulfide was detected. During well purging it was noted that water became more entrained with bubbles and flow rate decreased substantially. Water pressure in house was minimal when exterior faucet was running. Mr. Freemyer indicated that the well had never made much water, and it would run dry if the exterior faucet continued to run. As purging continued the water went from clear to slightly off-color yellow with some silica sand in the purge bucket. Water was sampled for normal suite of organic and inorganic constituents as well as bacteria and gas composition. Lab results for water samples received 3/11/08. No BTEX detected. Total Dissolved Solids at 652 mg/l. Lab results for gas sample pending.

 Type:
 WATER WELL
 Date:
 02/27/2008

 Complainant:
 Michael & Desri Murray
 7636 WCR 10
 Ft. Lupton
 CO
 80621

Description of Complaint:

Complainant alleges there is an oil film on water that they believe may come from nearby oil & gas wells. Location of domestic well is: NWNE 17, T1N, R67W.

COGCC Response:

Site visit to Murray residence to collect groundwater sample. Water exhibited a sulfur odor and there was moderate effervescing. Collected sample for normal suite of organic/inorganic constituents, bacteria and gas comp. Lab results received 3/5/08. No BTEX detected. Gas sample indicated a small volume of biogenic methane gas. No evidence that water well impacted by nearby oil and gas operations. Letter summarizing all lab results pending.



WILDLIFE

COGCC Complaint Report January 01, 2008 - March 31, 2008

Type: WILDLIFE		Date:	02/13/2008	
Complainant: Leslie Ta	ylor PO Box 126	Cahone	CO 8 ²	1320
Description of Complaint:	Noise is killing deer and elk by running them off winter gro	ounds.		
COGCC Response:	No blasting has occurred to date. DOW has temporary "B since the heavy snowcover has pushed them down into an		0	1
	from hay ricks. Mortality is high along the highway. Drill	rigs being used are small and move	9 quickly -	

tractor pulling it is smaller than standard farm tractors used in the area. No drilling or tractor use at night.

DOW is using propane canons to scare away the elk.