UCSU1.9/5/2009-10 C.2

CONTROLLED MAINTENANCE

REQUEST

construction

FISCAL YEAR 2009-2010

design

planning

CSU FACILITIES

DMINISTRATIVE AGEMENT



Colorado













TABLE OF CONTENTS

| TAB 1 | CM-02: 5-YEAR PLAN |
|-------|--|
| TAB 2 | CM-4: CM PROJECT STATUS |
| TAB 3 | CC-01: CC PROJECT STATUS |
| TAB 4 | CM-05: BUILDING INVENTORY |
| TAB 5 | CM-07: O&M COST |
| TAB 6 | CM-01: CM REQUEST SUMMARY |
| TAB 7 | CM-02.1: ASSET MANAGEMENT MAINTENANCE STRATEGY |
| TAB 8 | CM-03: CM PROJECT REQUEST FY 2009/2010 |

△ AVERY

| (1) | | (3) | (4) | (5) | (6) | (7) | (8) | (9) | (10) |
|----------|--------|--|----------------|--|--------------|--------------|-------------|-------------|-------------|
| Agency | ect | Project Title - Number of Phases | Fotal Project | Prior | FY 09/10 | FY 10/11 | FY 11/12 | FY 12/1: | FY 13/14 |
| Priority | .√# | | Cost | Appropriatio | Current Yr | Budget | Budget | Budget | Budget |
| lumber | | | | n | Request | Request | Request | Request | Request |
| 1 | M06057 | Replace Environmental Control System - Phase 3 of 3 | \$989,028 | \$611,894 | \$377,134 | | | | |
| 1 | M06056 | Replace Steam & Condensate - North Line - Phase 3 of 3 | \$2,599,406 | \$1,169,079 | \$1,430,327 | | | | |
| 1 | M07026 | Sanitary Sewer Improvements, Main Campus - Phase 2 of 3 | \$2,035,532 | \$639,852 | \$697,840 | \$697,840 | | | |
| 1 | 03-140 | Replace Failed Roofing - Main Campus - Phase 1 of 2 | \$3,377,550 | | \$1,992,100 | \$1,385,450 | | | |
| 1 | 03-124 | Replace Inadequate Ventilation Systems - Painter Center - Phase 1 of 1 | \$1,887,883 | | \$1,887,883 | | | | |
| 1 | 98-086 | Replace Unsafe Overhead Electrical Service - Foothills Campus - Phase 1 of 2 | \$1,690,304 | | \$1,156,210 | \$534,094 | | | |
| 1 | 08-086 | Replace Inadequate Ventilation Systems and Failing Electrical & Mechanical Systems - Visual Arts - Phase 1 of 3 | \$3,168,165 | | \$439,725 | \$1 345 300 | \$1,383,140 | | |
| | 00 000 | Replace Unsafe Electrical and Inadequate Mechanical Systems - Engineering | ψο, 100, 100 | | ψ 100,120 | ψ1,010,000 | Ψ1,000,110 | | |
| 1 | 99-005 | Research Center - Phase 1 of 2 | \$3,102,930 | | \$1,551,465 | \$1,551,465 | | | |
| 1 | 03-123 | Direct Digital Control System Conversion - Phase 1 of 3 | \$1,290,418 | | \$597,418 | \$346,500 | \$346,500 | | |
| | 03-123 | I was a second to the second t | \$1,290,410 | | \$397,410 | \$340,300 | \$340,300 | | |
| 1 | 03-121 | Improve Fire Alarm Systems for Additional Life Safety and Code Compliance - Phase 1 of 2 | \$1,284,376 | | \$499,617 | \$784,759 | | | |
| 1 | 00-001 | Remove Asbestos and Replace Deteriorated Electrical & Mechanical - Guggenheim - Phase 1 of 2 | \$1,776,070 | | | \$572,000 | \$1,204,070 | | |
| | | Replace Broken and Dilapidated Lecture Hall Seating and Improve | | | | | | | |
| 2 | 00-005 | Accessibility - Phase 1 of 1 | \$768,439 | | | \$768,439 | | | |
| 2 | 07-082 | Replace Det. Electrical & Mechanical - Shepardson - Phase 1 of 3 | \$1,999,999 | | | \$608,702 | \$820,942 | \$570,355 | |
| 2 | 02-008 | Replace Det. Chillers with Cooling Loop Connection - Phase 1 of 2 | \$1,150,000 | | | \$575,000 | \$575,000 | | |
| 2 | 98-112 | Replace Det. Roads & Sidewalks - Phase 1 of 3 | \$1,275,510 | | | \$425,170 | \$425,170 | \$425,170 | |
| 2 | 98-145 | Replace Det. Electrical & Mechanical - Military Science - Phase 1 of 1 | \$640,000 | | | \$640,000 | | | |
| 2 | 03-023 | Replace Det. Items - Multiple Agricultural Research Centers - Phase 1 of 2 | \$749,790 | | | \$374,895 | \$374,895 | | |
| 2 | 02-009 | Replace District Heating Plant Boiler No. 3 - Phase 1 of 3 | \$871,820 | | | | \$290,606 | \$290,606 | \$290,60 |
| 2 | NEW | Replace Det. Electrical & mechanical - Eng. "E" Wing - Phase 1 of 2 | \$1,600,000 | | | | \$800,000 | \$800,000 | |
| 2 | 03-089 | Replace Det. Condensate Line - West Drive - Phase 1 of 1 | \$641,250 | | | | \$641,250 | | |
| 2 | 03-122 | Replace Det. Boilers - VTH - Phase 1of 1 | \$750,000 | | | | | \$750,000 | |
| 2 | 99-015 | Replace Det. Items - San Juan Basin - Phase 1 of 4 | \$1,999,999 | Annual Company of the | | | | \$1,000,000 | \$999,99 |
| 3 | 00-003 | Replace Det. Items - Lake Street Greenhouse - Phase 1of 2 | \$1,220,712 | | | | | \$610,356 | \$610,35 |
| 3 | 98-152 | Replace Det. Electrical & Mechanical - Insectary & Weed Research -1 of 1 | \$951,856 | | | | | \$951,856 | |
| 3 | 98-083 | Replace Det. Steam & Condensate - Northwest Campus - Phase 1 of 3 | \$1,680,750 | | | | | | \$1,680,75 |
| 3 | 98-146 | Replace Det. Electrical & Mechanical - Military Annex - Phase 1 of 1 | \$613,140 | the supplementary of the second of the second | | | | | \$613,14 |
| 3 | 01-009 | Replace Det. Refrigeration Units Group 2 - Phase 1of 1 | \$623,000 | | | | | | \$623,00 |
| 3 | 98-059 | Annual Phase Health & Life Safety - Phase 1 of 3 | \$1,746,800 | and the same and the same of the | | | | | \$1,746,80 |
| 3 | 03-038 | Replace Det. Chillers - Anatomy Zoology - Phase 1 of 3 | \$1,999,999 | | | | | | \$1,999,99 |
| 3 | 08-074 | Replace Overhead Electric Lines - Foothills Campus - Phase 1 of 3 | \$1,880,700 | CARLES OF THE OWNER OF THE REAL PROPERTY AND ADDRESS OF THE PARTY AND A | | | | | \$1,880,70 |
| 3 | 02-010 | Replace Air Handling Units - Main Campus - Phase 1 of 2 | \$1,236,500 | | | | | | \$1,236,50 |
| | | | | | | | | | |
| | | The state of the s | Totals for eac | CONTRACTOR DESCRIPTION OF STREET STREET | \$10,629,719 | \$10,609,614 | \$6,861,573 | \$5,398,343 | \$11,681,85 |
| | | (12) Grand Total of the Five Year Plan | \$45,181,100 | | | | | | |

S AVERY

| (1) | (2) | (3) | (4) | (5) | (6a) | (6b) | (7a) | | (8) | (9) | (10) | |
|------------------|---|---------------------------|-----------|----------------------------|-------------------------|---------------------------------------|-------------------|---------------------|------------|---|-------------------------------|----------------------------------|
| roject lumber | | CCFE Appropriatio n | Other | Date Funds Available | Funds Encumbere d | Percent of Funds Encumber ed | Funds Expended | Percent Expended | Acceptan | Code Complianc e/Final SC 4.1 Date Received | Comments/Status | |
| 13020F | Replace Deteriorated Flooring, Painter Center, Ph 1 of 1 | \$0 | \$330,405 | 10/03 | \$330,359 | 100% | \$330,359 | 100% | 4/08-R | 11/04 | Completed Project | Remove from list |
| 105009 | Replace Deteriorated Plumbing Items, Ph 1 of 2 | \$481,390 | \$0 | 7/05 | \$481,390 | 100% | \$481,390 | 100% | N/A | N/A | Phase Complete | |
| 105009 | Replace Deteriorated Plumbing Items, Ph 2 of 2 | \$283,173 | \$0 | 7/06 | \$281,981 | 99% | \$274,656 | 97% | 6/08 | 12/08 | In Closeout | |
| / 06003 | Replace Deteriorated Electrical System, Flooring, Ceiling and Windows, Wagar, Ph 1 of | \$696,293 | \$0 | 7/06 | \$695,805 | 100% | \$695,805 | 100% | 6/08 | 8/08 | Closeout | |
| | Replace Deteriorated Electrical, Heating, and Plumbing Systems, Music, Ph 1 of 2 Replace Deteriorated | \$697,565 | \$0 | 7/06 | \$697,565 | 100% | \$486,155 | 70% | N/A | N/A | Phase Complete | |
| Л06055 | Electrical, Heating, and Plumbing Systems, Music Ph 2 of 2 | \$585,024 | \$0 | 7/07 | \$447,118 | 76% | \$0 | 0% | 1/09 | 5/09 | In Construction | \$66,576 transferred to M08001 |
| | Replace Steam and Condensate, North Line, Ph 1 of 3 Replace Steam and Condensate, North Line, | \$490,415 | | 7/06 | \$490,415 | 100% | \$490,415 | | | N/A | Phase Complete | |
| | Ph 2 of 3 Replace Environmental Control System, Ph 1 of 3 | \$678,664 | | 7/07 | \$656,083 \$267,121 | 97% | | | N/A N/A | N/A N/A | Phase Complete Phase Complete | |
| M06057 | Replace Environmental Control System, Ph 2 of 3 Replace Deteriorated Electrical, Heating, and Plumbing Systems, | \$344,773 | \$0 | 7/07 | \$266,724 | 77% | \$67,341 | 20% | N/A | N/A | In Construction | |
| M06058 | Forestry, Ph 1 of 2 Replace Deteriorated Electrical, Heating, and | \$551,876 | \$0 | 7/06 | \$551,876 | 100% | \$551,876 | 100% | N/A | N/A | Phase Complete | |
| M06058 | Plumbing Systems, Forestry, Ph 2 of 2 | \$588,694 | \$0 | 7/07 | \$487,079 | 83% | \$460,193 | 78% | 11/08 | 3/09 | In Construction | |
| 106059 | Replace Deteriorated Fire Alarms, Ph 1 of 3 | \$400,000 | \$0 | 7/06 | \$400,000 | 100% | \$400,000 | 100% | N/A | N/A | Phase Complete | |
| 1 06059 | Replace Deteriorated Fire Alarms, Ph 2 of 3 Replace Deteriorated Fire | \$400,000 | \$0 | 7/07 | \$400,000 | 100% | \$17,058 | 4% | N/A | N/A | Construction | |
| 1 06059 | Alarms, Ph 3 of 3 Sanitary Sewer | \$424,256 | \$0 | 7/08 | \$78,825 | 19% | \$0 | 0% | 10/09 | 2/10 | Design | |
| 107026 | Improvements, Main Campus, Ph 1 of 3 Pitkin Station Electrical | \$639,852 | \$0 | 7/07 | \$502,684 | 79% | \$249,033 | 39% | N/A | N/A | In Construction | |
| 108001 | Switchgear Replacement, Ph 1 of 1 | \$647,376 | \$0 | 12/07 | \$576,391 | 89% | \$2,986 | 1% | 8/09 | 11/09 | Switchgear due 5/09 | \$66,576 transferred from M06055 |

M AWERY

| | CCFE Appropriatio | | Date Funds | | Percent of Funds Encumber | | Percent | Notice of Acceptan | Code Complian ce/Final SC 4.1 Date | 0 | НРСР | |
|--|----------------------|-----------------------------|---------------|-----------------------------|---------------------------|---------------------------|----------|-----------------------|--|---|--------|--|
| Project Description, Phase | n | Other Funds | Available | Funds Encumbered | ed | Expended | Expended | ce 6.27 | Received | Comments/Status | status | |
| University Center for the Arts, Ph 1 | 0000 044 | AF 070 457 | 7/04 | ec ese 204 | 100 000/ | ¢c cac and | 100.00% | NI/A | N/A | Phase Complete | N/A | |
| of 4 | \$699,844 | \$5,070,457 | 7/04 | \$6,636,301 | 100.00% | \$6,636,301 | 100.00% | IN/A | N/A | Phase Complete | IN/A | |
| University Center for the Arts, Ph 3 of 4 | \$0 | \$21,751,841 | 7/06 | \$21,751,841 | 100.00% | \$21,751,841 | 100.00% | N/A | N/A | Phase Complete | N/A | |
| University Center for the Arts, Ph 4 of 4 | \$0 | \$7,000,000 | 7/07 | \$5,837,906 | 83.00% | \$5,738,597 | 82.00% | 9/08 | 4/09 | In Construction | N/A | |
| University Center for the Arts, Ph 2 of 4 | \$0 | \$866,000 | 10/04 | \$866,000 | 100.00% | \$866,000 | 100.00% | N/A | N/A | Phase Complete | N/A | |
| University Center for the Arts Concert Hall, Ph 1 of 1 | \$7,001,633 | \$0 | 7/05 | \$7,001,633 | 100.00% | \$7,001,633 | 100.00% | 4/08-R | N/A | Completed Project | | Remove from list |
| Bioenvironmental Research Building | | | | | | | | | | | | |
| Expansion, Ph 1 of 2 | \$0 | \$10,250,000 | 6/03 | \$10,250,000 | 100.00% | \$10,250,000 | 100.00% | N/A | N/A | Phase Complete | N/A | |
| Bioenvironmental Research Building Expansion, Supplemental, Ph 2 of 2 Hughes Stadium Expansion, Ph 1 of | \$0 | \$1,652,175 \$14,534,534 | | \$1,532,102 \$14,534,534 | | \$954,025 \$14,535,534 | | | 2/09 | In Construction Completed Project | N/A | Cash funds were less than total spending authority Remove from list |
| Regional Biocontainment | \$0 | φ14,004,004 | 1703 | \$14,554,554 | 100.0076 | Ψ14,000,004 | 100.0070 | 4/00-11 | 0/00 | Completed Froject | | Tremeve went net |
| Laboratory, Ph 1 of 1 Atmospheric Science Chemistry | \$0 | \$31,271,055 | 7/06 | \$30,225,773 | 97.00% | \$29,826,349 | 95.00% | 4/08 | 12/08 | In Closeout | N/A | |
| Addition, Ph 1 of 1 | \$0 | \$2,500,000 | 7/04 | \$2,498,140 | 100.00% | \$2,498,140 | 100.00% | 4/08-R | 6/07 | Completed Project | | Remove from list |
| Small Animal Research Annex, Ph 1 of 1 | \$0 | \$1,960,405 | 7/05 | \$1,960,405 | 100.00% | \$1,960,405 | 100.00% | 4/08-R | 6/07 | Completed Project | | Remove from list |
| Regulated Materials Handling Facility, Ph 1 of 1 | \$1,502,078 | \$301,000 | 7/07 | \$1,801,640 | 99.00% | \$1,729,639 | 96.00% | 9/08 | 11/09 | In Construction | N/A | |
| Shortgrass Steppe Field Station Additions and Alternations, Ph 1 of 1 Atompheric Sciences Building | \$0 | \$2,320,828 | 7/05 | \$2,320,828 | 100.00% | \$2,207,875 | 95.00% | 9/08 | 12/08 | In Construction - Per House Bill 08- 1303 reversion date is 6/30/2011. | N/A | |
| Construction, Ph 1 of 1 | \$0 | \$4,965,627 | 7/06 | \$4,107,376 | 83.00% | \$1,885,578 | 38.00% | 3/09 | 7/09 | In Construction | N/A | |
| Diagnostic Medicine Center, Ph 1 of 3 | \$3,500,000 | \$0 | 7/06 | \$3,500,000 | 100.00% | \$3,500,000 | 100.00% | N/A | N/A | Phase Complete | N/A | |
| Diagnostic Medicine Center, Ph 2 of 3 | \$19,420,741 | \$0 | 7/07 | \$19,420,741 | 100.00% | \$12,051,065 | 62.00% | N/A | N/A | In Construction | N/A | |
| Diagnostic Medicine Center, Ph 3 of 3 | \$19,156,307 | \$2,922,952 | 7/08 | \$15,757,524 | 71% | \$0 | 0 | 5/09 | 9/09 | In Construction | N/À | |
| Foothills Campus, Renovation of the Center for Environmental Toxicology and Technology, Ph 1 of 1 | \$0 | \$6,052,619 | 7/06 | \$0 | 0.00% | \$0 | 0.00% | N/A | N/A | Cancelled-never funded | N/A | Remove from list |
| Relocate Computer Sciences Dept Information Sciences and Technology Center Addition/Renovation, Ph 1 of 1 Veterinary Teaching Hospital, Food | \$0 | \$13,420,141 | 7/06 | \$12,828,692 | 96.00% | \$11,266,689 | 84.00% | 10/08 | 3/09 | In Construction | N/A | Cash funds were less than total spending authority |
| Animal Care Facility Construction, Ph 1 of 1 | \$0 | \$13,029,000 | 7/06 | \$0 | 0.00% | \$0 | 0.00% | N/A | N/A | Cancelled | N/A | Remove from list |
| Veterinary Teaching Hospital, Mechanical and Fire Sprinklers, Ph | \$3,225,172 | | 7/06 | \$3,139,449 | | \$3,139,449 | | | 10/08 | In Closeout | N/A | |

| | | | | r | | | | | 10 1 | | | |
|---|--------------|-------------------|-----------|----------------------|------------------|-------------|----------|-----------|---|---------------------|--------|------------------------------|
| | | | | | D | | | | Code | | | |
| | CCFE | | Date | | Percent of Funds | | | Madian of | ce/Final SC 4.1 | | | |
| | Appropriatio | | Funds | | Encumber | Funda | Percent | Notice of | | | | |
| Project Description, Phase | | Other Funda | | Funds Encumbered | | Expended | | Acceptan | Date | | HPCP | |
| cademic Training and Indoor | 111 | Other Funds | Available | Funds Encumbered | ed | Expended | Expended | ce 6.27 | Received | Comments/Status | status | |
| Practice Facility, Ph 1 of 1 | 60 | \$20,000,000 | 7/07 | 04 400 076 | 00.000/ | 0047 700 | F 000/ | 14/00 | 4440 | | Gold- | |
| Biomass District Heating Plant, | \$0 | \$20,000,000 | 7107 | \$4,463,870 | 22.00% | \$917,729 | 5.00% | 11/09 | 4/10 | In Design | Pre | |
| Foothills Campus, Ph 1 of 1 | 60 | C4 004 000 | 7/07 | 0010 505 | 00 000/ | 054.407 | 4.000/ | F/00 | 0.000 | | | |
| District Cooling Plant No. 2, Ph 1 of | \$0 | \$1,231,000 | 7107 | \$318,585 | 26.00% | \$54,427 | 4.00% | 5/09 | 9/09 | In Design | N/A | <5000sf |
| district Cooling Flant No. 2, Fit 1 of | 60 | #0.000.000 | 7/07 | 00 000 000 | 100 000/ | 60 000 000 | 100 000/ | | | | | |
| District Cooling Plant No. 2, | \$0 | \$2,800,000 | 7107 | \$2,800,000 | 100.00% | \$2,800,000 | 100.00% | N/A | N/A | In Construction | N/A | <5000sf |
| | | | | | | | | | | | | |
| Supplemental | \$0 | \$4,300,000 | 12/07 | \$2,639,369 | 61.00% | \$2,503,899 | 58.00% | 12/08 | 2/09 | In Construction | | |
| Research Innovation Center, Ph 1 of | | | | | | | | | | | Gold- | |
| | \$0 | \$52,000,000 | 7/07 | \$10,874,612 | 21.00% | \$1,992,854 | 4.00% | 10/10 | 2/11 | In Design | Pre | |
| Rockwell Hall Business Expansion, | | | | | | | | | | | | |
| Supplemental | \$0 | \$3,496,150 | 3/08 | \$0 | 0.00% | \$0 | 0.00% | 3/10 | N/A | In Design | | |
| Rockwell Hall Business Expansion, | | | | | | | | | | | Gold- | |
| Ph 1 of 1 | | \$11,803,850 | | \$1,421,730 | 12.00% | | | | N/A | | Reg | |
| Clark Building Revitalization, Ph 1 | | \$2,000,000 | 1/08 | \$812,911 | 20% | \$83,834 | 2% | N/A | N/A | In Design | N/A | limited scope |
| Clark Building Revitalization, Ph 2 of | f | | | | | | | | | | | |
| 3 | \$2,000,000 | | 7/08 | \$0 | 0% | \$0 | 0 | N/A | N/A | In Design | | |
| | | | | | | | | | | | Gold- | Cash funds were less than |
| New Academic Village, Phase 1B | \$0 | \$22,144,617 | 7/08 | \$44,048,644,768,420 | 21.00% | \$942,090 | 4.00% | 9/09 | 1/10 | In Construction | Reg | total spending authority |
| Industrial Science Building | | | | | | | | | | | | |
| | | 00 770 075 | 7/00 | 0045 404 | 00/ | 000 540 | 901 | 0/00 | 10/00 | | | Historical Bldg-construction |
| Renovation | \$0 | \$3,773,375 | 7/08 | \$245,401 | 6% | \$83,519 | 2% | 6/09 | 12/09 | In Design | N/A | being donated |
| Moby B & C Wings Expansion and Remodel, Human | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| Performance/Clinical Research Lab, | | | | | | | | | | | Gold- | Cash funds were less than |
| Ph 1 of 4 | \$0 | \$2,300,000 | 7/08 | \$332,262 | 14% | \$8,262 | 2 0% | N/A | N/A | In Design | Pre | total spending authority |
| North Entrance Addition, | | | | | | | | | | Hold- pending | | |
| Engineering Building, Ph 1 of 1 | \$0 | \$6,000,000 | 7/08 | | | | | | | cash funds | | |
| Painter Center Addition/Renovation, | | | | | | | | | | Hold- pending | | |
| Ph 1 of 5 | \$0 | \$1,924,858 | 7/08 | | | | | | | cash funds | | |
| Professional Veterinary Medicine | | | | | | | | | | | | |
| Program, Community Practice | | | | | | | | | | Hold- pending | | |
| Building, Ph 1 of 1 | \$0 | \$17,300,000 | 7/08 | | | | | | 100000000000000000000000000000000000000 | cash funds | | |
| Professional Veterinary Medicine | | | | | | | | | | | | |
| Program, Veterinary Teaching | | | | | | | | | | Hold- pending | | |
| Hospital, Ph 1 of 1 | \$0 | \$21,800,000 | 7/08 | | | | | | | cash funds | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | Waiting on transfer | | |
| PET/CT Scanner Purchase and | | | | | | | | | | of Federal grant | | |
| Installation | \$0 | \$4,310,000 | 7/08 | \$0 | 0% | \$0 | 0% | 8/09 | 12/09 | funds | n/a | Equipment installation |

CONTROLLED MAINTENANCE AGENCY'S BUILDING INVENTORY LIST - 2009/2010 STATE BUILDINGS AND REAL ESTATE PROGRAMS

COLORADO STATE UNIVERSITY

FACILITIES MANAGEMENT DEPARTMENT

August 28, 2007

| Building Name | | Bldg. | Occ. | Fund. | G.S.F. | C.R.V. | | - | | 02 Audit | F.C.I. | Target | A/DET | T/DET | T Backlog | Code | CC | CM | EN |
|--------------------------------------|------|-------|------|-------|---------|---------------|-------|---------|---------|----------|--------|--------|--------------|-------------|--------------|------------|----------------------------|---------------|-----|
| | No. | No. | Type | | | | Built | Acqudit | Da F.C. | . Date | | FCI | | | | Projects | Projects | Projects | |
| | | | | | | | | | | | | | | | | | | | |
| Alumni Center | 3188 | 0001 | 16 | 100 | 4,690 | \$582,076 | 1946 | | | 2003 | 69.00 | 94.00 | \$180,444 | \$34,925 | \$145,519 | | | | |
| Palmer Center | 3189 | 0004 | 50 | 0 | 17,671 | \$2,189,591 | 1967 | | | 2003 | 94.00 | 94.00 | \$131,375 | \$131,375 | \$0 | | | | |
| Westfall Hall | 3190 | 0005 | 50 | 0 | 104,898 | \$12,997,775 | 1967 | | | 2003 | 94.00 | 94.00 | \$779,867 | \$779,867 | \$0 | | | | |
| Durrell Center | 3191 | 0006 | 50 | 0 | 46,226 | \$5,727,804 | 1967 | | | 2003 | 82.00 | 94.00 | \$1,031,005 | \$343,668 | \$687,336 | | | | |
| Durward Hall | 3192 | 0007 | 50 | 0 | 104,898 | \$12,997,775 | 1967 | - | | 2003 | 91.00 | 94.00 | \$1,169,800 | \$779,867 | \$389,933 | | | | |
| Lory South | 3193 | 0008 | 50 | 0 | 34,638 | \$3,755,511 | 1950 | | | 2003 | 81.00 | 94.00 | \$713,547 | \$225,331 | \$488,216 | | | | |
| Lory North | 3194 | 0009 | 50 | 0 | 34,638 | \$3,755,511 | 1950 | | | 2003 | 81.00 | 94.00 | \$713,547 | \$225,331 | \$488,216 | | The Land State of the Land | | |
| Corbett Hall | 3195 | 0010 | 50 | 0 | 223,334 | \$24,214,252 | 1965 | | | 2003 | 88.00 | 94.00 | \$2,905,710 | \$1,452,855 | \$1,452,855 | | | | |
| Parmelee Hall | 3196 | 0011 | 50 | 0 | 111,034 | \$12,038,495 | 1962 | | | 2003 | 81.00 | 94.00 | \$2,287,314 | \$722,310 | \$1,565,004 | | | | |
| Green Hall | 3197 | 0013 | 16 | 100 | 18,755 | \$2,033,419 | 1953 | | | 2003 | 84.00 | 94.00 | \$325,347 | \$122,005 | \$203,342 | | | | |
| Allison Hall | 3198 | 0014 | 50 | 0 | 98,023 | \$10,627,820 | 1957 | | | 2003 | 77.00 | 94.00 | \$2,444,399 | \$637,669 | \$1,806,729 | | | | |
| Rockwell Hall | 3199 | 0015 | 16 | 100 | 61,198 | \$11,927,154 | 1940 | 20 | 0 94.5 | 8 2006 | 88.00 | 94.00 | \$1,472,144 | \$715,629 | \$765,515 | | | | |
| Softball Dugouts | 5125 | 0016 | 15 | 100 | 255 | \$48,735 | 1995 | | | 2003 | 49.00 | 90.00 | \$24,855 | \$4,874 | \$19,981 | | | | |
| Ingersoll Hall | 3200 | 0017 | 50 | 0 | 98,802 | \$10,712,281 | 1964 | | | 2003 | 70.00 | 94.00 | \$3,213,684 | \$642,737 | \$2,570,947 | | | | |
| Edwards Hall | 3201 | 0018 | 50 | 0 | 98,023 | \$10,627,820 | 1964 | | | 2003 | 78.00 | 94.00 | \$2,338,120 | \$637,669 | \$1,700,451 | | | | |
| Newsom Hall | 3203 | 0020 | 50 | 0 | 104,510 | \$11,331,152 | 1954 | | | 2003 | 63.00 | 94.00 | \$4,192,526 | \$679,869 | \$3,512,657 | | | | |
| Aylesworth Hall | 3204 | 0021 | 10 | 100 | 87,523 | \$10,845,360 | 1956 | 20 | 00 71.6 | 6 2006 | 59.00 | 94.00 | \$4,446,598 | \$650,722 | \$3,795,876 | | | M01013 | |
| Braiden Hall | 3205 | 0022 | 50 | 0 | 110,837 | \$12,476,519 | 1963 | | | 2003 | 86.00 | 94.00 | \$1,746,713 | \$748,591 | \$998,122 | | | | |
| Baseball Press Box | 3206 | 0023 | 15 | 100 | 128 | \$24,398 | 1984 | | | 2003 | 49.00 | 90.00 | \$12,443 | \$2,440 | \$10,003 | | | | |
| Softball Scorers Box | 5126 | 0024 | 15 | 100 | 95 | \$8,360 | 1995 | 200 | | 2003 | 49.00 | 90.00 | \$4,264 | \$836 | \$3,428 | Same and | | | |
| Hartshorn Health Center (HHC) | 3207 | 0025 | 41 | 0 | 39,169 | \$6,094,442 | 1964 | 19 | 9 78.4 | 0 2005 | 77.00 | 94.00 | \$1,401,722 | \$365,667 | \$1,036,055 | | | | |
| Baseball Dugouts | 3208 | 0026 | 15 | 100 | 528 | \$31,673 | 1960 | | | 2003 | 49.00 | 90.00 | \$16,153 | \$3,167 | \$12,986 | | | | |
| Auditorium Gymnasium | 3209 | 0027 | 15 | 100 | 278,488 | \$34,907,464 | 1966 | 20 | 00 71.7 | 7 2007 | 68.00 | 94.00 | \$11,170,388 | \$2,094,448 | \$9,075,941 | | P0014, P0015 | | |
| Athletic Storage | 3210 | 0028 | 15 | 100 | 536 | \$5,990 | 1982 | | | 2003 | 49.00 | 90.00 | \$3,055 | \$599 | \$2,456 | | | | |
| Thurman "Fum" McGraw Athletic Center | 5161 | 0029 | 16 | 0 | 26,512 | \$3,784,455 | 1999 | | | 2003 | 96.00 | 94.00 | \$151,378 | \$227,067 | \$0 | | | | 8 6 |
| Student Rec. Center | 5004 | 0030 | 15 | 0 | 90,804 | \$25,733,125 | 1989 | 78 18 | | 2003 | 85.10 | 94.00 | \$3,834,236 | \$1,543,988 | \$2,290,248 | To Halling | | | |
| Tennis Court Storage | 3211 | 0031 | 15 | 100 | 45 | \$2,509 | 1999 | | | 2003 | 49.00 | 90.00 | \$1,280 | \$251 | \$1,029 | | | | |
| Weather Station | 3212 | 0032 | 11 | 100 | 350 | \$43,370 | 1989 | 19 | 9 78.0 | 5 2005 | 78.10 | 94.00 | \$9,498 | \$2,602 | \$6,896 | | | | |
| Intermural Field Restrooms | 8015 | 0033 | 15 | 0 | 558 | \$118,338 | 1997 | | | 2003 | 58.00 | 90.00 | \$49,702 | \$11,834 | \$37,868 | | | | |
| Intermural Field First Aid/Storage | 8016 | 0034 | 15 | 0 | 776 | \$13,395 | 1997 | | | 2003 | 58.00 | 90.00 | \$5,626 | \$1,340 | \$4,286 | | | | |
| Student Center | 3213 | 0040 | 40 | 0 | 295,488 | \$45,771,268 | 1961 | | | 2003 | 74.30 | 94.00 | \$11,763,216 | \$2,746,276 | \$9,016,940 | | | | |
| Engineering | 3217 | 0041 | 12 | 100 | 211,410 | \$106,236,273 | 1957 | 20 | 00 91.1 | 9 2006 | 84.30 | 94.00 | \$16,679,095 | \$6,374,176 | \$10,304,918 | | | | 1 |
| Computer Cent. Annex | 3220 | 0042 | 11 | 100 | 800 | \$24,810 | 1963 | | | 2003 | 59.00 | 90.00 | \$10,172 | \$2,481 | \$7,691 | | | | 1 |
| Statistics | 3221 | 0044 | 16 | 100 | 25,528 | \$4,880,410 | 1908 | 20 | 00 87.2 | 4 2006 | 79.70 | 94.00 | \$990,723 | \$292,825 | \$697,899 | | | | |
| Louis R. Weber | 3222 | 0045 | 11 | 100 | 55,225 | \$6,842,858 | 1922 | | | 2007 | 80.60 | 94.00 | \$1,327,514 | \$410,571 | \$916,943 | | | | |
| Music | 3224 | 0046 | 13 | 100 | 31,370 | \$3,887,141 | 1927 | 19 | 9 48.9 | | 46.60 | 94.00 | \$2,075,733 | \$233,228 | \$1,842,505 | | | M00034, M0101 | 1 |
| Ammons Hall | 3226 | 0050 | 16 | 100 | 24,467 | \$3,183,176 | 1921 | 20 | | | 86.30 | 94.00 | \$436,095 | \$190,991 | \$245.105 | | 7 | | |
| Danforth Chapel | 3227 | 0051 | 20 | 100 | 1,059 | \$659,069 | 1954 | 19 | - | | 66.80 | 94.00 | \$218,811 | \$39,544 | \$179,267 | | | | |
| Guggenheim Hall | 3228 | 0055 | 10 | 100 | 16,735 | \$1,904,833 | 1910 | 20 | | | 73.70 | 94.00 | \$500,971 | \$114,290 | \$386,681 | | | M00034 | |
| Home Management | 3229 | 0056 | 16 | 100 | 4,331 | \$402,486 | 1925 | - | 13.2 | 2003 | 64.00 | 94.00 | \$144,895 | \$24,149 | \$120,746 | | | 11100004 | - |
| Industrial Sciences | 3231 | 0058 | 14 | 100 | 28.009 | \$3,036,783 | 1884 | 20 | 75.8 | | 70.70 | 94.00 | \$889,777 | \$182,207 | \$707,570 | | | | |
| Laurel Hall | 3232 | 0059 | 30 | 100 | 14,780 | \$1,602,473 | 1884 | 20 | - | | 92.70 | 94.00 | \$116,981 | \$96,148 | \$0 | - | | | - |

| Industrial Sci. Labs | 3233 | 0060 | 14 | 100 | 20,246 | \$2,195,073 | 1925 | 1999 | 75.28 | 2005 | 67.00 | 94.00 | \$724,374 | \$131,704 | \$592,670 | | |
|---------------------------------------|------|------|----|-----|---------|--------------|------|------|--------|------|-------|-------|-------------|-------------|-------------|-------|----------------|
| Routt Hall | 3234 | 0061 | 16 | 100 | 4,918 | \$778,639 | 1890 | 2000 | 92.96 | 2006 | 84.30 | 94.00 | \$122,246 | \$46,718 | \$75,528 | | |
| Potting Shed | 3235 | 0062 | 11 | 100 | 498 | \$38,567 | 1896 | 1999 | 88.60 | 2005 | 84.30 | 90.00 | \$6,055 | \$3,857 | \$2,198 | | |
| Sage Hall | 3236 | 0063 | 11 | 100 | 7,038 | \$1,124,851 | 1896 | 2001 | 86.43 | 2007 | 80.60 | 94.00 | \$218,221 | \$67,491 | \$150,730 | | |
| Spruce Hall | 3238 | 0064 | 16 | 100 | 18,738 | \$2,031,576 | 1881 | 2000 | 86.67 | 2006 | 79.30 | 94.00 | \$420,536 | \$121,895 | \$298,642 | | |
| Occupational Therapy Annex | 3240 | 0065 | 30 | 100 | 984 | \$76,546 | 1910 | 2001 | 95.77 | 2007 | 85.20 | 94.00 | \$11,329 | \$4,593 | \$0 | | |
| Occupational Therapy | 3241 | 0066 | 10 | 100 | 22,104 | \$2,738,878 | 1919 | 1999 | 86.08 | 2005 | 79.30 | 94.00 | \$566,948 | \$164,333 | \$402,615 | | |
| . L. Gibbons | 3242 | 0067 | 14 | 100 | 14,084 | \$1,745,130 | 1905 | 2001 | 96.88 | 2007 | 87.70 | 94.00 | \$214,651 | \$104,708 | \$0 | | |
| Heating Plant | 3245 | 0068 | 30 | 100 | 19,416 | \$18,918,451 | 1915 | 2001 | 92.25 | 2007 | 85.90 | 94.00 | \$2,667,502 | \$1,135,107 | \$1,532,395 | | M00034 |
| Chilled Water Plant | 8830 | 0069 | 30 | 100 | 3,482 | \$441,510 | 1999 | | | 2003 | 97.00 | 94.00 | \$13,245 | \$26,491 | \$0 | | |
| Alder Hall | 3248 | 0071 | 10 | 100 | 6,103 | \$678,512 | 1930 | 1999 | 84.36 | 2005 | 77.00 | 94.00 | \$156,058 | \$40,711 | \$115,347 | | |
| College Avenue Gym | 3250 | 0073 | 15 | 100 | 61,877 | \$7,901,229 | 1924 | 2000 | 91.49 | 2006 | 82.90 | 94.00 | \$1,351,110 | \$474,074 | \$877,036 | | |
| /ocational Education | 3251 | 0075 | 16 | 100 | 11,491 | \$1,252,368 | 1910 | 2001 | 96.72 | 2007 | 83.40 | 94.00 | \$207,893 | \$75,142 | \$0 | | |
| Student Services | 3254 | 0076 | 16 | 100 | 36,243 | \$3,981,019 | 1948 | 1999 | 75.81 | 2005 | 74.91 | 94.00 | \$998,838 | \$238,861 | \$759,977 | P0014 | |
| Administration Annex | 3255 | 0077 | 16 | 100 | 43,145 | \$4,699,384 | 1950 | 2001 | 81.00 | 2007 | 80.20 | 94.00 | \$930,478 | \$281,963 | \$0 | | |
| Johnson Hall | 3257 | 0079 | 10 | 100 | 48,013 | \$6,188,696 | 1936 | 2000 | 77.12 | 2006 | 72.10 | 94.00 | \$1,726,646 | \$371,322 | \$1,355,324 | | |
| Administration | 3258 | 0080 | 16 | 100 | 32.172 | \$4,004,603 | 1924 | 1999 | 73.48 | 2005 | 73.10 | 94.00 | \$1,077,238 | \$240,276 | \$836,962 | | M00034 |
| Forestry | 3260 | 0081 | 10 | 100 | 27,046 | \$3,351,389 | 1937 | 2001 | 58.43 | 2007 | 65.60 | 94.00 | \$1,152,878 | \$201,083 | \$951,794 | | M00034, M01017 |
| Natural Resources | 3262 | 0082 | 10 | 100 | 73.027 | \$9,688,236 | 1975 | 1999 | 78.25 | 2005 | 70.90 | 94.00 | \$2,819,277 | \$581,294 | \$2,237,983 | | |
| Nat Resource Res Lab | 3263 | 0083 | 16 | 100 | 4,000 | \$495,651 | 1968 | | | 2005 | 48.50 | 94.00 | \$255,260 | \$29,739 | \$225,521 | | |
| V.K. Wagar | 3264 | 0084 | 11 | 100 | 48,160 | \$7,162,972 | 1939 | 2001 | 81.20 | 2007 | 76.30 | 94.00 | \$1,697,624 | \$429,778 | \$1,267,846 | | M00032 |
| Ingineering South/Glover | 3269 | 0088 | 12 | 100 | 52,823 | \$9.017.573 | 1950 | 2001 | 88.20 | 2007 | 81.10 | 94.00 | \$1,704,321 | \$541,054 | \$1,163,267 | | |
| Morgan Library | 3275 | 0090 | 17 | 100 | 299,584 | \$39,243,437 | 1964 | 2001 | 94.08 | 2007 | 82.60 | 94.00 | \$6,828,358 | \$2,354,606 | \$0 | P0014 | |
| Andrew G. Clark | 3276 | 0091 | 10 | 100 | 254,792 | \$27,624,115 | 1967 | 1999 | 68.33 | 2005 | 65.50 | 94.00 | \$9,530,320 | \$1,657,447 | \$7,872,873 | | |
| Plant Sciences | 3278 | 0092 | 11 | 100 | 82,725 | \$11,532,097 | 1959 | 2001 | 94.67 | 2007 | 91.60 | 94.00 | \$968,696 | \$691,926 | \$276,770 | P0017 | |
| Shepardson | 3281 | 0093 | 10 | 100 | 47,354 | \$6,601,280 | 1939 | 2001 | 58.61 | 2007 | 54.30 | 94.00 | \$3,016,785 | \$396,077 | \$2,620,708 | P0014 | M01012 |
| Military Sciences | 3282 | 0094 | 10 | 100 | 13.814 | \$1,497,737 | 1927 | 1999 | 48.75 | 2005 | 47.20 | 94.00 | \$790,805 | \$89,864 | \$700,941 | | |
| Ailitary Annex | 3284 | 0095 | 10 | 100 | 6,730 | \$521,191 | 1927 | 2001 | 28.08 | 2007 | 62.70 | 94.00 | \$194,404 | \$31,271 | \$163,133 | | |
| Iammable Liquids | 3286 | 0099 | 30 | 100 | 160 | \$14,108 | 1977 | | | 2003 | 69.00 | 90.00 | \$4,373 | \$1,411 | \$2,963 | | |
| General Services Bld | 3287 | 0102 | 16 | 0 | 74,907 | \$11,653,831 | 1948 | 1999 | 72.25 | 2005 | 63.60 | 94.00 | \$4,241,994 | \$699,230 | \$3,542,765 | | |
| facilities Svc-North | 3294 | 0104 | 16 | 100 | 31,566 | \$3,422,525 | 1957 | 2000 | 77.49 | 2006 | 67.20 | 94.00 | \$1,122,588 | \$205,352 | \$917,237 | | |
| nsectary | 3296 | 0105 | 11 | 100 | 4,313 | \$534,435 | 1967 | 2000 | 71,44 | 2006 | 74.70 | 94.00 | \$135,212 | \$32,066 | \$103,146 | | M00034 |
| Madison Macdonald Observatory | 3297 | 0106 | 11 | 100 | 687 | \$159,620 | 1965 | 2001 | 88.44 | 2007 | 78.20 | 94.00 | \$34,797 | \$9,577 | \$25,220 | | |
| Veed Research Laboratory | 3298 | 0107 | 11 | 100 | 17,329 | \$1,878,812 | 1964 | 2001 | 71.89 | 2007 | 63.80 | 94.00 | \$680,130 | \$112,729 | \$567,401 | | |
| Jniv. Greenhouses | 3302 | 0108 | 11 | 100 | 42.614 | \$4,620,214 | 1960 | 2000 | 50.66 | 2006 | 83.20 | 94.00 | \$776,196 | \$277,213 | \$498,983 | | M90026 |
| Natural & Environmental Services Bldg | 7334 | 0109 | 11 | 100 | 77,000 | \$12,928,169 | 1994 | 2000 | 86.73 | 2006 | 82.00 | 94.00 | \$2,327,070 | \$775,690 | \$1,551,380 | | |
| nimal Sciences | 3305 | 0110 | 11 | 100 | 40,412 | \$5,633,582 | 1959 | 2001 | 59.39 | 2007 | 61,00 | 94.00 | \$2,197,097 | \$338,015 | \$1,859,082 | P0014 | M01012 |
| nst Serv Maint Shop | 3307 | 0111 | 30 | 100 | 220 | \$128,244 | 1989 | | | 2003 | 64.00 | 94.00 | \$46,168 | \$7,695 | \$38,473 | | |
| Villard O. Eddy Hall | 3308 | 0113 | 10 | 100 | 69,457 | \$7,530,410 | 1963 | 2001 | 79.56 | 2007 | 73.70 | 94.00 | \$1,980,498 | \$451,825 | \$1,528,673 | | |
| Education | 3309 | 0114 | 10 | 100 | 40,931 | \$5,071,940 | 1964 | 2000 | 82.80 | 2006 | 75.90 | 94.00 | \$1,222,338 | \$304,316 | \$918,021 | | |
| Aicrobiology | 3310 | 0120 | 11 | 100 | 85,131 | \$15,009,081 | 1968 | 2001 | 82.03 | 2007 | 77.00 | 94.00 | \$3,452,089 | \$900,545 | \$2,551,544 | | |
| Stock Judging Pav. | 3311 | 0121 | 11 | 100 | 9.376 | \$726,075 | 1960 | 2000 | | 2006 | 73.50 | 94.00 | \$192,410 | \$43,565 | \$148,845 | | |
| Notor Pool Storage | 3313 | 0123 | 30 | 100 | 268 | \$5,237 | 1984 | | | 2003 | 49.00 | 90.00 | \$2,671 | \$524 | \$2,147 | | |
| ehicle Maintenance | 3314 | 0124 | 30 | 100 | 1,860 | \$74,136 | 1984 | | | 2003 | 59.00 | 94.00 | \$30,396 | \$4,448 | \$25,948 | | |
| acilities Svc-South | 3315 | 0125 | 30 | 100 | 12,194 | \$1,133,207 | 1957 | 1999 | 74.02 | 2005 | 71.30 | 94.00 | \$325,230 | \$67,992 | \$257,238 | | |
| ast Garages | 3317 | 0126 | 30 | 100 | 3,572 | \$66,303 | 1927 | | | 2003 | 49.00 | 90.00 | \$33,815 | \$6,630 | \$27,184 | | |
| lectric Shop | 3318 | 0127 | 30 | 100 | 2,088 | \$162,439 | 1957 | | | 2003 | 49.00 | 94.00 | \$82,844 | \$9,746 | \$73,098 | | |
| acilities Storage | 3320 | 0129 | 30 | 100 | 9,249 | \$286,780 | 1027 | | 100.53 | 2003 | 49.00 | 90.00 | \$146,258 | \$28,678 | \$117,580 | | |
| ehicle Wash | 3321 | 0130 | 30 | 100 | 836 | \$38.845 | 1964 | | | 2003 | 59.00 | 90.00 | \$15,926 | \$3,885 | \$12,042 | | |
| entral Receiving | 3322 | 0131 | 30 | 100 | 15.675 | \$1,456,689 | 1967 | 2001 | 83.42 | 2007 | 75.30 | 94.00 | \$359,802 | \$87,401 | \$272,401 | | |

| Central Rec. Storage | 3324 | 0132 | 30 | 100 | 4,203 | \$130,321 | 1927 | 2001 | 65.20 | 2007 | 60.00 | 90.00 | \$52,128 | \$13,032 | \$39,096 | | T |
|------------------------------|------|------|----|-----|---------|-----------------------------|--------------|------|----------------|------|-------|-------|-------------|-------------|-------------|-------------|----------------|
| Hazardous Waste | 3325 | 0133 | 30 | 100 | 910 | \$212,370 | 1983 | 2000 | 88.04 | 2007 | 88.04 | 90.00 | \$25,399 | \$13,032 | | | |
| Hazardous Waste | 3326 | 0134 | 30 | 100 | 2,500 | \$55,762 | 1984 | 2000 | 86.62 | 2003 | 86.62 | 90.00 | | | \$4,162 | | |
| Chemical Storage Unit | 7935 | 0135 | 31 | 100 | 144 | \$56,788 | 1998 | 2000 | 00.02 | 2003 | 65.00 | 90.00 | \$7,461 | \$5,576 | \$1,885 | | |
| Central Rec. Storage | 3328 | 0136 | 30 | 100 | 4.042 | \$68,851 | 1975 | 2001 | 81.26 | 2003 | 74.20 | 90.00 | \$19,876 | \$5,679 | \$14,197 | | |
| Book Storage Folty | 3329 | 0137 | 29 | 100 | 28,000 | \$722,918 | 1985 | 2000 | 88.39 | 2007 | | | \$17,764 | \$6,885 | \$10,878 | | |
| MC Substation | 7175 | 0137 | 30 | 100 | 546 | \$588,919 | - | 2000 | 00.39 | - | 87.00 | 94.00 | \$93,979 | \$43,375 | \$50,604 | | |
| Pathology | 3330 | 0140 | 11 | 100 | 58,902 | | 1967 | 2004 | 02.52 | 2003 | 55.00 | 90.00 | \$265,014 | \$58,892 | \$206,122 | | |
| Environmental Health | 3332 | 0140 | 11 | 100 | 18.173 | \$8,417,079 \$2,251,865 | 1976 1970 | 2001 | 83.53 | 2007 | 78.30 | 94.00 | \$1,826,506 | \$505,025 | \$1,321,481 | P0014 | |
| Physiology | 3336 | 0141 | 11 | 100 | 64,740 | \$10,027,883 | 1966 | 2001 | 73.56 68.64 | 2007 | 73.70 | 94.00 | \$592,240 | \$135,112 | \$457,129 | | |
| Anatomy-Zoology | 3337 | 0142 | 11 | | 148,437 | \$23,095,832 | | 2000 | - | - | 67.50 | 94.00 | \$3,259,062 | \$601,673 | \$2,657,389 | | M01012 |
| Painter Center | 3338 | 0143 | 11 | 100 | 31,139 | | 1973 | | 80.95 | 2006 | 74.60 | 94.00 | \$5,866,341 | \$1,385,750 | \$4,480,591 | P0014, P011 | 3 |
| Albert C. Yates Hall | 3336 | 0144 | 11 | 100 | 87,841 | \$4,257,642 \$20,283,901 | 2002 | 1999 | 84.34 | 2008 | 94.00 | 94.00 | \$830,240 | \$255,459 | \$574,782 | | |
| Chemistry | 3339 | 0145 | 11 | - | 168,037 | | 1971 | 1000 | 70.00 | - | | | \$1,217,034 | \$1,217,034 | \$0 | | |
| | | | | 100 | | \$31,230,735 | | 1999 | 76.96 | 2008 | 71.20 | 94.00 | \$8,994,452 | \$1,873,844 | \$7,120,608 | P9909 | |
| Visual Arts Gifford | 3341 | 0151 | 13 | 100 | 91,997 | \$9,302,663 | 1973 | 2000 | 77.64 | 2006 | 76.70 | 94.00 | \$2,167,520 | \$558,160 | \$1,609,361 | | |
| Mol. & Rad. Biosci. | 3343 | 0152 | 10 | 100 | 92,278 | \$9,650,193 | 1975 | 2001 | 73.61 | 2007 | 73.20 | 94.00 | \$2,586,252 | \$579,012 | \$2,007,240 | P0014 | M00034, M90023 |
| | 5003 | 0155 | 11 | 100 | 87,670 | \$17,932,486 | 1989 | 2000 | 92.15 | 2006 | 89.20 | 94.00 | \$1,936,708 | \$1,075,949 | \$860,759 | P0014 | |
| Hort. Storage Shed | 3344 | 0172 | 31 | 100 | 1,156 | \$24,457 | 1976 | | | 2003 | 49.00 | 90.00 | \$12,473 | \$2,446 | \$10,027 | | |
| Horticulture Garage | 3345 | 0173 | 31 | 100 | 768 | \$47,600 | 1976 | | | 2003 | 49.00 | 90.00 | \$24,276 | \$4,760 | \$19,516 | | |
| Greenhouse | 3348 | 0184 | 11 | 100 | 960 | \$14,883 | 1976 | | | 2003 | 49.00 | 94.00 | \$7,590 | \$893 | \$6,697 | | |
| Greenhouse No. 6 | 3354 | 0191 | 11 | 100 | 264 | \$12,267 | 1971 | | | 2003 | 39.00 | 94.00 | \$7,483 | \$736 | \$6,747 | | |
| Greenhouse No. 7 | 3355 | 0192 | 11 | 100 | 264 | \$12,267 | 1971 | | | 2003 | 39.00 | 94.00 | \$7,483 | \$736 | \$6,747 | | |
| Greenhouse | 3356 | 0193 | 11 | 100 | 1,105 | \$85,574 | 1960 | | | 2003 | 39.00 | 94.00 | \$52,200 | \$5,134 | \$47,066 | | |
| Hort. Quonset-North | 3357 | 0194 | 14 | 100 | 3,099 | \$239,986 | 1954 | | | 2003 | 39.00 | 94.00 | \$146,391 | \$14,399 | \$131,992 | | |
| Hort. Quonset-South | 3358 | 0195 | 14 | 100 | 3,188 | \$246,878 | 1954 | | | 2003 | 39.00 | 94.00 | \$150,596 | \$14,813 | \$135,783 | | |
| Lake St. Greenhouses | 3359 | 0196 | 11 | 100 | 19,398 | \$1,502,237 | 1949 | 2001 | 58.75 | 2007 | 51.70 | 94.00 | \$725,580 | \$90,134 | \$635,446 | | |
| Greenhouse | 3361 | 0197 | 11 | 100 | 960 | \$14,883 | 1976 | | | 2003 | 49.00 | 94.00 | \$7,590 | \$893 | \$6,697 | | |
| Greenhouse | 3362 | 0198 | 11 | 100 | 960 | \$14,883 | 1976 | | 1 1 1 1 | 2003 | 49.00 | 94.00 | \$7,590 | \$893 | \$6,697 | | |
| Aggie Vill North 1 | 3364 | 0201 | 51 | 0 | 2,568 | \$198,865 | 1961 | | | 2003 | 88.00 | 94.00 | \$23,864 | \$11,932 | \$11,932 | | |
| Aggie Vill North 2 | 3365 | 0202 | 51 | 0 | 8,264 | \$639,962 | 1961 | | | 2003 | 88.00 | 94.00 | \$76,795 | \$38,398 | \$38,398 | | 7 |
| Aggie Vill North 3 | 3366 | 0203 | 51 | 0 | 2,568 | \$198,865 | 1961 | | | 2003 | 88.00 | 94.00 | \$23,864 | \$11,932 | \$11,932 | | |
| University Children's Center | 3367 | 0204 | 60 | 0 | 3,083 | \$238,747 | 1961 | | | 2003 | 88.00 | 94.00 | \$28,650 | \$14,325 | \$14,325 | | |
| Aggie Vill North 5 | 3368 | 0205 | 51 | 0 | 8,264 | \$639,962 | 1961 | | | 2003 | 88.00 | 94.00 | \$76,795 | \$38,398 | \$38,398 | | |
| Aggie Vill North 6 | 3369 | 0206 | 51 | 0 | 8,264 | \$639,962 | 1961 | | | 2003 | 88.00 | 94.00 | \$76,795 | \$38,398 | \$38,398 | | |
| Aggie Vill North 7 | 3370 | 0207 | 51 | 0 | 8,264 | \$639,962 | 1961 | | | 2003 | 88.00 | 94.00 | \$76,795 | \$38,398 | \$38,398 | | |
| Aggie Vill North 8 | 3371 | 0208 | 51 | 0 | 8,264 | \$639,988 | 1961 | | | 2003 | 88.00 | 94.00 | \$76,799 | \$38,399 | \$38,399 | | |
| Aggie Vill North 9 | 3372 | 0209 | 51 | 0 | 3,855 | \$298,530 | 1961 | | | 2003 | 88.00 | 94.00 | \$35,824 | \$17,912 | \$17,912 | | |
| Aggie Vill North 10 | 3373 | 0210 | 51 | 0 | 8,264 | \$639,962 | 1961 | | | 2003 | 88.00 | 94.00 | \$76,795 | \$38,398 | \$38,398 | | |
| Aggie Vill North 11 | 3374 | 0211 | 51 | 0 | 8,264 | \$639,962 | 1961 | | | 2003 | 88.00 | 94.00 | \$76,795 | \$38,398 | \$38,398 | | |
| Aggie Vill North 12 | 3375 | 0212 | 51 | 0 | 8,264 | \$639,962 | 1961 | | | 2003 | 88.00 | 94.00 | \$76,795 | \$38,398 | \$38,398 | | |
| Aggie Vill North 13 | 3376 | 0213 | 51 | 0 | 8,264 | \$639,962 | 1961 | | | 2003 | 88.00 | 94.00 | \$76,795 | \$38,398 | \$38,398 | | |
| Aggie Vill North 14 | 3377 | 0214 | 51 | 0 | 2,568 | \$198,865 | 1961 | | | 2003 | 88.00 | 94.00 | \$23,864 | \$11,932 | \$11,932 | | |
| Aggie Vill North 15 | 3378 | 0215 | 51 | 0 | 2,568 | \$198,865 | 1961 | | | 2003 | 88.00 | 94.00 | \$23,864 | \$11,932 | \$11,932 | | |
| Aggie Vill North 16 | 3379 | 0216 | 51 | 0 | 8,264 | \$639,962 | 1961 | | | 2003 | 88.00 | 94.00 | \$76,795 | \$38,398 | \$38,398 | | |
| Aggie Vill North 17 | 3380 | 0217 | 51 | 0 | 2,568 | \$198,865 | 1961 | | | 2003 | 88.00 | 94.00 | \$23,864 | \$11,932 | \$11,932 | | |
| Aggie Vill North 6s | 3384 | 0221 | 51 | 0 | 135 | \$10,454 | 1961 | | | 2003 | 88.00 | 94.00 | \$1,254 | \$627 | \$627 | | |
| Aggie Vill North 7s | 3386 | 0223 | 51 | 0 | 135 | \$10,454 | 1961 | | | 2003 | 88.00 | 94.00 | \$1,254 | \$627 | \$627 | | |
| Aggie Vill North 11s | 3392 | 0229 | 51 | 0 | 135 | \$10,454 | 1961 | | | 2003 | 88.00 | 94.00 | \$1,254 | \$627 | \$627 | | |
| Aggie Vill North 12s | 3394 | 0231 | 51 | 0 | 135 | \$10,454 | 1961 | | | 2003 | 88.00 | 94.00 | \$1,254 | \$627 | \$627 | | |
| Aggie Vill South 18 | 3399 | 0301 | 51 | 0 | 2,559 | \$198,168 | 1964 | | | 2003 | 89.00 | 94.00 | \$21,798 | \$11,890 | \$9,908 | | |

| | 1 2 400 | | | | 0.550 | 0100 100 | 1 1001 | | | | 00.00 | | 1 201 700 | 244.000 | | | | |
|-------------------------------------|---------|------|----|-----|---------|--------------|--------|------|-------|-------|--------|-------|-------------|-------------|-------------|----------------|-------------|---|
| Aggie Vill South 19 | 3400 | 0302 | 51 | 0 | 2,559 | \$198,168 | 1964 | | | 2003 | 89.00 | 94.00 | \$21,798 | \$11,890 | \$9,908 | | | |
| Aggie Vill South 20 | 3401 | 0303 | 51 | 0 | 8,234 | \$637,638 | 1964 | | | 2003 | 89.00 | 94.00 | \$70,140 | \$38,258 | \$31,882 | | | - |
| Aggie Vill South 21 | 3402 | 0304 | 51 | 0 | 2,559 | \$167,168 | 1964 | | | 2003 | 89.00 | 94.00 | \$18,388 | \$10,030 | \$8,358 | | | |
| Aggie Vill South 22 | 3403 | 0305 | 51 | 0 | 8,234 | \$637,638 | 1964 | | | 2003 | 89.00 | 94.00 | \$70,140 | \$38,258 | \$31,882 | | | |
| Aggie Vill South 23 | 3404 | 0306 | 51 | 0 | 8,234 | \$637,638 | 1964 | | | 2003 | 89.00 | 94.00 | \$70,140 | \$38,258 | \$31,882 | | | |
| Aggie Vill South 24 | 3405 | 0307 | 51 | 0 | 3,281 | \$254,080 | 1964 | | | 2003 | 88.00 | 94.00 | \$30,490 | \$15,245 | \$15,245 | | | |
| Aggie Vill South 25 | 3407 | 0308 | 51 | 0 | 8,234 | \$637,638 | 1964 | | | 2003 | 89.00 | 94.00 | \$70,140 | \$38,258 | \$31,882 | | | |
| Aggie Vill South 26 | 3408 | 0309 | 51 | 0 | 8,234 | \$637,638 | 1964 | | | 2003 | 89.00 | 94.00 | \$70,140 | \$38,258 | \$31,882 | | | |
| Aggie Vill South 27 | 3409 | 0310 | 51 | 0 | 8,234 | \$637,638 | 1964 | | 1 | 2003 | 89.00 | 94.00 | \$70,140 | \$38,258 | \$31,882 | | | |
| Aggie Vill South 28 | 3410 | 0311 | 51 | 0 | 8,234 | \$637,638 | 1964 | | | 2003 | 89.00 | 94.00 | \$70,140 | \$38,258 | \$31,882 | | | |
| Aggie Vill South 29 | 3411 | 0312 | 51 | 0 | 8,234 | \$637,638 | 1964 | | | 2003 | 89.00 | 94.00 | \$70,140 | \$38,258 | \$31,882 | | | |
| Aggie Vill South 30 | 3412 | 0313 | 51 | 0 | 8,234 | \$637,638 | 1964 | | | 2003 | 89.00 | 94.00 | \$70,140 | \$38,258 | \$31,882 | | | |
| Aggie Vill South 31 | 3413 | 0314 | 51 | 0 | 2,559 | \$198,168 | 1964 | | | 2003 | 89.00 | 94.00 | \$21,798 | \$11,890 | \$9,908 | | | |
| Aggie Vill South 32 | 3414 | 0315 | 51 | 0 | 8,234 | \$637,638 | 1964 | | | 2003 | 89.00 | 94.00 | \$70,140 | \$38,258 | \$31,882 | | | |
| Aggie Vill South 33 | 3415 | 0316 | 51 | 0 | 2,559 | \$198,168 | 1964 | | | 2003 | 89.00 | 94.00 | \$21,798 | \$11,890 | \$9,908 | | | |
| Aggie Vill South 34 | 3416 | 0317 | 51 | 0 | 2,559 | \$198,168 | 1964 | | | 2003 | 89.00 | 94.00 | \$21,798 | \$11,890 | \$9,908 | | | |
| S. Aggie Mail Kiosk | 7180 | 0318 | 60 | 0 | 109 | \$22,082 | 1992 | | | 2003 | 89.00 | 94.00 | \$2,429 | \$1,325 | \$1,104 | | | |
| Storage | 3439 | 0422 | 31 | 100 | 402 | \$12,467 | 1964 | | | 2003 | 49.00 | 90.00 | \$6,358 | \$1,247 | \$5,111 | | | |
| Storage | 3440 | 0423 | 31 | 100 | 1,579 | \$48,969 | 1964 | | | 2003 | 49.00 | 90.00 | \$24,974 | \$4,897 | \$20,077 | | | |
| Ground Storage | 5127 | 0425 | 31 | 100 | 634 | \$8,970 | 1995 | | | 2003 | 49.00 | 90.00 | \$4,575 | \$897 | \$3,678 | | | |
| Pump House | 3441 | 0431 | 31 | 100 | 49 | \$1,519 | 1964 | | | 2003 | 49.00 | 90.00 | \$775 | \$152 | \$623 | | | |
| Mary and Robert Flint Cancer Center | 9400 | 0550 | 41 | 100 | 35,217 | \$8,406,323 | 2002 | | | 2003 | 100.00 | 94.00 | \$0 | \$504,379 | \$0 | | | |
| VTH - Feed Storage | 7940 | 0551 | 31 | 100 | 140 | \$1,415 | 1998 | | | 2003 | 49.00 | 90.00 | \$722 | \$142 | \$580 | | | |
| Isolation Barn | 3443 | 0553 | 41 | 100 | 2,109 | \$183,232 | 1979 | 2000 | 75.39 | 2005 | 69.90 | 94.00 | \$55,153 | \$10,994 | \$44,159 | | | |
| Horse Barn and Animal Food Barn | 3444 | 0554 | 41 | 100 | 45,194 | \$3,926,495 | 1979 | 2000 | 77.46 | 2008 | 71.00 | 94.00 | \$1,138,684 | \$235,590 | \$903,094 | | | |
| Vet. Teaching Hosp. | 3445 | 0555 | 41 | 100 | 137,233 | \$23,847,719 | 1979 | 2000 | 78.40 | 2006 | 72.10 | 94.00 | \$6,653,514 | \$1,430,863 | \$5,222,650 | | M01016 | |
| Canine/Raptor | 3446 | 0556 | 41 | 100 | 3,632 | \$812,599 | 1981 | 2000 | 83.98 | 2005 | 80.60 | 94.00 | \$157,644 | \$48,756 | \$108,888 | | | |
| Dairy Center | 3448 | 0557 | 31 | 100 | 91,157 | \$2,063,056 | 1981 | 2000 | 75.47 | 2007 | 76.50 | 94.00 | . \$484,818 | \$123,783 | \$361,035 | | | |
| Maintenance Garage | 3449 | 0558 | 29 | 100 | 1,212 | \$52,067 | 1981 | 2000 | 83.51 | 2007 | 76.60 | 94.00 | \$12,184 | \$3,124 | \$9,060 | | | |
| Storage | 3450 | 0559 | 31 | 100 | 2,125 | \$39,444 | 1957 | | | 2003 | 49.00 | 90.00 | \$20,116 | \$3,944 | \$16,172 | | | |
| Storage | 3451 | 0560 | 31 | 100 | 2,125 | \$39,444 | 1957 | | | 2003 | 49.00 | 90.00 | \$20,116 | \$3,944 | \$16,172 | | | |
| Solids Separator | 3452 | 0561 | 31 | 100 | 400 | \$17,185 | 1981 | | | 2003 | 49.00 | 90.00 | \$8,764 | \$1,719 | \$7,046 | | | |
| Storage | 3453 | 0562 | 31 | 100 | 2,125 | \$39,444 | 1957 | | | .2003 | 49.00 | 90.00 | \$20,116 | \$3,944 | \$16,172 | | | |
| Gail Holmes Orthopedic Research lab | | 0563 | 31 | 100 | 14,507 | \$1,521,912 | 2002 | | | 2003 | 100.00 | 94.00 | \$0 | \$91,315 | \$0 | | | |
| Hay Shed | 3456 | 0565 | 31 | 100 | 3,684 | \$134,641 | 1957 | | | 2003 | 49.00 | 90.00 | \$68,667 | \$13,464 | \$55,203 | | | |
| Hay Shed | 3457 | 0566 | 31 | 100 | 3,684 | \$114,250 | 1957 | | | 2003 | 49.00 | 90.00 | \$58,268 | \$11,425 | \$46,843 | | | |
| Hay Shed | 3458 | 0567 | 31 | 100 | 8,500 | \$116,610 | 1981 | | | 2003 | 49.00 | 90.00 | \$59,471 | \$11,661 | \$47,810 | | | |
| Hay Shed | 3459 | 0568 | 31 | 100 | 8,500 | \$116,610 | 1981 | | | 2003 | 49.00 | 90.00 | \$59,471 | \$11,661 | \$47,810 | | | |
| Digester Building | 3460 | 0569 | 31 | 100 | 2,990 | \$210,776 | 1983 | | | 2003 | 49.00 | 90.00 | \$107,496 | \$21,078 | \$86,418 | | | |
| Settling Tank | 3461 | 0570 | 31 | 100 | 930 | \$13,514 | 1983 | | 1 | 2003 | 49.00 | 90.00 | \$6,892 | \$1,351 | \$5,541 | | | |
| Grain Bin | 3462 | 0571 | 31 | 100 | 257 | \$4,550 | 1984 | | | 2003 | 49.00 | 90.00 | \$2,321 | \$455 | \$1,866 | | | |
| Grain Bin | 3463 | 0572 | 31 | 100 | 257 | \$4,550 | 1984 | | | 2003 | 49.00 | 90.00 | \$2,321 | \$455 | \$1,866 | | | |
| Grain Bin | 3464 | 0573 | 31 | 100 | 257 | \$4,550 | 1984 | | | 2003 | 49.00 | 90.00 | \$2,321 | \$455 | \$1,866 | | | |
| Animal Shelter | 3465 | 0574 | 31 | 100 | 913 | \$15,008 | 1985 | | | 2003 | 49.00 | 90.00 | \$7,654 | \$1,501 | \$6,153 | | | |
| Animal Shelter | 3466 | 0575 | 31 | 100 | 913 | \$15,008 | 1985 | | | 2003 | 49.00 | 90.00 | \$7,654 | \$1,501 | \$6,153 | | | |
| Animal Shelter | 3467 | 0576 | 31 | 100 | 1,408 | \$23,152 | 1985 | | | 2003 | 49.00 | 90.00 | \$11,808 | \$2,315 | \$9,492 | | | |
| Pump House | 3468 | 0577 | 31 | 100 | 462 | \$13,488 | 1979 | | | 2003 | 49.00 | 90.00 | \$6,879 | \$1,349 | \$5,530 | | | |
| Lrg.Anim.Rehab.Unit | 3469 | 0578 | 41 | 100 | 3,900 | \$158,961 | 1986 | | | 2003 | 74.00 | 94.00 | \$41,330 | \$9,538 | \$31,792 | To discontinue | | |
| Animal Shelter | 7323 | 0579 | 31 | 100 | 900 | \$9,806 | 1993 | | | 2003 | 49.00 | 90.00 | \$5,001 | \$981 | \$4,020 | | | |
| | | | | | | | | | | | | | | | | | | |

| Hazardous Chemical Storage | 7961 | 0581 | 31 | 100 | 257 | \$48,003 | 1999 | | | | 2003 | 70.00 | 90.00 | \$14,401 | \$4,800 | \$9,601 | | | |
|--|------|------|----|-----|---------|--------------|-------|----|------|-------|------|-------|-------|--------------|-------------|--------------|--------|---|----|
| Old Fort Collins High School | 4239 | 0601 | 10 | 100 | 143,399 | \$28,841,562 | 1926 | ## | 2000 | 58.75 | 2006 | 48.80 | 94.00 | \$14,766,880 | \$1,730,494 | \$13,036,386 | P0013 | | |
| Old Fort Collins High School - Annex | 4240 | 0602 | 16 | 100 | 18,025 | \$2,720,241 | 1957 | ## | 2000 | 74.69 | 2006 | 78.50 | 94.00 | \$584,852 | \$163,214 | \$421,637 | 1,0010 | | |
| Old Fort Collins High School - Classroom | 4241 | 0603 | 10 | 100 | 1,083 | \$60,401 | 1957 | ## | | | 2003 | 74.00 | 94.00 | \$15,704 | \$3,624 | \$12,080 | | | |
| Old Fort Collins High School - Storage | 4242 | 0604 | 30 | 100 | 370 | \$10,133 | 1957 | ## | | | 2003 | 65.00 | 90.00 | \$3,547 | \$1,013 | \$2,533 | | | + |
| Old Fort Collins High School - Lawn Shed | 4238 | 0606 | 31 | 100 | 1,874 | \$64,558 | 1997 | ## | | | 2003 | 49.00 | 90.00 | \$32,925 | \$6,456 | \$26,469 | | | + |
| Natural Resource Research Center A | 5162 | 0701 | 16 | 0 | 123,253 | \$13,884,241 | 1999 | | | 2.00 | 2003 | 99.00 | 94.00 | \$138,842 | \$833,054 | \$0 | | | + |
| Natural Resource Research Center B | | 0702 | 16 | 0 | 121,012 | \$16,393,592 | 2002 | | | | 2003 | 99.00 | 94.00 | \$163,936 | \$983,616 | \$0 | | | - |
| Univ Village East 1 | 3470 | 0801 | 51 | 0 | 10,764 | \$733,415 | 1968 | | | | 2003 | 84.00 | 94.00 | \$117,346 | \$44,005 | \$73,342 | | | |
| Univ Village East 2 | 3471 | 0802 | 51 | 0 | 9,227 | \$628,690 | 1968 | | | | 2003 | 84.00 | 94.00 | \$100,590 | \$37,721 | \$62,869 | | | |
| Univ Village East 3 | 3472 | 0803 | 51 | 0 | 6,401 | \$436,138 | 1968 | | | | 2003 | 84.00 | 94.00 | \$69,782 | \$26,168 | \$43,614 | | | |
| Univ Village East 4 | 3473 | 0804 | 51 | 0 | 6,151 | \$419,104 | 1968 | | | | 2003 | 84.00 | 94.00 | \$67,057 | \$25,146 | \$41,910 | | - | |
| Univ Village East 5 | 3474 | 0805 | 51 | 0 | 6,151 | \$419,104 | 1968 | | | | 2003 | 84.00 | 94.00 | \$67,057 | \$25,146 | \$41,910 | | | |
| Univ Village East 6 | 3475 | 0806 | 51 | 0 | 12,302 | \$838,208 | 1968 | | 7.13 | | 2003 | 84.00 | 94.00 | \$134,113 | \$50,292 | \$83,821 | | | |
| Univ Village East 7 | 3476 | 0807 | 51 | 0 | 6,366 | \$433,753 | 1968 | | | | 2003 | 84.00 | 94.00 | \$69,400 | \$26,025 | \$43,375 | | | |
| Univ Village East 8 | 3477 | 0808 | 51 | 0 | 10,764 | \$733,415 | 1968 | | | | 2003 | 84.00 | 94.00 | \$117,346 | \$44,005 | \$73,342 | | | |
| Univ Village East 9 | 3478 | 0809 | 51 | 0 | 2,262 | \$154,123 | 1968 | | | | 2003 | 87.00 | 94.00 | \$20,036 | \$9,247 | \$10,789 | | | |
| Univ Village East 10 | 3479 | 0810 | 51 | 0 | 6,151 | \$419,104 | 1968 | | 100 | | 2003 | 84.00 | 94.00 | \$67.057 | \$25,146 | \$41,910 | | | |
| Univ Village East 11 | 3480 | 0811 | 51 | 0 | 7,689 | \$523,897 | 1968 | 1 | | | 2003 | 84.00 | 94.00 | \$83,824 | \$31,434 | \$52,390 | | | |
| Univ Village East 12 | 3481 | 0812 | 51 | 0 | 9,441 | \$643,271 | 1968 | | | | 2003 | 84.00 | 94.00 | \$102,923 | \$38,596 | \$64,327 | | | |
| Univ Village East 13 | 3482 | 0813 | 51 | 0 | 9,227 | \$628,690 | 1968 | | | | 2003 | 84.00 | 94.00 | \$100,590 | \$37.721 | \$62,869 | | | |
| Univ Village East 14 | 3483 | 0814 | 51 | 0 | 6,366 | \$433,753 | 1968 | 1 | | | 2003 | 84.00 | 94.00 | \$69,400 | \$26,025 | \$43,375 | | | 1 |
| Univ Village East 15 | 3484 | 0815 | 51 | 0 | 9,227 | \$628,690 | 1968 | | | | 2003 | 84.00 | 94.00 | \$100,590 | \$37,721 | \$62,869 | | | |
| Univ Village West 16 | 3485 | 0816 | 51 | 0 | 6,572 | \$447,789 | 1974 | | | | 2003 | 95.00 | 94.00 | \$22,389 | \$26,867 | \$0 | | | |
| Univ Village West 17 | 3486 | 0817 | 51 | 0 | 6,543 | \$445,813 | 1974 | | | | 2003 | 95.00 | 94.00 | \$22,291 | \$26,749 | \$0 | | | |
| Univ Village West 18 | 3487 | 0818 | 51 | 0 | 8,171 | \$556,738 | 1974 | | | | 2003 | 95.00 | 94.00 | \$27,837 | \$33,404 | \$0 | _ | 4 | |
| Univ Village West 19 | 3488 | 0819 | 51 | 0 | 11,896 | \$810,545 | 1974 | | | | 2003 | 95.00 | 94.00 | \$40,527 | \$48,633 | \$0 | | | |
| Univ Village West 20 | 3489 | 0820 | 51 | 0 | 11,891 | \$810,545 | 1974 | - | | | 2003 | 95.00 | 94.00 | \$40,527 | \$48,633 | \$0 | | | |
| Univ Village West 21 | 3490 | 0821 | 51 | 0 | 6,553 | \$446,495 | 1974 | 1 | | | 2003 | 95.00 | 94.00 | \$22,325 | \$26,790 | \$0 | | | |
| Univ Village West 22 | 3491 | 0822 | 51 | 0 | 4,915 | \$334,888 | 1974 | - | | | 2003 | 95.00 | 94.00 | \$16,744 | \$20,093 | \$0 | | | |
| Univ Village West 23 | 3492 | 0823 | 51 | 0 | 8,179 | \$557,284 | 1974 | - | | | 2003 | 95.00 | 94.00 | \$27.864 | \$33,437 | \$0 | | | |
| Univ Village West 24 | 3493 | 0824 | 51 | 0 | 9,825 | \$669,435 | 1974 | 1 | | | 2003 | 95.00 | 94.00 | \$33,472 | \$40,166 | \$0 | | | |
| Univ Village West 25 | 3494 | 0825 | 51 | 0 | 9,836 | \$670,185 | 1974 | | | | 2003 | 95.00 | 94.00 | \$33,509 | \$40,211 | \$0 | | | |
| Univ Village West 26 | 3495 | 0826 | 51 | 0 | 11,887 | \$809,931 | 1974 | | | | 2003 | 95.00 | 94.00 | \$40,497 | \$48,596 | \$0 | | | |
| Univ Village West 27 | 3496 | 0827 | 51 | 0 | 11,468 | \$781,383 | 1974 | | | | 2003 | 95.00 | 94.00 | \$39,069 | \$46,883 | \$0 | | | |
| Univ Village West 28 | 3497 | 0828 | 51 | 0 | 11,459 | \$780,769 | 1974 | | | | 2003 | 95.00 | 94.00 | \$39,038 | \$46,846 | \$0 | | | 16 |
| Univ Village West 29 | 3498 | 0829 | 51 | 0 | 8,616 | \$587,059 | 197.4 | | | | 2003 | 95.00 | 94.00 | \$29,353 | \$35,224 | \$0 | | | |
| Univ Village West 30 | 3499 | 0830 | 51 | 0 | 8,195 | \$558,374 | 1974 | | | | 2003 | 95.00 | 94.00 | \$27,919 | \$33,502 | \$0 | | | |
| Univ Village West 31 | 3500 | 0831 | 51 | 0 | 8,631 | \$588,081 | 1974 | | | | 2003 | 95.00 | 94.00 | \$29,404 | \$35,285 | \$0 | | | |
| Univ Village West 32 | 3501 | 0832 | 51 | 0 | 9,852 | \$671,275 | 1974 | | | | 2003 | 95.00 | 94.00 | \$33,564 | \$40,277 | \$0 | | | |
| Univ Village West 33 | 3502 | 0833 | 51 | 0 | 11,444 | \$779,747 | 1974 | | | | 2003 | 95.00 | 94.00 | \$38,987 | \$46,785 | \$0 | | | |
| International House | 7335 | 0835 | 51 | 0 | 98,038 | \$7,585,220 | 1994 | 7 | | | 2003 | 95.00 | 94.00 | \$379,261 | \$455,113 | \$0 | | | |
| Univ Village West 34 | 3503 | 0839 | 51 | 0 | 8,641 | \$936,872 | 1974 | | | | 2003 | 91.00 | 94.00 | \$84,318 | \$56,212 | \$28,106 | | | |
| Housing Services Center | 3504 | 0840 | 30 | 0 | 14,675 | \$1,136,475 | 1974 | - | | | 2003 | 97.00 | 94.00 | \$34,094 | \$68,189 | \$0 | | | |
| Housing Warehouse | 7936 | 0845 | 30 | 0 | 40,600 | \$2,141,890 | 1997 | | | | 2003 | 94.00 | 90.00 | \$128,513 | \$214,189 | \$0 | | | |
| University Village North/West 1 | 7336 | 0851 | 51 | 0 | 8,259 | \$695,314 | 1994 | | | 17934 | 2003 | 94.00 | 94.00 | \$41,719 | \$41,719 | \$0 | | | |
| University Village North/West 2 | 7337 | 0852 | 51 | 0 | 8,259 | \$695,314 | 1994 | | | | 2003 | 94.00 | 94.00 | \$41,719 | \$41,719 | \$0 | | | |
| University Village North/West 3 | 7338 | 0853 | 51 | 0 | 8,259 | \$695,314 | 1994 | | | 10000 | 2003 | 94.00 | 94.00 | \$41,719 | \$41,719 | \$0 | | | |
| University Village North/West 4 | 7339 | 0854 | 51 | 0 | 8,259 | \$695,314 | 1994 | | | | 2003 | 94.00 | 94.00 | \$41,719 | \$41,719 | \$0 | | | |
| University Village North/West 5 | 7328 | 0855 | 51 | 0 | 8,259 | \$695,314 | 1994 | | | | 2003 | 94.00 | 94.00 | \$41,719 | \$41,719 | \$0 | | | |

| University Village North/West 6 | 7329 | 0856 | 51 | 0 | 8,259 | \$695,314 | 1994 | | <u> </u> | 2003 | 94.00 | 94.00 | \$41,719 | \$41,719 | \$0 | | | |
|---------------------------------|------|------|-----|-----|---------|--------------|------|------|-----------|------|-------|-------|-------------|-------------|-------------|---|--------|---|
| | 7340 | 0857 | 51 | 0 | 8.259 | \$695,314 | 1994 | - | | 2003 | 94.00 | 94.00 | \$41,719 | \$41,719 | \$0 | | | |
| University Village North/West 7 | 7937 | 0858 | 51 | 0 | 8,259 | \$695,314 | 1994 | | | 2003 | 94.00 | 94.00 | \$41,719 | \$41,719 | \$0 | | | |
| University Village North/West 8 | 7220 | 0930 | 29 | 100 | 5,688 | \$596,288 | 1991 | | | 2003 | 74.00 | 94.00 | \$155,035 | \$35,777 | \$119,258 | | | |
| Visitors Center | 7221 | 0930 | 16 | 100 | 16,575 | \$1,642,375 | 1993 | | | 2003 | 69.90 | 94.00 | \$494,355 | \$98,543 | \$395,812 | | | - |
| University Square # 1311 | 1221 | 0935 | 50 | 0 | 22,531 | \$3,103,602 | 2002 | | | 2003 | 74.00 | 94.00 | \$806,937 | \$186,216 | \$620,720 | | | |
| Helmshire Hall | 7484 | 0935 | 11 | 100 | 5,139 | \$446,074 | 1993 | | | 2003 | 64.40 | 94.00 | \$158,802 | \$26,764 | \$132,038 | | | |
| Meat Packing Plant | 3511 | 1001 | 29 | 100 | 148 | \$4,590 | 1941 | | | 2003 | 49.00 | 90.00 | \$2,341 | \$459 | \$1,882 | | | |
| Runway Light Control | 3512 | 1001 | 30 | 100 | 4,870 | \$301,219 | 1941 | 2000 | 83.70 | 2003 | 82.40 | 90.00 | \$53,015 | \$30,122 | \$22,893 | | | |
| West Hangar | | 1002 | | 100 | 293 | \$27,229 | 1941 | 2000 | 03.70 | 2003 | 49.00 | 90.00 | \$13,887 | \$2,723 | \$11,164 | | | |
| Ram Flying Club | 3513 | | 29 | 100 | | \$559,629 | 1941 | | | 2003 | 49.00 | 94.00 | \$285,411 | \$33,578 | \$251,833 | 100000000000000000000000000000000000000 | | |
| Shop Hangar | 3514 | 1004 | 29 | - | 6,022 | | 1941 | | | - | 64.00 | 94.00 | \$43,239 | \$7,207 | \$36,033 | | | |
| Engr. Renewal+Growth | 3516 | 1005 | 11 | 100 | 1,551 | \$120,109 | - | | | 2003 | | | | | | | | |
| Facilities Maint. | 3517 | 1006 | 30 | 100 | 6,004 | \$557,956 | 1940 | | | 2003 | 64.00 | 94.00 | \$200,864 | \$33,477 | \$167,387 | | | |
| Atmos. Simulation | 3518 | 1007 | 11 | 100 | 10,260 | \$2,224,656 | 1968 | 2000 | 87.26 | 2006 | 85.60 | 94.00 | \$320,350 | \$133,479 | \$186,871 | | | |
| Storage | 3519 | 1008 | 31 | 100 | 2,045 | \$102,879 | 1981 | | | 2003 | 49.00 | 90.00 | \$52,468 | \$10,288 | \$42,180 | | | - |
| Storage | 3520 | 1009 | .31 | 100 | 407 | \$3,115 | 1981 | | | 2003 | 49.00 | 90.00 | \$1,589 | \$312 | \$1,277 | | | |
| ENSR | | 1011 | 12 | 0 | 20,079 | \$2,686,181 | 1994 | | | 2003 | 85.00 | 94.00 | \$402,927 | \$161,171 | \$241,756 | | | |
| Storage | 3521 | 1013 | 31 | 100 | 176 | \$1,294 | 1984 | | | 2003 | 49.00 | 90.00 | \$660 | \$129 | \$531 | A | | |
| A.E.R.C. Annex | 3522 | 1014 | 16 | 100 | 5,041 | \$303,490 | 1980 | 2000 | 53.02 | 2006 | 36.40 | 94.00 | \$193,020 | \$18,209 | \$174,810 | | | |
| Ag. Engr. Rsch. Ctr. | 3523 | 1015 | 11 | 100 | 15,174 | \$1,416,158 | 1939 | 2000 | 86.78 | 2006 | 81.80 | 94.00 | \$257,741 | \$84,969 | \$172,771 | | | |
| Project Lab | 3524 | 1016 | 11 | 100 | 1,471 | \$38,433 | 1977 | | | 2003 | 59.00 | 94.00 | \$15,758 | \$2,306 | \$13,452 | | | |
| Storage | 3525 | 1017 | 31 | 100 | 4,766 | \$229,054 | 1980 | | | 2003 | 49.00 | 90.00 | \$116,818 | \$22,905 | \$93,912 | | | |
| Explosives Storage | 3527 | 1040 | 31 | 100 | 58 | \$7,636 | 1975 | | | 2003 | 49.00 | 90.00 | \$3,894 | \$764 | \$3,131 | | | |
| Explosives Storage | 3528 | 1041 | 31 | 100 | 37 | \$4,871 | 1975 | | | 2003 | 49.00 | 90.00 | \$2,484 | \$487 | \$1,997 | | | |
| Explosives Storage | 3529 | 1042 | 31 | 100 | 58 | \$7,636 | 1975 | | | 2003 | 49.00 | 90.00 | \$3,894 | \$764 | \$3,131 | | | |
| Pump House | 3530 | 1051 | 31 | 100 | 249 | \$77,138 | 1961 | | | 2006 | 41.70 | 90.00 | \$44,971 | \$7,714 | \$37,258 | | | |
| Headquarters | 3531 | 1052 | 16 | 100 | 8,560 | \$1,060,693 | 1958 | | | 2006 | 95.60 | 94.00 | \$46,670 | \$63,642 | (\$16,971) | | | |
| Shop | 3532 | 1053 | 30 | 100 | 6,916 | \$642,709 | 1961 | | | 2006 | 75.60 | 94.00 | \$156,821 | \$38,563 | \$118,258 | | | |
| Storage | 3533 | 1054 | 31 | 100 | 5,201 | \$322,354 | 1965 | | | 2006 | 76.00 | 90.00 | \$77,365 | \$32,235 | \$45,130 | | | |
| Supplies Storage | 3534 | 1055 | 31 | 100 | 208 | \$19,330 | 1974 | | | 2006 | 76.20 | 90.00 | \$4,601 | \$1,933 | \$2,668 | | | |
| Fire Trucks | 3535 | 1056 | 30 | 100 | 5,357 | \$141,091 | 1974 | | | 2006 | 42.90 | 90.00 | \$80,563 | \$14,109 | \$66,454 | | | |
| Paint Shop | 3537 | 1057 | 30 | 100 | 2,417 | \$74,957 | 1975 | | | 2006 | 54.40 | 94.00 | \$34,180 | \$4,497 | \$29,683 | | | |
| Storage | 3538 | 1058 | 31 | 100 | 2,268 | \$62,437 | 1975 | | | 2006 | 40.50 | 90.00 | \$37,150 | \$6,244 | \$30,906 | | | |
| Storage | 3539 | 1059 | 31 | 100 | 2,894 | \$89,750 | 1975 | | | 2006 | 73.40 | 90.00 | \$23,874 | \$8,975 | \$0 | | | |
| Nursery | 3540 | 1060 | 31 | 100 | 28,983 | \$3,142,340 | 1964 | | | 2006 | 66.60 | 94.00 | \$1,049,542 | \$188,540 | \$861,001 | | | |
| Storage | 3544 | 1061 | 31 | 100 | 1,031 | \$31,974 | 1969 | | | 2003 | 49.00 | 90.00 | \$16,307 | \$3,197 | \$13,109 | | | |
| Storage | 3545 | 1062 | 31 | 100 | 5,419 | \$41,176 | 1984 | | | 2006 | 16.70 | 90.00 | \$34,300 | \$4,118 | \$30,182 | | | |
| Larimer Fire Cache | 3547 | 1064 | 31 | 100 | 2,050 | \$99,654 | 1980 | | acid acid | 2006 | 43.10 | 90.00 | \$56,703 | \$9,965 | \$46,738 | | | |
| Machine Shed | 3548 | 1065 | 31 | 100 | 3,340 | \$72,354 | 1958 | | | 2006 | 62.50 | 90.00 | \$27,133 | \$7,235 | \$19,897 | | | |
| Modular Office | 3550 | 1066 | 16 | 100 | 646 | \$30,556 | 1974 | | | 2003 | 81.33 | 94.00 | \$5,705 | \$1,833 | \$3,871 | | | |
| Trailer Office | 3551 | 1067 | 16 | 100 | 222 | \$11,662 | 1974 | | | 2003 | 59.00 | 94.00 | \$4,781 | \$700 | \$4,082 | | | |
| Garage | 3552 | 1068 | 31 | 100 | 1,185 | \$29,904 | 1977 | | | 2006 | 58.20 | 94.00 | \$12,500 | \$1,794 | \$10,706 | | | |
| | 3553 | 1069 | 31 | 100 | 823 | \$6,299 | 1982 | | | 2006 | 21.50 | 90.00 | \$4,945 | \$630 | \$4,315 | | | |
| Chip Storage Sawmill | 3554 | 1070 | 31 | 100 | 2,242 | \$30,655 | 1987 | | | 2003 | 49.00 | 94.00 | \$15,634 | \$1,839 | \$13,795 | | | |
| | 5005 | 1071 | 31 | 100 | 2,472 | \$75,039 | 1979 | | | 2003 | 49.00 | 94.00 | \$38,270 | \$4,502 | \$33,768 | | | |
| Nursery Storage | 3555 | 1083 | 31 | 100 | 1,037 | \$22,464 | 1915 | | | 2003 | 34.00 | 90.00 | \$14.826 | \$2,246 | \$12,580 | | | |
| Storage | 3557 | 1101 | 12 | 100 | 149,915 | \$23,221,923 | 1962 | 1999 | 72.62 | 2008 | 64.20 | 94.00 | \$8,313,448 | \$1,393,315 | \$6,920,133 | | M00034 | |
| Engr. Res. Center | 3559 | 1101 | 30 | 100 | 3.216 | \$161,789 | 1980 | 1999 | 12.02 | 2003 | 64.00 | 94.00 | \$58,244 | \$9,707 | \$48,537 | | | |
| Workshop | | | 11 | - | 3,216 | \$41,552 | 1993 | | | 2003 | 64.00 | 94.00 | \$14,959 | \$2,493 | \$12,466 | | | |
| Aquatic Greenhouse | 7324 | 1104 | | 100 | | | - | | | - | | - | - | - | | | | |
| West Office | 3560 | 1105 | 16 | 100 | 11,317 | \$894,192 | 1964 | | | 2003 | 69.00 | 94.00 | \$277,200 | \$53,652 | \$223,548 | | | - |

| Workshop | 3563 | 1106 | 30 | 100 | 2 200 | \$125,223 | 1963 | | | 2003 | 60.00 | 0400 | 200.040 | 47.5.0 | | | | | |
|--|--------|--------|------|-------|--------|--------------|------|-------|-------|--------|-------|---------|-------------|-----------|-------------|------|-------------|--------|---|
| Quonset | 3564 | 1107 | - | | 3,369 | | - | | | - | 69.00 | 94.00 | \$38,819 | \$7,513 | \$31,306 | | | | |
| Quonset | | | 31 | 100 | 988 | \$30,640 | 1940 | | | 2003 | 49.00 | 94.00 | \$15,626 | \$1,838 | \$13,788 | | | | |
| | 3565 | 1108 | 31 | 100 | 1,003 | \$31,106 | 1940 | | | 2003 | 49.00 | 94.00 | \$15,864 | \$1,866 | \$13,998 | | | | |
| Rainfall Facility | 3566 | 1110 | 11 | 100 | 2,914 | \$90,370 | 1972 | | | 2003 | 49.00 | 94.00 | \$46,089 | \$5,422 | \$40,667 | | | | |
| Hydro-Machinery Lab | 3567 | 1111 | 12 | 100 | 16,826 | \$2,084,955 | 1966 | 1999 | 73.55 | 2008 | 58.20 | 94.00 | \$871,511 | \$125,097 | \$746,414 | | 4.6.29.65.5 | | |
| Turbine Pumphouse | 7176 | 1114 | 11 | 100 | 559 | \$41,454 | 1974 | | | 2003 | 49.00 | 90.00 | \$21,142 | \$4,145 | \$16,996 | | | | |
| Storage | 3569 | 1115 | 31 | 100 | 264 | \$3,001 | 1985 | | | 2003 | 49.00 | 90.00 | \$1,531 | \$300 | \$1,230 | | | | |
| Pump House | 3570 | 1116 | 31 | 100 | 300 | \$12,324 | 1967 | | | 2003 | 49.00 | 90.00 | \$6,285 | \$1,232 | \$5,053 | | | | |
| Erc Publication Trlr | 3571 | 1117 | 16 | 100 | 720 | \$13,859 | 1982 | | | 2003 | 49.00 | 94.00 | \$7,068 | \$832 | \$6,237 | | | | |
| Coop Institute for Research in the Atmos | 3573 | 1119 | 11 | 100 | 12,743 | \$1,760,847 | 1981 | 1999 | 88.98 | 2008 | 79.70 | 94.00 | \$357,452 | \$105,651 | \$251,801 | | | M00034 | |
| Atmospheric Science | 3575 | 1120 | 11 | 100 | 37,079 | \$4,594,411 | 1967 | 2001 | 72.29 | 2007 | 70.50 | 94.00 | \$1,355,351 | \$275,665 | \$1,079,687 | | P0114 | M90023 | |
| Atmos. Science Annex | 3576 | 1121 | 11 | 100 | 4,984 | \$540,174 | 1967 | 2001 | 86.47 | 2007 | 79.70 | 94.00 | \$109,655 | \$32,410 | \$77,245 | 3 | | | |
| Solar Energy House 1 | 3577 | 1122 | 12 | 100 | 4,558 | \$706,037 | 1974 | 1999 | 76.75 | 2005 | 68.10 | 94.00 | \$225,226 | \$42,362 | \$182,864 | | | M00034 | |
| Solar Energy House 2 | 3579 | 1123 | 12 | 100 | 3,626 | \$561,670 | 1975 | 1999 | 73.36 | 2005 | 70.10 | 94.00 | \$167,939 | \$33,700 | \$134,239 | | | M00034 | |
| Solar Energy House 3 | 3580 | 1124 | 12 | 100 | 3,630 | \$562,289 | 1975 | 1999 | 69.63 | 2008 | 60.20 | 94.00 | \$223,791 | \$33,737 | \$190,054 | | | Mooo34 | |
| ATS/CIRA Research Center | | 1125 | 11 | 100 | 14,260 | \$2,216,040 | 2002 | | | 2003 | 95.00 | 94.00 | \$110,802 | \$132,962 | \$0 | | | | |
| Solar Greenhouse | 3581 | 1126 | 11 | 100 | 1,393 | \$175,763 | 1977 | 1999 | 82.35 | 2005 | 64.80 | 90.00 | \$61,869 | \$17,576 | \$44,292 | | | | |
| Research Building | 3582 | 1127 | 11 | 100 | . 882 | \$38,321 | 1978 | | | 2003 | 59.00 | 94.00 | \$15,712 | \$2,299 | \$13,412 | | | | |
| Storage Shed | 3584 | 1129 | 31 | 100 | 164 | \$5,342 | 1978 | | | 2003 | 49.00 | 90.00 | \$2,724 | \$534 | \$2,190 | | | | |
| Storage Shed | 3585 | 1130. | 31 | 100 | 164 | \$5,342 | 1978 | | | 2003 | 49.00 | 90.00 | \$2,724 | \$534 | \$2,190 | | | | |
| R.E.P.E.A.T. Facility | 3586 | 1132 | 16 | 100 | 2,963 | \$238,363 | 1981 | 1999 | 80.94 | 2008 | 69.60 | 94.00 | \$72,462 | \$14,302 | \$58,161 | | | | |
| River Model Facility | 3589 | 1135 | 1.1 | 100 | 5,212 | \$119,516 | 1978 | | | 2003 | 59.00 | 94.00 | \$49,002 | \$7,171 | \$41,831 | | | | 1 |
| Engineer.Res.Valvehs | 3591 | 1137 | 11 | 100 | 168 | \$3,131 | 1974 | | | 2003 | 49.00 | 90.00 | \$1,597 | \$313 | \$1,284 | | | | |
| Engineer.Res.Valvehs | 3592 | 1138 | 11 | 100 | 217 | \$2,652 | 1974 | | | 2003 | 49.00 | 90.00 | \$1,353 | \$265 | \$1,087 | | | | |
| Engineer.Res.Valvehs | 3593 | 1139 | 11 | 100 | 242 | \$2,958 | 1967 | | | 2003 | 49.00 | 90.00 | \$1,509 | \$296 | \$1,213 | | | | |
| Trailer | 3594 | 1140 | 11 | 100 | 164 | \$3,137 | 1985 | | | 2003 | 49.00 | 94.00 | \$1,600 | \$188 | \$1,412 | | | | |
| West Valve House | 7177 | 1141 | 11 | 100 | 194 | \$17,138 | 1991 | | | 2003 | 49.00 | 90.00 | \$8,740 | \$1,714 | \$7,027 | | | | |
| East Valve House | 7168 | 1142 | 11 | 100 | 280 | \$24,735 | 1991 | | | 2003 | 49.00 | 90.00 | \$12,615 | \$2,474 | \$10,141 | | | | |
| KCSU Transmitter | 3595 | 1171 | 60 | 0 | 49 | \$8,227 | 1966 | | | 2003 | 74.00 | 90.00 | \$2,139 | \$823 | \$1,316 | | | | |
| KCSU Transmitter | 3596 | 1172 | 60 | 0 | 145 | \$15,161 | 1984 | | | 2003 | 74.00 | 90.00 | \$3,942 | \$1,516 | \$2,426 | | | | |
| Cattle Barn | 3597 | 1173 | 31 | 100 | 3,135 | \$67,896 | 1928 | | | 2003 | 59.00 | 90.00 | \$27,837 | \$6,790 | \$21,048 | | | | |
| Livestock Shed | 3598 | 1174 | 31 | 100 | 672 | \$20,286 | 1980 | | | 2003 | 49.00 | 90.00 | \$10,346 | \$2,029 | \$8,317 | | | | |
| Pump House | 3600 | 1175 | 31 | 100 | 100 | \$4,024 | 1980 | | | 2003 | 49.00 | 90.00 | \$2,052 | \$402 | \$1,650 | | | | |
| C.D.CCenter for Disease Control | 3602 | 1301 | 11 | 0 | 41,565 | \$12,876,392 | 1967 | 2003 | 71.80 | 2003 | 71.80 | 94.00 | \$3,631,143 | \$772,584 | \$2,858,559 | | | | |
| CDC Modular | 5165 | 1302 | 11 | 0 | 4,427 | \$111,726 | 1967 | | | 2003 | 74.00 | 94.00 | \$29,049 | \$6,704 | \$22,345 | | | | |
| CDC Modular | 5166 | 1303 | 11 | 0 | 5,312 | \$1,311,566 | 1967 | | | 2003 | 74.00 | 94.00 | \$341,007 | \$78,694 | \$262,313 | | | | |
| Blockhouse | 3605 | 1305 | 31 | 100 | 1,080 | \$167,283 | 1964 | | | 2003 | 49.00 | 94.00 | \$85,314 | \$10,037 | \$75,277 | | | | |
| Rad. Genetics Bldg. | 3606 | 1309 | 30 | 100 | 510 | \$23,701 | 1963 | | | 2003 | 59.00 | 94.00 | \$9,717 | \$1,422 | \$8,295 | | | | |
| C.D.C. Storage | 3608 | 1312 | 31 | 0 | 685 | \$19,213 | 1967 | | | 2003 | 74.00 | 90.00 | \$4,995 | \$1,921 | \$3,074 | | | | |
| C D.C. Storage | 3609 | 1313 | 31 | 0 | 256 | \$7,180 | 1967 | 6.764 | | 2003 | 74.00 | 90.00 | \$1,867 | \$718 | \$1,149 | | | | |
| C.D.C. Storage/Lab | 3610 | 1314 | 31 | 0 | 729 | \$20,448 | 1967 | | | 2003 | 74.00 | 94.00 | \$5,316 | \$1,227 | \$4,090 | | | | |
| C.D.C. Storage | 3611 | 1315 | 31 | 0 | 1,380 | \$38,707 | 1967 | | | 2003 | 74.00 | 90.00 | \$10,064 | \$3,871 | \$6,193 | | | | 1 |
| C.D.C. Storage | 3612 | 1316 | 31 | 0 | 180 | \$3,088 | 1967 | | | 2003 | 74.00 | 90.00 | \$803 | \$3,071 | \$494 | | | | - |
| C.D.C. Laboratory | 3613 | 1317 | 11 | 0 | 3.861 | \$53,361 | 1967 | | | 2003 | 74.00 | 94.00 | \$13.874 | \$3.202 | \$10.672 | | | | + |
| B.W. Pickett Equine Center | 3614 | 1330 | 31 | 100 | 95,154 | \$5,837,247 | 1994 | 2000 | 80.51 | 2003 | 71.40 | 94.00 | \$1,669,453 | \$350,235 | \$1,319,218 | | | | - |
| Horse Shelter | 3615 | 1331 | 31 | 100 | 1,320 | \$23,049 | 1986 | 2000 | 00.51 | 2008 | 59.00 | 90.00 | \$9,450 | \$2,305 | \$7,145 | | | | - |
| Horse Shelter | 3616 | 1331 | 31 | 100 | 1,320 | \$23,049 | 1986 | | | 2003 | 59.00 | 90.00 | \$9,450 | \$2,305 | \$7,145 | | | | - |
| Horse Shelter | 3617 | 1333 | 31 | 100 | 1,320 | \$23,049 | 1986 | | | 2003 | 59.00 | 90.00 | \$9,450 | \$2,305 | \$7,145 | | | | - |
| Horse Shelter | 3618 | 1333 | 31 | 100 | 1,320 | \$23,049 | 1986 | | | 2003 | 59.00 | 90.00 | \$9,450 | \$2,305 | \$7,145 | | | | - |
| | 3619 | 1335 | 31 | 100 | 1,320 | \$23,049 | - | | | 2003 | 59.00 | 90.00 | \$9,450 | \$2,305 | \$7,145 | | | | - |
| Horse Shelter | 1 3019 | 1 1335 | 1 31 | 1 100 | 1,320 | Φ23,049 | 1900 | | | 1 2003 | 39.00 | 1 90.00 | \$9,450 | Φ2,305 | \$1,145 | 1, 1 | | | |

| Adams Atkinson Arena | 7330 | 1336 | 31 | 100 | 38,446 | \$1,504,761 | 1984 | | | 2003 | 64.00 | 94.00 | \$541,714 | \$90,286 | \$451,428 | | |
|--|------|------|-----|-----|--------|--------------|------|------|-------------|------|--------|-------|-------------|-----------|-----------|--|--------|
| Foothills Fisheries Facility | | 1353 | 11 | 100 | 4,649 | \$735,265 | 2002 | | 3, 118.0 | 2003 | 100.00 | 94.00 | \$0 | \$44,116 | \$0 | | |
| Fisheries Maint. | 3620 | 1354 | 31 | 100 | 3,829 | \$223,396 | 1976 | | | 2003 | 54.00 | 90.00 | \$102,762 | \$22,340 | \$80,423 | | |
| Sheep Shed | 3621 | 1355 | 31 | 100 | 2,652 | \$73,015 | 1976 | | | 2003 | 49.00 | 90.00 | \$37,238 | \$7,302 | \$29,936 | | |
| Sheep Shed | 3622 | 1356 | 31 | 100 | 3,418 | \$74,044 | 1953 | | | 2003 | 49.00 | 90.00 | \$37,762 | \$7,404 | \$30,358 | | |
| Hay Storage | 3623 | 1357 | 31 | 100 | 9,496 | \$205,711 | 1954 | | | 2003 | 49.00 | 90.00 | \$104,913 | \$20,571 | \$84,342 | | |
| Irrigation Filter | 3624 | 1359 | 30 | 100 | 242 | \$4,533 | 1984 | | | 2003 | 59.00 | 90.00 | \$1,859 | \$453 | \$1,405 | | |
| Photo Barn | 3625 | 1361 | 31 | 100 | 2,886 | \$62,519 | 1968 | | | 2003 | 59.00 | 90.00 | \$25,633 | \$6,252 | \$19,381 | | |
| Grain Storage | 3626 | 1362 | 31 | 100 | 1,833 | \$56,846 | 1964 | | | 2003 | 49.00 | 90.00 | \$28,991 | \$5,685 | \$23,307 | | |
| Animal Shed | 3629 | 1365 | -31 | 100 | 576 | \$12,478 | 1974 | | | 2003 | 49.00 | 90.00 | \$6,364 | \$1,248 | \$5,116 | | |
| Office | 5013 | 1366 | 16 | 100 | 590 | \$37,738 | 1950 | 4 | | 2003 | 64.00 | 94.00 | \$13,586 | \$2,264 | \$11,321 | | |
| Horse Barn | 3631 | 1377 | 31 | 100 | 1,708 | \$52,969 | 1958 | | | 2003 | 49.00 | 90.00 | \$27,014 | \$5,297 | \$21,717 | | |
| Isolation Shed | 3632 | 1380 | 31 | 100 | 2,367 | \$59,738 | 1977 | | | 2003 | 59.00 | 90.00 | \$24,493 | \$5,974 | \$18,519 | | |
| Mare Barn | 3635 | 1385 | 31 | 100 | 5,167 | \$160,242 | 1973 | | | 2003 | 59.00 | 90.00 | \$65,699 | \$16,024 | \$49,675 | | |
| Foaling Barn | 3636 | 1386 | 31 | 100 | 586 | \$15,403 | 1961 | | | 2003 | 59.00 | 90.00 | \$6,315 | \$1,540 | \$4,775 | | |
| Storage Building | 3638 | 1388 | 31 | 100 | 402 | \$7,381 | 1961 | | | 2003 | 49.00 | 90.00 | \$3,764 | \$738 | \$3.026 | | |
| Stallion Laboratory | 3639 | 1389 | 31 | 100 | 4,649 | \$696,078 | 1979 | 2001 | 86.98 | 2003 | 81.00 | 94.00 | \$132,255 | \$41,765 | \$90,490 | | |
| Stallion Pens | 3643 | 1391 | 31 | 100 | 1,534 | \$47,573 | 1968 | 2001 | 00.36 | 2007 | 49.00 | 90.00 | \$24,262 | \$4,757 | \$19,505 | | |
| Stallion Pens Stallion Pens | 3644 | 1391 | 31 | 100 | 848 | \$26,299 | 1968 | | | 2003 | 49.00 | 90.00 | \$13,412 | \$2,630 | \$19,303 | | |
| Stallion Pens Stallion Barn | 3044 | 1392 | 11 | 100 | 3,612 | \$300,226 | 2002 | | | 2003 | 100.00 | 94.00 | \$13,412 | \$18,014 | \$10,763 | | |
| | 3645 | | 31 | - | 5,167 | \$160,242 | 1974 | | | - | 49.00 | 90.00 | \$81,723 | \$16,014 | \$65,699 | | |
| Stallion Barn | 3646 | 1394 | 31 | 100 | 2,672 | | 1974 | | | 2003 | 49.00 | 90.00 | \$46,571 | \$9,132 | \$37,439 | | |
| Stallion Pen | | | 31 | | 2,458 | \$91,315 | 1977 | 2001 | 83.01 | - | 82.60 | 94.00 | \$46,571 | \$10,716 | \$20,360 | | |
| Swine Confinement | 5131 | 1396 | | 100 | | \$178,593 | - | 2001 | 03.01 | 2007 | - | | | | | | |
| Shaving Shed | 3649 | 1397 | 31 | 100 | 546 | \$23,723 | 1979 | | | - | 49.00 | 90.00 | \$12,099 | \$2,372 | \$9,726 | | |
| Semen Collect. Shed | 3650 | 1398 | 31 | 100 | 2,528 | \$78,400 | 1975 | | | 2003 | 59.00 | 90.00 | \$32,144 | \$7,840 | \$24,304 | | |
| Mare Barn | 5167 | 1399 | 31 | 100 | 13,000 | \$285,295 | 1999 | | | 2003 | 49.00 | 90.00 | \$145,500 | \$28,530 | \$116,971 | | |
| Radiation Waste | 3651 | 1400 | 31 | 100 | 2,560 | \$55,457 | 1960 | | | 2003 | 49.00 | 90.00 | \$28,283 | \$5,546 | \$22,737 | | |
| Animal Disease Lab | 3652 | 1401 | 41 | 100 | 8,775 | \$1,087,334 | 1960 | 1000 | 04.00 | 2004 | 58.90 | 94.00 | \$446,894 | \$65,240 | \$381,654 | | |
| Animal Reproduction & Biotechnology Lat | 3653 | 1402 | 11 | 100 | 41,288 | \$7,281,634 | 1964 | 1999 | 91.80 | 2008 | 81.40 | 94.00 | \$1,354,384 | \$436,898 | \$917,486 | | |
| Shed | 3656 | 1405 | 31 | 100 | 391 | \$8,470 | 1968 | | | 2003 | 49.00 | 90.00 | \$4,320 | \$847 | \$3,473 | | |
| Shed | 3657 | 1406 | 31 | 100 | 391 | \$8,470 | 1968 | | | 2003 | 49.00 | 90.00 | \$4,320 | \$847 | \$3,473 | | |
| Utility Building | 8013 | 1407 | 31 | 100 | 930 | \$171,504 | 1995 | | | 2003 | 94.00 | 90.00 | \$10,290 | \$17,150 | \$0 | | |
| Shed | 3658 | 1408 | 31 | 100 | 630 | \$13,648 | 1968 | | | 2003 | 49.00 | 90.00 | \$6,960 | \$1,365 | \$5,596 | | |
| Shed | 3659 | 1409 | 31 | 100 | 630 | \$13,648 | 1968 | | | 2003 | 49.00 | 90.00 | \$6,960 | \$1,365 | \$5,596 | | |
| Shed | 3660 | 1410 | 31 | 100 | 630 | \$13,648 | 1968 | | | 2003 | 49.00 | 90.00 | \$6,960 | \$1,365 | \$5,596 | | |
| Animal Holding Facility | 3654 | 1411 | 31 | 100 | 2,368 | \$157,492 | 1997 | | | 2003 | 49.00 | 94.00 | \$80,321 | \$9,450 | \$70,871 | | |
| Sewage Chlorination | 3661 | 1412 | 30 | 100 | 66 | \$1,430 | 1960 | | | 2003 | 49.00 | 90.00 | \$729 | \$143 | \$586 | | |
| Monkey House | 3662 | 1413 | 11 | 100 | 369 | \$40,008 | 1964 | | | 2003 | 64.00 | 94.00 | \$14,403 | \$2,400 | \$12,002 | | |
| Office-Residence Anx | 3663 | 1414 | 16 | 100 | 1,749 | \$135,442 | 1966 | | - 9 11 11 1 | 2003 | 59.00 | 94.00 | \$55,531 | \$8,127 | \$47,405 | | |
| Animal Quarters | 3664 | 1415 | 31 | 100 | 2,167 | \$234,950 | 1964 | | | 2003 | 59.00 | 94.00 | \$96,330 | \$14,097 | \$82,233 | | M00034 |
| Surgical Annex | 3665 | 1416 | 11 | 100 | 3,564 | \$386,415 | 1975 | | | 2003 | 79.00 | 94.00 | \$81,147 | \$23,185 | \$57,962 | | |
| Cattle Processing | 3666 | 1417 | 31 | 100 | 288 | \$5,434 | 1981 | | | 2003 | 59.00 | 90.00 | \$2,228 | \$543 | \$1,685 | | |
| Food Preparation | 3667 | 1420 | 41 | 100 | 2,200 | \$102,241 | 1968 | 1999 | 85.12 | 2008 | 75.90 | 94.00 | \$24,640 | \$6,134 | \$18,506 | | |
| Arthropod-Borne & Infectious Disease Lat | 3668 | 1421 | 11 | 100 | 14,329 | \$1,783,425 | 1964 | 2001 | 72.56 | 2007 | 65.30 | 94.00 | \$618,848 | \$107,006 | \$511,843 | | |
| Center for Envir Toxicology & Technology | 3669 | 1422 | 11 | 100 | 14,676 | \$1,884,527 | 1966 | 2001 | 66.41 | 2007 | 77.40 | 94.00 | \$425,903 | \$113,072 | \$312,831 | | |
| Irradiation Site | 3670 | 1423 | 11 | 100 | 2,627 | \$325,523 | 1967 | | | 2003 | 59.00 | 94.00 | \$133,464 | \$19,531 | \$113,933 | | |
| Bio-environmental Hazards Research | 8822 | 1424 | 11 | 100 | 18,657 | \$12,017,599 | 2000 | | | 2003 | 97.00 | 94.00 | \$360,528 | \$721,056 | \$0 | | |
| Motor Performance | 3671 | 1425 | 31 | 100 | 800 | \$61,952 | 1968 | | | 2003 | 49.00 | 94.00 | \$31,596 | \$3,717 | \$27,878 | | |
| Maintenance Garage | 3672 | 1427 | 31 | 100 | 1,017 | \$27,283 | 1981 | | | 2003 | 49.00 | 94.00 | \$13,914 | \$1,637 | \$12,277 | | |
| Dog Holding Facility | 5001 | 1430 | 11 | 100 | 2,380 | \$292,515 | 1988 | | | 2003 | 79.00 | 94.00 | \$61,428 | \$17,551 | \$43,877 | | |

| lu- ou-d | 7000 | | | | | | | | | | | | | | | | | |
|---|------|------|----|-----|--------|--------------|------|-----|--------|------|--------|-------|-------------|-------------|-------------|---|---|---|
| Hay Shed | 7938 | 1450 | 31 | 100 | 12,000 | \$106,108 | 1998 | | | 2003 | 49.00 | 90.00 | \$54,115 | \$10,611 | \$43,504 | | | |
| Shelter | 3673 | 1451 | 31 | 100 | 432 | \$5,630 | 1985 | | | 2003 | 49.00 | 90.00 | \$2,871 | \$563 | \$2,308 | | | |
| Shelter | 3674 | 1452 | 31 | 100 | 432 | \$5,630 | 1985 | | | 2003 | 49.00 | 90.00 | \$2,871 | \$563 | \$2,308 | | | |
| Shelter | 3675 | 1453 | 31 | 100 | 617 | \$7,022 | 1955 | | | 2003 | 49.00 | 90.00 | \$3,581 | \$702 | \$2,879 | | | |
| Shelter | 3676 | 1454 | 31 | 100 | 617 | \$7,022 | 1955 | | | 2003 | 49.00 | 90.00 | \$3,581 | \$702 | \$2,879 | | | |
| Shelter | 3677 | 1455 | 31 | 100 | 432 | \$5,630 | 1985 | | | 2003 | 49.00 | 90.00 | \$2,871 | \$563 | \$2,308 | | | |
| Shelter | 7166 | 1456 | 31 | 100 | 924 | \$11,700 | 1970 | | | 2003 | 49.00 | 90.00 | \$5,967 | \$1,170 | \$4,797 | | | |
| Shelter | 3678 | 1457 | 31 | 100 | 509 | \$5,793 | 1955 | | | 2003 | 49.00 | 90.00 | \$2,954 | \$579 | \$2,375 | | | |
| CSFS Pumphouse | 3679 | 1458 | 31 | 100 | 64 | \$2,637 | 1975 | | | 2003 | 49.00 | 90.00 | \$1,345 | \$264 | \$1,081 | | | |
| Shelter | 7167 | 1459 | 31 | 100 | 924 | \$11,700 | 1970 | | | 2003 | 49.00 | 90.00 | \$5,967 | \$1,170 | \$4,797 | | | |
| Sheep Facility | 3680 | 1460 | 31 | 100 | 7,500 | \$160,664 | 1985 | | | 2003 | 49.00 | 94.00 | \$81,939 | \$9,640 | \$72,299 | | | |
| Coll. Lake Pump Stat | 7170 | 1461 | 30 | 100 | 414 | \$64,488 | 1955 | | | 2003 | 59.00 | 90.00 | \$26,440 | \$6,449 | \$19,991 | | | |
| Hughes Stadium | 3682 | 1901 | 15 | 100 | 40,867 | \$55,455,671 | 1968 | 200 | 73.24 | 2006 | 88.10 | 94.00 | \$6,599,225 | \$3,327,340 | \$3,271,885 | | | |
| Office | 3686 | 2010 | 16 | 100 | 1,228 | \$76,116 | 1959 | | | 2003 | 49.00 | 94.00 | \$38,819 | \$4,567 | \$34,252 | | | |
| Foundation Seed Proc | 3687 | 2011 | 31 | 100 | 2,482 | \$153,844 | 1959 | | | 2003 | 49.00 | 94.00 | \$78,460 | \$9,231 | \$69,230 | | | |
| Drying Shed | 3688 | 2012 | 31 | 100 | 7,530 | \$466,738 | 1961 | | 1 2000 | 2003 | 49.00 | 90.00 | \$238,036 | \$46,674 | \$191,363 | | | |
| Machine Shed | 3689 | 2013 | 31 | 100 | 7,459 | \$463,435 | 1963 | | | 2003 | 49.00 | 90.00 | \$236,352 | \$46,344 | \$190,008 | | | |
| Processing | 3690 | 2014 | 31 | 100 | 4,000 | \$247,935 | 1961 | | | 2003 | 49.00 | 94.00 | \$126,447 | \$14,876 | \$111,571 | | | |
| Raptor Cage | 8003 | 2420 | 31 | 100 | 2,807 | \$6,876 | 1991 | | | 2003 | 49.00 | 90.00 | \$3,507 | \$688 | \$2,819 | | | |
| Picnic Shelter | 8004 | 2421 | 31 | 100 | 422 | \$2,753 | 1978 | | | 2003 | 59.00 | 90.00 | \$1,129 | \$275 | \$853 | | | |
| Restroom | 3741 | 2422 | 31 | 100 | 57 | \$2,296 | 1973 | | | 2003 | 69.00 | 94.00 | \$712 | \$138 | \$574 | | | |
| Cattle Barn | 8005 | 2423 | 31 | 100 | 1,742 | \$95,895 | 1988 | | | 2003 | 34.00 | 90.00 | \$63,291 | \$9,590 | \$53,701 | | | |
| Storage | 3743 | 2424 | 31 | 100 | 86 | \$2,237 | 1973 | | | 2003 | 49.00 | 90.00 | \$1,141 | \$224 | \$917 | | | |
| Residence-Environmental Learning Center | - | 2425 | 52 | 100 | 942 | \$75,193 | 1992 | | | 2004 | 53.40 | 94.00 | \$35,040 | \$4,512 | \$30,528 | | | |
| Shop Storage | 7342 | 2426 | 31 | 100 | 2,304 | \$41,215 | 1988 | | | 2003 | 49.00 | 90.00 | \$21,020 | \$4,122 | \$16,898 | | | |
| Original Barn | 8006 | 2427 | 31 | 100 | 609 | \$33,525 | 1988 | | | 2003 | 34.00 | 90.00 | \$22,127 | \$3,353 | \$18,774 | | | |
| Boxcar | 8007 | 2428 | 31 | 100 | 596 | \$14,575 | 1988 | | | 2003 | 34.00 | 90.00 | \$9,620 | \$1,458 | \$8.162 | | | |
| Outhouse | 8008 | 2429 | 31 | 100 | 20 | \$1,376 | 1988 | | | 2003 | 34.00 | 90.00 | \$908 | \$138 | \$771 | | | |
| Coal Shed | 8009 | 2430 | 31 | 100 | 77 | \$688 | 1988 | | | 2003 | 34.00 | 90.00 | \$454 | \$69 | \$385 | | | - |
| Run-In-Barn | 8011 | 2432 | 31 | 100 | 567 | \$11,065 | 1988 | | | 2003 | 34.00 | 90.00 | \$7,303 | \$1,107 | \$6,196 | | | |
| Cattle Chute | 8012 | 2433 | 31 | 100 | 341 | \$2,755 | 1988 | | | 2003 | 34.00 | 90.00 | \$1,818 | \$276 | \$1,543 | | | |
| Storage Shed | 8013 | 2434 | 31 | 100 | 161 | \$3,441 | 2000 | | | 2003 | 34.00 | 90.00 | \$2,271 | \$344 | \$1,927 | | | |
| Coors Pavilion | 5468 | 2501 | 16 | 100 | 9,353 | \$1,185,941 | 2000 | | | 2003 | 99.00 | 94.00 | \$11,859 | \$71,156 | \$0 | | | + |
| Faculty Cabin No. 1 | 3745 | 3001 | 52 | 0 | 957 | \$88,935 | 1939 | | | 2003 | 77.00 | 94.00 | \$20,455 | \$5,336 | \$15,119 | | | |
| Faculty Cabin #2 | 3746 | 3002 | 52 | 0 | 957 | \$88,935 | 1958 | | | 2003 | 93.00 | 94.00 | \$6,225 | \$5,336 | \$889 | - | | |
| Faculty Cabin #3 | 3747 | 3003 | 52 | 0 | 957 | \$88,935 | 1939 | | | 2003 | 80.00 | 94.00 | \$17,787 | \$5,336 | \$12,451 | | | |
| Faculty Cabin #4 | 3748 | 3004 | 52 | 0 | 749 | \$69,605 | 1948 | | - | 2003 | 96.00 | 94.00 | \$2,784 | \$4,176 | \$0 | | | |
| Faculty Cabin #5 | 3749 | 3005 | 52 | 0 | 957 | \$88,935 | 1939 | | - | 2003 | 90.00 | 94.00 | \$8,894 | \$5,336 | \$3,557 | | | + |
| Faculty Cabin #6 | 3750 | 3005 | 52 | 0 | 637 | \$29,603 | 1972 | | | 2003 | 89.00 | 94.00 | \$3,256 | \$1,776 | \$1,480 | | | |
| Staff Duplex Cabin - A & B | 5146 | 3007 | 52 | 0 | 1,522 | \$335,486 | 1996 | | | 2003 | 100.00 | 94.00 | \$0,230 | \$20,129 | \$1,460 | | | |
| | 5147 | - | - | 0 | | | 1996 | | - | 2003 | 100.00 | 94.00 | \$0 | \$7,575 | | | | |
| Faculty Cabin #8 | - | 3008 | 52 | - | 768 | \$126,247 | | - | - | 2003 | | 94.00 | \$0 | | | | - | + |
| Faculty Cabin #9 | 5148 | 3009 | 52 | 0 | 768 | \$126,247 | 1996 | | | - | 100.00 | - | - | \$7,575 | | | | |
| Faculty Washhouse | 3756 | 3010 | 31 | 0 | 427 | \$52,909 | 1951 | | | 2003 | 80.00 | 94.00 | \$10,582 | \$3,175 | | | | |
| Storage Building | 3757 | 3018 | 31 | 0 | 306 | \$8,424 | 1972 | | | 2003 | 100.00 | 90.00 | \$0 | \$842 | \$0 | | | |
| Storage Building | 3758 | 3019 | 31 | 0 | 175 | \$4,818 | 1972 | | - | 2003 | 100.00 | 90.00 | \$0 | \$482 | \$0 | | | |
| Cabin | 3759 | 3020 | 52 | 0 | 410 | \$28,199 | 1972 | | - | 2003 | 100.00 | 94.00 | \$0 | \$1,692 | . \$0 | | | |
| Cabin | 3760 | 3021 | 52 | 0 | 443 | \$30,468 | 1972 | - | - | 2003 | 100.00 | 94.00 | \$0 | \$1,828 | \$0 | | | |
| Cabin | 3761 | 3022 | 52 | 100 | 460 | \$31,638 | 1972 | | - | 2003 | 49.00 | 94.00 | \$16,135 | \$1,898 | \$14,237 | | | |
| Koenig Homestead | 3762 | 3023 | 52 | 0 | 1,548 | \$106,468 | 1972 | | | 2003 | 100.00 | 94.00 | \$0 | \$6,388 | \$0 | | | |
| Storage Building | 3763 | 3024 | 31 | 0 | 255 | \$7,020 | 1972 | | | 2003 | 100.00 | 90.00 | \$0 | \$702 | \$0 | | | |

| | 1 0704 | 2005 | 50 | | 407 | 607.000 | 4070 | | 1 200 | 02 | 100.00 | 04.00 | 0.0 | 61 690 | \$0 | | | |
|-------------------------------------|--------|------|-----|-----|-------|-----------|------|---|-------|-----|--------|--------|-----------|----------|-----------|--|---|--|
| Cabin | 3764 | 3025 | 52 | 0 | 407 | \$27,992 | 1972 | | 200 | - | 100.00 | 94.00 | \$0 | \$1,680 | \$37,372 | | | |
| South Classroom | 3765 | 3026 | 10 | 100 | 1,508 | \$186,860 | 1963 | | 200 | - | 74.00 | 94.00 | \$48,584 | \$11,212 | | | | |
| South Dormitory | 3766 | 3027 | 50 | 0 | 4,382 | \$407,222 | 1961 | | 200 | - | 68.00 | 94.00 | \$130,311 | \$24,433 | \$105,878 | | | |
| The Cave | 3769 | 3028 | 40 | 0 | 146 | \$6,785 | 1923 | | 200 | - | 68.00 | 94.00 | \$2,171 | \$407 | \$1,764 | | | |
| Custodial Storage | 3770 | 3029 | 30 | 0 | 343 | \$26,562 | 1961 | | 20 | - | 94.00 | 90.00 | \$1,594 | \$2,656 | \$0 | | | |
| North Classroom | 3771 | 3030 | 10 | 100 | 2,545 | \$315,358 | 1923 | | 20 | _ | 74.00 | 94.00 | \$81,993 | \$18,921 | \$63,072 | | - | |
| Dining Hall | 3772 | 3031 | 60 | 0 | 5,297 | \$658,712 | 1961 | | 20 | | 99.00 | 94.00 | \$6,587 | \$39,523 | \$0 | | - | |
| Nurses Cabin | 3773 | 3032 | 52 | 0 | 341 | \$15,847 | 1939 | | 20 | _ | 85.00 | 94.00 | \$2,377 | \$951 | \$1,426 | | | |
| Ticonderoga Cabin | 3774 | 3033 | 52 | 0 | 344 | \$15,987 | 1961 | | 20 | _ | 93.00 | 94.00 | \$1,119 | \$959 | \$160 | | | |
| Grounds Shop | 3775 | 3034 | 30 | 0 | 347 | \$21,507 | 1950 | | 20 | _ | 100.00 | 94.00 | \$0 | \$1,290 | \$0 | | | |
| Recreation Hall | 3776 | 3035 | 40 | 0 | 2,055 | \$159,139 | 1949 | - | 20 | _ | 92.00 | 94.00 | \$12,731 | \$9,548 | \$3,183 | | | |
| Outhouse | 3777 | 3036 | 31. | 0 | 50 | \$24,092 | 1999 | | 20 | - | 100.00 | 90.00 | \$0 | \$2,409 | \$0 | | | |
| Pump House | 3778 | 3038 | 31 | 0 | 66 | \$2,047 | 1974 | | 20 | _ | 100.00 | 90.00 | \$0 | \$205 | \$0 | | | |
| Student Cabin | 3779 | 3045 | 52 | 0 | 340 | \$15,801 | 1956 | | 20 | _ | 93.00 | 94.00 | \$1,106 | \$948 | \$158 | | | |
| Student Cabin | 3780 | 3046 | 52 | 0 | 340 | \$15,801 | 1956 | | 20 | - | 93.00 | 94.00 | \$1,106 | \$948 | \$158 | | | |
| Student Cabin | 3781 | 3047 | 52 | 0 | 340 | \$15,801 | 1956 | | 20 | _ | 93.00 | 94.00 | \$1,106 | \$948 | \$158 | | | |
| Student Cabin | 3782 | 3048 | 52 | 0 | 340 | \$15,801 | 1956 | | 20 | - | 93.00 | 94.00 | \$1,106 | \$948 | \$158 | | | |
| Student Cabin | 3783 | 3049 | 52 | 0 | 340 | \$15,801 | 1957 | | 20 | - | 93.00 | 94.00 | \$1,106 | \$948 | \$158 | | | |
| Student Cabin | 3784 | 3050 | 52 | 0 | 353 | \$15,801 | 1957 | | 20 | - | 94.00 | 94.00 | \$948 | \$948 | \$0 | | | |
| Student Cabin | 3785 | 3051 | 52 | 0 | 353 | \$15,801 | 1958 | | 20 | _ | 92.00 | 94.00 | \$1,264 | \$948 | \$316 | | | |
| Student Cabin | 3786 | 3052 | 52 | 0 | 353 | \$15,801 | 1958 | | 20 | | 92.00 | 94.00 | \$1,264 | \$948 | \$316 | | | |
| North Dormitory | 5149 | 3053 | 50 | 0 | 5,282 | \$548,324 | 1996 | | 20 | - | 100.00 | 94.00 | \$0 | \$32,899 | \$0 | | | |
| Outhouse | 5150 | 3054 | 31 | 0 | 80 | \$4,910 | 1996 | | 20 | - | 74.00 | 90.00 | \$1,277 | \$491 | \$786 | | | |
| Staff Cabin | 5151 | 3055 | 52 | 0 | 2,792 | \$349,685 | 1996 | | 20 | - | 100.00 | 94.00 | \$0 | \$20,981 | \$0 | | | |
| Pingree Park Multipurpose Classroom | 8823 | 3056 | 10 | 0 | 3,910 | \$363,357 | 2000 | | 20 | 03 | 97.00 | 94.00 | \$10,901 | \$21,801 | \$0 | | | |
| Student Washhouse | 3789 | 3060 | 60 | 0 | 1,406 | \$65,331 | 1950 | | 20 | 03 | 100.00 | 94.00 | \$0 | \$3,920 | \$0 | | | |
| Student Cabin | 3790 | 3061 | 52 | 0 | 356 | \$16,542 | 1938 | | 20 | - | 70.00 | 94.00 | \$4,963 | \$993 | \$3,970 | | | |
| Student Cabin | 3791 | 3062 | 52 | 0 | 356 | \$16,542 | 1960 | | 20 | 03 | 70.00 | 94.00 | \$4,963 | \$993 | \$3,970 | | | |
| Student Cabin | 3792 | 3063 | 52 | 0 | 347 | \$16,124 | 1949 | | 20 | 103 | 69.00 | 94.00 | \$4,998 | \$967 | \$4,031 | | | |
| Student Cabin | 3793 | 3064 | 52 | 0 | 347 | \$16,124 | 1949 | | 20 | 03 | 69.00 | 94.00 | \$4,998 | \$967 | \$4,031 | | | |
| Student Cabin | 3794 | 3065 | 52 | 0 | 347 | \$16,124 | 1949 | | 20 | 03 | 69.00 | 94.00 | \$4,998 | \$967 | \$4,031 | | | |
| Student Cabin | 3795 | 3066 | 52 | 0 | 347 | \$16,124 | 1949 | | 20 | 03 | 69.00 | 94.00 | \$4,998 | \$967 | \$4,031 | | | |
| Student Cabin | 3796 | 3067 | 52 | 0 | 347 | \$16,124 | 1949 | | 20 | 03 | 69.00 | 94.00 | \$4,998 | \$967 | \$4,031 | | | |
| Student Cabin | 3797 | 3068 | 52 | 0 | 347 | \$16,124 | 1949 | | 20 | 03 | 69.00 | 94.00 | \$4,998 | \$967 | \$4,031 | | | |
| Student Cabin | 3798 | 3069 | 52 | 0 | 347 | \$16,124 | 1949 | | 20 | 03 | 69.00 | 94.00 | \$4,998 | \$967 | \$4,031 | | | |
| Student Cabin | 3799 | 3070 | 52 | 0 | 347 | \$16,124 | 1949 | | 20 | 03 | 69.00 | 94.00 | \$4,998 | \$967 | \$4,031 | | | |
| Student Cabin | 3800 | 3071 | 52 | 0 | 347 | \$16,124 | 1949 | | 20 | 03 | 69.00 | 94.00 | \$4,998 | \$967 | \$4,031 | | | |
| Student Cabin | 3801 | 3072 | 52 | 0 | 347 | \$16,124 | 1949 | | 20 | 03 | 69.00 | 94.00 | \$4,998 | \$967 | \$4,031 | | | |
| Student Cabin | 3802 | 3073 | 52 | 0 | 347 | \$16,124 | 1949 | | 20 | 003 | 60.00 | 94.00 | \$6,450 | \$967 | \$5,482 | | | |
| Student Cabin | 3803 | 3074 | 52 | 0 | 347 | \$16,124 | 1949 | | 20 | 003 | 69.00 | 94.00 | \$4,998 | \$967 | \$4,031 | | | |
| Student Cabin | 3804 | 3075 | 52 | 0 | 347 | \$16,124 | 1955 | | 20 | 003 | 60.00 | 94.00 | \$6,450 | \$967 | \$5,482 | | | |
| Student Cabin | 3805 | 3076 | 52 | 0 | 326 | \$15,148 | 1955 | | 20 | 003 | 57.00 | 94.00 | \$6,514 | \$909 | \$5,605 | | | |
| Winter Research Lab | 3806 | 3077 | 11 | 100 | 2,733 | \$380,990 | 1967 | | 20 | 003 | 74.00 | 94.00 | \$99,057 | \$22,859 | \$76,198 | | | |
| Hotchkiss Lodge | 3807 | 3080 | 50 | 0 | 4,681 | \$386,523 | 1975 | | 20 | 003 | 99.00 | 94.00 | \$3,865 | \$23,191 | \$0 | | | |
| Columbine | 3808 | 3081 | 50 | 0 | 1,536 | \$99,917 | 1975 | | 20 | 03 | 100.00 | 100.00 | \$0 | \$0 | \$0 | | | |
| Paintbrush | 5152 | 3082 | 50 | 0 | 2,160 | \$241,501 | 1996 | | 20 | 003 | 100.00 | 94.00 | \$0 | \$14,490 | \$0 | | | |
| Staff Duplex Cabin - A & B | 5153 | 3083 | 52 | 0 | 1,522 | \$335,486 | 1966 | | 20 | - | 100.00 | 94.00 | \$0 | \$20,129 | \$0 | | | |
| Blue Spruce | 5154 | 3084 | 50 | 0 | 2,160 | \$241,501 | 1996 | | 20 | 003 | 100.00 | 94.00 | \$0 | \$14,490 | \$0 | | | |
| Aspen | 5155 | 3085 | 50 | 0 | 2,160 | \$241,501 | 1996 | | 20 | 003 | 100.00 | 94.00 | \$0 | \$14,490 | \$0 | | | |
| | 5156 | 3086 | 50 | 0 | 2,160 | \$241,501 | 1996 | | 20 | 003 | 100.00 | 94.00 | \$0 | \$14,490 | \$0 | | | |

| Kinnikinnik | 5157 | 3087 | 50 | 0 | 2,160 | \$241,501 | 1996 | | T | 2003 | 100.00 | 94.00 | \$0 | \$14,490 | \$0 | | 1 | |
|--|------|------|----|-----|-----------|--------------------|------|---|---|------|----------------|-------|----------------|----------|------------|----------------|---|--|
| Lodgepole | 5158 | 3088 | 50 | 0 | 2,160 | \$241,501 | 1996 | | | 2003 | 100.00 | - | \$0 | \$14,490 | \$0 | | | |
| Outhouse | 5169 | 3089 | 60 | 0 | 50 | \$1,761 | 1996 | | | 2003 | 97.00 | _ | \$53 | \$176 | \$0 | | + | |
| Storage | 3816 | 3093 | 31 | 0 | 576 | \$10,700 | 1984 | | | 2003 | | - | \$3,852 | \$1,070 | \$2,782 | | | |
| Sewage Treatment Fac | 3817 | 3095 | 30 | 100 | 4,028 | \$875,968 | 1974 | | | 2003 | - | | \$315,348 | \$52,558 | \$262,790 | | | |
| Storage Barn | 3819 | 4001 | 31 | 100 | 1,008 | \$16,801 | 1983 | | | 2003 | 49.00 | | \$8,569 | \$1,680 | \$6,888 | | | |
| Storage | 3820 | 4002 | 31 | 100 | 3,248 | \$150,944 | 1963 | | | 2003 | | | \$76,981 | \$15,094 | \$61,887 | | | |
| Storage | 3821 | 4003 | 31 | 100 | 287 | \$6,217 | 1925 | | | 2003 | 49.00 | | \$3,171 | \$622 | \$2,549 | | | |
| Conference Center | 8824 | 4010 | 29 | 100 | 11,989 | \$1,180,876 | 2000 | | | 2003 | 95.00 | | \$59.044 | \$70.853 | \$0 | | | |
| Water Treatment Pump House | 8825 | 4011 | 30 | 100 | 300 | \$76,079 | 2000 | | | 2003 | 95.00 | | \$3,804 | \$7,608 | \$0 | | | |
| Cow/Calf Unit | 8826 | 4012 | 31 | 100 | 14,214 | \$817,525 | 2000 | | | 2003 | 95.00 | 90.00 | \$40,876 | \$81,753 | \$0 | | | |
| Covered Bale Hay Shed | 8827 | 4013 | 31 | 100 | 3,750 | \$76,079 | 2000 | | | 2003 | 95.00 | | \$3,804 | \$7,608 | \$0 | | | |
| Sheep Unit | 8828 | 4014 | 31 | 100 | 14,447 | \$705,811 | 2000 | | | 2003 | 95.00 | | \$35,291 | \$70,581 | \$0 | | | |
| Swine Units | 8829 | 4015 | 31 | 100 | 812 | \$34,317 | 2000 | | | 2003 | _ | - | \$1,716 | \$3,432 | \$0 | | | |
| Swine Units | 8821 | 4016 | 31 | 100 | 1,080 | \$45,643 | 2000 | | | 2003 | - | | \$2,282 | \$4,564 | \$0 | | | |
| Palpation Chutes | 8850 | 4018 | 31 | 100 | 1,200 | \$304,315 | 2000 | | | 2003 | - | | \$15,216 | \$30,432 | \$0 | | | |
| Palpation Chutes | 8842 | 4019 | 31 | 100 | 600 | \$50,973 | 2000 | | - | 2003 | 95.00 | | \$2,549 | \$5,097 | \$0 | | | |
| Animal Water Pump House | 8843 | 4021 | 31 | 100 | 300 | \$71,514 | 2000 | | | 2003 | | | \$3,576 | \$7,151 | \$0 | | | |
| Intensive Monogastric Ruminant Research | 8844 | 4022 | 11 | 100 | 9,000 | \$764,591 | 2000 | | - | 2003 | | | \$38,230 | \$45,875 | \$0 | | | |
| Feedlot Units | 8845 | 4023 | 31 | 100 | 10,417 | \$66,043 | 2000 | | - | 2003 | | | \$3,302 | \$6,604 | | | | |
| Central Mix/Diet Prep | 846 | 4024 | 31 | 100 | 2,500 | \$316,995 | 2000 | | | 2003 | | | \$15,850 | \$31,700 | \$0 | | | |
| Grain Bins | 8847 | 4025 | 31 | 100 | 128 | \$20,383 | 2000 | | - | 2003 | | | \$1,223 | \$2,038 | \$0 \$0 | | | |
| Grain Bins | 8848 | 4026 | 31 | 100 | 128 | \$20,383 | 2000 | | - | 2003 | | | \$1,223 | \$2,038 | \$0 | | | |
| Hay Feed Bunker | 8841 | 4028 | 31 | 100 | 2,119 | \$10,747 | 2000 | | - | 2003 | 94.00 | | \$645 | \$1,075 | | | | |
| Hay Feed Bunker | 8840 | 4029 | 31 | 100 | 4,290 | \$21,758 | 2000 | | - | 2003 | 95.00 | | \$1,088 | \$2,176 | \$0 \$0 | | | |
| Feed Storage | 8832 | 4030 | 31 | 100 | 2,160 | \$34,235 | 2000 | | | 2003 | 95.00 | | | | | | | |
| Scale House | 8833 | 4030 | 31 | 100 | 100 | \$3,170 | 2000 | | | | - | | \$1,712 | \$3,424 | \$0 | | | |
| Grain Bins | 5170 | 4031 | 31 | 100 | 42 | \$9,691 | 2000 | | | 2003 | | | \$159 | \$317 | \$0 | | | |
| Grain Bins | 5171 | 4032 | 31 | 100 | 42 | \$9,691 | | | - | 2003 | - | | \$581 | \$969 | \$0 | | | |
| Grain Bins | 5172 | 4033 | 31 | 100 | 21 | \$2,423 | 2000 | | | 2003 | | | \$581 | \$969 | \$0 | | | |
| Pump House | 8834 | 4034 | 31 | 100 | 50 | | 2000 | | - | 2003 | | | \$145 | \$242 | \$0 | | | |
| Pump House | 8835 | 4037 | 31 | 100 | 50 | \$1,078 | 2000 | | | 2003 | 95.00 | | \$54 | \$108 | \$0 | | | |
| Pump House | 8836 | 4039 | 31 | 100 | 50 | \$23,775 | 2000 | | - | 2003 | - | | \$1,189 | \$2,378 | \$0 | | | |
| Pump House | 0030 | 4039 | 31 | 100 | 177 | \$1,056 \$3,773 | 1980 | | - | | 95.00 | | \$53 | \$106 | \$0 | | | |
| Pump House | 5173 | 4041 | 31 | 100 | 74 | \$1,577 | 1980 | | | 2003 | 48.00 | | \$1,962 | \$377 | \$1,585 | | | |
| Pump House | 5174 | 4042 | 31 | 100 | 50 | \$1,066 | 1980 | | | | - | 90.00 | \$820 | \$158 | \$662 | | | |
| Pump House | 5175 | 4044 | 31 | 100 | 16 | \$341 | 1980 | | | 2003 | - | | \$554 | \$107 | \$448 | | | |
| Irrigation House | 5176 | 4045 | 31 | 100 | 80 | \$1,785 | 1980 | | | 2003 | 48.00 73.00 | | \$177 \$482 | \$34 | \$143 | | | |
| Residence | 3822 | 4045 | 52 | 100 | 2,669 | \$202,935 | | | - | | | | - | \$107 | \$375 | | | |
| Grain Bin | 3823 | 4050 | 31 | 100 | | \$5,447 | 1950 | | | 2003 | - | | \$52,763 | \$12,176 | \$40,587 | | | |
| Grain Bin | 5177 | 4051 | 31 | 100 | 65 540 | | 2000 | | - | | | - | \$1,416 | \$545 | \$872 | | | |
| Animal Science Shop | 3825 | 4052 | 31 | - | | \$72,136 | | | - | 2003 | 74.00 | | \$18,755 | \$7,214 | \$11,542 | | | |
| General Processing | | | | 100 | 2,560 | \$83,372 | 1950 | | | 2003 | 74.00 | 94.00 | \$21,677 | \$5,002 | \$16,674 | | | |
| Pump House | 7195 | 4054 | 31 | 100 | 24,771 | \$1,362,167 | 1992 | | - | 2003 | 93.00 | | \$95,352 | \$81,730 | \$13,622 | | 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 | |
| Grain Bin | 5178 | 4055 | 31 | 100 | 36 | \$1,173 | 1950 | | | 2003 | 49.00 | 90.00 | \$598 | \$117 | \$481 | | | |
| | | 4057 | 31 | 100 | 314 | \$14,411 | 2000 | | | 2003 | 74.00 | 90.00 | \$3,747 | \$1,441 | \$2,306 | | | |
| Foundation Seed Processing Machine Shed | 5179 | 4058 | 31 | 100 | 8,726 | \$291,272 | 1992 | | | 2003 | 74.00 | | \$75,731 | \$29,127 | \$46,604 | | | |
| | 7188 | 4060 | 31 | 100 | 30,000 | \$352,026 | 1992 | - | - | 2003 | | | \$24,642 | \$35,203 | \$0 | | | |
| Bulk/Soil Storage | 7189 | 4061 | 31 | 100 | 10,800 | \$181,588 | 1992 | - | | 2003 | 93.00 | | \$12,711 | \$18,159 | \$0 | | | |
| Fertilizer Storage | 7190 | 4062 | 31 | 100 | 800 | \$34,193 | 1992 | | | 2003 | 93.00 | 90.00 | \$2,394 | \$3,419 | \$0 | | | |
| Pesticide Storage | 7191 | 4063 | 31 | 100 | 240 | \$72,437 | 1992 | | | 2003 | 93.00 | 90.00 | \$5,071 | \$7,244 | \$0 | KIND HELD LINE | | |

| Pesticide Storage N | 7192 | 4064 | 31 | 100 | 320 | \$62,171 | 1992 | | | 2003 | 93.00 | 90.00 | \$4,352 | \$6,217 | \$0 | | | |
|-----------------------------|------|------|----|-----|-------|------------------------|------|---|---|------|-------|-------|----------|----------|-----------|---------------|---|---------|
| Pesticide Storage E | 7193 | 4065 | 31 | 100 | 320 | \$62,171 | 1992 | | | 2003 | 93.00 | 90.00 | \$4,352 | \$6,217 | \$0 | | | |
| Grain Bin | 5180 | 4066 | 31 | 100 | 384 | \$88,603 | 2000 | | | 2003 | _ | | \$23,037 | \$8,860 | \$14,176 | | | |
| Grain Bin | 5181 | 4067 | 31 | 100 | 200 | \$87,438 | 2000 | | | 2003 | | 90.00 | \$22,734 | \$8,744 | \$13,990 | | | |
| Grain Bin | 5182 | 4068 | 31 | 100 | 228 | \$24,920 | 2000 | | | 2003 | | | | \$2,492 | \$3,987 | | | |
| Well House | 5183 | 4069 | 31 | 100 | 30 | \$911 | 2001 | | | 2003 | | 90.00 | \$237 | \$91 | \$146 | | | |
| Lockman Residence | | 4070 | 52 | 0 | 3,118 | \$280,124 | 1999 | | | 2004 | _ | | | \$28,012 | \$21,850 | | | |
| Lockman Shop and Equipment | 7966 | 4071 | 31 | 100 | 5,090 | \$178,814 | 1999 | | | 2003 | | | | \$10,729 | \$1,788 | | | |
| Lockman Machine Shed / Shop | 7967 | 4072 | 31 | 100 | 2,045 | \$28,623 | 1999 | | | 2003 | - | | | \$1,717 | \$286 | | | |
| Lockman Utility Shed | 7969 | 4074 | 31 | 100 | 263 | \$3,322 | 1999 | | | 2003 | | | | \$332 | \$0 | CONTRACTOR IN | | |
| Lockman Granary | 7970 | 4075 | 31 | 100 | 1,600 | \$31,581 | 1999 | | | 2003 | | | | \$3,158 | \$0 | | | |
| Lockman Pump House | 8837 | 4076 | 31 | 100 | 10 | \$126 | 1999 | | | 2003 | | | | \$13 | \$52 | | | |
| Headquarters | 3830 | 4101 | 31 | 100 | 2,357 | \$292,062 | 1969 | | | 2003 | _ | - | | \$17,524 | \$58,412 | | | |
| Storage | 3831 | 4102 | 31 | 100 | 1,510 | \$116,934 | 1970 | | | 2003 | | _ | | \$11,693 | \$47,943 | 0.000 | | |
| Dormitory | 3832 | 4103 | 50 | 100 | 1,042 | \$96,834 | 1969 | | | 2003 | | - | | \$5,810 | \$29,050 | | | |
| Pump House | 3833 | 4104 | 31 | 100 | 112 | \$2,426 | 1969 | | | 2003 | _ | _ | - | \$243 | \$995 | | | |
| Residence | 3834 | 4105 | 52 | 100 | 1,615 | \$150,083 | 1970 | | | 2003 | | | | \$9,005 | \$45,025 | | | |
| Tack Room | 3835 | 4106 | 31 | 100 | 86 | \$1,863 | 1969 | - | - | 2003 | | | | \$186 | \$764 | | | - |
| Shed | 3836 | 4107 | 31 | 100 | 580 | \$12,564 | 1969 | | | 2003 | | | | \$1,256 | \$5,151 | | | |
| Shed | 3837 | 4108 | 31 | 100 | 576 | \$12,478 | 1969 | | | 2003 | | | | \$1,248 | \$5,116 | | | |
| Radiation Control | 3838 | 4109 | 11 | 100 | 125 | \$19,362 | 1968 | | - | 2003 | - | _ | | \$1,936 | \$6,002 | | | |
| | 3839 | 4302 | 31 | 100 | 6,735 | \$312,996 | 1955 | | - | 2003 | | | | \$18.780 | \$109.549 | | | |
| Processing Residence | 3840 | 4302 | 52 | 0 | 2,042 | \$189,764 | 1967 | | - | 2003 | | | | \$11,386 | \$66,417 | | | |
| Shop-Machine Storage | 3841 | 4303 | 31 | 100 | 2,882 | \$133,935 | 1965 | | | 2003 | _ | | | \$8,036 | \$60,271 | | | |
| Pesticide Storage | 5184 | 4304 | 31 | 100 | 290 | \$46,840 | 2000 | - | - | 2003 | | | | \$2,810 | \$0 | | | |
| Pump House | 3842 | 4305 | 31 | 100 | 81 | \$1,755 | 1983 | | | 2003 | - | | | \$176 | \$720 | | | |
| Pump House | 3843 | 4307 | 31 | 100 | 83 | \$1,798 | 1955 | | | 2003 | | _ | | \$180 | \$737 | | | |
| | 3844 | 4601 | 52 | 0 | 2,194 | \$124,854 | 1900 | | | 2007 | 66,30 | | | \$7,491 | \$34,585 | | | |
| Residence | 3845 | 4602 | 31 | 100 | 1,600 | \$72,841 | 1932 | | - | 2007 | 75.00 | | | \$7,284 | \$10,926 | | | M90030 |
| Onion Storage | 3846 | 4603 | 31 | 100 | 3,055 | \$156,490 | 1956 | | | 2007 | 76.30 | | | \$15.649 | \$21,439 | | | M90030 |
| Utility Storage | 3847 | - | 11 | | | | 1964 | | | 2007 | 86.40 | | | \$10,181 | \$12,896 | | | M90030 |
| Animal Disease Lab | 3848 | 4604 | 11 | 100 | 2,293 | \$169,687 \$145,185 | 1964 | | | 2007 | 80.20 | | | \$8,711 | \$20,036 | | | VI30030 |
| Entomology Lab/Grnhs | 3849 | 4606 | 11 | 100 | 188 | \$17,118 | 1966 | | | 2007 | 78.80 | | | \$1,027 | \$2,602 | | , | M90030 |
| Insectary | 3850 | 4608 | 31 | 100 | 145 | \$6,601 | 1975 | | | 2007 | 65.40 | - | | \$660 | \$1,624 | | | M90030 |
| Storage Shed | | - | | - | | | | | | | 77.20 | | | \$496 | \$634 | | | M90030 |
| Sheep Shed | 3851 | 4609 | 31 | 100 | 145 | \$4,955 | 1975 | | - | 2007 | 71.80 | | | \$736 | \$1,340 | | | VI90030 |
| Chemical Storage | 7171 | 4610 | 31 | 100 | 240 | \$7,360 | 1991 | | | 2007 | | - | | \$3,233 | \$1,340 | | | |
| Pesticide Shed | 5185 | 4611 | 31 | 100 | 153 | \$32,330 | 2000 | | - | 200 | 85.50 | | | \$5,685 | | | | |
| Machine Shed | 5186 | 4612 | 31 | 100 | 2,400 | \$56,845 | 1998 | | | 200 | 83.30 | | | | \$3,809 | | | |
| Animal Quarters | 3852 | 4613 | 31 | 100 | 273 | \$10,869 | 1975 | | - | 200 | 71.60 | - | | \$1,087 | | | | 400020 |
| Adobe Shed | 5007 | 4614 | 31 | 100 | 1,440 | \$31,987 | 1930 | | | 200 | 61.20 | | | \$3,199 | \$9,212 | | | V90030 |
| Pesticide Storage | 5188 | 4619 | 31 | 100 | 153 | \$32,330 | 2000 | | - | 2003 | | - | | \$3,233 | | | | |
| Supplementation Barn | 5019 | 4620 | 31 | 100 | 2,688 | \$19,075 | 1989 | | - | 200 | 65.40 | | | \$1,908 | \$4,692 | | | |
| Office | 3853 | 4621 | 16 | 100 | 909 | \$51,729 | 1957 | | - | 200 | 66.70 | - | | \$3,104 | \$14,122 | | | |
| Calving Shed | 3854 | 4622 | 31 | 100 | 2,700 | \$92,272 | 1920 | | - | 2007 | 76.60 | | | \$9,227 | \$12,364 | | | |
| Grain Storage | 3855 | 4623 | 31 | 100 | 133 | \$4,464 | 1983 | | | 200 | 82.40 | | | \$446 | \$339 | | | |
| Grain Storage | 3856 | 4624 | 31 | 100 | 133 | \$4,464 | 1983 | | | 2007 | 81.90 | | | \$446 | \$362 | | | |
| Vehicle Shed | 3857 | 4625 | 31 | 100 | 1,261 | \$42,324 | 1983 | | | 200 | 68.30 | | | \$4,232 | \$9,184 | | | |
| Feed Storage | 3858 | 4626 | 31 | 100 | 1,261 | \$42,324 | 1983 | | | 200 | 52.10 | - | | \$4,232 | \$16,041 | | | |
| Barn | 3859 | 4627 | 31 | 100 | 1,031 | \$35,234 | 1920 | | | 2007 | 59.60 | | | \$3,523 | \$10,711 | | | |
| North Residence | 3860 | 4628 | 52 | 0 | 2,301 | \$130,943 | 1957 | | | 200 | 69.30 | 94.00 | \$40,200 | \$7,857 | \$32,343 | | | |

| South Residence | 3861 | 4629 | 52 | 0 | 2,356 | \$134,073 | 1957 | | 2007 | 65.40 | 94.00 | \$46,389 | \$8,044 | \$38,345 | | |
|-----------------------|------|------|----|-----|------------|---------------------|------|--|------|----------------|-------|------------------|----------|--------------|-------|----------|
| Bunkhouse | 3862 | 4630 | 31 | 100 | 1,987 | \$113,075 | 1910 | | 2007 | 65.60 | 94.00 | \$38,898 | \$6,785 | \$32,113 | | |
| Shop/Storage | 3863 | 4631 | 31 | 100 | 2,100 | \$95,604 | 1945 | | 2007 | 69.00 | 94.00 | \$29,637 | \$5,736 | \$23,901 | | M90030 |
| Garage | 3864 | 4632 | 31 | 100 | 436 | \$19,849 | 1940 | | 2007 | 65.20 | 90.00 | \$6.907 | \$1,985 | \$4,923 | | 14130030 |
| ab/Storage | 3865 | 4633 | 31 | 100 | 1,004 | \$45,708 | 1945 | | 2007 | 64.60 | 94.00 | \$16,181 | \$2,742 | \$13,438 | | |
| Pump House | 3866 | 4634 | 31 | 100 | 39 | \$4,256 | 1983 | | 2007 | 57.80 | 90.00 | \$1,796 | \$426 | \$1,370 | | |
| Office/Shop | 3867 | 4635 | 31 | 100 | 2,400 | \$136,577 | 1977 | | 2007 | 85.70 | 94.00 | \$19,531 | \$8,195 | \$11,336 | | |
| Pesticide Storage | 5188 | 4636 | 31 | 100 | 153 | \$32,330 | 2000 | | 2007 | 93.00 | 90.00 | \$2,263 | \$3,233 | \$0 | | |
| CSFS-Golden/Trailer | 3879 | 4653 | 31 | 100 | 1,525 | \$38,418 | 1980 | | 2005 | 62.80 | 94.00 | \$14,291 | \$2,305 | \$11,986 | | M90030 |
| Residence | 3881 | 4701 | 52 | 100 | 2,550 | \$145,113 | 1963 | | 2007 | 71.60 | 94.00 | \$41,212 | \$8,707 | \$32,505 | | 10190030 |
| Office/Machine Shop | 3882 | 4702 | 16 | 100 | 1,696 | \$86,876 | 1962 | | 2007 | 80.10 | 94.00 | \$17,288 | \$5,213 | \$12,076 | | M90030 |
| Machine Shed | 3883 | 4703 | 31 | 100 | 3.007 | \$136,896 | 1967 | | 2007 | 84.60 | 90.00 | \$21,082 | \$13,690 | \$0 | | 10190030 |
| Greenhouse | 3884 | 4704 | 31 | 100 | 1,467 | \$66,783 | 1977 | | 2007 | 84.20 | 94.00 | \$10.552 | \$4,007 | \$6,545 | | M90030 |
| Laboratory/Offices | 3885 | 4705 | 16 | 100 | 4,132 | \$467,315 | 1982 | | 2007 | 82.80 | 94.00 | \$80,378 | \$28,039 | \$52,339 | | M90030 |
| Pole Barn | 3886 | 4706 | 31 | 100 | 2,880 | \$120,863 | 1983 | | 2007 | 89.40 | 90.00 | \$12,811 | \$12,086 | \$0 | | |
| Pesticide Storage | 5190 | 4706 | 31 | 100 | 2,880 | \$38,553 | 2000 | | 2007 | 92.10 | 90.00 | \$3,046 | \$3,855 | \$0 | | M90030 |
| Anim, Diagnostic Lab | 3887 | 4707 | 11 | 100 | 2,758 | \$282,552 | 1973 | | 2007 | 78.70 | 94.00 | \$60,184 | \$16,953 | \$43,230 | | |
| Barn | 3888 | 4711 | 31 | 100 | 2,063 | \$70,503 | 1940 | | 2007 | 80.90 | 90.00 | \$13,466 | \$7,050 | \$6,416 | | M90030 |
| Machine Shed | 5002 | - | 31 | 100 | 2,063 | \$4,494 | 1940 | | 2007 | 49.00 | 90.00 | \$2,292 | \$449 | \$1,843 | | 10190030 |
| Machine Shed | 3889 | 4722 | 31 | 100 | 1.024 | \$46,618 | 1973 | | 2007 | 79.30 | 90.00 | \$9,650 | \$4,662 | \$4,988 | | M90030 |
| | 3890 | 4724 | 16 | 100 | 2,611 | \$165,088 | 1938 | | 2007 | 81.50 | 94.00 | \$30,541 | \$9,905 | \$20,636 | | M90030 |
| Administration | | | - | - | | \$22,763 | 1930 | | 2007 | 77.60 | 94.00 | \$5,099 | \$1,366 | \$3,733 | | 10190030 |
| Bunkhouse | 3891 | 4725 | 31 | 100 | 400 | | - | | | | 90.00 | | | | | |
| Pesticide Storage | 5191 | 4726 | 31 | 100 | 153 154 | \$32,330 \$7,011 | 1940 | | 2007 | 87.60 86.40 | 90.00 | \$4,009 \$953 | \$3,233 | \$0 \$252 | | |
| Grain Bin | 3894 | 4729 | 31 | 100 | | | - | | | | - | | \$701 | | | 1400000 |
| Seed Conditioning | 5160 | 4730 | 31 | 100 | 7,000 | \$361,273 | 1982 | | 2007 | 85.40 | 94.00 | \$52,746 | \$21,676 | \$31,069 | | M90030 |
| Grain Bin | 7182 | 4731 | 31 | 100 | 154 | \$2,576 | 1991 | | 2007 | 86.40 | 90.00 | \$350 | \$258 | \$93 | | |
| Grain Bin | 7178 | 4732 | 31 | 100 | 154 | \$2,576 | 1991 | | 2007 | 86.40 | 90.00 | \$350 | \$258 | \$93 | | |
| Residence | 3896 | 4741 | 52 | 0 | 2,414 | \$137,374 | 1941 | | 2007 | 71.70 | 94.00 | \$38,877 | \$8,242 | \$30,634 | | |
| Barn | 3897 | 4742 | 31 | 100 | 957 | \$32,705 | 1939 | | 2007 | 72.40 | 90.00 | \$9,027 | \$3,271 | \$5,756 | | |
| Packing Shed | 3898 | 4743 | 31 | 100 | 1,465 | \$66,695 | 1941 | | 2007 | 67.10 | 90.00 | \$21,943 | \$6,670 | \$15,273 | | 1400000 |
| Office/Laboratory | 3899 | 4744 | 16 | 100 | 4,826 | \$357,113 | 1962 | | 2007 | 79.20 | - | \$74,280 | \$21,427 | \$52,853 | | M90030 |
| Storage Shed | 3900 | 4745 | 31 | 100 | 885 | \$40,290 | 1962 | | 2007 | 65.70 | 90.00 | \$13,819 | \$4,029 | \$9,790 | | |
| Greenhouse | 3903 | 4748 | 11 | 100 | 1,205 | \$54,856 | 1962 | | 2007 | 88.40 | 94.00 | \$6,363 | \$3,291 | \$3,072 | | |
| Shop And Shed | 3905 | 4750 | 31 | 100 | 2,448 | \$111,447 | 1962 | | 2007 | 83.30 | 94.00 | \$18,612 | \$6,687 | \$11,925 | | 1400000 |
| Headhouse/Insectary | 3906 | 4751 | 11 | 100 | 1,598 | \$145,493 | 1962 | | 2007 | 84.00 | 94.00 | \$23,279 | \$8,730 | \$14,549 | | M90030 |
| Tank | 7194 | 4756 | 31 | 100 | 472 | \$3,822 | 1962 | | 2003 | 49.00 | 90.00 | \$1,949 | \$382 | \$1,567 | | |
| Viticulture Pumphouse | 7343 | 4757 | 31 | 100 | 124 | \$2,724 | 1971 | | 2007 | 82.70 | 90.00 | \$471 | \$272 | \$199 | | |
| Model 10 Pest. Strg. | 7344 | 4758 | 31 | 100 | 63 | \$14,723 | 1987 | | 2007 | 91.60 | 90.00 | \$1,237 | \$1,472 | (\$236) | | |
| Pesticide Storage | 5192 | 4759 | 31 | 100 | 222 | \$38,553 | 1992 | | 2007 | 91.60 | 90.00 | \$3,238 | \$3,855 | (\$617) | | |
| Residence | 3910 | 4781 | 52 | 0 | 1,214 | \$69,085 | 1963 | | 2007 | 61.10 | 94.00 | \$26,874 | \$4,145 | \$22,729 | | |
| New Cellar | 3911 | 4783 | 31 | 100 | 9,033 | \$411,235 | 1950 | | 2007 | 82.60 | 90.00 | \$71,555 | \$41,124 | \$30,431 | D00:- | |
| Office/Lab | 3912 | 4784 | 16 | 100 | 4,236 | \$314,889 | 1968 | | 2007 | 76.30 | 94.00 | \$74,629 | \$18,893 | \$55,735 | P0016 | |
| Lab/Storage | 3913 | 4785 | 11 | 100 | 2,809 | \$162,509 | 1960 | | 2003 | 86.85 | 94.00 | \$21,370 | \$9,751 | \$11,619 | | |
| Machine Shop | 3914 | 4786 | 31 | 100 | 4,381 | \$199,449 | 1964 | | 2007 | 86.20 | 94.00 | \$27,524 | \$11,967 | \$15,557 | P0016 | |
| Pump House | 3915 | 4787 | 31 | 100 | 237 | \$10,790 | 1952 | | 2007 | 77.00 | 90.00 | \$2,482 | \$1,079 | \$1,403 | | |
| Garage | 3916 | 4788 | 31 | 100 | 1,898 | \$86,408 | 1952 | | 2007 | 85.60 | 90.00 | \$12,443 | \$8,641 | \$3,802 | | M90030 |
| Pesticide Storage | 5193 | 4790 | 31 | 100 | 290 | \$46,840 | 2000 | | 2007 | 94.20 | 90.00 | \$2,717 | \$4,684 | \$0 | | |
| Greenhouse/Headhouse | 7325 | 4791 | 11 | 100 | 10,027 | \$246,325 | 1993 | | 2007 | 88.10 | 94.00 | \$29,313 | \$14,780 | \$14,533 | | |
| Tool Shed | 3919 | 4792 | 31 | 100 | 121 | \$5,509 | 1952 | | 2007 | 77.90 | 90.00 | \$1,217 | \$551 | \$667 | | |
| Gas House | 3920 | 4793 | 31 | 100 | 204 | \$9,287 | 1952 | | 2007 | 77.90 | 90.00 | \$2,052 | \$929 | \$1,124 | | |

| Crain Din | 3921 | 4794 | 31 | 100 | 254 | \$11,564 | 1960 | | 2007 | 80.70 | 90.00 | \$2,232 | \$1,156 | \$1,075 | | | 1 |
|-------------------------|--------------|------|-----|-----|-------|-----------|------|---|------|----------------|-------|---------------------|-------------------|-----------|--|---------|----|
| Grain Bin Grain Bin | 3921 | 4794 | 31 | 100 | 154 | \$7,011 | 1960 | | 2007 | 80.20 | 90.00 | \$1,388 | \$701 | \$687 | | | + |
| Grain Bin | 3923 | 4796 | 31 | 100 | 154 | \$7,011 | 1960 | | 2007 | 80.70 | 90.00 | \$1,353 | \$701 | \$652 | | | +- |
| Administration | 3923 | 4821 | 16 | 100 | 4,030 | \$229,336 | 1921 | | 2007 | 80.90 | 94.00 | \$43,803 | \$13,760 | \$30,043 | | | |
| Library | 3925 | 4822 | 17 | 100 | 4,277 | \$243,392 | 1938 | | 2007 | 68.50 | 94.00 | \$76,668 | \$14,604 | \$62,065 | | | |
| Storage Shed | 3926 | 4824 | 31 | 100 | 153 | \$32,330 | 2000 | | 2007 | 68.50 | 90.00 | \$10,184 | \$3,233 | \$6,951 | | | - |
| Bus Garage | 3928 | 4826 | 30 | 100 | 3,500 | \$159,340 | 1918 | | 2003 | 54.00 | 90.00 | \$73,296 | \$15,934 | \$57,362 | | | - |
| Dwelling 19 | 3930 | 4830 | 52 | 0 | 4,470 | \$103,343 | 1920 | | 2007 | 76.50 | 94.00 | \$24,286 | \$6,201 | \$18,085 | | | |
| Dwelling 12 | 3931 | 4831 | 52 | 100 | 1,816 | \$89,970 | 1920 | | 2007 | 57.40 | 94.00 | \$38,327 | \$5,398 | \$32,929 | | | - |
| | 3932 | 4832 | 52 | 0 | 1,581 | \$135,496 | 1920 | | 2007 | 83.50 | 94.00 | \$22,357 | \$8,130 | \$14,227 | | | |
| Dwelling 13 Dwelling 14 | 3933 | 4833 | 52 | 0 | 2,381 | \$131,683 | 1920 | | 2007 | 87.10 | 94.00 | \$16,987 | \$7,901 | \$9,086 | | | |
| | 3934 | 4834 | 52 | 0 | 2,314 | \$116,830 | 1920 | | 2007 | 69.40 | 94.00 | \$35,750 | \$7,010 | \$28,740 | | | - |
| Dwelling 15 | 3935 | 4836 | 52 | 0 | 2,604 | \$148,186 | 1920 | | 2007 | 69.60 | 94.00 | \$45,049 | \$8,891 | \$36,157 | | | - |
| Dwelling 18 | 3936 | 4837 | 52 | 0 | 4,193 | \$238,607 | 1920 | | 2007 | 71.60 | 94.00 | \$67,764 | \$14,316 | \$53,448 | | | |
| Dwelling 10 | | - | 52 | 100 | 4,193 | \$23,901 | 1962 | | 2007 | 69.60 | 94.00 | \$7,266 | \$1,434 | \$5,832 | | | |
| Dwelling 20 | 3937 | 4838 | | | 3,519 | \$160,205 | 1902 | | 2007 | 69.60 | 90.00 | \$48,702 | \$16,021 | \$32,682 | | | - |
| Garage | 3938 3939 | 4840 | 31 | 100 | 240 | \$10,205 | 1920 | | 2007 | 79.90 | 90.00 | \$2,196 | \$1,093 | \$1,104 | | | |
| Gas And Oil Building | 3939 | 4841 | 31 | 100 | 5,825 | \$199,069 | 1895 | | 2007 | 64.20 | 90.00 | \$71,267 | \$19,907 | \$1,104 | | | |
| Dairy Barn | 3940 | 4844 | 31 | 100 | 1,500 | \$68,289 | 1920 | | 2007 | 71.10 | 94.00 | \$19,736 | \$4,097 | \$15,638 | | | - |
| Farm Shop | | - | | - | | | | - | 2007 | | - | | | \$35,785 | | | - |
| Horse Barn | 3942 | 4845 | 31 | 100 | 6,196 | \$211,748 | 1920 | - | | 73.10 68.80 | 90.00 | \$56,960 \$2,187 | \$21,175 \$701 | \$1,486 | | | - |
| Silo | 3943 | 4846 | | 100 | 154 | \$7,011 | 1920 | - | 2007 | | 90.00 | \$95,505 | \$30,416 | \$65.090 | | | - |
| Cattle Shed | 3944 | 4847 | 31 | 100 | 8,900 | \$304,157 | 1920 | | 2007 | 68.60 | | | | | | | - |
| Scale House | 3945 | 4848 | 31 | 100 | 795 | \$36,193 | 1970 | | 2007 | 77.60 | 90.00 | \$8,107 | \$3,619 | \$4,488 | | | - |
| Bull Barn | 3946 | 4849 | 31 | 100 | 6,830 | \$233,415 | 1935 | | 2007 | 74.10 | 90.00 | \$60,454 | \$23,342 | \$37,113 | | | |
| Granary | 3947 | 4850 | 31 | 100 | 3,000 | \$136,577 | 1895 | | 2007 | 55.10 | 90.00 | \$61,323 | \$13,658 | \$47,665 | | | - |
| Calf Shed | 3948 | 4851 | 31 | 100 | 480 | \$16,404 | 1920 | | 2007 | 71.30 | 90.00 | \$4,708 | \$1,640 | \$3,068 | | | - |
| Pump House | 3949 | 4853 | 31 | 100 | 640 | \$29,137 | 1920 | | 2007 | 68.90 | 90.00 | \$9,062 | \$2,914 | \$6,148 | | | - |
| Hay Barn | 3950 | 4857 | 31 | 100 | 2,560 | \$99,572 | 1980 | | 2007 | 78.80 | 90.00 | \$21,109 | \$9,957 | \$11,152 | | | |
| Pole Barn | 3951 | 4858 | 31 | 100 | 1,400 | \$47,845 | 1960 | | 2007 | 76.90 | 90.00 | \$11,052 | \$4,785 | \$6,268 | | | - |
| Pole Barn | 3952 | 4859 | 31 | 100 | 2,400 | \$82,020 | 1960 | | 2007 | 76.90 | 90.00 | \$18,947 | \$8,202 | \$10,745 | | | - |
| Pole Barn | 3953 | 4860 | 31 | 100 | 2,800 | \$95,690 | 1970 | | 2007 | 76.90 | 90.00 | \$22,104 | \$9,569 | \$12,535 | | | - |
| Cattle Shed | 3954 | 4861 | 31 | 100 | 512 | \$17,498 | 1960 | | 2007 | 74.30 | 90.00 | \$4,497 | \$1,750 | \$2,747 | | | - |
| Cattle Shed | 3955 | 4862 | 31 | 100 | 420 | \$14,353 | 1960 | | 2007 | 73.50 | 90.00 | \$3,804 | \$1,435 | \$2,368 | | | |
| Cattle Shed | 3956 | 4863 | 31 | 100 | 360 | \$12,303 | 1960 | | 2003 | 49.00 | 90.00 | \$6,275 | \$1,230 | \$5,044 | | | - |
| Shop | 3957 | 4880 | 31 | 100 | 1,600 | \$61,231 | 1982 | | 2007 | 99.00 | 94.00 | \$612 | \$3,674 | (\$3,062) | | | |
| Office . | 3958 | 4881 | 16 | 100 | 2,304 | \$119,041 | 1983 | | 2003 | 88.22 | 94.00 | \$14,023 | \$7,142 | \$6,881 | | | - |
| Pole Barn | 8838 | 4882 | 16 | 100 | 1,800 | \$22,824 | 2000 | | 2007 | 88.30 | 90.00 | \$2,670 | \$2,282 | \$0 | | | - |
| Pesticide Storage | 8839 | 4883 | 31 | 100 | 153 | \$32,330 | 2000 | | 2007 | 92.80 | 90.00 | \$2,328 | \$3,233 | \$0 | | | - |
| Hay Barn | 8831 | 4884 | 31 | 100 | 5,615 | \$23,495 | 2000 | | 2003 | 98.00 | 90.00 | \$470 | \$2,350 | \$0 | | 1400000 | |
| Laboratory/Office | 3960 | 4891 | 11 | 100 | 6,042 | \$447,122 | 1969 | | 2007 | 80.70 | 94.00 | \$86,295 | \$26,827 | \$59,467 | | M90030 | - |
| Greenhouse | 3961 | 4892 | 11 | 100 | 1,000 | \$45,524 | 1969 | | 2007 | 86.20 | 94.00 | \$6,282 | \$2,731 | \$3,551 | | | |
| Shop/Storage | 3962 | 4893 | 31 | 100 | 2,430 | \$110,628 | 1976 | | 2007 | 81.40 | 94.00 | \$20,577 | \$6,638 | \$13,939 | | | - |
| Scale House | 3963 | 4894 | .31 | 100 | 336 | \$15,297 | 1976 | | 2007 | 84.80 | 90.00 | \$2,325 | \$1,530 | \$795 | | | |
| Animal Shelter | 3965 | 4896 | 31 | 100 | 800 | \$3,581 | 1986 | | 2007 | 63.10 | 90.00 | \$1,321 | \$358 | \$963 | | 4 | |
| Residence/Duplex | 3966 | 4901 | 52 | 100 | 3,169 | \$180,339 | 1920 | | 2003 | 64.00 | 94.00 | \$64,922 | \$10,820 | \$54,102 | | | |
| Residence | 3967 | 4902 | 52 | 100 | 4,064 | \$231,271 | 1920 | | 2003 | 34.00 | 94.00 | \$152,639 | \$13,876 | \$138,763 | | | |
| Office/Lab | 3968 | 4903 | 16 | 100 | 5,714 | \$357,728 | 1848 | | 2003 | 34.00 | 94.00 | \$236,100 | \$21,464 | \$214,637 | | | |
| Garage | 3969 | 4905 | 31 | 100 | 513 | \$23,355 | 1920 | | 2003 | 34.00 | 90.00 | \$15,414 | \$2,336 | \$13,079 | | | |
| Machine Shed | 3970 | 4906 | 31 | 100 | 2,027 | \$92,281 | 1946 | | 2003 | 34.00 | 90.00 | \$60,905 | \$9,228 | \$51,677 | | | |
| Garage/Onion Drying | 3971 | 4907 | 31 | 100 | 3,866 | \$176,003 | 1948 | | 2003 | 34.00 | 90.00 | \$116,162 | \$17,600 | \$98,562 | | | |

| Potato Cellar | 3972 | 4908 | 31 | 100 | 3,053 | \$138,990 | 1920 | | 2003 | 34.0 | 90.0 | 00 | \$91,733 | \$13,899 | \$77,834 | | | T |
|------------------------------|------|---------|----|-----|-------|-----------|------|--|------|--------|----------|---------|-------------|----------|---------------|--|--------|---|
| Pump House | 3973 | 4910 | 31 | 100 | 122 | \$5,554 | 1936 | | 2003 | 34.0 | 90.0 | 00 | \$3,666 | \$555 | \$3,110 | | | 1 |
| Machine Shed | 3975 | 4912 | 31 | 100 | 1,555 | \$70,793 | 1948 | | 2003 | 34.0 | 90.0 | 00 | \$46,723 | \$7,079 | \$39,644 | | | 1 |
| Well House | 3976 | 4913 | 31 | 100 | 71 | \$3,232 | 1950 | | 2003 | 34.0 | 90.0 | 00 | \$2,133 | \$323 | \$1,810 | | | 1 |
| Office Building | 5011 | 4914 | 16 | 100 | 2,333 | \$158,248 | 1991 | | 2007 | 82.9 | 94.0 | 00 | \$27,060 | \$9,495 | \$17,566 | | | T |
| Radome | 5012 | 4915 | 11 | 100 | 3,706 | \$189,950 | 1991 | | 2007 | 95.5 | 94.0 | 00 | \$8,548 | \$11,397 | (\$2,849) | | | T |
| CSFS-Alamosa/Shop | 3977 | 6021 | 31 | 100 | 2,000 | \$37,152 | 1978 | | 2007 | 74.3 | 94.0 | 00 | \$9,548 | \$2,229 | \$7,319 | | | T |
| CSFS - Boulder Office | 5195 | 6131 | 16 | 100 | 1,867 | \$454,456 | 2001 | | 2006 | 95.5 | 94.0 | 00 | \$20,451 | \$27,267 | \$0 | | | |
| CSFS - Boulder Shop | | 6132 | 31 | 100 | 1,573 | \$27,218 | 2001 | | 2006 | 99.6 | 94. | 00 | \$109 | \$1,633 | \$0 | | | 1 |
| CSFS-Franktown Office/Garage | 7939 | 6341 | 16 | 100 | 3,540 | \$122,214 | 1963 | | 2006 | 78.5 | 94. | 00 | \$26,276 | \$7,333 | \$18,943 | | | T |
| CSFS-Canon City/Off. | 3980 | 6421 | 16 | 100 | 1,440 | \$219,638 | 1978 | | 2007 | 75.0 | 94. | 00 | \$54,910 | \$13,178 | \$41,731 | | M90030 | T |
| CSFS-Canon City/Stor | 3981 | 6422 | 31 | 100 | 2,400 | \$44,585 | 1978 | | 2007 | 75.2 | 90. | 00 | \$11,057 | \$4,459 | \$0 | | | T |
| CSFS-La Veta/Office | 3982 | 6541 | 16 | 100 | 775 | \$14,989 | 1978 | | 2007 | 75.0 | 94. | 00 | \$3,747 | \$899 | \$2,848 | | | T |
| CSFS-La Veta/Storage | 3983 | 6542 | 31 | 100 | 720 | \$13,375 | 1978 | | 200 | 7308. | 90. | 00 | (\$964,070) | \$1,338 | \$0 | | | T |
| CSFS-Durango/Storage | 3985 | 6662 | 31 | 100 | 2,000 | \$38,682 | 1978 | | 200 | 79.2 | 90. | 00 | \$8,046 | \$3,868 | \$4,178 | | | |
| CSFS-Durango/Office | 5203 | 6664 | 16 | 100 | 1,821 | \$295,043 | 1999 | | 200 | 82.3 | 94. | 00 | \$52,223 | \$17,703 | \$34,520 | | | T |
| CSFS Ft Morgan/Offc. | 5144 | 6863 | 16 | 100 | 2,607 | \$278,807 | 1967 | | 2000 | 74.5 | 94. | 00 | \$71,096 | \$16,728 | \$54,367 | | | T |
| CSFS - Woodland Storage | 3993 | 7182 | 31 | 100 | 2,304 | \$42,809 | 1978 | | 200 | 83.2 | 94. | 00 | \$7,192 | \$2,569 | \$4,623 | | | T |
| CSFS Woodland Office - # 1 | 7184 | 7183 | 16 | 100 | 609 | \$36,807 | 1971 | | 200 | 43.5 | 0 94. | 00 | \$20,796 | \$2,208 | \$18,588 | | | 1 |
| CSFS Woodland Main Office | 5145 | 7184 | 16 | 100 | 1,848 | \$277,341 | 1995 | | 200 | 83.4 | 0 94. | 00 | \$46,039 | \$16,640 | \$29,398 | | | |
| | | 9/4/201 | | | | | | | | Buildi | ng Estir | nated l | Backlog | | \$134,720,987 | | | |

| R&M | |
|------------|--|
| Janitorial | |
| R&G | |
| Utilities | |
| | |

| GSF | Expenses | \$/GSF |
|------------|--------------|--------|
| 5,084,811 | \$6,779,436 | \$1.33 |
| 5,084,811 | \$4,472,976 | \$0.88 |
| 11,918,248 | \$1,253,886 | \$0.11 |
| 5,408,845 | \$12,427,944 | \$2.30 |

Building Estimated Backlog Code Compliance Estimated Backlog Total Estimated Backlog \$137,104,985

\$2,383,998

2.11 INSTRUCTIONS FOR THE AGENCY'S OPERATION AND MAINTENANCE COST (FORM SBREP CM-07, Excel Spreadsheet, New 5/05)

This new worksheet was part of the building inventory, but SBREP decided it should be a separate worksheet.

The agency's abbreviation, form title, current date, and page numbering is done automatically by the spreadsheet.

Blank

Repair and Maintenance:

1):

Expenditures for the general repairs and maintenance of buildings and supporting infrastructure including piped distribution systems and central power plants. Includes both in-house salaries for operating engineers and maintenance personnel, and contracted services such as elevator, HVAC, electrical, structural/roof, plumbing, fire and life safety expenses and other maintenance and supplies. For institutions of higher education, this category does not include expenditures made from institutional plant funds.

- a) Enter total gross square feet (GSF) of all agency general funded buildings, as applicable. For specific building complexes or sites, provide additional breakdown if known.
- b) Enter actual agency repairs and maintenance expenses for FY2004/2005.
- a) Enter cost per agency GSF determined by dividing the repair and maintenance annual expenses "b" by the agency's GSF "a".

Blank

Janitorial:

2):

Expenditures from both daytime and nighttime cleaning of all general funded buildings internal areas. Include expenses categories such as salaries for in-house janitorial personnel, contract services for both routine and special cleaning (window washing, carpet cleaning), trash removal, supplies and miscellaneous cleaning expenses.

- a) Enter total gross square feet (GSF) of all agency general funded buildings, as applicable.
- b) Enter actual agency janitorial expenses for FY2004/2005.
- c) Enter cost per agency GSF determined by dividing the janitorial annual expenses "b" by the agency's GSF "a".

Blank 3) Roads and Grounds:

Expenditures related to the exterior maintenance of general funded buildings (such as the landscaping, snow removal, parking lot repairs, site signage, site lighting, etc). Includes salaries for inhouse roads and grounds personnel as well as contract services for specified duties and supplies (fertilizer, ice melt chemicals). Parking area maintenance is included in this area only for those lots

that do not chare a parking fee.

- a) Enter total gross square feet (GSF) or acreage, of all agency general funded site(s) areas, as applicable.
- b) Enter actual agency road and grounds expenses for FY2004/2005.
- c) Enter cost per agency GSF (or acres) determined by dividing the roads and grounds annual expenses "b" by the agency's GSF "a".

Blank 4):

Utilities:

Expenditures for utilities (whether purchased or produced/generated locally) for general funded buildings including natural gas, electricity, water, sewage, and fuel oil. Do not include telecommunication utilities.

- a) Enter total gross square feet (GSF) of all agency general funded buildings, as applicable.
- b) Enter actual agency utilities expenses for FY2004/2005.
- c) Enter cost per agency GSF determined by dividing the utilities "b" by the agency's GSF "a".

| | a) GSF | b) Expenses \$ | c) \$/GSF |
|--------------------------------|------------|----------------|-----------|
| Repair & Maintenance - Blank 1 | 5,084,811 | \$6,779,436 | \$1.33 |
| Janitorial - Blank 2 | 5,084,811 | \$4,472,976 | \$0.88 |
| Roads & Grounds - Blank 3 | 11,918,248 | \$1,253,886 | \$0.11 |
| Utilities -Blank 4 | 5,408,845 | \$12,427,944 | \$2.30 |

Page __1_ of _3__

| 3) Date | | gust 2008 | 2) Depa | artment <u>ni</u> | gner Education | | |
|------------------|------------------------|---|--|----------------------------|---------------------------------|------------------------------|--------------------------|
| | | | | Agency Priority # AP | Operational Criteria x OC | Criticality Index x CI | Project Score = PS |
| 4) Proj M# | 4) Agency ID NO. | | 6) PROJ. ESTIMATE \$ | 7) Nos. 1-5 | 8) Nos. 1-3 | 9) | 10) |
| 06057 | | Replace Environmental Control System | | 1 | 1 | | |
| | | Phase _3_of _3_ | | | | | |
| | | Total Project Cost: Prior Appropriation: Current Year Request: Project Balance: | \$989,028 \$611,894 \$377,134 \$0 | | | | |
| 06056 | | Replace Steam & Condensate-North Line | | 1 | 1 | | |
| | | Phase _3_of _3_ | | | | | |
| | | Total Project Cost: Prior Appropriation: Current Year Request: Project Balance: | \$2,599,406 \$1,169,079 \$1,430,327 \$0 | | | | |
| | 98-166 | Sanitary Sewer Improvements | | 1 | 1 | | |
| | | Phase _2_of _3_ | | | | | |
| | | Total Project Cost: Prior Appropriation: Current Year Request: Project Balance: | \$2,035, \$639,852 \$697,840 \$697,840 | | | | |
| | | ^A Current-Year CM Total \$ | | | | | |
| | | ^A FY 2008/2009 CM Total \$ | | | | | |
| | | ^A FY 2009/2010 CM Total \$ | | | | | |
| | | ^A FY 2010/2011 CM Total \$ | | | | | |
| | | ^A FY 2011/2012 CM Total \$ | | | | | |
| | | M Plan (Short-Term Needs) \$ | | | | | |
| | | Building Maintenance Total \$ | | | | | |
| | | d Infrastructure Maintenance Total \$ | | | | | |
| ETot | al Non-P | rioritized (Long-Term) Needs | | | | | |

| | | 100 AND REAL ESTATE | | Agency Priority # AP | Operational Criteria x OC | Criticality Index x CI | Project Score = PS |
|------------------|------------------------|---|--|----------------------------|---------------------------------|------------------------|--------------------------|
| 4) Proj M# | 4) Agency ID NO. | 5) PROJECT TITLE and PHASE | 6) PROJ. ESTIMATE \$ | 7) Nos. 1-5 | 8) Nos. 1-3 | 9) | 10) |
| | 00-005 | Replace Failed Roofing | | 1 | 1 | | |
| | | Phase _1_of _2_ | | | | | |
| | | Total Project Cost: Prior Appropriation: Current Year Request: Project Balance: | \$3,377,550 \$0 \$1,992,100 \$1,385,450 | | | | |
| | 03-124 | Replace Inadequate Ventilation System – Painter Center | | 1 | 1 | | |
| | | Phase _1_of_1_ | | | | | |
| | | Total Project Cost: | \$1,887,883 | | | | |
| | | Prior Appropriation: Current Year Request: Project Balance: | \$0 \$1,887,883 \$0 | | | | |
| | 98-086 | Replace Unsafe Overhead Electrical Service – Foothills | | 1 | 1 | | |
| | | Phase _1_of _2_ Total Project Cost: Prior Appropriation: Current Year Request: Project Balance: | \$1,690,304 \$0 \$1,156,210 \$534,094 | | | | |
| | 08-086 | Replace Inadequate Ventilation Systems and Failing Electrical & Mechanical Systems - Visual Arts | | 1 | 1 | | |
| | The state of | Phase _1_of _3_ | | | | | |
| | | Total Project Cost: Prior Appropriation: Current Year Request: Project Balance: | \$3,168,165 \$0 \$439,725 \$2,728,440 | | | | |
| | 99-005 | Replace Heating, Cooling, Electrical, and Architectural Items Engineering Research Center | | 1 | 1 | | |
| | | Phase _1_of _2_ Total Project Cost: Prior Appropriation: Current Year Request: Project Balance: | \$3,102,930 \$0 \$1,551,465 \$1,551,465 | | | | |

| | STATE | 03-12 | | Direct Digital Control System Conversion Phase _1_of _3_ Total Project Cost: | \$1,290,418 | 1 | 1 | |
|---|--|-----------|-----|--|---|---|---|--|
| | | | | Prior Appropriation: Current Year Request: Project Balance: | Britanian Company of the Company of | | | |
| | | | 1 | Current-Year CM Total \$ | | | | |
| | | | , | ^A FY 2008/2009 CM Total \$ | | | | |
| | | | , | ^A FY 2009/2010 CM Total \$ | | | | |
| | | | , | ^A FY 2010/2011 CM Total \$ | | | | |
| | | | , | ^A FY 2011/2012 CM Total \$ | | | | |
| В | ^B Total Five Year CM Plan (Short-Term Needs) \$ | | | | | | | |
| ſ | ^c Non-P | rioritize | d B | uilding Maintenance Total \$ | | | | |
| | D Non-Prioritized Infrastructure Maintenance Total \$ | | | | | | | |
| | ^E Total Non-Prioritized (Long-Term) Needs | | | | | | | |

Page 3 of 3

1) Agency Colorado State University 2) Department Higher Education

3) Date August 2007

| | | | | Agency Priority # AP | Operational Criteria x OC | Criticality Index x Cl | Project Score = PS |
|------------------|------------------------|--|--|----------------------------|---------------------------------|------------------------------|--------------------------|
| 4) Proj M# | 4) Agency ID NO. | 5) PROJECT TITLE and PHASE | 6) PROJ. ESTIMATE \$ | 7) Nos. 1-5 | 8) Nos. 1-3 | 9) | 10) |
| | 03-121 | Improve Fire Alarm Systems for Additional Life Safety and Code Compliance Phase _1_of _2_ | ¢4 204 270 | 1 | 1 | | |
| | | Total Project Cost: Prior Appropriation: Current Year Request: Project Balance: | \$1,284,376 \$0 \$499,617 \$784,759 | | | | |
| | 03-121 | Replace Deteriorated Electrical and Mechanical - Guggenheim | | 1 | 1 | | |
| | | Phase _1_of _2_ Total Project Cost: Prior Appropriation: Current Year Request: Project Balance: | \$1,776,070 \$0 \$572,000 \$1,204,070 | | | | |

| | A Current-Year CM Total \$ | \$ 10,629,719 |
|--|---------------------------------------|---------------|
| | ^A FY 2010/2011 CM Total \$ | \$10,609,614 |
| | ^A FY 2011/2012 CM Total \$ | \$6,861,573 |
| | ^A FY 2012/2013 CM Total \$ | \$5,398,343 |
| | ^A FY 2013/2014 CM Total \$ | \$11,681,851 |
| Total Five Ye | ear CM Plan (Short-Term Needs) \$ | \$45,181,100 |
| ^c Non-Prior | tized Building Maintenance Total \$ | \$179,805,936 |
| D Non-Prioritized Infrastructure Maintenance | | \$218,701,387 |
| | Total \$ | |
| Total I | Non-Prioritized (Long-Term) Needs | \$410,532,469 |

AGENCY ASSET MANAGEMENT MAINTENANCE STRATEGY FY 2009/2010 STATE BUILDINGS AND REAL ESTATE PROGRAMS

Page _1_of _1_

| 1) Agency: | Colorado State University |
|-----------------|---------------------------|
| 2) Department: | Higher Education |
| 3) Prepared by: | Dewey Wearne |
| 4) Date: | August 2008 |

#1. Please describe your agency's overall strategy for maintaining and upgrading the condition of your general funded buildings and related infrastructure as supported by your current Facilities Audit Process and indicated in the Five Year Controlled Maintenance Plan. (For example is the intent to upgrade as funding allows, by criticality, by building, by system, by infrastructure, by complex or by a combination of these components). Please provide examples of project requests taken directly from your current Controlled Maintenance Five Year Plan.

We use our Facilities Audit Program to develop each building's Facilities Conditions Index, plus we have a Utilities Audit. Based on these audits, we determine which building, utilities, and system to improve. We then break it down into areas with the System Component Index. We look at the building or utilities first, system second, and individual piece of equipment third. For example, the chiller may need to be replaced in lieu of the whole system. Most of our building repairs fall into more than one system, Visual Arts for example; we document numerous systems and individual items. The Fire Alarm project replaces panels and other parts that we can't maintain anymore without newer components. The Chemistry fume hood replacement project replaces old fume hoods only that don't meet safety standards.

#2. Please describe how your agency coordinates the Five Year Controlled Maintenance Plan with routine and preventative maintenance programs and, the Capital Construction Five Year Plan including Capital Renewal project requests.

Our routine maintenance plan tackles small maintenance and extends the life of equipment and smaller parts. Preventative maintenance is done on various systems but not all. Mechanical filters, belts and oil are changed on a regular bases. This helps us determine if a piece of equipment is failing. Electrical switches on the utilities are tested every six months. Routine preventative maintenance feeds into our Audit program, helping us to decide which project to forward into controlled maintenance.

#3. Please identify any other internal or external maintenance funding sources and the amount of annual funding that your agency receives by source to address buildings and infrastructure deficiencies and emergency needs and, describe how these are coordinated with your Five Year Controlled Maintenance Plan. (Note that this does not refer to line-item operating budgets for routine maintenance and utilities, but availability of other internal funds and funding sources such as, student fees, revenues, gifts, grants, bond financing, federal, state or local funds, etc.)

We have no other funding sources for maintenance. The University General fund, and/or Student Fees, will sometimes line item a project for maintenance.

#4. If your agency has auxiliary funded buildings or buildings funded through other sources, is there a similar Facilities Audit Process and Five Year Deferred Maintenance Plan to address building and infrastructure deficiencies and describe how these are identified and coordinated with your Five Year Controlled Maintenance Plan?

Our Auxiliaries have an Audit program that identifies their deficiencies. The Auxiliary is responsible for all of their maintenance. They must keep their buildings equivalent to University Standard Facilities Conditions Index (Range 68-78). Auxiliary building maintenance projects are coordinated at the Administrative, Vice- President level. Facilities Management utility engineers cover all utilities.

| A. AGENCY BASIC DATA: | | | | | | | |
|--|---------|--------------|-------------|-------------------|---------------|-------------|--------|
| x Controlled Mainter | ance | Request | | oital Re quest | enewal Buildi | ng/Infrastr | ucture |
| 1) Agency Colorado Sta | te Univ | ersity | | | | | |
| 2) Department Higher Educa | ation | | | | | | |
| 3) Physical Plant ID No. 1- | 04 | | | | Project M # | | |
| 4) Agency Priority # 1 | | | | | | | |
| 5) Project Title Replace Envi | ronme | ntal Control | System - | Phase 3 | 3 of 3 | | |
| B. FACILITY PROFILE | | | | | | | |
| 1) Facility Type Site (Utilities underground) | | | | | | | |
| or Site (Improvements above ground) | | | | | | | |
| | | ne (s) | | | | | |
| | | lg(s) ID# | | | | | |
| | | Foothills C | | | | 3 3 3 3 3 | |
| 3) Facility Area/Age GSF S | | | ASF S | See Belo | w Date | Built See | Below |
| 4) Facility Functional Use/Occupancy See Below | | | | | | | |
| 5) Facility Construction (Type) | | | | | | | |
| 6) Facility Physical Condition an | | | n Index (FC | CI) Num | ber See Below | | |
| Actual FCI = See Below | | | | | | t Audit 200 | 5 |
| (Describe) | Risk | GSF | ASF D | ate Built | Occupancy | Const. Type | FCI |
| Chemistry | 3339 | 168,037 | 102,587 | 1971 | Science | II-FR | 69.70 |
| Andrew G. Clark | 3276 | 254,792 | 137,463 | 1967 | Classroom/off | ice II-FR | 66.26 |
| Engineering | 3217 | 211,410 | 134,650 | 1957 | Engineering | II-1HR | 87.76 |
| Gifford | 3343 | 92,278 | 59,453 | 1975 | Science | II-1HR | 72.85 |
| Glover | 3269 | 52,823 | 33,369 | 1950 | Engineering | II-1HR | 84.51 |
| Auditorium Gymnasium | 3209 | 280,438 | 170,644 | 1966 | Physical Ed. | II-FR | 71.07 |
| Natural Resources | 3262 | 73,027 | 45,856 | 1975 | Science | II-1HR | 74.91 |
| Visual Arts | 3341 | 91,997 | 71,132 | 1973 | Fine Arts | II-1HR | 77.61 |
| AIDL | 3668 | 14,329 | 8,979 | 1964 | Science | II-1HR | 68.84 |
| Animal Sciences | 3305 | 40,412 | 27,253 | 1959 | | II-1HR | 54.00 |
| ARBL | 3653 | 41,288 | 24,903 | 1964 | | V-N | 84.87 |
| Atmospheric Science | 3575 | 37,079 | | 1967 | | II-1HR | 72.55 |
| Aylesworth Hall | 3204 | 87,523 | | 1956 | | | 66.11 |
| CETT | 3669 | | 13,042 | 1966 | | II-1HR | 68.19 |
| Engineering Research Center | | | 134,490 | 1962 | | II-1HR | 67.98 |
| Plant Sciences | 3278 | 82,725 | | | | II-1HR | 94.29 |
| GSB | 3287 | 74,907 | 49,821 | 1948 | | III-N | 69.93 |
| John E. Painter | 3338 | 31,139 | 12,688 | | Science | II-1HR | 82.35 |
| Spruce Hall | 3238 | 18,738 | 11,797 | 1881 | Office | III-N | 82.55 |

|) Facility - Current Replacement Va | ue See Below : | |
|-------------------------------------|---|--------------|
| | Chemistry | \$30,717,752 |
| | Andrew G. Clark | \$27,170,356 |
| | Engineering | \$88,463,627 |
| | Gifford | \$9,491,678 |
| | Glover | \$7,508,990 |
| | Auditorium Gymnasium | \$34,334,080 |
| | Natural Resources | \$9,529,096 |
| | Visual Arts | \$9,149,865 |
| | AIDL | \$1,754,132 |
| | Animal Sciences | \$5,541,047 |
| | ARBL | \$7,162,031 |
| | Atmospheric Science | \$3,825,793 |
| | Aylesworth Hall | \$10,667,224 |
| | CETT | \$1,514,262 |
| | Engineering Research Center | \$22,840,480 |
| | Plant Sciences | \$9,493,501 |
| | GSB | \$11,462,561 |
| | John E. Painter | \$4,187,707 |
| | Spruce Hall | \$1,691,706 |
|) Master Plan Status - Check one o | r more of the followina: | |
| a) Facility 'useful' life is less | | |
| b) x Facility 'useful' life is more | | |
| c) Master Plan is obsolete; | | |
| madel Flam to excellete, | (by OSPB/CCHE) | |
| | novations, or program revisions are ongoing or ease explain below if these facility renovations on his CM request.) | |
| may have an impact on the | iis own request.) | |
| | | |
| | | |

| | | | | Page _ | _3_ | of_ | _6 |
|----------------------|--|---------------------|-------------------|-------------------|----------------------------|---------|-------|
| 10) Facility Audit S | Survey: | | | | | | |
| a) Facility A | udit Survey concluded a | and submitted to S | BREP - | Date | 200 |)5 | |
| b) Status of | the Infrastructure Asse | ssment. | | % Completed | 50 | | |
| c) Facility A | udit Survey Cycle | 5/2 | | | | | |
| | ntrolled maintenance, ca or ongoing projects that | | | s CM building | or infra | astruc | cture |
| Project No. P0017 | Project Title Plant Science Renova | ation | | | Compl or stat June 0 | us | date |
| 1 00 17 | Traint Coloride Traine v | 3001 | | | | | |
| | | | | | | | |
| | | | | | | | |
| C. INTEGRATE | D PROGRAM PLAN | DATA | | | | | |
| | ital Renewal Building/In ed to support the reque | | est, refer to the | instructions for | the ac | dditio | nal |
| 1) Narrative Descr | ription of CM Problem (| Initial problem and | I solution by pha | ise): | | | |
| | s have are controlled w | | | | n does | s not | |
| interface with t | he University's digital co | ontrol system. Sir | ice the pneumat | ic systems are | not al | arme | |
| | do not report to the cent uipment and closed roo | | | | | | 9 |
| are difficult to | obtain and maintenance | costs are high. | All pneumatic co | mponents will I | | | |
| with digital con | nponents that match the | e existing Johnson | Controls Metas | sys system. | | | |
| | | | | | | | |
| 2) Total Project Co | ost Estimate (From Cos | st Breakdown) \$ | 989,028 | | | | |
| 3) Consequences | (cost effects, program | impacts facility in | nacts etc.) of n | ot funding and | iustify | vina th | nis |
| | t request: Energy costs | | | | | | |
| | oneumatic systems are | | | | | | |
| component fail | ures have caused dam | age to mechanica | l equipment. Thi | is results in eve | en high | her | |
| maintenance c | osts. | | | | | | |
| | | | | | | | |
| | = | | | L. Landarda etta | | f | |
| | clude Facility Audit doc project request. | umentation from i | nost recent audi | t. Include site | maps | ior a | пу |
| | de photographs and an | y other supporting | documents. | | | | |
| | how this project will imp | | | on index or imp | prove a | а | |
| | ructure system. | | | | | | |
| | | | | | | | |

| D. <u>DETAILED COST ESTIMATE</u> (detail by phase, one | e page per ph | Page4 of6 ase, include all phases) | State of the state |
|--|---------------|---------------------------------------|--|
| 1) Approved By Dewey Wearne | 2) Phase? | 3 | |
| 3) Method of Estimate Historic | | | |
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | | | |
| Code Review/Inspection | | | |
| Other (Explain) | | | |
| Total of Professional Services | | \$0 | |

5) Construction Improvement

| WORK ITEM (Labor/Material/Equipment) | UNIT | UNIT COST | EXTENDED COST |
|--------------------------------------|------|-----------|---------------|
| Structure/System/Components | | | |
| Visual Arts | | | |
| Receiver controller | EA | \$5,214 | \$10,428 |
| Valves/actuators | EA | \$665 | \$3,990 |
| Programming | LS | \$3,162 | \$3,162 |
| AIDL | - 20 | Ψ0,102 | Ψ0,102 |
| Receiver controller | EA | \$5,214 | \$26,070 |
| Valves/actuators | EA | \$665 | \$9,310 |
| Programming | LS | \$6,197 | \$6,197 |
| Animal Sciences | | | |
| Receiver controller | EA | \$5,214 | \$15,642 |
| Valves/actuators | EA | \$665 | \$4,655 |
| Programming | LS | \$975 | \$975 |
| ARBL | | | |
| Receiver controller | EA | \$5,214 | \$26,070 |
| Valves/actuators | EA | \$665 | \$9,310 |
| Programming | LS | \$5,650 | \$5,650 |
| Aylesworth Hall | | | |
| Receiver controller | EA | \$5,214 | \$20,856 |
| Valves/actuators | EA | \$665 | \$6,650 |
| Programming | LS | \$1,795 | \$1,795 |
| CETT | | | |
| Receiver controller | EA | \$5,214 | \$31,284 |
| Valves/actuators | EA | \$665 | \$11,305 |
| Programming | LS | \$5,113 | \$5,113 |
| Engineering Research Center | | A | |
| Receiver controller | EA | \$5,214 | \$26,070 |
| Valves/actuators | EA | \$665 | \$8,645 |
| Programming | LS | \$4,016 | \$4,016 |

| Plant Sciences | | | |
|------------------------------------|-------|---------|-----------|
| Receiver controller | EA | \$5,214 | \$36,498 |
| Valves/actuators | EA | \$665 | \$12,635 |
| Programming | LS | \$5,722 | \$5,722 |
| General Services | | | |
| Receiver controller | EA | \$5,214 | \$10,428 |
| Valves/actuators | EA | \$665 | \$3,325 |
| Programming | LS | \$429 | \$429 |
| John E. Painter Center | | | |
| Receiver controller | EA | \$5,214 | \$5,214 |
| Valves/actuators | EA | \$665 | \$1,330 |
| Programming | LS | \$774 | \$774 |
| Spruce Hall | | | |
| Receiver controller | EA | \$5,214 | \$20,856 |
| Valves/actuators | EA | \$665 | \$6,650 |
| Programming | LS | \$1,795 | \$1,795 |
| Total of Construction Improvements | Costs | | \$342,849 |

6) Miscellaneous (explain)

| Total of Miscellaneous Costs | | \$0 |
|------------------------------|--|-----|

7) Project Contingency

| 7)110,360,000 | |
|---|----------|
| Contingency (10% CM) (Percentage of total of professional services, | \$34,285 |
| construction improvements, and miscellaneous costs.) | |

8) Subtotal of professional services, construction improvements, miscellaneous costs, and project contingency percentage (by phase) \$377,134

| | THE RESERVE AND THE PARTY OF TH |
|---|--|
| 9) TOTAL PROJECT COST (all phases)= REQUEST | \$989,028 |

Note: Agency formatted cost estimates may accompany this page.

| = 550 | DOOED I | | | Page _ | _6 of6_ |
|---------------------------------|-----------------------|--|---------------------------------|--|--------------|
| | PHASING | PHASING | | | |
| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Actual Appropriation) | |
| | 1-04 | FY 2006/2007 | 1 | \$267,121 | |
| | | | | \$ 267,121 | _ (Subtotal) |
| CURRE | NT PHAS | SE ² REQUESTED | | | |
| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase of Work | Dollar Amount (Per Detailed Budget) | |
| | 1-04 | FY 2007/2008 | 2 | \$344,773 | |
| FUTUR | E PHASI | NG^2 | | \$ 344,773 | _ (Subtotal) |
| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Per Detailed Budget) | |
| | 1-04 | FY 2009/2010 | 3 | \$377,134 | |
| | | | | \$ 377,134 | _ (Subtotal) |
| | | ar Amount of All Pro and Future Phases) | pjects Phases Requested | \$ 989,028 | - |
| reques ² List all | ted amour | nt. | propriation by year (include fe | | |
| F. PRO | POSED I | PROJECT IMPLEM | ENTATION SCHEDULE (| PLAN): | |
| | F | PHASE | FROM | | ТО |
| | esign (Ins | | July 07 | | |
| | n (Insert D | | Dec 07 | May 08 | |
| | | sert Dates) | May 08 | May 09 | |
| 4. Projec | ct Close-o | ut/Final Completion | May 10 | July 11 | |
| G. AGE | NCY AP | PROVAL | | | |
| Agency | Authorized | d Signature | | D | ate |

Building Name: Arthropod-Borne & Infectious Disease Lab Number: 1421

Construction Date: 1964 Gross Square Feet: 14,329 Net Square Feet: 11,914

Date of Audit: 04/09/2007 Cycle: 6 Phase: 1 No. of Stories: 1

Classification: M150 College, Laboratory SBP Class: 11 Science

Replacement Cost: \$1,783,424.60 Cost Per SF: \$124.46

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1500 | 0.07 | 0.0105 | \$18,725.96 |
| Ext Walls | 0.2000 | 0.06 | 0.0120 | \$21,401.10 |
| Floors | 0.2500 | 0.07 | 0.0175 | \$31,209.93 |
| Roof | 0.2500 | 0.06 | 0.0150 | \$26,751.37 |
| Ceiling | 0.4000 | 0.03 | 0.0120 | \$21,401.10 |
| Int Walls | 0.6000 | 0.09 | 0.0540 | \$96,304.94 |
| Windows | 0.5000 | 0.02 | 0.0100 | \$17,834.25 |
| Doors | 0.5000 | 0.02 | 0.0100 | \$17,834.25 |
| Cool Vent | 0.3200 | 0.06 | 0.0208 | \$37,095.23 |
| Heat | 0.3800 | 0.06 | 0.0247 | \$44,050.59 |
| Plumbing | 0.3900 | 0.14 | 0.0546 | \$97,374.99 |
| Electrical | 0.6540 | 0.07 | 0.0458 | \$81,645.18 |
| Safety | 0.3500 | 0.02 | 0.0070 | \$12,483.97 |
| AE/OP | 0.2939 | 0.18 | 0.0529 | \$94,340.31 |

Component Deficiency Total:

Outstanding Maintenance:

0.3468

\$618,453.14

Facilities Condition Index (FCI):

65.32

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

Building Name: Animal Sciences

Number: 0110

Construction Date: 1959

Gross Square Feet: 40,412 Net Square Feet: 35,974

Date of Audit: 11/29/2004 Cycle: 5 Phase: 2 No. of Stories: 2

Classification: M150 College, Laboratory

SBP Class: 11 Science

Replacement Cost:

\$5,541,046.93

Cost Per SF: \$137.11

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1000 | 0.07 | 0.0070 | \$38,787.33 |
| Ext Walls | 0.1700 | 0.06 | 0.0102 | \$56,518.68 |
| Floors | 0.3500 | 0.07 | 0.0245 | \$135,755.65 |
| Roof | 0.7000 | 0.06 | 0.0420 | \$232,723.98 |
| Ceiling | 0.9000 | 0.03 | 0.0270 | \$149,608.26 |
| Int Walls | 0.3000 | 0.09 | 0.0270 | \$149,608.28 |
| Windows | 0.8000 | 0.02 | 0.0160 | \$88,656.75 |
| Doors | 0.4000 | 0.02 | 0.0080 | \$44,328.38 |
| Cool Vent | 0.5000 | 0.05 | 0.0250 | \$138,526.18 |
| Heat | 0.9500 | 0.08 | 0.0760 | \$421,119.55 |
| Plumbing | 0.4100 | 0.14 | 0.0574 | \$318,056.09 |
| Electrical | 0.7300 | 0.07 | 0.0511 | \$283,147.48 |
| Convey | 0.1000 | 0.01 | 0.0010 | \$5,541.05 |
| Safety | 0.4000 | 0.02 | 0.0080 | \$44,328.38 |
| AE/OP | 0.3802 | 0.21 | 0.0798 | \$442,408.25 |

Component Deficiency Total:

0.4600

Outstanding Maintenance:

\$2,549,114.27

Facilities Condition Index (FCI):

54.00

 $FCI = (I-Component Deficiency Total) \times 100$

Building Name: Atmospheric Science

Number: 1120

Construction Date: 1967

Gross Square Feet: 37,079

Net Square Feet: 31,042

Date of Audit: 03/26/2007 Cycle: 6 Phase: 1 No. of Stories: 4

Classification: M460 Office Building

SBP Class: 11 Science

Replacement Cost:

\$4,594,410.69

Cost Per SF: \$123.91

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.2000 | 0.02 | 0.0040 | \$18,377.64 |
| Ext Walls | 0.3500 | 0.09 | 0.0315 | \$144,723.94 |
| Floors | 0.3000 | 0.16 | 0.0480 | \$220,531.72 |
| Roof | 0.3000 | 0.03 | 0.0090 | \$41,349.70 |
| Ceiling | 0.2500 | 0.05 | 0.0125 | \$57,430.13 |
| Int Walls | 0.2000 | 0.05 | 0.0100 | \$45,944.11 |
| Windows | 0.6000 | 0.02 | 0.0120 | \$55,132.93 |
| Doors | 0.6000 | 0.05 | 0.0300 | \$137,832.33 |
| Cool Vent | 0.1800 | 0.09 | 0.0153 | \$70,294.48 |
| Heat | 0.1800 | 0.09 | 0.0153 | \$70,294.48 |
| Plumbing | 0.3000 | 0.02 | 0.0060 | \$27,566.46 |
| Electrical | 0.3980 | 0.12 | 0.0478 | \$219,429.05 |
| Convey | 0.2000 | 0.03 | 0.0060 | \$27,566.46 |
| Safety | 0.2500 | 0.01 | 0.0025 | \$11,486.03 |
| AE/OP | 0.2499 | 0.18 | 0,0450 | \$206,632.71 |

Component Deficiency Total:

0.2948

Outstanding Maintenance:

\$1,354,592.16

Facilities Condition Index (FCI):

70.52

FCI = (1-Component Deficiency Total) x 100

Building Name: Aylesworth Hall

Number: 0021

Construction Date: 1956

Gross Square Feet: 86,723

Net Square Feet: 79,996

Date of Audit: 09/15/2003 Cycle: 4 Phase: 4 No. of Stories: 3

Classification: M460 Office Building

SBP Class: 10 Classroom/Office

Replacement Cost:

\$8,948,460.72

Cost Per SF: \$103.18

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1100 | 0.02 | 0.0022 | \$19,686.61 |
| Ext Walls | 0.0900 | 0.09 | 0.0081 | \$72,482.53 |
| Floors | 0.2500 | 0.16 | 0.0400 | \$357,938.42 |
| Roof | 0.4500 | 0.03 | 0.0135 | \$120,804.21 |
| Ceiling | 0.8000 | 0.05 | 0.0400 | \$357,938.44 |
| Int Walls | 0.3000 | 0.05 | 0.0150 | \$134,226.92 |
| Windows | 0.9000 | 0.02 | 0.0180 | \$161,072.30 |
| Doors | 0.6000 | 0.05 | 0.0300 | \$268,453.84 |
| Cool Vent | 0.6000 | 0.17 | 0.1020 | \$912,743.04 |
| Heat | 0.6700 | 0.00 | 0.0000 | \$0.00 |
| Plumbing | 0.4500 | 0.02 | 0.0090 | \$80,536.15 |
| Electrical | 0.0450 | 0.12 | 0.0054 | \$48,321.68 |
| Convey | 0.1000 | 0.03 | 0.0030 | \$26,845.38 |
| Safety | 0.1000 | 0.01 | 0.0010 | \$8,948.46 |
| AE/OP | 0.2872 | 0.18 | 0.0517 | \$462,599.66 |

Component Deficiency Total:

0.3389

Outstanding Maintenance:

\$3,032,597.66

Facilities Condition Index (FCI):

66.11

 $FCI = (1-Component Deficiency Total) \times 100$

Building Name: Chemistry

Number: 0150

Construction Date: 1971

Gross Square Feet: 168,037

Net Square Feet: 153,500

Date of Audit: 01/10/2005 Cycle: 5 Phase: 2 No. of Stories: 3

Classification: M150 College, Laboratory

SBP Class: 11 Science

Replacement Cost: \$30,717,751.73

Cost Per SF: \$182.80

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.2000 | 0.07 | 0.0140 | \$430,048.53 |
| Ext Walls | 0.0800 | 0.06 | 0.0048 | \$147,445.20 |
| Floors | 0.2000 | 0.07 | 0.0140 | \$430,048.53 |
| Roof | 0.3000 | 0.06 | 0.0180 | \$552,919.54 |
| Ceiling | 0.4500 | 0.03 | 0.0135 | \$414,689.63 |
| Int Walls | 0.2000 | 0.09 | 0.0180 | \$552,919.56 |
| Windows | 0.4000 | 0.02 | 0.0080 | \$245,742.01 |
| Doors | 0.3000 | 0.02 | 0.0060 | \$184,306.51 |
| Cool Vent | 0.1800 | 0.06 | 0.0108 | \$331,751.72 |
| Heat | 0.2100 | 0.07 | 0.0147 | \$451,550.94 |
| Plumbing | 0.5500 | 0.14 | 0.0770 | \$2,365,266.94 |
| Electrical | 0.7000 | 0.07 | 0.0490 | \$1,505,169.82 |
| Convey | 0.2200 | 0.01 | 0.0022 | \$67,579.05 |
| Safety | 0.0200 | 0.02 | 0.0004 | \$12,287.10 |
| AE/OP | 0.2504 | 0.21 | 0.0526 | \$1,615,262.21 |

Component Deficiency Total:

0.3030

Outstanding Maintenance:

\$9,306,987.30

Facilities Condition Index (FCI):

69.70

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

Building Name: Engr. Res. Center

Number: 1101

Construction Date: 1962

Gross Square Feet: 149,915 Net Square Feet: 134,490

Date of Audit: 02/07/2005 Cycle: 5 Phase: 2 No. of Stories: 3

Classification: M150 College, Laboratory

SBP Class: 12 Engineering

Replacement Cost:

\$22,840,479.72

Cost Per SF: \$152.36

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0800 | 0.07 | 0.0056 | \$127,906.68 |
| Ext Walls | 0.1000 | 0.06 | 0.0060 | \$137,042.88 |
| Floors | 0.2000 | 0.07 | 0.0140 | \$319,766.72 |
| Roof | 0.3000 | 0.06 | 0.0180 | \$411,128.64 |
| Ceiling | 0.5000 | 0.03 | 0.0150 | \$342,607.19 |
| Int Walls | 0.1000 | 0.09 | 0.0090 | \$205,564.33 |
| Windows | 0.7000 | 0.02 | 0.0140 | \$319,766.70 |
| Doors | 0.1500 | 0.02 | 0,0030 | \$68,521.44 |
| Cool Vent | 0.6700 | 0.06 | 0.0402 | \$918,187.29 |
| Heat | 0.6700 | 0.07 | 0.0469 | \$1,071,218.53 |
| Plumbing | 0.1700 | 0.14 | 0.0238 | \$543,603.43 |
| Electrical | 0.9500 | 0.07 | 0.0665 | \$1,518,891.89 |
| Convey | 0.2000 | 0.01 | 0.0020 | \$45,680.96 |
| Salety | 0.0300 | 0.02 | 0.0006 | \$13,704.29 |
| AE/OP | 0.2646 | 0.21 | 0.0556 | \$1,269,154.06 |

Component Deficiency Total:

0.3202

Outstanding Maintenance:

\$7,312,745.02

Facilities Condition Index (FCI):

67.98

FCI = (1-Component Deficiency Total) x 100

Building Name: Engineering South/Glover

Number: 0088

Construction Date: 1950

Gross Square Feet: 52,823 Net Square Feet: 45,202

Date of Audit: 01/08/2007 Cycle: 6 Phase: 1 No. of Stories: 2

Classification: M120 Classroom, 2-3 Story

SBP Class: 12 Engineering

Replacement Cost:

\$9,017,572.80

Cost Per SF: \$170.71

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0800 | 0.02 | 0.0016 | \$14,428.12 |
| Ext Walls | 0.1000 | 0.04 | 0.0040 | \$36,070.29 |
| Floors | 0.1500 | 0.12 | 0.0180 | \$162,316.31 |
| Roof | 0.5500 | 0.05 | 0.0275 | \$247,983.26 |
| Ceiling | 0.1100 | 0.04 | 0.0044 | \$39,677.32 |
| Int Walls | 0.0800 | 0.06 | 0.0048 | \$43,284.35 |
| Windows | 0.2000 | 0.03 | 0.0060 | \$54,105.44 |
| Doors | 0.1100 | 0.04 | 0.0044 | \$39,677.32 |
| Cool Vent | 0.3000 | 0.09 | 0.0270 | \$243,474.48 |
| Heat | 0.2000 | 0.08 | 0.0160 | \$144,281.16 |
| Plumbing | 0.2600 | 0.07 | 0.0182 | \$164,119.82 |
| Electrical | 0.2080 | 0.11 | 0.0229 | \$206,322.07 |
| Convey | 0.3500 | 0.01 | 0.0035 | \$31,561.50 |
| Safety | 0.2000 | 0.01 | 0.0020 | \$18,035.15 |
| AE/OP | 0.1603 | 0.18 | 0.0289 | \$260,160.60 |

Component Deficiency Total:

0.1891

Outstanding Maintenance:

\$1,705,497.23

Facilities Condition Index (FCI):

81.09

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

Building Name: Natural Resources

Number: 0082

Construction Date: 1975

Gross Square Feet: 73,027

Net Square Feet: 66,550

Date of Audit: 11/29/2005 Cycle: 5 Phase: 3 No. of Stories: 3

Classification: M120 Classroom, 2-3 Story

SBP Class: 10 Classroom/Office

Replacement Cost:

\$9,529,096.06

Cost Per SF: \$130.49

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0500 | 0.02 | 0.0010 | \$9,529.10 |
| Ext Walls | 0.1600 | 0.04 | 0.0064 | \$60,986.21 |
| Floors | 0.3000 | 0.12 | 0.0360 | \$343,047.46 |
| Roof | 0.2000 | 0.05 | 0.0100 | \$95,290.96 |
| Ceiling | 0.5000 | 0.04 | 0.0200 | \$190,581.92 |
| Int Walls | 0.2000 | 0.06 | 0.0120 | \$114,349.15 |
| Windows | 0.2200 | 0.03 | 0.0066 | \$62,892.03 |
| Doors | 0.3000 | 0.04 | 0.0120 | \$114,349.15 |
| Cool Vent | 0.4500 | 0.10 | 0.0450 | \$428,809.35 |
| Heat | 0.5000 | 0.07 | 0.0350 | \$333,518.36 |
| Plumbing | 0.2700 | 0.07 | 0.0189 | \$180,099.92 |
| Electrical | 0.3600 | 0.11 | 0.0396 | \$377,352.22 |
| Convey | 0.2500 | 0.01 | 0.0025 | \$23,822.74 |
| Safety | 0.2000 | 0.01 | 0.0020 | \$19,058.19 |
| AE/OP | 0.2470 | 0.18 | 0.0445 | \$423,663.64 |

Component Deficiency Total:

0.2915

Outstanding Maintenance:

\$2,777,350.41

Facilities Condition Index (FCI):

70.85

 $FCI = (1-Component Deficiency Total) \times 100$

Building Name: Plant Sciences

Number: 0092

Construction Date: 1959

Gross Square Feet: 81,783

Net Square Feet: 71,642

Date of Audit: 12/08/2003 Cycle: 4 Phase: 4 No. of Stories: 2

Classification: M150 College, Laboratory

SBP Class: 11 Science

Replacement Cost:

\$9,493,501.49

Cost Per SF: \$116.08

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0500 | 0.07 | 0.0035 | \$33,227.25 |
| Ext Walls | 0.0100 | 0.06 | 0.0006 | \$5,696.10 |
| Floors | 0.0100 | 0.07 | 0.0007 | \$6,645.45 |
| Roof | 0.0100 | 0.06 | 0.0006 | \$5,696.10 |
| Ceiling | 0.0200 | 0.03 | 0.0006 | \$5,696.10 |
| Int Walls | 0.0100 | 0.09 | 0.0009 | \$8,544.15 |
| Windows | 0.0100 | 0.02 | 0.0002 | \$1,898.70 |
| Doors | 0.0100 | 0.02 | 0.0002 | \$1,898.70 |
| Cool Vent | 0.1000 | 0.03 | 0.0030 | \$28,480.50 |
| Heat | 0.1000 | 0.10 | 0.0100 | \$94,935.02 |
| Plumbing | 0.1600 | 0.14 | 0.0224 | \$212,654.43 |
| Electrical | 0.0200 | 0.07 | 0.0014 | \$13,290.90 |
| Convey | 0.1100 | 0.01 | 0.0011 | \$10,442.85 |
| Safety | 0.1000 | 0.02 | 0.0020 | \$18,987.00 |
| AE/OP | 0.0472 | 0.21 | 0.0099 | \$94,099.58 |

Component Deficiency Total:

0.0571

Outstanding Maintenance:

\$542,192.86

Facilities Condition Index (FCI):

94.29

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

Building Name: Visual Arts

Number: 0151

Construction Date: 1973 Gross Square Feet: 91,997

Net Square Feet: 86,135

Date of Audit: 02/21/2006 Cycle: 5 Phase: 3 No. of Stories: 1

Classification: M120 Classroom, 2-3 Story

SBP Class: 13 Fine Arts

Replacement Cost:

\$9,149,865.00

Cost Per SF: \$99.46

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1500 | 0.02 | 0.0030 | \$27,449.59 |
| Ext Walls | 0.2200 | 0.04 | 0.0088 | \$80,518.81 |
| Floors | 0.2000 | 0.12 | 0.0240 | \$219,596.76 |
| Roof | 0.0800 | 0.05 | 0.0040 | \$36,599.46 |
| Ceiling | 0.4000 | 0.04 | 0.0160 | \$146,397.84 |
| Int Walls | 0.3500 | 0.06 | 0.0210 | \$192,147.16 |
| Windows | 0.5000 | 0.03 | 0.0150 | \$137,247.97 |
| Doors | 0.5000 | 0.04 | 0.0200 | \$182,997.30 |
| Cool Vent | 0.7500 | 0.05 | 0.0375 | \$343,119.94 |
| Heat | 0.1200 | 0.12 | 0.0144 | \$131,758.05 |
| Plumbing | 0.3000 | 0.07 | 0.0210 | \$192,147.17 |
| Electrical | 0.0760 | 0.11 | 0.0084 | \$76,492.87 |
| Safety | 0.4000 | 0.01 | 0.0040 | \$36,599.46 |
| AE/OP | 0.1971 | 0.18 | 0.0355 | \$324,553.05 |

Component Deficiency Total:

0.2325

Outstanding Maintenance:

\$2,127,625.47

Facilities Condition Index (FCI):

76.75

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

Building Name: Andrew G. Clark

Number: 0091

Construction Date: 1967 Gross Square Feet: 254,792

Net Square Feet: 229,960

Date of Audit: 12/06/2005 Cycle: 5 Phase: 3 No. of Stories: 3

Classification: M120 Classroom, 2-3 Story

SBP Class: 10 Classroom/Office

Replacement Cost:

\$27,170,356.42

Cost Per SF: \$106.64

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.2500 | 0.02 | 0.0050 | \$135,851.78 |
| Ext Walls | 0.4000 | 0.04 | 0.0160 | \$434,725.70 |
| Floors | 0.4000 | 0.12 | 0.0480 | \$1,304,177.10 |
| Roof | 0.5500 | 0.05 | 0.0275 | \$747,184.83 |
| Ceiling | 0.3700 | 0.04 | 0.0148 | \$402,121.27 |
| Int Walls | 0.1800 | 0.06 | 0.0108 | \$293,439.85 |
| Windows | 0.3000 | 0.03 | 0.0090 | \$244,533.21 |
| Doors | 0.3000 | 0.04 | 0.0120 | \$326,044.28 |
| Cool Vent | 0.1300 | 0.09 | 0.0110 | \$300,232.43 |
| Heat | 0.3200 | 0.09 | 0.0272 | \$739,033.69 |
| Plumbing | 0.3500 | 0.07 | 0.0245 | \$665,673.72 |
| Electrical | 0.7000 | 0.11 | 0.0770 | \$2,092,117.40 |
| Convey | 0.2100 | 0.01 | 0.0021 | \$57,057.75 |
| Safety | 0.7000 | 0.01 | 0.0070 | \$190,192.49 |
| AE/OP | 0.2920 | 0.18 | 0.0526 | \$1,427,829.47 |

Component Deficiency Total:

0.3445

Outstanding Maintenance:

\$9,360,215.06

Facilities Condition Index (FCI):

65.55

FCI = (1-Component Deficiency Total) x 100

Building Name: Animal Reproduction & Biotechnology Lab Number: 1402

Construction Date: 1964 Gross Square Feet: 41,288 Net Square Feet: 36,048

Date of Audit: 03/21/2005 Cycle: 5 Phase: 2 No. of Stories: 1

Classification: M150 College, Laboratory SBP Class: 11 Science

Replacement Cost: \$7,162,031.18 Cost Per SF: \$173.47

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0300 | 0.07 | 0.0021 | \$15,040.27 |
| Ext Walls | 0.0500 | 0.06 | 0.0030 | \$21,486.09 |
| Floors | 0.1000 | 0.07 | 0.0070 | \$50,134.22 |
| Roof | 0.2500 | 0.06 | 0.0150 | \$107,430.47 |
| Ceiling | 0.0500 | 0.03 | 0.0015 | \$10,743.05 |
| Int Walls | 0.0300 | 0.09 | 0.0027 | \$19,337.48 |
| Windows | 0.1000 | 0.02 | 0.0020 | \$14,324.06 |
| Doors | 0.0600 | 0.02 | 0.0012 | \$8,594.44 |
| Cool Vent | 0.2000 | 0.06 | 0.0130 | \$93,106.40 |
| Heat | 0.2000 | 0.06 | 0.0130 | \$93,106.40 |
| Plumbing | 0.3200 | 0.14 | 0.0448 | \$320,858.99 |
| Electrical | 0.2250 | 0.07 | 0.0158 | \$112,802.00 |
| Safety | 0.2000 | 0.02 | 0.0040 | \$28,648.12 |
| AE/OP | 0.1250 | 0.21 | 0.0263 | \$188,078.51 |

Component Deficiency Total:

0.1513

Outstanding Maintenance:

\$1,083,690.49

Facilities Condition Index (FCI):

84.87

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

Building Name: Auditorium Gymnasium

Number: 0027

Construction Date: 1966

Gross Square Feet: 278,488

Net Square Feet: 231,783

Date of Audit: 09/13/2004 Cycle: 5 Phase: 2 No. of Stories: 2

Classification: M310 Gymnasium, 1 Story

SBP Class: 15 Physical Education

Replacement Cost:

\$28,865,531.84

Cost Per SF: \$103.65

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0700 | 0.04 | 0.0028 | \$80,823.49 |
| Ext Walls | 0.2300 | 0.06 | 0.0138 | \$398,344.31 |
| Floors | 0.0800 | 0.15 | 0.0120 | \$346,386.39 |
| Roof | 0.2500 | 0.18 | 0.0450 | \$1,298,948.98 |
| Ceiling | 0.5700 | 0.01 | 0.0057 | \$164,533.53 |
| Int Walls | 0.3000 | 0.04 | 0.0120 | \$346,386.35 |
| Windows | 0.2400 | 0.02 | 0.0048 | \$138,554.55 |
| Doors | 0.4300 | 0.02 | 0.0086 | \$248,243.57 |
| Cool Vent | 0.4000 | 0.06 | 0.0240 | \$692,772.76 |
| Heat | 0.3500 | 0.05 | 0.0175 | \$505,146.81 |
| Plumbing | 0.7000 | 0.06 | 0.0420 | \$1,212,352.29 |
| Electrical | 0.5920 | 0.07 | 0.0414 | \$1,196,187.66 |
| Convey | 0.1500 | 0.02 | 0.0030 | \$86,596.60 |
| Safety | 0.3500 | 0.03 | 0.0105 | \$303,088.07 |
| AE/OP | 0.2431 | 0.19 | 0.0462 | \$1,333,489.40 |

Component Deficiency Total:

0.2893

Outstanding Maintenance:

\$8,351,854.74

Facilities Condition Index (FCI):

71.07

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

Building Name: Center for Envir Toxicology & Technology Number: 1422

Construction Date: 1966 Gross Square Feet: 15,209 Net Square Feet: 13,585

Date of Audit: 04/15/2007 Cycle: 6 Phase: 1 No. of Stories: 1

Classification: M150 College, Laboratory SBP Class: 11 Science

Replacement Cost: \$1,884,527.42 Cost Per SF: \$123.91

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1200 | 0.07 | 0.0084 | \$15,830.03 |
| Ext Walls | 0.1400 | 0.06 | 0.0084 | \$15,830.03 |
| Floors | 0.1000 | 0.07 | 0.0070 | \$13,191.69 |
| Roof | 0.3000 | 0.06 | 0.0180 | \$33,921.49 |
| Ceiling | 0.0500 | 0.03 | 0.0015 | \$2,826.79 |
| Int Walls | 0.0500 | 0.09 | 0.0045 | \$8,480.37 |
| Windows | 0.6500 | 0.02 | 0.0130 | \$24,498.86 |
| Doors | 0.3000 | 0.02 | 0.0060 | \$11,307.16 |
| Cool Vent | 0.2500 | 0.07 | 0.0175 | \$32,979.23 |
| Heat | 0.6000 | 0.06 | 0.0360 | \$67,842.99 |
| Plumbing | 0.3000 | 0.14 | 0.0420 | \$79,150.16 |
| Electrical | 0.2210 | 0.07 | 0.0155 | \$29,153.64 |
| Safety | 0.7000 | 0.02 | 0.0140 | \$26,383.38 |
| AE/OP | 0.1918 | 0.18 | 0.0345 | \$65,051.25 |

Component Deficiency Total: 0.2263

Outstanding Maintenance: \$426,447.09

Facilities Condition Index (FCI): 77.37

 $FCI = (1-Component Deficiency Total) \times 100$

Building Name: Engineering

Number: 0041

Construction Date: 1957

Gross Square Feet: 211,410

Net Square Feet: 198,935

Date of Audit: 09/22/2003 Cycle: 4 Phase: 4 No. of Stories: 2

Classification: M120 Classroom, 2-3 Story

SBP Class: 12 Engineering

Replacement Cost:

\$88,463,626.58

Cost Per SF: \$418.45

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0500 | 0.02 | 0.0010 | \$88,463.62 |
| Ext Walls | 0.0600 | 0.04 | 0.0024 | \$212,312.69 |
| Floors | 0.1500 | 0.12 | 0.0180 | \$1,592,345.31 |
| Roof | 0.2500 | 0.05 | 0.0125 | \$1,105,795.35 |
| Ceiling | 0.2000 | 0.04 | 0.0080 | \$707,709.01 |
| Int Walls | 0.2000 | 0.06 | 0.0120 | \$1,061,563.51 |
| Windows | 0.1700 | 0.03 | 0.0051 | \$451,164.49 |
| Doors | 0.1800 | 0.04 | 0.0072 | \$636,938.07 |
| Cool Vent | 0.0450 | 0.08 | 0.0036 | \$318,469.03 |
| Heat | 0.0200 | 0.09 | 0.0018 | \$159,234.53 |
| Plumbing | 0.3900 | 0.07 | 0.0273 | \$2,415,056.93 |
| Electrical | 0.0300 | 0.11 | 0.0033 | \$291,929.96 |
| Convey | 0.1000 | 0.01 | 0.0010 | \$88,463.63 |
| Safety | 0.0500 | 0.01 | 0.0005 | \$44,231.81 |
| AE/OP | 0.1037 | 0.18 | 0.0187 | \$1,651,262.10 |

Component Deficiency Total:

0.1224

Outstanding Maintenance:

\$10,824,940.12

Facilities Condition Index (FCI):

87.76

 $FCI = (I-Component\ Deficiency\ Total)\ x\ 100$

Building Name: Gifford

Number: 0152

Construction Date: 1975

Gross Square Feet: 92,278

Net Square Feet: 84,174

Date of Audit: 02/09/2004 Cycle: 5 Phase: 1 No. of Stories: 3

Classification: M120 Classroom, 2-3 Story

SBP Class: 10 Classroom/Office

Replacement Cost:

\$9,491,678.17

Cost Per SF: \$102.86

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0800 | 0.02 | 0.0016 | \$15,186.68 |
| Ext Walls | 0.1300 | 0.04 | 0.0052 | \$49,356.72 |
| Floors | 0.3000 | 0.12 | 0.0360 | \$341,700.42 |
| Roof | 0.0300 | 0.05 | 0.0015 | \$14,237.52 |
| Ceiling | 0.3000 | 0.04 | 0.0120 | \$113,900.14 |
| Int Walls | 0.3000 | 0.06 | 0.0180 | \$170,850.21 |
| Windows | 0.2000 | 0.03 | 0.0060 | \$56,950.07 |
| Doors | 0.2000 | 0.04 | 0.0080 | \$75,933.42 |
| Cool Vent | 0.3800 | 0.09 | 0.0323 | \$306,581.20 |
| Heat | 0.3300 | 0.09 | 0.0281 | \$266,241.59 |
| Plumbing | 0.4300 | 0.07 | 0.0301 | \$285,699.52 |
| Electrical | 0.4300 | 0.11 | 0.0473 | \$448,956.38 |
| Convey | 0.1000 | 0.01 | 0.0010 | \$9,491.68 |
| Safety | 0.3000 | 0.01 | 0.0030 | \$28,475.04 |
| AE/OP | 0.2300 | 0.18 | 0.0414 | \$393,040.93 |

Component Deficiency Total:

0.2715

Outstanding Maintenance:

\$2,576,601.52

Facilities Condition Index (FCI):

72.85

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

Building Name: General Services Building

Number: 0102

Construction Date: 1948

Gross Square Feet: 74,907

Net Square Feet: 66,167

Date of Audit: 12/20/2005 Cycle: 5 Phase: 3 No. of Stories: 3

Classification: M460 Office Building

SBP Class: 16 Office

Replacement Cost:

\$11,462,561.28

Cost Per SF: \$153.02

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1500 | 0.02 | 0.0030 | \$34,387.68 |
| Ext Walls | 0.1400 | 0.09 | 0.0126 | \$144,428.28 |
| Floors | 0.1500 | 0.16 | 0.0240 | \$275,101.48 |
| Roof | 0.1500 | 0.03 | 0.0045 | \$51,581.53 |
| Ceiling | 0.1700 | 0.05 | 0.0085 | \$97,431.77 |
| Int Walls | 0.1700 | 0.05 | 0.0085 | \$97,431.77 |
| Windows | 0.1700 | 0.02 | 0.0034 | \$38,972.71 |
| Doors | 0.2500 | 0.05 | 0.0125 | \$143,282.02 |
| Cool Vent | 0.6700 | 0.09 | 0.0603 | \$691,192.49 |
| Heat | 0.4800 | 0.08 | 0.0384 | \$440,162.33 |
| Plumbing | 0.3300 | 0.02 | 0.0066 | \$75,652.91 |
| Electrical | 0.9800 | 0.12 | 0.1176 | \$1,347,997.20 |
| Convey | 0.1800 | 0.03 | 0.0054 | \$61,897.83 |
| Safety | 0.3000 | 0.01 | 0.0030 | \$34,387.68 |
| AE/OP | 0.3083 | 0.18 | 0.0555 | \$636,103.41 |

Component Deficiency Total:

0.3638

Outstanding Maintenance:

\$4,170,011.12

Facilities Condition Index (FCI):

63.62

 $FCI = (1-Component Deficiency Total) \times 100$

Building Name: John E. Painter Center for Lab Animals Number: 0144

Construction Date: 1980 Gross Square Feet: 31,139 Net Square Feet: 27,591

Date of Audit: 01/03/2005 Cycle: 5 Phase: 2 No. of Stories: 1

Classification: M330 Hospital, 1-3 Story SBP Class: 11 Science

Replacement Cost: \$4,187,706.62 Cost Per SF: \$134.48

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.2000 | 0.02 | 0.0040 | \$16,750.83 |
| Ext Walls | 0.0300 | 0.08 | 0.0024 | \$10,050.50 |
| Floors | 0.0500 | 0.12 | 0.0060 | \$25,126.24 |
| Roof | 0.2500 | 0.04 | 0.0100 | \$41,877.07 |
| Ceiling | 0.3500 | 0.03 | 0.0105 | \$43,970.92 |
| Int Walls | 0.0500 | 0.08 | 0.0040 | \$16,750.83 |
| Windows | 0.1500 | 0.01 | 0.0015 | \$6,281.56 |
| Doors | 0.2000 | 0.05 | 0.0100 | \$41,877.07 |
| Cool Vent | 0.3700 | 0.07 | 0.0259 | \$108,461.60 |
| Heat | 0.5800 | 0.02 | 0.0116 | \$48,577.40 |
| Plumbing | 0.3200 | 0.12 | 0.0384 | \$160,807.93 |
| Electrical | 0.2400 | 0.07 | 0.0168 | \$70,353.47 |
| Safety | 0.2000 | 0.03 | 0.0060 | \$25,126.24 |
| AE/OP | 0.1471 | 0.20 | 0.0294 | \$123,202.33 |

Component Deficiency Total: 0.1765

Outstanding Maintenance: \$739,213.97

Facilities Condition Index (FCI): 82.35

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

Building Name: Spruce Hall

Number: 0064

Construction Date: 1881

Gross Square Feet: 18,738

Net Square Feet: 15,936

Date of Audit: 12/04/2006 Cycle: 6 Phase: 1 No. of Stories: 2

Classification: M460 Office Building

SBP Class: 16 Office

Replacement Cost:

\$2,031,575.83

Cost Per SF: \$108.42

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| | | | | |
| Foundation | 0.2000 | 0.02 | 0.0040 | \$8,126.30 |
| Ext Walls | 0.1500 | 0.09 | 0.0135 | \$27,426.27 |
| Floors | 0.2000 | 0.16 | 0.0320 | \$65,010.43 |
| Roof | 0.3500 | 0.03 | 0.0105 | \$21,331.55 |
| Ceiling | 0.1500 | 0.05 | 0.0075 | \$15,236.82 |
| Int Walls | 0.1700 | 0.05 | 0.0085 | \$17,268.40 |
| Windows | 0.2000 | 0.02 | 0.0040 | \$8,126.30 |
| Doors | 0.2000 | 0.05 | 0.0100 | \$20,315.76 |
| Cool Vent | 0.2600 | 0.09 | 0.0221 | \$44,897.82 |
| Heat | 0.1900 | 0.09 | 0.0161 | \$32,809.95 |
| Plumbing | 0.1800 | 0.02 | 0.0036 | \$7,313.67 |
| Electrical | 0.3120 | 0.12 | 0.0374 | \$76,062.20 |
| Convey | 0.1300 | 0.03 | 0.0039 | \$7,923.15 |
| Safety | 0.2000 | 0.01 | 0.0020 | \$4,063.15 |
| AE/OP | 0.1752 | 0.18 | 0.0315 | \$64,064.12 |

Component Deficiency Total:

0.2067

Outstanding Maintenance:

\$419,975.90

Facilities Condition Index (FCI):

79.33

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

| A. AGENCY BASIC DATA: | |
|---|-----------|
| x Controlled Maintenance Request Capital Renewal Building/Infrastruct Request | ure |
| 1) Agency Colorado State University | |
| 2) Department Higher Education | |
| 3) Physical Plant ID No. 2-01 Project M # | |
| 4) Agency Priority # 1 | |
| 5) Project Title Replace Deteriorated Steam and Condensate - North Line, Phase 3 of 3 | |
| B. FACILITY PROFILE | |
| 1) Facility Type x Site (Utilities underground) Steam and Condensate | |
| or Site (Improvements above ground) | |
| or Building Name (s) | |
| Risk Mgmt. Bldg(s) ID# | |
| 2) Facility Location Main Campus | |
| 3) Facility Area/Age GSF ASF Date Built | |
| 4) Facility Functional Use/Occupancy | |
| 5) Facility Construction (Type) | |
| 6) Facility Physical Condition and Facility Condition Index (FCI) Number | |
| Actual FCI = Targeted FCI = Date of Last Audit | |
| (Describe) | |
| 7) Facility - Intensity of Use, Time(s) of Operation: (Hours/Day, Days/Month, Months/Year) 24/31/12 | |
| 8) Facility - Current Replacement Value \$ | |
| 9) Master Plan Status - Check one or more of the following: | |
| a) Facility 'useful' life is less than five (5) years. | |
| b) x Facility 'useful' life is more than five (5) years. | |
| c) Master Plan is obsolete; Last Date Approved (by OSPB/CCHE) | |
| d) Major facility changes, renovations, or program revisions are ongoing or anticipated in th next five years, (If yes, please explain below if these facility renovations or program revisions may have an impact on this CM request.) | e ions |
| | |

Page __1__ of __4__

| | Page | _2_ of4_ |
|---|--|-------------------------|
| a) Facility Audit Survey concluded and submitted to SBREP - b) Status of the Infrastructure Assessment. 5/2 | Date % Completed | 2005 |
| c) Facility Audit Survey Cycle 5/2 | | |
| 11) List all the controlled maintenance, capital construction, and emerger last five years or ongoing projects that can be associated with either trequest. | his CM building o | r infrastructure |
| Project No. Project Title | | r status |
| C. INTEGRATED PROGRAM PLAN DATA | | |
| NOTE: For a Capital Renewal Building/Infrastructure Request, refer to th information required to support the request. | e instructions for t | the additional |
| 1) Narrative Description of CM Problem (Initial problem and solution by p steam and condensate system is over 60 years old and the piping was depressure. This creates a safety hazard if a pressure reduction valve should be providing 125-PSI steam. The new lines will be rated at 125 PSI and w rest of the campus system. | esigned for 10 PS ld fail since the H | l steam eating Plant |
| 2) Total Project Cost Estimate (From Cost Breakdown) \$ \$2,599,406 | | |
| 3) Consequences (cost effects, program impacts, facility impacts, etc.) o specific project request: A failure in these lines would cause a total local center of campus. | | |
| Mandatory - Include Facility Audit documentation from most recent as infrastructure project request. | udit. Include site r | maps for any |
| 5) Optional - Include photographs and any other supporting documents. | | |
| 6) Explanation of how this project will improve the building(s) facility cond specific infrastructure system. | lition index or imp | rove a |
| | | |
| | | |

| | | Page3 of4 |
|----------------------------|-----------------------|---|
| D. <u>DETAILED COST</u> | STIMATE (detail by pl | nase, one page per phase, include all phases) |
| 1) Approved By Dew | vey Wearne | 2) Phase? 3 |
| 3) Method of Estimate | Historic | |
| 4) Professional Services | | |
| Site Surveys Investigation | ns. and Reports | |

| 4) Professional Services | |
|---|-----|
| Site Surveys, Investigations, and Reports | |
| Arch/Eng/Basic Services | |
| Code Review/Inspection | |
| Other (Explain) | |
| Total of Professional Services | \$0 |

| WORK ITEM (Labor/Material/Equipment) | UNIT | UNIT COST | EXTENDED COST |
|--|------|--------------|------------------|
| Infrastructure | | | |
| a) Utility Services | | | |
| New trench – Ammons to Rockwell | LF | \$620 | \$471,200 |
| Piping – Ammons to Rockwell | LF | \$387 | \$294,120 |
| Compressed air | LF | \$15.74 | \$12,277 |
| Additional Costs see attached. | | \$552,700 | \$552,700 |
| | | | |
| Total of Construction Improvements Costs | | | \$1,300,297 |

6) Miscellaneous (explain)

| o) micocharrecae (explain) | | | | PROPERTY AND PROPERTY OF THE P |
|------------------------------|--|--|--|--|
| | | | | |
| | | | | |
| Total of Miscellaneous Costs | | | | \$0 |

7) Project Contingency

| 7) Project Contingency | | 4 |
|---|-----------|---|
| Contingency (10% CM) (Percentage of total of professional services, | \$130,030 | ı |
| construction improvements, and miscellaneous costs.) | | |

| | \$1,430,327 |
|--|-------------|
| miscellaneous costs, and project contingency percentage (by phase) | |

| 9) TOTAL PROJECT COST (all phases) - NEQUEST \$2,399,400 | 9) TOTAL PROJECT COST | (all phases)= REQUEST | \$2,599,406 |
|--|-----------------------|-----------------------|-------------|
|--|-----------------------|-----------------------|-------------|

Note: Agency formatted cost estimates may accompany this page.

| Page | 4 | of | 4 |
|------|---------------------|----|---------------------------|
| | ARTERIOR MARKETONIA | - | Characteristic amountains |

| E. | PRO | POS | ED | PHAS | SING |
|----|-----|-----|-----|------|------|
| DE | NOR | DHA | SIN | G1 | |

| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Actual Appropriation) |
|-------------|-----------------------|--------------|-------------------------|--|
| | 2-01 | FY 2006/2007 | 1 | \$490,415 |

\$ 490,415 (Subtotal)

CURRENT PHASE² REQUESTED

| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase of Work | Dollar Amount (Per Detailed Budget) |
|-------------|-----------------------|--------------|---------------|---|
| | 2-01 | FY 2007/2008 | 2 | \$678,664 |

\$ 678,664 (Subtotal)

FUTURE PHASING²

| FUIC | INL I I I AOII | 10 | | |
|-------------|-----------------------|--------------|-------------------------|---|
| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Per Detailed Budget) |
| | 2-01 | FY 2009/2010 | 3 | \$1,430,327 |
| | | FY 2010/2011 | | |

\$1,430,327 (Subtotal)

Project Total Dollar Amount of All Projects Phases Requested \$2,599,406

(Prior, Current and Future Phases)

¹ List <u>all</u> previous phases with actual appropriation by year (include federal funding). Note if different from requested amount.

² List all current and anticipated future phases with estimated costs as listed in the detailed cost estimate subtotal blank 8.

F. PROPOSED PROJECT IMPLEMENTATION SCHEDULE (PLAN):

| PHASE | FROM | ТО |
|---------------------------------------|---------|---------|
| 1. Pre-Design (Insert Dates) | July 06 | Dec 06 |
| 2. Design (Insert Dates) | Dec 06 | May 07 |
| 3. Construction (Insert Dates) | May 07 | May 08 |
| 4. Project Close-out/Final Completion | May 09 | July 10 |

G. AGENCY APPROVAL

Agency Authorized Signature _____ Date ____



3155 Rookery Road Fort Collins, CO 80528 970.988.8605 970.204.1673 fax

Delivered via email

August 27, 2008

Dewey Wearne Assistant Project Manager Facilities Management Colorado State University Fort Collins, CO 80523-6030

RE:

Verification of CMO3 Funds Request for Steam and Condensate – North Line Replacement State Project #M06056

CSU Project #05-040

Dear Dewey:

This letter follows on our recent discussions regarding an updated CMO3 funds request for the Replace Deteriorated Steam and Condensate – North Line Project (#05-040). This letter is a continuation of the additional funds request prepared on August 13, 2007.

As you know, the North Steam Line Project Segments 2, 3 and 4 have been constructed. Segments 1 and 5 remain and have been delayed due to lack of funding appropriations. The appropriation originally expected in FY 2008/09 was to be \$801,689. In addition to this, the project was requesting another \$400,000 to cover the cost of steel inflation from 2004 to 2007 and other project changes encountered during construction of Phase 1 and 2. This resulted in an overall budget request of approximately \$1.2 million. With the delay in funding, material costs for Phase 3 (Segments 1 & 5) continue to rise thereby creating another deficit in the construction budget.

Steel costs have continued to steadily rise over the past year and are, on average approximately 10 to 12% higher. The material portion of the overall project budget is approximately 30% of the total budget or \$360,000. With this, our additional funding request should include another \$43,200 (12% of \$360,000) bringing our total budget to \$1,257,097 plus \$43,200 or \$1,300,297.

While not direct correlation, the attached ENR summary report for pipe product increases supports the referenced increase. This comparable is for ductile iron. As referenced above, steel has also witnessed these types of price increases.

Please let me know if you have any questions or I can provide further information.

Sincerely.

Keith Meyer, P.E. Contract Project Manager

Cc: file

Construction Economics

Cost Indexes

V

Construction Cost Index
Labor costs gave the CCI its biggest
boost this month, as the annual increase
for the CCI rose from 4.2% to 4.4%.

| 20-CTY: 1913=100 | AUG. 2008 INDEX VALUE | % CHG. MONTH | % CHG. YEAR |
|-------------------|--------------------------|-----------------|----------------|
| CONSTRUCTION COST | 8361.74 | +0.8 | +4.4 |
| COMMON LABOR | 17398.95 | +1.0 | +3.4 |
| WAGE S/HR. | 33.06 | +1.0 | +3.4 |

Building Cost Index

The year-to-year increase for the BCI slipped from 5.1% fast month to 4.8% in August.

| August. | | | Edward |
|-------------------|---------------------------|-----------------|----------------|
| 20-CITY: 1913=108 | AUG. 2008 INIOEX VALUE | % CHG. MONTH | % CHG. YEAR |
| BAILDING COST | 4733.44 | +0.2 | +4.8 |
| SKELED LABOR | 7860.96 | +0.2 | +2.7 |

43.63



WAGE SHR.

Materials Cost Index

Steel prices increased just 0.6% this month, following strong gains during the previous four months.

+0.2

+2.7

| 20-CITY: 1913=100 | AUG. 2008 INDEX VALUE | % CHG. MONTH | % CHG. YEAR |
|-------------------|--------------------------|-----------------|----------------|
| MATERIALS | 2822.80 | +0.3 | +8.2 |
| CEMENT \$/TON | 100.39 | 0.0 | +0.2 |
| STEEL \$ACWT | 46.87 | +0.6 | +15.3 |
| LUMBER S/MBF | 427.53 | -0.4 | -3.4 |

Weak Lumber Prices Undercut Cost Indexes



Building costs in New Orleans are increasing one percentage point less than the national average. ENR's building cost index for the city is up 3.7% for the year, compared to a 4.8% increase nationwide. Lumber prices in the New Orleans index fell 16% from August 2007, following declines of 6% last year and 8% in 2006. Cement price rose just 0.6% this year, following an 8% increase over the previous two years.

| Cost Inde | ixes by | City • | | | NAME OF THE OWNER, SOME | Silven seigen de syn | | CHARLESCO COCO | | |
|------------------|--------------------------------|------------------------------------|-------------------------------|--------------------------|-----------------------------|----------------------|------------------------------|------------------------|----------------------------|----------------------|
| 1913=100 CITY | CONSTRUCT AUG. '08 INDEX | TON COST SHO & SHO & YEAR | BUILDING AUS. '98 INDEX | S COST % CHO. YEAR | COMMON AUG. '08 INDEX | | SKILLED AUG. '08 INDEX | LABOR % CHG YEAR | MATER AUG. '88 RIDEX | NALS N CHE YEA |
| ATLANTA | 5397.48 | +2.5 | 3763.75 | +3.6 | 9707,89 | 0.0 | 5415.62 | 0.0 | 2755.61 | +8.2 |
| BALTIMORE | 5765.27 | +8.2 | 4253.20 | +4.4 | 10600.00 | +4.9 | 6629.43 | +1.2 | 2802.05 | 49.5 |
| BIRMINGHAM | 5833.65 | +4.6 | 3561.01 | +5.6 | 11094.74 | +4.5 | 5120.72 | +6.3 | 2609.12 | +4.8 |
| BOSTON | 10120.42 | +3.6 | 5541.41 | +3.0 | 22236.84 | +25 | 10200.00 | 40.3 | 2694.22 | +9.8 |
| CHICAGO | 11290.90 | +1.3 | 5735.01 | +2.7 | 24878.95 | 0.0 | 10271.47 | 0.0 | 2962.74 | +8.8 |
| CINCINNATI | 7940.97 | +4.6 | 4218.39 | +6.3 | 16492.11 | +3.6 | 6704.50 | +4.9 | 2699.96 | +8.5 |
| CLEVELAND | 9726.17 | +14.2 | 4708.64 | +7.2 | 21305.26 | 15.0 | 8111.71 | +5.5 | 2629.31 | +10.5 |
| DALLAS | 5124.26 | +2.9 | 3629.65 | +4.1 | 8700.00 | 0.0 | 4772.97 | 0.0 | 2902.68 | +8.5 |
| DENVER | 5892,17 | +2.1 | 3890.02 | +3.2 | 10831.58 | 0.0 | 5569.97 | 0.0 | 2864.79 | +7.3 |
| DETROIT | 9162.02 | +2.8 | 5024.53 | +24 | 19647.37 | +2.0 | 8770.57 | +0.5 | 2735.52 | +6.3 |
| KANSAS CITY | 9421.57 | +8.5 | 5165.47 | +9.8 | 19615.79 | +7.7 | 8426.43 | +8.5 | 3173.50 | +11.5 |
| LOS ANGELES | 9342.44 | 45.4 | 4963.21 | +5.3 | 19936.84 | +4.8 | 8423.42 | +3.8 | 2849.10 | +8.2 |
| MINNEAPOLIS | 9760.67 | +5.4 | 4979.73 | +5.7 | 21257.89 | +5.6 | 8687.69 | +3.4 | 2713.98 | +10.6 |
| NEW ORLEANS | 4654.50 | +1.6 | 3410.58 | +3.7 | 7763.16 | 0.0 | 4495.50 | +3.0 | 2749.20 | +4.4 |
| NEW YORK | 13028.37 | +4.7 | 6900.93 | +4.9 | 29265.79 | +4.0 | 13157.96 | +3.5 | 3076.40 | +8.5 |
| PHILADELPHIA | 9991.70 | +3.7 | 5587.97 | +4.2 | 21652.63 | +2.6 | 10076.88 | +2.0 | 2844.68 | +9.1 |
| PITTSBURGH | 7735.32 | +5.0 | 4627.85 | +6.7 | 15550.00 | +3.7 | 7381.98 | +5.0 | 2945.67 | +9.3 |
| ST. LOUIS | 8992.31 | +3.0 | 4642.36 | +4.9 | 19294.74 | +1.5 | 7857.66 | +24 | 2677.92 | *9.5 |
| SAN FRANCISCO | 9292.92 | +2.4 | 5320.60 | +6.7 | 19778.95 | +0.8 | 9337.54 | +5.1 | 2866.00 | +10.0 |
| SEATTLE | 8761.59 | +1.6 | 4744.50 | +2.9 | 18368.42 | 0.0 | 7807.21 | 0.0 | 2873.54 | 48.2 |
| MONTREAL | 8756.62 | +4.5 | 4965.11 | +6.3 | 17650.00 | +3.0 | 7682.28 | +4.3 | 3305.84 | 49.4 |
| TORONTO | 9555.05 | +2.1 | 5055,67 | +4.0 | 19373.68 | 0.0 | 7542.94 | 0.0 | 3537.18 | +9.7 |

| TEM | LIMIT | ATLANTA | BALTIMORE | BIRMINGHAM | BOSTON | CHICAGO | CINCINNATI | CLEVELAND | DALLAS | DENVER | DETROIT | KANSAS CITY |
|--|-------|---------|-----------|------------|--------|---------|------------|-----------|--------|------------------------------------|---------|-------------|
| REINFORCED CONCRETE PIPE (RCP): | | | | | | | | | | | | |
| 12" | ft | 11.80 | 25,30 | 11.08 | 9.35 | 10.40 | 15.75 | 9.10 | +12.75 | 12.42 | 12.50 | 12.70 |
| 24" | ft | 29.90 | 50.40 | 25.93 | 22.10 | 22.45 | 27.95 | 21.00 | +27.67 | 22.35 | 36.55 | 27.00 |
| 36" | ft | 51.07 | 99.75 | 52.34 | 48.50 | 45.20 | 67.75 | 44.80 | +57.00 | 52.73 | 74.75 | 53.80 |
| 48" | ft | 82.00 | 166.06 | 85,42 | 73.20 | 71.60 | 114.67 | 72.00 | +85.58 | 81.10 | 112.45 | 93.70 |
| CORRUGATED STEEL PIPE | | | | | | | | | | | | |
| 12" | ft | 8.51 | +10.44 | 7.52 | 8.34 | 8.74 | -6.95 | 8.70 | 8.04 | 7.70 | 6.00 | 10.26 |
| 36" | n | 23.78 | +30.42 | 23.68 | 27.38 | 20.70 | +23.45 | 19.85 | 23.78 | 25.18 | 28.23 | 28.69 |
| 60" | ft | 54,20 | +62.50 | 48.50 | 63.89 | 77.35 | +52.72 | 54.00 | 68.00 | 67.39 | 81.80 | 77.92 |
| VITRIFIED CLAY PIPE (VCP): FREMIUM JOINT | | | | | | | | | | | | |
| 12" | ft | 12.40 | 16.75 | 13.40 | 15,50 | 12.50 | 12,74 | 12.50 | - | - | 14.50 | 7.60 |
| 24 | n | 66.00 | 62.00 | 67.00 | 63,00 | 60.50 | 68,73 | 59.75 | - | A STATE OF THE PARTY OF THE PARTY. | 60.75 | 33.38 |
| POLYETHYLENE PIPE (PE): UNDERDRAIN | | | | | | | | | | | | |
| • | tt | +1.30 | | 0.65 | 0.80 | 2.07 | 0.70 | 0.59 | 1.30 | 1.23 | 0.48 | - |
| POLYVINYLCHLORIDE PIPE (PVC): SEWER | | | | | | | | | | | | |
| 410 | ft | +1.95 | +3.71 | 1.90 | 1,59 | 2,52 | 1.20 | 1.40 | 2.19 | 1.98 | 1.58 | 1.50 |
| 9'* | R | +5.57 | 3.82 | 7.64 | 4.48 | 7.70 | 4,80 | 5.47 | 4.42 | 7.84 | 4,33 | 4.85 |
| Water 6" | ft | +5.96 | +2.62 | 4.26 | 6.20 | 8.50 | 4,49 | 4.97 | 5.20 | 6.15 | 6.23 | 2.53 |
| 0" | - 11 | +9.31 | +4.70 | 7.64 | 10.59 | 8.89 | 7.40 | 7.15 | 6.35 | 9.38 | 11.78 | 4.55 |
| 12" | ft | +18.24 | +10.57 | 17.21 | 21.97 | 19.04 | 15.82 | 15.05 | 14.12 | 15.92 | 23.48 | 11.10 |
| DUCTILE IRON PIPE (DIP): | | | | | | | | | | | | |
| 6" | n | +10.57 | 18.50 | 10.37 | 13.40 | +14.00 | 17,94 | 12.05 | 14.45 | 10.50 | 15.63 | 13.00 |
| 8** | ft | 15.14 | 44.22 | 14.38 | 18.32 | +19.45 | 35.44 | 16.60 | 18.79 | 17.00 | 21.50 | 18.00 |
| 12" | n | +24.15 | 54.63 | 24.29 | 28.00 | +33.29 | 46.37 | 26.28 | 31.00 | 28.30 | 34.70 | 30.25 |
| COPPER WATER TUBING: TYPE L | | | | | | | | | | | | |
| 1/2" | ft | 2.25 | -1.29 | 1.82 | 1.70 | 2.13 | -1.29 | 2.27 | 2.22 | 1.85 | 2.84 | 3.50 |
| 1 1/2" | ft | 3.30 | -5.50 | 4.85 | 5.38 | 4.70 | -6.50 | 6.20 | 4.90 | 4.07 | 3.78 | +14.93 |

+ or - denoted price has risen or fallen since previous report; all-maters, includes facilitate business as of Aug. 8, 2058. All prices are spot prices quoted from a single source, Quotes are delivered prices unless noted. Some prices may include bases or discounts for prompt, payment, dic. Product specification may vary, depending on what is most commonly used or must successively in a city. All quantities are truckloads unless noted. Quotes for Montreal and Toronto are in Calsidian solians and a mix of metric and American units. RCP gips in ASTM C76; 12 in, and 24 in, are notice—gasket painted, others are non-corrupted. Comugated stent pipe

FOR A COMPLETE HISTORY OF COST INDEXES, VISIT OUR WEBSITE, ENR. COM.

Softer Markets Dampen Pipe Price Escalation

The depressed housing market is cutting demand for much of the small-diameter pipe used in residential construction, tracked by ENR. However, higher production costs in some cases are nudging prices up despite tackluster demand. Prices for ductile iron pipe


tracked by ENR are up between 7% and 11% from a year ago, due primarily from the spike in raw-material prices. In the PVC water and sewer pipe markets, weak demand is trumping high oil costs and the annual price increases for PVC pipe are just about 2%.




ENR's Materials Price Indexes









SOURCE: MCGRAW-HILL CONSTRUCTION RESEARCH & ANALYTICS/ENR.

| ПЭМ | UNIT | PERCE | % CHG. 880. | % CHS |
|--|------|--------|----------------|-----------|
| REINFORCED CONCRETE PIPE (RCP): | | | | 1 50/1761 |
| 12" | - 11 | 12.63 | +0.1 | 426 |
| 24" | - 11 | 26.00 | 0.0 | +2.3 |
| 36" | 教 | 53.83 | 40.1 | +25 |
| 48" | 推 | 87.22 | 0.0 | +30 |
| CORRUGATED STEEL PIPE: | | | | 7.3.0 |
| 12" | ft | 8,42 | +0.2 | +2.3 |
| 36" | - 61 | 25.20 | +9.6 | +1.9 |
| 60" | n | 65,46 | +0.5 | +1.7 |
| VITRIFIED CLAY PIPE (VCP): PREMIUM JOINT | | | 7.7 | 7.000 |
| 12" | n | 14.61 | 0.0 | +6.3 |
| 24" | fit. | 55.89 | 0.0 | -21 |
| POLYETHYLENE PIPE (PE): UNDERORANE | | | 14.64 | -61 |
| 4" | ft | 0.96 | +0.4 | +22 |
| POLYVINYLCHLORIDE PIPE (PVC): SEWER | | | | |
| 4" | ft | 1.72 | +2.7 | +5.4 |
| i" | ft | 5.30 | +0.1 | +0.1 |
| Water, 6" | ft | 5.57 | +0.7 | +1.9 |
| 8" | ft | 8.89 | +0.7 | +21 |
| 12" | ft | 18.40 | +0.7 | +22 |
| DUCTILE IRON PIPE (DIP): | | 10/4/ | +0.7 | +62 |
| 5" | ft | 14.02 | +0.1 | +9.0 |
| y. | ** | 20.79 | 0.0 | +10.5 |
| 12" | | 32.04 | +0.1 | |
| COPPER WATER TUBING: TYPE L | | 134 47 | 70.1 | +7.1 |
| 12" | # | 2.09 | -1.0 | +2.6 |
| 1/2" | tt | 5.62 | -0.5 | +1.7 |

| | | | | | SALL CONTRACTOR | NAME OF TAXABLE PARTY. | | | | | Can | ada |
|--|------|-------------|-------------|--|---------------------------------|--|--|--|--|----------|--|--|
| REINFORCED CONCRETE PIPE (RCP): | uraT | LOS ANGELES | MINNEAPOLIS | NEW ORLEANS | NEW YORK | PHRADELPHIA | PITTSBURGH | ST. LOUIS | SAN FRANCISCO | SEATTLE | MONTREAL | TORONTO |
| 12" | | 11.78 | 19.98 | 10.91 | | | | | | | | Anna de la Caración d |
| 24' | 60 | 24.18 | 35.00 | 25.34 | NAME OF THE PARTY OF THE PARTY. | +8.90 | 12.00 | 9,00 | 12.02 | 12.09 | 67.50a | 49,10a |
| 36" | 40 | 51.38 | 73.00 | 52.48 | | +14.80 | 21.35 | 17.30 | 24.96 | 25.00 | 206.40a | 95,40a |
| 48" | | 82.96 | 125.80 | The first the first Appendix to the first terminal for | | +28.10 | 45.80 | 31,90 | 52.02 | 50,97 | 421.90a | 260,20a |
| CORRUGATED STEEL PIPE: | 31 | 54.30 | 1460100 | 84.70 | - | +45.00 | 72.80 | 55.30 | 83.89 | 88.13 | 694.808 | 430.60a |
| 121 | ft | 7.99 | 10.23 | 8.82 | 950 | 5.87 | 6.95 | - | | | | |
| 36" | 71 | 25.02 | 36.25 | 23.47 | In the party state of the last | 29.70 | 19.77 | 9.11 | 8.03 | 11.82 | | 35.27a |
| 50" | ft | 63.11 | 92.60 | 52.08 | | 50.00 | DOMESTIC STREET, STREE | 23.92 | 25,54 | 33,30 | Section 2015 | 123.10a |
| TITRIFIED CLAY PIPE (VCP): PREMIUM JOINT | | | | 06.00 | TO THE REAL PROPERTY. | 50.00 | 57,00 | 52.90 | 63.89 | 88.58 | 236,40 | 309.41a |
| | ft | 13.60 | 14.80 | 3000 | - | 28.00 | 8.66 | 14.50 | 13.74 | 15.10 | 40.00 | |
| M. | Ħ | 50,46 | 46.00 | | _ | 62.00 | 43.35 | 45.00 | 50.71 | 55.61 | 16.30 | 16.50 |
| OLYETHYLENE PIPE (PE): UNDERDRAIN | | | | | | TO THE OWNER OF THE PARTY OF TH | - | 40,00 | 30.71 | 20.01 | 70.00 | 60.75 |
| | ft | 0.89 | 0.64 | 1,42 | 600 | 1.08 | 0.35 | 0.65 | 0.91 | 1.30 | | 0.35a |
| OLYVINYLCHLORIDE PIPE (PVC): SEWER | | | | | | | The same | | Water and the William of the Control | - Little | | V.308 |
| | ft | 1.68 | 1.18 | 1.73 | Non | 1.33 | 1.26 | 1.15 | 1.79 | 1.55 | 6.69 b | 9.89 |
| | ft | 5,50 | 4.53 | 4.70 | | 5.59 | 4.29 | 4.27 | 5.40 | 5.38 | 22.50b | 33.34 |
| Vater 6" | ft | 5.26 | 5.63 | 5.84 | Assa | 7.30 | 6.66 | 5.37 | 5.30 | 6.32 | 36,406 | 49.70 |
| ** | R | 8.35 | 9.78 | 8.58 | | 12.77 | 11.16 | 9.12 | 8.39 | 8.47 | 47.72b | 83,30 |
| 2" | ft | 17.94 | 20.67 | 18.74 | | 28.00 | 20.64 | 19.58 | 18.06 | 17.15 | 106.316 | |
| UCTILE IRON PIPE (DIP): | | | | | | | and the state of the same of t | and the state of t | 10/00 | 17.10 | 100.310 | 132.00 |
| **************************** | ft | 12.20 | 13.45 | 14.97 | | 14.33 | 12.62 | 13.38 | 12.31 | 15.65 | 40.55 | 02.00- |
| | ft | 18.06 | 18.58 | 19.16 | Sept. | 20,17 | 17,22 | 18.38 | 18.25 | 18.50 | 59.06 | 91,00a |
| 21 | ft | 28.94 | 30.60 | 28.15 | The second second | 30.26 | 28.11 | 30.80 | 30.40 | 25.74 | THE PERSON NAMED IN COLUMN TWO IS NOT THE OWNER. | 38.02a |
| OPPER WATER TUBING: TYPE L | | | | | | | white the brades are | Gration) | 30,40 | 25.74 | 89.49 | 63.86a |
| | tt | 1.99 | 2.80 | 1.72 | _ | 1.70 | 1.85 | 2.10 | 2.04 | 2.49 | 8.73 | 5.18 |
| 12" | ft | 4.87 | 7.80 | 3.97 | data | 5.48 | 4.05 | 8.00 | 4.99 | 5.12 | 30.00 | 21.38 |

is used applications; 12 in: to 16 gauge, 36 in: to 14 gauge, 60 in: to 12 gauge, 90 in: to 12 gauge, 90 in: to 12 gauge, 90 pipe to ASTM CFOOL ESTM CFOOL

UTILITY AUDIT SUMMARY FY07 ALL CAMPUSES

G:\UTILITY\Audits - Utility\Summary of Audit Values and Unit Costs\[All Campuses - Utility Audit Summary FY07.xls]All Campuses FY07 Revision No. 1
28-Aug-08

| Utility Audit Summary | | | | | | |
|----------------------------|---------|--|-------|----|------------|--|
| Audit Update: | Jan-07 | Renewal Cost: | | \$ | 29,879,592 | |
| No. of Years in Update: | 3.00 | Average Deteriortation & Inflation Rate: | 10.0% | | | |
| Original Audit Date: | July-01 | | | | | |
| Prior Audit Cost Update: | May-04 | | | | | |
| | | Replacement Value: | | \$ | 91,248,41 | |
| Average Condition Index ** | 0.67 | Average Construction Inflation Rate: | 3.0% | | | |

| Utility System | 2001 | Replacement Value | 2001 Condition Index ** | 2001 Renewal Cost | | |
|----------------------|------|----------------------|-------------------------------|----------------------|------------|--|
| ELECTRIC | \$ | 3,755,700 | 0.85 | \$ | 557,580 | |
| DISTRICT HEATING | | | | | | |
| Steam | \$ | 5,754,800 | 0.40 | \$ | 3,454,500 | |
| Condensate | \$ | 2,353,200 | 0.40 | \$ | 1,406,600 | |
| Tunnel | \$ | 26,202,800 | 0.90 | \$ | 2,496,300 | |
| Heating Plant System | | 16,115,000 | 0.56 | \$ | 7,102,000 | |
| Subtotal | \$ | 50,425,800 | 0.71 | \$ | 14,459,400 | |
| DISTRICT COOLING | | | | | | |
| Pipes | \$ | 2,393,400 | 0.96 | \$ | 97,000 | |
| Plant Equipment | \$ | 3,566,600 | 0.95 | \$ | 178,330 | |
| Subtotal | \$ | 5,960,000 | | \$ | 275,330 | |
| NATURAL GAS/PROPANE | \$ | 663,700 | 0.35 | \$ | 431,200 | |
| WATER | \$ | 5,074,300 | 0.77 | \$ | 1,161,200 | |
| SANITARY | \$ | 3,546,500 | 0.72 | \$ | 1,002,600 | |
| STORMWATER | \$ | 5,625,000 | 0.75 | \$ | 1,425,000 | |
| IRRIGATION | \$ | 1,386,800 | 0.35 | \$ | 907,600 | |
| COMPRESSED AIR | \$ | 1,105,100 | 0.43 | \$ | 626,200 | |
| Total | \$ | 77,542,900 | 0.73 | \$ | 20,846,110 | |

S AWERY

| A. AGENCY BASIC DATA: |
|--|
| x Controlled Maintenance Request Capital Renewal Building/Infrastructure Request |
| 1) Agency Colorado State University |
| 2) Department Higher Education |
| 3) Physical Plant ID No. 16-00 Project M # |
| 4) Agency Priority # 1 |
| 5) Project Title Sanitary Sewer Improvements, Main Campus – Phase 2 of 3 |
| B. FACILITY PROFILE |
| 1) Facility Type x Site (Utilities underground) |
| or Site (Improvements above ground) |
| or Building Name (s) Risk Mgmt. Bldg(s) ID# |
| 2) Facility Location Main Campus |
| 3) Facility Area/Age GSF ASF Date Built |
| 4) Facility Functional Use/Occupancy |
| 5) Facility Construction (Type) |
| 6) Facility Physical Condition and Facility Condition Index (FCI) Number |
| Actual FCI = Targeted FCI = Date of Last Audit |
| (Describe) |
| |
| |
| |
| 7) Facility - Intensity of Use, Time(s) of Operation: (Hours/Day, Days/Month, Months/Year)24/31/12 |
| 8) Facility - Current Replacement Value \$ |
| 9) Master Plan Status - Check one or more of the following: |
| a) Facility 'useful' life is less than five (5) years. |
| b) x Facility 'useful' life is more than five (5) years. |
| c) Master Plan is obsolete; Last Date Approved |
| (by OSPB/CCHE) |
| d) Major facility changes, renovations, or program revisions are ongoing or anticipated in the next five years, (If yes, please explain below if these facility renovations or program revisions may have an impact on this CM request.) |
| |
| |
| |
| |

Page __1__ of __5_

| 10) Facility Audit Survey: a) Facility Audit Survey concluded and submitted to SBREP - Date b) Status of the Infrastructure Assessment. % Completed 50 C) Facility Audit Survey Cycle 11) List all the controlled maintenance, capital construction, and emergency projects completed within the last five years or ongoing projects that can be associated with either this CM building or infrastructure request. Completion date or status Completion date or status Completion date or status Completion of CM Problem (Initial problem and solution by phase): The lower end of the "C" basin is overloaded and there is excessive groundwater infiltration. Many sections of the "C" basin collection mains have excessive groundwater infiltration and the manholes need rehabilitation. The line size of the lower section of the system will be increased using pipe expansion technology. Slip lining will repair the collection lines. Old brick manholes will be replaced with precast concrete units. 2) Total Project Cost Estimate (From Cost Breakdown) \$ 2,035,532 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request. Further deterioration of the swer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a specific infrastructure system. | | | Page _ | _2_ of _5_ |
|---|---|---|--|--|
| a) Facility Audit Survey concluded and submitted to SBREP - | 10) Facility Audit Surve | eV: | | |
| c) Facility Audit Survey Cycle 11) List all the controlled maintenance, capital construction, and emergency projects completed within the last five years or ongoing projects that can be associated with either this CM building or infrastructure request. Project No. Project Title Completion date or status C. INTEGRATED PROGRAM PLAN DATA NOTE: For a Capital Renewal Building/Infrastructure Request, refer to the instructions for the additional information required to support the request. 1) Narrative Description of CM Problem (Initial problem and solution by phase): The lower end of the "C" basin is overloaded and there is excessive groundwater infiltration. Many sections of the "C" basin collection mains have excessive groundwater infiltration and the manholes need rehabilitation. The line size of the lower section of the system will be increased using pipe expansion technology. Slip lining will repair the collection lines. Old brick manholes will be replaced with precast concrete units. 2) Total Project Cost Estimate (From Cost Breakdown) \$ 2,035,532 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | | | Date | |
| 11) List all the controlled maintenance, capital construction, and emergency projects completed within the last five years or ongoing projects that can be associated with either this CM building or infrastructure request. Project No. Project Title Completion date or status C. INTEGRATED PROGRAM PLAN DATA NOTE: For a Capital Renewal Building/Infrastructure Request, refer to the instructions for the additional information required to support the request. 1) Narrative Description of CM Problem (Initial problem and solution by phase): The lower end of the "C" basin is overloaded and there is excessive groundwater infiltration. Many sections of the "C" basin collection mains have excessive groundwater infiltration and the manholes need rehabilitation. The line size of the lower section of the system will be increased using pipe expansion technology. Slip lining will repair the collection lines. Old brick manholes will be replaced with precast concrete units. 2) Total Project Cost Estimate (From Cost Breakdown) \$ 2,035,532 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | b) Status of the Ir | nfrastructure Assessment. | % Completed | 50 |
| last five years or ongoing projects that can be associated with either this CM building or infrastructure request. Completion date or status C. INTEGRATED PROGRAM PLAN DATA NOTE: For a Capital Renewal Building/Infrastructure Request, refer to the instructions for the additional information required to support the request. 1) Narrative Description of CM Problem (Initial problem and solution by phase): The lower end of the "C" basin is overloaded and there is excessive groundwater infiltration. Many sections of the "C" basin collection mains have excessive groundwater infiltration and the manholes need rehabilitation. The line size of the lower section of the system will be increased using pipe expansion technology. Slip lining will repair the collection lines. Old brick manholes will be replaced with precast concrete units. 2) Total Project Cost Estimate (From Cost Breakdown) \$ 2,035,532 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | c) Facility Audit S | Survey Cycle | | |
| Completion date or status C. INTEGRATED PROGRAM PLAN DATA NOTE: For a Capital Renewal Building/Infrastructure Request, refer to the instructions for the additional information required to support the request. 1) Narrative Description of CM Problem (Initial problem and solution by phase): The lower end of the "C" basin is overloaded and there is excessive groundwater infiltration. Many sections of the "C" basin collection mains have excessive groundwater infiltration and the manholes need rehabilitation. The line size of the lower section of the system will be increased using pipe expansion technology. Slip lining will repair the collection lines. Old brick manholes will be replaced with precast concrete units. 2) Total Project Cost Estimate (From Cost Breakdown) \$ 2,035,532 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | last five years or or | ed maintenance, capital construction, and emergageing projects that can be associated with eith | gency projects comper this CM building | oleted within the or infrastructure |
| C. INTEGRATED PROGRAM PLAN DATA NOTE: For a Capital Renewal Building/Infrastructure Request, refer to the instructions for the additional information required to support the request. 1) Narrative Description of CM Problem (Initial problem and solution by phase): The lower end of the "C" basin is overloaded and there is excessive groundwater infiltration. Many sections of the "C" basin collection mains have excessive groundwater infiltration and the manholes need rehabilitation. The line size of the lower section of the system will be increased using pipe expansion technology. Slip lining will repair the collection lines. Old brick manholes will be replaced with precast concrete units. 2) Total Project Cost Estimate (From Cost Breakdown) \$ 2,035,532 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | | | | |
| NOTE: For a Capital Renewal Building/Infrastructure Request, refer to the instructions for the additional information required to support the request. 1) Narrative Description of CM Problem (Initial problem and solution by phase): The lower end of the "C" basin is overloaded and there is excessive groundwater infiltration. Many sections of the "C" basin collection mains have excessive groundwater infiltration and the manholes need rehabilitation. The line size of the lower section of the system will be increased using pipe expansion technology. Slip lining will repair the collection lines. Old brick manholes will be replaced with precast concrete units. 2) Total Project Cost Estimate (From Cost Breakdown) \$ 2,035,532 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | Project No. Pro | ject Title | | or status |
| NOTE: For a Capital Renewal Building/Infrastructure Request, refer to the instructions for the additional information required to support the request. 1) Narrative Description of CM Problem (Initial problem and solution by phase): The lower end of the "C" basin is overloaded and there is excessive groundwater infiltration. Many sections of the "C" basin collection mains have excessive groundwater infiltration and the manholes need rehabilitation. The line size of the lower section of the system will be increased using pipe expansion technology. Slip lining will repair the collection lines. Old brick manholes will be replaced with precast concrete units. 2) Total Project Cost Estimate (From Cost Breakdown) \$ 2,035,532 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | | | | |
| NOTE: For a Capital Renewal Building/Infrastructure Request, refer to the instructions for the additional information required to support the request. 1) Narrative Description of CM Problem (Initial problem and solution by phase): The lower end of the "C" basin is overloaded and there is excessive groundwater infiltration. Many sections of the "C" basin collection mains have excessive groundwater infiltration and the manholes need rehabilitation. The line size of the lower section of the system will be increased using pipe expansion technology. Slip lining will repair the collection lines. Old brick manholes will be replaced with precast concrete units. 2) Total Project Cost Estimate (From Cost Breakdown) \$ 2,035,532 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | | | | |
| NOTE: For a Capital Renewal Building/Infrastructure Request, refer to the instructions for the additional information required to support the request. 1) Narrative Description of CM Problem (Initial problem and solution by phase): The lower end of the "C" basin is overloaded and there is excessive groundwater infiltration. Many sections of the "C" basin collection mains have excessive groundwater infiltration and the manholes need rehabilitation. The line size of the lower section of the system will be increased using pipe expansion technology. Slip lining will repair the collection lines. Old brick manholes will be replaced with precast concrete units. 2) Total Project Cost Estimate (From Cost Breakdown) \$ 2,035,532 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | | | | |
| 1) Narrative Description of CM Problem (Initial problem and solution by phase): The lower end of the "C" basin is overloaded and there is excessive groundwater infiltration. Many sections of the "C" basin collection mains have excessive groundwater infiltration and the manholes need rehabilitation. The line size of the lower section of the system will be increased using pipe expansion technology. Slip lining will repair the collection lines. Old brick manholes will be replaced with precast concrete units. 2) Total Project Cost Estimate (From Cost Breakdown) \$ 2,035,532 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | C. INTEGRATED PR | ROGRAM PLAN DATA | | |
| "C" basin is overloaded and there is excessive groundwater infiltration. Many sections of the "C" basin collection mains have excessive groundwater infiltration and the manholes need rehabilitation. The line size of the lower section of the system will be increased using pipe expansion technology. Slip lining will repair the collection lines. Old brick manholes will be replaced with precast concrete units. 2) Total Project Cost Estimate (From Cost Breakdown) \$\(\frac{2}{,035,532}\)\$ 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | | | the instructions for | the additional |
| 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | "C" basin is overloaded collection mains have e size of the lower section | I and there is excessive groundwater infiltration. excessive groundwater infiltration and the manh n of the system will be increased using pipe exp | . Many sections of the coles need rehabilitate cansion technology. | he "C" basin ition. The line Slip lining |
| specific project request: Further deterioration of the sewer mains and manholes may cause portions of the lines to collapse, resulting in back-ups in buildings and overflow from manholes. Groundwater infiltration decreases system capacity, and also causes back-ups. 4) Mandatory - Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | 2) Total Project Cost Es | stimate (From Cost Breakdown) \$2,035,532 | 2 | |
| infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | specific project requ of the lines to collap | uest: Further deterioration of the sewer mains are use, resulting in back-ups in buildings and overfl | nd manholes may c | ause portions |
| infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | | | | |
| infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility condition index or improve a | 4) Mandatory - Include | E Facility Audit documentation from most recent | audit Include site | maps for any |
| 5) Optional - Include photographs and any other supporting documents.6) Explanation of how this project will improve the building(s) facility condition index or improve a | | | and manage site | , , , , , , |
| 6) Explanation of how this project will improve the building(s) facility condition index or improve a | | | S. | |
| | | | | prove a |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

| | | | Page3 of5_ |
|---|--------------|-----------------|--------------------------|
| D. <u>DETAILED COST ESTIMATE</u> (detail by | y phase, or | ne page per pha | ase, include all phases) |
| 1) Approved By Dewey Wearne | | 2) Phase? | 2 |
| 3) Method of Estimate Historic | | | _ |
| 7110110 | | | |
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | | | |
| Code Review/Inspection | | | |
| Other (Explain) | | | |
| Total of Professional Services | | | \$0 |
| 5) 0 t t' t | | | |
| 5) Construction Improvement WORK ITEM | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) | OINIT | ONIT COST | LATENDED COOT |
| Infrastructure | | | |
| a) Utility Services | | | |
| Rehab lines North of Isotope Dr. | LF | \$79.30 | \$634,400 |
| Trends meet version and pro- | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Total of Construction Improvements Costs | | | \$634,400 |
| | | | |
| 6) Miscellaneous (explain) | | | |
| | | | |
| | | | |
| Total of Miscellaneous Costs | | | \$0 |
| 7) Project Contingency | | | |
| 7) Project Contingency Contingency (10% CM) (Percentage of total or | f profession | al services | \$63,440 |
| construction improvements, and miscellaneou | | ar 551 11555, | 400,110 |
| | | | |
| 8) Subtotal of professional services, construct | ion improve | ments, | \$697,840 |
| miscellaneous costs, and project contingen | cy percenta | ige (by phase) | |
| | | | |
| | | | T |
| 9) TOTAL PROJECT COST (all phases)= | REQUES | | \$2,035,532 |

Note: Agency formatted cost estimates may accompany this page.

| | | | Page4_ of5_ |
|---|--|---------------------|--------------------------|
| D. <u>DETAILED COST ESTIMATE</u> (detail by | / phase, or | ne page per ph | ase, include all phases) |
| 1) Approved By Dewey Wearne | | 2) Phase? | 3 |
| 3) Method of Estimate Historic | | | |
| 1) D. (| | | |
| Professional Services Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | | | |
| Code Review/Inspection | | | |
| Other (Explain) | | | |
| Total of Professional Services | | | \$0 |
| 5) O and a time language and | | | |
| 5) Construction Improvement WORK ITEM | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) | OIVII | 01411 0001 | EXTENDED COOT |
| Infrastructure | | | |
| a) Utility Services | | | |
| Rehab lines South of Isotope Dr. | LF | \$79.30 | \$634,400 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Total of Construction Improvements Costs | | | \$634,400 |
| | | | |
| 6) Miscellaneous (explain) | | 1 | |
| | | | |
| T. L. L. S. M. Constant | | | \$0 |
| Total of Miscellaneous Costs | | | φυ |
| 7) Project Contingency | | | |
| Contingency (10% CM) (Percentage of total of | professiona | al services, | \$63,440 |
| construction improvements, and miscellaneous | s costs.) | | |
| | on impress | monte | \$607.840 |
| 8) Subtotal of professional services, construction miscellaneous costs, and project contingender | on improvei | ge (by phase) | \$697,840 |
| This centaries as sosts, and project contingent | - Porconta | J - (,) p , (,) | |
| | | | |
| 9) TOTAL PROJECT COST (all phases)= | REQUES | Γ | \$2,035,532 |
| Note: Agency formatted cost estimates m | CAMPBELL PROPERTY AND ADDRESS OF THE PARTY AND | | |

SBREP CM-03 - FY2009/2010

| STATE | BUILDIN | GS AND REAL ES | TATE PROGRAMS | | |
|------------------------------|----------------|---------------------------|---------------------------------|--------------------------------|----------------|
| E PRO | POSED F | PHASING | | Page | 5 of5 |
| | PHASING | | | | |
| Proj. | Phys. | Fiscal Year | Phase or Phases of Work | Dollar Amount | |
| M# | Plant ID# | | | (Actual Appropriation) | |
| | | FY 2006/2007 | | \$639,852 | |
| | | | | | _ |
| | | | | \$ 639,852 | (Subtotal) |
| | | | | | |
| - | | SE ² REQUESTED | Di CAAi | Dallas Assault | 7 |
| Proj. M# | Phys. Plant | Fiscal Year | Phase of Work | Dollar Amount (Per Detailed | |
| | ID# | | | Budget) | |
| | 16-00 | FY 2009/2010 | 2 | \$697,840 | |
| | | | | | |
| | | | | \$697,840 | _ (Subtotal) |
| - | PHASI | | | | 7 |
| Proj. M# | Phys. Plant | Fiscal Year | Phase or Phases of Work | Dollar Amount (Per Detailed | |
| 1407 | ID# | | | Budget) | |
| A SHE | 16-00 | FY 2010/2011 | 3 | \$697,840 | |
| | | | | | |
| | | | | \$ 697,840 | _ (Subtotal) |
| Project 1 | Total Dolla | ar Amount of All Pro | jects Phases Requested | \$ 2,035,532 | |
| | | and Future Phases) | | | |
| 1 List all a | araviava n | haces with actual enr | proprietion by year (include fo | doral funding) Noto if | different from |
| | ted amour | | propriation by year (include fe | derai funding). Note ii | different from |
| ² List all | current an | d anticipated future pl | hases with estimated costs as | s listed in the detailed | cost estimate |
| subtota | Il blank 8. | | | | |
| F. PROI | POSED F | PROJECT IMPLEM | ENTATION SCHEDULE (F | PLAN): | |
| | | | | | |
| | P | PHASE | FROM | | ТО |
| 1. Pre-Design (Insert Dates) | | July 06 | Dec 06 | | |
| 2. Design (Insert Dates) | | Dec 06 | May 07 | | |
| | | sert Dates) | May 07 | May 10 | |
| 4. Projec | t Close-ou | ut/Final Completion | May 11 | July 11 | |
| | | | | | |
| | | | | | |
| G. AGE | NCY APP | PROVAL | | | |

Date

Agency Authorized Signature

UTILITY AUDIT SUMMARY FY07 ALL CAMPUSES

G:\UTILITY\Audits - Utility\Summary of Audit Values and Unit Costs\[All Campuses - Utility Audit Summary FY07.xls]All Campuses FY07 Revision No. 1
28-Aug-08

| | | Utility Audit Summary | | |
|----------------------------|--------|--|-------|------------------|
| Audit Update: | Jan-07 | Renewal Cost: | | \$ 29,879,592 |
| No. of Years in Update: | | Average Deteriortation & Inflation Rate: | 10.0% | |
| Original Audit Date: | | | | |
| Prior Audit Cost Update: | | | | |
| | | Replacement Value: | | \$ 91,248,41 |
| Average Condition Index ** | 0.67 | Average Construction Inflation Rate: | 3.0% | |

| Utility System | 2001 | Replacement Value | 2001 Condition Index ** | Re | 2001 newal Cost |
|----------------------|----------|----------------------|-------------------------------|----|--------------------|
| ELECTRIC | \$ | 3,755,700 | 0.85 | \$ | 557,580 |
| DISTRICT HEATING | | | | | |
| Steam | \$ | 5,754,800 | 0.40 | \$ | 3,454,500 |
| Condensate | \$ | 2,353,200 | 0.40 | \$ | 1,406,600 |
| Tunnel | | 26,202,800 | 0.90 | \$ | 2,496,300 |
| Heating Plant System | \$ \$ | 16,115,000 | 0.56 | \$ | 7,102,000 |
| Subtotal | \$ | 50,425,800 | 0.71 | \$ | 14,459,400 |
| DISTRICT COOLING | | | | | |
| Pipes | \$ | 2,393,400 | 0.96 | \$ | 97,000 |
| Plant Equipment | \$ | 3,566,600 | 0.95 | \$ | 178,330 |
| Subtotal | \$ | 5,960,000 | | \$ | 275,330 |
| NATURAL GAS/PROPANE | \$ | 663,700 | 0.35 | \$ | 431,200 |
| WATER | \$ | 5,074,300 | 0.77 | \$ | 1,161,200 |
| SANITARY | \$ | 3,546,500 | 0.72 | \$ | 1,002,600 |
| STORMWATER | \$ | 5,625,000 | 0.75 | \$ | 1,425,000 |
| IRRIGATION | \$ | 1,386,800 | 0.35 | \$ | 907,600 |
| COMPRESSED AIR | \$ | 1,105,100 | 0.43 | \$ | 626,200 |
| Total | \$ | 77,542,900 | 0.73 | \$ | 20,846,110 |

| A. AGENCY BA | ASIC DATA: | |
|------------------------|------------------------|--|
| X Controlle Request | d Maintenance | Capital Renewal Building/Infrastructure Request HPCP required in Capital Renewal Request (Y/N) (on CC-A specify HPCP compliance) |
| 1) Agency | Colorado State Univers | ity |
| 2) Department | Higher Education | |

3) Physical Plant ID No. 00-002 Project M #

4) Agency Priority # 1

5) Project Title Replace Failed Roofing Phase 1 of 2

B. FACILITY PROFILE

| 1) Facility Type | | Site (Utilities underground | d) |
|------------------|---|-----------------------------|-------------|
| | | or Site (Improvements ab | ove ground) |
| | x | or Building Name (s) | See below |
| | | Risk Mgmt. Bldg(s) ID# | See below |
| | | 0 1 1 | |

2) Facility Location See below

3) Facility Area/Age GSF See below ASF See below Date Built See below

4) Facility Functional Use/Occupancy See below

5) Facility Construction (Type) See below

6) Facility Physical Condition and Facility Condition Index (FCI) Number See below

| Actual FCI = _ | See below | w Targ | eted FCI = | = See | e below | Date of Last A | udit See belov | W |
|------------------|-----------|---------|------------|--------|----------------|----------------|----------------|---|
| (Describe) | Risk | GSF | ASF | Date B | uilt Occupancy | Const. Type | FCI | |
| VTH | 3445 | 137,233 | 125,020 | 1979 | Vet Medicine | II-FR | 72.09 | |
| Horse Barn | 3444 | 45,194 | 42,312 | 1979 | Vet Medicine | II-FR | 70.98 | |
| Microbiology | 3310 | 85,131 | 76,830 | 1968 | Science | II-FR | 77.02 | |
| Student Services | 3254 | 36,717 | 31,412 | 1948 | Office | II-FR | 74.88 | |
| Painter | 3338 | 31,139 | 27,591 | 1980 | Animal Science | e II-FR | 80.47 | |
| Chemistry | 3339 | 168,037 | 153,007 | 1971 | Bio Science | II-FR | 71.23 | |
| | | | | | | | | |

⁷⁾ Facility - Intensity of Use, Time(s) of Operation: (Hours/Day, Days/Month, Months/Year) 12/21/12

⁸⁾ Facility - Current Replacement Value \$ VTH - \$23,456,002, Horse Barn - \$3,926,459, Microbiology \$3,915,626, Student Services - \$3,915,626, Painter - \$4,257,642, Chemistry - \$31,230,735

| 9) Mas | ster | Plan Status - Check one or more of the following: | |
|--------|------|---|---|
| a) | | Facility 'useful' life is less than five (5) years. | |
| b) | X | Facility 'useful' life is more than five (5) years. | |
| c) | | Master Plan is obsolete; Last Date Approved | |
| | | (by OSPB/CDHE) | |
| d) | | Major facility changes, renovations, or program revisions are ongoing or anticipated in the next five years, (If yes, please explain below if these facility renovations or program revisions may have an impact on this CM request.) | } |
| | | | |

| | 10) = ''' | | | | |
|---|--|---|---|---------------------------------------|-------------------------------------|
| | 10) Facility Audita) Facility A | Survey: Audit Survey concluded a | nd submitted to SBP - | Date | 01/2008 |
| | b) Status of | f the Infrastructure Asses | sment. | % Completed | 100 |
| | | audit Survey Cycle | 6/2 | | |
| | 11) List all the co | ntrolled maintenance, ca | pital construction, and emergen can be associated with either t | cy projects comp his CM building o | oleted within the or infrastructure |
| | | | | | Completion date |
| | Project No. | Project Title | sonital Machanias and Fire Co | | or status In Closeout |
| - | P0622 | | ospital, Mechanical and Fire Sp | IIIIKIEIS I | III Closeout |
| - | | | | | |
| - | | | | | |
| | C. INTEGRATE | ED PROGRAM PLAN [| DATA | | |
| | | oital Renewal Building/Inf red to support the reques | rastructure Request, refer to the t. | e instructions for | the additional |
| | 1) Narrative Desc | cription of CM Problem (In | nitial problem and solution by ph | nase): | |
| | | | cted in 1979. The roofing is buil ked, the flashings are bad and t | | |
| | Center section | of Microbiology has an | EPDM roof. The existing roofing | was installed in | 1988 and is |

2) Total Project Cost Estimate (From Cost Breakdown) \$ 3,377,550

beyond life expectancy. The seams are opening and flashing is torn.

Student Services has an EPDM installed in 1981 with the same problems.

3) Consequences (cost effects, program impacts, facility impacts, etc.) of <u>not</u> funding and justifying this specific project request:

As roofs fail we will continue to have leaks into laboratories, classrooms, and office areas below. With no swing space available this will cause loss of use to these areas.

Painter Center has two different roofing types. The west side is EPDM that was installed in 1988. The east side is built-up asphalt that was installed when the building was constructed in 1980. Chemistry has built-up asphalt roofing that was installed in 1981 with the same problems.

- 4) **Mandatory** Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request.
- 5) Optional Include photographs and any other supporting documents.
- 6) Explanation of how this project will improve the building(s) facility condition index or improve a specific infrastructure system.

Life expectancy of new roofing would be 20 years. The roofing component would increase to 95 – 100 improving the overall facility condition index on each building.

| 1) Approved By | UNIT | 2) Phase? | \$180,000 \$35,000 \$215,000 EXTENDED COST |
|---|--|--------------|---|
| 3) Method of Estimate Historic 4) Professional Services Site Surveys, Investigations, and Reports Arch/Eng/Basic Services Code Review/Inspection Other (Explain) Total of Professional Services 5) Construction Improvement WORK ITEM (Labor/Material/Equipment) Infrastructure a) Utility Services | UNIT | | \$180,000 \$35,000 \$215,000 |
| Site Surveys, Investigations, and Reports Arch/Eng/Basic Services Code Review/Inspection Other (Explain) Total of Professional Services 5) Construction Improvement WORK ITEM (Labor/Material/Equipment) Infrastructure a) Utility Services | UNIT | UNIT COST | \$35,000 \$215,000 |
| Site Surveys, Investigations, and Reports Arch/Eng/Basic Services Code Review/Inspection Other (Explain) Total of Professional Services 5) Construction Improvement WORK ITEM (Labor/Material/Equipment) Infrastructure a) Utility Services | UNIT | UNIT COST | \$35,000 \$215,000 |
| Arch/Eng/Basic Services Code Review/Inspection Other (Explain) Total of Professional Services 5) Construction Improvement WORK ITEM (Labor/Material/Equipment) Infrastructure a) Utility Services | UNIT | UNIT COST | \$35,000 \$215,000 |
| Code Review/Inspection Other (Explain) Total of Professional Services 5) Construction Improvement WORK ITEM (Labor/Material/Equipment) Infrastructure a) Utility Services | UNIT | UNIT COST | \$35,000 \$215,000 |
| Other (Explain) Total of Professional Services 5) Construction Improvement WORK ITEM (Labor/Material/Equipment) Infrastructure a) Utility Services | UNIT | UNIT COST | \$215,000 |
| Total of Professional Services 5) Construction Improvement WORK ITEM (Labor/Material/Equipment) Infrastructure a) Utility Services | UNIT | UNIT COST | |
| 5) Construction Improvement WORK ITEM (Labor/Material/Equipment) Infrastructure a) Utility Services | UNIT | UNIT COST | |
| WORK ITEM (Labor/Material/Equipment) Infrastructure a) Utility Services | UNIT | UNIT COST | EXTENDED COST |
| WORK ITEM (Labor/Material/Equipment) Infrastructure a) Utility Services | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) Infrastructure a) Utility Services | | | |
| a) Utility Services | | | |
| | | | |
| b) Site Improvements | | | |
| | | | |
| | THE RESERVE OF THE PARTY OF THE | | |
| Structure/System/Components | | | |
| | | | |
| Other(explain) | | | |
| VTH | 660 Sq. | \$1500 | \$990,000 |
| Horse Barn | 404 Sq. | \$1500 | \$606,000 |
| | | | |
| | | | |
| | | | |
| | | | |
| T.1.1.50 | | | #4 500 000 |
| Total of Construction Improvements Costs | | | \$1,596,000 |
| 6) Miscellaneous (explain) | | | _ |
| | | | |
| Total of Miscellaneous Costs | | | \$ |
| 7) Project Contingency | | | |
| Contingency (10% CM) (Percentage of total or construction improvements, and miscellaneous | | al services, | \$181,100 |
| 8) Project or Phase total of professional service | ces (4), cons | struction | \$1,992,100 |
| improvements(5), miscellaneous costs(6), | | | |
| | | | |
| 9) TOTAL PROJECT COST (all phases)= | = REQUES | T | \$3,377,550 |

Note: Agency formatted cost estimates may accompany this page.

| DETAILED COST ESTIMATE (detail by pl | nase, one | page per phase | e, include all phases) |
|---|--------------|----------------|------------------------|
| 1) Approved By Dewey Wearne | | 2) Phase? | 2 |
| 3) Method of Estimate Historic | | | |
| | | | |
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | | | |
| Code Review/Inspection | | | |
| Other (Explain) | | | |
| Total of Professional Services | | | |
| 5) Construction Improvement | | | |
| <u>WORK ITEM</u> | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) | | | |
| Infrastructure | | | |
| a) Utility Services | | | |
| b) Site Improvements | | | |
| | | | |
| Structure/System/Components | | | |
| Other(evaluin) | | | |
| Other(explain) | | | |
| | | | |
| Microbiology | 97 Sq. | \$1500 | \$145,000 |
| Student Services | 135 Sq. | \$1500 | \$202,500 |
| Painter Center | 152 Sq. | \$1500 | \$229,500 |
| Chemistry | 455 Sq. | \$1500 | \$682,500 |
| | ' | | |
| Total of Construction Improvements Costs | | | \$1,259,500 |
| | | | |
| 6) Miscellaneous (explain) | | | |
| | | | |
| | | | |
| Total of Miscellaneous Costs | | | \$ |
| 7) Project Contingency | | | |
| Contingency (10% CM) (Percentage of total of | professiona | al services, | \$125,950 |
| construction improvements, and miscellaneous | costs.) | | |
| 8) Project or Phase total of professional service | es (4), cons | truction | \$1,385,450 |
| improvements(5), miscellaneous costs(6), a | nd project o | contingency(7) | |
| | | | _ |
| | | | |
| 9) TOTAL PROJECT COST (all phases)= | REQUEST | Γ | \$3,377,550 |

Note: Agency formatted cost estimates may accompany this page.

E. PROPOSED PHASING PRIOR PHASING1

| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Actual Appropriation) |
|-------------|-----------------------|--------------|-------------------------|--|
| | | FY 2006/2007 | | |
| | | FY 2006/2007 | | |
| | | FY 2007/2008 | | |
| | | FY 2008/2009 | | |

(Subtotal) \$

CURRENT PHASE² REQUESTED

| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase of Work | Dollar Amount (Per Detailed Budget) |
|-------------|-----------------------|--------------|---------------|---|
| | | FY 2009/2010 | 1 | \$1,992,100 |

\$ 1,992,100 (Subtotal)

FUTURE PHASING²

| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Per Detailed Budget) |
|-------------|-----------------------|--------------|-------------------------|---|
| | | FY 2010/2011 | 2 | \$1,385,450 |
| | | FY 2011/2012 | | |
| | | FY 2012/2013 | | |
| | | FY 2013/2014 | | |

\$ 1,385,450 (Subtotal)

Project Total Dollar Amount of All Projects Phases Requested \$3,377,550

(Prior, Current and Future Phases)

¹ List <u>all</u> previous phases with actual appropriation by year (include federal funding). Note if different from

requested amount.

² List all current and anticipated future phases with estimated costs as listed in the detailed cost estimate subtotal blank 8.

Page 7

F. PROPOSED PROJECT IMPLEMENTATION SCHEDULE (PLAN):

| PHASE | FROM | 10 | |
|---------------------------------------|---------|--------|--|
| 1. Pre-Design (Insert Dates) | | | |
| 2. Design (Insert Dates) | July 09 | Dec 09 | |
| 3. Construction (Insert Dates) | Jan 10 | May 10 | |
| 4. Project Close-out/Final Completion | May 10 | Dec 10 | |
| | | | |
| | | | |
| G. AGENCY APPROVAL | | | |
| Agency Authorized Signature | | Date | |

Building Name: James L. Voss Vet. Teaching Hospital Number: 0555

Construction Date: 1979 Gross Square Feet: 137,233 Net Square Feet: 125,020

Date of Audit: 03/07/2006 Cycle: 5 Phase: 3 No. of Stories: 2

Classification: M330 Hospital, 1-3 Story SBP Class: 41 Hospital or Infirmary

Replacement Cost: \$23,456,001.59 Cost Per SF: \$170.92

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0800 | 0.02 | 0.0016 | \$37,529.60 |
| Ext Walls | 0.1500 | 0.08 | 0.0120 | \$281,472.02 |
| Floors | 0.2500 | 0.12 | 0.0300 | \$703,680.03 |
| Roof | 0.5000 | 0.04 | 0.0200 | \$469,120.02 |
| Ceiling | 0.2500 | 0.03 | 0.0075 | \$175,920.01 |
| Int Walls | 0.1000 | 0.08 | 0.0080 | \$187,648.01 |
| Windows | 0.1200 | 0.01 | 0.0012 | \$28,147.20 |
| Doors | 0.2500 | 0.05 | 0.0125 | \$293,200.02 |
| Cool Vent | 0.7800 | 0.07 | 0.0546 | \$1,280,697.65 |
| Heat | 0.4800 | 0.02 | 0.0096 | \$225,177.61 |
| Plumbing | 0.4700 | 0.12 | 0.0564 | \$1,322,918.46 |
| Electrical | 0.1800 | 0.07 | 0.0126 | \$295,545.61 |
| Convey | 0.0600 | 0.02 | 0.0012 | \$28,147.20 |
| Safety | 0.1800 | 0.03 | 0.0054 | \$126,662.41 |
| AE/OP | 0.2326 | 0.20 | 0.0465 | \$1,091,173.17 |

Component Deficiency Total: 0.2791

Outstanding Maintenance: \$6,547,038.94

Facilities Condition Index (FCI):

72.09

 $FCI = (1-Component Deficiency Total) \times 100$

Building Name: Horse Barn and Animal Food Barn Number: 0554

Construction Date: 1979 Gross Square Feet: 45,194 Net Square Feet: 42,312

Date of Audit: 02/25/2008 Cycle: 6 Phase: 2 No. of Stories: 1

Classification: M410 Medical Office SBP Class: 41 Hospital or Infirmary

Replacement Cost: \$3,926,495.39 Cost Per SF: \$86.88

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1000 | 0.04 | 0.0040 | \$15,705.98 |
| Ext Walls | 0.3000 | 0.10 | 0.0300 | \$117,794.87 |
| Floors | 0.3000 | 0.11 | 0.0330 | \$129,574.35 |
| Roof | 0.4500 | 0.03 | 0.0135 | \$53,007.69 |
| Ceiling | 0.2000 | 0.02 | 0.0040 | \$15,705.98 |
| Int Walls | 0.1000 | 0.11 | 0.0110 | \$43,191.45 |
| Doors | 0.3000 | 0.08 | 0.0240 | \$94,235.89 |
| Cool Vent | 0.6300 | 0.05 | 0.0315 | \$123,684.61 |
| Heat | 0.5900 | 0.06 | 0.0354 | \$138,997.93 |
| Plumbing | 0.3200 | 0.08 | 0.0256 | \$100,518.28 |
| Electrical | 0.5967 | 0.05 | 0.0298 | \$117,146.99 |
| Safety | | 0.03 | | |
| AE/OP | 0.2418 | 0.20 | 0.0484 | \$189,912.81 |

Component Deficiency Total:

0.2902

Outstanding Maintenance:

\$1,139,476.82

Facilities Condition Index (FCI):

70.98

FCI = (1-Component Deficiency Total) x 100

Building Name: Microbiology Number: 0120

Construction Date: 1968 Gross Square Feet: 85,131 Net Square Feet: 76,830

Date of Audit: 02/12/2007 Cycle: 6 Phase: 1 No. of Stories: 4

Classification: M150 College, Laboratory SBP Class: 11 Science

Replacement Cost: \$15,009,080.55 Cost Per SF: \$176.31

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0500 | 0.07 | 0.0035 | \$52,531.78 |
| Ext Walls | 0.2500 | 0.06 | 0.0150 | \$225,136.20 |
| Floors | 0.2500 | 0.07 | 0.0175 | \$262,658.91 |
| Roof | 0.6000 | 0.06 | 0.0360 | \$540,326.86 |
| Ceiling | 0.3000 | 0.03 | 0.0090 | \$135,081.73 |
| Int Walls | 0.1500 | 0.09 | 0.0135 | \$202,622.60 |
| Windows | 0.2000 | 0.02 | 0.0040 | \$60,036.32 |
| Doors | 0.2600 | 0.02 | 0.0052 | \$78,047.21 |
| Cool Vent | 0.2700 | 0.06 | 0.0176 | \$263,409.36 |
| Heat | 0.2700 | 0.06 | 0.0175 | \$263,409.34 |
| Plumbing | 0.2200 | 0.14 | 0.0308 | \$462,279.68 |
| Electrical | 0.2380 | 0.07 | 0.0167 | \$250,051.29 |
| Convey | 0.3500 | 0.01 | 0.0035 | \$52,531.78 |
| Safety | 0.2500 | 0.02 | 0.0050 | \$75,045.40 |
| AE/OP | 0.1948 | 0.18 | 0.0351 | \$526,170.35 |

Component Deficiency Total: 0.2298

Outstanding Maintenance: \$3,449,338.84

Facilities Condition Index (FCI): 77.02

FCI = (1-Component Deficiency Total) x 100

Building Name: Student Services Number: 0076

Construction Date: 1948 Gross Square Feet: 36,717 Net Square Feet: 31,412

Date of Audit: 11/08/2005 Cycle: 5 Phase: 3 No. of Stories: 2

Classification: M460 Office Building SBP Class: 16 Office

Replacement Cost: \$3,915,625.72 Cost Per SF: \$106.64

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1500 | 0.02 | 0.0030 | \$11,746.88 |
| Ext Walls | 0.2000 | 0.09 | 0.0180 | \$70,481.27 |
| Floors | 0.1200 | 0.16 | 0.0192 | \$75,180.01 |
| Roof | 0.5000 | 0.03 | 0.0150 | \$58,734.38 |
| Ceiling | 0.1200 | 0.05 | 0.0060 | \$23,493.75 |
| Int Walls | 0.2000 | 0.05 | 0.0100 | \$39,156.26 |
| Windows | 0.9000 | 0.02 | 0.0180 | \$70,481.26 |
| Doors | 0.2500 | 0.05 | 0.0125 | \$48,945.32 |
| Cool Vent | 0.1500 | 0.04 | 0.0060 | \$23,493.75 |
| Heat | 0.1900 | 0.13 | 0.0247 | \$96,715.95 |
| Plumbing | 0.3700 | 0.02 | 0.0074 | \$28,975.63 |
| Electrical | 0.5470 | 0.12 | 0.0656 | \$257,021.66 |
| Convey | 0.1800 | 0.03 | 0.0054 | \$21,144.38 |
| Safety | 0.2000 | 0.01 | 0.0020 | \$7,831.25 |
| AE/OP | 0.2128 | 0.18 | 0.0383 | \$150,012.32 |

Component Deficiency Total:

0.2512

Outstanding Maintenance:

\$983,414.08

Facilities Condition Index (FCI):

74.88

FCI = (1-Component Deficiency Total) x 100

Building Name: John E. Painter Center for Lab Animals Number: 0144

Construction Date: 1980 Gross Square Feet: 31,139 Net Square Feet: 27,591

Date of Audit: 01/02/2008 Cycle: 6 Phase: 2 No. of Stories: 1

Classification: M330 Hospital, 1-3 Story SBP Class: 11 Science

Replacement Cost: \$4,257,641.70 **Cost Per SF:** \$136.73

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0500 | 0.02 | 0.0010 | \$4,257.64 |
| Ext Walls | 0.0500 | 0.08 | 0.0040 | \$17,030.57 |
| Floors | 0.0500 | 0.12 | 0.0060 | \$25,545.85 |
| Roof | 0.3300 | 0.04 | 0.0132 | \$56,200.87 |
| Ceiling | 0.4000 | 0.03 | 0.0120 | \$51,091.70 |
| Int Walls | 0.1000 | 0.08 | 0.0080 | \$34,061.13 |
| Windows | 0.2000 | 0.01 | 0.0020 | \$8,515.28 |
| Doors | 0.2500 | 0.05 | 0.0125 | \$53,220.52 |
| Cool Vent | 0.4500 | 0.07 | 0.0315 | \$134,115.71 |
| Heat | 0.6400 | 0.02 | 0.0128 | \$54,497.81 |
| Plumbing | 0.2900 | 0.12 | 0.0348 | \$148,165.92 |
| Electrical | 0.2490 | 0.07 | 0.0174 | \$74,210.69 |
| Safety | 0.2500 | 0.03 | 0.0075 | \$31,932.31 |
| AE/OP | 0.1627 | 0.20 | 0.0325 | \$138,569.21 |

Component Deficiency Total: 0.1953

Outstanding Maintenance: \$831,415.22

Facilities Condition Index (FCI): 80.47

 $FCI = (1-Component Deficiency Total) \times 100$

Building Name: Chemistry Number: 0150

Construction Date: 1971 Gross Square Feet: 168,037 Net Square Feet: 153,007

Date of Audit: 01/07/2008 Cycle: 6 Phase: 2 No. of Stories: 3

Classification: M150 College, Laboratory SBP Class: 11 Science

Replacement Cost: \$31,230,735.08 Cost Per SF: \$185.86

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.2000 | 0.07 | 0.0140 | \$437,230.30 |
| Ext Walls | 0.1000 | 0.06 | 0.0060 | \$187,384.41 |
| Floors | 0.2000 | 0.07 | 0.0140 | \$437,230.30 |
| Roof | 0.4000 | 0.06 | 0.0240 | \$749,537.64 |
| Ceiling | 0.4000 | 0.03 | 0.0120 | \$374,768.82 |
| Int Walls | 0.2000 | 0.09 | 0.0180 | \$562,153.26 |
| Windows | 0.4000 | 0.02 | 0.0080 | \$249,845.88 |
| Doors | 0.3000 | 0.02 | 0.0060 | \$187,384.41 |
| Cool Vent | 0.2300 | 0.06 | 0.0138 | \$430,984.11 |
| Heat | 0.2600 | 0.07 | 0.0182 | \$568,399.36 |
| Plumbing | 0.4000 | 0.14 | 0.0560 | \$1,748,921.20 |
| Electrical | 0.7127 | 0.07 | 0.0499 | \$1,558,070.17 |
| Convey | 0.3500 | 0.01 | 0.0035 | \$109,307.57 |
| Safety | 0.0200 | 0.02 | 0.0004 | \$12,492.29 |
| AE/OP | 0.2438 | 0.18 | 0.0439 | \$1,370,467.82 |

Component Deficiency Total:

0.2877

Outstanding Maintenance:

\$8,984,177.66

Facilities Condition Index (FCI):

71.23

 $FCI = (1-Component Deficiency Total) \times 100$

| 2) Department3) Physical Plant I4) Agency Priority | | | |
|--|------------------------------|---|-----------------|
| Department Physical Plant I Agency Priority | Higher Education D No03-124 | | |
| 3) Physical Plant I4) Agency Priority | D No. 03-124 | | |
| 4) Agency Priority | | | |
| 4) Agency Priority5) Project Title | " 4 | Project M # | |
| 5) Project Title | # 1 | | |
| | Replace Inadequa | e Ventilation Systems – Painter Center – Phase | 1 of 1. |
| B. FACILITY PR | OFILE | | |
| D. 1710121111 | | | |
| 1) Facility Type | Site (Utilities | | |
| | | vements above ground) | |
| | | me (s) John E. Painter Center for Lab Anim | ials |
| | | dg(s) ID#3338 | |
| 2) Facility Location | | D 1 D | 1000 |
| 3) Facility Area/Ag | | | ilt <u>1980</u> |
| , | nal Use/Occupancy | | |
| | ction (Type) II-1 | | |
| | | ility Condition Index (FCI) Number | udit 1/02/2008 |
| Actual FCI = | 80.47 | rgeted FCI = <u>85.00</u> Date of Last A | udit 1/02/2008 |
| (Describe) | | | |
| | | | |
| | | | |
| | | | |
| 7) Facility - Intens | ty of Use, Time(s) | of Operation: (Hours/Day, Days/Month, Months/Y | ear) |
| | | | |
| 8) Facility - Currer | nt Replacement Val | ue \$ _4,257,642 | |
| 9) Master Plan Sta | atus - Check one or | more of the following: | |
| a) Facility | 'useful' life is less | han five (5) years. | |
| b) X Facility | 'useful' life is more | than five (5) years. | |
| c) Master | Plan is obsolete; L | | |
| | | (by OSPB/CDHE) ovations, or program revisions are ongoing or ar | |

| 40) = -1114 | dia Common | | |
|----------------------------------|---|---|------------------------------|
| | Audit Survey: ility Audit Survey concluded and submitted to SBP - | Date | 2008 |
| , | us of the Infrastructure Assessment. | % Completed | |
| | ility Audit Survey Cycle 6/2 | · /o Comploted | |
| 11) List all t | ne controlled maintenance, capital construction, and emerge years or ongoing projects that can be associated with either | this CM building of | or infrastructure |
| Designet No. | Drainet Title | | Completion date or status |
| Project No. | Project Title | | or status |
| | | | |
| | | | |
| | | | |
| C. INTEGE | ATED PROGRAM PLAN DATA | | |
| | a Capital Renewal Building/Infrastructure Request, refer to t required to support the request. | he instructions for | the additional |
| 1) Narrative | Description of CM Problem (Initial problem and solution by | phase): | |
| Painter (system) average | Center is 28 years old, the AHU's and exhaust fans need to be longer works. The high pressure direct inject humidification 72 degrees for animal room space @ 40% RH. The cooling ratory Animal Standards, piping needs to be installed for fut | oe replaced. The hon system needs to system will not ke | o provide and eep up with |
| O) Total Dra | icat Coat Estimata (Fram Coat Brookdown) \$ 1 997 993 | | |
| | ject Cost Estimate (From Cost Breakdown) \$1,887,883 ences (cost effects, program impacts, facility impacts, | | |
| | ot funding and justifying this specific project request: | | |
| Painter Assessr system | Center is a BSL-3 Laboratory and is at the upper limits of menent and Accreditation of Laboratory Animal Care, (AAALAC will not make up the 10 degrees difference caused from the down when Accreditation is not met. |). This is because | the cooling |
| | ry - Include Facility Audit documentation from most recent acture project request. | audit. Include site | maps for any |
| | Include photographs and any other supporting documents. | | |
| | on of how this project will improve the building(s) facility cor | | prove a |
| | nfrastructure system. | | |
| The hea | t component should go from 64% deficient to 5%. The cooling rall Facilities Condition Index should improve from 80.47 to | ng should go from 85. | 45% to 1%. |
| | | | |

| D. | DETAILED COST | ESTIMATE (de | etail by phase, | one page per phase, | include all phases) |
|----|---------------|--------------|-----------------|---------------------|---------------------|
| | | | | | |

| 1) Approved By Dewey Wearne | 2) Phase? _1 |
|---|--------------|
| 3) Method of Estimate Historic | |
| | |
| 4) Professional Services | |
| Site Surveys, Investigations, and Reports | |
| | \$200,000 |

| Site Surveys, Investigations, and Reports | |
|---|-----------|
| Arch/Eng/Basic Services | \$200,000 |
| Code Review/Inspection | \$5,000 |
| Other (Explain) | |
| Total of Professional Services | \$205,000 |

| 5) Construction Improvement | | | | | |
|---|------|------------------|---------------|--|--|
| WORK ITEM (Labor/Material/Equipment) | UNIT | <u>UNIT COST</u> | EXTENDED COST | | |
| Infrastructure | | | | | |
| a) Utility Services | | | | | |
| b) Site Improvements | | | | | |
| Structure/System/Components | | | | | |
| Other(explain) | | | | | |
| AHU, Built-up, Cool/Heat coils, Filters, Mix Box, Constant Volume. | 5 @ | \$137,400 | \$685,000 | | |
| Exhaust Fans – Roof vent. | 5@ | \$60,150 | \$300,750 | | |
| Crane Services – Difficult Access. | LS | \$18,000 | \$18,000 | | |
| Internal piping for future connection to chill water loop with use of existing pumps and redundant chiller. | LS | \$245,000 | \$245,000 | | |
| High-pressure direct injection humidification system. Move in and out, Demo, and installation | Each | \$162,507 | \$162,507 | | |
| Heat reclaim system (not working) | Each | \$100,000 | \$100,000 | | |
| Total of Construction Improvements Costs | | | \$1,511,257 | | |

6) Miscellaneous (explain)

| Total of Miscellaneous Costs | | \$ |
|------------------------------|--|----|

7) Project Contingency

| 7) Project Contingency | The second secon |
|---|--|
| Contingency (10% CM) (Percentage of total of professional services, | \$171,626 |
| construction improvements, and miscellaneous costs.) | |

8) Project or Phase total of professional services (4), construction \$1,887,883 improvements(5), miscellaneous costs(6), and project contingency(7)

| 9) TOTAL PROJECT COST (all phases)= REQUEST | \$1,887,883 |
|---|-------------|
| | |

Note: Agency formatted cost estimates may accompany this page.

E. PROPOSED PHASING PRIOR PHASING1

| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Actual Appropriation) |
|-------------|-----------------------|--------------|-------------------------|--|
| | | FY 2006/2007 | | |
| | | FY 2006/2007 | | |
| | | FY 2007/2008 | | |
| a a | | FY 2008/2009 | | |

(Subtotal)

CURRENT PHASE² REQUESTED

| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase of Work | Dollar Amount (Per Detailed Budget) |
|-------------|-----------------------|--------------|---------------|---|
| | | FY 2009/2010 | 1 | \$1,887,883 |

\$ 1,887,883 (Subtotal)

FUTURE PHASING²

| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Per Detailed Budget) |
|-------------|-----------------------|--------------|-------------------------|---|
| | | FY 2010/2011 | | |
| | | FY 2011/2012 | | |
| | | FY 2012/2013 | | |
| | | FY 2013/2014 | | |

(Subtotal) \$0

Project Total Dollar Amount of All Projects Phases Requested \$ 1,887,883

(Prior, Current and Future Phases)

¹ List <u>all</u> previous phases with actual appropriation by year (include federal funding). Note if different from requested amount.

² List all current and anticipated future phases with estimated costs as listed in the detailed cost estimate subtotal blank 8.

F. PROPOSED PROJECT IMPLEMENTATION SCHEDULE (PLAN):

| PHASE | FROM | ТО |
|---------------------------------------|---------|---------|
| 1. Pre-Design (Insert Dates) | | |
| 2. Design (Insert Dates) | June 09 | Dec 09 |
| 3. Construction (Insert Dates) | Dec 09 | June 10 |
| 4. Project Close-out/Final Completion | June 10 | Dec 10 |
| | | |
| | | |
| G. <u>AGENCY APPROVAL</u> | | |
| Agency Authorized Signature | | Date |

Building Name: John E. Painter Center for Lab Animals Number: 0144

Construction Date: 1980 Gross Square Feet: 31,139 Net Square Feet: 27,591

Date of Audit: 01/02/2008 Cycle: 6 Phase: 2 No. of Stories: 1

Classification: M330 Hospital, 1-3 Story SBP Class: 11 Science

Replacement Cost: \$4,257,641.70 Cost Per SF: \$136.73

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0500 | 0.02 | 0.0010 | \$4,257.64 |
| Ext Walls | 0.0500 | 0.08 | 0.0040 | \$17,030.57 |
| Floors | 0.0500 | 0.12 | 0.0060 | \$25,545.85 |
| Roof | 0.3300 | 0.04 | 0.0132 | \$56,200.87 |
| Ceiling | 0.4000 | 0.03 | 0.0120 | \$51,091.70 |
| Int Walls | 0.1000 | 0.08 | 0.0080 | \$34,061.13 |
| Windows | 0.2000 | 0.01 | 0.0020 | \$8,515.28 |
| Doors | 0.2500 | 0.05 | 0.0125 | \$53,220.52 |
| Cool Vent | 0.4500 | 0.07 | 0.0315 | \$134,115.71 |
| Heat | 0.6400 | 0.02 | 0.0128 | \$54,497.81 |
| Plumbing | 0.2900 | 0.12 | 0.0348 | \$148,165.92 |
| Electrical | 0.2490 | 0.07 | 0.0174 | \$74,210.69 |
| Safety | 0.2500 | 0.03 | 0.0075 | \$31,932.31 |
| AE/OP | 0.1627 | 0.20 | 0.0325 | \$138,569.21 |

Component Deficiency Total:

Outstanding Maintenance: \$831,415.22

0.1953

Facilities Condition Index (FCI): 80.47

 $FCI = (1-Component Deficiency Total) \times 100$

A. AGENCY BASIC DATA:

| | Page 1 of 5 |
|---|--|
| X Controlled Maintenance Request | Capital Renewal Building/Infrastructure Request |
| | Nequest |
| 1) Agency Colorado State University | |
| 2) Department Higher Education | |
| 3) Physical Plant ID No. 4-04 | Project M # |
| 4) Agency Priority # 1 | |
| 5) Project Title Replace Unsafe Overhead Electrica | al Service – Foothills Campus - Phase 1 of 2 |
| B. FACILITY PROFILE | |
| 1) Facility Type X Site (Utilities underground) | Electric |
| | round) |
| | |
| Risk Mgmt. Bldg(s) ID# | |
| 2) Facility Location Foothills Campus | |
| | F Date Built |
| 4) Facility Functional Use/Occupancy Science | |
| 5) Facility Construction (Type) | |
| 6) Facility Physical Condition and Facility Condition Ind | ex (FCI) Number- |
| Actual FCI = Target FCI | Date of Last Audit |
| (Describe) | |
| | |
| | |
| | |
| | |
| 7) Facility - Intensity of Use, Time(s) of Operation: (Ho | urs/Day, Days/Month, Months/Year) 12/25/12 |
| | |
| | |
| 9) Master Plan Status - Check one or more of the follow | |
| a) Facility 'useful' life is less than five (5) years | |
| b) X Facility 'useful' life is more than five (5) year | |
| c) Master Plan is obsolete; Last Date Approve | |
| | (by OSPB/CCHE) |
| | ram revisions are ongoing or anticipated in the w if these facility renovations or program revisions |
| | |
| | |
| | |
| | |
| | |

Page 2 of 5

| | 1 age 2 of 6 |
|--|--------------------------------------|
| 10) Facility Audit Survey: | |
| a) Facility Audit Survey concluded and submitted to SBREP - | Date |
| b) Status of the Infrastructure Assessment. | % Completed |
| c) Facility Audit Survey Cycle Phase 3 | |
| 11) List all the controlled maintenance, capital construction, and emer last five years or ongoing projects that can be associated with eith request. | |
| | Completion date |
| Project No. Project Title M01015 Replace Det. Electrical Feeders | or status Construction |
| M90024 Replace Overhead Lines | 2001 |
| | |
| C. <u>INTEGRATED PROGRAM PLAN DATA</u> | |
| NOTE: For a Capital Renewal Building/Infrastructure Request, refer to information required to support the request. | the instructions for the additional |
| 1) Narrative Description of CM Problem (Initial problem and solution b | y phase): |
| PH1 – Foothills Campus – Rampart to ARBL area: This project i | |
| circular mills) copper underground line from Rampart to the ARBL | |
| | |
| <u>PH2 – Foothills Campus – ARBL to CETT:</u> This project extends mills) copper underground line from the ARBL area to the CETT arkcmil copper, 15kv EPR conductor, manholes, vault switches and lines. | rea. New 2-way duct bank 500 |
| line | nardware will be installed with this |
| 2) Total Project Cost Estimate (From Cost Breakdown) \$ 1,690,304 | 4 |
| 3) Consequences (cost effects, program impacts, facility impacts, etc. | |
| specific project request: | |
| Foothills Campus: Overhead lines may fail, due to age, in weather | related events and we are |
| nearing capacity of the existing system, the current electrical syste | m is also unreliable in regards to |
| the quality of power and its' delivery to complex pieces of research buildings. These research endeavors and the associated continued | equipment in research intensive |
| Campus has lasting positive benefits to the state of Colorado as re | search at CSU is highlighted on |
| both the national and international stage. The need for continuous | reliable power service to |
| accommodate research-intensive programs is paramount to the su | iccess of the programs. More |
| immediate are reoccurring ground fires with collapse of the power 4) Mandatory - Include Facility Audit documentation from most recent | |
| infrastructure project request. | radali. Molade Site Maps for any |
| 5) Optional - Include photographs and any other supporting document | S. |
| | |
| Explanation of how this project will improve the building(s) facility co | ondition index or improve a |
| specific infrastructure system. | , |
| | |
| Foothills Campus – Updated electrical systems to allow for continu | ous high quality power at this |
| research driven campus, which is poised for growth. | cas, mgn quanty pontor at this |
| | |

Page 3 of 5

| D. <u>DETAILED COST ESTIMATE</u> (detail | il by phase, o | ne page per pn | ase, include all phases |
|---|------------------|----------------|-------------------------|
| 1) Approved By Dewey Wearne | | 2) Phase | 1 of 2 |
| 3) Method of Estimate Historic Unit C | Cost | | |
| | | | |
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | \$75,000 | | |
| Code Review/Inspection | \$15,500 | | |
| Other (Explain) | | | |
| Total of Professional Services | \$90,500 | | |
| 5) Construction Improvement | | | |
| WORK ITEM | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) | | | |
| Infrastructure | | | |
| Trenching and Backfill | 2980 | \$10.00 | \$29,800 |
| Underground Duct Bank | 2980 | \$50.00 | \$149,000 |
| Manholes | 10 | \$6,180 | \$61,800 |
| 15kv Cable/Terminations | 3000 | \$60.00 | \$180,000 |
| Transformers | 8 | \$45,000 | \$360,000 |
| Switches | 4 | \$45,000 | \$180,000 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Total of Construction Improvements Costs | | | \$960,600 |
| | | | |
| 6) Miscellaneous (explain) | | | T |
| | | | |
| Total of Miccollege conta | | | • |
| Total of Miscellaneous Costs | | | \$ |
| 7) Project Contingency | | | |
| Contingency (10% CM) (Percentage of total | al of profession | al services | \$105,110 |
| construction improvements, and miscellane | | ai 30i vi003, | ψ100,110 |
| | | | |
| 8) Subtotal of professional services, constru | | | \$1,156,210 |
| miscellaneous costs, and project conting | gency percenta | ige (by phase) | |
| | | | |
| 9) TOTAL PROJECT COST (all phase | s)= REOLIES | Т | \$1,690,304 |
| o) TOTAL TROOLOT COOT (all priase | o) ILQUE | • | Ψ1,000,004 |

Page 4 of 5

| D. <u>DETAILED COST ESTIMATE</u> (detail b | y phase, o | ne page per ph | iase, include all phase |
|--|-------------|----------------|-------------------------|
| 1) Approved By Dewey Wearne | | 2) Phase | 2 of 2 |
| 3) Method of Estimate Historic Unit Cos | st | | |
| | | | |
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | 4.5.000 |
| Arch/Eng/Basic Services | | | \$45,000 |
| Code Review/Inspection | | | |
| Other (Explain) | | | 0.45,000 |
| Total of Professional Services | | | \$45,000 |
| 5) Construction Improvement | | | |
| WORK ITEM | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) | | | |
| Infrastructure | | | |
| Trenching and Backfill | 1600 | \$10.00 | \$16,000 |
| Underground Duct Bank | 1600 | \$50.00 | \$80,000 |
| Manholes | 3 | \$6,180 | \$18,540 |
| 15kv Cable/Terminations | 1600 | \$60.00 | \$96,000 |
| Transformers | 2 | \$45,000 | \$95,000 |
| Switches | 3 | \$45,000 | \$135,000 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Total of Construction Improvements Costs | | \$440,540 | |
| C) Microlleneous (symlein) | | | |
| 6) Miscellaneous (explain) | | | |
| | | | |
| Total of Miscellaneous Costs | | | \$ |
| Total of Micconariosus Secto | | | |
| 7) Project Contingency | | | |
| Contingency (10% CM) (Percentage of total of | profession | al services, | \$48,554 |
| construction improvements, and miscellaneou | s costs.) | | |
| 8) Subtotal of professional services, constructi | ion improve | ments. | \$534,094 |
| miscellaneous costs, and project contingen | cy percenta | ge (by phase) | |
| | | | |
| 0) TOTAL DD0 IFOT 000T (-11 -1) | DEOLIES | T | \$1,690,304 |
| 9) TOTAL PROJECT COST (all phases)= | KEQUES | 1 | ψ1,090,304 |

| | POSED PHASIN | PHASING G ¹ | | | |
|----------------------------|-----------------------|---|---------------------------------|--|----------|
| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Actual Appropriation) | |
| | | | | \$ | (Subtota |
| CHARLES WHEN THE PARTY OF | | SE ² REQUESTED Fiscal Year | Phase of Work | Dollar Amount | 7 |
| Proj. M# | Phys. Plant ID# | riscal Year | Phase of Work | (Per Detailed Budget) | |
| | | FY 2009/2010 | 1 | \$1,156,210 | |
| FUTUF | RE PHASI | NG ² | | \$1,156,210 | (Subtota |
| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Per Detailed Budget) | |
| | | FY 2010/2011 | 2 | \$534,094 | |
| | | | | \$534,094 | (Subtota |
| | | lar Amount of All Pro and Future Phases) | ojects Phases Requested | \$1,690,304 | _ |
| reque ² List al | sted amou | nt. nd anticipated future p | propriation by year (include fe | | |
| F. PRO | POSED | PROJECT IMPLEM | ENTATION SCHEDULE (F | PLAN): | |
| 1. Pre-l | PH Design (Ins | ASE ONE sert Dates) | FROM | | то |
| | gn (Insert [| | July 09 | Dec 09 | |
| | | nsert Dates) | Jan 10 | May 10 | |
| 4. Proje | ect Close-o | ut/Final Completion | May 10 | June 10 | |
| G. AG | ENCY AP | PROVAL | | | |
| Agonov | Authorize | d Signature | | n | ate |

UTILITY AUDIT SUMMARY FY07 ALL CAMPUSES

G:\UTILITY\Audits - Utility\Summary of Audit Values and Unit Costs\[All Campuses - Utility Audit Summary FY07.xls]All Campuses FY07

Revision No. 1 28-Aug-08

| Audit Update: | Jan-07 | Renewal Cost: | | \$ 29,879,592 |
|----------------------------|---------|--|-------|------------------|
| No. of Years in Update: | 3.00 | Average Deteriortation & Inflation Rate: | 10.0% | |
| Original Audit Date: | July-01 | | | |
| Prior Audit Cost Update: | May-04 | | | |
| | | Replacement Value: | | \$ 91,248,411 |
| Average Condition Index ** | 0.67 | Average Construction Inflation Rate: | 3.0% | |

| Utility System | 2001 | Replacement Value | 2001 Condition Index ** | Re | 2001 newal Cost |
|----------------------|----------------|----------------------|-------------------------------|----|--------------------|
| ELECTRIC | \$ | 3,755,700 | 0.85 | \$ | 557,580 |
| DISTRICT HEATING | | | | | |
| Steam | \$ | 5,754,800 | 0.40 | \$ | 3,454,500 |
| Condensate | \$ | 2,353,200 | 0.40 | \$ | 1,406,600 |
| Tunnel | \$ | 26,202,800 | 0.90 | \$ | 2,496,300 |
| Heating Plant System | \$ \$ \$ | 16,115,000 | 0.56 | \$ | 7,102,000 |
| Subtotal | \$ | 50,425,800 | 0.71 | \$ | 14,459,400 |
| DISTRICT COOLING | | | | | |
| Pipes | \$ | 2,393,400 | 0.96 | \$ | 97,000 |
| Plant Equipment | \$ | 3,566,600 | 0.95 | \$ | 178,330 |
| Subtotal | \$ | 5,960,000 | | \$ | 275,330 |
| NATURAL GAS/PROPANE | \$ | 663,700 | 0.35 | \$ | 431,200 |
| WATER | \$ | 5,074,300 | 0.77 | \$ | 1,161,200 |
| SANITARY | \$ | 3,546,500 | 0.72 | \$ | 1,002,600 |
| STORMWATER | \$ | 5,625,000 | 0.75 | \$ | 1,425,000 |
| IRRIGATION | \$ | 1,386,800 | 0.35 | \$ | 907,600 |
| COMPRESSED AIR | \$ | 1,105,100 | 0.43 | \$ | 626,200 |
| Total | \$ | 77,542,900 | 0.73 | \$ | 20,846,110 |

| A. AGENCY BASIC DATA: | |
|---|---|
| x Controlled Maintenance Request | Capital Renewal Building/Infrastructure Request |
| Agency | |
| 2) Department Higher Education | |
| 3) Physical Plant ID No. 08-086 | Project M # |
| 4) Agency Priority # | |
| 5) Project Title Replace Inadequate Ventilation Visual Arts – Phase 1 of 3 | System and Failing Electrical & Mechanical Systems – |
| B. <u>FACILITY PROFILE</u> | |
| 1) Facility Type Site (Utilities underground) | |
| or Site (Improvements abo | ve ground) |
| x or Building Name (s) | Visual Arts |
| Risk Mgmt. Bldg(s) ID# | 3341 |
| 2) Facility Location Main Campus | |
| 3) Facility Area/Age GSF 91,997 | ASF 71132 Date Built 1973 |
| 4) Facility Functional Use/Occupancy Fine Arts | |
| 5) Facility Construction (Type) II-1HR | |
| 6) Facility Physical Condition and Facility Condition | Index (FCI) Number |
| Actual FCI = 76 Targeted FCI = | 84 Date of Last Audit 2/21/2006 |
| (Describe) | |
| | |
| | |
| | |
| | |
| 7) Facility - Intensity of Use, Time(s) of Operation: | (Hours/Day, Days/Month, Months/Year) |
| 8) Facility - Current Replacement Value \$ 9,149 | 9,865 |
| 9) Master Plan Status - Check one or more of the f | following: |
| a) Facility 'useful' life is less than five (5) y | |
| b) x Facility 'useful' life is more than five (5) | |
| c) Master Plan is obsolete; Last Date App | |
| C) [Nactor : land of ordering | (by OSPB/CCHE) |
| d) Major facility changes, renovations, or property next five years, (If yes, please explain to may have an impact on this CM requestions). | program revisions are ongoing or anticipated in the pelow if these facility renovations or program revisions st.) |
| | |
| | |
| | |
| | |

Page __1__ of __6__

| | | Page _ | _2_ 016 |
|----------------------------|---|-------------------------|---------------------------|
| 10) Facility Audit S | Survey: | | |
| | udit Survey concluded and submitted to SBREP - | Date | 2006 |
| b) Status of | the Infrastructure Assessment. | % Completed | 100 |
| | udit Survey Cycle 5/3 | | |
| | ntrolled maintenance, capital construction, and emerg | ency projects comp | leted within the |
| | s or ongoing projects that can be associated with either | er this CM building of | or infrastructure |
| Project No. | Project Title | | Completion date or status |
| | | | |
| | | | |
| C. INTEGRATE | D PROGRAM PLAN DATA | | |
| | oital Renewal Building/Infrastructure Request, refer to red to support the request. | the instructions for | the additional |
| 1) Narrative Desc | cription of CM Problem (Initial problem and solution by | / phase): | |
| Electrical and | Mechanical systems are 34 years old. The cooling ar | nd ventilation system | n is beyond |
| | y. Air handling units, dampers, chillers, exhaust fans, | | and |
| | ust be replaced. Phase 1 Design will determine scope | | thermal |
| | single glaze and most gaskets have failed, should be ong with new casings and roof curbs. | replaced with low E | Hermai |
| | ns have been replaced except 50SQ. of built up when | e most leaks occur. | |
| | | | |
| 2) Total Project C | Cost Estimate (From Cost Breakdown) \$ 3,168,165 | 5 | |
| | s (cost effects, program impacts, facility impacts, etc.) | | justifying this |
| In the last 1-1/2 | ½ years, there have been 4 incidents of students or mo | | |
| paramedics be ventilation. | eing called. The problem is a combination of heat, lac | ck of air circulation a | and |
| | ssrooms are filled with trashcans, buckets, and tarps of adequately sealed skylights. | during rains and me | lting snow |
| 4) Mandatory - II | nclude Facility Audit documentation from most recent | audit. Include site | maps for any |
| | project request. | | |
| 5) Optional - Inclu | ude photographs and any other supporting documents | S. | |
| 6) Explanation of | how this project will improve the building(s) facility co | ondition index or imp | orove a |
| specific infras | tructure system. | | |
| | n component should go from 75% deficient to 05% de Windows should go from 50% to 10%. The Facilities | | |

| D. <u>DETAILED COST ESTIMATE</u> (detail by | y phase, or | ne page per ph | Page3 of _ ase, include all phases |
|--|-------------|----------------|---------------------------------------|
| 1) Approved By Dewey Wearne | | 2) Phase? | 1 |
| 3) Method of Estimate Historic Unit Cos | | | |
| Thotono of the osc | | | |
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | | | \$310,000 |
| Code Review/Inspection | | | \$25,000 |
| Other (Explain) | | | |
| Total of Professional Services | | | \$335,000 |
| 5) Construction Improvement | | | |
| WORK ITEM | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) | | | |
| Phase 1 Design will determine how many | | | |
| exhaust fans, AHUs, VAVs, controls, chillers | | | |
| fan coils, ect. will be replaced. | | | |
| Design will also determine the cost for replacing 929 skylights at approximately | | | |
| \$60/sf. | | | |
| Roof - Replace 50 SQ. of built up roof that | SQ. | \$1,295 | \$64,750 |
| was installed in 1973 with EPDM. | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Total of Construction Improvements Costs | | | \$64,750 |
| | | | |
| 6) Miscellaneous (explain) | | | |
| | | | |
| T. I. CAN: Harris O. I. | | | ФО |
| Total of Miscellaneous Costs | | | \$0 |
| 7) Project Contingency | | | |
| Contingency (10% CM) (Percentage of total of | professiona | I services, | \$39,975 |
| construction improvements, and miscellaneous | costs.) | | |
| | | | |
| 8) Subtotal of professional services, construction | | | \$439,725 |
| miscellaneous costs, and project contingenc | y percentag | ge (by priase) | |
| | | | |
| 9) TOTAL PROJECT COST (all phases)= | REQUEST | | \$3,168,165 |
| | | | |

SBREP CM-03 - FY2009/2010

| D DETAILED COST ESTIMATE (dotail b | v phase o | no nago nor nh | Page4 of _6 |
|---|--------------|----------------|---------------------------|
| D. <u>DETAILED COST ESTIMATE</u> (detail b | y priase, o | ne page per pn | ase, include all priases) |
| 1) Approved By Dewey Wearne | | 2) Phase? | 2 |
| 3) Method of Estimate Historic Unit Cos | st | | |
| | | | |
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | | | |
| Code Review/Inspection | | | |
| Other (Explain) | | | |
| Total of Professional Services | | | \$ |
| 5) Construction Improvement | | | |
| WORK ITEM | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) | | | |
| Quantities as currently surveyed: to be | | | |
| verified during design. | | | |
| AHU's and multi zone dampers. | EA | \$60,000 | \$240,000 |
| Exhaust fans. | EA | \$6,125 | \$147,000 |
| VAVs, Controls, Power, Crane. | LS | \$232,000 | \$232,000 |
| Chillers. | LS | \$373,000 | \$373,000 |
| Fan Coil Units. | LS | \$231,000 | \$231,000 |
| Tall Golf Gillio. | 20 | 4201,000 | 7201,000 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Total of Construction Improvements Costs | | | \$1,223,000 |
| Total of Construction improvements Costs | | | Ψ1,220,000 |
| 6) Miscellaneous (explain) | | | |
| e) mice ilane de (explain) | | | |
| | | | |
| Total of Miscellaneous Costs | | | \$ |
| | | | |
| 7) Project Contingency | | | |
| Contingency (10% CM) (Percentage of total of | f profession | al services, | \$122,300 |
| construction improvements, and miscellaneou | is costs.) | | |
| | | | |
| 8) Subtotal of professional services, construct | | | \$1,345,300 |
| miscellaneous costs, and project contingen | icy percenta | ige (by phase) | |
| | | | |
| | DEOLIES | = | 00.400.405 |
| 9) TOTAL PROJECT COST (all phases)= | REQUES | L | \$3,168,165 |
| | | | |

| D. <u>DETAILED COST ESTIMATE</u> (detail by | y phase, or | ne page per ph | Page5 of ase, include all phases |
|--|---------------------|----------------|----------------------------------|
| 1) Approved By Dewey Wearne | | 2) Phase? | 3 |
| 3) Method of Estimate Historic Unit Cos | | | |
| Thistoric of the objection of the object | | | |
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | | | |
| Code Review/Inspection | | | |
| Other (Explain) | | | |
| Total of Professional Services | | | \$ |
| 5) Construction Improvement | | | |
| WORK ITEM | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) | | | |
| Skylights – 929 - Low E thermal, | 929 | \$600 | \$557,400 |
| Repair frames and louvers. | LS | \$500,000 | \$500,000 |
| Provide and install curb and vertical flashing. | LS | \$200,000 | \$200,000 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Total of Construction Improvements Costs | | | \$1,257,400 |
| 6) Miscellaneous (explain) | | | |
| o) Miscellaricodo (explairi) | | | |
| | | | 0 |
| Total of Miscellaneous Costs | | | \$ |
| 7) Project Contingency | | | |
| Contingency (10% CM) (Percentage of total of | professiona | al services, | \$125,740 |
| construction improvements, and miscellaneous | s costs.) | | |
| 8) Subtotal of professional services, construction | on improver | ments. | \$1,383,140 |
| miscellaneous costs, and project contingend | cy percentag | ge (by phase) | **,*** |
| | | | |
| 9) TOTAL PROJECT COST (all phases)= | REQUES ⁻ | Г | \$3,168,165 |
| | | | |

CONTROLLED MAINTENANCE PROJECT REQUEST FY 2009/2010

| STATI | BUILDIN | NGS AND REAL ES | STATE PROGRAMS | | |
|---------------------|--|---------------------------|----------------------------------|--------------------------|--------------------------------------|
| F PR | OPOSED | PHASING | | Page | 6 of6_ |
| | R PHASIN | | | | |
| Proj. | Phys. | Fiscal Year | Phase or Phases of Work | Dollar Amount | |
| M# | Plant | | | (Actual | |
| | ID# | | | Appropriation) | |
| | | | | \$ | (Subtotal) |
| | | | | | |
| | THE RESERVE OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAME | SE ² REQUESTED | | _ | _ |
| Proj. | Phys. | Fiscal Year | Phase of Work | Dollar Amount | |
| M# | Plant ID# | | | (Per Detailed Budget) | |
| | 10# | FY 2009/2010 | 1 | \$439,725 | |
| | | F 1 2009/2010 | | ψ439,720 | _ |
| | | | | \$ 439,725 | (Subtotal) |
| FUTU | RE PHASI | NG ² | | Ψ 100,120 | (*********************************** |
| Proj. | Phys. | Fiscal Year | Phase or Phases of Work | Dollar Amount | |
| M# | Plant | | | (Per Detailed | |
| | ID# | | | Budget) | - |
| | | FY 20010/2011 | 2 | \$1,345,300 | - |
| | | FY 2011/2012 | 3 | \$1,383,140 | |
| | | FY 2012/2013 | | | |
| | | FY 2013/2014 | | | |
| | | | | \$ 2,728,440 | (Subtotal) |
| | | | rojects Phases Requested | \$ 3,168,165 | |
| (Pri | or, Current | and Future Phases) | | | |
| 1 List a | Il previous i | nhases with actual ar | opropriation by year (include fe | deral funding) Note it | different from |
| reque | ested amou | nt. | | | |
| ² List a | Il current ar | nd anticipated future | phases with estimated costs a | s listed in the detailed | cost estimate |
| subto | otal blank 8. | | | | |
| F PR | OPOSED | PROJECT IMPLEM | MENTATION SCHEDULE (F | PLAN): | |
| | 0.0022 | THOUSEN THE SELECTION | MENTION CONEDCE (| | |
| | | PHASE | FROM | | ТО |
| 1. Pre- | Design (Ins | sert Dates) | July 09 | Dec 09 | |
| 2. Des | ign (Insert I | Dates) | Dec 09 | May 10 | |
| 3. Con | struction (Ir | nsert Dates) | May 10 | Dec 14 | |
| 4. Proj | ect Close-o | out/Final Completion | Dec 14 | Jan 15 | |
| | | | | | |
| G. AG | ENCY AP | PROVAL | | | |
| | | | | | |
| Agenc | y Authorize | d Signature | | D | ate |

Building Name: Visual Arts Number: 0151

Construction Date: 1973 Gross Square Feet: 91,997 Net Square Feet: 86,135

Date of Audit: 02/21/2006 Cycle: 5 Phase: 3 No. of Stories: 1

Classification: M120 Classroom, 2-3 Story SBP Class: 13 Fine Arts

Replacement Cost: \$9,149,865.00 Cost Per SF: \$99.46

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| | | | | |
| Foundation | 0.1500 | 0.02 | 0.0030 | \$27,449.59 |
| Ext Walls | 0.2200 | 0.04 | 0.0088 | \$80,518.81 |
| Floors | 0.2000 | 0.12 | 0.0240 | \$219,596.76 |
| Roof | 0.0800 | 0.05 | 0.0040 | \$36,599.46 |
| Ceiling | 0.4000 | 0.04 | 0.0160 | \$146,397.84 |
| Int Walls | 0.3500 | 0.06 | 0.0210 | \$192,147.16 |
| Windows | 0.5000 | 0.03 | 0.0150 | \$137,247.97 |
| Doors | 0.5000 | 0.04 | 0.0200 | \$182,997.30 |
| Cool Vent | 0.7500 | 0.05 | 0.0375 | \$343,119.94 |
| Heat | 0.1200 | 0.12 | 0.0144 | \$131,758.05 |
| Plumbing | 0.3000 | 0.07 | 0.0210 | \$192,147.17 |
| Electrical | 0.0760 | 0.11 | 0.0084 | \$76,492.87 |
| Safety | 0.4000 | 0.01 | 0.0040 | \$36,599.46 |
| AE/OP | 0.1971 | 0.18 | 0.0355 | \$324,553.05 |

Component Deficiency Total:

0.2325

Outstanding Maintenance:

\$2,127,625.47

Facilities Condition Index (FCI):

76.75

FCI = (1-Component Deficiency Total) x 100



ENGINEERING RESEARCH CENTER

| A. AGENCY BASIC DATA: |
|--|
| X Controlled Maintenance Request Capital Renewal Building/Infrastructure Request |
| 1) Agency Colorado State University |
| 2) Department Higher Education |
| 3) Physical Plant ID No. 8-03 Project M # |
| 4) Agency Priority #1 |
| 5) Project Title Replace Unsafe Electrical Systems and Inadequate Mechanical Systems - Engineering Research Center - Phase 1 of 2 |
| B. FACILITY PROFILE |
| 1) Facility Type Site (Utilities underground) |
| or Site (Improvements above ground) |
| x or Building Name (s) Engineering Research Center |
| Risk Mgmt. Bldg(s) ID# 3557 |
| 2) Facility Location Fort Collins Foothills Campus |
| 3) Facility Area/Age GSF 149,915 ASF 12,398 Date Built 1962 |
| 4) Facility Functional Use/Occupancy Engineering |
| 5) Facility Construction (Type) II-1HR |
| 6) Facility Physical Condition and Facility Condition Index (FCI) Number Remodeling – A (CCHE2) |
| Actual FCI = 67.98 Targeted FCI = 85.00 Date of Last Audit 2005 |
| _(Describe) |
| The Engineering Building is due for another facility condition audit in 2008. We estimate the actual FCI is now about 66 due to the time that has passed since the last audit and the normal deterioration that has occurred to the building since then. |
| 7) Facility - Intensity of Use, Time(s) of Operation: (Hours/Day, Days/Month, Months/Year) |
| The building is used for ongoing research and is available for research endeavors all the time. |
| 8) Facility - Current Replacement Value \$22,840,400 |
| 9) Master Plan Status - Check one or more of the following: |
| a) Facility 'useful' life is less than five (5) years. |
| b) X Facility 'useful' life is more than five (5) years. |
| c) Master Plan is obsolete; Last Date Approved |
| (by OSPB/CCHE) |
| d) Major facility changes, renovations, or program revisions are ongoing or anticipated in the next five years, (If yes, please explain below if these facility renovations or program revisions may have an impact on this CM request.) |

| | | Page2 of4 |
|---|--|--|
| 10) Facility Audit S | Survey: | |
| | udit Survey concluded and submitted to SBREP - | Date 2005 |
| b) Status of | the Infrastructure Assessment. In Progress | % Completed 100 |
| | udit Survey Cycle 5/2 | |
| | ntrolled maintenance, capital construction, and emerge or ongoing projects that can be associated with eithe | r this CM building or infrastructure |
| Project No. | Project Title | Completion date or status |
| | NONE | |
| C. INTEGRATEI | D PROGRAM PLAN DATA | |
| | ital Renewal Building/Infrastructure Request, refer to educate to support the request. | the instructions for the additional |
| The Engineering windows are significant system trips out on low pneumatic and so there are tiredeteriorated are | ription of CM Problem (Initial problem and solution by the Research Building (RM #3557) is 43 years old and single glazed and allow water and air to infiltrate. Energism is at life expectancy and undersized for current used voltage and offices only have 2 outlets each. The term of the replacement parts are difficult to get. The heating and mes when areas are being heated and cooled at the send unable to operate at full capacity. Phase 1 is designed and electrical systems, replaced. | all systems are original. The gy loss is very high. The e. HVAC equipment frequently imperature controls are d cooling systems are separate, ame time. The chiller is in work and chiller replacement. |
| 2) Total Project Co | ost Estimate (From Cost Breakdown) \$ 3,102,930 | |
| 3) Consequences specific project | (cost effects, program impacts, facility impacts, etc.) t request: | of <u>not</u> funding and justifying this |
| being damage | eing impacted by insufficient and undependable electr d by low voltage shutdowns. Energy usage is very hig ndows and due to the heating and cooling systems runs. | h due to heat transmission |
| | nclude Facility Audit documentation from most recent | audit. Include site maps for any |
| | project request. Ide photographs and any other supporting documents | |
| 6) Explanation of | how this project will improve the building(s) facility contracture system. | |
| The window co | omponent should go from 70% deficient to 1% deficient to 1% deficient from 67% to 15%. Electrical from 95% to 10%. The from 67.98 to 85.03. | |

Page 3 of 4 D. DETAILED COST ESTIMATE (detail by phase, one page per phase, include all phases) 1) Approved By Dewey Wearne 2) Phase 1 thru 2 3) Method of Estimate Historic Unit Cost 4) Professional Services Site Surveys, Investigations, and Reports Arch/Eng/Basic Services \$256.316 \$3,318 Code Review/Inspection Other (Explain) Total of Professional Services \$259,634 5) Construction Improvement **UNIT COST EXTENDED COST** WORK ITEM UNIT (Labor/Material/Equipment) Structure/System/Component SF \$39.75 \$492,820 Replace windows SF \$4.38 \$657,000 Replace Lighting Install branch circuits SF \$2.04 \$314,054 Replace distribution equipment LS \$421,648 \$421,648 LS \$70,140 \$70,140 Replace HVAC wiring SF \$.34 \$51,490 Electrical demolition LS \$334,759 Replace chiller \$334,759 EA \$2,193 \$219.300 Replace unit ventilators & temp. controls Total of Construction Improvements Costs \$2,561,211 6) Miscellaneous (explain) \$0 Total of Miscellaneous Costs 7) Project Contingency Contingency (10% CM) (Percentage of total of professional services, \$282,085 construction improvements, and miscellaneous costs.) 8) Subtotal of professional services, construction improvements, \$3,102,930 miscellaneous costs, and project contingency percentage (by phase) Total Phase One - Two = \$3,102,930 divided equally into two phases at \$1,551,465 each.

9) TOTAL PROJECT COST (all phases)= REQUEST \$3,102,930

| | | GS AND REAL ES | | Dane | 1 -5 1 |
|---|---|--|---|--|------------------|
| F PRO | POSED F | PHASING | | Page _ | _4_ of4 |
| | PHASING | | | | |
| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Actual Appropriation) | |
| | 1.00.11 | | | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,, | |
| | | | | \$ 0 | _ (Subtotal) |
| | | 2=2==================================== | | | |
| THE RESERVE OF THE PERSON NAMED IN COLUMN TWO | | SE ² REQUESTED Fiscal Year | Phase of Work | Dollar Amount | 7 |
| Proj. M# | Phys. Plant ID# | Fiscal Year | Priase of Work | (Per Detailed Budget) | |
| | 8-03 | FY 2009-2010 | 1 | \$1,551,465 | |
| | | | | | |
| | T DILAGU | 102 | | \$ 1,551,465 | _ (Subtotal |
| Proj. | Phys. | Fiscal Year | Phase or Phases of Work | Dollar Amount | 7 |
| M# | Plant | riscal real | Filase of Filases of Work | (Per Detailed | |
| | ID# | | | Budget) | |
| | 8-03 | FY 2010/2011 | 2 | \$1,551,465 | |
| | 8-03 | | | | |
| | | | | \$ 1,551,465 | |
| | | | | Ψ 1,00 1, 100 | _ (Subtotal |
| | | | ojects Phases Requested | \$ 3,102,930 | (Subtotal |
| | | ar Amount of All Pro and Future Phases) | ojects Phases Requested | | _ (Subtotal _ |
| (Prio | r, Current a | and Future Phases) hases with actual ap | propriation by year (include fee | \$ 3,102,930 | |
| (Prio | previous p | and Future Phases) hases with actual applet. | propriation by year (include fee | \$ 3,102,930 deral funding). Note if | different fro |
| (Prio ¹ List <u>all</u> reques ² List all | previous p | and Future Phases) hases with actual applet. | | \$ 3,102,930 deral funding). Note if | different fro |
| (Prio ¹ List <u>all</u> reques ² List all subtot | previous p sted amour current an al blank 8. | and Future Phases) hases with actual aport. d anticipated future p | propriation by year (include fee | \$ 3,102,930 deral funding). Note if s listed in the detailed of | different fro |
| (Prio ¹ List <u>all</u> reques ² List all subtot | previous p sted amour current an al blank 8. | and Future Phases) hases with actual aport. d anticipated future p | propriation by year (include fee | \$ 3,102,930 deral funding). Note if s listed in the detailed of | different fro |
| (Prio 1 List <u>all</u> reques 2 List all subtot F. <u>PRC</u> | previous p sted amour current an al blank 8. | and Future Phases) hases with actual aport. d anticipated future p | propriation by year (include fee | \$ 3,102,930 deral funding). Note if s listed in the detailed of | different fro |
| (Prio 1 List <u>all</u> reques 2 List all subtot F. <u>PRC</u> | previous p sted amour current an al blank 8. | and Future Phases) hases with actual apont. d anticipated future p | propriation by year (include feathbases with estimated costs as ENTATION SCHEDULE (F | \$ 3,102,930 deral funding). Note if s listed in the detailed of | different fro |
| 1 List <u>all</u> reques List all subtot F. <u>PRC</u> PHASE 1. Pre-E | previous posted amound current and all blank 8. POSED F | and Future Phases) hases with actual appart. d anticipated future p PROJECT IMPLEM ert Dates) | propriation by year (include fed hases with estimated costs as ENTATION SCHEDULE (F | \$ 3,102,930 deral funding). Note if s listed in the detailed of PLAN): | different fro |
| (Prio 1 List <u>all</u> reques 2 List all subtot F. <u>PRC</u> PHASE 1. Pre-D 2. Design | previous posted amount current and all blank 8. DPOSED For a serious procession (Insert Design | and Future Phases) hases with actual appart. d anticipated future p PROJECT IMPLEM ert Dates) | propriation by year (include feat hases with estimated costs as ENTATION SCHEDULE (F FROM July 09 | \$ 3,102,930 deral funding). Note if a listed in the detailed of PLAN): | different fro |

Date

Agency Authorized Signature

Building Name: Daryl B. Simons Building at the ERC Number: 1101

Construction Date: 1962 Gross Square Feet: 149,915 Net Square Feet: 134,495

Date of Audit: 02/04/2008 Cycle: 6 Phase: 2 No. of Stories: 3

Classification: M150 College, Laboratory SBP Class: 12 Engineering

Replacement Cost: \$23,221,923.45 Cost Per SF: \$154.90

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1000 | 0.07 | 0.0070 | \$162,553.47 |
| Ext Walls | 0.1500 | 0.06 | 0.0090 | \$208,997.31 |
| Floors | 0.3000 | 0.07 | 0.0210 | \$487,660.41 |
| Roof | 0.3500 | 0.06 | 0.0210 | \$487,660.41 |
| Ceiling | 0.5000 | 0.03 | 0.0150 | \$348,328.84 |
| Int Walls | 0.2000 | 0.09 | 0.0180 | \$417,994.64 |
| Windows | 0.3500 | 0.02 | 0.0070 | \$162,553.46 |
| Doors | 0.2500 | 0.02 | 0.0050 | \$116,109.61 |
| Cool Vent | 0.2700 | 0.06 | 0.0162 | \$376,195.12 |
| Heat | 0.2600 | 0.07 | 0.0182 | \$422,638.99 |
| Plumbing | 0.6800 | 0.14 | 0.0952 | \$2,210,727.15 |
| Electrical | 0.9600 | 0.07 | 0.0672 | \$1,560,513.23 |
| Convey | 0.3000 | 0.01 | 0.0030 | \$69,665.77 |
| Safety | 0.0300 | 0.02 | 0.0006 | \$13,933.15 |
| AE/OP | 0.3034 | 0.18 | 0.0546 | \$1,268,195.74 |

Component Deficiency Total:

0.3580

Outstanding Maintenance:

\$8,313,727.37

Facilities Condition Index (FCI):

64.20

FCI = (1-Component Deficiency Total) x 100

Page 1 of 6

A. AGENCY BASIC DATA:

| X Contro | olled Maintenance | Request | Capital Renewal Building/Info | rastructure | | | |
|-------------------------|--|--------------------|--|---------------------------|--|--|--|
| 1) Agency | Colorado State Uni | versity | | | | | |
| 2) Department | Higher Education | | | | | | |
| 3) Physical Plant | ID No. 1-05 | | Project M# | | | | |
| 4) Agency Priority | 4) Agency Priority #1 | | | | | | |
| 5) Project Title | | | | | | | |
| B. FACILITY PE | ROFILE | | | | | | |
| 1) Facility Type | Site (Utilities u | underground) | | | | | |
| | | vements above | ground) | | | | |
| | X or Building Na | ime (s) Se | ee Below | | | | |
| | Risk Mgmt. Bl | dg(s) ID# | | | | | |
| 2) Facility Location | on | | | | | | |
| 3) Facility Area/A | ge GSF | A | SF Date Built | | | | |
| 4) Facility Function | onal Use/Occupancy | | | | | | |
| 5) Facility Constru | | | | | | | |
| | al Condition and Fac | ility Condition Ir | ndex (FCI) Number - Typical audits, ot | ners available | | | |
| on request. | To | racted ECL = | Data of Last Audit | 2005 2007 | | | |
| Actual FCI = (Describe) | 1ai | geled FCI = _ | Date of Last Audit | 2005 - 2007 | | | |
| | sity of Lise Time(s) | of Operation: (H | Hours/Day, Days/Month, Months/Year) | | | | |
| | ent Replacement Valu | | Spruce Hall | \$1,691,706 | | | |
| Weed Potato | | \$1,878,812 | Visual Arts | \$9,149,865 | | | |
| Industrial Science | es Lab | \$2,159,017 | Moby | \$28,865,532 | | | |
| Perc | | | Engineering | \$88,463,627 | | | |
| Military Science | | \$1,473,136 | Industrial Sciences | \$2,528,748 | | | |
| Shepardson | | \$6,601,280 | Routt Hall | \$648,378 | | | |
| NRRL | | \$487,509 | Insectary | \$906,624 | | | |
| AERC | | \$298,504 | Vocational Education | \$1,231,797 | | | |
| Central Receiving |) | \$1,456,689 | Facilities Service North | \$3,366,306 | | | |
| Foothills Animal H | Holdings | | | | | | |
| 9) Master Plan St | tatus - Check one or | more of the foll | owing: | | | | |
| a) Facilit | y 'useful' life is less t | han five (5) yea | nrs. | | | | |
| b) X Facilit | y 'useful' life is more | than five (5) ye | ears. | | | | |
| c) Maste | er Plan is obsolete; La | ast Date Approv | | | | | |
| | | | (by OSPB/CCHE) | | | | |
| next fi | facility changes, renewed years, (If yes, pleasure an impact on this | ase explain belo | ogram revisions are ongoing or anticipa ow if these facility renovations or progr | ated in the ram revisions | | | |

Page 2 of 6

10) Facility Audit Survey:

Facility Audit Survey concluded and submitted to SBREP -2005 - 2007 Date

% Completed Status of the Infrastructure Assessment. 60 b)

5/2 - 6/1Facility Audit Survey Cycle C)

11) List all the controlled maintenance, capital construction, and emergency projects completed within the last five years or ongoing projects that can be associated with either this CM building or infrastructure

Completion date

Project No.

Project Title NONE

or status

C. INTEGRATED PROGRAM PLAN DATA

NOTE: For a Capital Renewal Building/Infrastructure Request, refer to the instructions for the additional information required to support the request.

1) Narrative Description of CM Problem (Initial problem and solution by phase):

Existing Johnson 8540 digital controls have become out dated, are in continuous need of repair and no longer function as originally designed. Control service calls for these systems can only be executed by Johnson Controls personnel and at a premium cost to the University and the State. The appropriate solution is to replace the existing 8540 Johnson controls with the new Metasys systems resulting in enhanced remote control capabilities, greater energy savings in all listed facilities and the ability to have University personnel service the systems in-house which will help reduce maintenance costs in the long term. The Metasys Digital Control Systems will allow for greater energy savings and energy management where installed with increased climate control, building comfort, remote setback and monitoring. The first phase includes replacement in the listed buildings and control platform upgrades. The second and third phases include interface conversions for central control and monitoring.

- 2) Total Project Cost Estimate (From Cost Breakdown) \$ \$1,290,418
- 3) Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request:

Repair dollars will continue to be spent at a premium trying to keep outdated digital systems operational. Parts are difficult to obtain and building climate control is often sacrificed even with comprehensive system repair. Energy could be better utilized as described above with the new Metasys Digital Control Systems that also allow internal personnel to troubleshoot, repair and adjust the systems.

- 4) Mandatory Include Facility Audit documentation from most recent audit. Include site maps for any infrastructure project request.
- 5) Optional Include photographs and any other supporting documents.
- 6) Explanation of how this project will improve the building(s) facility condition index or improve a specific infrastructure system.

This project will convert the existing control system in the above-mentioned buildings allowing for ease of future maintenance, greater energy efficiency, energy management, remote sensing, setback and control. The digital control system also enables fire alarm system tie-in and remote monitoring which improves life safety aspects within the existing buildings.

D. <u>DETAILED COST ESTIMATE</u> (detail by phase, one page per phase, include all phases)

| 1) Approved By | Dewey Wearne | 2) Phase | 1 of 3 | |
|----------------------|-----------------------|----------|--------|--|
| 3) Method of Estimat | te Historic Unit Cost | | | |

4) Professional Services

| Site Surveys, Investigations, and Reports | |
|---|-----------|
| Arch/Eng/Basic Services | \$120,000 |
| Code Review/Inspection | \$10,0000 |
| Other (Explain) | |
| Total of Professional Services | \$130,000 |

• Conversion does not require engineering specs. or drawings.

5) Construction Improvement - Replace JCI 8540 components

| 5) Construction Improvement – Replace JCI 8540 components | | | | | |
|---|-----------|--|--|--|--|
| UNIT | UNIT COST | EXTENDED COST | | | |
| | | | | | |
| 1 | \$28,869 | \$28,869 | | | |
| 1 | \$24,500 | \$24,500 | | | |
| 1 | \$72,738 | \$72,738 | | | |
| 1 | \$173,840 | \$173,840 | | | |
| 1 | \$11,660 | \$11,660 | | | |
| 1 | \$15,000 | \$10,600 | | | |
| 1 | \$15,900 | \$15,900 | | | |
| 1 | \$75,000 | \$75,000 | | | |
| Total of Construction Improvements Costs | | | | | |
| | | UNIT UNIT COST 1 \$28,869 1 \$24,500 1 \$72,738 1 \$173,840 1 \$11,660 1 \$15,000 1 \$15,900 | | | |

6) Miscellaneous (explain)

Total of Miscellaneous Costs \$

7) Project Contingency

| T) TTO COST COSTRUING COST | |
|---|----------|
| Contingency (10% CM) (Percentage of total of professional services, | \$54,311 |
| construction improvements, and miscellaneous costs.) | |

8) Subtotal of professional services, construction improvements, miscellaneous costs, and project contingency percentage (by phase) \$597,418

| 9) TOTAL PROJECT COST (all phases)= REQUEST | \$1,290,418 |
|---|-------------|

| Approved By | st | 2) Phase | Page 4 o |
|---|--------------|--------------|---------------|
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | | | |
| Code Review/Inspection | | | |
| Other (Explain) | | | |
| Total of Professional Services | | | |
| Conversion does not require engineer | ing specs. c | or drawings. | |
| 5) Construction Improvement – Replace JCI 8 | 540 compor | nents | |
| WORK ITEM (Labor/Material/Equipment) | UNIT | UNIT COST | EXTENDED COST |
| NCM retrofit – Replace remaining Network Communication Module with extended architecture platform NAE – Network Automation Engine components and modify graphics. | 21 | \$15,000 | \$315,000 |
| Total of Construction Improvements Costs | | | \$315,000 |
| 6) Miscellaneous (explain) Total of Miscellaneous Costs | | | |
| 7) Project Contingency | | | |
| Contingency (10% CM) (Percentage of total of construction improvements, and miscellaneous | | al services, | \$31,500 |
| Subtotal of professional services, construction improvements, miscellaneous costs, and project contingency percentage (by phase) | | | \$346,500 |
| | | | |
| 9) TOTAL PROJECT COST (all phases)= | REQUES | Т | \$1,290,418 |
| | | | |

Page 5 of 6

| 1) Approved By Dewey Wearne | | 2) Phase | 3 of 3 | | | |
|--|---|-------------|---------------|--|--|--|
| 3) Method of Estimate | | | | | | |
| 4) Professional Services | | | | | | |
| Site Surveys, Investigations, and Reports | | | | | | |
| Arch/Eng/Basic Services | | | | | | |
| Code Review/Inspection | | | | | | |
| Other (Explain) | | | | | | |
| Total of Professional Services | | | | | | |
| Conversion does not require engineering | ng specs. or | r drawings. | | | | |
| | | | | | | |
| 5) Construction Improvement – Replace JCI 85 | | | EVTENDED COCT | | | |
| WORK ITEM (Labor/Material/Equipment) | UNIT | UNIT COST | EXTENDED COST | | | |
| NCM retrofit – Replace remaining Network | 21 | \$15,000 | \$315,000 | | | |
| Connectivity Monitors with extended | 21 | \$10,000 | Ψ010,000 | | | |
| architecture platform NAE - Network | | | | | | |
| Attached Encryption components and modify | | | | | | |
| graphics. | | | | | | |
| Total of Construction Improvements Costs | | | \$315,000 | | | |
| 6) Miscellaneous (explain) | | | | | | |
| Total of Miscellaneous Costs | | | | | | |
| Total of Missellational Octob | | | | | | |
| 7) Project Contingency | | | | | | |
| Contingency (10% CM) (Percentage of total of | \$31,500 | | | | | |
| construction improvements, and miscellaneous | | | | | | |
| | | | | | | |
| 8) Subtotal of professional services, construction | on improven | nents, | \$346,500 | | | |
| miscellaneous costs, and project contingend | | | | | | |
| | | | | | | |
| 9) TOTAL PROJECT COST (all phases)= | 9) TOTAL PROJECT COST (all phases)= REQUEST | | | | | |

| | POSED | PHASING | | | Page 6 of 6 |
|--|--|---|--|--|-------------|
| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Actual Appropriation) | |
| | | | | | (Subtotal) |
| CURRE | ENT PHA | SE ² REQUESTED | | | |
| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase of Work | Dollar Amount (Per Detailed Budget) | |
| | | FY 2009/2010 | ONE | \$597,418 | |
| FUTUE | RE PHASI | NG ² | | \$597,418 | (Subtotal) |
| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Per Detailed Budget) | |
| | | FY 2010/2011 | TWO | \$346,500 | |
| | | FY 2011/2012 | THREE | \$346,500 | |
| | | | | \$ 693,000 | (Subtotal) |
| | | lar Amount of All Pro and Future Phases) | ojects Phases Requested | \$1,290,418 | |
| ¹ List <u>all</u> reque ² List all subtot | previous pated amoust current artal blank 8. | phases with actual ap nt. nd anticipated future p | propriation by year (include fe phases with estimated costs as IENTATION SCHEDULE (F | s listed in the detailed | |
| | | PHASE | FROM | | то |
| | Design (Ins gn (Insert [| | July 09 | Sept 09 | |
| | | nsert Dates) | Oct 09 | Jan 10 | |
| | | ut/Final Completion | Jan 10 | Feb 11 | |
| G. <u>AGI</u> | ENCY AP | PROVAL | | | |
| Agency | Authorize | d Signature | | | Date |

Building Name: Insectary

Number: 0105

Construction Date: 1967

Gross Square Feet: 4,313

Net Square Feet: 3,955

Date of Audit: 01/10/2006 Cycle: 5 Phase: 3 No. of Stories: 1

Classification: M150 College, Laboratory

SBP Class: 11 Science

Replacement Cost:

\$525,656.79

Cost Per SF: \$121.88

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.2500 | 0.07 | 0.0175 | \$9,198.99 |
| Ext Walls | 0.2000 | 0.06 | 0.0120 | \$6,307.88 |
| Floors | 0.2000 | 0.07 | 0.0140 | \$7,359.20 |
| Roof | 0.0200 | 0.06 | 0.0012 | \$630.79 |
| Ceiling | 0.3500 | 0.03 | 0.0105 | \$5,519.40 |
| Int Walls | 0.2200 | 0.09 | 0.0198 | \$10,408.00 |
| Windows | 0.9200 | 0.02 | 0.0184 | \$9,672.09 |
| Doors | 0.8500 | 0.02 | 0.0170 | \$8,936.17 |
| Cool Vent | 0.1000 | 0.04 | 0.0040 | \$2,102.63 |
| Heat | 0.1600 | 0.09 | 0.0144 | \$7,569.46 |
| Plumbing | 0.2400 | 0.14 | 0.0336 | \$17,662.07 |
| Electrical | 0.7400 | 0.07 | 0.0518 | \$27,229.02 |
| AE/OP | 0.2142 | 0.18 | 0.0386 | \$20,267.22 |

Component Deficiency Total:

0.2528

Outstanding Maintenance:

\$132,862.91

Facilities Condition Index (FCI):

74.72

 $FCI = (1-Component Deficiency Total) \times 100$

Building Name: Engineering

Number: 0041

Construction Date: 1957

Gross Square Feet: 211,410 Net Square Feet: 198,530

Date of Audit: 10/16/2006 Cycle: 6 Phase: 1 No. of Stories: 2

Classification: M120 Classroom, 2-3 Story

SBP Class: 12 Engineering

Replacement Cost:

\$104,491,274.00

Cost Per SF: \$494.26

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| | | | | 0440.007.70 |
| Foundation | 0.0700 | 0.02 | 0.0014 | \$146,287.78 |
| Ext Walls | 0.0750 | 0.04 | 0.0030 | \$313,473.80 |
| Floors | 0.2500 | 0.12 | 0.0300 | \$3,134,738.15 |
| Roof | 0.3000 | 0.05 | 0.0150 | \$1,567,369.20 |
| Ceiling | 0.2200 | 0.04 | 0.0088 | \$919,523.19 |
| Int Walls | 0.2400 | 0.06 | 0.0144 | \$1,504,674.28 |
| Windows | 0.2200 | 0.03 | 0.0066 | \$689,642.39 |
| Doors | 0.2400 | 0.04 | 0.0096 | \$1,003,116.19 |
| Cool Vent | 0.0500 | 0.08 | 0.0040 | \$417,965.09 |
| Heat | 0.0250 | 0.09 | 0.0023 | \$235,105.38 |
| Plumbing | 0.4000 | 0.07 | 0.0280 | \$2,925,755.73 |
| Electrical | 0.0580 | 0.11 | 0.0064 | \$666,654.31 |
| Convey | 0.2700 | 0.01 | 0.0027 | \$282,126.44 |
| Safety | 0.1000 | 0.01 | 0.0010 | \$104,491.27 |
| AE/OP | 0.1331 | 0.18 | 0.0240 | \$2,503,966.29 |

Component Deficiency Total:

0.1571

Outstanding Maintenance:

\$16,414,889.60

Facilities Condition Index (FCI):

84.29

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

Building Name: Spruce Hall

Number: 0064

Construction Date: 1881

Gross Square Feet: 18,738

Net Square Feet: 15,936

Date of Audit: 12/04/2006 Cycle: 6 Phase: 1 No. of Stories: 2

Classification: M460 Office Building

SBP Class: 16 Office

Replacement Cost:

\$2,031,575.83

Cost Per SF: \$108.42

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.2000 | 0.02 | 0.0040 | \$8,126.30 |
| Ext Walls | 0.1500 | 0.09 | 0.0135 | \$27,426.27 |
| Floors | 0.2000 | 0.16 | 0.0320 | \$65,010.43 |
| Roof | 0.3500 | 0.03 | 0.0105 | \$21,331.55 |
| Ceiling | 0.1500 | 0.05 | 0.0075 | \$15,236.82 |
| Int Walls | 0.1700 | 0.05 | 0.0085 | \$17,268.40 |
| Windows | 0.2000 | 0.02 | 0.0040 | \$8,126.30 |
| Doors | 0.2000 | 0.05 | 0.0100 | \$20,315.76 |
| Cool Vent | 0.2600 | 0.09 | 0.0221 | \$44,897.82 |
| Heat | 0.1900 | 0.09 | 0.0161 | \$32,809.95 |
| Plumbing | 0.1800 | 0.02 | 0.0036 | \$7,313.67 |
| Electrical | 0.3120 | 0.12 | 0.0374 | \$76,062.20 |
| Convey | 0.1300 | 0.03 | 0.0039 | \$7,923.15 |
| Safety | 0.2000 | 0.01 | 0.0020 | \$4,063.15 |
| AE/OP | 0.1752 | 0.18 | 0.0315 | \$64,064.12 |

Component Deficiency Total:

0.2067

Outstanding Maintenance:

\$419,975.90

Facilities Condition Index (FCI):

79.33

 $FCI = (1-Component Deficiency Total) \times 100$

Building Name: Industrial Sciences

Number: 0058

Construction Date: 1884

Gross Square Feet: 28,009

Net Square Feet: 24,290

Date of Audit: 11/06/2006 Cycle: 6 Phase: 1 No. of Stories: 3

Classification: M120 Classroom, 2-3 Story

SBP Class: 14 Instructional Shop

Replacement Cost:

\$2,986,902.00

Cost Per SF: \$106.64

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1600 | 0.02 | 0.0032 | \$9,558.09 |
| Ext Walls | 0.2000 | 0.04 | 0.0080 | \$23,895.22 |
| Floors | 0.2000 | 0.12 | 0.0240 | \$71,685.65 |
| Roof | 0.1500 | 0.05 | 0.0075 | \$22,401.77 |
| Ceiling | 0.8000 | 0.04 | 0.0320 | \$95,580.86 |
| Int Walls | 0.1700 | 0.06 | 0.0102 | \$30,466.40 |
| Windows | 0.1900 | 0.03 | 0.0057 | \$17,025.34 |
| Doors | 0.3300 | 0.04 | 0.0132 | \$39,427.10 |
| Cool Vent | 0.0900 | 0.01 | 0.0009 | \$2,688.21 |
| Heat | 0.1750 | 0.16 | 0.0280 | \$83,633.25 |
| Plumbing | 0.3400 | 0.07 | 0.0238 | \$71,088.27 |
| Electrical | 0.7430 | 0.11 | 0.0817 | \$244,119.51 |
| Safety | 0.2500 | 0.04 | 0.0100 | \$29,869.02 |
| AE/OP | 0.2482 | 0.18 | 0.0447 | \$133,458.97 |

Component Deficiency Total:

0.2929

Outstanding Maintenance:

\$874,897.65

Facilities Condition Index (FCI):

70.71

FCI = (1-Component Deficiency Total) x 100

Building Name: Routt Hall

Number: 0061

Construction Date: 1890

Gross Square Feet: 4,918

Net Square Feet: 4,228

Date of Audit: 11/27/2006 Cycle: 6 Phase: 1 No. of Stories: 1

Classification: M460 Office Building

SBP Class: 16 Office

Replacement Cost:

\$765,850.00

Cost Per SF: \$155.72

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0500 | 0.02 | 0.0010 | \$765.85 |
| Ext Walls | 0.0700 | 0.09 | 0.0063 | \$4,824.86 |
| Floors | 0.1500 | 0.16 | 0.0240 | \$18,380.40 |
| Roof | 0.1000 | 0.03 | 0.0030 | \$2,297.55 |
| Ceiling | 0.0600 | 0.05 | 0.0030 | \$2,297.55 |
| Int Walls | 0.2600 | 0.05 | 0.0130 | \$9,956.05 |
| Windows | 0.7000 | 0.02 | 0.0140 | \$10,721.90 |
| Doors | 0.6000 | 0.05 | 0.0300 | \$22,975.50 |
| Cool Vent | 0.1300 | 0.02 | 0.0026 | \$1,991.21 |
| Heat | 0.1000 | 0.11 | 0.0110 | \$8,424.35 |
| Plumbing | 0.1500 | 0.02 | 0.0030 | \$2,297.55 |
| Electrical | 0.0660 | 0.12 | 0.0079 | \$6,065.53 |
| Convey | 0.4300 | 0.03 | 0.0129 | \$9,879.46 |
| Safety | 0.1500 | 0.01 | 0.0015 | \$1,148.78 |
| AE/OP | 0.1332 | 0.18 | 0.0240 | \$18,364.78 |

Component Deficiency Total:

0.1572

Outstanding Maintenance:

\$120,391.31

Facilities Condition Index (FCI):

84.28

 $FCI = (1-Component Deficiency Total) \times 100$

Building Name: Visual Arts

Number: 0151

Construction Date: 1973

Gross Square Feet: 91,997

Net Square Feet: 86,135

Date of Audit: 02/21/2006 Cycle: 5 Phase: 3 No. of Stories: 1

Classification: M120 Classroom, 2-3 Story

SBP Class: 13 Fine Arts

Replacement Cost:

\$9,149,865.00

Cost Per SF: \$99.46

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1500 | 0.02 | 0.0030 | \$27,449.59 |
| Ext Walls | 0.2200 | 0.04 | 0.0088 | \$80,518.81 |
| Floors | 0.2000 | 0.12 | 0.0240 | \$219,596.76 |
| Roof | 0.0800 | 0.05 | 0.0040 | \$36,599.46 |
| Ceiling | 0.4000 | 0.04 | 0.0160 | \$146,397.84 |
| Int Walls | 0.3500 | 0.06 | 0.0210 | \$192,147.16 |
| Windows | 0.5000 | 0.03 | 0.0150 | \$137,247.97 |
| Doors | 0.5000 | 0.04 | 0.0200 | \$182,997.30 |
| Cool Vent | 0.7500 | 0.05 | 0.0375 | \$343,119.94 |
| Heat | 0.1200 | 0.12 | 0.0144 | \$131,758.05 |
| Plumbing | 0.3000 | 0.07 | 0.0210 | \$192,147.17 |
| Electrical | 0.0760 | 0.11 | 0.0084 | \$76,492.87 |
| Safety | 0.4000 | 0.01 | 0.0040 | \$36,599.46 |
| AE/OP | 0.1971 | 0.18 | 0.0355 | \$324,553.05 |

Component Deficiency Total:

0.2325

Outstanding Maintenance:

\$2,127,625.47

Facilities Condition Index (FCI):

76.75

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

MAN WAR

| A. AGENCY BA | SIC DATA: | | | | Pa | ige1 c | of5 |
|-------------------------------------|---|------------|-------------|---------------------|----------------------|-------------|-------|
| A. AGENCT BA | ISIC DATA. | | | | | | |
| Contro | lled Maintenance | Request | | apital Re equest | enewal Buildin | g/Infrastru | cture |
| 1) Agency | Colorado State Univ | versity | | | | | |
| 2) Department | Higher Education | | | | | | |
| 3) Physical Plant | ID No. 03-121 | | | | Project M# | | |
| 4) Agency Priority | /# | | | | | | |
| 5) Project Title | 5) Project Title Improve Fire Alarm Systems For Additional Life Safety and Code Compliance – Phase 1 of 2 | | | | | | |
| B. FACILITY PROFILE | | | | | | | |
| 1) Facility Type | Site (Utilities u | ndergroun | nd) | | | | |
| or Site (Improvements above ground) | | | | | | | |
| | x or Building Name (s) See Below | | | | | | |
| | Risk Mgmt. Bldg(s) ID# See Below | | | | | | |
| 2) Facility Location | n | | | | | | |
| 3) Facility Area/A | ge GSF See Be | low | _ ASF | See Belo | Date B | uilt See | Below |
| 4) Facility Function | onal Use/Occupancy | See Be | elow | | | | |
| 5) Facility Constr | uction (Type) See | Below | | | | | |
| | al Condition and Faci | | | | | | |
| | | geted FCI | | | _ Date of Last | | |
| (Describe) | Risk | GSF | ASF | Date | Occupancy | | |
| Administration | 3890 | 32,172 | 23,618 | 1924 | Office | II-1HR | 73.08 |
| Clark | 5000 | 254,792 | 137,426 | 1967 | Class/Office | II-FR | 65.55 |
| Glover | 3269 | 52,823 | 33,111 | 1950 | Engineering | II-1HR | 81.09 |
| Central Receiv | | 15,675 | 13,276 | 1967 | Phys Plant | II-FR | 75.30 |
| AIDL | 3668 | 14,329 | 9,101 | 1964 | Science | II-1HR | 65.32 |
| | sity of Use, Time(s) o | Operatio | n: (Hours/I | Day, Days | s/ivionin, ivionins/ | rear) | |
| All buildings are | ent Replacement Valu | ۸۵ ع | ministratio | n ¢3 036 | 3,824; Clark - \$27 | 7 170 356 | |
| o) racility - Curre | nt Replacement valu | | | | entral Receiving | | ۵٠ |
| | | | DL - \$1,78 | | entrai receiving | Ψ1,400,000 | , |
| 0) 14 1 - DI - 0 | 4-4 Obb | | | | | | |
| | tatus - Check one or | | |). | | | |
| | ty 'useful' life is less t | | | | | | |
| | ty 'useful' life is more | | | | | | |
| c) Maste | er Plan is obsolete; La | ast Date A | pproved | (by OSP | B/CCHE) | | |
| | facility changes, renewive years, (If yes, plea | | | revisions | are ongoing or a | | |
| | nave an impact on thi | | | | | | |

| | | Page | 2 of5 |
|---|--|---|--|
| 10) Facility Audit | Survey: | | |
| | Audit Survey concluded and submitted to SBREP - | Date | 2005 |
| | f the Infrastructure Assessment. | % Completed | 100 |
| | Audit Survey Cycle 5/2 | | |
| 11) List all the collast five year request. | ontrolled maintenance, capital construction, and emerge s or ongoing projects that can be associated with either | this CM building | pleted within the or infrastructure Completion date |
| Project No. | Project Title | | or status |
| | | | |
| | | | |
| | | | |
| C. INTEGRATE | ED PROGRAM PLAN DATA | | |
| | pital Renewal Building/Infrastructure Request, refer to the red to support the request. | ne instructions for | the additional |
| 1) Narrative Desc | printion of CM Problem (Initial problem and solution by | phase). | |
| | cription of CM Problem (Initial problem and solution by p m systems in these buildings are original (30 to 40 year | | very difficult to |
| obtain, comr Systems nee | munication is incomplete in many areas, and none of the ed to be replaced with current technology. This would in | e systems meet on prove the life saf | current code. |
| of the syster | n, however the alarms do currently evacuate the buildin | g occupants. | |
| | | | |
| | | | |
| O) Total Design of C | Seet Estimate (From Cost Brookdown) \$ \$1,294,276 | | |
| | Cost Estimate (From Cost Breakdown) \$\$1,284,376 s (cost effects, program impacts, facility impacts, etc.) of | | iustifying this |
| specific project | 등 그 전에 보고 있는 것이 되는 것 같아. 그는 것 같아 있는 것 같아 있는 것 같아 없는 것 같아 없는 것 같아 없는 것 같아 없는 것 같아. | n <u>not</u> runding and | jacarying and |
| | coverage and a lack of ADA compliant devices will not r | neet code compli | ance. |
| madequate | soverage and a lack of his recompliant across summer. | | |
| | | | |
| | | | |
| | nclude Facility Audit documentation from most recent a project request. | udit. Include site | maps for any |
| | ude photographs and any other supporting documents. | | |
| | how this project will improve the building(s) facility contructure system. | dition index or imp | prove a |
| | mponent in these buildings will improve by 50% - 100% | | |
| The salety co | The state of the s | | |
| | | | |
| | | | |

_5__

| | | | Page3 of _ |
|--|--------------|----------------|-------------------------|
| D. <u>DETAILED COST ESTIMATE</u> (detail by | y phase, or | ne page per ph | ase, include all phases |
| 1) Approved By Dewey Wearne | | 2) Phase? | 1 |
| 3) Method of Estimate Historic | | 2) i nasc : | |
| 1 Historie | | | |
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | | | \$130,000 |
| Code Review/Inspection | | | \$5,000 |
| Other (Explain) | | | |
| Total of Professional Services | | | \$135,000 |
| | | | |
| 5) Construction Improvement | | T LINUT OCCT | EVTENDED COOT |
| <u>WORK ITEM</u> (Labor/Material/Equipment) | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) | | | |
| Administration | SF | 62.90 | \$87,282 |
| Glover | SF | \$2.80 | \$147,904 |
| | SF | \$2.80 | \$43,890 |
| Central Receiving AIDL | SF | \$2.80 | \$40,121 |
| AIDL | OF . | \$2.00 | 940,121 |
| | | | |
| | | | |
| | | | |
| | | | |
| La contraction de la contracti | | | |
| | | | |
| | | | |
| | | | |
| Total of Construction Improvements Costs | | | \$319,197 |
| Total of Construction Improvements costs | | | ψο το, το τ |
| 6) Miscellaneous (explain) | | | |
| | | | |
| | | | |
| Total of Miscellaneous Costs | | | \$ |
| | | | |
| 7) Project Contingency | | Asset to the | |
| Contingency (10% CM) (Percentage of total of | | al services, | \$45,420 |
| construction improvements, and miscellaneou | s costs.) | | |
| 9) Subtatal of professional convices, construct | \$499,617 | | |
| 8) Subtotal of professional services, construction miscellaneous costs, and project contingen | | | \$499,017 |
| This senance de decis, and project sommigen | -, po. oonta | .go (b) phace) | |
| | | | |
| 9) TOTAL PROJECT COST (all phases)= | REQUES | Т | \$1,284,3765 |
| o) To Trice Tricolor (all pridoco) | 1 .,, | | |

| D. <u>DETAILED COST ESTIMATE</u> (detail b | y phase, o | ne page per ph | Page4 of ase, include all phases |
|--|----------------|----------------|----------------------------------|
| 1) Approved By Dewey Wearne | | 2) Phase? | 2 |
| 3) Method of Estimate Historic | | | |
| | | | |
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | | | |
| Code Review/Inspection | | | |
| Other (Explain) | | | |
| Total of Professional Services | | | |
| 5) Construction Improvement | | | |
| WORK ITEM | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) | | | |
| | 05 | 0.70 | ¢740,440 |
| Clark | SF | \$2.70 | \$713,418 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| Total of Construction Improvements Costs | | | \$713,418 |
| | | | |
| 6) Miscellaneous (explain) | | | |
| | | | |
| | | | |
| Total of Miscellaneous Costs | | | \$ |
| 7) Project Contingency | | | |
| Contingency (10% CM) (Percentage of total of | f professiona | al services, | \$71,342 |
| construction improvements, and miscellaneou | s costs.) | | |
| 2) 2 de la faction de la companyant | \$784,759 | | |
| 8) Subtotal of professional services, construct miscellaneous costs, and project contingen | \$704,739 | | |
| | -) portocritar | 3 - (a) p. (a) | |
| | | | |
| 9) TOTAL PROJECT COST (all phases)= | REQUES | Т | \$1,284,376 |
| | | | |

| | | | | Page | 5 of5 | | |
|--|----------------------------------|---------------------------|---------------------------------|---|----------------|--|--|
| | | PHASING | | | | | |
| PRIOR Proj. M# | PHASING Phys. Plant | Fiscal Year | Phase or Phases of Work | Dollar Amount (Actual |] | | |
| | ID# | | | Appropriation) | | | |
| | | | | \$ | _ (Subtotal) | | |
| CURRE | NT PHAS | SE ² REQUESTED | | | | | |
| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase of Work | Dollar Amount (Per Detailed Budget) | | | |
| | | FY 2009/2010 | 1 | \$499,617 | | | |
| | | | | | _ | | |
| | | | | \$ 499,617 | _ (Subtotal) | | |
| - | E PHASI | | | Dallan Amazanak | 7 | | |
| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Per Detailed Budget) | | | |
| | | FY 2010/2011 | 2 | \$784,759 | | | |
| | | | | | | | |
| | | | | \$ 784,759 | _ (Subtotal) | | |
| Project | Total Doll | ar Amount of All Pro | jects Phases Requested | \$ 1,284,376 | | | |
| | | and Future Phases) | Jeous i nases requested | Ψ 1,201,010 | | | |
| 1 List all | provious r | phagos with actual apr | propriation by year (include fe | deral funding) Note if | different from | | |
| reques | ted amour | nt. | | | | | |
| | | d anticipated future p | hases with estimated costs as | s listed in the detailed | cost estimate | | |
| | al blank 8. POSED F | PROJECT IMPLEM | ENTATION SCHEDULE (F | PLAN): | | | |
| | | | | | | | |
| | F | PHASE | FROM | | ТО | | |
| | | ert Dates) | July 09 | Dec 09 | | | |
| | n (Insert D | | Dec 09 | May 10 | | | |
| 3. Construction (Insert Dates) May 10 | | | May 11 | | | | |
| 4. Project Close-out/Final Completion May 11 | | May 11 | July 11 | | | | |
| | | | | | | | |
| | | | | | | | |
| G. AGENCY APPROVAL | | | | | | | |
| | | | | | | | |
| Agency | Agency Authorized Signature Date | | | | | | |

Building Name: Administration

Number: 0080

Construction Date: 1924

Gross Square Feet: 32,172

Net Square Feet: 29,530

Date of Audit: 11/15/2005 Cycle: 5 Phase: 3 No. of Stories: 3

Classification: M460 Office Building

SBP Class: 16 Office

Replacement Cost:

\$3,938,824.39

Cost Per SF: \$122.43

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| | | | | |
| Foundation | 0.3000 | 0.02 | 0.0060 | \$23,632.95 |
| Ext Walls | 0.3000 | 0.09 | 0.0270 | \$106,348.27 |
| Floors | 0.1500 | 0.16 | 0.0240 | \$94,531.79 |
| Roof | 0.1000 | 0.03 | 0.0030 | \$11,816.47 |
| Ceiling | 0.1800 | 0.05 | 0.0090 | \$35,449.42 |
| Int Walls | 0.3500 | 0.05 | 0.0175 | \$68,929.43 |
| Windows | 0.4000 | 0.02 | 0.0080 | \$31,510.59 |
| Doors | 0.2800 | 0.05 | 0.0140 | \$55,143.54 |
| Cool Vent | 0.0600 | 0.07 | 0.0042 | \$16,543.06 |
| Heat | 0.0600 | 0.08 | 0.0048 | \$18,906.36 |
| Plumbing | 0.2300 | 0.02 | 0.0046 | \$18,118.59 |
| Electrical | 0.8000 | 0.12 | 0.0960 | \$378,127.11 |
| Convey | 0.2000 | 0.03 | 0.0060 | \$23,632.95 |
| Safety | 0.4000 | 0.01 | 0.0040 | \$15,755.30 |
| AE/OP | 0.2281 | 0.18 | 0.0411 | \$161,720.26 |

Component Deficiency Total:

0.2692

Outstanding Maintenance:

\$1,060,166.08

Facilities Condition Index (FCI):

73.08

 $FCI = (1-Component Deficiency Total) \times 100$

Building Name: Central Receiving

Number: 0131

Construction Date: 1967

Gross Square Feet: 15,675

Net Square Feet: 14,550

Date of Audit: 02/19/2007 Cycle: 6 Phase: 1 No. of Stories: 1

Classification: M500 Post Office

SBP Class: 30

Physical Plant Service

Replacement Cost:

\$1,456,688.72

Cost Per SF: \$92.93

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1500 | 0.06 | 0.0090 | \$13,110.20 |
| Ext Walls | 0.1000 | 0.11 | 0.0110 | \$16,023.58 |
| Floors | 0.1500 | 0.07 | 0.0105 | \$15,295.23 |
| Roof | 0.4000 | 0.11 | 0.0440 | \$64,094.30 |
| Ceiling | 0.2500 | 0.01 | 0.0025 | \$3,641.72 |
| Int Walls | 0.1000 | 0.09 | 0.0090 | \$13,110.20 |
| Windows | 0.1000 | 0.03 | 0.0030 | \$4,370.07 |
| Doors | 0.4000 | 0.06 | 0.0240 | \$34,960.53 |
| Cool Vent | 0.6000 | 0.05 | 0.0300 | \$43,700.66 |
| Heat | 0.1800 | 0.06 | 0.0108 | \$15,732.24 |
| Plumbing | 0.3100 | 0.02 | 0.0062 | \$9,031.47 |
| Electrical | 0.3630 | 0.09 | 0.0327 | \$47,590.02 |
| Convey | 0.4200 | 0.01 | 0.0042 | \$6,118.09 |
| Safety | 0.3000 | 0.03 | 0.0090 | \$13,110.20 |
| AE/OP | 0.2059 | 0.20 | 0.0412 | \$59,977.70 |

Component Deficiency Total:

0.2470

Outstanding Maintenance:

\$359,866.22

Facilities Condition Index (FCI):

75.30

 $FCI = (1-Component\ Deficiency\ Total)\ x\ 100$

Building Name: Andrew G. Clark Building

Number: 0091

Construction Date: 1967

Gross Square Feet: 254,792 Net Square Feet: 229,960

Date of Audit: 12/06/2005 Cycle: 5 Phase: 3 No. of Stories: 3

Classification: M120 Classroom, 2-3 Story

SBP Class: 10 Classroom/Office

Replacement Cost:

\$27,170,356.42

Cost Per SF: \$106.64

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.2500 | 0.02 | 0.0050 | \$135,851.78 |
| Ext Walls | 0.4000 | 0.04 | 0.0160 | \$434,725.70 |
| Floors | 0.4000 | 0.12 | 0.0480 | \$1,304,177.10 |
| Roof | 0.5500 | 0.05 | 0.0275 | \$747,184.83 |
| Ceiling | 0.3700 | 0.04 | 0.0148 | \$402,121.27 |
| Int Walls | 0.1800 | 0.06 | 0.0108 | \$293,439.85 |
| Windows | 0.3000 | 0.03 | 0.0090 | \$244,533.21 |
| Doors | 0.3000 | 0.04 | 0.0120 | \$326,044.28 |
| Cool Vent | 0.1300 | 0.09 | 0.0110 | \$300,232.43 |
| Heat | 0.3200 | 0.09 | 0.0272 | \$739,033.69 |
| Plumbing | 0.3500 | 0.07 | 0.0245 | \$665,673.72 |
| Electrical | 0.7000 | 0.11 | 0.0770 | \$2,092,117.40 |
| Convey | 0.2100 | 0.01 | 0.0021 | \$57,057.75 |
| Safety | 0.7000 | 0.01 | 0.0070 | \$190,192.49 |
| AE/OP | 0.2920 | 0.18 | 0.0526 | \$1,427,829.47 |

Component Deficiency Total:

0.3445

Outstanding Maintenance:

\$9,360,215.06

Facilities Condition Index (FCI):

65.55

 $FCI = (I-Component\ Deficiency\ Total)\ x\ 100$

Building Name: Arthropod-Borne & Infectious Disease Lab Number: 1421

Construction Date: 1964 Gross Square Feet: 14,329 Net Square Feet: 11,914

Date of Audit: 04/09/2007 Cycle: 6 Phase: 1 No. of Stories: 1

Classification: M150 College, Laboratory SBP Class: 11 Science

Replacement Cost: \$1,783,424.60 Cost Per SF: \$124.46

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.1500 | 0.07 | 0.0105 | \$18,725.96 |
| Ext Walls | 0.2000 | 0.06 | 0.0120 | \$21,401.10 |
| Floors | 0.2500 | 0.07 | 0.0175 | \$31,209.93 |
| Roof | 0.2500 | 0.06 | 0.0150 | \$26,751.37 |
| Ceiling | 0.4000 | 0.03 | 0.0120 | \$21,401.10 |
| Int Walls | 0.6000 | 0.09 | 0.0540 | \$96,304.94 |
| Windows | 0.5000 | 0.02 | 0.0100 | \$17,834.25 |
| Doors | 0.5000 | 0.02 | 0.0100 | \$17,834.25 |
| Cool Vent | 0.3200 | 0.06 | 0.0208 | \$37,095.23 |
| Heat | 0.3800 | 0.06 | 0.0247 | \$44,050.59 |
| Plumbing | 0.3900 | 0.14 | 0.0546 | \$97,374.99 |
| Electrical | 0.6540 | 0.07 | 0.0458 | \$81,645.18 |
| Safety | 0.3500 | 0.02 | 0.0070 | \$12,483.97 |
| AE/OP | 0.2939 | 0.18 | 0.0529 | \$94,340.31 |

Component Deficiency Total:

0.3468

Outstanding Maintenance:

\$618,453.14

Facilities Condition Index (FCI):

65.32

 $FCI = (1-Component Deficiency Total) \times 100$

Building Name: Engineering South/Glover

Number: 0088

Construction Date: 1950

Gross Square Feet: 52,823 Net Square Feet: 45,202

Date of Audit: 01/08/2007 Cycle: 6 Phase: 1 No. of Stories: 2

Classification: M120 Classroom, 2-3 Story

SBP Class: 12 Engineering

Replacement Cost:

\$9,017,572.80

Cost Per SF: \$170.71

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.0800 | 0.02 | 0.0016 | \$14,428.12 |
| Ext Walls | 0.1000 | 0.04 | 0.0040 | \$36,070.29 |
| Floors | 0.1500 | 0.12 | 0.0180 | \$162,316.31 |
| Roof | 0.5500 | 0.05 | 0.0275 | \$247,983.26 |
| Ceiling | 0.1100 | 0.04 | 0.0044 | \$39,677.32 |
| Int Walls | 0.0800 | 0.06 | 0.0048 | \$43,284.35 |
| Windows | 0.2000 | 0.03 | 0.0060 | \$54,105.44 |
| Doors | 0.1100 | 0.04 | 0.0044 | \$39,677.32 |
| Cool Vent | 0.3000 | 0.09 | 0.0270 | \$243,474.48 |
| Heat | 0.2000 | 0.08 | 0.0160 | \$144,281.16 |
| Plumbing | 0.2600 | 0.07 | 0.0182 | \$164,119.82 |
| Electrical | 0.2080 | 0.11 | 0.0229 | \$206,322.07 |
| Convey | 0.3500 | 0.01 | 0.0035 | \$31,561.50 |
| Safety | 0.2000 | 0.01 | 0.0020 | \$18,035.15 |
| AE/OP | 0.1603 | 0.18 | 0.0289 | \$260,160.60 |

Component Deficiency Total:

0.1891

Outstanding Maintenance:

\$1,705,497.23

Facilities Condition Index (FCI):

81.09

 $FCI = (1-Component Deficiency Total) \times 100$

|) | A. AGENCY BASIC DATA: |
|---|--|
| | Controlled Maintenance Request HPCP required in Capital Renewal Request (Y/N) (on CC-A specify HPCP compliance) |
| | 1) Agency Colorado State University |
| | 2) Department Higher Education |
| | 3) Physical Plant ID No. 00-001 Project M # |
| | 4) Agency Priority # 1 |
| | 5) Project Title Remove Asbestos and Replace Deteriorated Electrical and Mechanical Systems Guggenheim Hall – Phase 1 of 2 |
| | B. FACILITY PROFILE |
| | 1) Facility Type Site (Utilities underground) |
| | or Site (Improvements above ground) |
| | x or Building Name (s) Guggenheim Hall |
| | Risk Mgmt. Bldg(s) ID# 3228 |
| | 2) Facility Location Main Campus |
| | 3) Facility Area/Age GSF 17,569 ASF 14,187 Date Built 1910 |
| | 4) Facility Functional Use/Occupancy Construction Management, Human Sciences |
| | 5) Facility Construction (Type) II-1HR |
| | 6) Facility Physical Condition and Facility Condition Index (FCI) Number |
| | Actual FCI = 73.69 Targeted FCI = 85.00 Date of Last Audit 9/24/2007 |
| | (Describe) |
| | |
| | |
| | |
| | 7) Facility - Intensity of Use, Time(s) of Operation: (Hours/Day, Days/Month, Months/Year) |
| | 8) Facility - Current Replacement Value \$1,776,070 |
| | 9) Master Plan Status - Check one or more of the following: |
| | a) Facility 'useful' life is less than five (5) years. |
| | b) X Facility 'useful' life is more than five (5) years. |
| | c) Master Plan is obsolete; Last Date Approved |
| | (by OSPB/CDHE) |
| | d) Major facility changes, renovations, or program revisions are ongoing or anticipated in the next five years, (If yes, please explain below if these facility renovations or program revisions may have an impact on this CM request.) |

| 10) Facility Audit Survey: a) Facility Audit Survey concluded and submitted to SBP - b) Status of the Infrastructure Assessment. c) Facility Audit Survey Cycle | Date % Completed | 2007 |
|--|--|---|
| 11) List all the controlled maintenance, capital construction, and emergence last five years or ongoing projects that can be associated with either the request. | nis CM building o | or infrastructure |
| Project No. Project Title None | | Completion date or status |
| C. INTEGRATED PROGRAM PLAN DATA NOTE: For a Capital Renewal Building/Infrastructure Request, refer to the information required to support the request. 1) Narrative Description of CM Problem (Initial problem and solution by phenomenant systems are beyond life expectancy. The mechanical pipe crawl space, most of which is damaged and degraded. This degraded earthen floor of the crawl space requiring soil remediation as well. Steam with hot water, which would require a mechanical room for pumps and needs to be replaced. Lighting needs to be replaced and occupancy seen trances need to be ADA compliant. Potable water system needs to with more efficient equipment. Hot water heater needs replaced. Front settled and are separating from stone entablature. 2) Total Project Cost Estimate (From Cost Breakdown) \$ 1,776,070 | hase): has Air Cell insu Air Cell has con am heat needs to controls. All buil ensors installed. be replaced as w | ulation in taminated the be replaced ding electrical Building vell as fixtures |
| Consequences (cost effects, program impacts, facility impacts, etc.) of not funding and justifying this specific project request: Loss of use will occur as mechanical systems fail in crawl space along occupants because crawl space is vented and asbestos could infiltrate. | g with liability issu e building. | ues to building |
| 4) Mandatory - Include Facility Audit documentation from most recent au infrastructure project request. 5) Optional - Include photographs and any other supporting documents. 6) Explanation of how this project will improve the building(s) facility cond specific infrastructure system. This is a historical building built in 1910. In 2006 Guggenheim had a find donations that did not address any mechanical, electrical, or structural systems to code should bring the FCI from 73 to 85. | ition index or implace. | orove a |

| 1) Approved By | | 2) Phase? | 1 |
|--|--------------|----------------|----------------|
| 3) Method of Estimate Historical | | | |
| | | | |
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | | | \$200.000 |
| Code Review/Inspection | | | \$25,000 |
| Other (Explain) | | | |
| Total of Professional Services | | | \$225,000 |
| | | | |
| 5) Construction Improvement | | | |
| WORK ITEM | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) | | | |
| Infrastructure | | | |
| a) Utility Services | | | |
| b) Site Improvements | | | |
| | | | |
| Structure/System/Components | | | |
| Remediation and repair of stone front | LS | | \$165,000 |
| entrance and columns | | | |
| Other(explain) | LS | | \$80,000 |
| Abatement – 6400sf of potentially contaminate area. Removal of 200+lf of | Lo | | \$60,000 |
| damaged Air Cell. | | | |
| | 1.5 | 0050 | #50.000 |
| Replace component abated piping in crawl | LF | \$250 | \$50,000 |
| space. | | | |
| Phase 1 Design will determine how many | | | |
| exhaust fans, AHU's, VAV"S, controls, fan coils, ect. will be replaced | | | |
| coils, ect. Will be replaced | | | |
| Total of Construction Improvements Costs | | | \$295,000 |
| | | | |
| 6) Miscellaneous (explain) | | _ | |
| | | | |
| Total of Miscellaneous Costs | | | \$ |
| | | | |
| 7) Project Contingency | function | al agricos | L \$52,000 |
| Contingency (10% CM) (Percentage of total of | r profession | ai services, | \$52,000 |
| construction improvements, and miscellaneou | 13 00313.7 | | |
| 8) Project or Phase total of professional service | ces (4) cons | struction | \$572,000 |
| improvements(5), miscellaneous costs(6), | and project | contingency(7) | |
| mproverne (e), moderane estate(e), | | | |
| | | | |
| | | Т | \$1,776,070 |

| STATE BUILDINGS PROGRAMS D. DETAILED COST ESTIMATE (detail) | | ne nage per ph | |
|--|----------------|----------------|---------------|
| D. DETAILED COST ESTIMATE (details | by phase, or | | |
| 1) Approved By | | 2) Phase? | 2 |
| 3) Method of Estimate Historical | | | |
| 4) Professional Services | | | |
| Site Surveys, Investigations, and Reports | | | |
| Arch/Eng/Basic Services | | | |
| Code Review/Inspection | | | |
| Other (Explain) | | | |
| Total of Professional Services | | | |
| E) Construction Improvement | 1 | | |
| 5) Construction Improvement WORK ITEM | UNIT | UNIT COST | EXTENDED COST |
| (Labor/Material/Equipment) | | | |
| Infrastructure | | | |
| a) Utility Services | | | |
| b) Site Improvements | | | |
| | | | |
| Structure/System/Components | | | |
| Pumps and Controls | LS | | \$232,000 |
| Other(explain) | | | |
| Fan Coil Units | LS | | \$231,000 |
| Electrical | SF | \$24.57 | \$431,670 |
| Plumbing | LS | | \$200,000 |
| Total of Construction Improvements Costs | | | \$1,094,000 |
| | | | |
| 6) Miscellaneous (explain) | | | |
| Total of Miscellaneous Costs | | | \$ |
| Total of Miscellaneous Costs | | | |
| 7) Project Contingency | | | |
| Contingency (10% CM) (Percentage of total | al services, | \$109,400 | |
| construction improvements, and miscellaned | ous costs.) | | |
| 8) Project or Phase total of professional serv | \$1,204,070 | | |
| improvements(5), miscellaneous costs(6) | contingency(7) | | |
| | | | |
| 9) TOTAL PROJECT COST (all phases |)= REQUES | Т | \$1,776,070 |

E. PROPOSED PHASING PRIOR PHASING1

| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Actual Appropriation) |
|-------------|-----------------------|--------------|-------------------------|--|
| | | FY 2006/2007 | | |
| | | FY 2006/2007 | | |
| | | FY 2007/2008 | | |
| | | FY 2008/2009 | | |

(Subtotal)

CURRENT PHASE² REQUESTED

| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase of Work | Dollar Amount (Per Detailed Budget) |
|-------------|-----------------------|--------------|---------------|---|
| | | FY 2009/2010 | 1 | \$572,000 |

(Subtotal) \$ 572,000

FUTURE PHASING2

| Proj. M# | Phys. Plant ID# | Fiscal Year | Phase or Phases of Work | Dollar Amount (Per Detailed Budget) |
|-------------|-----------------------|--------------|-------------------------|---|
| | | FY 2010/2011 | 2 | \$1,204,070 |
| | | FY 2011/2012 | | |
| | | FY 2012/2013 | | |
| | | FY 2013/2014 | | |

\$ 1,204,070 (Subtotal)

Project Total Dollar Amount of All Projects Phases Requested \$ 1,776,070

(Prior, Current and Future Phases)

¹ List <u>all</u> previous phases with actual appropriation by year (include federal funding). Note if different from

requested amount.

List all current and anticipated future phases with estimated costs as listed in the detailed cost estimate subtotal blank 8.

| F. PROPOSED | PROJECT IMPL | EMENTATION | SCHEDULE | (PLAN) |
|-------------|--------------|------------|----------|--------|
|-------------|--------------|------------|----------|--------|

| PHASE | FROM | ТО |
|---------------------------------------|---------|---------|
| 1. Pre-Design (Insert Dates) | June 09 | Dec 09 |
| 2. Design (Insert Dates) | Jan 10 | May 10 |
| 3. Construction (Insert Dates) | May 10 | Dec 10 |
| 4. Project Close-out/Final Completion | Jan 11 | June 11 |
| | | |
| G. <u>AGENCY APPROVAL</u> | | |
| Agency Authorized Signature | | Date |

Building Name: Guggenheim Hall Number: 0055

Construction Date: 1910 Gross Square Feet: 17,569 Net Square Feet: 14,187

Date of Audit: 09/24/2007 Cycle: 6 Phase: 2 No. of Stories: 2

Classification: M120 Classroom, 2-3 Story SBP Class: 10 Classroom/Office

Replacement Cost: \$1,904,832.74 Cost Per SF: \$108.42

| Component | Total Rating | Multiplier Used | Component Deficiency | Renewal Cost |
|------------|-----------------|--------------------|-------------------------|-----------------|
| Foundation | 0.2000 | 0.02 | 0.0040 | \$7,619.33 |
| Ext Walls | 0.2500 | 0.04 | 0.0100 | \$19,048.33 |
| Floors | 0.1000 | 0.12 | 0.0120 | \$22,857.99 |
| Roof | 0.1000 | 0.05 | 0.0050 | \$9,524.16 |
| Ceiling | 0.3000 | 0.04 | 0.0120 | \$22,857.99 |
| Int Walls | 0.2000 | 0.06 | 0.0120 | \$22,857.99 |
| Windows | 0.5000 | 0.03 | 0.0150 | \$28,572.49 |
| Doors | 0.4000 | 0.04 | 0.0160 | \$30,477.32 |
| Heat | 0.0700 | 0.17 | 0.0119 | \$22,667.51 |
| Plumbing | 0.3500 | 0.07 | 0.0245 | \$46,668.40 |
| Electrical | 0.8900 | 0.11 | 0.0979 | \$186,483.12 |
| Convey | 0.2200 | 0.01 | 0.0022 | \$4,190.63 |
| Safety | 0.0500 | 0.01 | 0.0005 | \$952.42 |
| AE/OP | 0.2230 | 0.18 | 0.0401 | \$76,459.99 |

Component Deficiency Total:

0.2631

Outstanding Maintenance:

\$501,237.68

Facilities Condition Index (FCI):

73.69

 $FCI = (1-Component Deficiency Total) \times 100$

RECEIVED

DEC 0 8 2009
STATE PUBLICATIONS
Colorado State Library